

OWNER: NORTHGATE AVIATION
ADDRESS: 16384 AIRPORT ROAD
 BRAINERD MN 56401
PHONE:
FAX:

OPERATOR: NORTHGATE AVIATION
ADDRESS: 16384 AIRPORT ROAD
 BRAINERD MN 56401
PHONE:
FAX:

ANALYST: BRYAN MONA 514-636-2020 (OFFICE) 800-787-9749 (EFAX-CARDS)
EMAIL: BMONA@CAMPSYSTEMS.COM 514-636-7866 (FAX) 631-980-4222 (EFAX-CARDS)
 WWW.CAMPSYSTEMS.COM

AIRCRAFT **SERIAL/REGNO:** 50000186/N9990M **MODEL:** EMB-500 - PHENOM 100 **MANUFACTURER:** EMBRAER

DATES

LAST ACTUALS

CERTIFICATION DATE: 03-AUG-2010 455.6 A/C HRS as of 30-NOV-2015
 320 AFL as of 30-NOV-2015

ENGINE NO. 1 **SERIAL/PART:** PCE-LC0355/35C3100-01 **MODEL:** PW617F-E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 18-JUN-2010

LAST ACTUALS

0 ENG. HRS 0 A/C HRS 455.6 ENG. HRS as of 30-NOV-2015
 0 ENC 320 ENC as of 30-NOV-2015

ENGINE NO. 2 **SERIAL/PART:** PCE-LC0359/35C3100-01 **MODEL:** PW617F-E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 18-JUN-2010

LAST ACTUALS

0 ENG. HRS 0 A/C HRS 455.6 ENG. HRS as of 30-NOV-2015
 0 ENC 320 ENC as of 30-NOV-2015



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 1 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 00-INFORMATION					
500-00-0001	GENERAL - INSPECTION /INSTALLATION OF CABLE GUARD PINS ON CONTROL CABLES, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0001 PART I	PERFORM GENERAL - INSPECTION /INSTALLATION OF CABLE GUARD PINS ON CONTROL CABLES, SERVICE BULLETIN FLIGHT CONTROL SYSTEM - CABLE GUARD/COTTER PIN INSPECTION	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0001 PART II	PERFORM GENERAL - INSPECTION /INSTALLATION OF CABLE GUARD PINS ON CONTROL CABLES, SERVICE BULLETIN AUTOPILOT SERVO CABLES - COTTER PIN INSPECTION	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0001 PART III	PERFORM GENERAL - INSPECTION /INSTALLATION OF CABLE GUARD PINS ON CONTROL CABLES, SERVICE BULLETIN PARKING BRAKE SYSTEM - CABLE GUARD PIN INSPECTION	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0002	GENERAL - RECONFIGURATION FROM EASA TO ANAC CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0003	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 2 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-00-0003 R1	GENERAL - RECONFIGURATION FROM ANAC TO FAA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-00-0004	GENERAL - RECONFIGURATION FROM FAA TO EASA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-00-0005	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-00-0005 R1	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-00-0005 R10	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-00-0005 R2	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 3 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-00-0005 R3	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0005 R4	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0005 R5	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0005 R6	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0005 R7	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-00-0005 R8	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 4 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-00-0005 R9	GENERAL - INCREASE OF THE MZFW (MAXIMUM ZERO FUEL WEIGHT), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-00-0006	GENERAL - RECONFIGURATION FROM EASA TO TCCA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-00-0007	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-00-0007 R1	GENERAL - CONVERSION FROM EASA TO FAA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-00-0008	GENERAL - INSPECTION OF THE TURNBUCKLES, SERVICE BULLETIN	MOS	17-JUL-2012	TECH :	INSP :
		HRS	194.40		LABOR HRS :
		AFL	112		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH					
500-00-0009	GENERAL - INSTALLATION OF THE GROUND SPOILER / SPEED BRAKE FUNCTION AND NEW HYDRAULIC SYSTEM, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 5 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL		
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
500-00-0009 R1	GENERAL - INSTALLATION OF THE GROUND SPOILER / SPEED BRAKE FUNCTION AND NEW HYDRAULIC SYSTEM, SERVICE BULLETIN	MOS				TECH :
		HRS				INSP :
		AFL				LABOR HRS :
		MSC		MSC		SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE						
500-00-0009 R2	GENERAL - INSTALLATION OF THE GROUND SPOILER / SPEED BRAKE FUNCTION AND NEW HYDRAULIC SYSTEM, SERVICE BULLETIN	MOS				TECH :
		HRS				INSP :
		AFL				LABOR HRS :
		MSC		MSC		SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE						
500-00-0009 R3	GENERAL - INSTALLATION OF THE GROUND SPOILER / SPEED BRAKE FUNCTION AND NEW HYDRAULIC SYSTEM, SERVICE BULLETIN	MOS				TECH :
		HRS				INSP :
		AFL				LABOR HRS :
		MSC		MSC		SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE						
500-00-0009 R4	GENERAL - INSTALLATION OF THE GROUND SPOILER / SPEED BRAKE FUNCTION AND NEW HYDRAULIC SYSTEM, SERVICE BULLETIN	MOS				TECH :
		HRS				INSP :
		AFL				LABOR HRS :
		MSC		MSC		SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE						
500-00-0010	GENERAL - RECONFIGURATION FROM FAA TO TCCA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	MOS				TECH :
		HRS				INSP :
		AFL				LABOR HRS :
		MSC		MSC		SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE						
500-00-0011	GENERAL - CONVERSION FROM FAA TO EASA CERTIFICATION BASIS REQUIREMENTS, SERVICE BULLETIN	MOS				TECH :
		HRS				INSP :
		AFL				LABOR HRS :
		MSC		MSC		SERVICE REMARKS -- ICAO:
MOC:						



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 6 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-00-0012	GENERAL - RECONFIGURATION FROM FAA TO TCCA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-00-0012 R1	GENERAL - RECONFIGURATION FROM FAA TO TCCA CERTIFICATION REQUIREMENTS , SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-00-0012 R2	GENERAL - RECONFIGURATION FROM FAA TO TCCA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-00-0012 R3	GENERAL - RECONFIGURATION FROM FAA TO TCCA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-00-0014	GENERAL - RECONFIGURATION OF AIRCRAFT FROM ANAC TO FAA TYPE DESIGN, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-00-0014 R1	GENERAL - RECONFIGURATION OF AIRCRAFT FROM ANAC TO FAA TYPE DESIGN, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 7 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-00-0015	GENERAL - RECONFIGURATION FROM TCCA TO FAA CERTIFICATION REQUIREMENTS, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-00-0016	GENERAL - RECONFIGURATION OF AIRCRAFT FROM DGCA (INDIA) TO FAA (USA) REGISTRATION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-30-0005 R2 PART I	INSTALLATION ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN OF WATER SEPARATOR ASSEMBLY	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-30-0005 R2 PART II	ADDITIONAL ACTION ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN - REPLACEMENT OF THE DOWNSTREAM HOSE	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 05-TIME LIMITS/MAINTENANCE CHECKS					
05-30-01	600 FH MAINTENANCE PACKAGE				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0		0	SERVICE REMARKS -- ICAO:
05-30-02	600 FH/12 MO MAINTENANCE PACKAGE				
	MOS	12-AUG-2015		TECH :	INSP :
	HRS	425.50			LABOR HRS :
	AFL	299		0	SERVICE REMARKS -- ICAO:
	MOS	12-AUG-2015		TECH :	INSP :
	HRS	425.50		-	LABOR HRS :
SCHEDULED	AFL	299		0	SERVICE REMARKS -- ICAO:
	MOS	12-AUG-2015		TECH :	INSP :
	HRS	425.50		-	LABOR HRS :
SCHEDULED	AFL	299		0	SERVICE REMARKS -- ICAO:
	MOS	08-AUG-2014		TECH : CRS KX5R005N	INSP : CRS KX5R005N
SCHEDULED	HRS	342.40		-	LABOR HRS :
	AFL	227			SERVICE REMARKS -- ICAO:
05-30-10	1200 FH MAINTENANCE PACKAGE				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0		0	SERVICE REMARKS -- ICAO:
05-30-12	1200 FH/24 MO MAINTENANCE PACKAGE				
	MOS	08-AUG-2014		TECH :	INSP :
	HRS	342.40			LABOR HRS :
	AFL	227		0	SERVICE REMARKS -- ICAO:
05-30-20	1800 FH MAINTENANCE PACKAGE				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0		0	SERVICE REMARKS -- ICAO:
05-30-23	1800 FH/36 MO MAINTENANCE PACKAGE				
	MOS	19-JUL-2013		TECH :	INSP :
	HRS	262.90			LABOR HRS :
	AFL	154		0	SERVICE REMARKS -- ICAO:
05-30-40	3000 FH MAINTENANCE PACKAGE				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0		0	SERVICE REMARKS -- ICAO:
05-30-41	3000 FH/48 MO MAINTENANCE PACKAGE				
	MOS	08-AUG-2014		TECH :	INSP :
	HRS	342.20			LABOR HRS :
	AFL	227		0	SERVICE REMARKS -- ICAO:
(D)05-30-43	3600 FH MAINTENANCE PACKAGE				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0		-	LABOR HRS :
UNSCHEDULED	AFL	0		0	SERVICE REMARKS -- ICAO:
05-30-46	4800 FH/72 MO MAINTENANCE PACKAGE				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0		0	SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL		
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
05-30-50	6000 FH MAINTENANCE PACKAGE	MOS HRS AFL	03-AUG-2010 0 0	TECH : 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
05-30-53	6000 FH/96 MO MAINTENANCE PACKAGE	MOS HRS AFL	03-AUG-2010 0 0	TECH : 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
05-30-60	7800 FH MAINTENANCE PACKAGE	MOS HRS AFL	03-AUG-2010 0 0	TECH : 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
05-30-66	12000 FH/120 MOS MAINTENANCE PACKAGE	MOS HRS AFL	03-AUG-2010 0 0	TECH : 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
05-30-80	12 MO MAINTENANCE PACKAGE	MOS HRS AFL	12-AUG-2015 425.50 299	TECH : 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
	SCHEDULED	MOS HRS AFL	12-AUG-2015 425.50 299	TECH : - 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
	SCHEDULED	MOS HRS AFL	12-AUG-2015 425.50 299	TECH : - 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
	SCHEDULED	MOS HRS AFL	08-AUG-2014 342.40 227	TECH : CRS KX5R005N -	INSP : CRS KX5R005N LABOR HRS : SERVICE REMARKS	ICAO: --
05-30-81	24 MO MAINTENANCE PACKAGE	MOS HRS AFL	08-AUG-2014 342.40 227	TECH : 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
05-30-83	48 MO MAINTENANCE PACKAGE	MOS HRS AFL	08-AUG-2014 342.40 227	TECH : 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
05-30-84	60 MO MAINTENANCE PACKAGE	MOS HRS AFL	12-AUG-2015 425.50 299	TECH : 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
	SCHEDULED	MOS HRS AFL	12-AUG-2015 425.50 299	TECH : - 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
	SCHEDULED	MOS HRS AFL	12-AUG-2015 425.50 299	TECH : - 0	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
05-30-85	72 MO MAINTENANCE PACKAGE		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
05-30-86	96 MO MAINTENANCE PACKAGE		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
(D)H05-01-120-001	GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS ON THE FORWARD FUSELAGE COCKPIT SECTION		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
	UNSCHEDULED	0	
			SERVICE REMARKS --
(D)H05-02-130-001	GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS ON THE CENTER FUSELAGE FRONT SECTION		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
	UNSCHEDULED	0	
			SERVICE REMARKS --
(D)H05-03-140-001	GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS/ OVERBRAIDS ON THE CENTER FUSELAGE BOTTOM REAR SECTION		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
	UNSCHEDULED	0	
			SERVICE REMARKS --
(D)H05-04-190-001	GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS ON THE CENTER FUSELAGE REAR SECTION		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
	UNSCHEDULED	0	
			SERVICE REMARKS --
(D)H05-05-210-001	GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS/ OVERBRAIDS ON THE FORWARD FUSELAGE NOSE SECTION		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
	UNSCHEDULED	0	
			SERVICE REMARKS --
(D)H05-06-240-001	GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS/ OVERBRAIDS ON THE CENTER FUSELAGE TOP REAR SECTION		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
	UNSCHEDULED	0	
			SERVICE REMARKS --
(D)H05-07-320-001	GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS ON THE AFT FUSELAGE REAR SECTION		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
	UNSCHEDULED	0	
			SERVICE REMARKS --
(D)H05-08-410-001	GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS ON THE PYLON		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
	UNSCHEDULED	0	
			SERVICE REMARKS --
H242-001	INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
H340-001	INTERNAL GENERAL VISUAL INSPECTION OF PITCH TRIM ACTUATOR ELECTRICAL BONDING		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 11 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
H430-001	INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
H700-001	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
H700-002	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
	PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
CHAPTER 21-AIR CONDITIONING									
21-21-02-001		OPERATIONAL CHECK LH AFT INLET AIR CHECK VALVE							
Part:	PN	SN-UNKNOWN	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-21-02-001		OPERATIONAL CHECK RH AFT INLET AIR CHECK VALVE							
Part:	PN	SN-UNKNOWN	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-23-03-002		OPERATIONAL CHECK OF RAM AIR VALVE POSITION							
Part:	PN	SN-UNKNOWN	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-23-03-003		OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION							
Part:	PN	SN-UNKNOWN	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-23-04-001		OPERATIONAL CHECK RH AFT FUSELAGE RAM AIR CHECK VALVE							
Part:	PN	SN-UNKNOWN	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-23-04-001		OPERATIONAL CHECK LH AFT FUSELAGE RAM AIR CHECK VALVE							
Part:	PN	SN-UNKNOWN	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-23-04-001		OPERATIONAL CHECK LH CENTER FUSELAGE RAM AIR CHECK VALVE							
Part:	PN	SN-UNKNOWN	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-23-05-001		GENERAL VISUAL INSPECTION TAIL CONE GROUND BLOWER (COOLING FAN) ASSEMBLY							
Part:	1133710-5	369	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-31-00-002		OPERATIONAL CHECK AFT BULKHEAD OUTFLOW (OFV) VALVE MANUAL PRESSURIZATION CONTROL MODE							
Part:	103920-1	103920-00146	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-31-00-003		OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)							
			MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
21-31-01-001		RESTORATION (OVERHAUL) OF ELECTRONIC CONTROL AND MONITORING UNIT							
Part:	2119286-4	2119286-00618	MOS	17-JUL-2012			TECH :	INSP :	
			HRS	194.40				LABOR HRS :	ICAO:
			AFL	112				SERVICE REMARKS	--
21-31-02-001		RESTORATION (OVERHAUL) OF AFT BULKHEAD OUTFLOW (OFV) VALVE							
Part:	103920-1	103920-00146	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 13 of 235

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
21-31-03-001	OPERATIONAL CHECK		NEGATIVE PRESSURE RELIEF VALVE			
Part: 130664-2	34163-0218	MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
21-31-04-001	FUNCTIONAL CHECK AFT BULKHEAD PRESSURE RELIEF (PRV) VALVE					
Part: 103916-2	103916-00188	MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
21-52-01-001	DETAILED VISUAL INSPECTION		VCS COMPRESSOR DRIVE MODULE OF VCS COMPRESSOR MOTOR DRIVE			
Part: 1133630-9	182	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: 1133630-9	182	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: 1133630-9	182	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
21-52-01-002	DISCARD		VCS COMPRESSOR DRIVE MODULE BELT			
Part: 1133630-9	182	MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
21-52-01-003	FUNCTIONAL CHECK		VCS COMPRESSOR DRIVE MODULE BELT TENSION			
Part: 1133630-9	182	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: 1133630-9	182	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: 1133630-9	182	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
21-52-01-004	DISCARD OF CDM COMPRESSOR MODULE					
		MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
21-52-02-001	GENERAL VISUAL INSPECTION		HEAT EXCHANGER PACK			
Part: 1133750-3	292	MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
21-52-03-001	GENERAL VISUAL INSPECTION		OF EVAPORATOR MODULES			
		MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
21-52-06-001	SERVICING OF VCS REFRIGERANT FLUID	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
	SCHEDULED	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
		AFL	299	0	ICAO:
					SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
21-61-00-001	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
21-61-06-001	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
500-21-0001	AIR CONDITIONING - REPLACEMENT OF THE FLOW CONTROL SHUTOFF VALVE (FCSOV), SERVICE BULLETIN	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-21-0001 R1	AIR CONDITIONING - REPLACEMENT OF THE FLOW CONTROL SHUTOFF VALVE (FCSOV), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-21-0002	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) TRAY REPLACEMENT, SERVICE BULLETIN	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-21-0003	AIR CONDITIONING - REPLACEMENT OF THE ECS TEMPERATURE CONTROLLER FROM PN 1300650-9 TO PN 1300650-10, SERVICE BULLETIN	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 15 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-21-0004	AIR CONDITIONING - CPCS CONTROLLER (ECMU) HARDWARE CORRECTION, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-21-0004 R1	AIR CONDITIONING - CPCS CONTROLLER (ECMU) HARDWARE CORRECTION, SERVICE BULLETIN	MOS	17-JUL-2012		
		HRS	194.40	TECH :	INSP :
		AFL	112		LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-21-0005	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) REWORK, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-21-0005 R1	COMPRESSOR DRIVE MODULE (CDM) REWORK, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-21-0005 R2	AIR CONDITIONING - COMPRESSOR DRIVE MODULE (CDM) REWORK, SERVICE BULLETIN	MOS	17-JUL-2012		
		HRS	194.40	TECH :	INSP :
		AFL	112		LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-21-0006	AIR CONDITIONING - REWORK OF FLOW CONTROL SHUT OFF VALVE (FCSOV) -15/25, SERVICE BULLETIN	MOS	17-JUL-2012		
		HRS	194.40	TECH :	INSP :
		AFL	112		LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 16 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-21-0007	AIR CONDITIONING - REPLACEMENT OF THE ECS TEMPERATURE CONTROLLER, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-21-0007 R1	AIR CONDITIONING - REPLACEMENT OF THE ECS TEMPERATURE CONTROLLER, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-21-0008	AIR CONDITIONING - GROUND COOLING FAN REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-21-0009	AIR CONDITIONING - REPLACEMENT OF THE ECS TEMPERATURE CONTROLLER, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-21-0009 R1	AIR CONDITIONING - REPLACEMENT OF THE ECS TEMPERATURE CONTROLLER, SERVICE BULLETIN	MOS HRS AFL MSC	19-JUL-2013 262.90 154	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
FAA 2010-23-16	REPLACEMENT OF BOTH FLOW CONTROL SHUTOFF VALVES, PART NUMBER (P/N) 1300230-13 AND P/N 1300230-23, WITH P/N 1300230-15 AND P/N 1300230-25	MOS HRS AFL MSC	10-APR-2015 382.70 258	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE - PER S/N					

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
CHAPTER 22-AUTO FLIGHT						
22-11-00-001	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR					
Part: 011-00878-10	71307674	MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50			LABOR HRS :
		AFL	299			ICAO:
						SERVICE REMARKS --
22-11-00-001	FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR					
Part: 011-00878-10	71307679	MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50			LABOR HRS :
		AFL	299			ICAO:
						SERVICE REMARKS --
22-11-00-001	FUNCTIONAL CHECK ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR					
Part: 011-00878-10	71307688	MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50			LABOR HRS :
		AFL	299			ICAO:
						SERVICE REMARKS --
	Part: 011-00878-10	71307688	MOS	12-AUG-2015	TECH :	INSP :
			HRS	425.50	-	LABOR HRS :
			AFL	299	0	ICAO:
						SERVICE REMARKS --
		SCHEDULED				
22-11-00-001	FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR					
Part: 011-00878-10	71307679	MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50		-	LABOR HRS :
		AFL	299		0	ICAO:
						SERVICE REMARKS --
		SCHEDULED				
22-11-00-001	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR					
Part: 011-00878-10	71307674	MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50		-	LABOR HRS :
		AFL	299		0	ICAO:
						SERVICE REMARKS --
		SCHEDULED				
22-11-00-001	FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR					
Part: 011-00878-10	71307679	MOS	08-AUG-2014		TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40		-	LABOR HRS :
		AFL	227			ICAO:
						SERVICE REMARKS --
		SCHEDULED				
22-11-00-001	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR					
Part: 011-00878-10	71307674	MOS	08-AUG-2014		TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40		-	LABOR HRS :
		AFL	227			ICAO:
						SERVICE REMARKS --
		SCHEDULED				
22-11-00-001	FUNCTIONAL CHECK ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR					
Part: 011-00878-10	71307688	MOS	08-AUG-2014		TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40		-	LABOR HRS :
		AFL	227			ICAO:
						SERVICE REMARKS --
		SCHEDULED				
22-11-00-002	LUBRICATION OF SERVO ACTUATORS					
		MOS	08-AUG-2014		TECH :	INSP :
		HRS	342.40			LABOR HRS :
		AFL	227			ICAO:
						SERVICE REMARKS --
22-11-00-003	DETAILED VISUAL INSPECTION OF AUTOPILOT SERVO CABLE					
		MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
22-11-04-001	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR CABLE					
Part: 011-00878-10	71307674	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 18 of 235

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
	PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
22-11-07-001	FUNCTIONAL CHECK ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR CABLE					
Part:	011-00878-10	71307688	MOS	12-AUG-2015	TECH :	INSP :
			HRS	425.50		LABOR HRS :
			AFL	299		ICAO:
						SERVICE REMARKS --
22-11-10-001	FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO ACTUATOR CABLE					
Part:	011-00878-10	71307679	MOS	03-AUG-2010	TECH :	INSP :
			HRS	0		LABOR HRS :
			AFL	0		ICAO:
						SERVICE REMARKS --
(D)H22-01-321-001	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE AUTOPILOT SERVOS					
			MOS	03-AUG-2010	TECH :	INSP :
			HRS	0	-	LABOR HRS :
			AFL	0		ICAO:
	UNSCHEDULED					SERVICE REMARKS --



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 19 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 23-COMMUNICATIONS					
23-51-00-001	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
23-61-00-001	FUNCTIONAL CHECK OF STATIC DISCHARGERS	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
500-23-0001	COMMUNICATIONS - VHF1 WIRING INSPECTION AND MODIFICATION, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-23-0001 PART I	PERFORM COMMUNICATIONS - VHF1 WIRING INSPECTION AND MODIFICATION, SERVICE BULLETIN WIRING INSPECTION	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-23-0001 PART II	PERFORM COMMUNICATIONS - VHF1 WIRING INSPECTION AND MODIFICATION, SERVICE BULLETIN WIRING MODIFICATION	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-23-0002	COMMUNICATIONS - ACTIVATION OF THE DATALINK MANAGEMENT SYSTEM, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-23-0003	COMMUNICATIONS - INSTALLATION OF THE DATA LINK MANAGEMENT SYSTEM (DLMS) WITHOUT HANDSET, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 20 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-23-0004	COMMUNICATIONS - REMOVAL OF THE HF AND SELCAL SYSTEMS TO COMPLY WITH TCCA REQUIREMENTS, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-23-0005	COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-23-0005 PART I	ACTIVATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION), SERVICE BULLETIN OF THE CPDLC SYSTEM	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-23-0005 PART II	INSTALLATION COMMUNICATIONS - COMPLEMENTATION AND ACTIVATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION), SERVICE BULLETIN OF THE LRUS AND ACTIVATION OF THE CPDLC SYSTEM	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-23-0006	COMMUNICATIONS - FULL INSTALLATION OF THE CPDLC (CONTROLLER-TO-PILOT DATA LINK COMMUNICATION), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.		SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
CHAPTER	24-ELECTRICAL POWER								
24-31-01	NO.1 28V, 325A -DC STARTER-GENERATOR								
Removed:	MG94F-1	434	MOS	03-AUG-2010	19-MAR-2015	TECH :	INSP :		
Installed:	MG94F-2	0737	HRS	0	366.20	REASON : UNKNOWN	LABOR HRS :		
		SCHEDULED	AFL	0	250	PRICE :	ICAO:		
24-31-01	NO.2 28V, 325A -DC STARTER-GENERATOR								
Removed:	MG94F-1	431	MOS	03-AUG-2010	19-MAR-2015	TECH :	INSP :		
Installed:	MG94F-2	0579	HRS	0	366.20	REASON : UNKNOWN	LABOR HRS :		
		SCHEDULED	AFL	0	250	PRICE :	ICAO:		
24-31-01-001	RESTORATION OF NO.1 ENGINE STARTER-GENERATOR (OVERHAUL) (FOR STARTER GENERATOR P/N MG94F-2 AND 400SG180Q)								
Part:	MG94F-2	0737	MOS	19-MAR-2015		TECH :	INSP :		
			HRS	366.20			LABOR HRS :		
			AFL	250			SERVICE REMARKS --		
24-31-01-001	RESTORATION OF NO.2 ENGINE STARTER-GENERATOR (OVERHAUL) (FOR STARTER GENERATOR P/N MG94F-2 AND 400SG180Q)								
Part:	MG94F-2	0579	MOS	19-MAR-2015		TECH :	INSP :		
			HRS	366.20			LABOR HRS :		
			AFL	250			SERVICE REMARKS --		
24-31-01-002	DETAILED INSPECTION OF NO.1 ENGINE STARTER-GENERATOR BRUSHES (FOR STARTER GENERATOR P/N MG94F-2 AND 400SG180Q)								
Part:	MG94F-2	0737	MOS	19-MAR-2015		TECH :	INSP :		
			HRS	366.20			LABOR HRS :		
			AFL	250			SERVICE REMARKS --		
24-31-01-002	DETAILED INSPECTION OF NO.2 ENGINE STARTER-GENERATOR BRUSHES (FOR STARTER GENERATOR P/N MG94F-2 AND 400SG180Q)								
Part:	MG94F-2	0579	MOS	19-MAR-2015		TECH :	INSP :		
			HRS	366.20			LABOR HRS :		
			AFL	250			SERVICE REMARKS --		
24-31-01-003	RESTORATION OF NO.1 ENGINE STARTER-GENERATOR (OVERHAUL) (FOR STARTER GENERATOR P/N MG94F-1)								
Part:	MG94F-2	0737	MOS	19-MAR-2015		TECH :	INSP :		
			HRS	366.20			LABOR HRS :		
			AFL	250			SERVICE REMARKS --		
			MSC		MSC				
24-31-01-003	RESTORATION OF NO.2 ENGINE STARTER-GENERATOR (OVERHAUL) (FOR STARTER GENERATOR P/N MG94F-1)								
Part:	MG94F-2	0579	MOS	19-MAR-2015		TECH :	INSP :		
			HRS	366.20			LABOR HRS :		
			AFL	250			SERVICE REMARKS --		
			MSC		MSC				
24-31-01-004	DETAILED INSPECTION OF NO.1 ENGINE STARTER-GENERATOR BRUSHES (FOR STARTER GENERATOR P/N MG94F-1)								
Part:	MG94F-2	0737	MOS	19-MAR-2015		TECH :	INSP :		
			HRS	366.20			LABOR HRS :		
			AFL	250			SERVICE REMARKS --		
			MSC		MSC				
24-31-01-004	DETAILED INSPECTION OF NO.2 ENGINE STARTER-GENERATOR BRUSHES (FOR STARTER GENERATOR P/N MG94F-1)								
Part:	MG94F-2	0579	MOS	19-MAR-2015		TECH :	INSP :		
			HRS	366.20			LABOR HRS :		
			AFL	250			SERVICE REMARKS --		
			MSC		MSC				
24-31-01-004	DETAILED INSPECTION OF NO.1 28V, 325A -DC STARTER-GENERATOR BRUSHES								
Part:	MG94F-1	434	MOS	19-MAR-2010		TECH :	INSP :		
			HRS	366.20	TIME ACCRUED:	-	LABOR HRS :		
		SCHEDULED	AFL	250		TSN:60	SERVICE REMARKS --		

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.		C/W	TIME SINCE	C/W	TIME SINCE			
24-36-01-001	FUNCTIONAL CHECK NO.2 MAIN BATTERY NOTE: INTERVAL BASED ON INSTALLATION DATE								
Part: 7639-27	G-02778070	MOS	12-AUG-2015				TECH :	INSP :	
		HRS	425.50				-	LABOR HRS :	ICAO:
	SCHEDULED	AFL	299				0	SERVICE REMARKS	--
24-36-01-001	FUNCTIONAL CHECK NO.1 MAIN BATTERY NOTE: INTERVAL BASED ON INSTALLATION DATE								
Part: 7639-27	G-02778067	MOS	12-AUG-2015				TECH :	INSP :	
		HRS	425.50				-	LABOR HRS :	ICAO:
	SCHEDULED	AFL	299				0	SERVICE REMARKS	--
24-36-01-001	FUNCTIONAL CHECK NO.2 MAIN BATTERY NOTE: INTERVAL BASED ON INSTALLATION DATE								
Part: 7639-27	G-02778070	MOS	08-AUG-2014				TECH : CRS KX5R005N	INSP : CRS KX5R005N	
		HRS	342.40				-	LABOR HRS :	ICAO:
	SCHEDULED	AFL	227					SERVICE REMARKS	--
24-36-01-001	FUNCTIONAL CHECK NO.1 MAIN BATTERY NOTE: INTERVAL BASED ON INSTALLATION DATE								
Part: 7639-27	G-02778067	MOS	08-AUG-2014				TECH : CRS KX5R005N	INSP : CRS KX5R005N	
		HRS	342.40				-	LABOR HRS :	ICAO:
	SCHEDULED	AFL	227					SERVICE REMARKS	--
24-36-01-003	DISCARD NO.1 MAIN BATTERY								
Part: 7639-27	G-02778067	MOS					TECH :	INSP :	
		HRS						LABOR HRS :	ICAO:
		AFL						SERVICE REMARKS	--
24-36-01-003	DISCARD NO.2 MAIN BATTERY								
Part: 7639-27	G-02778070	MOS					TECH :	INSP :	
		HRS						LABOR HRS :	ICAO:
		AFL						SERVICE REMARKS	--
24-36-01-004	FUNCTIONAL CHECK NO.1 MAIN BATTERY - (PRE-MOD SB 500-24-0014)								
Part: 7639-27	G-02778067	MOS	12-AUG-2015				TECH :	INSP :	
		HRS	425.50					LABOR HRS :	ICAO:
		AFL	299					SERVICE REMARKS	--
24-36-01-004	FUNCTIONAL CHECK NO.2 MAIN BATTERY - (PRE-MOD SB 500-24-0014)								
Part: 7639-27	G-02778070	MOS	12-AUG-2015				TECH :	INSP :	
		HRS	425.50					LABOR HRS :	ICAO:
		AFL	299					SERVICE REMARKS	--
24-36-01-005	FUNCTIONAL CHECK OF NO.2 MAIN BATTERY - (POS-MOD SB 500-24-0014)								
Part: 7639-27	G-02778070	MOS	03-AUG-2010				TECH :	INSP :	
		HRS	0					LABOR HRS :	ICAO:
		AFL	0					SERVICE REMARKS	--
		MSC				MSC			
24-36-01-005	FUNCTIONAL CHECK OF NO.1 MAIN BATTERY - (POS-MOD SB 500-24-0014)								
Part: 7639-27	G-02778067	MOS	03-AUG-2010				TECH :	INSP :	
		HRS	0					LABOR HRS :	ICAO:
		AFL	0					SERVICE REMARKS	--
		MSC				MSC			
24-36-02-001	OPERATIONAL CHECK BATTERY CURRENT (HB2) SENSOR								
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010				TECH :	INSP :	
		HRS	0					LABOR HRS :	ICAO:
		AFL	0					SERVICE REMARKS	--



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 23 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-24-0002	ELECTRICAL POWER - PROTECTION TO PREVENT INTERFERENCES WITH HARNESS W101 IN THE FORWARD REGION, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
500-24-0002 PART I	PERFORM ELECTRICAL POWER - PROTECTION TO PREVENT INTERFERENCES WITH HARNESS W101 IN THE FORWARD REGION, SERVICE BULLETIN INSTALLATION OF CLAMPS TO HARNESS W101 AND OXYGEN TUBE (GROUP 1)	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-24-0002 PART II	PERFORM ELECTRICAL POWER - PROTECTION TO PREVENT INTERFERENCES WITH HARNESS W101 IN THE FORWARD REGION, SERVICE BULLETIN INSTALLATION OF CLAMPS TO HARNESS W101 (GROUPS 1 E 2)	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-24-0003	ELECTRICAL POWER - PDU CONTACTORS INSPECTION AND REPLACEMENT (THIS SB WAS SUPERSEDED BY SB500-24-0010 R2), SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-24-0004	ELECTRICAL POWER - PROTECTION TO PREVENT INTERFERENCE BETWEEN HARNESS W201 AND THE OXYGEN TUBE, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
500-24-0005	ELECTRICAL POWER - SPACER INSTALLATION FOR HARNESSES W314 AND W601, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 24 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-24-0006	ELECTRICAL POWER - PYLON CONNECTOR - MISSING SCREWS, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								
500-24-0006 R1	ELECTRICAL POWER - PYLON CONNECTOR - MISSING SCREWS, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								
500-24-0006 R2	ELECTRICAL POWER - PYLON CONNECTOR - MISSING SCREWS, SERVICE BULLETIN	MOS	25-JUL-2011			TECH :	INSP :	ICAO:
		HRS	137.20				LABOR HRS :	
		AFL	68				SERVICE REMARKS	--
		MSC		MSC				
MOC:COMPLIED WITH								
500-24-0007	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								
500-24-0007 PART I	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, SERVICE BULLETIN OF THE STARTER GENERATOR PN MG94F-1 WITH OTHER NEW STARTER GENERATOR PN MG94F-2	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								
500-24-0007 PART II	INSPECTION ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, SERVICE BULLETIN OF THE CLAMP PN MS21919WCH6 INSTALLATION	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 25 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-24-0007 R1	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, SERVICE BULLETIN	MOS HRS AFL MSC	19-MAR-2015 366.20 250	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-24-0007 R1 PART I	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, SERVICE BULLETIN OF THE STARTER GENERATOR PN MG94F-1 WITH OTHER NEW STARTER GENERATOR PN MG94F-2	MOS HRS AFL MSC	19-MAR-2015 366.20 250	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-24-0007 R1 PART II	INSPECTION ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, SERVICE BULLETIN OF THE CLAMP PN MS21919WCH6 INSTALLATION	MOS HRS AFL MSC	19-MAR-2015 366.20 250	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-24-0008	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS (THIS SB WAS SUPERSEDED BY SB500-24-0010 R2), SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-24-0008 PART I	ELECTRICAL POWER ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS (THIS SB WAS SUPERSEDED BY SB500-24-0010 R2), SERVICE BULLETIN REPLACEMENT OF THE CONTACTORS PN SM400D117 IN THE LPDU	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 26 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-24-0008 PART II	ELECTRICAL POWER REPLACEMENT OF THE CONTACTORS PN SM400D117 IN THE RPDU	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS (THIS SB WAS SUPERSEDED BY SB500-24-0010 R2), SERVICE BULLETIN						
		MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-24-0008 PART III	ELECTRICAL POWER REPLACEMENT OF THE CONTACTORS PN SM400D117 IN THE EPDU	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU CONTACTORS (THIS SB WAS SUPERSEDED BY SB500-24-0010 R2), SERVICE BULLETIN						
		MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-24-0009	ELECTRICAL POWER - MODIFICATION OF THE EMERGENCY BUS CONTACTOR (EBC) 1 GROUND WIRE, SERVICE BULLETIN							
		MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-24-0009 R1	ELECTRICAL POWER - MODIFICATION OF THE EMERGENCY BUS CONTACTOR (EBC) 1 GROUND WIRE, SERVICE BULLETIN							
		MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-24-0010	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN							
		MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-24-0010 PART I	REPLACEMENT SX7EG16-1A.	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN - OF THE LEFT POWER DISTRIBUTION UNIT (LPDU) PN SX7EG16-1 OR						
		MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 27 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-24-0010 PART II	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN SX7EG17-1A.				OF THE RIGHT POWER DISTRIBUTION UNIT (RPDU) PN SX7EG17-1 OR
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-24-0010 PART III	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN SX7EG18-1A.				OF THE EMERGENCY POWER DISTRIBUTION UNIT (EPDU) PN SX7EG18-1 OR
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-24-0010 R1	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-24-0010 R1 PART I	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN				OF THE LEFT POWER DISTRIBUTION UNIT (LPDU)
		MOS	19-JUL-2013	TECH :	INSP :
		HRS	262.90		LABOR HRS :
		AFL	154		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH					
500-24-0010 R1 PART II	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN				OF THE RIGHT POWER DISTRIBUTION UNIT (RPDU)
		MOS	19-JUL-2013	TECH :	INSP :
		HRS	262.90		LABOR HRS :
		AFL	154		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH					
500-24-0010 R1 PART III	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN				OF THE EMERGENCY POWER DISTRIBUTION UNIT (EPDU)
		MOS	19-JUL-2013	TECH :	INSP :
		HRS	262.90		LABOR HRS :
		AFL	154		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 28 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-24-0010 R2	ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-24-0010 R2 PART I	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN OF THE LEFT POWER DISTRIBUTION UNIT (LPDU)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-24-0010 R2 PART II	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN OF THE RIGHT POWER DISTRIBUTION UNIT (RPDU)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-24-0010 R2 PART III	REPLACEMENT ELECTRICAL POWER - REPLACEMENT OF THE LPDU, RPDU AND EPDU, SERVICE BULLETIN OF THE EMERGENCY POWER DISTRIBUTION UNIT (EPDU)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-24-0011	ELECTRICAL POWER - RE-ROUTE OF THE W102 IN THE PASSENGER CABIN, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-24-0012	ELECTRICAL POWER - INSPECTION/REPAIR OF THE HARNESS W201 WITH MAIN PANEL STRUCTURE, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 29 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL		
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-24-0013	ELECTRICAL POWER - INSTALLATION OF BRACKET TO REMOVE CHAFING BETWEEN W207 AND PEDAL MECHANISM, SERVICE BULLETIN	MOS HRS AFL MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC		
MOC:					
500-24-0014	ELECTRICAL POWER - MAIN BATTERY REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC		
MOC:					
500-24-0015	ELECTRICAL POWER - GCU (GENERATOR CONTROL UNIT) REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC		
MOC:					
500-24-0015 PART I	REPLACEMENT ELECTRICAL POWER - GCU (GENERATOR CONTROL UNIT) REPLACEMENT, SERVICE BULLETIN OF THE GCU PN CG301A-10 WITH PN CG301A-12	MOS HRS AFL MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC		
MOC:					
500-24-0015 PART II	REPLACEMENT ELECTRICAL POWER - GCU (GENERATOR CONTROL UNIT) REPLACEMENT, SERVICE BULLETIN OF THE GCU PN CG301A-11 WITH PN CG301A-12	MOS HRS AFL MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC		
MOC:					
500-24-A007	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, ALERT SERVICE BULLETIN	MOS HRS AFL MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC		
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 30 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-24-A007 PART I	REPLACEMENT	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, ALERT SERVICE BULLETIN	OF LEFT-HAND (LH) STARTER GENERATOR
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-24-A007 PART II	REPLACEMENT	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, ALERT SERVICE BULLETIN	OF RIGHT-HAND (RH) STARTER GENERATOR
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-24-A007 R1		ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, ALERT SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-24-A007 R1 PART I	REPLACEMENT	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, ALERT SERVICE BULLETIN	OF LEFT-HAND (LH) STARTER GENERATOR
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-24-A007 R1 PART II	REPLACEMENT	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS, ALERT SERVICE BULLETIN	OF RIGHT-HAND (RH) STARTER GENERATOR
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-24-A007 R2		ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS (SUPERSEDED BY SB 500-24-0007 R1), ALERT SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 31 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-24-A007 R2 PART I	REPLACEMENT GENERATOR	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS (SUPERSEDED BY SB 500-24-0007 R1), ALERT SERVICE BULLETIN		LEFT-HAND (LH) STARTER	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-24-A007 R2 PART II	REPLACEMENT GENERATOR	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS (SUPERSEDED BY SB 500-24-0007 R1), ALERT SERVICE BULLETIN		RIGHT-HAND (RH) STARTER	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-24-A007 R2 PART III	INSPECTION	ELECTRICAL POWER - REPLACEMENT OF THE STARTER GENERATORS (SUPERSEDED BY SB 500-24-0007 R1), ALERT SERVICE BULLETIN		CLAMP PN MS21919WCH6	
	INSTALLATION ON THE LH ENGINE FUEL SYSTEM				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
(D)H24-01-240-001	GENERAL VISUAL INSPECTION	OF THE L/HIRF PROTECTION ON THE GCUS			
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H24-02-433-001	DETAILED VISUAL INSPECTION	OF THE L/HIRF PROTECTION ON THE GENERATORS			
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
	PART NO.	SERIAL NO.		C/W	TIME SINCE		C/W	TIME SINCE	
CHAPTER	25-EQUIPMENT/FURNISHINGS								
25-11-01-001	DETAILED VISUAL INSPECTION COPILOT CITRINE FINISH GOODRICH SEAT								
Part:	1429-621AK	999-1429	MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-11-01-001	DETAILED VISUAL INSPECTION PILOT CITRINE FINISH GOODRICH SEAT								
Part:	1429-521AK	998-1429	MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-11-01-002	DETAILED VISUAL INSPECTION OF COCKPIT SEAT BELTS								
			MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-21-01-001	DETAILED VISUAL INSPECTION LH AFT PAX SEAT								
Part:	403176-4AB	47715	MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-21-01-001	DETAILED VISUAL INSPECTION RH AFT PAX SEAT								
Part:	403176-1ABR	47681	MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-21-01-001	DETAILED VISUAL INSPECTION LH FWD PAX SEAT								
Part:	403176-3AB	47683	MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-21-01-001	DETAILED VISUAL INSPECTION RH FWD PAX SEAT								
Part:	403176-2ABR	47682	MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-21-01-002	DETAILED VISUAL INSPECTION OF PASSENGER SEAT BELTS								
			MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-21-03-001	DETAILED INSPECTION OF FIFTH SEAT (NOTE: AIRCRAFT WITH FIFTH SEAT INSTALLED.)								
			MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-21-03-002	DETAILED INSPECTION OF THE FIFTH SEAT BELT (NOTE:AIRCRAFT WITH FIFTH SEAT INSTALLED.)								
			MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-43-01-001	DETAILED VISUAL INSPECTION OF BELTED TOILET UNIT (NOTE: AIRCRAFT WITH BELTED TOILET UNIT INSTALLED)								
			MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
25-43-01-002	DETAILED VISUAL INSPECTION OF BELTED TOILET SEAT BELT (NOTE: AIRCRAFT WITH BELTED TOILET UNIT INSTALLED)								
			MOS HRS AFL	08-AUG-2014	342.40 227	TECH :		INSP : LABOR HRS : SERVICE REMARKS	ICAO: --

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 33 of 235

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER SYSTEM					
Part: S1821502-02	2622156-0043	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: S1821502-02	2622156-0043	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
Part: S1821502-02	2622156-0043	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
25-61-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER					
Part: S1821502-02	2622156-0043	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY					
Part: S1820506-01	SN-UNKNOWN	MOS				TECH :
		HRS				INSP :
		AFL				LABOR HRS :
		MSC		MSC		ICAO:
						SERVICE REMARKS --
25-62-01-001	VISUAL CHECK FIRST AID KIT					
Part: PLA-005	NSN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: PLA-005	NSN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
Part: PLA-005	NSN	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
25-62-02-003	DISCARD OF NO.4 PAX LIFE VEST (NOTE: FROM THE MANUFACTURING DATE)					
Part: 66601-105	L1398925	MOS	01-MAR-2010			TECH :
		HRS				INSP :
		AFL				LABOR HRS :
						ICAO:
						SERVICE REMARKS --
25-62-02-003	DISCARD OF NO.3 PAX LIFE VEST (NOTE: FROM THE MANUFACTURING DATE)					
Part: 66601-105	L1398922	MOS	01-MAR-2010			TECH :
		HRS				INSP :
		AFL				LABOR HRS :
						ICAO:
						SERVICE REMARKS --
25-62-02-003	DISCARD OF NO.2 PAX LIFE VEST (NOTE: FROM THE MANUFACTURING DATE)					
Part: 66601-105	L1398926	MOS	01-MAR-2010			TECH :
		HRS				INSP :
		AFL				LABOR HRS :
						ICAO:
						SERVICE REMARKS --
25-62-02-003	DISCARD OF NO.1 PAX LIFE VEST (NOTE: FROM THE MANUFACTURING DATE)					
Part: 66601-105	L1398923	MOS	01-MAR-2010			TECH :
		HRS				INSP :
		AFL				LABOR HRS :
						ICAO:
						SERVICE REMARKS --
25-62-02-003	DISCARD OF COPILOT CREW LIFE VEST (NOTE: FROM THE MANUFACTURING DATE)					
Part: 66601-505	L1396419	MOS	01-MAR-2010			TECH :
		HRS				INSP :
		AFL				LABOR HRS :
						ICAO:
						SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 34 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
25-62-02-003	DISCARD OF PILOT CREW LIFE VEST (NOTE: FROM THE MANUFACTURING DATE)				
Part: 66601-505	L1396418	MOS	01-MAR-2010	TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
25-62-02-003	DISCARD OF NO.5 PAX LIFE VEST (NOTE: FROM THE MANUFACTURING DATE)				
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		SERVICE REMARKS -- ICAO:
25-62-04-001	DETAILED DIMENSIONAL INSPECTION LAV WATER BARRIER				
Part: PN	SN-UNKNOWN	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:
500-25-0001	EQUIPMENT/FURNISHINGS - EMERGENCY-DOOR WATER-D RIP PREVENTION, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-25-0001 REV 01	EQUIPMENT/FURNISHINGS - EMERGENCY-DOOR WATER-D RIP PREVENTION, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-25-0003	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE PASSENGER SEATS, SERVICE BULLETIN				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH - AT MANUFACTURE					
500-25-0004	EQUIPMENT/FURNISHINGS - INTERIOR CONFIGURATION CONVERSION FROM CITRINE TO TOPAZ PATTERN, SERVICE BULLETIN				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 35 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-25-0005	EQUIPMENT/FURNISHINGS - COCKPIT SUNSHADE AND SUNVISOR INSTALLATION, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS --
		MSC		MSC	ICAO:
MOC:NOT APPLICABLE					
500-25-0006	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS --
		MSC		MSC	ICAO:
MOC:					
500-25-0006 PART I	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND DECAL INSTALLATION FOR S/N 50000007	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS --
		MSC		MSC	ICAO:
MOC:					
500-25-0006 PART II	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR, DECAL AND SUBWOOFER INSTALLATION FOR S/N 50000120	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS --
		MSC		MSC	ICAO:
MOC:					
500-25-0006 PART III	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND DECAL INSTALLATION FOR S/N 50000096	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS --
		MSC		MSC	ICAO:
MOC:					
500-25-0006 PART IV	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR, DECAL AND SUBWOOFER INSTALLATION FOR S/N 50000088	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS --
		MSC		MSC	ICAO:
MOC:					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 36 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-25-0006 R5	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R5 PART I	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000007	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R5 PART II	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE AND DADO PANEL, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION FOR S/N 50000120	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R5 PART III	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000096, 50000227, AND 50000234	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R5 PART IV	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE AND DADO PANEL, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION FOR S/N 50000088 AND 50000136	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R5 PART V	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000169 AND 50000188	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 37 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0006 R6	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0006 R6 PART I	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000007	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0006 R6 PART II	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE AND DADO PANEL, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION FOR S/N 50000120	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0006 R6 PART III	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000096, 50000227 AND 50000234	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0006 R6 PART IV	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDEEDGE AND DADO PANEL, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION FOR S/N 50000088 AND 50000136	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 38 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0006 R6 PART V	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000169 AND 50000188	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 R7	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 R7 PART I	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN RIGID DOOR AND PLACARD INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 R7 PART II	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN RIGID DOOR AND SUBWOOFER BOX INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 R7 PART III	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN RIGID DOOR AND PLACARD INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 R7 PART IV	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN RIGID DOOR AND SUBWOOFER BOX INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 39 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-25-0006 R7 PART V	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN PLACARD INSTALLATION				REWORK OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R8	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R8 PART I	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN RIGID DOOR AND PLACARD INSTALLATION				OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R8 PART II	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN PLACARD AND SUBWOOFER BOX INSTALLATION				OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR,
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R8 PART III	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN PLACARD INSTALLATION				OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0006 R8 PART IV	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN PLACARD AND SUBWOOFER BOX INSTALLATION				OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR,
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 40 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0006 R8 PART V	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 02	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 02 PART I	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND DECAL INSTALLATION FOR S/N 50000007	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 02 PART II	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND DECAL INSTALLATION FOR S/N 50000120	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 02 PART III	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND DECAL INSTALLATION FOR S/N 50000096	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 41 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0006 REV 02 PART IV	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND DECAL INSTALLATION FOR S/N 50000088	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 02 PART V	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND DECAL INSTALLATION FOR S/N 50000169,50000188	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 1	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 1 PART I	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN SIDELEDGE, DADO PANEL AND FLOOR PANEL REWORK, LAVATORY RIGID DOOR AND PLACARD INSTALLATION S/N: 50000007	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-25-0006 REV 1 PART II	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN SIDELEDGE AND DADO PANEL REWORK, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION S/N: 50000120	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 42 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-25-0006 REV 1 PART III	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN SIDELEDGE AND DADO PANEL REWORK, LAVATORY RIGID DOOR AND PLACARD INSTALLATION S/N: 50000096	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-25-0006 REV 1 PART IV	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN SIDELEDGE AND DADO PANEL REWORK, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION S/N: 50000088	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-25-0006 REV 1 PART V	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN SIDELEDGE AND DADO PANEL , LAVATORY RIGID DOOR AND PLACARD INSTALLATION S/N: 50000188	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-25-0006 REV 3	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-25-0006 REV 3 PART I	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000007	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 43 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0006 REV 3 PART II	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION FOR S/N 50000120	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 3 PART III	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000096 AND 50000234	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 3 PART IV	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION FOR S/N 50000088	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 3 PART V	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000169 AND 50000188	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 4	EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 4 PART I	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE, DADO PANEL AND FLOOR PANEL, LAVATORY RIDGE DOOR AND PLACARD INSTALLATION FOR S/N 50000007	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 44 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0006 REV 4 PART II	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION FOR S/N 500000120	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 4 PART III	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000096 AND 50000234	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 4 PART IV	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEDGE AND DADO PANEL, LAVATORY RIDGE DOOR, PLACARD AND SUBWOOFER BOX INSTALLATION FOR S/N 50000088	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0006 REV 4 PART V	REWORK EQUIPMENT/FURNISHINGS - REPLACEMENT OF THE LAVATORY DIVIDER WITH RIGID DOOR, SERVICE BULLETIN OF SIDELEGE AND DADO PANEL, LAVATORY RIGID DOOR AND PLACARD INSTALLATION FOR S/N 50000169 AND 50000188	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0007	EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-25-0007 PART I	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 45 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0007 PART II	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-25-0007 R1	EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN		
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-25-0007 R1 PART I	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R1 PART II	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R2	EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN		
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R2 PART I	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 46 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0007 R2 PART II	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R3	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R3 PART I	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R3 PART II	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R5	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R5 PART I	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 47 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0007 R5 PART II	ACCOMPLISH	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R6		EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R6 PART I	AIRCRAFT	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	EQUIPPED WITH LAVATORY RIGID DOOR (LRD)
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R6 PART II	AIRCRAFT	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	EQUIPPED WITH LAVATORY CURTAIN
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R7		EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-25-0007 R7 PART I	AIRCRAFT	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	EQUIPPED WITH LAVATORY RIGID DOOR (LRD)
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 48 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL		
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-25-0007 R7 PART II	AIRCRAFT	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	EQUIPPED WITH LAVATORY CURTAIN		
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC	MSC		SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0007 R7 PART III	ADDITIONAL ACTION	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	- INSTALLATION OF PLACARDS FOR AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)		
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC	MSC		SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0007 R7 PART IV	ADDITIONAL ACTION	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	- INSTALLATION OF PLACARDS FOR AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN		
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC	MSC		SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0007 R8		EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN			
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC	MSC		SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0007 R8 PART I	AIRCRAFT	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	EQUIPPED WITH LAVATORY RIGID DOOR (LRD)		
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC	MSC		SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0007 R8 PART II	AIRCRAFT	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	EQUIPPED WITH LAVATORY CURTAIN		
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC	MSC		SERVICE REMARKS --
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 49 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0007 R8 PART III	ADDITIONAL ACTION EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN - INSTALLATION OF PLACARDS FOR AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0007 R8 PART IV	ADDITIONAL ACTION EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN - INSTALLATION OF PLACARDS FOR AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0007 REV 4	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0007 REV 4 PART I	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0007 REV 4 PART II	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0008	EQUIPMENT/FURNISHINGS - SIDE FACING SEAT INSTALLATION (FIFTH SEAT INSTALLATION), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 50 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0008 R1	EQUIPMENT/FURNISHINGS - SIDE FACING SEAT INSTALLATION (FIFTH SEAT INSTALLATION), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0008 R2	EQUIPMENT/FURNISHINGS - SIDE FACING SEAT INSTALLATION (FIFTH SEAT INSTALLATION), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0008 R2 PART I	EQUIPMENT/FURNISHINGS - SIDE FACING SEAT INSTALLATION (FIFTH SEAT INSTALLATION), SERVICE BULLETIN FIFTH SEAT INSTALLATION TO AIRCRAFT WITHOUT IFE SYSTEM	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0008 R2 PART II	EQUIPMENT/FURNISHINGS - SIDE FACING SEAT INSTALLATION (FIFTH SEAT INSTALLATION), SERVICE BULLETIN FIFTH SEAT INSTALLATION TO AIRCRAFT WITH IFE SYSTEM	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0009	EQUIPMENT/FURNISHINGS - PLACARD INSTALLATION TO THE ELT REMOTE CONTROL PANEL, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0010	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 51 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0010 R1	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R1 PART I	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R1 PART II	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R2	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R2 PART A	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R2 PART B	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 52 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0010 R3	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R3 PART I	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R3 PART II	ACCOMPLISH EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R3 PART III	ADDITIONAL ACTION EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN INSTALLATION OF PLACARDS FOR AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R3 PART IV	ADDITIONAL ACTION EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN INSTALLATION OF PLACARD FOR AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-25-0010 R4	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 53 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0010 R4 PART I	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY RIGID DOOR (LRD)	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		ICAO:
	MSC	MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE			
500-25-0010 R4 PART II	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	AIRCRAFT EQUIPPED WITH LAVATORY CURTAIN	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		ICAO:
	MSC	MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE			
500-25-0010 R4 PART III	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	ADDITIONAL ACTION - INSTALLATION OF PLACARDS FOR AIRCRAFT	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		ICAO:
	MSC	MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE			
500-25-0010 R4 PART IV	EQUIPMENT/FURNISHINGS - BELTED TOILET INSTALLATION FOR PROVISIONED AIRCRAFT, SERVICE BULLETIN	ADDITIONAL ACTION - INSTALLATION OF PLACARDS FOR AIRCRAFT	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		ICAO:
	MSC	MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE			
500-25-0012	EQUIPMENT/FURNISHINGS - PREMIUM SEAT INSTALLATION, SERVICE BULLETIN		
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		ICAO:
	MSC	MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE			
500-25-0012 R1	EQUIPMENT/FURNISHINGS - PREMIUM SEAT INSTALLATION, SERVICE BULLETIN		
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		ICAO:
	MSC	MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 54 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-25-0012 R2	EQUIPMENT/FURNISHINGS - PREMIUM SEAT INSTALLATION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0012 R3	EQUIPMENT/FURNISHINGS - PREMIUM SEAT INSTALLATION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0013	EQUIPMENT/FURNISHINGS - AIRCRAFT SN 329 INTERIOR FURNISHING RECONFIGURATION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0014	EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0014 PART I	INSTALLATION EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN - FIFTH SEAT	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-25-0014 PART II	REMOVE EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN - IFE SYSTEM	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 55 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-25-0014 R1	EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0014 R1 PART I	INSTALLATION EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN - FIFTH SEAT	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0014 R1 PART II	REMOVE EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN - IFE SYSTEM	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0014 R2	EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0014 R2 PART I	INSTALLATION EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN - FIFTH SEAT	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0014 R2 PART II	REMOVE EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) INSTALLATION FOR AIRCRAFT WITH STRUCTURAL PROVISION, SERVICE BULLETIN - IFE SYSTEM	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 56 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-25-0014 R2 PART III	REROUTE EQUIPMENT/FURNISHINGS - SINGLE SIDE FACING SEAT (FIFTH SEAT) HARNESS (W201)				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0016	EQUIPMENT/FURNISHINGS - SEATS INSTALLATION FITTINGS INSPECTION, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0016 PART I	INSPECTION EQUIPMENT/FURNISHINGS - SEATS INSTALLATION FITTINGS INSPECTION, SERVICE BULLETIN OF FLOOR FITTINGS				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-25-0016 PART II	REPOSITION EQUIPMENT/FURNISHINGS - SEATS INSTALLATION FITTINGS INSPECTION, SERVICE BULLETIN OF FLOOR FITTING				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
FAA 1974-08-09 R3	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION				
		MOS	19-JUL-2013	TECH :	INSP :
		HRS	262.90		LABOR HRS :
		AFL	154		ICAO:
					SERVICE REMARKS --
MOC:COMPLIED WITH					
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE - FOUND TO BE N/A BY MFG OF SEATS CURRENTLY INSTALLED.					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 57 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
FAA 2015-10-02 (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2	MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS : ICAO:
		AFL	299		SERVICE REMARKS --
		MSC		MSC	
MOC:NOT APPLICABLE - FOUND TO BE N/A BY MFG OF SEATS CURRENTLY INSTALLED.					
FAA 2015-10-02 (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK	MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS : ICAO:
		AFL	299		SERVICE REMARKS --
		MSC		MSC	
MOC:NOT APPLICABLE - FOUND TO BE N/A BY MFG OF SEATS CURRENTLY INSTALLED.					
FAA 2015-10-02 (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS	MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS : ICAO:
		AFL	299		SERVICE REMARKS --
		MSC		MSC	
MOC:NOT APPLICABLE - FOUND TO BE N/A BY MFG OF SEATS CURRENTLY INSTALLED.					

TASK NO	DESCRIPTION			COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL			
PART NO.		SERIAL NO.		C/W	TIME SINCE	C/W	TIME SINCE		
CHAPTER 26-FIRE PROTECTION									
26-11-01-001 DETAILED VISUAL INSPECTION RH ENGINE FIRE DETECTOR									
Part:		3951-49-565/211C-3.7M	42804	MOS	03-AUG-2010	TECH :		INSP :	
				HRS	0			LABOR HRS :	ICAO:
				AFL	0			SERVICE REMARKS	--
26-11-01-001 DETAILED VISUAL INSPECTION LH ENGINE FIRE DETECTOR									
Part:		3951-49-565/211C-3.7M	42761	MOS	03-AUG-2010	TECH :		INSP :	
				HRS	0			LABOR HRS :	ICAO:
				AFL	0			SERVICE REMARKS	--
26-11-01-002 OPERATIONAL CHECK LH ENGINE FIRE DETECTOR									
Part:		3951-49-565/211C-3.7M	42761	MOS	03-AUG-2010	TECH :		INSP :	
				HRS	0			LABOR HRS :	ICAO:
				AFL	0			SERVICE REMARKS	--
26-11-01-002 OPERATIONAL CHECK RH ENGINE FIRE DETECTOR									
Part:		3951-49-565/211C-3.7M	42804	MOS	03-AUG-2010	TECH :		INSP :	
				HRS	0			LABOR HRS :	ICAO:
				AFL	0			SERVICE REMARKS	--
26-21-01-001 FUNCTIONAL CHECK FIRE/ENGINE START STOP/IGNITION/TRIM CONTROL PANEL FIREX PANEL/SYSTEM									
Part:		441-42702-002	0180	MOS	03-AUG-2010	TECH :		INSP :	
				HRS	0			LABOR HRS :	ICAO:
				AFL	0			SERVICE REMARKS	--
26-21-03-001 HYDROSTATIC TEST ENGINE FIRE EXTINGUISHING BOTTLE									
Part:		33000073-4	56405A1	MOS	01-APR-2010	TECH :		INSP :	
				HRS				LABOR HRS :	ICAO:
				AFL				SERVICE REMARKS	--
26-21-05-001 OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)									
				MOS	03-AUG-2010	TECH :		INSP :	
				HRS	0			LABOR HRS :	ICAO:
				AFL	0			SERVICE REMARKS	--
26-21-07-001 DISCARD LEFT ENG FIREX CARTRIDGE									
Part:		30903962-1	0635LD	MOS	01-APR-2010	TECH :		INSP :	
				HRS				LABOR HRS :	ICAO:
				AFL				SERVICE REMARKS	--
26-21-07-001 DISCARD RIGHT ENG FIREX CARTRIDGE									
Part:		30903962-1	0899LC	MOS	01-APR-2010	TECH :		INSP :	
				HRS				LABOR HRS :	ICAO:
				AFL				SERVICE REMARKS	--
26-21-09-001 DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING									
				MOS	03-AUG-2010	TECH :		INSP :	
				HRS	0			LABOR HRS :	ICAO:
				AFL	0			SERVICE REMARKS	--
26-24-01 COCKPIT PORTABLE EXTINGUISHER									
Removed:	RT-A1200	W-760487	MOS	03-AUG-2010	TSN:0	12-AUG-2015	TSN:60	TECH :	INSP :
Installed:	RT-A1200	W-760487	HRS	0	TSN:0	425.50	TSN:425.5	REASON : SERVICE	LABOR HRS :
	SCHEDULED		AFL	0	TSN:0	299	TSN:299	PRICE :	ICAO:

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH				COMPONENT TIMES AFTER REMOVAL			
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE				
26-24-01-001	WEIGHT CHECK COCKPIT PORTABLE EXTINGUISHER								
Part: RT-A1200	W-760487	MOS	12-AUG-2015			TECH :	INSP :	LABOR HRS :	ICAO:
		AFL						SERVICE REMARKS	--
Part: RT-A1200	W-760487	MOS	12-AUG-2015			TECH :	INSP :	LABOR HRS :	ICAO:
	SCHEDULED	AFL				-		SERVICE REMARKS	--
Part: RT-A1200	W-760487	MOS	12-AUG-2015			TECH :	INSP :	LABOR HRS :	ICAO:
	SCHEDULED	AFL				-		SERVICE REMARKS	--
Part: RT-A1200	W-760487	MOS	08-AUG-2014			TECH : CRS KX5R005N	INSP : CRS KX5R005N	LABOR HRS :	ICAO:
	SCHEDULED	AFL	342.40	TIME ACCRUED:		-		SERVICE REMARKS	--
			227		TSN:12				
26-24-01-002	DISCARD COCKPIT PORTABLE EXTINGUISHER P/N RTA1200								
Part: RT-A1200	W-760487	MOS	01-DEC-2008			TECH :	INSP :	LABOR HRS :	ICAO:
		AFL						SERVICE REMARKS	--
(D)26-24-01-003	DISCARD COCKPIT PORTABLE EXTINGUISHER P/N BA51015G-3 OR BA51015-5								
Part: RT-A1200	W-760487	MOS	03-AUG-2010			TECH :	INSP :	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0			-		SERVICE REMARKS	--
500-26-0001	FIRE PROTECTION - ENGINE FIRE DETECTOR REROUTING, SERVICE BULLETIN								
		MOS				TECH :	INSP :	LABOR HRS :	ICAO:
		HRS						SERVICE REMARKS	--
		AFL			MSC				
		MSC							
MOC:									
500-26-0001 R1	FIRE PROTECTION - ENGINE FIRE DETECTOR REROUTING, SERVICE BULLETIN								
		MOS				TECH :	INSP :	LABOR HRS :	ICAO:
		HRS						SERVICE REMARKS	--
		AFL			MSC				
		MSC							
MOC:									
500-26-0001 R2	FIRE PROTECTION - ENGINE FIRE DETECTOR REROUTING, SERVICE BULLETIN								
		MOS	19-JUL-2013			TECH :	INSP :	LABOR HRS :	ICAO:
		HRS	262.90					SERVICE REMARKS	--
		AFL	154						
		MSC			MSC				
MOC:COMPLIED WITH									



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 60 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-26-0002	FIRE PROTECTION - ADDITIONAL FIRE EXTINGUISHER FOR 7 PASSENGERS CONFIGURATION, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-26-0002 R1	FIRE PROTECTION - ADDITIONAL FIRE EXTINGUISHER FOR 7 PASSENGERS CONFIGURATION, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-26-0002 R2	FIRE PROTECTION - ADDITIONAL FIRE EXTINGUISHER FOR 7 PASSENGERS CONFIGURATION, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-26-0003	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-26-0003 R1	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-26-0003 R2	FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER REPLACEMENT, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 61 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
FAA 2003-26-14	APPLIANCE AD -	TO REMOVE FROM SERVICE FIRE EXTINGUISHERS THAT HAVE THIS INCOMPLETE CRIMPING OF THE SIPHON TUBE			
		MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		AFL	258		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE - BY EQUIPMENT					
FAA 2010-01-03	APPLIANCE AD -	REPLACE PORTABLE HALON 1211 (BCF) FIRE EXTINGUISHERS MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH SERVICEABLE FIRE EXTINGUISHERS			
		MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		AFL	258		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE - BY EQUIPMENT					
FAA 2010-04-16	APPLIANCE AD -	REPLACE ALL TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI, HAVING P/N 1708337B4			
		MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		AFL	258		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE - BY EQUIPMENT					

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 27-FLIGHT CONTROLS					
27-01-03-001	LUBRICATION OF ROTARY BALL SPLINE	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-04-01-001	FUNCTIONAL CHECK OF TRIM ACTUATION TIME LIMITER	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-04-01-002	FUNCTIONAL CHECK OF TRIM TABS ELECTRICAL STOP	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-04-01-003	OPERATIONAL CHECK OF TRIM TAB JAM MONITORING FUNCTION	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-11-00-001	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-11-02-002	DETAILED VISUAL INSPECTION OF AILERON CONTROL CABLES	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-14-02-001 Part: 452900-1007	FUNCTIONAL CHECK ROLL TRIM ACTUATOR AILERON TRIM BACKLASH/ INTEGRITY 0232	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-21-00-001	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-21-02-002	DETAILED VISUAL INSPECTION OF RUDDER CONTROL CABLES	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
27-24-02-001 Part: 453000-1007	FUNCTIONAL CHECK YAW TRIM ACTUATOR RUDDER TRIM BACKLASH INTEGRITY 0233	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
27-31-00-001	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
27-31-02-002	DETAILED VISUAL INSPECTION OF ELEVATOR CONTROL CABLES	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
27-34-02-001	FUNCTIONAL CHECK OF PITCH TRIM BACKLASH/ INTEGRITY	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
27-36-01-001	OPERATIONAL CHECK OF ANGLE-OF-ATTACK (AOA) SENSOR	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
	SCHEDULED	AFL	299	0	ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
	SCHEDULED	AFL	227		ICAO:
					SERVICE REMARKS --
27-36-03-001	OPERATIONAL CHECK OF SPWS CUTOUT SWITCH	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
27-51-01-001	LUBRICATION OF FLAP ACTUATORS BALL SCREWS	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
	SCHEDULED	AFL	299	0	ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
	SCHEDULED	AFL	227		ICAO:
					SERVICE REMARKS --
27-51-01-002	DETAILED VISUAL INSPECTION LEFT FLAP ACTUATOR	MOS	03-AUG-2010	TECH :	INSP :
Part: 6094A0001-05	0525	HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
27-51-01-002	DETAILED VISUAL INSPECTION RIGHT FLAP ACTUATOR	MOS	03-AUG-2010	TECH :	INSP :
Part: 6094A0001-05	0538	HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 64 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
27-51-01-003	RESTORE (OVERHAUL) LEFT FLAP ACTUATOR				
Part: 6094A0001-05	0525	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
27-51-01-003	RESTORE (OVERHAUL) RIGHT FLAP ACTUATOR				
Part: 6094A0001-05	0538	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
27-60-00-001	OPERATIONAL CHECK OF GROUND SPOILER SYSTEM				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
500-27-0001	FLIGHT CONTROLS - REPLACEMENT OF THE SWPC AND FSCU WOW FUNCTION ACTIVATION, SERVICE BULLETIN				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-27-0001 PART I	PERFORM FLIGHT CONTROLS - REPLACEMENT OF THE SWPC AND FSCU WOW FUNCTION ACTIVATION, SERVICE BULLETIN REPLACEMENT OF THE STALL WARNING AND PROTECTION COMPUTER (SWPC)				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-27-0001 PART II	PERFORM FLIGHT CONTROLS - REPLACEMENT OF THE SWPC AND FSCU WOW FUNCTION ACTIVATION, SERVICE BULLETIN FLAP SYSTEM CONTROL UNIT (FSCU) WEIGHT-ON-WHEELS (WOW) FUNCTION ACTIVATION				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-27-0002	FLIGHT CONTROLS - REPLACEMENT OF THE FLAP SYSTEM CONTROL UNIT (FSCU), SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 65 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-27-0002 R1	FLIGHT CONTROLS - REPLACEMENT OF THE FLAP SYSTEM CONTROL UNIT (FSCU), SERVICE BULLETIN							
		MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-27-0002 R2	FLIGHT CONTROLS - REPLACEMENT OF THE FLAP SYSTEM CONTROL UNIT (FSCU), SERVICE BULLETIN							
		MOS	03-AUG-2010			TECH :	INSP :	ICAO:
		HRS	0				LABOR HRS :	
		AFL	0				SERVICE REMARKS	--
		MSC		MSC				
MOC:COMPLIED WITH - AT MANUFACTURE								
500-27-0003	FLIGHT CONTROLS - REMOVAL OF THE FLAP LIMITATION, SERVICE BULLETIN							
		MOS	03-AUG-2010			TECH :	INSP :	ICAO:
		HRS	0				LABOR HRS :	
		AFL	0				SERVICE REMARKS	--
		MSC		MSC				
MOC:COMPLIED WITH - AT MANUFACTURE								
500-27-0003 R1	FLIGHT CONTROLS - REMOVAL OF THE FLAP LIMITATION, SERVICE BULLETIN							
		MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-27-0003 R1 PART I	PERFORM FLIGHT CONTROLS - REMOVAL OF THE FLAP LIMITATION, SERVICE BULLETIN			REMOVAL OF THE FLAP POSITION 3 LIMITATION				
		MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE								
500-27-0003 R1 PART II	PERFORM FLIGHT CONTROLS - REMOVAL OF THE FLAP LIMITATION, SERVICE BULLETIN			REMOVAL OF THE FLAP POSITION FULL LIMITATION				
		MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 66 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-27-0003 R1 PART III	PERFORM FLIGHT CONTROLS - REMOVAL OF THE FLAP LIMITATION, SERVICE BULLETIN FSCU-08)	MOS	25-JUL-2011	TECH :	INSP :
		HRS	137.20		LABOR HRS :
		AFL	68		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH					
500-27-0005	FLIGHT CONTROLS - REPLACEMENT OF THE FLAP SYSTEM CONTROL UNIT (FSCU-3/4 TO FSCU-5), SERVICE BULLETIN	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-27-0005 R1	FLIGHT CONTROLS - REPLACEMENT OF THE FLAP SYSTEM CONTROL UNIT (FSCU- 3/4 TO FSCU-5) (THIS BULLETIN IS SUPERSEDED BY SB500-27-0003), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-27-0006	FLIGHT CONTROLS - CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C-100117-2 TO PN C-100117-3, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-27-0006 R1	FLIGHT CONTROLS - CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C-100117-2 TO PN C-100117-3, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-27-0006 R2	FLIGHT CONTROLS - CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C-100117-2 TO PN C-100117-3 (SUPERSEDED BY SB 500-27-0022), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-27-0006 R2 PART I	ACCOMPLISH FLIGHT CONTROLS - CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C-100117-2 TO PN C-100117-3 (SUPERSEDED BY SB 500-27-0022), SERVICE BULLETIN CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C-100117-2 TO PN C-100117-3				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-27-0006 R2 PART II	ACCOMPLISH FLIGHT CONTROLS - CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C-100117-2 TO PN C-100117-3 (SUPERSEDED BY SB 500-27-0022), SERVICE BULLETIN INSPECTION OF THE AOA SENSOR, AND SEALANT APPLYING				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-27-0006 R3	FLIGHT CONTROLS - CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C- 100117-2 TO PN C-100117-3 (SUPERSEDED BY SB 500-27-0022), SERVICE BULLETIN				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:					
500-27-0006 R3 PART I	CHANGE FLIGHT CONTROLS - CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C- 100117-2 TO PN C-100117-3 (SUPERSEDED BY SB 500-27-0022), SERVICE BULLETIN OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C-100117-2 TO PN C-100117-3				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-27-0006 R3 PART II	INSPECTION FLIGHT CONTROLS - CHANGE OF ANGLE OF ATTACK (AOA) SENSOR FROM PN C- 100117-2 TO PN C-100117-3 (SUPERSEDED BY SB 500-27-0022), SERVICE BULLETIN OF THE AOA SENSOR, AND SEALANT APPLYING - ADDITIONAL ACTION				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:					
500-27-0007	FLIGHT CONTROLS - PILOT CONTROL-YOKE ASSEMBLY INSTALLATION, SERVICE BULLETIN				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 68 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-27-0007 R1	FLIGHT CONTROLS - PILOT CONTROL-YOKE ASSEMBLY INSTALLATION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-27-0007 R1 PART I	PERFORM FLIGHT CONTROLS - PILOT CONTROL-YOKE ASSEMBLY INSTALLATION, SERVICE BULLETIN	INSPECTION OF HOLE OF PILOT CONTROL YOKE GUST-LOCK FITTING	MOS HRS AFL MSC
MOC:NOT APPLICABLE			
500-27-0007 R1 PART II	PERFORM FLIGHT CONTROLS - PILOT CONTROL-YOKE ASSEMBLY INSTALLATION, SERVICE BULLETIN	CORRECTIVE ACTION ON PILOT CONTROL YOKE GUST-LOCK FITTING HOLE	MOS HRS AFL MSC
MOC:NOT APPLICABLE			
500-27-0007 R1 PART III	PERFORM FLIGHT CONTROLS - PILOT CONTROL-YOKE ASSEMBLY INSTALLATION, SERVICE BULLETIN	PILOT CONTROL YOKE ASSEMBLY INSPECTION	MOS HRS AFL MSC
MOC:NOT APPLICABLE			
500-27-0007 R1 PART IV	PERFORM FLIGHT CONTROLS - PILOT CONTROL-YOKE ASSEMBLY INSTALLATION, SERVICE BULLETIN	CORRECTIVE ACTION ON PILOT CONTROL YOKE INSTALLATION	MOS HRS AFL MSC
MOC:NOT APPLICABLE			
500-27-0008	FLIGHT CONTROLS - GROUND SPOILER SYSTEM INSTALLATION (SUPERSEDED BY SB 500-00-0009 REV 1), SERVICE BULLETIN		MOS HRS AFL MSC
MOC:NOT APPLICABLE			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 69 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-27-0008 R1	FLIGHT CONTROLS - GROUND SPOILER SYSTEM INSTALLATION (SUPERSEDED BY SB 500-00-0009 R4), SERVICE BULLETIN					TECH :	INSP :	ICAO:
		MOS					LABOR HRS :	
		HRS					SERVICE REMARKS	--
		AFL			MSC			
		MSC						
MOC:NOT APPLICABLE								
500-27-0009	FLIGHT CONTROLS - CONTROL YOKE REPLACEMENT, SERVICE BULLETIN					TECH :	INSP :	ICAO:
		MOS	03-AUG-2010				LABOR HRS :	
		HRS	0				SERVICE REMARKS	--
		AFL	0		MSC			
		MSC						
MOC:COMPLIED WITH - AT MANUFACTURE								
500-27-0010	FLIGHT CONTROLS - CONTROL YOKE MAP HOLDER REPLACEMENT, SERVICE BULLETIN					TECH :	INSP :	ICAO:
		MOS					LABOR HRS :	
		HRS					SERVICE REMARKS	--
		AFL			MSC			
		MSC						
MOC:								
500-27-0010 R1	FLIGHT CONTROLS - CONTROL YOKE MAP HOLDER REPLACEMENT, SERVICE BULLETIN					TECH :	INSP :	ICAO:
		MOS					LABOR HRS :	
		HRS					SERVICE REMARKS	--
		AFL			MSC			
		MSC						
MOC:NOT APPLICABLE								
500-27-0011	FLIGHT CONTROLS - REPLACEMENT OF TRIM ACTUATOR CONTROLLER, SERVICE BULLETIN					TECH :	INSP :	ICAO:
		MOS	03-AUG-2010				LABOR HRS :	
		HRS	0				SERVICE REMARKS	--
		AFL	0		MSC			
		MSC						
MOC:NOT APPLICABLE								
500-27-0011 R1	FLIGHT CONTROLS - REPLACEMENT OF TRIM ACTUATOR CONTROLLER, SERVICE BULLETIN					TECH :	INSP :	ICAO:
		MOS	25-JUL-2011				LABOR HRS :	
		HRS	137.20				SERVICE REMARKS	--
		AFL	68		MSC			
		MSC						
MOC:COMPLIED WITH								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 70 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-27-0013	FLIGHT CONTROLS - MODIFICATION OF THE PEDAL POSITION TRANSDUCER STOPS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-27-0013 REV 1	FLIGHT CONTROLS - MODIFICATION OF THE PEDAL POSITION TRANSDUCER STOPS, SERVICE BULLETIN	MOS	25-JUL-2011	TECH :	INSP :
		HRS	137.20		LABOR HRS :
		AFL	68		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH					
500-27-0015	REPLACEMENT OF THE BOLT THAT ATTACHES THE LINK ARM TO THE FLAP POSITION SENSOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-27-0015 REV 1	FLIGHT CONTROLS - REPLACEMENT OF THE BOLT THAT ATTACHES THE LINK ARM TO THE FLAP POSITION SENSOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-27-0015 REV 1 PART I	REPLACEMENT FLIGHT CONTROLS - REPLACEMENT OF THE BOLT THAT ATTACHES THE LINK ARM TO THE FLAP POSITION SENSOR, SERVICE BULLETIN OF BOLT THAT ATTACHES THE LINK ARM FROM PN NAS6303-11 TO PN NAS1801-3-16	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-27-0015 REV 1 PART II	REPLACEMENT FLIGHT CONTROLS - REPLACEMENT OF THE BOLT THAT ATTACHES THE LINK ARM TO THE FLAP POSITION SENSOR, SERVICE BULLETIN OF BOLT THAT ATTACHES THE LINK ARM FROM PN NAS1801-3-15 TO PN NAS1801-3-16	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 71 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-27-0016	FLIGHT CONTROLS - ELECTRICAL WIRING MODIFICATION IN THE COPILOT CONTROL WHEEL CONNECTOR 2J0505, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								
500-27-0016 R1	FLIGHT CONTROLS - ELECTRICAL WIRING MODIFICATION IN THE COPILOT CONTROL WHEEL CONNECTOR 2J0505, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								
500-27-0017	FLIGHT CONTROLS - CONTROL PEDAL ASSEMBLY MODIFICATION, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:NOT APPLICABLE								
500-27-0017 R1	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								
500-27-0017 R1 PART I	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN OF BOLT PIN ASSEMBLY	MOS	16-MAY-2013			TECH :	INSP :	ICAO:
		HRS	254.60				LABOR HRS :	
		AFL	144				SERVICE REMARKS	--
		MSC		MSC				
MOC:COMPLIED WITH								
500-27-0017 R1 PART II	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN OF LIMITER BOLT ASSEMBLY	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:NOT APPLICABLE								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 72 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-27-0017 R2	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-27-0017 R2 PART I	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN OF BOLT PIN ASSEMBLY	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-27-0017 R2 PART II	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN OF LIMITER BOLT ASSEMBLY	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-27-0017 R2 PART III	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN OF ADJUSTABLE STOP SCREW ASSEMBLY	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-27-0017 R2 PART IV	INSTALLATION FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN OF ADJUSTABLE STOP SCREW ASSEMBLY AND ROLLERS STANDARDIZATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-27-0017 R3	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 73 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-27-0017 R3 PART I	INSTALLATION	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN - OF BOLT PIN ASSEMBLY	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-27-0017 R3 PART II	INSTALLATION	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN - OF LIMITER BOLT ASSEMBLY	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-27-0017 R3 PART III	INSTALLATION	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN - OF ADJUSTABLE STOP SCREW ASSEMBLY	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
MSC			
MOC:			
500-27-0017 R3 PART IV	INSTALLATION	FLIGHT CONTROLS - PILOT CONTROL PEDAL ASSEMBLY REWORK, SERVICE BULLETIN - OF ADJUSTABLE STOP SCREW ASSEMBLY AND ROLLERS STANDARDIZATION	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
MSC			
MOC:			
500-27-0019		FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
MSC			
MOC:			
500-27-0019 PART I	CHECK	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN FOR LOCK WIRE PROPER ROUTING	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
MSC			
MOC:			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 74 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-27-0019 PART II	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN	LOCK WIRE REINSTALLATION - ROLL TRIM ACTUATOR	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		SERVICE REMARKS -- ICAO:
	MSC	MSC	
MOC:			
500-27-0019 PART III	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN	LOCK WIRE REINSTALLATION - YAW TRIM ACTUATOR	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		SERVICE REMARKS -- ICAO:
	MSC	MSC	
MOC:			
500-27-0019 PART IV	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN	LOCK WIRE REINSTALLATION - PITCH TRIM ACTUATOR	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		SERVICE REMARKS -- ICAO:
	MSC	MSC	
MOC:			
500-27-0019 R1	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN		
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		SERVICE REMARKS -- ICAO:
	MSC	MSC	
MOC:			
500-27-0019 R1 PART I	CHECK FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN	FOR LOCK WIRE PROPER ROUTING	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		SERVICE REMARKS -- ICAO:
	MSC	MSC	
MOC:			
500-27-0019 R1 PART II	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN	LOCK WIRE REINSTALLATION - ROLL TRIM ACTUATOR	
	MOS	TECH :	INSP :
	HRS		LABOR HRS :
	AFL		SERVICE REMARKS -- ICAO:
	MSC	MSC	
MOC:			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 75 of 235

TASK NO		DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.		C/W	TIME SINCE	C/W	TIME SINCE			
500-27-0019 R1 PART III	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN				LOCK WIRE REINSTALLATION - YAW TRIM ACTUATOR				
		MOS					TECH :	INSP :	ICAO:
		HRS						LABOR HRS :	
		AFL			MSC			SERVICE REMARKS	--
		MSC							
MOC:									
500-27-0019 R1 PART IV	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN				LOCK WIRE REINSTALLATION - PITCH TRIM ACTUATOR				
		MOS					TECH :	INSP :	ICAO:
		HRS						LABOR HRS :	
		AFL			MSC			SERVICE REMARKS	--
		MSC							
MOC:									
500-27-0019 R2	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN								
		MOS	08-AUG-2014				TECH :	INSP :	ICAO:
		HRS	342.40					LABOR HRS :	
		AFL	227		MSC			SERVICE REMARKS	--
		MSC							
MOC:COMPLIED WITH									
500-27-0019 R2 PART I	CHECK FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN FOR LOCK WIRE PROPER ROUTING ON ROLL TRIM ACTUATOR, YAW TRIM ACTUATOR AND PITCH TRIM ACTUATOR								
		MOS					TECH :	INSP :	ICAO:
		HRS						LABOR HRS :	
		AFL			MSC			SERVICE REMARKS	--
		MSC							
MOC:									
500-27-0019 R2 PART II	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN				LOCK WIRE REINSTALLATION - ROLL TRIM ACTUATOR				
		MOS					TECH :	INSP :	ICAO:
		HRS						LABOR HRS :	
		AFL			MSC			SERVICE REMARKS	--
		MSC							
MOC:									
500-27-0019 R2 PART III	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN				LOCK WIRE REINSTALLATION - YAW TRIM ACTUATOR				
		MOS					TECH :	INSP :	ICAO:
		HRS						LABOR HRS :	
		AFL			MSC			SERVICE REMARKS	--
		MSC							
MOC:									



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 76 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL			
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE		
500-27-0019 R2 PART IV	FLIGHT CONTROLS - CHECK OF LOCK WIRE FOR PROPER ROUTING, SERVICE BULLETIN	MOS		LOCK WIRE REINSTALLATION - PITCH TRIM ACTUATOR		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		HRS					
		AFL		MSC			
		MSC					
MOC:							
500-27-0020	FLIGHT CONTROLS - REPLACEMENT OF THE FLAP SYSTEM CONTROL UNIT (FSCU), SERVICE BULLETIN	MOS	19-JUL-2013			TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		HRS	262.90				
		AFL	154				
		MSC		MSC			
MOC:COMPLIED WITH							
500-27-0021	FLIGHT CONTROLS - REPLACEMENT OF FLAP LINEAR ACTUATORS, SERVICE BULLETIN	MOS				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		HRS					
		AFL					
		MSC		MSC			
MOC:							
500-27-0021 R1	FLIGHT CONTROLS - REPLACEMENT OF FLAP LINEAR ACTUATORS, SERVICE BULLETIN	MOS	19-JUL-2013			TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		HRS	262.90				
		AFL	154				
		MSC		MSC			
MOC:COMPLIED WITH							
500-27-0022	FLIGHT CONTROLS - ANGLE OF ATTACK (AOA) SENSOR REPLACEMENT, SERVICE BULLETIN	MOS	08-AUG-2014			TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		HRS	342.40				
		AFL	227				
		MSC		MSC			
MOC:COMPLIED WITH							
ANAC 2009-02-04	EMERGENCY AD - INCLUSION OF A TEMPORARY LIMITATION TO THE ANAC-APPROVED AIRPLANE FLIGHT MANUAL (AFM)	MOS	13-AUG-2010			TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		HRS					
		AFL					
		MSC		MSC			
MOC:NOT APPLICABLE - TO P/N C100106-2 EQUIPPED.							

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 77 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
ANAC 2009-10-01 R2	MODIFICATION OF THE APPROVED AIRPLANE FLIGHT MANUAL (AFM)	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
FAA 2009-05-06	INCORPORATE INTO THE AIRPLANE FLIGHT MANUAL (AFM) THE PROCEDURES AND LIMITATIONS SECTION REVISIONS	MOS	10-APR-2015			TECH :	INSP :	
		HRS	382.70				LABOR HRS :	ICAO:
		AFL	258				SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE - BY EQUIPMENT								
FAA 2009-23-11	INSERTION OF INFORMATION INTO THE ABNORMAL PROCEDURES SECTION OF THE FAA-APPROVED AIRPLANE FLIGHT MANUAL (AFM)	MOS	13-AUG-2010			TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:COMPLIED WITH								
FAA 2009-24-14	REPLACEMENT OF THE NUTS OF THE RIGHT AND LEFT ELEVATORS MASS BALANCE FASTENERS	MOS	10-APR-2015			TECH :	INSP :	
		HRS	382.70				LABOR HRS :	ICAO:
		AFL	258				SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE - BY AIRCRAFT S/N								
FAA 2010-15-09	INSERTION OF INFORMATION INTO THE ABNORMAL PROCEDURES SECTION OF THE FAA-APPROVED AIRPLANE FLIGHT MANUAL (AFM)	MOS	10-APR-2015			TECH :	INSP :	
		HRS	382.70				LABOR HRS :	ICAO:
		AFL	258				SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE - BY EQUIPMENT								
FAA 2011-17-15	REPLACEMENT OF BOTH ANGLE OF ATTACK (AOA) SENSORS AND COVER PLATES, INSPECTION OF THE SENSOR AREA, AND, IF NEEDED, APPLICATION OF SEALANT BETWEEN THE AOA COVERS AND THE AOA SENSORS.	MOS	10-APR-2015			TECH :	INSP :	
		HRS	382.70				LABOR HRS :	ICAO:
		AFL	258				SERVICE REMARKS	--
		MSC		MSC				
MOC:COMPLIED WITH								

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
(D)H27-01-240-001	DETAILED VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE FLAP SYSTEM CONTROL UNIT	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-02-571-001	DETAILED VISUAL INSPECTION RIGHT L/HIRF PROTECTION ON THE FLAP LINEAR ACTUATOR	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-02-571-001	DETAILED VISUAL INSPECTION LEFT L/HIRF PROTECTION ON THE FLAP LINEAR ACTUATOR	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-03-571-001	DETAILED VISUAL INSPECTION LEFT L/HIRF PROTECTION ON THE FLAP SENSOR POSITION UNIT	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-03-571-001	DETAILED VISUAL INSPECTION RIGHT L/HIRF PROTECTION ON THE FLAP SENSOR POSITION UNIT	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-04-220-001	DETAILED VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE FLAP SELECTOR LEVER	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-05-310-001	DETAILED VISUAL INSPECTION LEFT L/HIRF PROTECTION ON THE TRIM ACTUATOR CONTROLLER	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-05-310-001	DETAILED VISUAL INSPECTION RIGHT L/HIRF PROTECTION ON THE TRIM ACTUATOR CONTROLLER	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-06-572-001	DETAILED VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE ROLL TRIM ACTUATOR	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-07-330-001	DETAILED VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE YAW TRIM ACTUATOR	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-08-340-001	DETAILED VISUAL INSPECTION LEFT L/HIRF PROTECTION ON THE PITCH TRIM ACTUATOR	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H27-08-340-001	DETAILED VISUAL INSPECTION RIGHT L/HIRF PROTECTION ON THE PITCH TRIM ACTUATOR	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
CHAPTER 28-FUEL						
28-11-00-001	FUNCTIONAL CHECK OF FUEL TANKS FOR MICRO-ORGANISMS					
		MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50			LABOR HRS :
		AFL	299			ICAO:
						SERVICE REMARKS --
		MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50		-	LABOR HRS :
	SCHEDULED	AFL	299		0	ICAO:
						SERVICE REMARKS --
		MOS	08-AUG-2014		TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40		-	LABOR HRS :
	SCHEDULED	AFL	227			ICAO:
						SERVICE REMARKS --
28-12-01-001	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA					
		MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50			LABOR HRS :
		AFL	299			ICAO:
						SERVICE REMARKS --
		MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50		-	LABOR HRS :
	SCHEDULED	AFL	299		0	ICAO:
						SERVICE REMARKS --
		MOS	08-AUG-2014		TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40		-	LABOR HRS :
	SCHEDULED	AFL	227			ICAO:
						SERVICE REMARKS --
28-12-03-001	OPERATIONAL CHECK RH WING FUEL TANK FLOAT VENT VALVE					
Part: L87-19-001P2	E38487	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
28-12-03-001	OPERATIONAL CHECK LH WING FUEL TANK FLOAT VENT VALVE					
Part: L87-19-001P2	E38511	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
28-21-07-001	OPERATIONAL CHECK RIGHT WING 0.75 IN SHUTOFF VALVE					
Part: B97-15-601	E39449	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
28-21-07-001	OPERATIONAL CHECK LEFT WING 0.75 IN SHUTOFF VALVE					
Part: B97-15-601	E28956	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
28-21-08-001	OPERATIONAL CHECK 1.5 IN FUEL SYSTEM SHUTOFF VALVE					
Part: B97-38-603P2	E28320	MOS	08-AUG-2014		TECH :	INSP :
		HRS	342.40			LABOR HRS :
		AFL	227			ICAO:
						SERVICE REMARKS --
28-43-01-001	FUNCTIONAL CHECK FUEL TEMPERATURE SENSOR					
Part: 798840-1-0	02060	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 80 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-28-0001	FUEL - REPLACEMENT OF THE ENGINE-FEED EJECTOR PUMP, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:

MOC:NOT APPLICABLE

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
CHAPTER 29-HYDRAULIC POWER						
29-00-00-001	VISUAL CHECK HYDRAULIC SYSTEM FILTER DIFFERENTIAL PRESSURE INDICATOR (DPI)					
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015	TECH :	INSP :	
		HRS	425.50		LABOR HRS :	ICAO:
		AFL	299		SERVICE REMARKS	--
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015	TECH :	INSP :	
		HRS	425.50	-	LABOR HRS :	ICAO:
	SCHEDULED	AFL	299	0	SERVICE REMARKS	--
Part: PN	SN-UNKNOWN	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N	
		HRS	342.40	-	LABOR HRS :	ICAO:
	SCHEDULED	AFL	227		SERVICE REMARKS	--
29-11-01-001	RESTORATION HYDRAULIC POWERPACK (REPAIR) OF ELECTRICAL MOTOR					
Part: 3032683-002	MX723944	MOS	05-AUG-2013	TECH :	INSP :	
		HRS	262.90		LABOR HRS :	ICAO:
		AFL	154		SERVICE REMARKS	--
29-11-09-001	FUNCTIONAL CHECK HYDRAULIC FLUID TEMPERATURE SWITCH					
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010	TECH :	INSP :	
		HRS	0		LABOR HRS :	ICAO:
		AFL	0		SERVICE REMARKS	--
(D)29-11-11-001	DISCARD OF HYDRAULIC RESERVOIR					
		MOS	03-AUG-2010	TECH :	INSP :	
		HRS	0	-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0		SERVICE REMARKS	--
(D)29-11-12-001	DISCARD OF BLEED/RELIEF VALVE					
		MOS	03-AUG-2010	TECH :	INSP :	
		HRS	0	-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0		SERVICE REMARKS	--
29-15-01-001	DISCARD OF GROUND-SPOILER ACTUATOR HOSES					
		MOS	03-AUG-2010	TECH :	INSP :	
		HRS	0		LABOR HRS :	ICAO:
		AFL	0		SERVICE REMARKS	--
29-20-01-001	OPERATIONAL CHECK POWERPACK VENTILATION FAN					
Part: SF9202D00	L00302	MOS	03-AUG-2010	TECH :	INSP :	
		HRS	0		LABOR HRS :	ICAO:
		AFL	0		SERVICE REMARKS	--
500-29-0001	HYDRAULIC POWER - TORQUE VERIFICATION IN THE HYDRAULIC FITTINGS, SERVICE BULLETIN					
		MOS	03-AUG-2010	TECH :	INSP :	
		HRS	0		LABOR HRS :	ICAO:
		AFL	0		SERVICE REMARKS	--
		MSC		MSC		
MOC:NOT APPLICABLE						
500-29-0002	HYDRAULIC POWER - HYDRAULIC POWER PACK REPLACEMENT, SERVICE BULLETIN					
		MOS		TECH :	INSP :	
		HRS			LABOR HRS :	ICAO:
		AFL			SERVICE REMARKS	--
		MSC		MSC		

MOC:

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 82 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-29-0002 REV 1	HYDRAULIC POWER - HYDRAULIC POWER PACK REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC	19-JUL-2013 262.90 154	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-29-0004	HYDRAULIC POWER - REDUCTION OF RESERVOIR FULL FLUID LEVEL INDICATION OF POWER-PACK, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-29-0004 R1	HYDRAULIC POWER - REDUCTION OF RESERVOIR FULL FLUID LEVEL INDICATION OF POWER-PACK, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-29-0004 R1 PART I	HYDRAULIC POWER - REDUCTION OF RESERVOIR FULL FLUID LEVEL INDICATION OF POWER-PACK, SERVICE BULLETIN	MOS HRS AFL MSC		FULL FLUID LEVEL INDICATION REPLACEMENT TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-29-0004 R1 PART II	HYDRAULIC POWER - REDUCTION OF RESERVOIR FULL FLUID LEVEL INDICATION OF POWER-PACK, SERVICE BULLETIN	MOS HRS AFL MSC		VISUAL MODIFICATION (YELLOW) LABEL PLATE REMOVAL TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
CHAPTER 30-ICE AND RAIN PROTECTION						
30-10-00-001	OPERATIONAL CHECK OF PNEUMATIC DE-ICING SYSTEM					
		MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50			LABOR HRS :
		AFL	299			ICAO:
						SERVICE REMARKS --
		MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50		-	LABOR HRS :
	SCHEDULED	AFL	299		0	ICAO:
						SERVICE REMARKS --
		MOS	08-AUG-2014		TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40		-	LABOR HRS :
	SCHEDULED	AFL	227			ICAO:
						SERVICE REMARKS --
30-11-03-001	CLEANING REAR FUS PRESSURE REGULATOR/RELIEVER VALVE					
Part: 4D2095-2011	N100787	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
30-11-04-001	CLEANING WATER SEPARATOR					
Part: 44E13-5A	N1407009	MOS	08-AUG-2014		TECH :	INSP :
		HRS	342.40			LABOR HRS :
		AFL	227			ICAO:
						SERVICE REMARKS --
30-11-05-001	FUNCTIONAL CHECK REAR FUS LOW PRESSURE SWITCH					
Part: 3D3552-02	0201	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
30-13-02-001	FUNCTIONAL CHECK NO.1 R/H WING DE ICE PRESSURE SWITCH					
Part: 3D3533-04	0816	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
30-13-02-001	FUNCTIONAL CHECK NO.2 R/H WING DE ICE PRESSURE SWITCH					
Part: 3D3533-04	0807	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
30-13-02-001	FUNCTIONAL CHECK NO.1 L/H WING DE ICE PRESSURE SWITCH					
Part: 3D3533-04	0798	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
30-13-02-001	FUNCTIONAL CHECK NO.2 L/H WING DE ICE PRESSURE SWITCH					
Part: 3D3533-04	0814	MOS	03-AUG-2010		TECH :	INSP :
		HRS	0			LABOR HRS :
		AFL	0			ICAO:
						SERVICE REMARKS --
30-13-03-001	GENERAL VISUAL INSPECTION LH WING DE-ICER BOOT					
Part: PS29S4D5321-23	MCDX680	MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50			LABOR HRS :
		AFL	299			ICAO:
						SERVICE REMARKS --
30-13-03-001	GENERAL VISUAL INSPECTION RH WING DE-ICER BOOT					
Part: PS29S4D5321-24	MCGZ790	MOS	12-AUG-2015		TECH :	INSP :
		HRS	425.50			LABOR HRS :
		AFL	299			ICAO:
						SERVICE REMARKS --
	Part: PS29S4D5321-24	MCGZ790	12-AUG-2015		TECH :	INSP :
		HRS	425.50		-	LABOR HRS :
		AFL	299		0	ICAO:
	SCHEDULED					SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION			COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL		
	PART NO.	SERIAL NO.		C/W	TIME SINCE	C/W	TIME SINCE	
30-13-03-001	GENERAL VISUAL INSPECTION LH WING DE-ICER BOOT							
Part:	PS29S4D5321-23	MCDX680	MOS		12-AUG-2015			TECH :
			HRS		425.50			INSP :
			AFL		299			LABOR HRS :
		SCHEDULED						ICAO:
								SERVICE REMARKS --
30-13-03-001	GENERAL VISUAL INSPECTION RH WING DE-ICER BOOT							
Part:	PS29S4D5321-24	MCGZ790	MOS		08-AUG-2014			TECH : CRS KX5R005N
			HRS		342.40			INSP : CRS KX5R005N
			AFL		227			LABOR HRS :
		SCHEDULED						ICAO:
								SERVICE REMARKS --
30-13-03-001	GENERAL VISUAL INSPECTION LH WING DE-ICER BOOT							
Part:	PS29S4D5321-23	MCDX680	MOS		08-AUG-2014			TECH : CRS KX5R005N
			HRS		342.40			INSP : CRS KX5R005N
			AFL		227			LABOR HRS :
		SCHEDULED						ICAO:
								SERVICE REMARKS --
30-15-02-001	FUNCTIONAL CHECK REAR FUS DE ICE PRESSURE SWITCH							
Part:	3D3533-04	0787	MOS		03-AUG-2010			TECH :
			HRS		0			INSP :
			AFL		0			LABOR HRS :
								ICAO:
								SERVICE REMARKS --
30-15-03-001	GENERAL VISUAL INSPECTION LH TAIL DE-ICER BOOT							
Part:	PS29S4D5321-21	MCGA480	MOS		12-AUG-2015			TECH :
			HRS		425.50			INSP :
			AFL		299			LABOR HRS :
								ICAO:
								SERVICE REMARKS --
30-15-03-001	GENERAL VISUAL INSPECTION RH TAIL DE-ICER BOOT							
Part:	PS29S4D5321-22	MCDX650	MOS		12-AUG-2015			TECH :
			HRS		425.50			INSP :
			AFL		299			LABOR HRS :
								ICAO:
								SERVICE REMARKS --
30-15-03-001	GENERAL VISUAL INSPECTION LH TAIL DE-ICER BOOT							
Part:	PS29S4D5321-21	MCGA480	MOS		12-AUG-2015			TECH :
			HRS		425.50			INSP :
			AFL		299			LABOR HRS :
		SCHEDULED						ICAO:
								SERVICE REMARKS --
30-15-03-001	GENERAL VISUAL INSPECTION RH TAIL DE-ICER BOOT							
Part:	PS29S4D5321-22	MCDX650	MOS		12-AUG-2015			TECH :
			HRS		425.50			INSP :
			AFL		299			LABOR HRS :
		SCHEDULED						ICAO:
								SERVICE REMARKS --
Part:	PS29S4D5321-22	MCDX650	MOS		08-AUG-2014			TECH : CRS KX5R005N
			HRS		342.40			INSP : CRS KX5R005N
			AFL		227			LABOR HRS :
		SCHEDULED						ICAO:
								SERVICE REMARKS --
30-15-03-001	GENERAL VISUAL INSPECTION LH TAIL DE-ICER BOOT							
Part:	PS29S4D5321-21	MCGA480	MOS		08-AUG-2014			TECH : CRS KX5R005N
			HRS		342.40			INSP : CRS KX5R005N
			AFL		227			LABOR HRS :
		SCHEDULED						ICAO:
								SERVICE REMARKS --
30-21-02-001	FUNCTIONAL CHECK LH ENG ANTI-ICE PRESSURE TRANSDUCER							
Part:	APTE-473A-1000-50G	7612-4-272	MOS		03-AUG-2010			TECH :
			HRS		0			INSP :
			AFL		0			LABOR HRS :
								ICAO:
								SERVICE REMARKS --
30-21-02-001	FUNCTIONAL CHECK RH ENG ANTI-ICE PRESSURE TRANSDUCER							
Part:	APTE-473A-1000-50G	7612-4-246	MOS		03-AUG-2010			TECH :
			HRS		0			INSP :
			AFL		0			LABOR HRS :
								ICAO:
								SERVICE REMARKS --
30-21-03-001	BOREScope INSPECTION OF PICCOLO TUBE							
			MOS		03-AUG-2010			TECH :
			HRS		0			INSP :
			AFL		0			LABOR HRS :
								ICAO:
								SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
30-21-04-001	DETAILED VISUAL INSPECTION OF ENGINE ANTI-ICE DUCTS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
30-31-00-001	OPERATIONAL CHECK OF PITOT, STATIC, AOA AND P-STATIC HEATING	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
30-41-01-001	FUNCTIONAL CHECK OF WINDSHIELD RAIN REPELLENT COATING	MOS HRS AFL	12-AUG-2015 425.50 299	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
	SCHEDULED	MOS HRS AFL	12-AUG-2015 425.50 299	TECH : - 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
	SCHEDULED	MOS HRS AFL	08-AUG-2014 342.40 227	TECH : CRS KX5R005N -	INSP : CRS KX5R005N LABOR HRS : SERVICE REMARKS -- ICAO:
30-42-00-001	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
500-30-0001	ICE AND RAIN PROTECTION - REPLACEMENT OF THE WHCU, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-30-0001 R1	ICE AND RAIN PROTECTION - REPLACEMENT OF THE WHCU, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
500-30-0002	ICE AND RAIN PROTECTION - TORQUE ON WINDSHIELD HEATING GROUND STUD, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 86 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-30-0004	ICE AND RAIN PROTECTION - DE-ICE LINE MODIFICATION, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-30-0004 R1	ICE AND RAIN PROTECTION - DE-ICE LINE MODIFICATION, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-30-0004 R2	ICE AND RAIN PROTECTION - DE-ICE LINE MODIFICATION, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-30-0004 R3	ICE AND RAIN PROTECTION - DE-ICE LINE MODIFICATION, SERVICE BULLETIN	MOS	08-AUG-2014		
		HRS	342.40	TECH :	INSP :
		AFL	227		LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-30-0005	ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-30-0005 R1	ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 87 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH				COMPONENT TIMES AFTER REMOVAL			
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE				
500-30-0005 R1 PART I	INSTALLATION	ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN				- OF WATER SEPARATOR ASSEMBLY			
		MOS				TECH :	INSP :		
		HRS					LABOR HRS :		ICAO:
		AFL			MSC		SERVICE REMARKS	--	
		MSC							
MOC:									
500-30-0005 R1 PART II	ADDITIONAL ACTION	ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN				- REPLACEMENT OF THE DOWNSTREAM HOSE			
		MOS				TECH :	INSP :		
		HRS					LABOR HRS :		ICAO:
		AFL			MSC		SERVICE REMARKS	--	
		MSC							
MOC:NOT APPLICABLE									
500-30-0005 R2	ICE AND RAIN PROTECTION	WATER SEPARATOR INSTALLATION, SERVICE BULLETIN							
		MOS				TECH :	INSP :		
		HRS					LABOR HRS :		ICAO:
		AFL			MSC		SERVICE REMARKS	--	
		MSC							
MOC:									
500-30-0005 R2 PART III	INSTALLATION	ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN				OF TUBES AND HOSES			
		MOS				TECH :	INSP :		
		HRS					LABOR HRS :		ICAO:
		AFL			MSC		SERVICE REMARKS	--	
		MSC							
MOC:NOT APPLICABLE									
500-30-0005 R3	ICE AND RAIN PROTECTION	WATER SEPARATOR INSTALLATION, SERVICE BULLETIN							
		MOS	08-AUG-2014			TECH :	INSP :		
		HRS	342.40				LABOR HRS :		ICAO:
		AFL	227		MSC		SERVICE REMARKS	--	
		MSC							
MOC:COMPLIED WITH									
500-30-0005 R3 PART I	ICE AND RAIN PROTECTION	WATER SEPARATOR INSTALLATION, SERVICE BULLETIN				WATER SEPARATOR ASSEMBLY INSTALLATION			
		MOS				TECH :	INSP :		
		HRS					LABOR HRS :		ICAO:
		AFL			MSC		SERVICE REMARKS	--	
		MSC							
MOC:									



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 88 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/WTIME SINCE	C/WTIME SINCE
500-30-0005 R3 PART II	ADDITIONAL ACTION	ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN - REPLACEMENT OF THE DOWNSTREAM HOSE	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-30-0005 R3 PART III	ICE AND RAIN PROTECTION - WATER SEPARATOR INSTALLATION, SERVICE BULLETIN	TUBES AND HOSES INSTALLATION	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 31-INDICATING/RECORDING SYSTEMS					
31-31-00-002	OPERATIONAL CHECK CVR - COCKPIT VOICE RECORDER				
Part: 2100-3083-50	000655842	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
Part: 2100-3083-50	000655842	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
		AFL	299	0	ICAO:
	SCHEDULED				SERVICE REMARKS --
Part: 2100-3083-50	000655842	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
		AFL	227		ICAO:
	SCHEDULED				SERVICE REMARKS --
31-31-03-001	DISCARD CVDR/ULB UNDERWATER LOCATOR BEACON BATTERY				
Part: DK120	SC73145	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
					SERVICE REMARKS --
31-42-00-001	OPERATIONAL CHECK OF HSDB SWITCH REVERSION				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
31-61-00-001	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
31-61-00-001	OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
31-61-00-001	OPERATIONAL CHECK MFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
500-31-0001	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 25.30 AVIONICS SOFTWARE AND CMC LOAD 6 SOFTWARE, SERVICE BULLETIN				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-31-0002	INDICATING/RECORDING SYSTEMS - ACTIVATION OF THE CVDR SYSTEM, SERVICE BULLETIN				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 90 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-31-0003	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 36 AVIONICS SOFTWARE AND CMC LOAD 7 SOFTWARE, SERVICE BULLETIN	MOS			
		HRS			
		AFL			
		MSC		MSC	
					TECH :
					INSP :
					LABOR HRS :
					SERVICE REMARKS -- ICAO:
MOC:					
500-31-0003 R1	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 36 AVIONICS SOFTWARE AND CMC LOAD 7 SOFTWARE, SERVICE BULLETIN	MOS	03-AUG-2010		
		HRS	0		
		AFL	0		
		MSC		MSC	
					TECH :
					INSP :
					LABOR HRS :
					SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
500-31-0004	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS			
		HRS			
		AFL			
		MSC		MSC	
					TECH :
					INSP :
					LABOR HRS :
					SERVICE REMARKS -- ICAO:
MOC:					
500-31-0004 R1	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS	03-AUG-2010		
		HRS	0		
		AFL	0		
		MSC		MSC	
					TECH :
					INSP :
					LABOR HRS :
					SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-31-0004 R10	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS			
		HRS			
		AFL			
		MSC		MSC	
					TECH :
					INSP :
					LABOR HRS :
					SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-31-0004 R11	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS			
		HRS			
		AFL			
		MSC		MSC	
					TECH :
					INSP :
					LABOR HRS :
					SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 91 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0004 R12	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0004 R13	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0004 R14	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0004 R2	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-31-0004 R3	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-31-0004 R4	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 92 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0004 R5	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-31-0004 R6	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0004 R7	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0004 R8	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0004 R9	INDICATING/RECORDING SYSTEMS - INSTALLATION OF ELECTRONIC CHECKLIST (ECL), SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 93 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R1	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-31-0005 R10	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R10 PART I	INSTALLATION INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R10 PART II	ACTIVATION INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R11	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-31-0005 R11 PART I	INSTALLATION INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 94 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R11 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R12		INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-31-0005 R12 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:			
500-31-0005 R12 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R13		INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R13 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 95 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R13 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R14	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R14 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R14 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R15	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R15 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 96 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R15 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R16		INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R16 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R16 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R17		INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R17 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 97 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R17 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R18	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN		
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R18 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R18 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R19	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN		
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R19 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 98 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R19 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R2	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN		
		MOS 03-AUG-2010	TECH :
		HRS 0	INSP :
		AFL 0	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:COMPLIED WITH - AT MANUFACTURE			
500-31-0005 R20	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN		
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R20 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R20 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN OF THE SYNTHETIC VISION	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R21	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN		
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 99 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R21 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	OF THE SYNTHETIC VISION
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R21 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	OF THE SYNTHETIC VISION
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R22		INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R22 PART I	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	INSTALLATION OF THE SYNTHETIC VISION	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R22 PART II	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	ACTIVATION OF THE SYNTHETIC VISION	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R23		INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 100 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R23 PART I	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	INSTALLATION OF THE SYNTHETIC VISION TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R23 PART II	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	ACTIVATION OF THE SYNTHETIC VISION TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R24	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R24 PART I	INSTALLATION INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	OF THE SYNTHETIC VISION TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R24 PART II	ACTIVATION INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	OF THE SYNTHETIC VISION TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-31-0005 R25	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 101 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R25 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	OF THE SYNTHETIC VISION
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R25 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	OF THE SYNTHETIC VISION
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R26		INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R26 PART I	INSTALLATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	OF THE SYNTHETIC VISION
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R26 PART II	ACTIVATION	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	OF THE SYNTHETIC VISION
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-31-0005 R3		INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	
		MOS	TECH :
		HRS	INSP :
		AFL	LABOR HRS :
		MSC	SERVICE REMARKS -- ICAO:
			MSC
MOC:			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 102 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0005 R4	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:		MSC	
500-31-0005 R5	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:		MSC	
500-31-0005 R6	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:		MSC	
500-31-0005 R7	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:		MSC	
500-31-0005 R8	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:		MSC	
500-31-0005 R9	INDICATING/RECORDING SYSTEMS - INSTALLATION OF THE SYNTHETIC VISION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:		MSC	



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 103 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL			
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE		
500-31-0006	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 43 AVIONICS SOFTWARE AND CMC LOAD 8 SOFTWARE, SERVICE BULLETIN	MOS				TECH :	INSP :
		HRS					LABOR HRS :
		AFL					ICAO:
		MSC		MSC			SERVICE REMARKS --
MOC:							
500-31-0006 R1	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 43 AVIONICS SOFTWARE AND CMC LOAD 8 SOFTWARE, SERVICE BULLETIN	MOS				TECH :	INSP :
		HRS					LABOR HRS :
		AFL					ICAO:
		MSC		MSC			SERVICE REMARKS --
MOC:							
500-31-0007	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 43.5 AVIONICS SOFTWARE AND CMC LOAD 9 SOFTWARE, SERVICE BULLETIN	MOS				TECH :	INSP :
		HRS					LABOR HRS :
		AFL					ICAO:
		MSC		MSC			SERVICE REMARKS --
MOC:							
500-31-0007 R1	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 43.5 AVIONICS SOFTWARE AND CMC LOAD 9 SOFTWARE, SERVICE BULLETIN	MOS	25-JUL-2011			TECH :	INSP :
		HRS	137.20				LABOR HRS :
		AFL	68				ICAO:
		MSC		MSC			SERVICE REMARKS --
MOC:COMPLIED WITH							
500-31-0008	INDCIATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 54 AVIONICS SOFTWARE AND CMC SOFTWARE LOAD 10, SERVICE BULLETIN	MOS	19-JUL-2013			TECH :	INSP :
		HRS	262.90				LABOR HRS :
		AFL	154				ICAO:
		MSC		MSC			SERVICE REMARKS --
MOC:COMPLIED WITH							
500-31-0009	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11, SERVICE BULLETIN	MOS				TECH :	INSP :
		HRS					LABOR HRS :
		AFL					ICAO:
		MSC		MSC			SERVICE REMARKS --
MOC:							



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 104 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-31-0009 R1	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
500-31-0009 R2	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
500-31-0009 R2 PART I	INSTALLATION INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11, SERVICE BULLETIN OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
500-31-0009 R2 PART II	ADDITIONAL ACTION INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11, SERVICE BULLETIN - DATA LINK FOLDERS CONFIGURATION AND LOG FILES	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
500-31-0010	INDICATING/RECORDING SYSTEMS - G1000 AVIONICS - DOWNGRADE FROM LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 SOFTWARE TO LOAD 55 AVIONICS SOFTWARE AND CMC LOAD 10.1 SOFTWARE, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-31-0010 R1	INDICATING/RECORDING SYSTEMS - G1000 AVIONICS - DOWNGRADE FROM LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 SOFTWARE TO LOAD 55 AVIONICS SOFTWARE AND CMC LOAD 10.1 SOFTWARE, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 105 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-31-0010 R2	INDICATING/RECORDING SYSTEMS - G1000 AVIONICS - DOWNGRADE FROM LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 SOFTWARE TO LOAD 55 AVIONICS SOFTWARE AND CMC LOAD 10.1 SOFTWARE, SERVICE BULLETIN				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC		MSC		SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-31-0010 R3	INDICATING/RECORDING SYSTEMS - G1000 AVIONICS - DOWNGRADE FROM LOAD 63.7 AVIONICS SOFTWARE AND CMC LOAD 11 SOFTWARE TO LOAD 55 AVIONICS SOFTWARE AND CMC LOAD 10.1 SOFTWARE, SERVICE BULLETIN				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC		MSC		SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-31-0011	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.4, SERVICE BULLETIN				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC		MSC		SERVICE REMARKS --
MOC:					
500-31-0011 R1	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.5, SERVICE BULLETIN				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC		MSC		SERVICE REMARKS --
MOC:					
500-31-0011 R1 PART I	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.5, SERVICE BULLETIN UPLOADING OF THE NEW G1000 LOAD 72.1 AVIONICS SOFTWARE AND THE CMC SOFTWARE LOAD 12.5				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC		MSC		SERVICE REMARKS --
MOC:					
500-31-0011 R1 PART II	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.5, SERVICE BULLETIN ADDITIONAL PART: UPLOADING OF THE CMC SOFTWARE LOAD 12.5				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC		MSC		SERVICE REMARKS --
MOC:					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 106 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-31-0011 R2	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.5, SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-31-0011 R2 PART I	UPLOADING INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.5, SERVICE BULLETIN OF THE NEW G1000 LOAD 72.1 AVIONICS SOFTWARE AND THE CMC SOFTWARE LOAD 12.5	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-31-0011 R2 PART II	INDICATING/RECORDING SYSTEMS - INSTALLATION OF G1000 LOAD 72.1 AVIONICS SOFTWARE AND CMC LOAD 12.5, SERVICE BULLETIN ADDITIONAL PART: UPLOADING OF THE CMC SOFTWARE LOAD 12.5	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
500-31-0012	INDICATING/RECORDING SYSTEMS - TAWS-A (TERRAIN AWARENESS AND WARNING SYSTEM) ELECTRICAL WIRING INSTALLATION, SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE								
(D)H31-01-220-001	GENERAL VISUAL INSPECTION PFD 1 L/HIRF PROTECTION ON THE DISPLAYS (PFD AND MFD)	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--
(D)H31-01-220-001	GENERAL VISUAL INSPECTION PFD 2 L/HIRF PROTECTION ON THE DISPLAYS (PFD AND MFD)	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--
(D)H31-01-220-001	GENERAL VISUAL INSPECTION MFD 1 L/HIRF PROTECTION ON THE DISPLAYS (PFD AND MFD)	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--
(D)H31-02-220-001	GENERAL VISUAL INSPECTION RIGHT L/HIRF PROTECTION ON THE GIAS	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--

(D)-- Deleted From Status (M)-- Migrated History Record



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 107 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
(D)H31-02-220-001	GENERAL VISUAL INSPECTION LEFT	L/HIRF PROTECTION ON THE GIAS			
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H31-03-220-001	GENERAL VISUAL INSPECTION NO. 3	L/HIRF PROTECTION ON THE GEAS			
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H31-03-220-001	GENERAL VISUAL INSPECTION NO. 1	L/HIRF PROTECTION ON THE GEAS			
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H31-03-220-001	GENERAL VISUAL INSPECTION NO. 2	L/HIRF PROTECTION ON THE GEAS			
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 32-LANDING GEAR					
32-00-00-001	EXTERNAL GENERAL VISUAL INSPECTION OF LANDING GEAR POLYURETHANE FILMS				
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
	SCHEDULED	AFL	299	0	ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
	SCHEDULED	AFL	227		ICAO:
					SERVICE REMARKS --
32-11-00-001	GENERAL VISUAL INSPECTION LEFT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
32-11-00-001	GENERAL VISUAL INSPECTION RIGHT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
32-11-00-001	GENERAL VISUAL INSPECTION LEFT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
	SCHEDULED	AFL	299	0	ICAO:
					SERVICE REMARKS --
32-11-00-001	GENERAL VISUAL INSPECTION RIGHT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
	SCHEDULED	AFL	299	0	ICAO:
					SERVICE REMARKS --
32-11-00-001	GENERAL VISUAL INSPECTION LEFT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
	SCHEDULED	AFL	227		ICAO:
					SERVICE REMARKS --
32-11-00-001	GENERAL VISUAL INSPECTION RIGHT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
	SCHEDULED	AFL	227		ICAO:
					SERVICE REMARKS --
32-11-00-002	RESTORE (OVERHAUL) RIGHT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
32-11-00-002	RESTORE (OVERHAUL) LEFT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
32-11-00-003	LUBRICATION LEFT MAIN GEAR ASSEMBLY				
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
32-11-00-003	LUBRICATION RIGHT MAIN GEAR ASSEMBLY					
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-11-00-003	LUBRICATION LEFT MAIN GEAR ASSEMBLY					
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
Part: PN	SN-UNKNOWN	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-11-00-003	LUBRICATION RIGHT MAIN GEAR ASSEMBLY					
Part: PN	SN-UNKNOWN	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-11-03-004	SERVICING LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY					
Part: 2310-4000-407	01081	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-11-03-004	SERVICING RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY					
Part: 2310-4000-407	01085	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: 2310-4000-407	01085	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-11-03-004	SERVICING LEFT MAIN GEAR SHOCK ABSORBER ASSEMBLY					
Part: 2310-4000-407	01081	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
Part: 2310-4000-407	01081	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-11-03-004	SERVICING RIGHT MAIN GEAR SHOCK ABSORBER ASSEMBLY					
Part: 2310-4000-407	01085	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-21-00-001	GENERAL VISUAL INSPECTION NOSE LANDING GEAR ASSEMBLY					
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
Part: PN	SN-UNKNOWN	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
32-21-00-002	RESTORE (OVERHAUL) NOSE LANDING GEAR ASSEMBLY					
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-21-00-003	LUBRICATION NOSE LANDING GEAR ASSEMBLY					
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: PN	SN-UNKNOWN	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
Part: PN	SN-UNKNOWN	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-21-05-004	SERVICING NOSE LANDING GEAR (ALUM STRUT) SHOCK ABSORBER					
Part: 2310-1100-403	00197	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: 2310-1100-403	00197	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
Part: 2310-1100-403	00197	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-21-06-005	VISUAL CHECK NOSE LANDING GEAR SHIMMY DAMPER					
Part: 2310-1500-403	00238	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: 2310-1500-403	00238	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
Part: 2310-1500-403	00238	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-35-00-001	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM					
		MOS	08-AUG-2014			TECH :
		HRS	342.40			INSP :
		AFL	227			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-35-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES					
		MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
		MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
	SCHEDULED					SERVICE REMARKS --
32-41-02-001	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER					
Part: Q3008	854244	MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
32-41-02-001	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER					
Part: Q3008	854241	MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-41-02-002	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER					
Part: Q3008	854241	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-41-02-002	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER					
Part: Q3008	854244	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-41-02-002	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER					
Part: Q3008	854241	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
	SCHEDULED					
						TECH : -
						INSP : -
						LABOR HRS : -
						ICAO: -
						SERVICE REMARKS --
32-41-02-002	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER					
Part: Q3008	854244	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
	SCHEDULED					
						TECH : CRS KX5R005N
						INSP : CRS KX5R005N
						LABOR HRS : -
						ICAO: -
						SERVICE REMARKS --
32-41-02-002	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER					
Part: Q3008	854241	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS : -
						ICAO: -
						SERVICE REMARKS --
	SCHEDULED					
32-41-11-001	FUNCTIONAL CHECK OF BRAKE HYDRAULIC ACCUMULATOR					
		MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-43-01-001	GENERAL VISUAL INSPECTION OF PARKING BRAKE/T-HANDLE CABLE MECHANICAL LINKAGE					
		MOS	03-AUG-2010			TECH :
		HRS	0			INSP :
		AFL	0			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-43-05-001	FUNCTIONAL CHECK EMERGENCY/PARKING BRAKE VALVE					
Part: 11056-5	0416	MOS	12-SEP-2014			TECH :
		HRS	351.30			INSP :
		AFL	237			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
32-43-11-001	OPERATIONAL CHECK EMERGENCY/PARKING BRAKE SHUT OFF VALVE					
Part: 2216-0001-401	00212	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
Part: 2216-0001-401	00212	MOS	12-AUG-2015			TECH :
		HRS	425.50			INSP :
		AFL	299			LABOR HRS :
						ICAO:
						SERVICE REMARKS --
	SCHEDULED					
						TECH : -
						INSP : -
						LABOR HRS : -
						ICAO: -
						SERVICE REMARKS --
Part: 2216-0001-401	00212	MOS	08-AUG-2014			TECH : CRS KX5R005N
		HRS	342.40			INSP : CRS KX5R005N
		AFL	227			LABOR HRS : -
						ICAO: -
						SERVICE REMARKS --
	SCHEDULED					

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
	PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
32-45-01-001	RESTORATION (OVERHAUL) OF RH MLG WHEEL ASSEMBLY						TECH :	INSP :	ICAO:
Part:	500-19026-401	0000629374	MOS	03-AUG-2010	MSC				
			HRS	0					
			AFL	0					
			MSC				SERVICE REMARKS	--	
32-45-01-001	RESTORATION (OVERHAUL) OF LH MLG WHEEL ASSEMBLY						TECH :	INSP :	ICAO:
Part:	500-19026-401	0000553590	MOS	03-AUG-2010	MSC				
			HRS	0					
			AFL	0					
			MSC				SERVICE REMARKS	--	
32-45-01-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LH MLG WHEEL ASSEMBLY						TECH :	INSP :	ICAO:
Part:	500-19026-401	0000553590	MOS	17-JUL-2012	MSC				
			HRS	194.40					
			AFL	112					
			MSC				SERVICE REMARKS	--	
32-45-01-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RH MLG WHEEL ASSEMBLY						TECH :	INSP :	ICAO:
Part:	500-19026-401	0000629374	MOS	17-JUL-2012	MSC				
			HRS	194.40					
			AFL	112					
			MSC				SERVICE REMARKS	--	
32-45-11-001	RESTORATION (OVERHAUL) OF NLG WHEEL ASSEMBLY						TECH :	INSP :	ICAO:
Part:	90005023-1	JUN09-0204	MOS	10-APR-2015	MSC				
			HRS	382.70					
			AFL	258					
			MSC				SERVICE REMARKS	--	
32-45-11-002	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NLG WHEEL ASSEMBLY						TECH :	INSP :	ICAO:
Part:	90005023-1	JUN09-0204	MOS	10-APR-2015	MSC				
			HRS	382.70					
			AFL	258					
			MSC				SERVICE REMARKS	--	
500-32-0001	LANDING GEAR - REPLACEMENT OF BRAKE CONTROL UNIT (BCU-1/2 TO BCU-3), SERVICE BULLETIN						TECH :	INSP :	ICAO:
			MOS		MSC				
			HRS						
			AFL						
			MSC				SERVICE REMARKS	--	
MOC:									
500-32-0001 R1	LANDING GEAR - REPLACEMENT OF BRAKE CONTROL UNIT (BCU-1/2 TO BCU-3), SERVICE BULLETIN						TECH :	INSP :	ICAO:
			MOS	03-AUG-2010	MSC				
			HRS	0					
			AFL	0					
			MSC				SERVICE REMARKS	--	

MOC:COMPLIED WITH - AT MANUFACTURE



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 113 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-32-0001 R2	LANDING GEAR - REPLACEMENT OF BRAKE CONTROL UNIT (BCU-1/2 TO BCU-3), SERVICE BULLETIN					TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
		MOS			MSC		--	
		HRS						
		AFL						
		MSC						
MOC:NOT APPLICABLE								
500-32-0002	LANDING GEAR - CONVERSION OF BRAKE ASSEMBLY 90005025 TO 90005025-2, SERVICE BULLETIN					TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
		MOS			MSC		--	
		HRS						
		AFL						
		MSC						
MOC:								
500-32-0002 R1	LANDING GEAR - CONVERSION OF BRAKE ASSEMBLY 90005025 TO 90005025-2, SERVICE BULLETIN		03-AUG-2010			TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
		MOS	0		MSC		--	
		HRS	0					
		AFL						
		MSC						
MOC:COMPLIED WITH - AT MANUFACTURE								
500-32-0002 R2	LANDING GEAR - CONVERSION OF BRAKE ASSEMBLY 90005025 TO 90005025-2, SERVICE BULLETIN					TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
		MOS			MSC		--	
		HRS						
		AFL						
		MSC						
MOC:NOT APPLICABLE								
500-32-0003	LANDING GEAR - MLG LOCKING ACTUATOR REWORK, SERVICE BULLETIN					TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
		MOS			MSC		--	
		HRS						
		AFL						
		MSC						
MOC:								
500-32-0004	LANDING GEAR - BRAKE CONTROL VALVE REPLACEMENT, SERVICE BULLETIN					TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
		MOS			MSC		--	
		HRS						
		AFL						
		MSC						
MOC:								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 114 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-32-0004 R1	LANDING GEAR - BRAKE CONTROL VALVE REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC	25-JUL-2011 137.20 68	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-32-0005	LANDING GEAR - REPLACEMENT OF EPBV (EMERGENCY/PARKING BRAKE VALVE), SERVICE BULLETIN	MOS HRS AFL MSC	17-JUL-2012 194.40 112	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-32-0006	LANDING GEAR - MLG SHOCK ABSORBER UPDATE, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-32-0006 R1	LANDING GEAR - MLG SHOCK ABSORBER UPDATE, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-32-0006 R2	LANDING GEAR - MLG SHOCK ABSORBER UPDATE, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-32-0006 R3	LANDING GEAR - MLG SHOCK ABSORBER UPDATE (SUPERSEDED BY SB 500-32-0012), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 115 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-32-0007 IN	LANDING GEAR - LANDING GEAR MANIFOLD REPLACEMENT, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-32-0007 R1	LANDING GEAR - LANDING GEAR MANIFOLD REPLACEMENT, SERVICE BULLETIN	MOS	25-JUL-2011		
		HRS	137.20	TECH :	INSP :
		AFL	68		LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-32-0008	LANDING GEAR - BRAKE CONTROL UNIT (BCU) REPLACEMENT, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-32-0008 R1	LANDING GEAR - BRAKE CONTROL UNIT (BCU) REPLACEMENT, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-32-0008 R2	LANDING GEAR - BRAKE CONTROL UNIT (BCU) REPLACEMENT , SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-32-0008 R3	LANDING GEAR - BRAKE CONTROL UNIT (BCU) REPLACEMENT, SERVICE BULLETIN	MOS	16-MAY-2013		
		HRS	254.60	TECH :	INSP :
		AFL	144		LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 116 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-32-0008 R4	LANDING GEAR - BRAKE CONTROL UNIT (BCU) REPLACEMENT (SUPERSEDED BY SB 500-32-0011 R2), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-32-0010	LANDING GEAR - NLG SHOCK STRUT BEARING REPLACEMENT, SERVICE BULLETIN	MOS	17-JUL-2012	TECH :	INSP :
		HRS	194.40		LABOR HRS :
		AFL	112		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH					
500-32-0010 R1	LANDING GEAR - NLG SHOCK STRUT BEARING REPLACEMENT, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-32-0011	LANDING GEAR - BRAKE CONTROL UNIT (BCU) REPLACEMENT, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-32-0011 R1	LANDING GEAR - BRAKE CONTROL UNIT (BCU) REPLACEMENT, SERVICE BULLETIN	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH					
500-32-0011 R2	LANDING GEAR - BRAKE CONTROL UNIT (BCU) REPLACEMENT, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 117 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-32-0012	LANDING GEAR - REWORK OF THE MLG SHOCK STRUT, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-32-0012 R1	LANDING GEAR - REWORK OF THE MLG SHOCK STRUT, SERVICE BULLETIN	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH					
500-32-0013	LANDING GEAR - CORRECTION OF THE WHEEL AXLE TORQUE OF MLG AND NLG, SERVICE BULLETIN	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH					
500-32-0014	LANDING GEAR - EMERGENCY AND NORMAL BRAKE HYDRAULIC HOSES - REPLACEMENT, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
Z700-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR BAY	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 118 of 235

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
	PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 33-LIGHTS						
33-43-01-001	DISCARD LH WING NAVIGATION/STROBE LIGHTS					
Part:	84016-1	000210	MOS	03-AUG-2010	TECH :	INSP :
			HRS	0		LABOR HRS :
			AFL	0		ICAO:
						SERVICE REMARKS --
33-43-01-001	DISCARD RH WING NAVIGATION/STROBE LIGHTS					
Part:	84016-2	000224	MOS	03-AUG-2010	TECH :	INSP :
			HRS	0		LABOR HRS :
			AFL	0		ICAO:
						SERVICE REMARKS --
33-43-01-002	GENERAL VISUAL INSPECTION OF RH WING NAVIGATION/STROBE LIGHTS					
Part:	84016-2	000224	MOS	03-AUG-2010	TECH :	INSP :
			HRS	0		LABOR HRS :
			AFL	0		ICAO:
						SERVICE REMARKS --
33-43-01-002	GENERAL VISUAL INSPECTION OF LH WING NAVIGATION/STROBE LIGHTS					
Part:	84016-1	000210	MOS	03-AUG-2010	TECH :	INSP :
			HRS	0		LABOR HRS :
			AFL	0		ICAO:
						SERVICE REMARKS --
500-33-0001	LIGHTS - REPLACEMENT OF THE LIGHTS CONTROL PANEL, SERVICE BULLETIN					
			MOS		TECH :	INSP :
			HRS			LABOR HRS :
			AFL			ICAO:
			MSC		MSC	SERVICE REMARKS --
MOC:						
500-33-0001 REV 1	LIGHTS - REPLACEMENT OF THE LIGHTS CONTROL PANEL, SERVICE BULLETIN					
			MOS		TECH :	INSP :
			HRS			LABOR HRS :
			AFL			ICAO:
						SERVICE REMARKS --
MOC:						
500-33-0002	LIGHTS - ELECTRICAL CONNECTOR P0030 AND P0031 KEY-WAY RE-ORIENTATION FOR NAV/STROBE LIGHTS PNS 84056-8 AND 84056-7, SERVICE BULLETIN					
			MOS		TECH :	INSP :
			HRS			LABOR HRS :
			AFL			ICAO:
			MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE						
500-33-0002 R1	LIGHTS - ASSISTANCE TO REPLACE NAV/STROBE LIGHTS PN 84056-3/ 84056-4 WITH PN 84056-7/84056-8, SERVICE BULLETIN					
			MOS		TECH :	INSP :
			HRS			LABOR HRS :
			AFL			ICAO:
			MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE						

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 34-NAVIGATION					
34-11-00-001	FUNCTIONAL CHECK INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT				
Part: C16221ANA01	C16221015108	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
34-11-02-001	RESTORATION PITOT-STATIC PROBE (CLEANING)				
Part: 101469-4-003	872666	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
34-15-00-001	FUNCTIONAL CHECK (CALIBRATION) OF AIR DATA SYSTEM				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
(D)34-15-00-001	FUNCTIONAL CHECK NO. 2 GDC 74B AIR DATA COMPUTER UNIT (CALIBRATION) OF AIR DATA SYSTEM				
		MOS		TECH :	INSP :
		HRS		-	LABOR HRS :
		AFL			ICAO:
	UNSCHEDULED				SERVICE REMARKS --
(D)34-15-00-001	FUNCTIONAL CHECK NO. 1 GDC 74B AIR DATA COMPUTER UNIT (CALIBRATION) OF AIR DATA SYSTEM				
		MOS		TECH :	INSP :
		HRS		-	LABOR HRS :
		AFL			ICAO:
	UNSCHEDULED				SERVICE REMARKS --
34-15-00-001	FUNCTIONAL CHECK OF AIR DATA SYSTEM				
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
		AFL	227		ICAO:
	SCHEDULED				SERVICE REMARKS --
34-15-00-002	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS				
		MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
34-15-00-003	SPECIAL DETAILED INSPECTION OF STATIC PORT SURROUNDING PLATE FOR FLUSHNESS				
		MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
(D)34-15-00-004	FUNCTIONAL CHECK NO. 2 GDC 74B AIR DATA COMPUTER UNIT OF AIR DATA SYSTEM				
Part: 011-01110-00	43806045	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40	-	LABOR HRS :
		AFL	227		ICAO:
	UNSCHEDULED				SERVICE REMARKS --
		MSC		MSC	
(D)34-15-00-004	FUNCTIONAL CHECK NO. 1 GDC 74B AIR DATA COMPUTER UNIT OF AIR DATA SYSTEM				
Part: 011-01110-00	43806031	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40	-	LABOR HRS :
		AFL	227		ICAO:
	UNSCHEDULED				SERVICE REMARKS --
		MSC		MSC	
34-15-03-001	RESTORATION OF PITOT PROBE (CLEANING)				
		MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
34-23-00-001	FUNCTIONAL CHECK MAGNETIC COMPASS				
Part: KCA0120W	BD3750609	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 120 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
34-52-00-001	FUNCTIONAL CHECK NO. 2	TRANSPONDER SYSTEM			
		MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
34-52-00-001	FUNCTIONAL CHECK NO. 1	TRANSPONDER SYSTEM			
		MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
500-34-0001	NAVIGATION - INSPECTION/CORRECTION OF THE INSTALLATION POSITION OF THE DUAL STATIC PORTS, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-34-0001 PART I	PERFORM NAVIGATION - INSPECTION/CORRECTION OF THE INSTALLATION POSITION OF THE DUAL STATIC PORTS, SERVICE BULLETIN	INSPECTION OF THE DUAL STATIC PORTS PN INSTALLATION			
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-34-0001 PART II	PERFORM NAVIGATION - INSPECTION/CORRECTION OF THE INSTALLATION POSITION OF THE DUAL STATIC PORTS, SERVICE BULLETIN	REINSTALLATION OF THE DUAL STATIC PORTS			
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-34-0002	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-34-0002 R1	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 121 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0002 R10	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-34-0002 R11	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-34-0002 R12	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-34-0002 R13	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-34-0002 R14	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-34-0002 R15	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 122 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0002 R2	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
500-34-0002 R3	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-34-0002 R4	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-34-0002 R5	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-34-0002 R6	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-34-0002 R7	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 123 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-34-0002 R8	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:NOT APPLICABLE								
500-34-0002 R9	NAVIGATION - ACTIVATION OF THE CHARTVIEW, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:NOT APPLICABLE								
500-34-0003	NAVIGATION - ACTIVATION OF THE FLITECHART, SERVICE BULLETIN	MOS	03-AUG-2010			TECH :	INSP :	ICAO:
		HRS	0				LABOR HRS :	
		AFL	0				SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE								
500-34-0003 R1	NAVIGATION - ACTIVATION OF THE FLITECHART, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:NOT APPLICABLE								
500-34-0004	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								
500-34-0004 R1	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS				TECH :	INSP :	ICAO:
		HRS					LABOR HRS :	
		AFL		MSC			SERVICE REMARKS	--
		MSC						
MOC:								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 124 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0004 R2	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R2 PART I	PERFORM NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN REWORK OF THE WING-TO-FUSELAGE FAIRING	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R2 PART II	PERFORM NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN REWORK OF THE UPPER FUSELAGE AND INSTALLATION OF THE HARNESS SUPPORTS	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R2 PART III	PERFORM NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN REWORK OF THE PALMER PANEL	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R2 PART IV	PERFORM NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN INSTALLATION OF THE ELECTRICAL HARNESS	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 125 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0004 R2 PART V	PERFORM NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN INSTALLATION OF THE ANTENNA CABLES, POWER AMPLIFIER (PA/LNA), AND TCAS UNIT				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R3	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R3 PART I	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE WING-TO-FUSELAGE FAIRING				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R3 PART II	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE UPPER FUSELAGE AND INSTALLATION OF THE HARNESS SUPPORTS				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R3 PART III	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE PALMER PANEL				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
500-34-0004 R3 PART IV	INSTALLATION NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE ELECTRICAL HARNESS				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 126 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-34-0004 R3 PART V	INSTALLATION NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE ANTENNA CABLES, POWER AMPLIFIER (PA/LNA), AND TCAS UNIT	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-34-0004 R4	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-34-0004 R4 PART I	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF, STRUCTURE AND PALMER, ELECTRICAL AND TCAS EQUIPMENT INSTALLATION.	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-34-0004 R4 PART II	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF AND STRUCTURE; ELECTRICAL AND TCAS EQUIPMENT INSTALLATION.	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-34-0004 R4 PART III	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 127 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0004 R4 PART IV	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE BOTTOM ANTENNA AND TCAS II TOP ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC		MSC	
TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --					
MOC:NOT APPLICABLE					
500-34-0004 R5	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS HRS AFL MSC		MSC	
TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --					
MOC:NOT APPLICABLE					
500-34-0004 R5 PART I	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF, STRUCTURE AND PALMER, ELECTRICAL AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC		MSC	
TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --					
MOC:NOT APPLICABLE					
500-34-0004 R5 PART II	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF AND STRUCTURE; ELECTRICAL AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC		MSC	
TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --					
MOC:NOT APPLICABLE					
500-34-0004 R5 PART III	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC		MSC	
TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --					
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 128 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-34-0004 R5 PART IV	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE BOTTOM ANTENNA AND TCAS II TOP ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-34-0004 R6	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-34-0004 R6 PART I	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF, STRUCTURE AND PALMER, ELECTRICAL AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-34-0004 R6 PART II	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF AND STRUCTURE; ELECTRICAL AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-34-0004 R6 PART III	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-34-0004 R6 PART IV	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE BOTTOM ANTENNA AND TCAS II TOP ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			

(D)-- Deleted From Status (M)-- Migrated History Record



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 129 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-34-0004 R7	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-34-0004 R7 PART I	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF, STRUCTURE AND PALMER, ELECTRICAL AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-34-0004 R7 PART II	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN REWORK ON THE WFF AND STRUCTURE; ELECTRICAL AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-34-0004 R7 PART III	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-34-0004 R7 PART IV	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE BOTTOM ANTENNA AND TCAS II TOP ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			
500-34-0004 R8	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
			MSC
MOC:NOT APPLICABLE			

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 130 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0004 R8 PART I	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF, STRUCTURE AND PALMER, ELECTRICAL AND TCAS EQUIPMENT INSTALLATION	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-34-0004 R8 PART II	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF AND STRUCTURE; ELECTRICAL AND TCAS EQUIPMENT INSTALLATION	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-34-0004 R8 PART III	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-34-0004 R8 PART IV	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE BOTTOM ANTENNA AND TCAS II TOP ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-34-0004 R9	NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-34-0004 R9 PART I	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF, STRUCTURE AND PALMER, ELECTRICAL AND TCAS EQUIPMENT INSTALLATION.	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 131 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0004 R9 PART II	REWORK NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN ON THE WFF AND STRUCTURE; ELECTRICAL AND TCAS EQUIPMENT INSTALLATION				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-34-0004 R9 PART III	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-34-0004 R9 PART IV	REMOVAL NAVIGATION - INSTALLATION OF THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) I, SERVICE BULLETIN OF THE BOTTOM ANTENNA AND TCAS II TOP ANTENNA COVERS AND TCAS EQUIPMENT INSTALLATION				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-34-0006	NAVIGATION - REPLACEMENT OF THE DUAL STATIC PORTS, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-34-0006 R1	NAVIGATION - REPLACEMENT OF THE DUAL STATIC PORTS, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-34-0006 R2	NAVIGATION - REPLACEMENT OF THE DUAL STATIC PORTS, SERVICE BULLETIN				
		MOS	25-JUL-2011	TECH :	INSP :
		HRS	137.20		LABOR HRS :
		AFL	68		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 132 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0007	NAVIGATION - REPLACEMENT OF THE PITOT-STATIC PROBE, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
500-34-0007 R1	NAVIGATION - REPLACEMENT OF THE PITOT-STATIC PROBE, SERVICE BULLETIN	MOS	25-JUL-2011		
		HRS	137.20	TECH :	INSP :
		AFL	68		LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-34-0010	NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-34-0010 R1	NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-34-0010 R1 PART I	AIRCRAFT NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN EQUIPPED WITH XPDR 1	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-34-0010 R1 PART II	AIRCRAFT NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN EQUIPPED WITH XPDR 1/2	MOS			
		HRS		TECH :	INSP :
		AFL			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 133 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-34-0010 R2	NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-34-0010 R2 PART I	NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
AIRCRAFT EQUIPPED WITH XPDR 1 MSC			
MOC:NOT APPLICABLE			
500-34-0010 R2 PART II	NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
AIRCRAFT EQUIPPED WITH XPDR 1/2 MSC			
MOC:NOT APPLICABLE			
500-34-0010 R3	NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:NOT APPLICABLE			
500-34-0010 R3 PART I	NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
AIRCRAFT EQUIPPED WITH XPDR 1 MSC			
MOC:NOT APPLICABLE			
500-34-0010 R3 PART II	NAVIGATION - REPLACEMENT OF THE TRANSPONDERS 1/2 WITH ADS-B OUT FUNCTIONALITY, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
AIRCRAFT EQUIPPED WITH XPDR 1/2 MSC			
MOC:NOT APPLICABLE			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 134 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-34-0011	NAVIGATION - DME (DISTANCE MEASURING EQUIPMENT) 1 INSTALLATION, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
500-34-0011 R1	NAVIGATION - DME (DISTANCE MEASURING EQUIPMENT) 1 INSTALLATION, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE					
FAA 2005-01-19	APPLIANCE AD - TO PREVENT INTERROGATING A/C FROM POSSIBLY RECEIVING INACCURATE REPLIES FROM A/C EQUIPPED WITH GARMIN GTX33/33D/330/330D MODE S TRANSPONDERS	MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		AFL	258		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE - BY SOFTWARE					
FAA 2010-07-02	APPLIANCE AD - TO ENSURE THAT THE FLIGHTCREW HAS ACCURATE LOCALIZER AND GLIDESLOPE DEVIATION INDICATIONS	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
FAA 2010-09-04	APPLIANCE AD - TO PROVIDE THE FLIGHTCREW WITH PROCEDURES TO RECOVER FROM OR WORK AROUND THESE SOFTWARE ANOMALIES DURING FLIGHT	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
FAA 2012-02-08	APPLIANCE AD - PREVENT TCAS UNITS FROM DROPPING TRACKS	MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		AFL	258		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:NOT APPLICABLE - BY EQUIPMENT					

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	TECH :	INSP :	ICAO:
FAA 2014-05-27	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION	MOS	04-APR-2014					
		HRS	314.80				LABOR HRS :	
		AFL	203				SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE - THIS EQUIPMENT IS NOT INSTALLED								
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS	MOS	12-AUG-2015			TECH : CRS KX5R005N	INSP : CRS KX5R005N	
		HRS	425.50				LABOR HRS :	ICAO:
		AFL	299				SERVICE REMARKS	--
		MSC		MSC				
MOC:NOT APPLICABLE - FOUND TO BE N/A BY AFFECTED EQUIPMENT NOT INSTALLED IN THIS AIRCRAFT.								
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		AFL					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
(D)H34-01-220-001	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE AHRs	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--
(D)H34-02-551-001	GENERAL VISUAL INSPECTION LEFT L/HIRF PROTECTION ON THE MAGNETOMETER	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--
(D)H34-02-551-001	GENERAL VISUAL INSPECTION RIGHT L/HIRF PROTECTION ON THE MAGNETOMETER	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--
(D)H34-03-224-001	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE PITOT-STATIC PROBE	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--
(D)H34-04-220-001	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE AIR DATA COMPUTER	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--
(D)H34-05-220-001	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE STATIC PORT	MOS	03-AUG-2010			TECH :	INSP :	
		HRS	0			-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0				SERVICE REMARKS	--



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 136 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
(D)H34-06-220-001	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE PITOT PROBE	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --
(D)H34-07-220-001	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE INTEGRATED ELECTRONIC STANDBY INSTRUMENT UNIT	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0	-	LABOR HRS :
	UNSCHEDULED	AFL	0		ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.		C/W	TIME SINCE	C/W	TIME SINCE			
CHAPTER 35-OXYGEN									
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE								
		MOS	19-JUL-2013				TECH :	INSP :	
		HRS	262.90					LABOR HRS :	ICAO:
		AFL	154					SERVICE REMARKS	--
35-01-00-001	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION								
		MOS	12-AUG-2015				TECH :	INSP :	
		HRS	425.50					LABOR HRS :	ICAO:
		AFL	299					SERVICE REMARKS	--
		MOS	12-AUG-2015				TECH :	INSP :	
		HRS	425.50				-	LABOR HRS :	ICAO:
	SCHEDULED	AFL	299				0	SERVICE REMARKS	--
35-02-01-001	FUNCTIONAL CHECK (HYDROSTATIC TEST) 50 CU.FT OXYGEN CYLINDER								
Part: 4441122-050	0252-1181	MOS	08-AUG-2014				TECH :	INSP :	
		HRS	342.40					LABOR HRS :	ICAO:
		AFL	227					SERVICE REMARKS	--
(D)35-02-01-002	RESTORE 50 CU.FT OXYGEN CYLINDER REGULATOR								
Part: 4441122-050	0252-1181	MOS	08-AUG-2014				TECH :	INSP :	
		HRS	342.40				-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	227					SERVICE REMARKS	--
35-02-01-003	DISCARD 50 CU.FT OXYGEN CYLINDER								
Part: 4441122-050	0252-1181	MOS	01-DEC-2009				TECH :	INSP :	
		HRS	0					LABOR HRS :	ICAO:
		AFL	0					SERVICE REMARKS	--
35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASKS AND STOWAGE BOX								
		MOS	19-JUL-2013				TECH :	INSP :	
		HRS	262.90					LABOR HRS :	ICAO:
		AFL	154					SERVICE REMARKS	--
35-11-00-002	OPERATIONAL CHECK OF CREW OXYGEN MASKS AND STOWAGE BOX								
		MOS	03-AUG-2010				TECH :	INSP :	
		HRS	0					LABOR HRS :	ICAO:
		AFL	0					SERVICE REMARKS	--
		MSC				MSC			
35-11-02-001	DETAILED VISUAL INSPECTION RH CREW MASK SWEEP								
Part: 174232-93	28598	MOS	19-JUL-2013				TECH :	INSP :	
		HRS	262.90					LABOR HRS :	ICAO:
		AFL	154					SERVICE REMARKS	--
35-11-02-001	DETAILED VISUAL INSPECTION LH CREW MASK SWEEP								
Part: 174232-93	28599	MOS	19-JUL-2013				TECH :	INSP :	
		HRS	262.90					LABOR HRS :	ICAO:
		AFL	154					SERVICE REMARKS	--
35-11-02-002	RESTORATION (OVERHAUL) OF RH CREW MASK SWEEP								
Part: 174232-93	28598	MOS					TECH :	INSP :	
		HRS						LABOR HRS :	ICAO:
		AFL						SERVICE REMARKS	--
35-11-02-002	RESTORATION (OVERHAUL) OF LH CREW MASK SWEEP								
Part: 174232-93	28599	MOS					TECH :	INSP :	
		HRS						LABOR HRS :	ICAO:
		AFL						SERVICE REMARKS	--

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.		C/W	TIME SINCE	C/W	TIME SINCE			
35-11-02-003	DETAILED INSPECT LH CREW MASK SWEEP						TECH :	INSP :	
Part: 174232-93	28599	MOS	03-AUG-2010					LABOR HRS :	ICAO:
		HRS	0					SERVICE REMARKS	--
		AFL	0						
		MSC			MSC				
35-11-02-003	DETAILED VISUAL INSPECTION RH CREW MASK SWEEP						TECH :	INSP :	
Part: 174232-93	28598	MOS	03-AUG-2010					LABOR HRS :	ICAO:
		HRS	0					SERVICE REMARKS	--
		AFL	0						
		MSC			MSC				
35-11-04-001	DETAILED VISUAL INSPECTION OF CREW GOGGLES						TECH :	INSP :	
		MOS	19-JUL-2013					LABOR HRS :	ICAO:
		HRS	262.90					SERVICE REMARKS	--
		AFL	154						
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE						TECH :	INSP :	
		MOS	19-JUL-2013					LABOR HRS :	ICAO:
		HRS	262.90					SERVICE REMARKS	--
		AFL	154						
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE						TECH :	INSP :	
		MOS	19-JUL-2013					LABOR HRS :	ICAO:
		HRS	262.90					SERVICE REMARKS	--
		AFL	154						
35-21-01-001	DETAILED VISUAL INSPECTION OF PASSENGER OXYGEN MASKS						TECH :	INSP :	
		MOS	19-JUL-2013					LABOR HRS :	ICAO:
		HRS	262.90					SERVICE REMARKS	--
		AFL	154						
35-31-01-001	DISCARD PROTECTIVE BREATHING EQUIPMENT (PBE)						TECH :	INSP :	
Part: PN	SN-UNKNOWN	MOS						LABOR HRS :	ICAO:
		HRS						SERVICE REMARKS	--
		AFL							
		MSC			MSC				
500-35-0001	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR), SERVICE BULLETIN						TECH :	INSP :	
		MOS						LABOR HRS :	ICAO:
		HRS						SERVICE REMARKS	--
		AFL							
		MSC			MSC				
MOC:									
500-35-0001 R1	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR), SERVICE BULLETIN						TECH :	INSP :	
		MOS						LABOR HRS :	ICAO:
		HRS						SERVICE REMARKS	--
		AFL							
		MSC			MSC				
MOC:									



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 139 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-35-0001 R2	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR), SERVICE BULLETIN	MOS HRS AFL MSC	25-JUL-2011 137.20 68	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-35-0001 R3	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-35-0001 R4	OXYGEN - REPLACEMENT OF THE ALTITUDE COMPENSATING REGULATOR (ACR), SERVICE BULLETIN	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
FAA 2010-11-05	APPLIANCE AD - TO PREVENT AN OXYGEN CYLINDER FROM RUPTURING	MOS HRS AFL MSC	10-APR-2015 382.70 258	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE - BY EQUIPMENT					
FAA 2011-01-09	APPLIANCE AD - TO PREVENT PBE UNITS FROM IGNITING	MOS HRS AFL MSC	10-APR-2015 382.70 258	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE - BY EQUIPMENT					
FAA 2011-04-09	TO PREVENT HAZARD OF CHEMICAL OXYGEN GENERATORS IN THE LAVATORIES.(SUPERSEDED BY AD 2012-11-09)	MOS HRS AFL MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 140 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
FAA 2011-14-08	APPLIANCE AD - TO PREVENT THE IN-LINE FLOW INDICATORS OF THE OXYGEN MASK ASSEMBLY FROM FRACTURING AND SEPARATING	MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		AFL	258		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE - BY EQUIPMENT					
FAA 2011-14-08 (G)	DO TO PREVENT THE IN-LINE FLOW INDICATORS OF THE OXYGEN MASK ASSEMBLY FROM FRACTURING AND SEPARATING A RECORDS CHECK TO DETERMINE IF ANY OXYGEN MASK ASSEMBLY PART NUMBER	MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		AFL	258		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE - BY EQUIPMENT					
FAA 2011-14-08 (H)	MODIFY TO PREVENT THE IN-LINE FLOW INDICATORS OF THE OXYGEN MASK ASSEMBLY FROM FRACTURING AND SEPARATING THE OXYGEN MASK ASSEMBLY	MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		AFL	258		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE - BY EQUIPMENT					
FAA 2012-11-09	ELIMINATE ALL CHEMICAL OXYGEN GENERATORS AND INSTALL NEW SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
FAA 2012-11-09 PARA (G)	DISCHARGE ELIMINATE ALL CHEMICAL OXYGEN GENERATORS AND INSTALL NEW SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES ALL CHEMICAL OXYGEN GENERATORS	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
FAA 2012-11-09 PARA (L)	INSTALL ELIMINATE ALL CHEMICAL OXYGEN GENERATORS AND INSTALL NEW SUPPLEMENTAL OXYGEN SYSTEM IN AFFECTED LAVATORIES A SUPPLEMENTAL OXYGEN SYSTEM THAT MEETS ALL APPLICABLE SECTIONS OF PARTS 25 AND 121 OF THE FEDERAL AVIATION REGULATIONS (14 CFR PART 25 AND 14 CFR PART 121) IN EACH LAVATORY	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 141 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSSES				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 142 of 235

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE				
CHAPTER 36-PNEUMATIC									
36-11-00-001	OPERATIONAL CHECK LH PYLON PRESSURE REGULATING SHUTOFF VALVE								
Part:	1330310-1	430	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
36-11-00-001	OPERATIONAL CHECK RH PYLON PRESSURE REGULATING SHUTOFF VALVE								
Part:	1330310-1	438	MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
36-11-02-001	DETAILED INSPECT OF BLEED LINE WATER DRAINS								
			MOS	08-AUG-2014			TECH :	INSP :	
			HRS	342.40				LABOR HRS :	ICAO:
			AFL	227				SERVICE REMARKS	--
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS								
			MOS	03-AUG-2010			TECH :	INSP :	
			HRS	0				LABOR HRS :	ICAO:
			AFL	0				SERVICE REMARKS	--
500-36-0001	PNEUMATIC - PRESSURE REGULATING SHUTOFF VALVE (PRSOV) REPLACEMENT, SERVICE BULLETIN								
			MOS				TECH :	INSP :	
			HRS					LABOR HRS :	ICAO:
			AFL					SERVICE REMARKS	--
			MSC		MSC				
MOC:NOT APPLICABLE									
500-36-0001 R1	PNEUMATIC - PRESSURE REGULATING SHUTOFF VALVE (PRSOV) REPLACEMENT, SERVICE BULLETIN								
			MOS				TECH :	INSP :	
			HRS					LABOR HRS :	ICAO:
			AFL					SERVICE REMARKS	--
			MSC		MSC				
MOC:NOT APPLICABLE									
500-36-0001 R2	PNEUMATIC - PRESSURE REGULATING SHUTOFF VALVE (PRSOV) REPLACEMENT, SERVICE BULLETIN								
			MOS				TECH :	INSP :	
			HRS					LABOR HRS :	ICAO:
			AFL					SERVICE REMARKS	--
			MSC		MSC				
MOC:									
500-36-0001 R3	PNEUMATIC - PRESSURE REGULATING SHUTOFF VALVE (PRSOV) REPLACEMENT, SERVICE BULLETIN								
			MOS				TECH :	INSP :	
			HRS					LABOR HRS :	ICAO:
			AFL					SERVICE REMARKS	--
			MSC		MSC				
MOC:									



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 143 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 52-DOORS					
500-52-0001	DOORS - MODIFICATION FROM STANDARD MAIN DOOR TO PREMIUM MAIN DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-52-0001 R1	DOORS - MODIFICATION FROM STANDARD MAIN DOOR TO PREMIUM MAIN DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-52-0001 R2	DOORS - MODIFICATION FROM STANDARD MAIN DOOR TO PREMIUM MAIN DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-52-0001 R3	DOORS - MODIFICATION FROM STANDARD MAIN DOOR TO PREMIUM MAIN DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-52-0001 R4	DOORS - MODIFICATION FROM STANDARD MAIN DOOR TO PREMIUM MAIN DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
500-52-0001 R5	DOORS - MODIFICATION FROM STANDARD MAIN DOOR TO PREMIUM MAIN DOOR, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-52-0002	DOORS - IMPROVEMENT ON THE BATTERY LOCK CAM DOOR, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
52-10-01-001	EXTERNAL GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY STRUCTURE				
Part: 500-09910-449	0000554353	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:
52-10-01-002	INTERNAL GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY STRUCTURE				
Part: 500-09910-449	0000554353	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		SERVICE REMARKS -- ICAO:
52-10-01-01-901	INTERNAL DETAILED VISUAL INSPECTION MAIN DOOR STRUCTURE UPPER EXTERNAL FRAME, UPPER HORIZONTAL STRINGER, EXTERNAL VERTICAL FRAME, AND LOWER HORIZONTAL FRAME.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	SERVICE REMARKS -- ICAO:
52-10-01-01-902	EXTERNAL DETAILED VISUAL INSPECTION MAIN DOOR STRUCTURE DOOR SKIN, VENT FLAP SKIN AND SKIN/VENT FLAP SKIN FASTENER.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	SERVICE REMARKS -- ICAO:
52-10-02-01-901	INTERNAL DETAILED VISUAL INSPECTION MAIN DOOR LATCH MECHANISM LATCH PINS.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	SERVICE REMARKS -- ICAO:
52-10-20-001	GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY RUBBER SEAL				
Part: 500-09910-449	0000554353	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:
52-11-00-001	GENERAL VISUAL INSPECTION MAIN PAX DOOR ASSEMBLY LOCKING AND ACTUATING MECHANISM				
Part: 500-09910-449	0000554353	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:
52-11-00-002	LUBRICATION LATCH PINS				
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		SERVICE REMARKS -- ICAO:
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
		AFL	299	0	SERVICE REMARKS -- ICAO:
	SCHEDULED				
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
		AFL	227		SERVICE REMARKS -- ICAO:
	SCHEDULED				
52-13-21-001	DISCARD MAIN DOOR BALANCE ASSEMBLY GEAR SECTOR				
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.		C/W	TIME SINCE	C/W	TIME SINCE			
52-13-22-002	DISCARD	MAIN DOOR BALANCE ASSEMBLY	MECHANISM CABLE						
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010				TECH :	INSP :	
		HRS	0					LABOR HRS :	ICAO:
		AFL	0					SERVICE REMARKS	--
(D)52-13-22-003	DETAILED INSPECTION OF	MAIN DOOR BALANCE ASSEMBLY	MECHANISM CABLE						
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010				TECH :	INSP :	
		HRS	0				-	LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0					SERVICE REMARKS	--
52-13-23-001	DISCARD	MAIN DOOR BALANCE ASSEMBLY	PINION SHAFT						
Part: PN	SN-UNKNOWN	MOS	03-AUG-2010				TECH :	INSP :	
		HRS	0					LABOR HRS :	ICAO:
		AFL	0					SERVICE REMARKS	--
52-20-01-01-901	INTERNAL DETAILED VISUAL INSPECTION	EMERGENCY DOOR STRUCTURE SPAR AND FRAMES.							
		MOS					TECH :	INSP :	
		HRS						LABOR HRS :	ICAO:
		AFL					0	SERVICE REMARKS	--
52-20-01-01-902	EXTERNAL - DETAILED INSPECTION	EMERGENCY DOOR STRUCTURE DOOR SKIN, VENT FLAP SKIN AND SKIN/VENT FLAP SKIN FASTENER.							
		MOS					TECH :	INSP :	
		HRS						LABOR HRS :	ICAO:
		AFL					0	SERVICE REMARKS	--
52-20-20-001	GENERAL VISUAL INSPECTION	CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY	LOCKING AND ACTUATING MECHANISM						
Part: 500-09700-431	0000554808	MOS	08-AUG-2014				TECH :	INSP :	
		HRS	342.40					LABOR HRS :	ICAO:
		AFL	227					SERVICE REMARKS	--
52-20-21-001	GENERAL VISUAL INSPECTION	CENTER FUSELAGE EMERGENCY DOOR ASSEMBLY	RUBBER SEAL						
Part: 500-09700-431	0000554808	MOS	08-AUG-2014				TECH :	INSP :	
		HRS	342.40					LABOR HRS :	ICAO:
		AFL	227					SERVICE REMARKS	--
52-31-20-001	GENERAL VISUAL INSPECTION	OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM							
		MOS	08-AUG-2014				TECH :	INSP :	
		HRS	342.40					LABOR HRS :	ICAO:
		AFL	227					SERVICE REMARKS	--
52-32-20-001	GENERAL VISUAL INSPECTION	OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM							
		MOS	08-AUG-2014				TECH :	INSP :	
		HRS	342.40					LABOR HRS :	ICAO:
		AFL	227					SERVICE REMARKS	--

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 53-FUSELAGE					
500-53-0001	FUSELAGE - PROTECTION TO PREVENT INTERFERENCE BETWEEN RUDDER CABLE AND AILERON QUADRANT, SERVICE BULLETIN				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-53-0002	FUSELAGE - REPLACEMENT OF THE LATERAL WINDSHIELD LOWER-BEAM, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-53-0003	FUSELAGE - REPLACEMENT OF UPPER FITTINGS ATTACHMENT PINS OF FRAME 16A, FOR AIRCRAFT PROVISIONED TO INSTALL THE BELTED TOILET, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
53-00-00-001	EXTERNAL GENERAL VISUAL INSPECTION OF FUSELAGE POLYURETHANE FILMS				
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
		AFL	299	0	ICAO:
	SCHEDULED				SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
		AFL	227		ICAO:
	SCHEDULED				SERVICE REMARKS --
53-05-00-001	DETAILED VISUAL INSPECTION OF FUSELAGE DRAINS				
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
		AFL	299	0	ICAO:
	SCHEDULED				SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
		AFL	227		ICAO:
	SCHEDULED				SERVICE REMARKS --
53-10-00-001	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE LOWER SKIN PANEL AND COCKPIT FLOOR STRUCTURES				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
53-10-00-002	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS, SKIN SPLICES AND WINDSHIELD CUTOUT STRUCTURE	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
53-10-01-01-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE MACHINE FR07, BEAMS, POSTS, GUSSET (SPLICES)	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-01-01-902	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE MACHINE FR07, BEAMS, POSTS, GUSSET (SPLICES)	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-01-01-903	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT STRUCTURE SKIN PANEL AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-02-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS FRAMES AND SPLICES.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-02-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS SKIN-TO-FRAMES AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-02-02-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS STRINGERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-02-02-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LEFT AND RIGHT SIDE SKIN PANELS SKIN-TO-STRINGERS AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-03-01-901	INTERNAL GENERAL VISUAL INSPECTION FORWARD FUSELAGE LOWER SKIN PANEL FRAMES AND STRINGERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-03-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LOWER SKIN PANEL SKIN-TO-FRAME/STRINGERS AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-04-01-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES LONGITUDINAL SPLICE	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-04-01-902	EXTERNAL - DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES - SKIN-TO-LONGITUDINAL SPLICE AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-10-04-02-901	INTERNAL DETAILED INSPECTION FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES CIRCUMFERENTIAL SPLICE.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 148 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
53-10-04-02-902	EXTERNAL - DETAILED INSPECTION	FORWARD FUSELAGE LONGITUDINAL AND CIRCUNFERENTIAL SKIN SPLICES	SKIN-TO-CIRCUMFERENTIAL-SPLICE AREA.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS
			ICAO:
			0
53-10-05-001	EXTERNAL DETAILED VISUAL INSPECTION	OF FORWARD FUSELAGE PRESSURE BULKHEAD	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS
			ICAO:
53-10-05-002	INTERNAL DETAILED VISUAL INSPECTION	OF FORWARD FUSELAGE PRESSURE BULKHEAD	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS
			ICAO:
53-10-05-01-901	INTERNAL GENERAL VISUAL INSPECTION	FORWARD FUSELAGE PRESSURE BULKHEAD.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS
			ICAO:
			0
53-10-06-002	INTERNAL DETAILED VISUAL INSPECTION	OF FORWARD FUSELAGE FORWARD SKIN PANELS	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS
			ICAO:
53-10-07-001	EXTERNAL GENERAL VISUAL INSPECTION	OF NOSE LANDING GEAR WHEELWELL METALLIC STRUCTURE	
	MOS	08-AUG-2014	TECH :
	HRS	342.40	INSP :
	AFL	227	LABOR HRS :
			SERVICE REMARKS
			ICAO:
53-10-07-01-901	EXTERNAL SPECIAL DETAILED INSPECTION	NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE (EDDY CURRENT) TRUNION.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS
			ICAO:
			0
53-10-07-02-901	EXTERNAL - DETAILED INSPECTION	NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS
			ICAO:
			0
53-10-07-02-902	EXTERNAL SPECIAL DETAILED INSPECTION	NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE (EDDY CURRENT) DRAG LOCKING STRUTS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS
			ICAO:
			0
53-10-08-002	INTERNAL GENERAL VISUAL INSPECTION	OF NOSE LANDING GEAR WHEELWELL COMPOSITE STRUCTURE	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS
			ICAO:
			--
53-10-08-01-901	EXTERNAL - DETAILED INSPECTION	NOSE LANDING GEAR WHEEL COMPOSITE STRUCTURE UPPER PANEL AND SIDE SKIN.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS
			ICAO:
			0
53-20-00-001	EXTERNAL DETAILED VISUAL INSPECTION	OF CENTER FUSELAGE SKIN PANELS AND SKIN SPLICES	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS
			ICAO:
			--

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 149 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
53-20-00-002	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE SKIN PANELS, SKIN SPLICES, AND FLOOR STRUCTURE	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
53-20-00-003	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TO-WING LATERAL AND CENTER LINKS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
53-20-01-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 1R TO 6L) FRAMES.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-01-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 1R TO 6L) SKIN TO FRAMES AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-01-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM STRINGER 1R TO 6L AND FROM FRAME 8 TO 19) STRINGERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-01-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE UPPER SKIN PANEL (FROM STRINGER 1R TO 6L AND FROM FRAME 8 TO 19) SKIN TO STRINGERS AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-02-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 2R TO 11R) FRAMES.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-02-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM FRAME 8 TO 19 AND FROM STRINGER 2R TO 11R) SKIN TO FRAMES AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-02-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM STRINGER 2R TO 11R AND FROM FRAME 8 TO 19) STRINGERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-02-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE SIDE SKIN PANEL (FROM STRINGER 2R TO 11R AND FROM FRAME 8 TO 19) SKIN TO STRINGERS AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-03-01-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) CUT-OUT REINFORCEMENT (SKIN DOUBLER).	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-03-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) SKIN TO CUT-OUT AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --
53-20-03-02-901	INTERNAL GENERAL VISUAL INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) FRAMES AND STRINGERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
53-20-03-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LOWER SKIN PANEL (FROM STRINGER 7L TO 12R AND FROM FRAME 8 TO 19) SKIN TO FRAMES AND STRINGERS AREA.		
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
53-20-04-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAP JOINT SKIN SPLICE AND CIRCUMFERENTIAL SKIN SPLICE LONGITUDINAL LAP JOINT SKIN SPLICE.		
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
53-20-04-01-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAP JOINT SKIN SPLICE AND CIRCUMFERENTIAL SKIN SPLICE LONGITUDINAL LAP JOINT SKIN SPLICE.		
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
53-20-04-02-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAP JOINT SKIN SPLICE AND CIRCUMFERENTIAL SKIN SPLICE CIRCUNFERENTIAL SKIN SPLICE.		
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
53-20-04-02-902	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE LONGITUDINAL LAP JOINT SKIN SPLICE AND CIRCUMFERENTIAL SKIN SPLICE SKIN AT CIRCUMFERENTIAL SKIN SPLICE AREA.		
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
53-20-05-002	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS	03-AUG-2010	
	MOS		TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
53-20-05-01-901	INTERNAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS SKIN (FROM STRINGER 12L TO 12R).		
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
53-20-05-01-902	EXTERNAL SPECIAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS (EDDY CURRENT) SPLICE (1ST AND 3RD ROWS) (FROM STRINGER 01R TO 01L, FROM STINGER 04R TO 07R AND FROM STRINGER 04L TO 07L).		
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
53-20-05-01-903	EXTERNAL - DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND END FITTINGS SKIN (FROM STRINGER 01R TO 01L, FROM STRINGER 04R TO 07R AND FROM STRINGER 04L TO 07L).	MOS HRS AFL	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-05-01-904	INTERNAL DETAILED INSPECTION CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES END FITTINGS	MOS HRS AFL	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-06-001	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE	MOS 08-AUG-2014 HRS 342.40 AFL 227	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-06-002	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE	MOS 08-AUG-2014 HRS 342.40 AFL 227	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-06-01-901	EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) THE DOUBLER 1 AT CORNERS OF MAIN DOOR CUTOUT STRUCTURE.	MOS HRS AFL	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-06-01-902	EXTERNAL SPECIAL DETAILED INSPECTION (EDDY CURRENT) THE SKIN AT CORNERS OF THE MAIN DOOR CUTOUT STRUCTURE.	MOS HRS AFL	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-06-01-903	EXTERNAL - DETAILED INSPECTION THE MAIN DOOR CUTOUT STRUCTURE SKIN TO DOOR CUTOUT STRUCTURE.	MOS HRS AFL	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-06-01-904	INTERNAL GENERAL VISUAL INSPECTION THE MAIN DOOR CUT-OUT STRUCTURE.	MOS HRS AFL	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-06-01-905	INTERNAL DETAILED INSPECTION MAIN DOOR CUTOUT STRUCTURE MACHINED FRAME AT LATCH PIN BOX AREA .	MOS HRS AFL	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-07-001	EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR CUTOUT STRUCTURE	MOS 08-AUG-2014 HRS 342.40 AFL 227	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-07-002	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR CUTOUT STRUCTURE	MOS 08-AUG-2014 HRS 342.40 AFL 227	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
53-20-07-01-901	INTERNAL GENERAL VISUAL INSPECTION EMERGENCY DOOR CUTOUT STRUCTURE (FROM STRINGER 3R TO 7R AND FROM FRAME 14 TO 16)	MOS HRS AFL	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 152 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
53-20-07-01-902	EXTERNAL - DETAILED INSPECTION	THE SKIN TO EMERGENCY DOOR CUTOUT STRUCTURE (FROM STRINGER 3R TO 7R AND FROM FRAME 14 TO 16)		TECH :	INSP :
	MOS				LABOR HRS :
	HRS				ICAO:
	AFL			0	SERVICE REMARKS --
53-20-08-002	INTERNAL GENERAL VISUAL INSPECTION	OF PASSENGER WINDOW CUT-OUT STRUCTURE		TECH :	INSP :
	MOS	03-AUG-2010			LABOR HRS :
	HRS	0			ICAO:
	AFL	0			SERVICE REMARKS --
53-20-08-01-901	INTERNAL GENERAL VISUAL INSPECTION	PASSENGER WINDOW CUTOUT STRUCTURE PASSENGER WINDOW FRAME (FROM STRINGER 4L TO 6L AND STRINGER 4R TO 6R AND FROM FRAME 10 TO 18)		TECH :	INSP :
	MOS				LABOR HRS :
	HRS			0	ICAO:
	AFL				SERVICE REMARKS --
53-20-08-01-902	EXTERNAL - DETAILED INSPECTION	PASSENGER WINDOW CUTOUT STRUCTURE PASSENGER (FROM STRINGER 4L TO 6L AND STRINGER 4R TO 6R AND FROM FRAME 10 TO 18) SKIN AT WINDOW AREA.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS			0	ICAO:
	AFL				SERVICE REMARKS --
53-20-10-01-901	INTERNAL DETAILED INSPECTION	CENTER FUSELAGE-TO-WING LATERAL LINKS.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS			0	ICAO:
	AFL				SERVICE REMARKS --
53-20-10-01-902	INTERNAL DETAILED INSPECTION	CENTER FUSELAGE-TO-WING LATERAL LINKS MACHINED FRAME (FRAME 14 AND FRAME 18) AND FASTENERS		TECH :	INSP :
	MOS				LABOR HRS :
	HRS			0	ICAO:
	AFL				SERVICE REMARKS --
53-20-11-01-901	INTERNAL SPECIAL DETAILED INSPECTION	CENTER FUSELAGE-TO-WING CONNECTION LINK (EDDY CURRENT) CONNECTION LINK FITTING (LUG AND INNER CAP).		TECH :	INSP :
	MOS				LABOR HRS :
	HRS			0	ICAO:
	AFL				SERVICE REMARKS --
53-20-11-01-902	INTERNAL DETAILED INSPECTION	CENTER FUSELAGE-TO-WING CONNECTION LINK FITTING.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS			0	ICAO:
	AFL				SERVICE REMARKS --
53-20-12-01-901	INTERNAL DETAILED INSPECTION	AFT PRESSURE BULKHEAD.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS			0	ICAO:
	AFL				SERVICE REMARKS --
53-30-00-001	EXTERNAL DETAILED VISUAL INSPECTION	OF AFT FUSELAGE SKINS AND ATTACHMENTS		TECH :	INSP :
	MOS	03-AUG-2010			LABOR HRS :
	HRS	0			ICAO:
	AFL	0			SERVICE REMARKS --
53-30-00-002	INTERNAL DETAILED VISUAL INSPECTION	OF AFT FUSELAGE UPPER SKIN, JUNCTIONS AND ATTACHEMENTS		TECH :	INSP :
	MOS	03-AUG-2010			LABOR HRS :
	HRS	0			ICAO:
	AFL	0			SERVICE REMARKS --
53-30-00-003	INTERNAL DETAILED VISUAL INSPECTION	OF AFT FUSELAGE SIDE SKIN, CUTOUTS AND ATTACHMENTS		TECH :	INSP :
	MOS	03-AUG-2010			LABOR HRS :
	HRS	0			ICAO:
	AFL	0			SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
53-30-01-01-901	INTERNAL DETAILED INSPECTION AFT FUSELAGE UPPER SKIN PANEL BEDPLATE AND ITS ATTACHMENTS, BEDPLATES TO STRINGER ATTACHMENTS AND SKIN TO BEDPLATE AREA.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-01-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE UPPER SKIN PANEL SKIN TO BEDPLATE AREA.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-02-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE SIDE SKIN PANEL FORWARD MACHINED FRAME (FRAME 22 AND FRAME 23)	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-02-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE SIDE SKIN PANEL SKIN TO FRAME AREA	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-02-02-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE SIDE SKIN PANEL AFT MACHINED FRAME (FRAME 25 AND FR25A)	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-02-02-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE SIDE SKIN PANEL - SKIN TO FRAME AREA	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-04-01-901	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES AFT FUSELAGE SKIN TO LONGITUDINAL SPLICE.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-04-01-902	INTERNAL DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES LONGITUDINAL SPLICE	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-04-02-901	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES TO CIRCUMFERENTIAL SPLICE.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-04-02-902	INTERNAL DETAILED INSPECTION AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES TO CIRCUMFERENTIAL SPLICE.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0
53-30-05-001	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE	MOS 08-AUG-2014 HRS 342.40 AFL 227	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO: 0

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
53-30-05-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE.				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL			0	SERVICE REMARKS -- ICAO:
53-30-05-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE AFT FUSELAGE THE SKIN TO BAGGAGE DOOR CUTOUT STRUCTURE.				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL			0	SERVICE REMARKS -- ICAO:
53-30-06-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE CUTOUT STRUCTURES - INTERNAL FRAMES, STRINGER, REINFORCEMENT, AND DOUBLER OF AFT FUSELAGE CUTOUT STRUCTURES.				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL			0	SERVICE REMARKS -- ICAO:
53-30-07-001	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE UPPER FRAMES 29 TO 32				
	MOS	08-AUG-2014		TECH :	INSP :
	HRS	342.40			LABOR HRS :
	AFL	227			SERVICE REMARKS -- ICAO:
53-30-07-01-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) MACHINED FRAMES.				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL			0	SERVICE REMARKS -- ICAO:
53-30-07-01-902	EXTERNAL - DETAILED INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) SKIN TO FRAME AREA.				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL			0	SERVICE REMARKS -- ICAO:
53-30-07-02-901	INTERNAL GENERAL VISUAL INSPECTION AFT FUSELAGE UPPER FRAMES (FROM FRAME 29 TO FRAME 32) BEDPLATES AND FASTENERS.				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL			0	SERVICE REMARKS -- ICAO:
53-30-08-001	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE MACHINED FRAME 32				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			SERVICE REMARKS -- ICAO:
Z210-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			SERVICE REMARKS -- ICAO:
Z210-002	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION				
	MOS	08-AUG-2014		TECH :	INSP :
	HRS	342.40			LABOR HRS :
	AFL	227			SERVICE REMARKS -- ICAO:
Z220-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION				
	MOS	08-AUG-2014		TECH :	INSP :
	HRS	342.40			LABOR HRS :
	AFL	227			SERVICE REMARKS -- ICAO:
Z220-002	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 155 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
Z230-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
					SERVICE REMARKS --
Z230-002	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
					SERVICE REMARKS --
Z240-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
					SERVICE REMARKS --
Z240-002	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
					SERVICE REMARKS --
Z310-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
					SERVICE REMARKS --
Z310-002	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
					SERVICE REMARKS --
Z320-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
					SERVICE REMARKS --
Z320-002	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION				
	MOS	08-AUG-2014		TECH :	INSP :
	HRS	342.40			LABOR HRS :
	AFL	227			ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 54-NACELLES/PYLONS					
54-00-00-001	EXTERNAL GENERAL VISUAL INSPECTION OF PYLON POLYURETHANE FILMS				
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
	SCHEDULED	AFL	299	0	ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
	SCHEDULED	AFL	227		ICAO:
					SERVICE REMARKS --
54-50-00-001	INTERNAL DETAILED VISUAL INSPECTION OF PYLON MAIN BOX				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
54-50-00-002	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD BEAM				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
54-50-01-01-901	INTERNAL DETAILED INSPECTION PYLON FORWARD BEAM PYLON SPARS 1 AND 2, UPPER AND LOWER SKIN AND FASTENERS.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
54-50-02-01-901	INTERNAL DETAILED INSPECTION PYLON AFT BEAM PYLON SPARS 3 AND 4 AND FASTENERS.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
54-50-03-001	EXTERNAL GENERAL VISUAL INSPECTION OF PYLON MAIN BOX				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
54-50-03-01-901	EXTERNAL GENERAL VISUAL INSPECTION PYLON MAIN BOX MAIN BOX SKIN AND FASTENERS.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
54-50-04-01-901	INTERNAL DETAILED INSPECTION PYLON-TO-FUSELAGE CONNECTIONS OF BOLTS.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
54-50-05-001	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES				
		MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
54-50-05-01-901	INTERNAL DETAILED INSPECTION PYLON YOKES LUG HOLES AT YOKES, YOKES, GUSSETS AND SHIELD.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 157 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
54-50-06-001	INTERNAL DETAILED VISUAL INSPECTION OF AFT MOUNT FITTINGS	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
54-50-06-01-901	INTERNAL DETAILED INSPECTION PYLON AFT FITTING AFT MOUNT FITTING AND FASTENERS.	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
Z410-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE PYLON	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
Z410-002	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
Z430-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
Z430-002	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 158 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 55-STABILIZERS					
500-55-0001	STABILIZERS - REPLACEMENT OF THE NUTS OF THE ELEVATOR MASS BALANCE FASTENERS, SERVICE BULLETIN				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-55-A004	STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-55-A004 PART I	INSPECTION STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN OF BARREL SELF-LOCKING NUTS				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-55-A004 PART II	REPLACEMENT STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN OF THE BARREL SELF-LOCKING NUT				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-55-A004 R1	STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:NOT APPLICABLE					
500-55-A004 R1 PART 2	INSPECTION STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN OF BARREL SELF-LOCKING NUTS				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			ICAO:
					SERVICE REMARKS --
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 159 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL			
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE		
500-55-A004 R1 PART I	INSPECTION	STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN OF BARREL SELF-LOCKING NUTS				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS			MSC		
		HRS					
		AFL					
		MSC					
MOC:NOT APPLICABLE							
500-55-A004 R1 PART II	REPLACEMENT	STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN OF THE BARREL SELF-LOCKING NUT				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS			MSC		
		HRS					
		AFL					
		MSC					
MOC:NOT APPLICABLE							
500-55-A004 R2		STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS			MSC		
		HRS					
		AFL					
		MSC					
MOC:NOT APPLICABLE							
500-55-A004 R2 PART I	INSPECTION	STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN OF BARREL SELF-LOCKING NUTS				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS	08-AUG-2014		MSC		
		HRS	342.40				
		AFL	227				
		MSC					
MOC:NOT APPLICABLE - BY THIS AIRCRAFT							
500-55-A004 R2 PART II	REPLACEMENT	STABILIZERS - INSPECTION AND REPLACEMENT OF THE BARREL SELF-LOCKING NUT, ALERT SERVICE BULLETIN OF THE BARREL SELF-LOCKING NUT				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS	08-AUG-2014		MSC		
		HRS	342.40				
		AFL	227				
		MSC					
MOC:NOT APPLICABLE - BY THIS AIRCRAFT							
55-00-00-001	EXTERNAL GENERAL VISUAL INSPECTION	OF STABILIZER POLYURETHANE FILMS				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS	12-AUG-2015				
		HRS	425.50				
		AFL	299				
		MOS	12-AUG-2015			TECH :	INSP :
		HRS	425.50			-	LABOR HRS :
	SCHEDULED	AFL	299			0	SERVICE REMARKS -- ICAO:
		MOS	08-AUG-2014			TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40			-	LABOR HRS : ICAO:
	SCHEDULED	AFL	227				SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 160 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
55-10-00-001	EXTERNAL - DETAILED INSPECTION OF HORIZONTAL-STABILIZER SPARS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-00-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER MAIN BOX	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL-TO-HORIZONTAL STABILIZER ATTACHMENTS	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-01-01-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER FRONT SPAR (BORESCOPIK) FRONT SPAR AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-02-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER FRONT SPAR FRONT SPAR AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER REAR SPAR (BORESCOPIK) REAR SPAR.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-03-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER REAR SPAR REAR SPAR AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-04-01-901	INTERNAL SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX UPPER SKIN (BORESCOPIK) STRINGERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-04-01-902	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX UPPER SKIN UPPER SKIN AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-05-01-901	EXTERNAL - DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX LOWER SKIN - LOWER SKIN.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-10-05-01-902	INTERNAL DETAILED INSPECTION HORIZONTAL STABILIZER MAIN BOX LOWER SKIN INCLUDING FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
55-10-06-01-901	INTERNAL SPECIAL DETAILED INSPECTION	HORIZONTAL STABILIZER COMPOSITE RIBS	(BORESCOPIC) COMPOSITE RIBS AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-10-07-001	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER TIP RIBS	03-AUG-2010	TECH :
	MOS		INSP :
	HRS	0	LABOR HRS :
	AFL	0	SERVICE REMARKS -- ICAO:
55-10-07-01-901	INTERNAL DETAILED INSPECTION	HORIZONTAL STABILIZER METALLIC RIBS	ROOT AND TIP METALLIC RIBS, INCLUDING FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-10-08-001	EXTERNAL - DETAILED INSPECTION	ON HORIZONTAL STABILIZER ROOT RIBS	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS -- ICAO:
55-10-08-01-901	INTERNAL SPECIAL DETAILED INSPECTION	HORIZONTAL STABILIZER LEADING EDGE	(BORESCOPIC) HORIZONTAL STABILIZER LEADING EDGE SKIN AND SPAR.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-10-08-01-902	EXTERNAL - DETAILED INSPECTION	HORIZONTAL STABILIZER LEADING EDGE	HORIZONTAL STABILIZER LEADING EDGE SKIN AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-10-09-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL STABILIZER LEADING EDGE	03-AUG-2010	TECH :
	MOS		INSP :
	HRS	0	LABOR HRS :
	AFL	0	SERVICE REMARKS -- ICAO:
55-10-09-01-901	EXTERNAL - DETAILED INSPECTION	HORIZONTAL STABILIZER ELEVATOR FITTING	HINGE FITTINGS, AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-10-09-02-901	INTERNAL SPECIAL DETAILED INSPECTION	HORIZONTAL STABILIZER ELEVATOR FITTING (EDDY CURRENT) LUGS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-10-09-03-901	INTERNAL DETAILED INSPECTION	HORIZONTAL STABILIZER ELEVATOR FITTING TORQUE BOX AND FASTENERS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-10-10-001	EXTERNAL GENERAL VISUAL INSPECTION	OF HORIZONTAL-STABILIZER HINGE FITTINGS	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS -- ICAO:
55-10-10-01-901	INTERNAL DETAILED INSPECTION	HORIZONTAL STABILIZER TRIM TAB ACTUATOR SUPPORT FITTINGS	TRIM TAB SUPPORTING FITTING AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
55-10-10-02-901	EXTERNAL - DETAILED INSPECTION	HORIZONTAL STABILIZER TRIM TAB ACTUATOR SUPPORT FITTINGS		TRIM TAB LINK SUPPORT FITTING AND FASTENERS.	
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
				0	SERVICE REMARKS --
55-10-11-002	INTERNAL DETAILED VISUAL INSPECTION	OF TRIM-TAB SUPPORT FITTINGS		TECH :	INSP :
	MOS	03-AUG-2010			LABOR HRS :
	HRS	0			ICAO:
	AFL	0			SERVICE REMARKS --
55-20-00-001	EXTERNAL - DETAILED INSPECTION	OF ELEVATOR FITTINGS AND TORQUE-TUBE ATTACHMENTS		TECH :	INSP :
	MOS	03-AUG-2010			LABOR HRS :
	HRS	0			ICAO:
	AFL	0			SERVICE REMARKS --
55-20-01-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX			TECH :	INSP :
	MOS	03-AUG-2010			LABOR HRS :
	HRS	0			ICAO:
	AFL	0			SERVICE REMARKS --
55-20-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION	ELEVATOR MAIN BOX (SKIN, SPARS AND RIBS)		(BORESCOPIC) SKIN, SPARS, RIBS AND FASTENERS.	
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
				0	SERVICE REMARKS --
55-20-01-01-902	EXTERNAL - DETAILED INSPECTION	ELEVATOR MAIN BOX (SKIN, SPARS AND RIBS) AND HORN.		SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE	
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
				0	SERVICE REMARKS --
55-20-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION	ELEVATOR HINGE FITTINGS (DYE PENETRANT) ELEVATOR HINGE PINS.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS				ICAO:
	AFL				SERVICE REMARKS --
				0	
55-20-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION	ELEVATOR HINGE FITTINGS (EDDY CURRENT) ELEVATOR HINGE FITTINGS.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS				ICAO:
	AFL				SERVICE REMARKS --
				0	
55-20-02-02-902	INTERNAL DETAILED INSPECTION	ELEVATOR HINGE FITTINGS ELEVATOR HINGE FITTINGS.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS				ICAO:
	AFL				SERVICE REMARKS --
				0	
55-20-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION	ELEVATOR TORQUE TUBE ASSY (EDDY CURRENT) ELEVATOR TORQUE TUBE FLANGE.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS				ICAO:
	AFL				SERVICE REMARKS --
				0	
55-20-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION	ELEVATOR TORQUE TUBE ASSY (DYE PENETRANT) ELEVATOR TORQUE TUBE.		TECH :	INSP :
	MOS				LABOR HRS :
	HRS				ICAO:
	AFL				SERVICE REMARKS --
				0	
55-22-01-001	EXTERNAL GENERAL VISUAL INSPECTION	OF ELEVATOR TAB PIANO HINGE		TECH :	INSP :
	MOS	03-AUG-2010			LABOR HRS :
	HRS	0			ICAO:
	AFL	0			SERVICE REMARKS --

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 163 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
55-22-02-001	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR TAB BOX	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER TO AFT FUSELAGE CONNECTIONS AT VERTICAL STABILIZER	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-01-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF FIN-TO-REAR FUSELAGE CONNECTIONS AT VERTICAL STABILIZER	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER (BORESCOPIC) FITTING, PINS AND SPARS ATTACHMENTS (UPPER PART OF CONNECTIONS).	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-01-01-902	INTERNAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER NUT, SEAL AND FASTENERS. FITTING, PINS AND SPAR ATTACHMENTS (LOWER PART OF CONNECTIONS),	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-01-02-901	INTERNAL DETAILED INSPECTION FIN-TO-FUSELAGE CONNECTIONS IN VERTICAL STABILIZER L SHAPE, RIB AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-02-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (BORESCOPIC) DOUBLER AND TIP RIB.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-02-01-902	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (EDDY CURRENT) DOUBLER AND TIP RIB AT FRONT AND REAR FITTING AREA.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-02-02-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER L SHAPE AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-02-02-902	INTERNAL SPECIAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER (BORESCOPIC) L SHAPE AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
55-30-02-03-901	INTERNAL DETAILED INSPECTION FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER FITTINGS AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 164 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
55-30-02-04-901	INTERNAL DETAILED INSPECTION	FIN-TO-HORIZONTAL STABILIZER CONNECTIONS ON VERTICAL STABILIZER COMPOSITE PLATES AND FASTENERS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-30-03-001	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL STABILIZER MAIN BOX		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS -- ICAO:
55-30-03-01-901	EXTERNAL - DETAILED INSPECTION	VERTICAL STABILIZER MAIN BOX (SKIN AND SPARS) SKIN AND SPAR.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-30-03-01-902	INTERNAL SPECIAL DETAILED INSPECTION	VERTICAL STABILIZER MAIN BOX (SKIN AND SPARS) (BORESCOPIC) SPAR.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-30-05-001	EXTERNAL DETAILED VISUAL INSPECTION	OF VERTICAL STABILIZER-TO-RUDDER FITTING	
	MOS	08-AUG-2014	TECH :
	HRS	342.40	INSP :
	AFL	227	LABOR HRS :
			SERVICE REMARKS -- ICAO:
55-30-05-01-901	EXTERNAL - DETAILED INSPECTION	RUDDER HINGE FITTINGS HINGE FITTING 1 AND FASTENERS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-30-05-02-901	INTERNAL SPECIAL DETAILED INSPECTION	RUDDER HINGE FITTINGS (EDDY CURRENT) HINGE FITTING 2 FLANGES.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-30-05-03-901	INTERNAL SPECIAL DETAILED INSPECTION	RUDDER HINGE FITTINGS (EDDY CURRENT) RUDDER LUG HINGE FITTINGS 1 AND 2.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-30-06-001	EXTERNAL DETAILED VISUAL INSPECTION	OF RUDDER TAB ACTUATOR FITTING AND SUPPORT FITTINGS	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS -- ICAO:
55-30-06-01-901	EXTERNAL - DETAILED INSPECTION	VERTICAL STABILIZER TAB ACTUATOR AND SUPPORT FITTINGS FITTINGS, LUGS AND FASTENERS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
55-40-01-001	EXTERNAL GENERAL VISUAL INSPECTION	OF RUDDER ASSEMBLY	
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS -- ICAO:
55-40-01-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER ASSEMBLY		
	MOS	03-AUG-2010	TECH :
	HRS	0	INSP :
	AFL	0	LABOR HRS :
			SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 165 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
55-40-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION	RUDDER MAIN BOX (BORESCOPIC) SKIN, SPARS, RIBS AND FASTENERS.	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-40-01-01-902	EXTERNAL - DETAILED INSPECTION	RUDDER MAIN BOX MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS.	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-40-02-001	EXTERNAL GENERAL VISUAL INSPECTION	OF RUDDER HINGE FITTINGS 03-AUG-2010 0 0	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-40-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION	RUDDER HINGE FITTINGS (DYE PENETRANT) RUDDER HINGE FITTINGS PINS.	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-40-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION	RUDDER HINGE FITTINGS (EDDY CURRENT) RUDDER HINGE FITTINGS.	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-40-02-02-902	INTERNAL DETAILED INSPECTION	RUDDER HINGE FITTINGS RUDDER HINGE FITTINGS.	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-40-03-001	EXTERNAL DETAILED VISUAL INSPECTION	OF RUDDER TORQUE-TUBE ASSEMBLY 03-AUG-2010 0 0	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-40-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION	RUDDER TORQUE TUBE ASSEMBLY (EDDY CURRENT) RUDDER TORQUE TUBE FLANGE.	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-40-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION	RUDDER TORQUE TUBE ASSEMBLY (DYE PENETRANT) RUDDER TORQUE TUBE.	TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
55-42-01-001	EXTERNAL DETAILED VISUAL INSPECTION	OF RUDDER TAB PIANO HINGE 03-AUG-2010 0 0	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL	
ANAC 2009-09-01	REPLACEMENT OF THE NUTS OF THE RIGHT AND LEFT ELEVATORS MASS BALANCE FASTENERS	13-AUG-2010	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
		MOS HRS AFL MSC	MSC

MOC:NOT APPLICABLE - TO S/N AIRCRAFT

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL			
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE		
FAA 2014-15-51	STABILIZERS - INSPECT/REPLACE ALL OF THE BARREL SELF-LOCKING NUTS AT THE HORIZONTAL STABILIZER TO VERTICAL STABILIZER JOINT	MOS	10-APR-2015			TECH :	INSP :
		HRS	382.70				LABOR HRS :
		AFL	258				ICAO:
		MSC		MSC		SERVICE REMARKS	--
MOC:NOT APPLICABLE - PER S/N							
FAA 2014-15-51 (G) (H)	INSPECTION/REPLACEMENT - BARREL SELF-LOCKING NUTS AT THE HORIZONTAL STABILIZER TO VERTICAL STABILIZER JOINT	MOS	10-APR-2015			TECH :	INSP :
		HRS	382.70				LABOR HRS :
		AFL	258				ICAO:
		MSC		MSC		SERVICE REMARKS	--
MOC:NOT APPLICABLE - PER S/N							
FAA 2014-15-51 (I)	REPORTING REQUIREMENT	MOS	10-APR-2015			TECH :	INSP :
		HRS	382.70				LABOR HRS :
		AFL	258				ICAO:
		MSC		MSC		SERVICE REMARKS	--
MOC:NOT APPLICABLE - PER S/N							
FAA 2014-15-51-E	EMERGENCY AD - STABILIZERS - INSPECT/REPLACE ALL OF THE BARREL SELF-LOCKING NUTS AT THE HORIZONTAL STABILIZER TO VERTICAL STABILIZER JOINT	MOS	10-APR-2015			TECH :	INSP :
		HRS	382.70				LABOR HRS :
		AFL	258				ICAO:
		MSC		MSC		SERVICE REMARKS	--
MOC:NOT APPLICABLE - PER S/N							
Z330-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER	MOS	03-AUG-2010			TECH :	INSP :
		HRS	0				LABOR HRS :
		AFL	0				ICAO:
						SERVICE REMARKS	--
Z330-002	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER	MOS	03-AUG-2010			TECH :	INSP :
		HRS	0				LABOR HRS :
		AFL	0				ICAO:
						SERVICE REMARKS	--
Z340-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER	MOS	03-AUG-2010			TECH :	INSP :
		HRS	0				LABOR HRS :
		AFL	0				ICAO:
						SERVICE REMARKS	--
Z340-002	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER	MOS	03-AUG-2010			TECH :	INSP :
		HRS	0				LABOR HRS :
		AFL	0				ICAO:
						SERVICE REMARKS	--



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 167 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 56-WINDOWS					
56-10-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF COCKPIT SIDE-WINDOWS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
56-10-01-002	FUNCTIONALLY CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
56-10-03-001	EXTERNAL DETAILED VISUAL INSPECTION OF WINDSHIELD AND COCKPIT SIDE WINDOW FRAMES AND FASTENERS	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
56-10-03-01-901	EXTERNAL SPECIAL DETAILED INSPECTION WINDSHIELD FRAME AND FASTENERS (EDDY CURRENT) FRAMES AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
56-20-01-001	EXTERNAL GENERAL VISUAL INSPECTION OF PASSENGER CABIN WINDOWS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 168 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 57-WINGS					
500-57-0001	WINGS - DRAIN HOLES IN CONTROL SURFACES, SERVICE BULLETIN	MOS HRS AFL MSC	03-AUG-2010 0 0	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
500-57-0001 R1	WINGS - DRAIN HOLES IN CONTROL SURFACES, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-57-0002	WINGS - REPLACEMENT OF THE FUEL PIPE SUPPORT, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-57-0003	WINGS - ELIMINATION OF INTERFERENCE IN THE AILERON TAB FITTING BOLT, SERVICE BULLETIN	MOS HRS AFL MSC	19-JUL-2013 262.90 154	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-57-0003 R1	WINGS - ELIMINATION OF INTERFERENCE IN THE AILERON TAB FITTING BOLT, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-57-0003 R1 PART I	INSPECTION WINGS - ELIMINATION OF INTERFERENCE IN THE AILERON TAB FITTING BOLT, SERVICE BULLETIN OF AILERON TRIM-TAB FITTING ATTACHMENT BOLTS	MOS HRS AFL		TECH : 	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 169 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
500-57-0003 R1 PART II	REWORK WINGS - ELIMINATION OF INTERFERENCE IN THE AILERON TAB FITTING BOLT, SERVICE BULLETIN				OF THE AILERON TRIM-TAB SURFACE			
			MOS			TECH :	INSP :	
			HRS				LABOR HRS :	ICAO:
			AFL				SERVICE REMARKS	--
MOC:								
500-57-0004	WINGS - MISSING BLUE VARNISH IN FUEL COMPONENTS INSTALLATION, SERVICE BULLETIN							
			MOS			TECH :	INSP :	
			HRS				LABOR HRS :	ICAO:
			AFL				SERVICE REMARKS	--
			MSC		MSC			
MOC:NOT APPLICABLE								
500-57-0004 PART I	VISUAL INSPECTION WINGS - MISSING BLUE VARNISH IN FUEL COMPONENTS INSTALLATION, SERVICE BULLETIN FOR CORROSION ON THE STRUCTURE WHERE THE FUEL COMPONENTS ARE INSTALLED.							
			MOS			TECH :	INSP :	
			HRS				LABOR HRS :	ICAO:
			AFL				SERVICE REMARKS	--
			MSC		MSC			
MOC:NOT APPLICABLE								
500-57-0004 PART II	REWORK WINGS - MISSING BLUE VARNISH IN FUEL COMPONENTS INSTALLATION, SERVICE BULLETIN THE STRUCTURE WHERE THE FUEL COMPONENTS WERE INSTALLED, IF NECESSARY.							
			MOS			TECH :	INSP :	
			HRS				LABOR HRS :	ICAO:
			AFL				SERVICE REMARKS	--
			MSC		MSC			
MOC:NOT APPLICABLE								
500-57-0005	WINGS - REINFORCEMENT OF LOWER SKIN IN MLG BAY, SERVICE BULLETIN							
			MOS			TECH :	INSP :	
			HRS				LABOR HRS :	ICAO:
			AFL				SERVICE REMARKS	--
			MSC		MSC			
MOC:								
500-57-0005 R1	WINGS - REINFORCEMENT OF LOWER SKIN IN MLG BAY, SERVICE BULLETIN							
			MOS			TECH :	INSP :	
			HRS				LABOR HRS :	ICAO:
			AFL				SERVICE REMARKS	--
			MSC		MSC			
MOC:								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 170 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
500-57-0005 R2	WINGS - REINFORCEMENT OF LOWER SKIN IN MLG BAY, SERVICE BULLETIN	MOS	19-JUL-2013	TECH :	INSP :
		HRS	262.90		LABOR HRS :
		AFL	154		SERVICE REMARKS
		MSC		MSC	ICAO: --
MOC:COMPLIED WITH					
500-57-0006	WINGS - LH WING AILERON MECHANISM ATTACHMENT - CHECK FOR PROPER INSTALLATION OF SHIM AND BOLTS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS
		MSC		MSC	ICAO: --
MOC:NOT APPLICABLE					
500-57-0006 PART I	WINGS - LH WING AILERON MECHANISM ATTACHMENT - CHECK FOR PROPER INSTALLATION OF SHIM AND BOLTS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS
		MSC		MSC	ICAO: --
MOC:NOT APPLICABLE					
500-57-0006 PART II	WINGS - LH WING AILERON MECHANISM ATTACHMENT - CHECK FOR PROPER INSTALLATION OF SHIM AND BOLTS, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL			SERVICE REMARKS
		MSC		MSC	ICAO: --
MOC:NOT APPLICABLE					
57-00-00-001	EXTERNAL GENERAL VISUAL INSPECTION OF WING POLYURETHANE FILMS	MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		SERVICE REMARKS
					ICAO: --
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
	SCHEDULED	AFL	299	0	SERVICE REMARKS
					ICAO: --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
	SCHEDULED	AFL	227		SERVICE REMARKS
					ICAO: --
57-10-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-FUSELAGE LINKS	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		SERVICE REMARKS
					ICAO: --
57-10-00-002	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		SERVICE REMARKS
					ICAO: --

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
57-10-00-003	INTERNAL DETAILED VISUAL INSPECTION OF WING MIDDLE AND REAR SPARS	MOS 08-AUG-2014 HRS 342.40 AFL 227	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-01-01-901	INTERNAL DETAILED INSPECTION WING LATERAL LINKS TO CENTER FUSELAGE	MOS HRS AFL	FRONT FITTING, BOLT, NUT AND SEAL. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-01-02-901	INTERNAL DETAILED INSPECTION WING LATERAL LINKS TO CENTER FUSELAGE	MOS HRS AFL	REAR FITTING, BOLT, NUT AND SEAL. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE	MOS HRS AFL	(EDDY CURRENT) WING CENTER FITTING AND LUG. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-02-01-902	INTERNAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE	MOS HRS AFL	WING CENTER FITTING. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE	MOS HRS AFL	(EDDY CURRENT) CENTER LINK LUGS. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-02-02-902	INTERNAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE	MOS HRS AFL	CENTER LINK FITTING, BOLT, NUT AND SEAL. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-02-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING CENTER LINKS-TO-CENTER FUSELAGE	MOS HRS AFL	(MAGNETIC PARTICLE) HORIZONTAL LINK BOLTS. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-03-01-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR	MOS HRS AFL	FRONT SPAR LOWER CAP BETWEEN RIB 1 AND 3 AND WINDOW ACCESS FRAMES, INCLUDING FASTENERS. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-03-02-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR	MOS HRS AFL	FRONT SPAR LOWER CAP BETWEEN RIB 3 AND 6 AND WINDOW ACCESS FRAMES, INCLUDING FASTENERS. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-03-03-901	EXTERNAL - DETAILED INSPECTION WING FRONT SPAR	MOS HRS AFL	LOWER SKIN BETWEEN RIB 6 AND 7, INCLUDING FASTENER. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-03-04-901	INTERNAL DETAILED INSPECTION WING FRONT SPAR	MOS HRS AFL	FRONT SPAR LOWER CAP BETWEEN RIB 7 AND 10 AND WINDOW ACCESS FRAMES, INCLUDING FASTENERS. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-10-03-05-901	EXTERNAL - DETAILED INSPECTION WING FRONT SPAR	MOS HRS AFL	LOWER SKIN BETWEEN RIB 10 AND 16, INCLUDING FASTENERS. TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
57-10-04-01-901	INTERNAL DETAILED INSPECTION	WING MIDDLE SPAR	MIDDLE SPAR LOWER CAP BETWEEN RIB 1 AND 3, INCLUDING FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-04-02-901	INTERNAL DETAILED INSPECTION	WING MIDDLE SPAR	MIDDLE SPAR LOWER CAP BETWEEN RIB 3 AND 7, INCLUDING FASTENERS .
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-04-03-901	INTERNAL DETAILED INSPECTION	WING MIDDLE SPAR	MIDDLE SPAR LOWER CAP BETWEEN RIB 7 AND 9, INCLUDING SPAR-STRINGER-SPLICE AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-04-04-901	INTERNAL SPECIAL DETAILED INSPECTION	WING MIDDLE SPAR	(EDDY CURRENT) MLG FRONT TRUNNION (LUG, SURFACE AND RADIUS).
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-04-04-902	INTERNAL DETAILED INSPECTION	WING MIDDLE SPAR	MLG FRONT TRUNNION AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-04-05-901	INTERNAL SPECIAL DETAILED INSPECTION	WING MIDDLE SPAR	(EDDY CURRENT) MLG ACTUATOR FITTING (SURFACE AND RADIUS).
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-04-05-902	INTERNAL DETAILED INSPECTION	WING MIDDLE SPAR	MLG ACTUATOR FITTING AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-05-01-901	INTERNAL DETAILED INSPECTION	WING REAR SPAR	REAR SPAR LOWER CAP BETWEEN RIB 1 AND 3 AND WINDOW ACCESS FRAME.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-05-02-901	EXTERNAL - DETAILED INSPECTION	WING REAR SPAR	REAR SPAR LOWER CAP BETWEEN RIB 3 AND 7, INCLUDING FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-05-03-901	INTERNAL DETAILED INSPECTION	WING REAR SPAR	REAR SPAR LOWER CAP BETWEEN RIB 7 AND 10, INCLUDING FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-05-04-901	EXTERNAL - DETAILED INSPECTION	WING REAR SPAR	LOWER SKIN BETWEEN RIB 10 AND 16, INCLUDING FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-05-05-901	EXTERNAL SPECIAL DETAILED INSPECTION	WING REAR SPAR	(EDDY CURRENT) MLG REAR TRUNNION (LUG, SURFACE AND MACHINED RADIUS).
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0
57-10-05-05-902	EXTERNAL - DETAILED INSPECTION	WING REAR SPAR	MLG REAR TRUNNION AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			SERVICE REMARKS -- ICAO:
			0

(D)-- Deleted From Status (M)-- Migrated History Record

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 173 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
57-10-06-001	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-07-001	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-07-002	INTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-07-01-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-07-02-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-07-03-901	EXTERNAL - DETAILED INSPECTION WING LOWER PANEL	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-08-01-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-08-02-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-08-03-901	INTERNAL DETAILED INSPECTION WING LOWER PANEL	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-10-001	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-10-002	INTERNAL GENERAL VISUAL INSPECTION OF WING CENTER SPLICE	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --
57-10-10-003	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTRAL SPLICE	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
57-10-10-01-901	EXTERNAL - DETAILED INSPECTION	WING CENTRAL SPLICES		FRONT SPAR SPLICE, LOWER SKIN SPLICES, REAR SPAR SPLICES, INCLUDING FASTENERS.	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
57-10-10-01-902	INTERNAL DETAILED INSPECTION	WING CENTRAL SPLICES		WING LOWER SKIN ON SPLICE AREA, BETWEEN RIB1 AND RIB 2, FRONT , REAR AND MIDDLE SPAR ON SPLICE AREA	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
57-10-11-001	EXTERNAL DETAILED VISUAL INSPECTION	OF AILERON TAB ACTUATOR SUPPORT FITTINGS AND TAB HINGE FITTINGS			
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
57-50-00-001	EXTERNAL DETAILED VISUAL INSPECTION	OF WING TRAILING-EDGE INBOARD AND OUTBOARD TORQUE BOXES			
		MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		AFL	227		ICAO:
					SERVICE REMARKS --
57-50-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION	WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS		(EDDY CURRENT) WING ROOT TRACK.	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
57-50-01-01-902	INTERNAL DETAILED INSPECTION	WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS		WING ROOT TRACK.	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
57-50-01-02-901	INTERNAL SPECIAL DETAILED INSPECTION	WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS		(DYE PENETRANT) WING ROOT ROLLER.	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
57-50-01-03-901	INTERNAL SPECIAL DETAILED INSPECTION	WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS		(EDDY CURRENT) RIB 1.	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
57-50-01-03-902	INTERNAL DETAILED INSPECTION	WING TRAILING EDGE INBOARD TORQUE BOX AND FLAP TRACK # 1 SUPPORTS		RIB 1 AND FASTENERS.	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
57-50-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION	WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS		(EDDY CURRENT) WING CENTER TRACK.	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
57-50-02-01-902	INTERNAL DETAILED INSPECTION	WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS		WING CENTER TRACK.	
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
57-50-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS (EDDY CURRENT) WING CENTER TRACK SUPPORT.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-02-02-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS WING CENTER TRACK SUPPORT.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-02-03-901	INTERNAL DETAILED INSPECTION WING TRAILING EDGE FLAP TRACK # 2 SUPPORTS FITTINGS (LUG, ATTACHMENTS, PIN AND FASTENERS).	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS (EDDY CURRENT) WING TIP TRACK.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-03-01-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS WING TIP TRACK.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS (DYE PENETRANT) WING TIP ROLLER.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-03-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS (EDDY CURRENT) RIBS 13 AND 13A WEB AND FLANGE.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-03-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS RIBS 13 AND 13A.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-03-04-901	EXTERNAL - DETAILED INSPECTION WING TRAILING EDGE OUTBOARD TORQUE BOX AND FLAP TRACK # 3 SUPPORTS TORQUE BOX SKIN AND FASTENERS.	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 0 --
57-50-04-001	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE AILERON HINGE FITTING	MOS HRS AFL	TECH : INSP : LABOR HRS : SERVICE REMARKS ICAO: 03-AUG-2010 0 0 --

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 176 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
57-50-04-01-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	(EDDY CURRENT) AILERON HINGE FITTING 01.	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-50-04-02-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	(EDDY CURRENT) AILERON HINGE FITTING 02 .	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-50-04-02-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	AILERON HINGE FITTING 02.	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-50-04-03-901	INTERNAL SPECIAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	(EDDY CURRENT) AILERON HINGE FITTING 03.	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-50-04-03-902	INTERNAL DETAILED INSPECTION WING TRAILING EDGE AILERON SUPPORT FITTINGS	AILERON HINGE FITTING 03.	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-51-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF FLAP ASSEMBLY	03-AUG-2010	
	MOS HRS AFL	0 0	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-51-01-01-901	EXTERNAL - DETAILED INSPECTION FLAP UPPER SKIN PANELS	FLAP UPPER SKIN FROM RIB 7 TO RIB 9.	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-51-02-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE FLAP MAIN BOX	03-AUG-2010	
	MOS HRS AFL	0 0	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-51-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS	(BORESCOPIC) FLAP FRONT SPAR BETWEEN RIB 5A AND RIB 5B.	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-51-02-03-901	EXTERNAL - DETAILED INSPECTION FLAP UPPER SKIN PANELS	FLAP LOWER SKIN FROM RIB 1 TO RIB 5A AND FROM RIB 5B TO RIB 10.	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-51-02-04-901	EXTERNAL SPECIAL DETAILED INSPECTION FLAP UPPER SKIN PANELS AREA.	(EDDY CURRENT) FLAP LOWER SKIN FROM RIB 4 TO RIB 5A AND FROM RIB 5B TO RIB 6 AT FRONT SPAR	
	MOS HRS AFL		TECH : 0 INSP : LABOR HRS : SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
57-51-02-05-901	INTERNAL SPECIAL DETAILED INSPECTION	FLAP UPPER SKIN PANELS	(BORESCOPIC) AROUND FASTENERS THAT CONNECT CENTER ROLLERS FITTING TO RIB 5A AND RIB 5B
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-02-06-901	INTERNAL SPECIAL DETAILED INSPECTION	FLAP UPPER SKIN PANELS	(EDDY CURRENT) FRONT SPAR FROM RIB 5A TO RIB 5B.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-02-07-901	INTERNAL SPECIAL DETAILED INSPECTION	FLAP UPPER SKIN PANELS	(EDDY CURRENT) RIB 1 AND RIB 10.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-03-001	EXTERNAL DETAILED VISUAL INSPECTION	OF FLAP TRACK FITTINGS AND ACTUATOR FITTING	
	MOS	08-AUG-2014	TECH :
	HRS	342.40	INSP :
	AFL	227	LABOR HRS :
			ICAO:
			SERVICE REMARKS --
57-51-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION	FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) FLAP ROOT TRACK.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-03-01-902	INTERNAL DETAILED INSPECTION	FLAP TRACKS SUPPORT FITTINGS FLAP ROOT TRACK.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION	FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) FLAP TIP TRACK.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-03-02-902	INTERNAL DETAILED INSPECTION	FLAP TRACKS SUPPORT FITTINGS FLAP TIP TRACK.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-03-03-901	INTERNAL SPECIAL DETAILED INSPECTION	FLAP TRACKS SUPPORT FITTINGS (DYE PENETRANT) FLAP ROOT AND TIP ROLLERS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-03-04-901	INTERNAL SPECIAL DETAILED INSPECTION	FLAP TRACKS SUPPORT FITTINGS (DYE PENETRANT) CENTER ROLLERS EXTERNAL PINS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-03-05-901	INTERNAL SPECIAL DETAILED INSPECTION	FLAP TRACKS SUPPORT FITTINGS (EDDY CURRENT) CENTER ROLLERS FITTING AROUND FASTENERS.	
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-04-01-901	INTERNAL DETAILED INSPECTION	FLAP ACTUATOR SUPPORT FITTING	FLAP ACTUATOR SUPPORT PIN.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --
57-51-04-02-901	INTERNAL DETAILED INSPECTION	FLAP ACTUATOR SUPPORT FITTING	FLAP ACTUATOR SUPPORT FITTING AND FASTENERS.
	MOS		TECH :
	HRS		INSP :
	AFL		LABOR HRS :
			ICAO:
			0
			SERVICE REMARKS --

(D)-- Deleted From Status (M)-- Migrated History Record

History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 178 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
57-60-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF AILERON ASSEMBLY AND AILERON TAB BOX	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-01-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON MAIN BOX	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON MAIN BOX (BORESCOPIC) SKIN, SPARS, RIBS AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-01-01-902	EXTERNAL - DETAILED INSPECTION AILERON MAIN BOX SKIN, SPARS, RIBS AND FASTENERS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-02-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON HINGE FITTINGS (DYE PENETRANT) AILERON HINGE FITTINGS PINS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-02-02-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON HINGE FITTINGS (EDDY CURRENT) AILERON HINGE FITTINGS (LUGS, STIFFENERS RADIUS).	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-02-02-902	INTERNAL DETAILED INSPECTION AILERON HINGE FITTINGS AILERON HINGE FITTINGS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-03-001	EXTERNAL GENERAL VISUAL INSPECTION OF AILERON ACTUATOR FITTING, HINGE FITTINGS AND PINS	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-03-01-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN (DYE PENETRANT) AILERON ACTUATOR HINGE FITTINGS PINS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-03-02-901	INTERNAL SPECIAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN (EDDY CURRENT) AILERON ACTUATOR HINGE FITTINGS (LUGS, STIFFEN-ERS RADIUS).	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-60-03-02-902	INTERNAL DETAILED INSPECTION AILERON CONTROL HINGE AND PIN AILERON ACTUATOR HINGE FITTINGS.	MOS HRS AFL		TECH : 0	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
57-63-00-001	EXTERNAL GENERAL VISUAL INSPECTION OF AILERON TAB ASSEMBLY	MOS HRS AFL	03-AUG-2010 0 0	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 179 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
ANAC 2010-07-01	REWORK THE ELEVATORS, ELEVATORS TRIM TABS AND AILERONS SURFACES BY DRILLING ADDITIONAL DRAIN HOLES IN THEM	MOS HRS AFL MSC	13-AUG-2010	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE - TO S/N AIRCRAFT					
FAA 2010-21-15	REWORK OF THE ELEVATORS, ELEVATORS TRIM TABS, AND AILERONS SURFACES BY DRILLING ADDITIONAL DRAIN HOLES IN THEM	MOS HRS AFL MSC	10-APR-2015 382.70 258	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE - PER S/N					
Z500-001	EXTERNAL GENERAL VISUAL INSPECTION OF THE WINGS	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
Z500-002	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS	MOS HRS AFL	08-AUG-2014 342.40 227	TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 180 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 71-POWER PLANT					
500-71-0001	POWERPLANT - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH, SERVICE BULLETIN	MOS HRS AFL MSC	04-MAR-2011 122.90 62	TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
500-71-0001 R1	POWERPLANT - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-71-0001 R1 PART I	POWERPLANT - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH, SERVICE BULLETIN REWORK OF BRACKETS	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-71-0001 R1 PART II	POWERPLANT - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH, SERVICE BULLETIN REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE					
500-71-0001 R1 PART III	POWERPLANT - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH, SERVICE BULLETIN ADDITIONAL ACTION - CORRECTION OF THE WEIGHT AND BALANCE VALUES	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
500-71-0002	POWERPLANT - AIR BAFFLE INSTALLATION, SERVICE BULLETIN	MOS HRS AFL MSC		TECH : MSC	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION		COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.		C/W	TIME SINCE	C/W	TIME SINCE			
500-71-0002 R1	POWERPLANT - AIR BAFFLE INSTALLATION, SERVICE BULLETIN								
		MOS					TECH :	INSP :	ICAO:
		HRS						LABOR HRS :	
		AFL						SERVICE REMARKS	--
		MSC			MSC				
MOC:									
500-71-0002 R2	POWERPLANT - AIR BAFFLE INSTALLATION, SERVICE BULLETIN								
		MOS					TECH :	INSP :	ICAO:
		HRS						LABOR HRS :	
		AFL						SERVICE REMARKS	--
		MSC			MSC				
MOC:									
500-71-0003	POWERPLANT - VISUAL INSPECTION ON THE RIVETED JUNCTION LINE OF THE INLET INNER BARREL AND LIP SKIN, SERVICE BULLETIN								
		MOS	12-AUG-2015				TECH :	INSP :	ICAO:
		HRS	425.50					LABOR HRS :	
		AFL	299					SERVICE REMARKS	--
		MSC			MSC				
MOC:NOT APPLICABLE									
		MOS	19-AUG-2013				TECH :	INSP :	ICAO:
		HRS	262.90				-	LABOR HRS :	
	SCHEDULED	AFL	154					SERVICE REMARKS	--
MOC:									
71-20-00-001	DISCARD LEFT ENGINE UPPER FORWARD MOUNT ISOLATOR								
Part: LM-474-SA11	LK1077	MOS	03-AUG-2010				TECH :	INSP :	ICAO:
		HRS	0					LABOR HRS :	
		AFL	0					SERVICE REMARKS	--
71-20-00-001	DISCARD RIGHT ENGINE UPPER FORWARD MOUNT ISOLATOR								
Part: LM-474-SA11	LK1046	MOS	03-AUG-2010				TECH :	INSP :	ICAO:
		HRS	0					LABOR HRS :	
		AFL	0					SERVICE REMARKS	--
71-20-00-001	DISCARD LEFT ENGINE LOWER FORWARD MOUNT ISOLATOR								
Part: LM-474-SA11	LK1057	MOS	03-AUG-2010				TECH :	INSP :	ICAO:
		HRS	0					LABOR HRS :	
		AFL	0					SERVICE REMARKS	--
71-20-00-001	DISCARD RIGHT ENGINE LOWER FORWARD MOUNT ISOLATOR								
Part: LM-474-SA11	LK1052	MOS	03-AUG-2010				TECH :	INSP :	ICAO:
		HRS	0					LABOR HRS :	
		AFL	0					SERVICE REMARKS	--
71-20-00-001	DISCARD LEFT ENGINE AFT MOUNT ISOLATOR								
Part: LM-474-SA2	LK0575	MOS	03-AUG-2010				TECH :	INSP :	ICAO:
		HRS	0					LABOR HRS :	
		AFL	0					SERVICE REMARKS	--

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
71-20-00-001	DISCARD RIGHT ENGINE AFT MOUNT ISOLATOR				
Part: LM-474-SA2	LK0569	MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
71-21-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ENGINE FORWARD MOUNTING ASSEMBLY (DYE PENETRANT) HOUSING.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
71-21-01-01-902	INTERNAL DETAILED INSPECTION ENGINE FORWARD MOUNTING ASSEMBLY ENGINE BOLT AND SLEEVE BOLT.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
71-22-01-01-901	INTERNAL SPECIAL DETAILED INSPECTION ENGINE AFT MOUNTING ASSEMBLY (DYE PENETRANT) HOUSING.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
71-22-01-01-902	INTERNAL DETAILED INSPECTION ENGINE AFT MOUNTING ASSEMBLY PYLON BOLTS, ENGINE BOLTS AND SLEEVE BOLTS.				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		AFL		0	ICAO:
					SERVICE REMARKS --
71-31-00-001	DETAILED VISUAL INSPECTION OF PYLON FIREWALL SEAL				
		MOS	03-AUG-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		AFL	0		ICAO:
					SERVICE REMARKS --
CHAPTER	72-ENGINE				
72-00-00-001	VISUAL CHECK OF ENGINE MAINTENANCE PAGE FOR ENGINE DISPATCH AND EXCEEDANCE INFORMATION				
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50		LABOR HRS :
		AFL	299		ICAO:
					SERVICE REMARKS --
		MOS	12-AUG-2015	TECH :	INSP :
		HRS	425.50	-	LABOR HRS :
		AFL	299	0	ICAO:
	SCHEDULED				SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	-	LABOR HRS :
		AFL	227		ICAO:
	SCHEDULED				SERVICE REMARKS --



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 183 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 73-ENGINE FUEL AND CONTROL					
500-73-0001	ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE UPGRADE - VERSION 4.0, SERVICE BULLETIN				
	MOS	03-AUG-2010		TECH :	INSP :
	HRS	0			LABOR HRS :
	AFL	0			ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
500-73-0002	ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE UPGRADE - VERSION 5.3, SERVICE BULLETIN				
	MOS	04-MAR-2011		TECH :	INSP :
	HRS	122.90			LABOR HRS :
	AFL	62			ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:COMPLIED WITH					
500-73-0002 R1	ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE UPGRADE - VERSION 5.3, SERVICE BULLETIN				
	MOS	25-JUL-2011		TECH :	INSP :
	HRS	137.20			LABOR HRS :
	AFL	68			ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:COMPLIED WITH - PCW					
500-73-0002 R2	ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE UPGRADE - VERSION 5.3 (SUPERSEDED BY SB 500-73-0003 R3), SERVICE BULLETIN				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:					
500-73-0003	ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE REPLACEMENT - VERSION 5.5, SERVICE BULLETIN				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:					
500-73-0003 R1	ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE VERSION 5.5 REPLACEMENT, SERVICE BULLETIN				
	MOS			TECH :	INSP :
	HRS				LABOR HRS :
	AFL				ICAO:
	MSC			MSC	SERVICE REMARKS --
MOC:					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 184 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
500-73-0003 R2	ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE VERSION 5.5 REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-73-0003 R3	ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE VERSION 5.5 REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-73-0003 R3 PART I	UPLOAD ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE VERSION 5.5 REPLACEMENT, SERVICE BULLETIN FADEC SOFTWARE VERSION 5.5	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-73-0003 R3 PART II	INSTALLATION ENGINE FUEL AND CONTROL - NEW FADEC (FULL AUTHORITY DIGITAL ENGINE CONTROL) SOFTWARE VERSION 5.5 REPLACEMENT, SERVICE BULLETIN OF ENHANCED TAKE-OFF PLACARD	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
500-73-0004	ENGINE FUEL AND CONTROL - TAKEOFF PLACARD INSPECTION / REPLACEMENT, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			
500-73-0005	ENGINE FUEL AND CONTROL - CONVERSION FROM STANDARD TAKEOFF CONFIGURATION TO ENHANCED TAKEOFF CONFIGURATION, SERVICE BULLETIN	MOS HRS AFL MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:NOT APPLICABLE			

(D)-- Deleted From Status (M)-- Migrated History Record

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL					
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE				
500-73-0005 R1	ENGINE FUEL AND CONTROL - CONVERSION FROM STANDARD TAKEOFF CONFIGURATION TO ENHANCED TAKEOFF CONFIGURATION, SERVICE BULLETIN								
		MOS				TECH :		INSP :	
		HRS						LABOR HRS :	ICAO:
		AFL						SERVICE REMARKS	--
		MSC			MSC				
MOC:NOT APPLICABLE									
(D)H73-01-240-001	GENERAL VISUAL INSPECTION LEFT L/HIRF PROTECTION ON THE FADEC								
		MOS	03-AUG-2010			TECH :		INSP :	
		HRS	0			-		LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0					SERVICE REMARKS	--
(D)H73-01-240-001	GENERAL VISUAL INSPECTION RIGHT L/HIRF PROTECTION ON THE FADEC								
		MOS	03-AUG-2010			TECH :		INSP :	
		HRS	0			-		LABOR HRS :	ICAO:
	UNSCHEDULED	AFL	0					SERVICE REMARKS	--
CHAPTER 92--									
FAA 2011-01-04	INSTALL CLAMPS AND PROTECTION SLEEVES TO HARNESS W101 WITHIN THE COCKPIT AREA AND REWORK STRUCTURES TO ELIMINATE THE FRETTING SPOTS OF THE HARNESS WITH THE MAIN DOOR LOCKING MECHANISM AND WITH THE OXYGEN TUBE								
		MOS	10-APR-2015			TECH :		INSP :	
		HRS	382.70					LABOR HRS :	ICAO:
		AFL	258					SERVICE REMARKS	--
		MSC			MSC				
MOC:NOT APPLICABLE - PER S/N									
CHAPTER 05-TIME LIMITS/MAINTENANCE CHECKS									
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0355 Part # 35C3100-01									
051254	NO. 1 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION								
		MOS	12-AUG-2015			TECH : CRS KX5R005N		INSP : CRS KX5R005N	
		HRS	425.50					LABOR HRS :	ICAO:
		ENC	299			0		SERVICE REMARKS	--
		ENC	299		ENC				
		MOS	08-AUG-2014			TECH : CRS KX5R005N		INSP : CRS KX5R005N	
		HRS	342.40			0		LABOR HRS :	ICAO:
	SCHEDULED	ENC	227			-		SERVICE REMARKS	--
		ENC	227		ENC				
CHAPTER 71-POWER PLANT									
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0355 Part # 35C3100-01									
710010	NO. 1 ENGINE - COMPRESSOR WASH								
		MOS	08-AUG-2014			TECH :		INSP :	
		HRS	342.40					LABOR HRS :	ICAO:
		MSC	227		MSC			SERVICE REMARKS	--

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 72-ENGINE					
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0355 Part # 35C3100-01					
118-2014 R1	NO. 1 ENGINE - OIL SAMPLING PROGRAM, SPECIAL INSTRUCTION				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
72-00-00-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET AREA				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
		ENC	227		ICAO:
		ENC	227	ENC	SERVICE REMARKS --
72-00-00-212-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE AGB				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
		ENC	227		ICAO:
		ENC	227	ENC	SERVICE REMARKS --
72-00-00-212-803	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
		ENC	227		ICAO:
		ENC	227	ENC	SERVICE REMARKS --
72-00-00-212-804	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
		ENC	227		ICAO:
		ENC	227	ENC	SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
72-00-00-212-805	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM	MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40	0	
	SCHEDULED	ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-212-806	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM	MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40	0	
	SCHEDULED	ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-215-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR INLET AREA	MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40	0	
	SCHEDULED	ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-215-802	NO. 1 ENGINE - DETAILED INSPECTION OF THE COMPRESSOR CASE ASSEMBLY	MOS	26-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-215-803	NO. 1 ENGINE - DETAILED INSPECTION OF THE FAN CASE EXTERNAL AREA	MOS	26-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-280-801	NO. 1 ENGINE - PERFORM ENGINE OIL SAMPLING AND ANALYSIS	MOS	26-MAR-2010		
		HRS	0		
		ENC	0	MSC	
		ENC	0		
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-290-815	NO. 1 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY	MOS	26-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
72-00-00-640-803	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS	12-AUG-2015	TECH :	CRS KX5R005N
		HRS	425.50		INSP : CRS KX5R005N
		ENC	299		LABOR HRS :
		ENC	299	ENC	ICAO: --
					SERVICE REMARKS
		MOS	08-AUG-2014	TECH :	CRS KX5R005N
	SCHEDULED	HRS	342.40	0	INSP : CRS KX5R005N
		ENC	227	-	LABOR HRS :
		ENC	227	ENC	ICAO: --
					SERVICE REMARKS
720000	NO. 1 ENGINE - PERFORM ENGINE OVERHAUL	MOS	26-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		ENC	0		ICAO: --
		ENC	0	ENC	SERVICE REMARKS
720001	NO. 1 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION	MOS	26-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		ENC	0		ICAO: --
		ENC	0	ENC	SERVICE REMARKS
720002	NO. 1 ENGINE - PERFORM EEC FAULT INTERROGATION(TLD/LTD) ENGINE CONTROL SYSTEM	MOS	26-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		ENC	0	MSC	ICAO: --
		ENC	0		SERVICE REMARKS
720003	NO. 1 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)	MOS	26-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		ENC	0		ICAO: --
		ENC	0	ENC	SERVICE REMARKS
720030	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF EXTERIOR SURFACES OF THE NACELLE FOR EVIDENCE OF OIL LEAKS	MOS	12-AUG-2015	TECH :	CRS KX5R005N
		HRS	425.50		INSP : CRS KX5R005N
		ENC	299		LABOR HRS :
		ENC	299	ENC	ICAO: --
					SERVICE REMARKS
		MOS	08-AUG-2014	TECH :	CRS KX5R005N
	SCHEDULED	HRS	342.40	0	INSP : CRS KX5R005N
		ENC	227	-	LABOR HRS :
		ENC	227	ENC	ICAO: --
					SERVICE REMARKS
FAA 2010-17-01	NO. 1 ENGINE - REPLACEMENT OF THE FOHE FUEL FILTER BYPASS POPPET VALVE	MOS	10-APR-2015	TECH :	INSP :
		HRS	382.70		LABOR HRS :
		ENC	258	MSC	ICAO: --
		ENC	258		SERVICE REMARKS

MOC:NOT APPLICABLE - BY EQUIPMENT



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 189 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL		
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
PW600-72-66002	NO. 1 ENGINE - HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR-BALANCING-ASSEMBLY ADJUSTING SPACERS - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC	26-MAR-2010 0 0			TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE						
PW600-72-66003	NO. 1 ENGINE - HIGH-PRESSURE-TURBINE (HPT) TIE SHAFT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC				TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:						
PW600-72-66003 R1	NO. 1 ENGINE - HIGH-PRESSURE-TURBINE (HPT) TIE SHAFT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC	26-MAR-2010 0 0			TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE						
PW600-72-66003 R2	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF HIGH-PRESSURE-TURBINE (HPT) TIE SHAFT, SERVICE BULLETIN	MOS HRS ENC MSC				TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:						
PW600-72-66004	NO. 1 ENGINE - FUEL METERING UNIT (FMU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC				TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:						
PW600-72-66004 R1	NO. 1 ENGINE - FUEL METERING UNIT (FMU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC				TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:						

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 190 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66004 R2	NO. 1 ENGINE - FUEL METERING UNIT (FMU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66005	NO. 1 ENGINE - DATA COLLECTION UNIT (DCU) - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66006	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC BALANCING ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66007	NO. 1 ENGINE - FUEL METERING UNIT (FMU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66008	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 191 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66008 R1	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66009	NO. 1 ENGINE - HIGH-PRESSURE-TURBINE (HPT) VANE RING ANTI-ROTATION PIN - INTRODUCTION OF, SERVICE BULLETIN	MOS	26-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		ENC	0		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66009 R1	NO. 1 ENGINE - HIGH-PRESSURE-TURBINE (HPT) VANE RING ANTI-ROTATION PIN - INTRODUCTION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66010	NO. 1 ENGINE - SPECIFIC ENGINE MAINTENANCE PROGRAM - INTRODUCTION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66011	NO. 1 ENGINE - SPECIFIC ENGINE MAINTENANCE PROGRAM - INTRODUCTION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66011 R1	NO. 1 ENGINE - SPECIFIC ENGINE MAINTENANCE PROGRAM - INTRODUCTION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 192 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66012	NO. 1 ENGINE - OIL PUMP PLAIN SEAL - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66013	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66013 R1	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66013 R2	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66013 R3	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66013 R4	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 193 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66014	NO. 1 ENGINE - NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66014 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66015	NO. 1 ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66016	NO. 1 ENGINE - IGNITER - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66017	NO. 1 ENGINE - BYPASS-DUCT FUEL FAIRING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 194 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
PW600-72-66017 R1	NO. 1 ENGINE - REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY, SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		ENC					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
PW600-72-66018	NO. 1 ENGINE - FRONT AND REAR BLEED VALVE ACTUATOR (BVA) BRACKETS - REPLACEMENT OF, SERVICE BULLETIN	MOS	26-MAR-2010			TECH :	INSP :	
		HRS	0				LABOR HRS :	ICAO:
		MSC	0	MSC			SERVICE REMARKS	--
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66022	NO. 1 ENGINE - FUEL OIL/HEATER EXCHANGER (FOHE) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS	26-MAR-2010			TECH :	INSP :	
		HRS	0				LABOR HRS :	ICAO:
		MSC	0	MSC			SERVICE REMARKS	--
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66023	NO. 1 ENGINE - FUEL-SHUT-OFF LEVER SUPPORT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN	MOS	26-MAR-2010			TECH :	INSP :	
		HRS	0				LABOR HRS :	ICAO:
		MSC	0	MSC			SERVICE REMARKS	--
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66024	NO. 1 ENGINE - REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE, SERVICE BULLETIN	MOS	26-MAR-2010			TECH :	INSP :	
		HRS	0				LABOR HRS :	ICAO:
		MSC	0	MSC			SERVICE REMARKS	--
MOC:COMPLIED WITH - AT MANUFACTURE								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 195 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
PW600-72-66025	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY AND NO. 5 BEARING OIL TUBE BRACKET ASSEMBLIES - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0			TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66025 R1	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY AND NO. 5 BEARING OIL TUBE BRACKET ASSEMBLIES - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC			MSC	TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:								
PW600-72-66027	NO. 1 ENGINE - TIE ROD HIGH PRESSURE TURBINE - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0		MSC	TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66027 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF TIE ROD, HIGH PRESSURE TURBINE, SERVICE BULLETIN	MOS HRS ENC MSC			MSC	TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:								
PW600-72-66028	NO. 1 ENGINE - OIL FILLER AND INDICATOR ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0		MSC	TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:COMPLIED WITH - AT MANUFACTURE								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 196 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
PW600-72-66029	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF HPT DISC BALANCING ASSEMBLY AND TRIM BALANCING INTRODUCTION OF, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0			TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
				MSC			--	
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66030	NO. 1 ENGINE - REPLACEMENT OF THE NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY AND NEW CLAMPING INTRODUCTION TO SUIT, SERVICE BULLETIN	MOS HRS MSC	26-MAR-2010 0 0			TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
				MSC			--	
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66030 R1	NO. 1 ENGINE - REPLACEMENT OF THE NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY AND NEW CLAMPING INTRODUCTION TO SUIT, SERVICE BULLETIN	MOS HRS ENC MSC				TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
				MSC			--	
MOC:								
PW600-72-66031	NO. 1 ENGINE - FIELD REPAIR FOR THE NO. 5 BEARING-OIL-TUBE DAMPER BRACKET ASSEMBLIES WITH REINFORCING TUBE HALF SLEEVES AND NEW CLAMPING ARRANGEMENT, SERVICE BULLETIN	MOS HRS ENC MSC				TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
				MSC			--	
MOC:								
PW600-72-66031 R1	NO. 1 ENGINE - FIELD REPAIR FOR THE NO. 5 BEARING-OIL-TUBE DAMPER BRACKET ASSEMBLIES WITH REINFORCING TUBE HALF SLEEVES AND NEW CLAMPING ARRANGEMENT, SERVICE BULLETIN	MOS HRS ENC MSC				TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO:
				MSC			--	
MOC:								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 197 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
PW600-72-66032	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS (TT0 SENSOR) - REPLACEMENT OF,	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
PW600-72-66032 R1	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR), SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
PW600-72-66033	NO. 1 ENGINE - BYPASS-DUCT FUEL FAIRING - INSPECTION OF, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
PW600-72-66034	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
PW600-72-66034 R1	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			
PW600-72-66035	NO. 1 ENGINE - NO. 4-BEARING FRONT AND REAR CARBON SEAL - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MSC			
MOC:			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 198 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
PW600-72-66036	NO. 1 ENGINE - HPT CUP WASHER - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66036 R1	NO. 1 ENGINE - HPT CUP WASHER - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66036 R2	NO. 1 ENGINE - HPT CUP WASHER - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66037	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR CASE ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66038	NO. 1 ENGINE - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH AND INTRODUCTION OF ADAPTER ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66038 R1	NO. 1 ENGINE - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH AND INTRODUCTION OF ADAPTER ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 199 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66039	NO. 1 ENGINE - REPLACEMENT OF NUMBER 2 BEARING, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66040	NO. 1 ENGINE - REPLACEMENT OF P3 AIR AND OIL FAIRING ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66041	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL - REPLACEMENT OF, SERVICE BULLETIN	MOS	25-JUL-2011		
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
PW600-72-66041 R1	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66042	NO. 1 ENGINE - REPLACEMENT OF OIL NOZZLE ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66043 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL METERING UNIT (FMU), SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 200 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66044	NO. 1 ENGINE - INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66045	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF P3 AIR PASSAGE SPACER, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66046	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66046 R1	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66046 R2	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66047	NO. 1 ENGINE - REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 201 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66047 R1	NO. 1 ENGINE - REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66048	NO. 1 ENGINE - REPLACEMENT OF OIL PUMP AND FILTER HOUSING, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66049	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL OIL HEAT EXCHANGER, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66050	NO. 1 ENGINE - TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66051	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT (DCU), SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66052	NO. 1 ENGINE - TURBOFAN ENGINE - HP TURBINE VANE AND SEAL RING - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 202 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66053	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE TIE ROD, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66053 R1	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE TIE ROD, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66054	NO. 1 ENGINE - INSPECTION OF - HP DIFFUSER CASE ASSY, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66055	NO. 1 ENGINE - REPLACEMENT OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66055 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66056	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT AND REAR CARBON SEALS, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 203 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL		
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66056 R1	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT AND REAR CARBON SEALS, SERVICE BULLETIN	MOS HRS ENC MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66056 R2	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT AND REAR CARBON SEALS (SUPERSEDED BY SB PW600-72-66061), SERVICE BULLETIN	MOS HRS ENC MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66057	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66057 R1	NO. 1 ENGINE - REPLACEMENT OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66058	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING OIL PRESSURE TUBE, SERVICE BULLETIN	MOS HRS ENC MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66059	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC		TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 204 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66061	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING CARBON SEAL AND IMPELLER BAFFLE, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66063	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FAN CASE, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-A66019	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE - INSPECTION OF, ALERT SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-A66019 R1	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE - INSPECTION OF, ALERT SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-A66021	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE - MODIFICATION OF, ALERT SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-A66021 R1	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE - MODIFICATION OF, ALERT SERVICE BULLETIN	MOS	26-MAR-2010		
		HRS	0	TECH :	INSP :
		ENC	0		LABOR HRS :
		MSC	0	MSC	SERVICE REMARKS -- ICAO:

MOC:COMPLIED WITH - AT MANUFACTURE



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 205 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
TCCA CF-2010-02	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR				
		MOS	13-AUG-2010	TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	

MOC:NOT APPLICABLE - TO P/N 35C4540-03 EQUIPPED

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 73-ENGINE FUEL AND CONTROL					
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0355 Part # 35C3100-01					
73-10-05-000-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER				
		MOS	26-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
					TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --
73-10-05-220-801	NO. 1 ENGINE - DETAILED INSPECTION FUEL FILTER				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014		
		HRS	342.40	0	
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
73-10-07-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014		
		HRS	342.40	0	
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
73-20-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014		
		HRS	342.40	0	
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
73-30-02-212-801	NO. 1 ENGINE - VISUAL CHECK OF THE FUEL FILTER BYPASS INDICATOR POPUP BUTTON				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014		
		HRS	342.40	0	
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
73-30-02-215-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER BYPASS INDICATOR	MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS : ICAO:
		ENC	299		SERVICE REMARKS --
		ENC	299	ENC	
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
	SCHEDULED	HRS	342.40	0 -	LABOR HRS : ICAO:
		ENC	227		SERVICE REMARKS --
		ENC	227	ENC	
PW600-72-66043	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL METERING UNIT (FMU), SERVICE BULLETIN	MOS	25-JUL-2011	TECH :	INSP :
		HRS			LABOR HRS : ICAO:
		ENC			SERVICE REMARKS --
		MSC		MSC	
MOC:COMPLIED WITH					
CHAPTER 74-IGNITION					
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0355 Part # 35C3100-01					
74-10-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER	MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS : ICAO:
		ENC	299		SERVICE REMARKS --
		ENC	299	ENC	
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
	SCHEDULED	HRS	342.40	0 -	LABOR HRS : ICAO:
		ENC	227		SERVICE REMARKS --
		ENC	227	ENC	
74-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES	MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS : ICAO:
		ENC	299		SERVICE REMARKS --
		ENC	299	ENC	
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
	SCHEDULED	HRS	342.40	0 -	LABOR HRS : ICAO:
		ENC	227		SERVICE REMARKS --
		ENC	227	ENC	
PW600-74-66001	NO. 1 ENGINE - IGNITION EXCITER - REPLACEMENT OF, SERVICE BULLETIN	MOS	26-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS : ICAO:
		ENC	0	MSC	SERVICE REMARKS --

MOC:COMPLIED WITH - AT MANUFACTURE



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 208 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 75-AIR					
ENGINE NO. 1	Model : PW617F-E	Serial #	PCE-LC0355	Part #	35C3100-01
75-30-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BVA				
		MOS	12-AUG-2015	TECH :	CRS KX5R005N
		HRS	425.50		INSP : CRS KX5R005N
		ENC	299		LABOR HRS :
		ENC	299	ENC	ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014	TECH :	CRS KX5R005N
		HRS	342.40	0	INSP : CRS KX5R005N
	SCHEDULED	ENC	227	-	LABOR HRS :
		ENC	227	ENC	ICAO:
					SERVICE REMARKS --
CHAPTER 77-ENGINE INDICATING					
ENGINE NO. 1	Model : PW617F-E	Serial #	PCE-LC0355	Part #	35C3100-01
77-20-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM				
		MOS	12-AUG-2015	TECH :	CRS KX5R005N
		HRS	425.50		INSP : CRS KX5R005N
		ENC	299		LABOR HRS :
		ENC	299	ENC	ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014	TECH :	CRS KX5R005N
		HRS	342.40	0	INSP : CRS KX5R005N
	SCHEDULED	ENC	227	-	LABOR HRS :
		ENC	227	ENC	ICAO:
					SERVICE REMARKS --
77-20-02-710-801	NO. 1 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM				
		MOS	19-JUL-2013	TECH :	
		HRS	262.90		INSP :
		ENC	154		LABOR HRS :
		ENC	154	ENC	ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 79-OIL					
ENGINE NO. 1 Model : PW617F-E Serial # PCE-LC0355 Part # 35C3100-01					
79-20-01-000-801	NO. 1 ENGINE - DISCARD OIL FILTER				
		MOS	08-AUG-2014		
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
					TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --
79-30-01-720-801	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	0	
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
79-30-02-210-802	NO. 1 ENGINE - VISUAL CHECK OF THE OIL FILTER IMPENDING BYPASS INDICATOR POPUP BUTTON				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	0	
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
79-30-02-215-801	NO. 1 ENGINE - DETAILED INSPECTION OF THE OIL FILTER IMPENDING BYPASS INDICATOR				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	0	
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
PW600-72-66040 R1	NO. 1 ENGINE - REPLACEMENT OF P3 AIR AND OIL FAIRING ASSEMBLY, SERVICE BULLETIN				
		MOS	12-AUG-2015		
		HRS	425.50		
		MSC	299	MSC	
					TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --

MOC:COMPLIED WITH



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 210 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-79-66026	NO. 1 ENGINE - OIL FILLER AND INDICATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS	26-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		MSC	0	MSC	ICAO:
					SERVICE REMARKS --

MOC:COMPLIED WITH - AT MANUFACTURE

CHAPTER 05-TIME LIMITS/MAINTENANCE CHECKS

ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0359 Part # 35C3100-01

051254	NO. 2 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION	MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299	0	ICAO:
		ENC	299	ENC	SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
	SCHEDULED	ENC	227	-	ICAO:
		ENC	227	ENC	SERVICE REMARKS --

CHAPTER 71-POWER PLANT

ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0359 Part # 35C3100-01

710010	NO. 2 ENGINE - COMPRESSOR WASH	MOS	08-AUG-2014	TECH :	INSP :
		HRS	342.40		LABOR HRS :
		MSC	227	MSC	ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 72-ENGINE					
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0359 Part # 35C3100-01					
118-2014 R1	NO. 2 ENGINE - OIL SAMPLING PROGRAM, SPECIAL INSTRUCTION				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			ICAO:
		MSC		MSC	SERVICE REMARKS --
MOC:					
72-00-00-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET AREA				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
		ENC	227		ICAO:
		ENC	227	ENC	SERVICE REMARKS --
72-00-00-212-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE AGB				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
		ENC	227		ICAO:
		ENC	227	ENC	SERVICE REMARKS --
72-00-00-212-803	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
		ENC	227		ICAO:
		ENC	227	ENC	SERVICE REMARKS --
72-00-00-212-804	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
		ENC	227		ICAO:
		ENC	227	ENC	SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
72-00-00-212-805	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM	MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
	SCHEDULED				0
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-212-806	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM	MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
	SCHEDULED				0
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-215-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE LP COMPRESSOR INLET AREA	MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
	SCHEDULED				0
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-215-802	NO. 2 ENGINE - DETAILED INSPECTION OF THE COMPRESSOR CASE ASSEMBLY	MOS	31-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-215-803	NO. 2 ENGINE - DETAILED INSPECTION OF THE FAN CASE EXTERNAL AREA	MOS	31-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-280-801	NO. 2 ENGINE - PERFORM ENGINE OIL SAMPLING AND ANALYSIS	MOS	31-MAR-2010		
		HRS	0		
		ENC	0	MSC	
		ENC	0		
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --
72-00-00-290-815	NO. 2 ENGINE - SPECIFIC DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY	MOS	31-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
72-00-00-640-803	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
		MOS	08-AUG-2014		
		HRS	342.40		
	SCHEDULED	ENC	227		
		ENC	227	ENC	
720000	NO. 2 ENGINE - PERFORM ENGINE OVERHAUL	MOS	31-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
720001	NO. 2 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION	MOS	31-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
720002	NO. 2 ENGINE - PERFORM EEC FAULT INTERROGATION(TLD/LTD) ENGINE CONTROL SYSTEM	MOS	31-MAR-2010		
		HRS	0		
		ENC	0	MSC	
720003	NO. 2 ENGINE - INSPECT LOW UTILIZATION ENGINE (IF REQUIRED - SEE NOTES)	MOS	31-MAR-2010		
		HRS	0		
		ENC	0		
		ENC	0	ENC	
720030	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF EXTERIOR SURFACES OF THE NACELLE FOR EVIDENCE OF OIL LEAKS	MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
		MOS	08-AUG-2014		
		HRS	342.40		
	SCHEDULED	ENC	227		
		ENC	227	ENC	
FAA 2010-17-01	NO. 2 ENGINE - REPLACEMENT OF THE FOHE FUEL FILTER BYPASS POPPET VALVE	MOS	10-APR-2015		
		HRS	382.70		
		ENC	258	MSC	

MOC:NOT APPLICABLE - BY EQUIPMENT



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 214 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL		
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE	
PW600-72-66002	NO. 2 ENGINE - HIGH-PRESSURE-COMPRESSOR (HPC) ROTOR-BALANCING-ASSEMBLY ADJUSTING SPACERS - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0			TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE						
PW600-72-66003	NO. 2 ENGINE - HIGH-PRESSURE-TURBINE (HPT) TIE SHAFT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC			MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:						
PW600-72-66003 R1	NO. 2 ENGINE - HIGH-PRESSURE-TURBINE (HPT) TIE SHAFT - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE						
PW600-72-66003 R2	NO. 2 ENGINE - MODIFICATION/REPLACEMENT OF HIGH-PRESSURE-TURBINE (HPT) TIE SHAFT, SERVICE BULLETIN	MOS HRS ENC MSC			MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:						
PW600-72-66004	NO. 2 ENGINE - FUEL METERING UNIT (FMU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC			MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:						
PW600-72-66004 R1	NO. 2 ENGINE - FUEL METERING UNIT (FMU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC			MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:						

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 215 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66004 R2	NO. 2 ENGINE - FUEL METERING UNIT (FMU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	
				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66005	NO. 2 ENGINE - DATA COLLECTION UNIT (DCU) - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	
				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66006	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC BALANCING ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	
				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66007	NO. 2 ENGINE - FUEL METERING UNIT (FMU) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	
				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66008	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	
				TECH :	INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 216 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66008 R1	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66009	NO. 2 ENGINE - HIGH-PRESSURE-TURBINE (HPT) VANE RING ANTI-ROTATION PIN - INTRODUCTION OF, SERVICE BULLETIN	MOS	31-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		ENC	0		SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66009 R1	NO. 2 ENGINE - HIGH-PRESSURE-TURBINE (HPT) VANE RING ANTI-ROTATION PIN - INTRODUCTION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66010	NO. 2 ENGINE - SPECIFIC ENGINE MAINTENANCE PROGRAM - INTRODUCTION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66011	NO. 2 ENGINE - SPECIFIC ENGINE MAINTENANCE PROGRAM - INTRODUCTION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66011 R1	NO. 2 ENGINE - SPECIFIC ENGINE MAINTENANCE PROGRAM - INTRODUCTION OF, SERVICE BULLETIN	MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 217 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66012	NO. 2 ENGINE - OIL PUMP PLAIN SEAL - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66013	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66013 R1	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66013 R2	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66013 R3	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66013 R4	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NUT - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					

(D)-- Deleted From Status (M)-- Migrated History Record



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 218 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66014	NO. 2 ENGINE - NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66014 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66015	NO. 2 ENGINE - FUEL MANIFOLD ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66016	NO. 2 ENGINE - IGNITER - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66017	NO. 2 ENGINE - BYPASS-DUCT FUEL FAIRING ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0	MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH - AT MANUFACTURE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 219 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66017 R1	NO. 2 ENGINE - REPLACEMENT OF BYPASS-DUCT FUEL FAIRING ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66018	NO. 2 ENGINE - FRONT AND REAR BLEED VALVE ACTUATOR (BVA) BRACKETS - REPLACEMENT OF, SERVICE BULLETIN	MOS	31-MAR-2010		
		HRS	0	TECH :	INSP :
		MSC	0	MSC	LABOR HRS : ICAO:
					SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66022	NO. 2 ENGINE - FUEL OIL/HEATER EXCHANGER (FOHE) - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS	31-MAR-2010		
		HRS	0	TECH :	INSP :
		MSC	0	MSC	LABOR HRS : ICAO:
					SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66023	NO. 2 ENGINE - FUEL-SHUT-OFF LEVER SUPPORT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN	MOS	31-MAR-2010		
		HRS	0	TECH :	INSP :
		MSC	0	MSC	LABOR HRS : ICAO:
					SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					
PW600-72-66024	NO. 2 ENGINE - REPLACEMENT OF THE FUEL-SHUT-OFF-LEVER COTTER PIN BY A SAFETY WIRE, SERVICE BULLETIN	MOS	31-MAR-2010		
		HRS	0	TECH :	INSP :
		MSC	0	MSC	LABOR HRS : ICAO:
					SERVICE REMARKS --
MOC:COMPLIED WITH - AT MANUFACTURE					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 220 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
PW600-72-66025	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY AND NO. 5 BEARING OIL TUBE BRACKET ASSEMBLIES - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0			TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66025 R1	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY AND NO. 5 BEARING OIL TUBE BRACKET ASSEMBLIES - REPLACEMENT OF, SERVICE BULLETIN	MOS HRS ENC MSC			MSC	TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:								
PW600-72-66027	NO. 2 ENGINE - TIE ROD HIGH PRESSURE TURBINE - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0		MSC	TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66027 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF TIE ROD, HIGH PRESSURE TURBINE, SERVICE BULLETIN	MOS HRS ENC MSC			MSC	TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:								
PW600-72-66028	NO. 2 ENGINE - OIL FILLER AND INDICATOR ASSEMBLY - MODIFICATION/REPLACEMENT OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0		MSC	TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:COMPLIED WITH - AT MANUFACTURE								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 221 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
PW600-72-66029	NO. 2 ENGINE - MODIFICATION/REPLACEMENT OF HPT DISC BALANCING ASSEMBLY AND TRIM BALANCING INTRODUCTION OF, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0			TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66030	NO. 2 ENGINE - REPLACEMENT OF THE NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY AND NEW CLAMPING INTRODUCTION TO SUIT, SERVICE BULLETIN	MOS HRS MSC	31-MAR-2010 0 0			TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:COMPLIED WITH - AT MANUFACTURE								
PW600-72-66030 R1	NO. 2 ENGINE - REPLACEMENT OF THE NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY AND NEW CLAMPING INTRODUCTION TO SUIT, SERVICE BULLETIN	MOS HRS ENC MSC				TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:								
PW600-72-66031	NO. 2 ENGINE - FIELD REPAIR FOR THE NO. 5 BEARING-OIL-TUBE DAMPER BRACKET ASSEMBLIES WITH REINFORCING TUBE HALF SLEEVES AND NEW CLAMPING ARRANGEMENT, SERVICE BULLETIN	MOS HRS ENC MSC				TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:								
PW600-72-66031 R1	NO. 2 ENGINE - FIELD REPAIR FOR THE NO. 5 BEARING-OIL-TUBE DAMPER BRACKET ASSEMBLIES WITH REINFORCING TUBE HALF SLEEVES AND NEW CLAMPING ARRANGEMENT, SERVICE BULLETIN	MOS HRS ENC MSC				TECH :	INSP : LABOR HRS : SERVICE REMARKS	ICAO: --
MOC:								



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 222 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66032	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS (TT0 SENSOR) - REPLACEMENT OF, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66032 R1	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS (TT0 SENSOR), SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66033	NO. 2 ENGINE - BYPASS-DUCT FUEL FAIRING - INSPECTION OF, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66034	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66034 R1	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					
PW600-72-66035	NO. 2 ENGINE - NO. 4-BEARING FRONT AND REAR CARBON SEAL - REPLACEMENT OF, SERVICE BULLETIN				
		MOS		TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	
MOC:					



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 223 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66036	NO. 2 ENGINE - HPT CUP WASHER - REPLACEMENT OF, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66036 R1	NO. 2 ENGINE - HPT CUP WASHER - REPLACEMENT OF, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66036 R2	NO. 2 ENGINE - HPT CUP WASHER - REPLACEMENT OF, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66037	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR CASE ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66038	NO. 2 ENGINE - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH AND INTRODUCTION OF ADAPTER ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66038 R1	NO. 2 ENGINE - REPLACEMENT OF FUEL-FILTER IMPENDING BYPASS SWITCH AND INTRODUCTION OF ADAPTER ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 224 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66039	NO. 2 ENGINE - REPLACEMENT OF NUMBER 2 BEARING, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66040	NO. 2 ENGINE - REPLACEMENT OF P3 AIR AND OIL FAIRING ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66041	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL - REPLACEMENT OF, SERVICE BULLETIN	MOS	25-JUL-2011		
		HRS	137.20	TECH :	INSP :
		ENC			LABOR HRS :
		MSC	68	MSC	SERVICE REMARKS -- ICAO:
MOC:COMPLIED WITH					
PW600-72-66041 R1	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66042	NO. 2 ENGINE - REPLACEMENT OF OIL NOZZLE ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66043 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FUEL METERING UNIT (FMU), SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 225 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH	COMPONENT TIMES AFTER REMOVAL
PART NO.	SERIAL NO.	C/W TIME SINCE	C/W TIME SINCE
PW600-72-66044	NO. 2 ENGINE - INSPECTION OF PRIMARY AND SECONDARY FUEL FAIRING REDUCERS, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66045	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF P3 AIR PASSAGE SPACER, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66046	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66046 R1	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66046 R2	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			
PW600-72-66047	NO. 2 ENGINE - REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY, SERVICE BULLETIN	MOS HRS ENC MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:			



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 226 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL				
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE			
PW600-72-66047 R1	NO. 2 ENGINE - REPLACEMENT OF HP DIFFUSER CASE ASSEMBLY, SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		ENC					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
PW600-72-66048	NO. 2 ENGINE - REPLACEMENT OF OIL PUMP AND FILTER HOUSING, SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		ENC					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
PW600-72-66049	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FUEL OIL HEAT EXCHANGER, SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		ENC					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
PW600-72-66050	NO. 2 ENGINE - TURBOFAN ENGINE - COMPRESSOR CASE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		ENC					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
PW600-72-66051	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT (DCU), SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		ENC					SERVICE REMARKS	--
		MSC		MSC				
MOC:								
PW600-72-66052	NO. 2 ENGINE - TURBOFAN ENGINE - HP TURBINE VANE AND SEAL RING - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN	MOS				TECH :	INSP :	
		HRS					LABOR HRS :	ICAO:
		ENC					SERVICE REMARKS	--
		MSC		MSC				
MOC:								



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 227 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66053	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE TIE ROD, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66053 R1	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE TURBINE TIE ROD, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66054	NO. 2 ENGINE - INSPECTION OF - HP DIFFUSER CASE ASSY, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66055	NO. 2 ENGINE - REPLACEMENT OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66055 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRONIC ENGINE CONTROL, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66056	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT AND REAR CARBON SEALS, SERVICE BULLETIN	MOS HRS ENC MSC		MSC	TECH : INSP : LABOR HRS : SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 228 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66056 R1	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT AND REAR CARBON SEALS, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66056 R2	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT AND REAR CARBON SEALS (SUPERSEDED BY SB PW600-72-66061), SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66057	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66057 R1	NO. 2 ENGINE - REPLACEMENT OF HIGH PRESSURE DIFFUSER CASE ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66058	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING OIL PRESSURE TUBE, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66059	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 229 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-72-66061	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING CARBON SEAL AND IMPELLER BAFFLE, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-66063	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF FAN CASE, SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-A66019	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE - INSPECTION OF, ALERT SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-A66019 R1	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE - INSPECTION OF, ALERT SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-A66021	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE - MODIFICATION OF, ALERT SERVICE BULLETIN	MOS			
		HRS		TECH :	INSP :
		ENC			LABOR HRS :
		MSC		MSC	SERVICE REMARKS -- ICAO:
MOC:					
PW600-72-A66021 R1	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL-FILTER BYPASS VALVE - MODIFICATION OF, ALERT SERVICE BULLETIN	MOS	31-MAR-2010		
		HRS	0	TECH :	INSP :
		ENC	0		LABOR HRS :
		MSC	0	MSC	SERVICE REMARKS -- ICAO:

MOC:COMPLIED WITH - AT MANUFACTURE



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 230 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
TCCA CF-2010-02	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER (FOHE) FUEL FILTER BYPASS VALVE WEAR				
		MOS	13-AUG-2010	TECH :	INSP :
		HRS			LABOR HRS :
		ENC			SERVICE REMARKS -- ICAO:
		MSC		MSC	

MOC:NOT APPLICABLE - TO P/N 35C4540-03 EQUIPPED

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 73-ENGINE FUEL AND CONTROL					
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0359 Part # 35C3100-01					
73-10-05-000-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER				
		MOS	31-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		ENC	0		ICAO:
		ENC	0	ENC	SERVICE REMARKS --
73-10-05-220-801	NO. 2 ENGINE - DETAILED INSPECTION FUEL FILTER				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
	SCHEDULED	ENC	227	-	ICAO:
		ENC	227	ENC	SERVICE REMARKS --
73-10-07-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
	SCHEDULED	ENC	227	-	ICAO:
		ENC	227	ENC	SERVICE REMARKS --
73-20-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
	SCHEDULED	ENC	227	-	ICAO:
		ENC	227	ENC	SERVICE REMARKS --
73-30-02-212-801	NO. 2 ENGINE - VISUAL CHECK OF THE FUEL FILTER BYPASS INDICATOR POPUP BUTTON				
		MOS	12-AUG-2015	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS :
		ENC	299		ICAO:
		ENC	299	ENC	SERVICE REMARKS --
		MOS	08-AUG-2014	TECH : CRS KX5R005N	INSP : CRS KX5R005N
		HRS	342.40	0	LABOR HRS :
	SCHEDULED	ENC	227	-	ICAO:
		ENC	227	ENC	SERVICE REMARKS --

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
73-30-02-215-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE FUEL FILTER BYPASS INDICATOR				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40		
	SCHEDULED	ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
PW600-72-66043	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FUEL METERING UNIT (FMU), SERVICE BULLETIN				
		MOS	25-JUL-2011		
		HRS	137.20		
		MSC	68	MSC	
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --

MOC:COMPLIED WITH

CHAPTER 74-IGNITION

ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0359 Part # 35C3100-01

74-10-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION EXCITER				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40		
	SCHEDULED	ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
74-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
		MOS	08-AUG-2014		
		HRS	342.40		
	SCHEDULED	ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N
					INSP : CRS KX5R005N
					LABOR HRS : ICAO:
					SERVICE REMARKS --
PW600-74-66001	NO. 2 ENGINE - IGNITION EXCITER - REPLACEMENT OF, SERVICE BULLETIN				
		MOS	31-MAR-2010		
		HRS	0		
		MSC	0	MSC	
					TECH :
					INSP :
					LABOR HRS : ICAO:
					SERVICE REMARKS --

MOC:COMPLIED WITH - AT MANUFACTURE

(D)-- Deleted From Status (M)-- Migrated History Record



History Report
EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015
Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016
Page 233 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 75-AIR					
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0359 Part # 35C3100-01					
75-30-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BVA	MOS	12-AUG-2015	TECH :	CRS KX5R005N INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS : ICAO:
		ENC	299		SERVICE REMARKS --
		ENC	299	ENC	
		MOS	08-AUG-2014	TECH :	CRS KX5R005N INSP : CRS KX5R005N
		HRS	342.40	0	- LABOR HRS : ICAO:
	SCHEDULED	ENC	227		SERVICE REMARKS --
		ENC	227	ENC	
CHAPTER 77-ENGINE INDICATING					
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0359 Part # 35C3100-01					
77-20-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM	MOS	12-AUG-2015	TECH :	CRS KX5R005N INSP : CRS KX5R005N
		HRS	425.50		LABOR HRS : ICAO:
		ENC	299		SERVICE REMARKS --
		ENC	299	ENC	
		MOS	08-AUG-2014	TECH :	CRS KX5R005N INSP : CRS KX5R005N
		HRS	342.40	0	- LABOR HRS : ICAO:
	SCHEDULED	ENC	227		SERVICE REMARKS --
		ENC	227	ENC	
77-20-02-710-801	NO. 2 ENGINE - OPERATIONAL CHECK OF THE T6 TEMPERATURE INDICATING SYSTEM	MOS	19-JUL-2013	TECH :	INSP :
		HRS	262.90		LABOR HRS : ICAO:
		ENC	154		SERVICE REMARKS --
		ENC	154	ENC	

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
CHAPTER 79-OIL					
ENGINE NO. 2 Model : PW617F-E Serial # PCE-LC0359 Part # 35C3100-01					
79-20-01-000-801	NO. 2 ENGINE - DISCARD OIL FILTER				
		MOS	08-AUG-2014		
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
					TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --
79-30-01-720-801	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	0	
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
79-30-02-210-802	NO. 2 ENGINE - VISUAL CHECK OF THE OIL FILTER IMPENDING BYPASS INDICATOR POPUP BUTTON				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	0	
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
79-30-02-215-801	NO. 2 ENGINE - DETAILED INSPECTION OF THE OIL FILTER IMPENDING BYPASS INDICATOR				
		MOS	12-AUG-2015		
		HRS	425.50		
		ENC	299		
		ENC	299	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
	SCHEDULED	MOS	08-AUG-2014	0	
		HRS	342.40		
		ENC	227		
		ENC	227	ENC	
					TECH : CRS KX5R005N INSP : CRS KX5R005N LABOR HRS : ICAO: SERVICE REMARKS --
PW600-72-66040 R1	NO. 2 ENGINE - REPLACEMENT OF P3 AIR AND OIL FAIRING ASSEMBLY, SERVICE BULLETIN				
		MOS	12-AUG-2015		
		HRS	425.50		
		MSC	299	MSC	
					TECH : INSP : LABOR HRS : ICAO: SERVICE REMARKS --

MOC:COMPLIED WITH



History Report

EMB-500 - PHENOM 100 S/N 50000186 (N9990M): 455.6 HRS, 320 AFL as of 30-Nov-2015

Owner/Operator: NORTHGATE AVIATION

Report Date: 19-JAN-2016

Page 235 of 235

TASK NO	DESCRIPTION	COMPONENT INSTALLED AND/OR SERVICE/INSPECTION COMPLIED WITH		COMPONENT TIMES AFTER REMOVAL	
PART NO.	SERIAL NO.	C/W	TIME SINCE	C/W	TIME SINCE
PW600-79-66026	NO. 2 ENGINE - OIL FILLER AND INDICATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN				
		MOS	31-MAR-2010	TECH :	INSP :
		HRS	0		LABOR HRS :
		MSC	0	MSC	ICAO:
					SERVICE REMARKS --

MOC:COMPLIED WITH - AT MANUFACTURE