Company

Owner: Jet America Inc
Operator:

Major Assemblies

Airframe	Learjet 45	**45-359**	30-Apr-2024	5,274.8 Hrs	3,272 Ldg	2,107 Hrs(APU)
Eng 1	TFE731-20BR	**P-116949C**	30-Apr-2024	5,274.8 Hrs	3,271 Enc	
Eng 2	TFE731-20BR	**P-116950C**	30-Apr-2024	5,274.8 Hrs	3,271 Enc	
APU 1	RE100[LJ] APU	**P-393**	27-Mar-2024	2,107 Hrs	4,036 APUS	

Additional Information

Program Type: Standard - Program No.1, General Categories: RVSM,EMM,FAR 91,Ch.5 Interval

Cost: 78,389.23+
Man Hrs: 11,817.65+

Analyst: David White dwhite@traxxall.com

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 0 - GENERAL											
2014-13-06 Para (g)(1)								RE (-)			
0 ENG1						Mos	14-Nov-2013				
Complied With	BULLETIN 45-78-9 DATED FEBRUARY 27, 2012 WAS COMPLIED WITH PRIOR TO AUGUST 19, 2014					Hrs					
						Enc					
2014-13-06 Para (g)(1)								RE (-)			
0 ENG2						Mos	14-Nov-2013				
Complied With	BULLETIN 45-78-9 DATED FEBRUARY 27, 2012 WAS COMPLIED WITH PRIOR TO AUGUST 19, 2014					Hrs					
						Enc					
▼ 1 - --											
45-00-1	**General - Installation of Performance Enhancement Upgrade**							RE (-)		Optional	
1 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-00-1 Rev 1	**General - Installation of Performance Enhancement Upgrade**							RE (-)		Optional	
1 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-00-1 Rev 2	**General - Installation of Performance Enhancement Upgrade**							RE (-)		Optional	
1 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-00-1 Rev 3	**General - Installation of Performance Enhancement Upgrade**							RE (-)		Optional	
1 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-00-1 Rev 4	**General - Installation of Performance Enhancement Upgrade**							RE (-)		Optional	
1 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-00-1 Rev 5	**General - Installation of Performance Enhancement Upgrade**							RE (-)		Optional	
1 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-00-1 Rev 6	**General - Installation of Performance Enhancement Upgrade**							RE (-)		Optional	
1 A/F						Mos	29-Aug-2019				
Eff: 10-Nov-2000 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS											
05-11-01	**Phase A1 - 300 Hour Checks**							RE		TLMC 05-10-00	**≈24-Jul-2024**
5 A/F						Mos	09-Feb-2024	12	-/+14d	09-Feb-2025	8.7 Months (+14 Days)
(SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
						Ldg	3,757				
05-11-02	**Phase A2 - 300 Hour Checks**							RE		TLMC 05-10-00	**≈24-Jul-2024**
5 A/F						Mos	09-Feb-2024	12	-/+14d	09-Feb-2025	8.7 Months (+14 Days)
(SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
						Ldg	3,757				
05-11-03	**Phase A3 - 300 Hour Checks**							RE		TLMC 05-10-00	**≈24-Jul-2024**
5 A/F						Mos	09-Feb-2024	12	-/+14d	09-Feb-2025	8.7 Months (+14 Days)
(SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
						Ldg	3,757				
05-11-04	**Phase A4 - 300 Hour Checks**							RE		TLMC 05-10-00	**≈24-Jul-2024**
5 A/F						Mos	09-Feb-2024	12	-/+14d	09-Feb-2025	8.7 Months (+14 Days)
(SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
						Ldg	3,757				
05-11-05	**Phase A5 - 300 Hour Checks**							RE		TLMC 05-10-00	**≈24-Jul-2024**
5 A/F						Mos	09-Feb-2024	12	-/+14d	09-Feb-2025	8.7 Months (+14 Days)
(SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
						Ldg	3,757				
05-11-06	**Phase A6 - 300 Hour Checks**							RE		TLMC 05-10-00	**≈24-Jul-2024**
5 A/F						Mos	09-Feb-2024	12	-/+14d	09-Feb-2025	8.7 Months (+14 Days)
(SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
						Ldg	3,757				
05-12-01	**Phase B1 - 600 Hour Checks**							RE		TLMC 05-10-00	**≈24-Oct-2024**
5 A/F						Mos	09-Feb-2024	24	-/+14d	09-Jan-2026	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)						Ldg	3,757				
05-12-02	**Phase B2 - 600 Hour Checks**							RE		TLMC 05-10-00	**≈24-Oct-2024**
5 A/F						Mos	09-Feb-2024	24	-/+14d	09-Jan-2026	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)						Ldg	3,757				
05-12-03	**Phase B3 - 600 Hour Checks**							RE		TLMC 05-10-00	**≈24-Oct-2024**
5 A/F						Mos	09-Feb-2024	24	-/+14d	09-Jan-2026	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)						Ldg	3,757				
05-12-04	**Phase B4 - 600 Hour Checks**							RE		TLMC 05-10-00	**≈24-Oct-2024**
5 A/F						Mos	09-Feb-2024	24	-/+14d	09-Jan-2026	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)						Ldg	3,757				
05-12-05	**Phase B5 - 600 Hour Checks**							RE		TLMC 05-10-00	**≈24-Oct-2024**
5 A/F						Mos	09-Feb-2024	24	-/+14d	09-Jan-2026	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)						Ldg	3,757				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
05-12-06	**Phase B6 - 600 Hour Checks**							RE		TLMC 05-10-00	**≈24-Oct-2024**
5 A/F						Mos	09-Feb-2024	24	-/+14d	09-Jan-2026	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
	(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
05-13-01	**Phase C1 - 1200 Hour Checks**							RE		TLMC 05-10-00	**≈24-Apr-2025**
5 A/F						Mos	09-Feb-2024	48	-/+14d	09-Jan-2028	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	6,453.5	1,178.7 Hrs (+25)
	(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
05-13-02	**Phase C2 - 1200 Hour Checks**							RE		TLMC 05-10-00	**≈24-Apr-2025**
5 A/F						Mos	09-Feb-2024	48	-/+14d	09-Jan-2028	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	6,453.5	1,178.7 Hrs (+25)
	(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
05-13-03	**Phase C3 - 1200 Hour Checks**							RE		TLMC 05-10-00	**≈24-Apr-2025**
5 A/F						Mos	09-Feb-2024	48	-/+14d	09-Jan-2028	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	6,453.5	1,178.7 Hrs (+25)
	(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
05-13-04	**Phase C4 - 1200 Hour Checks**							RE		TLMC 05-10-00	**≈24-Apr-2025**
5 A/F						Mos	09-Feb-2024	48	-/+14d	09-Jan-2028	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	6,453.5	1,178.7 Hrs (+25)
	(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
05-13-05	**Phase C5 - 1200 Hour Checks**							RE		TLMC 05-10-00	**≈24-Apr-2025**
5 A/F						Mos	09-Feb-2024	48	-/+14d	09-Jan-2028	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	6,453.5	1,178.7 Hrs (+25)
	(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
05-13-06	**Phase C6 - 1200 Hour Checks**							RE		TLMC 05-10-00	**≈24-Apr-2025**
5 A/F						Mos	09-Feb-2024	48	-/+14d	09-Jan-2028	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	6,453.5	1,178.7 Hrs (+25)
	(Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
05-14-01	**Phase D1 - 2400 Hour Checks**							RE		TLMC 05-10-00	**≈12-Oct-2025**
5 A/F						Mos	10-Feb-2021	96	-/+14d	10-Feb-2029	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	7,010.5	1,735.7 Hrs (+25)
	(SOURCE: MM-104, MM-105)					Ldg	2,822				
05-14-02	**Phase D2 - 2400 Hour Checks**							RE		TLMC 05-10-00	**≈12-Oct-2025**
5 A/F						Mos	10-Feb-2021	96	-/+14d	10-Feb-2029	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	7,010.5	1,735.7 Hrs (+25)
	(SOURCE: MM-104, MM-105)					Ldg	2,822				
05-14-03	**Phase D3 - 2400 Hour Checks**							RE		TLMC 05-10-00	**≈12-Oct-2025**
5 A/F						Mos	10-Feb-2021	96	-/+14d	10-Feb-2029	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	7,010.5	1,735.7 Hrs (+25)
	(SOURCE: MM-104, MM-105)					Ldg	2,822				
05-14-04	**Phase D4 - 2400 Hour Checks**							RE		TLMC 05-10-00	**≈12-Oct-2025**
5 A/F						Mos	10-Feb-2021	96	-/+14d	10-Feb-2029	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	7,010.5	1,735.7 Hrs (+25)
	(SOURCE: MM-104, MM-105)					Ldg	2,822				
05-14-05	**Phase D5 - 2400 Hour Checks**							RE		TLMC 05-10-00	**≈12-Oct-2025**
5 A/F						Mos	10-Feb-2021	96	-/+14d	10-Feb-2029	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	7,010.5	1,735.7 Hrs (+25)
	(SOURCE: MM-104, MM-105)					Ldg	2,822				
05-14-06	**Phase D6 - 2400 Hour Checks**							RE		TLMC 05-10-00	**≈12-Oct-2025**
5 A/F						Mos	10-Feb-2021	96	-/+14d	10-Feb-2029	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	7,010.5	1,735.7 Hrs (+25)
	(SOURCE: MM-104, MM-105)					Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
05-15-00	**4800 Hour Inspections**							RE		TLMC 05-10-00	**≈14-Oct-2027**
5 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	9,410.5	4,135.7 Hrs (+25)
(SOURCE: MM-104, MM-105)						Ldg	2,822				
05-16-00	**9600 Hour Inspections**							RE		TLMC 05-10-00	**≈10-Dec-2027**
5 A/F						Mos					
						Hrs		9,600	-/+25	9,600	4,325.2 Hrs (+25)
(SOURCE: MM-104, MM-105)						Ldg					
05-17-00	**Major Landing Gear Inspection**							RE		TLMC 05-10-00	**≈12-Dec-2029**
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg		10,000	-/+25	10,000	6,728 Ldg (+25)
05-50-00-1	**Bird Strike - Inspection**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					
05-50-00-10	**High Ground Wind Gust - Inspection**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					
05-50-00-11	**Heat Damage - Inspection**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					
05-50-00-12	**Nacelle Heat Fail Message - Inspection**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					
05-50-00-13	**Elevator Disconnect - Inspection**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					
05-50-00-14	**Wing Flap System Overspeed Check**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					
05-50-00-15	**Volcanic Ash Inspection and Maintenance Procedures**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					
05-50-00-16	**Pressure cabin Skin Thickness Measurements - Inspection**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
05-50-00-17	**Aircraft Operations in Salt Influenced Environments - Inspection**						RE (A/R)	Unscheduled	Maintenance Check	
5 A/F					Mos					
					Hrs					
					Ldg					
05-50-00-18	**Foreign Object Damage**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					
05-50-00-19	**Engine Vibration Indication**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					
05-50-00-2	**Overweight Landing (Weight in Excess of Maximun Landing Weight) - Inspection**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					
05-50-00-3	**Hard landing - Inspection**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					
05-50-00-4	**Sever turbulence and/or Maneuvers - Inspection**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					
05-50-00-5	**Engine Change/Removal - Inspection**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					
05-50-00-6	**High Energy Stop (Landing and Rejected Takeoff) - Inspection**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					
05-50-00-7	**Thrust Reverser - Inspection**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					
05-50-00-8	**Overspeed Recovery Landing Gear Inspection (landing Gear Extension at High Speed)**						RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F					Mos					
					Hrs					
(SOURCE: MM-104, MM-105)					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
05-50-00-9	**Lightning Strike - Inspection**							RE (A/R)		05-50-00, Unscheduled Maintenance Check	
5 A/F						Mos					
						Hrs					
(SOURCE: MM-104, MM-105)						Ldg					
057110	**Perform 150 to 250 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈08-Jun-2024**
5 ENG1						Mos	09-Feb-2024				
						Hrs	5,253.5	150	+100	5,403.5	128.7 Hrs (+100)
Brand C:057110						Enc	3,756				
057110	**Perform 150 to 250 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈08-Jun-2024**
5 ENG2						Mos	09-Feb-2024				
						Hrs	5,253.5	150	+100	5,403.5	128.7 Hrs (+100)
Brand C:057110						Enc	3,756				
057120	**Perform 300 to 440 Hour Routine Inspection Per Manufacturer's Instructions**							RE (N/A)			
5 ENG1						Mos					
						Hrs					
Brand C:057120						Enc					
057120	**Perform 300 to 440 Hour Routine Inspection Per Manufacturer's Instructions**							RE (N/A)			
5 ENG2						Mos					
						Hrs					
Brand C:057120						Enc					
057130	**Perform 500 to 650 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈24-Oct-2024**
5 ENG1						Mos	09-Feb-2024				
						Hrs	5,253.5	600	-100/+50	5,853.5	578.7 Hrs (+50)
Brand C:057130						Enc	3,756				
057130	**Perform 500 to 650 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈24-Oct-2024**
5 ENG2						Mos	09-Feb-2024				
						Hrs	5,253.5	600	-100/+50	5,853.5	578.7 Hrs (+50)
Brand C:057130						Enc	3,756				
057140	**Perform 500 to 850 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈24-Dec-2024**
5 ENG1						Mos	09-Feb-2024				
						Hrs	5,253.5	800	-300/+50	6,053.5	778.7 Hrs (+50)
Brand C:057140						Enc	3,756				
057140	**Perform 500 to 850 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈24-Dec-2024**
5 ENG2						Mos	09-Feb-2024				
						Hrs	5,253.5	800	-300/+50	6,053.5	778.7 Hrs (+50)
Brand C:057140						Enc	3,756				
057150	**Perform 1000 to 1300 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈24-Apr-2025**
5 ENG1						Mos	09-Feb-2024				
						Hrs	5,253.5	1,200	-200/+100	6,453.5	1,178.7 Hrs (+100)
Brand C:057150						Enc	3,756				
057150	**Perform 1000 to 1300 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈24-Apr-2025**
5 ENG2						Mos	09-Feb-2024				
						Hrs	5,253.5	1,200	-200/+100	6,453.5	1,178.7 Hrs (+100)
Brand C:057150						Enc	3,756				
057160	**Perform 1500 to 1650 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈05-Feb-2025**
5 ENG1						Mos	20-May-2020				
						Hrs	4,593.2	1,600	-100/+50	6,193.2	918.4 Hrs (+50)
Brand C:057160						Enc	2,809				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
057160	**Perform 1500 to 1650 Hour Routine Inspection Per Manufacturers Instructions**							RE			**≈05-Feb-2025**
5 ENG2						Mos	20-May-2020				
						Hrs	4,593.2	1,600	-100/+50	6,193.2	918.4 Hrs (+50)
Brand C:057160						Enc	2,809				
2008-01-03	**Principal structural elements (PSEs)**							RE (-)		Mandatory	
5 A/F						Mos	11-Feb-2010				
Eff: 14-Feb-2008 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
						Ldg	739				
2012-0121	**Time Limits / Maintenance Checks - Airworthiness Limitations Section - Implementation**							T (A/R)		Mandatory	
5 A/F						Mos					
Eff: 20-Jul-2012						Hrs					
						Ldg					
2012-08-08	**Periodic Inspections**							RE (-)		Mandatory	
5 A/F						Mos	01-Aug-2012				
Eff: 29-May-2012 Complied With						Hrs	2,548.4				
						Ldg	1,517				
45-5-1	**Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program**							T (-)		Optional	
5 A/F						Mos					
Eff: 16-Oct-2013						Hrs					
						Ldg					
45-5-1 Rev 1	**Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program**							T (-)		Optional	
5 A/F						Mos					
Eff: 23-Mar-2015						Hrs					
(APX COST: 70,000) (NOTE: Except special mission air-craft. (Controlled by eINSPECTOR applicability list.))						Ldg					
45-5-1 Rev 2	**Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program**							T (A/R)		Optional	
5 A/F						Mos					
Eff: 05-Mar-2018						Hrs					
(NOTE: EFFECTIVITY: As per aircraft serialization, except special mission aircraft. (Controlled by eINSPECTOR applicability list.))						Ldg					
▼ 8 - LEVELING AND WEIGHING.											
08-10-01-001	**Aircraft Weighing and Balancing**							RE			
8 A/F						Mos	03-Mar-2022	36		17-Feb-2025	9 Months
Inspected Date 17-Feb-2022						Hrs	4,883				
(AVG MAN HRS: 45.5) (APX COST: 325) (UPDATE NOTE: 5 YEAR REWEIGHT AND BALANCE C/O IAW IR 45 AMM 08-10-00.)						Ldg	3,012				
45-8-1	**Leveling and Weighing - Ballast Weight Installation, Fuselage Station 630**							T (A/R)		Optional	
8 A/F						Mos					
Eff: 09-Aug-2010						Hrs					
						Ldg					
45-8-2	**Ballast Weight Installation - Fuselage Station 623 (This is an un-released SB available for Proof)**							T (A/R)		Optional	
8 A/F						Mos					
Eff: 09-Aug-2010						Hrs					
(NOTE: NOTE: THIS IS NOT FAA APPROVED DATA FOR INSTALLATION ON THE AIRCRAFT.)						Ldg					
45-8-3	**Ballast Weight Installation - Fuselage Station 602 Mid shelf (This is an un-released SB available for Proof)**							T (A/R)		Optional	
8 A/F						Mos					
Eff: 09-Aug-2010						Hrs					
(NOTE: NOTE; THIS IS NOT FAA APPROVED DATA FOR INSTALLATION ON THE AIRCRAFT.)						Ldg					
45-8-4	**Ballast Weight Installation - Fuselage Station 609 Upper Shelf (This is an un-released SB available for Proof)**							T (A/R)		Optional	
8 A/F						Mos					
Eff: 09-Aug-2010						Hrs					
(NOTE: NOTE: THIS IS NOT FAA APPROVED DATA FOR INSTALLATION ON THE AIRCRAFT.)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-8-5	**Ballast Weight Installation - Aft Equipment Shelf (Bottom Shelf) (This is an un-released SB available for Proof)**							T (A/R)		Optional	
8 A/F						Mos					
Eff: 09-Aug-2010						Hrs					
	(NOTE: NOTE: THIS IS NOT FAA APPROVED DATA FOR INSTALLATION ON THE AIRCRAFT.)					Ldg					
▼ 11 - PLACARDS AND MARKINGS											
45-11-1	**Placard - Removal of Anti-Icing Additive Requirement from Placard**							RE (-)		Optional	
11 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-11-1 Rev 1	**Placard - Removal of Anti-Icing Additive Requirement from Placard**							RE (-)		Optional	
11 A/F						Mos	29-Aug-2019				
Eff: 10-Dec-1999 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-11-2	**Placards and Markings - Installation of U.S. and Metric Oxygen Fill Table Placard**							RE (-)		Optional	
11 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-11-2 Rev 1	**Placards and Markings - Installation of U.S. and Metric Oxygen Fill Table Placard**							RE (-)		Optional	
11 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-11-2 Rev 2	**Placards and Markings - Installation of U.S. and Metric Oxygen Fill Table Placard**							RE (-)		Optional	
11 A/F						Mos	13-Mar-2008				
Eff: 30-Nov-2004 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-11-3	**Placards and Markings - Installation of Upper Entry Door Emergency Exit Placard**							RE (-)		Recommended	
11 A/F						Mos	14-Dec-2020				
Eff: 17-May-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-11-4	**Placards and Markings - Increase Maximum Take-Off Weight to 21,500 Pounds**							RE (-)		Optional	
11 A/F						Mos	13-Mar-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-11-4 Rev 1	**Placards and Markings - Increase Maximum Take-Off Weight to 21,500 Pounds**							RE (-)		Optional	
11 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-11-4 Rev 2	**Placards and Markings - Increase Maximum Take-Off Weight to 21,500 Pounds**							RE (-)		Optional	
11 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-11-4 Rev 3	**Placards and Markings - Increase Maximum Take-Off Weight to 21,500 Pounds**							RE (-)		Optional	
11 A/F						Mos	13-Mar-2008				
Complied With						Hrs					
						Ldg					
45-11-4 Rev 4	**Placards and Markings - Increase Maximum Take-Off Weight to 21,500 Pounds**							RE (-)		Optional	
11 A/F						Mos	29-Aug-2019				
Eff: 11-Feb-2013 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-11-5	**Placards and Markings - Increase Maximum Zero Fuel Weight (16,500 pounds)**							RE (-)		Optional	
11 A/F						Mos					
Eff: 24-Sep-2007						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-11-5 Rev 1	**Placards and Markings - Increase Maximum Zero Fuel Weight (16,500 pounds)**							RE (-)		Optional	
11 A/F						Mos					
Eff: 04-Feb-2008						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-11-5 Rev 2	**Placards and Markings - Increase Maximum Zero Fuel Weight (16,500 pounds)**							RE (-)		Optional	
11 A/F						Mos					
Eff: 12-May-2008						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-11-5 Rev 3	**Placards and Markings - Increase Maximum Zero Fuel Weight (16,500 pounds)**							RE (-)		Optional	
11 A/F						Mos					
Eff: 18-Mar-2013						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-11-5 Rev 4	**Placards and Markings - Increase Maximum Zero Fuel Weight (16,500 pounds)**							RE (-)		Optional	
11 A/F						Mos					
Eff: 20-Oct-2014						Hrs					
						Ldg					
45-11-5 Rev 5	**Placards and Markings - Increase Maximum Zero Fuel Weight (16,500 pounds)**							T (-)		Optional	
11 A/F						Mos					
Eff: 24-Sep-2007						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-11-5 Rev 6	**Placards and Markings - Increase Maximum Zero Fuel Weight (16,500 pounds)**							T (A/R)		Optional	
11 A/F						Mos					
Eff: 09-Nov-2015						Hrs					
(AVG MAN HRS: 1) (NOTE: ForLearjet 45-368, when equipped with Garmin Avionics)						Ldg					
45-11-6	**Placards and Markings - Replacement of Nose Strut Servicing Placards**							RE (-)		Recommended	
11 A/F						Mos					
Eff: 10-Dec-2012						Hrs					
(AVG MAN HRS: 4)						Ldg					
45-11-6 Rev 1	**Placards and Markings - Replacement of Nose Strut Servicing Placards**							RE (-)		Recommended	
11 A/F						Mos	01-Mar-2013				
Eff: 21-Jan-2013 Complied With						Hrs	2,753.9				
(AVG MAN HRS: 4)						Ldg	1,625				
45-11-6 Rev 2	**Placards and Markings - Replacement of Nose Strut Servicing Placards**							RE (-)		Recommended	
11 A/F						Mos	01-Jul-2013				
Eff: 28-May-2013 Complied With	NO REWORK IF PREVIOUS C/W					Hrs	2,890.4				
(AVG MAN HRS: 4)						Ldg	1,692				
45-11-6 Rev 3	**Placards and Markings - Replacement of Nose Strut Servicing Placards**							RE (-)		Recommended	
11 A/F						Mos	13-Jun-2014				
Eff: 19-May-2014 Complied With	NO REWORK REQUIRED IF PREVIOUS COMPLIED WITH					Hrs	3,195.4				
(AVG MAN HRS: 4)						Ldg	1,869				
45-11-6 Rev 4	**Placards and Markings - Replacement of Nose Strut Servicing Placards**							RE (-)		Recommended	
11 A/F						Mos	08-Jan-2015				
Eff: 05-Jan-2015 Not Applicable	NO WORK IS REQUIRED FOR AIRCRAFT WHICH HAVE COMPLIED WITH PREVIOUS ISSUES					Hrs	3,360				
(AVG MAN HRS: 4)						Ldg	1,961				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-11-6 Rev 5	**Placards and Markings - Replacement of Nose Strut Servicing Placards**							RE (-)		Recommended	
11 A/F						Mos	29-Aug-2019				
Eff: 27-Feb-2017 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 4)						Ldg	2,733				
G1130000	**Check brightness level of all self-luminous placards.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
11 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:11-30-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 11-30-00.))						Ldg	3,757				
▼ 12 - SERVICING - ROUTINE MAINTENANCE											
45-12-1	**Servicing - Installation of Remote Oxygen Servicing Provisions**							RE (-)		Optional	
12 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-12-1 Rev 1	**Servicing - Installation of Remote Oxygen Servicing Provisions**							RE (-)		Optional	
12 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-12-1 Rev 2	**Servicing - Installation of Remote Oxygen Servicing Provisions**							RE (-)		Optional	
12 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-12-1 Rev 3	**Servicing - Installation of Remote Oxygen Servicing Provisions**							RE (-)		Optional	
12 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-12-1 Rev 4	**Servicing - Installation of Remote Oxygen Servicing Provisions**							RE (-)		Optional	
12 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-12-1 Rev 5	**Servicing - Installation of Remote Oxygen Servicing Provisions**							RE (-)		Optional	
12 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-12-1 Rev 6	**Servicing - Installation of Remote Oxygen Servicing Provisions**							RE (-)		Optional	
12 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-12-1 Rev 7	**Servicing - Installation of Remote Oxygen Servicing Provisions**							RE (-)		Optional	
12 A/F						Mos	29-Aug-2019				
Eff: 30-Jul-2009 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
AB1210060	**Main Landing Gear Up-Lock Actuator - Lubricate**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	Left05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
3000H000-006											
2317						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
Ref:12-21-01 (ZONE: 720BL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-01))						Ldg	3,757				
AB1210060	**Main Landing Gear Up-Lock Actuator - Lubricate**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	Right05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
3000H000-006											
2031						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
Ref:12-21-01 (ZONE: 730BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-01.))						Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 12-001	**Aircraft Upper Cabin Door Pin Lubrication**							RE (-)		Advisory Wire	
12 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
O1210002	**Flap Actuators - Check oil level.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
12 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:12-21-03 (ZONE: 540/640) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21- 03.))						Ldg	3,757				
Q1221064	**Flap Actuator Joint (P/N 145673-1) - Apply Corrosion Preventive Compound (CPC).**							RE (N/A)		TLMC 05-19-00	
12 A/F	Left Inboard					Mos	07-Apr-2013				
159174-1						Hrs	2,797.6				
Unknown						Ldg	1,647				
Alias1:12-21-03 (ZONE: 540BL,540JL,540CL,540KL, 640BR,640JR,640CR,640KR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-03.))											
Q1221064	**Flap Actuator Joint (P/N 145673-1) - Apply Corrosion Preventive Compound (CPC).**							RE (N/A)		TLMC 05-19-00	
12 A/F	Left Outboard					Mos	07-Apr-2013				
159174-1						Hrs	2,797.6				
Unknown						Ldg	1,647				
Alias1:12-21-03 (ZONE: 540BL,540JL,540CL,540KL, 640BR,640JR,640CR,640KR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-03.))											
Q1221064	**Flap Actuator Joint (P/N 145673-1) - Apply Corrosion Preventive Compound (CPC).**							RE (N/A)		TLMC 05-19-00	
12 A/F	Right Inboard					Mos	07-Apr-2013				
159174-1						Hrs	2,797.6				
Unknown						Ldg	1,647				
Alias1:12-21-03 (ZONE: 540BL,540JL,540CL,540KL, 640BR,640JR,640CR,640KR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-03.))											
Q1221064	**Flap Actuator Joint (P/N 145673-1) - Apply Corrosion Preventive Compound (CPC).**							RE (N/A)		TLMC 05-19-00	
12 A/F	Right Outboard					Mos	07-Apr-2013				
159174-1						Hrs	2,797.6				
Unknown						Ldg	1,647				
Alias1:12-21-03 (ZONE: 540BL,540JL,540CL,540KL, 640BR,640JR,640CR,640KR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-03.))											
U1210004	**Flap Flexible Transmission Shafts - Hand Lubricate.**							RE		TLMC 05-19-00	**≈14-Oct-2027**
12 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	9,410.5	4,135.7 Hrs (+25)
(ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: Note: On Aircraft with over 4,800 Hours from C of A or from the last replacement date of the flexible drive shaft, perform at the next 1,200 Hour C-Phase (C4) inspection.)						Ldg	2,822				
Y1210000	**Nose Landing Gear Shock Strut - Check for Proper Fluid Level and Inflation Pressure.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Alias1:12-10-02 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-10-02.))						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210001	**Main Landing Gear Shock Struts - Check for Proper Fluid Level and Inflation Pressure.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Alias1:12-10-03 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-10-03.))						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210003	**Flap Actuator Ballnut - Lubricate.**							RE		TLMC 05-11-04	**≈24-Jul-2024**
12 A/F	05-11-04					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Alias1:12-21-03 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21- 03.) Note: On aircraft that have exceeded 300 Hours total time, perform at next 300 Hour inspection.)						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210005	**Nose Landing Gear Trunnion Pin - Lubricate.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Ref:12-21-01 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-01.))						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
Y1210006	**Nose Landing Gear Actuator Attach Fitting - Lubricate.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-01 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-01.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210007	**Nose and Main Tires - Check for proper inflation.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-10-04 (ZONE: 710 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-10-04))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210009	**Nose Gear Door Hinge - Lubricate.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
12 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12- 21-02.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210011	**Main Landing Gear Actuator Joints - Lubricate.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-01.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210012	**Main Landing Gear Axle Beam/Piston Joints - Lubricate.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-01.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210013	**Main Landing Gear Torque Links - Lubricate .**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-01.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210014	**Main Gear Door Hinge - Lubricate.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-02.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210016	**Passenger/Crew Door Hinge - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 810AL) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210017	**Passenger/Crew Door Pins - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 810AL) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210018	**Passenger/Crew Door Tension Bolts - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 810AL) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
Y1210019	**Emergency Exit Door Latching Mechanism - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 820AR) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210020	**Emergency Exit Door Pins - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 820AR) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210021	**Baggage Compartment Door Latch Pins - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 830AR) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210022	**Baggage Compartment Door Hinge - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 830AR) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210023	**Oxygen System Servicing Door Hinge - Lubricate.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
12 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 120BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-02.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210024	**Toilet Servicing Door Hinge - Lubricate.**							RE		TLMC 05-11-04	**≈24-Jul-2024**
12 A/F	05-11-04					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 610DR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-02.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210025	**Pressure Refueling Door Hinge - Lubricate.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
12 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 300/ 310HR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-02.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210026	**Fuselage Fuel Filler Door Hinge - Lubricate.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
12 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 300/ 310CR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-02.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210027	**Tailcone Access Door Pins - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 840AR) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1210028	**Tailcone Access Door Hinge - Lubricate.**							RE		TLMC 05-11-06	**≈24-Jul-2024**
12 A/F	05-11-06					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-02 (ZONE: 840AR) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y1210029	**Main Landing Gear Trunnion Pin - Lubricate.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
12 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-21-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-21-01.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1221037	**Flaps - Lubricate rolling surfaces of main and nose roller tracks.**							RE		TLMC 05-11-04	**≈24-Jul-2024**
12 A/F	05-11-04					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Ref:12-21-03 (ZONE: 500/600) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-005 thru 45-367, 45-369 thru 45-445, (Effective on Aircraft 45-005 thru 45-367, 45-369 thru 45-445, 45-447 thru 45-451 not modified by SB45-27-46.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y1221042	**Horizontal Stabilizer Upper and Lower Torque Links - Lubricate.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
12 A/F	05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Ref:12-21-03 (ZONE: 330AC, 330BC, 330CC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-005 thru 45-241 modified by SB 45-27-13, "Replacement of Upper and Lower Torque Link Assemblies", and 45-242 and subsequent.))					Ldg	3,757				
Y1227000	**Emergency Park Brake Handle Shaft - Lubricate.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
12 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Ref:12-27-00 (ZONE: 200) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-27-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
▼ 20 - STANDARD PRACTICES – AIRFRAME											
45-20-1	**Standard Practices - Modification of the Relay Panel Wire Harness Installation**							RE (-)		Recommended	
20 A/F						Mos	08-Jun-2009				
Not Applicable	PER A/C S/N					Hrs	801				
						Ldg	521				
45-20-1 Rev 1	**Standard Practices - Modification of the Relay Panel Wire Harness Installation**							RE (-)		Recommended	
20 A/F						Mos	14-Dec-2020				
Eff: 09-Mar-2009 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-20-2	**Standard Practices - Inspection/Modification of Wire Chafe Behind Center Switch Panel (P5)**							RE (-)		Optional	
20 A/F						Mos					
						Hrs					
						Ldg					
45-20-2 Rev 1	**Standard Practices - Inspection/Modification of Wire Chafe Behind Center Switch Panel (P5)**							RE (-)		Optional	
20 A/F						Mos	07-Apr-2013				
Eff: 04-Mar-2013 Not Applicable	DID NOT APPLY TO AIRCRAFT SERIAL NUMBER BUT DID ANY WAY					Hrs	2,797.6				
						Ldg	1,647				
AW 20-007	**Flight Compartment Window Maintenance/Cleaning**							RE (-)		Advisory Wire	
20 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 20-008	**Engine Hydraulic Line + Wiring Chafing**							RE (-)		Advisory Wire	
20 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 21 - AIR CONDITIONING AND PRESSURIZATION												
		ACM Bypass Check Valve							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		ACM Precooler Assembly							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Air Conditioning Compressor							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Air Conditioning Compressor Drive Motor							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Air Cycle Machine							RE (O/C)			
	21 A/F						Mos	24-Mar-2021				
	P14126						Hrs					
	1412616819						Ldg					
		Air Cycle Machine Turbine							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Avionics Cooling (B13) Fan							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Bi-Level Pressure Regulating & Shutoff (L19) Valve							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Blower Motor							RE (O/C)			
	21 A/F	Aft					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Blower Motor							RE (O/C)			
	21 A/F	Fwd					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Cabin Air Check Valve							RE (O/C)			
	21 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cabin Air Check Valve							RE (O/C)			
	21 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cabin Duct Overtemp Limiter							RE (O/C)			
	21 A/F		0				Mos	13-Mar-2008				
	627962-2/N531-9056	New	0				Hrs	0				
	627962-21177		0				Ldg	0				
		Cabin Overheat Thermostat							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cabin Pressure Controller							RE (O/C)			
	21 A/F					0	Mos	14-Dec-2010				
	2119858-10	Repaired				0	Hrs	1,704.2				
	27-50182					0	Ldg	1,036				
		Cabin Pressurization Check Valve							RE (O/C)			
	21 A/F		0				Mos	13-Mar-2008				
	130158-3-1	New	0				Hrs	0				
	77-A1025		0				Ldg	0				
		Cabin Refrigeration Condenser							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cabin Temp 28Vdc Sensor/Fan Assembly							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cabin Temperature Control Selector							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cabin Temperature Control Valve							RE (O/C)			
	21 A/F		0				Mos	13-Mar-2008				
	3291222-1	New	0				Hrs	0				
	1065		0				Ldg	0				
		Cabin Temperature, Duct Sensor							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Cabin Temperature, Low Limit Sensor							RE (O/C)			
21 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Check, Ecs (3.0 Diameter) Valve							RE (O/C)			
21 A/F	Unknown	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Check, Ecs (3.0 Diameter) Valve							RE (O/C)			
21 A/F	Unknown	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cockpit Air Check Valve							RE (O/C)			
21 A/F	Unknown	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cockpit Air Check Valve							RE (O/C)			
21 A/F	Unknown	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cockpit Duct Temperature Sensor							RE (O/C)			
21 A/F	627962-2/N531-9056	New	0				Mos	13-Mar-2008				
	627962-21120		0				Hrs	0				
			0				Ldg	0				
		Cockpit Overheat Thermostat							RE (O/C)			
21 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cockpit Temperature Control Selector							RE (O/C)			
21 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cockpit Temperature Control Valve							RE (O/C)			
21 A/F	3291222-1	New	0				Mos	13-Mar-2008				
	1062		0				Hrs	0				
			0				Ldg	0				
		Cockpit Temperature Sensor							RE (O/C)			
21 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Ecs Transition Duct							RE (O/C)			
21 A/F	Unknown	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Ecs Transition Duct							RE (O/C)			
21 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Emergency Pressure Aneroid Switch							RE (O/C)			
21 A/F			0				Mos	13-Mar-2008				
E45C-47		New	0				Hrs	0				
5615			0				Ldg	0				
		Emergency Pressure Shutoff Valve							RE (O/C)			
21 A/F		Left	0				Mos	13-Mar-2008				
3291224-1		New	0				Hrs	0				
1053			0				Ldg	0				
		Emergency Pressure Shutoff Valve							RE (O/C)			
21 A/F		Right	0				Mos	13-Mar-2008				
3291224-1		New	0				Hrs	0				
1033			0				Ldg	0				
		Emergency Pressurization Isolation Check Valve							RE (O/C)			
21 A/F		Left	0				Mos	13-Mar-2008				
3202744-1		New	0				Hrs	0				
2913			0				Ldg	0				
		Emergency Pressurization Isolation Check Valve							RE (O/C)			
21 A/F		Right	0				Mos	13-Mar-2008				
3202744-1		New	0				Hrs	0				
2914			0				Ldg	0				
		Engine Ozone Converter							RE (O/C)			
21 A/F		Left	0				Mos	22-Dec-2015				
4520000100-801		New	0				Hrs	3,621.8				
1900			0				Ldg	2,105				
		Engine Ozone Converter							RE (O/C)			
21 A/F		Right	0				Mos	22-Dec-2015				
4520000100-801		New	0				Hrs	3,621.8				
1875			0				Ldg	2,105				
		Environmental Control Unit							RE (O/C)			
21 A/F			0				Mos	13-Mar-2008				
2215150-3		New	0				Hrs	0				
577			0				Ldg	0				
		Evaporator							RE (O/C)			
21 A/F		Aft					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Evaporator							RE (O/C)			
21 A/F		Fwd					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Foot Warmer (S167) Thermostat							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Gasper Air Check Valve							RE (O/C)			
	21 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Gasper Air Check Valve							RE (O/C)			
	21 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Heat, Primary, Secondary Exchanger							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Integrated Ecs Temperature Controller							RE (O/C)			
	21 A/F					9	Mos	09-Oct-2012				
	6621000000-081						Hrs	2,650.5				
	070C-0498						Ldg	1,567				
		Jet Pump Ejector							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Heel Plate Assembly, Foot Warmer							RE (O/C)			
	21 A/F	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Heel Plate Assembly, Foot Warmer							RE (O/C)			
	21 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Linear Electro-Mechanical Actuator							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Low Limit Temperature Control Valve							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Mount Assy Fan Avionics Cooling							RE (O/C)			
	21 A/F		0				Mos	13-Mar-2008				
	4521208521-009	New	0				Hrs	0				
	A00806543-01		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Outflow, Secondary Valve							RE (O/C)			
21 A/F	6621300000-021	Repaired			0		Mos	08-Nov-2010				
	45-B0039				0		Hrs	1,639				
					0		Ldg	995				
		Plenum Check Valve							RE (O/C)			
21 A/F	6621000000-037	Left New	0				Mos	28-Apr-2009				
	3835		0				Hrs	753				
			0				Ldg	494				
		Plenum Check Valve							RE (O/C)			
21 A/F	6621000000-037	Right New	0				Mos	28-Apr-2009				
	3947		0				Hrs	753				
			0				Ldg	494				
		Pressure Switch							RE (O/C)			
21 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Primary Outflow Valve							RE (O/C)			
21 A/F	103858-1	Repaired			0		Mos	11-Mar-2011				
	89-A0164				0		Hrs	1,857.4				
					0		Ldg	1,121				
		Regulating, Servo Air Pressure Valve							RE (O/C)			
21 A/F	6600245-004	New					Mos	14-Jan-2022				
	1717						Hrs	4,857.3				
							Ldg	2,991				
		Right Heel Plate Assembly, Foot Warmer							RE (O/C)			
21 A/F	Unknown	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Right Heel Plate Assembly, Foot Warmer							RE (O/C)			
21 A/F	Unknown	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Servo Air Pressure Regulating Valve							RE (O/C)			
21 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Tailcone Check Valve							RE (O/C)			
21 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Thermal Control Actuator							RE (O/C)			
21 A/F	Unknown	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Thermal Control Actuator							RE (O/C)			
	21 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Water Separator Assembly							RE (O/C)			
	21 A/F			0			Mos	09-May-2008				
	2341168-1	Overhauled		0			Hrs	125.6				
	109-214			0			Ldg	102				
		Water Seperator Bypass Valve							RE (O/C)			
	21 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
2002-17-01		**Foot Warm Circuit Breaker**							RE (-)		Mandatory	
	21 A/F						Mos	11-Feb-2010				
	Eff: 12-Sep-2002 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
							Ldg	739				
2017-06-03 Paragraph (g)		**Heating System - Inspection and Pressure Decay Test (PDT) of the Combustion Heater**							RE (-)		Mandatory (Appliance AD)	
	21 A/F						Mos					
	Eff: 05-May-2017						Hrs					
							Ldg					
2017-06-03 Paragraph (k)		**Heating System - Disable or Removal of the Combustion Heater**							RE (-)		Mandatory (Appliance AD)	
	21 A/F						Mos					
	Eff: 05-May-2017						Hrs					
							Ldg					
45-21-1		**Air Conditioning - Installation of Aft Lavatory Cabin Air Plenum**							RE (-)		Optional	
	21 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-21-1 Rev 1		**Air Conditioning - Installation of Aft Lavatory Cabin Air Plenum**							RE (-)		Optional	
	21 A/F						Mos	29-Aug-2019				
	Eff: 11-Jan-2002 Not Applicable						Hrs	4,516.2				
							Ldg	2,733				
45-21-10		**Air Conditioning - Replacement of Cabin Overhead Registers**							RE (-)		Optional	
	21 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-21-10 Rev 1		**Air Conditioning - Replacement of Cabin Overhead Registers**							RE (-)		Optional	
	21 A/F						Mos	29-Aug-2019				
	Eff: 09-Mar-2005 Not Applicable						Hrs	4,516.2				
							Ldg	2,733				
45-21-11		**Air Conditioning - Installation of Cabin Pressure Controller Bonding Jumper**							RE (-)		Recommended	
	21 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-21-11 Rev 1		**Air Conditioning - Installation of Cabin Pressure Controller Bonding Jumper**							RE (-)		Recommended	
	21 A/F						Mos	14-Dec-2020				
	Eff: 12-Apr-2002 Not Applicable						Hrs	4,610.5				
							Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-21-12	**Air Conditioning - Reactivation of Auxiliary Cabin Heat**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 23-Jan-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-13	**Air Conditioning - Upgrade of the Cabin Pressure Controller**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-13 Rev 1	**Air Conditioning - Upgrade of the Cabin Pressure Controller**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-13 Rev 2	**Air Conditioning - Upgrade of the Cabin Pressure Controller**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 11-Aug-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-15	**Air Conditioning - Replacement/Modification of the Pilot and Copilot Heel Plate Assemblies**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-15 Rev 1	**Air Conditioning - Replacement/Modification of the Pilot and Copilot Heel Plate Assemblies**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-15 Rev 2	**Air Conditioning - Replacement/Modification of the Pilot and Copilot Heel Plate Assemblies**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 25-Nov-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-16	**Air Conditioning - Installation of Pneumatic Tube Assembly Filters**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 22-Jul-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-17	**Air Conditioning - Improvement of Keith R-134A Optional Heating/Cooling System**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 29-Jul-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-18	**Air Conditioning - Installation of ECS Diverter Doors**							RE (-)		Optional	
21 A/F						Mos					
						Hrs					
						Ldg					
45-21-18 Rev 1	**Air Conditioning - Installation of ECS Diverter Doors**							T (A/R)		Optional	
21 A/F						Mos					
Eff: 19-Jan-2009						Hrs					
						Ldg					
45-21-19	**Air Conditioning - Cabin Air Supply Duct Assembly Domenut Replacement**							T (-)		Optional	
21 A/F						Mos					
Eff: 16-Jun-2008						Hrs					
						Ldg					
45-21-19 Rev 1	**Air Conditioning - Cabin Air Supply Duct Assembly Domenut Replacement**							T (A/R)		Optional	
21 A/F						Mos					
Eff: 22-May-2017						Hrs					
(AVG MAN HRS: 90)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-21-2	**Air Conditioning - Installation of Improved Cockpit Foot Warmers**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-2 Rev 1	**Air Conditioning - Installation of Improved Cockpit Foot Warmers**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-2 Rev 2	**Air Conditioning - Installation of Improved Cockpit Foot Warmers**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-2 Rev 3	**Air Conditioning - Installation of Improved Cockpit Foot Warmers**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-2 Rev 4	**Air Conditioning - Installation of Improved Cockpit Foot Warmers**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 19-Mar-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-20	**Air Conditioning - Inspection/Replacement of PerkinElmer Bleed Air Couplings in the Anti-Ice System**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 12-Apr-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-21	**Air Conditioning - Inspection/Modification of the Keith Products R-134A System Wiring**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 26-Nov-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-22	**Air Conditioning - Modification of the Keith Products Heating Power/Ground Contact Installation**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 21-May-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-23	**Air Conditioning - Modification of the Cabin Blower Circuit Wiring**							RE (-)		Recommended	
21 A/F						Mos					
Eff: 18-May-2009						Hrs					
(AVG MAN HRS: 7)						Ldg					
45-21-23 Rev 1	**Air Conditioning - Modification of the Cabin Blower Circuit Wiring**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 29-Nov-2010 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 7)						Ldg	2,822				
45-21-24	**Air Conditioning - Replacement of Keith Products Air Conditioning Terminal Lugs**							RE (-)		Recommended	
21 A/F						Mos					
Eff: 21-Sep-2009						Hrs					
(AVG MAN HRS: 65)						Ldg					
45-21-24 Rev 1	**Air Conditioning - Replacement of Keith Products Air Conditioning Terminal Lugs**							RE (-)		Recommended	
21 A/F						Mos					
Eff: 11-Jan-2010						Hrs					
(AVG MAN HRS: 65)						Ldg					
45-21-24 Rev 2	**Air Conditioning - Replacement of Keith Products Air Conditioning Terminal Lugs**							RE (-)		Recommended	
21 A/F						Mos					
Eff: 16-Aug-2010						Hrs					
(AVG MAN HRS: 65)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-21-24 Rev 3	**Air Conditioning - Replacement of Keith Products Air Conditioning Terminal Lugs**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 01-Dec-2010 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 65)						Ldg	2,822				
45-21-25	**Air Conditioning - Modification of the Environmental Control System (ECS) Plenum Assembly Duct Flange**							RE (-)		Recommended	
21 A/F						Mos					
Eff: 01-Aug-2011						Hrs					
(AVG MAN HRS: 20)						Ldg					
45-21-25 Rev 1	**Air Conditioning - Modification of the Environmental Control System (ECS) Plenum Assembly Duct Flange**							RE (-)		Recommended	
21 A/F						Mos	14-May-2012				
Eff: 30-Jan-2012 Complied With	MODIFICATION OF THE ENVIRONMENTAL CONTROL SYATTEM (ECS) PLENUM ASSEMBLY DUCT FLANGE					Hrs	2,466.6				
(AVG MAN HRS: 20)						Ldg	1,468				
45-21-26	**Air Conditioning - Inspection of Air Conditioning System Power Distribution Panel**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 25-Nov-2013 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 5)						Ldg	2,822				
45-21-27	**Air Conditioning - Baggage Compartment Heater Replacement - Special Spares Kit**							T (A/R)		Optional	
21 A/F						Mos					
Eff: 07-Jul-2014						Hrs					
						Ldg					
45-21-28	**Air Conditioning - Cabin Pressure Controller Inspection/Replacement**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 29-Sep-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 13)						Ldg	2,822				
45-21-3	**Air Conditioning - Relocation of Baggage Heater Switch**							RE (-)		Optional	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-3 Rev 1	**Air Conditioning - Relocation of Baggage Heater Switch**							RE (-)		Optional	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-3 Rev 2	**Air Conditioning - Relocation of Baggage Heater Switch**							RE (-)		Optional	
21 A/F						Mos	29-Aug-2019				
Eff: 12-Apr-2002 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-21-4	**Air Conditioning - Modification of the Environmental Control System for Reduced Cabin Noise Levels**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-4 Rev 1	**Air Conditioning - Modification of the Environmental Control System for Reduced Cabin Noise Levels**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-4 Rev 2	**Air Conditioning - Modification of the Environmental Control System for Reduced Cabin Noise Levels**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-21-4 Rev 3	**Air Conditioning - Modification of the Environmental Control System for Reduced Cabin Noise Levels**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-4 Rev 4	**Air Conditioning - Modification of the Environmental Control System for Reduced Cabin Noise Levels**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 20-Nov-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-4 Rev 5	**Air Conditioning - Modification of the Environmental Control System for Reduced Cabin Noise Levels**							RE (-)		Recommended	
21 A/F						Mos					
Eff: 12-Jun-2023						Hrs					
(AVG MAN HRS: 35)						Ldg					
45-21-5	**Air Conditioning - Installation of ECS Diverter Doors**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-5 Rev 1	**Air Conditioning - Installation of ECS Diverter Doors**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-5 Rev 2	**Air Conditioning - Installation of ECS Diverter Doors**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-5 Rev 3	**Air Conditioning - Installation of ECS Diverter Doors**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 19-Jan-2009 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-6	**Air Conditioning - Restrictor Plate Installation**							RE (-)		Optional	
21 A/F						Mos	17-Jan-2014				
Not Applicable	PER THIS EQUIPMENT NOT INSTALLED ON THIS AIRCRAFT					Hrs	3,055.8				
						Ldg	1,792				
45-21-6 Rev 1	**Air Conditioning - Restrictor Plate Installation**							RE (-)		Optional	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-6 Rev 2	**Air Conditioning - Restrictor Plate Installation**							RE (-)		Optional	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-6 Rev 3	**Air Conditioning - Restrictor Plate Installation**							RE (-)		Optional	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-6 Rev 4	**Air Conditioning - Restrictor Plate Installation**							RE (-)		Optional	
21 A/F						Mos	29-Aug-2019				
Eff: 11-Feb-2005 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-21-7	**Air Conditioning - Inspection of Check Valve**							RE (-)		Recommended	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-21-7 Rev 1	**Air Conditioning - Inspection of Check Valve**							RE (-)		Recommended	
21 A/F						Mos	14-Dec-2020				
Eff: 12-Oct-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-21-8	**Air Conditioning - Installation of Environmental Control System Noise Reduction Kit**							RE (-)		Optional	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-8 Rev 1	**Air Conditioning - Installation of Environmental Control System Noise Reduction Kit**							RE (-)		Optional	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-8 Rev 2	**Air Conditioning - Installation of Environmental Control System Noise Reduction Kit**							RE (-)		Optional	
21 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-21-8 Rev 3	**Air Conditioning - Installation of Environmental Control System Noise Reduction Kit**							RE (-)		Optional	
21 A/F						Mos	29-Aug-2019				
Eff: 06-Jul-2009 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
A45-21-14	**Electrical Power - Deactivation of Cockpit Foot Warmers**							RE (-)		Alert	
21 A/F						Mos	14-Dec-2020				
Eff: 24-May-2002 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 0.5)						Ldg	2,822				
A45-21-9	**Air Conditioning - Deactivation of Auxiliary Cabin Heat**							RE (-)		Alert	
21 A/F						Mos	13-Mar-2008				
Eff: 27-Feb-2001 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 3.5)						Ldg					
A45-21-9 Rev 1	**Air Conditioning - Deactivation of Auxiliary Cabin Heat**							RE (-)		Alert	
21 A/F						Mos	14-Dec-2020				
Eff: 18-Jun-2003 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 3.5)						Ldg	2,822				
AW 21-004	**Uncommanded Cabin Altitude Increase**							RE (-)		Advisory Wire	
21 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 21-006	**Learjet 45 Foot Warmer Reactivation**							RE (-)		Advisory Wire	
21 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 21-010	**Inspection of Keith Products Air Conditioning Power Panel Hardware**							RE (-)		Advisory Wire	
21 A/F						Mos					
Not Applicable	WE DO NOT HAVE THIS SYSTEM.					Hrs					
						Ldg					
AW21-010	**Inspection of Keith Products - Air Conditioning Power - Panel Hardware**							RE (-)		Mandatory	
21 A/F						Mos					
Eff: 02-Aug-2013 Not Applicable	WE DO NOT HAVE THIS SYSTEM					Hrs					
						Ldg					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
J2160007	**Temperature Control System - Inspect and clean cabin and cockpit temperature control valve servo air filters.**							RE		TLMC 05-12-02	**≈24-Oct-2024**
21 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:21-60-11 (ZONE: 300) (Tol. Adjustment: -30d) (SOURCE: MM-104) (NOTE: (Refer to 21-60-11.))					Ldg	3,757				
L2150054	**Air Conditioning Compressor Drive Motor Brushes - Perform Wear Inspection. (Return Drive Motor to authorized service facility for overhaul.)**							RE (N/A)		TLMC 05-19-00	
21 A/F						Mos					
						Hrs					
	(ZONE: 300) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-250 and subsequent equipped with Keith Products vapor cycle air conditioning system using refrigerant R-134.))					Ldg					
L2150055	**Air Conditioning Compressor Motor - Perform Overhaul. (Return Drive Motor to authorized service facility for overhaul.)**							RE (N/A)		TLMC 05-19-00	
21 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
	(ZONE: 300) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-250 and subsequent equipped with Keith Products vapor cycle air conditioning system using refrigerant R-134.))										
L2150056	**** Auxiliary Heat System - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-12-02, Ch.5 Interval		**≈24-Oct-2024**
21 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:21-51-00 (ZONE: 300) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-51-00.) (Effective on Aircraft 45-250 and subsequent equipped with Keith Products vapor cycle air conditioning system using refrigerant R-134.))					Ldg	3,757				
L2150057	**** Auxiliary Heat System - Perform Auxiliary Heater Electrical and Temperature Switch Test.**							RE	TLMC 04-10-00, TLMC 05-13-02, Ch.5 Interval		**≈24-Apr-2025**
21 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:21-51-00 (ZONE: 300) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-51-00.) (Effective on Aircraft 45-250 and subsequent equipped with Keith Products vapor cycle air conditioning system using refrigerant R-134.))					Ldg	3,757				
O2130000	**Primary and Secondary Outflow Valves - Perform Inspection.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
21 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:21-30-01, 21-30-02 (ZONE: 210) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (refer to 21-30-01 and 21-30-02))					Ldg	3,757				
O2130001	**Outflow Valve Air Filter - Remove and replace.**							RE		TLMC 05-14-01	**≈12-Oct-2025**
21 A/F	05-14-01					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:21-30-04 (ZONE: 210) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-30-04.))					Ldg	2,822				
O2130002	**** Pressurization Control System - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-13-01, Ch.5 Interval		**≈24-Apr-2025**
21 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:21-30-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-30-00.))					Ldg	3,757				
WYB-2022-02-15-02	**RE/RE SENSOR, DUCT TEMP (COCKPIT)**							RE (-)			
21 A/F						Mos	03-Mar-2022				
6600423-4						Hrs	4,883				
Unknown						Ldg	3,012				
	(AVG MAN HRS: 6) (UPDATE NOTE: SENSOR BENCH CHECKED SERVICEABLE. UNIT TO BE RE INSTALLED IN COCKPIT DUCT.)										
Y2130003	**Pressurization Control System - Perform Operational Check.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
21 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:21-30-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-30-00.))					Ldg	3,757				
Y2130065	**Cabin Pressurization System - Perform Cabin Leakage Test.**							RE		TLMC 05-19-00	**≈05-Oct-2024**
21 A/F						Mos	22-May-2020				
						Hrs	4,593.2	1,200	-/+25	5,793.2	518.4 Hrs (+25)
	Alias1:21-30-00 (ZONE: 200) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-30-00.))					Ldg	2,809				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
Y2140000	**Air Cycle Machine Heat Exchanger Inlet - Perform visual inspection.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
21 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 310FR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2140001	**Ozone Converters - Perform Efficiency Test.**							RE		TLMC 05-19-00	**≈15-Dec-2025**
21 A/F	Left					Mos	22-Dec-2015				
4520000100-801						Hrs	3,621.8	3,600	-/+25	7,221.8	1,947 Hrs (+25)
1900						Ldg	2,105				
	Ref:05-19-01 (ZONE: 340FL, 340FR, 340CL, 340CR) (SOURCE: MM-104, MM-105) (NOTE: NOTE: Ship ozone converter to RSA Engineered Products, 110-A W. Cochran St., Simi Valley, California (93065), for cleaning and efficiency testing.)										
Y2140001	**Ozone Converters - Perform Efficiency Test.**							RE		TLMC 05-19-00	**≈15-Dec-2025**
21 A/F	Right					Mos	22-Dec-2015				
4520000100-801						Hrs	3,621.8	3,600	-/+25	7,221.8	1,947 Hrs (+25)
1875						Ldg	2,105				
	Ref:05-19-01 (ZONE: 340FL, 340FR, 340CL, 340CR) (SOURCE: MM-104, MM-105) (NOTE: NOTE: Ship ozone converter to RSA Engineered Products, 110-A W. Cochran St., Simi Valley, California (93065), for cleaning and efficiency testing.)										
Y2141000	**Environmental Control Unit - Perform visual inspection.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
21 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 310HL, 310QR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2141001	**Water Separator Coalescer Bag - Perform Visual Inspection. Clean if necessary.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
21 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 310HL, 310RR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) Note: The servicing activity may require a more frequent interval, depending on environmental and operational requirements, and should be adjusted by individual operators.)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y2141002	**Water Separator Coalescer Bag - Replace.**							RE (-)		TLMC 05-19-01	
21 A/F						Mos	18-Mar-2009				
						Hrs	697.2				
	Brand C:Y2141002 (ZONE: 310HL, 310RR) (SOURCE: MM-104, MM-105)					Ldg	470				
Y2142000	**Baggage Compartment Heating System - Perform Functional Test.**							RE		TLMC 05-14-02	**≈12-Oct-2025**
21 A/F	05-14-02					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:21-40-00 (ZONE: 310) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-40-00.))					Ldg	2,822				
Y2145000	**ECS Plenum Assembly Check Valves - Perform visual inspection. Verify freedom of movement of butterfly assembly.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
21 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:21-20-03, 21-20-09 (ZONE: 310) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-20-03 for the Emergency Pressurization Isolation Check Valve.) (Refer to 21-20-09 for Plenum Assembly Check Valve.))					Ldg	3,757				
Y2150058	**Perform visual inspection of air conditioning system components, including compressor motor belt for wear and proper V-belt tension, condenser coils for cleanliness and hoses for chafing and wear. If oil leaks are visible and/or refrigerant dumped, check compressor oil level (some leakage is allowable around shaft.)**							RE		TLMC 05-13-02	**≈24-Apr-2025**
21 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 300) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft 45-250 and Subsequent equipped with Keith Products vapor cycle air conditioning system using refrigerant R-134.))					Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y2150059	**Air Conditioning System - Perform Load Shed Assembly Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
21 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:21-51-00 (ZONE: 300) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 21-51-00.) (Effective on Aircraft 45-250 and subsequent equipped with Keith Products vapor cycle air conditioning system using refrigerant R-134.))					Ldg	3,757				
▼ 22 - AUTOFLIGHT											
	Autopilot, Pitch Servo							RE (O/C)			
22 A/F		0				Mos	13-Mar-2008				
4006719-923	New	0				Hrs	0				
0705H764		0				Ldg	0				
	Autopilot, Roll Servo							RE (O/C)			
22 A/F		0				Mos	13-Mar-2008				
4006719-949	New	0				Hrs	0				
0701H564		0				Ldg	0				
	Autopilot, Yaw Servo							RE (O/C)			
22 A/F				0		Mos	30-Nov-2009				
7012919-904	Repaired			0		Hrs	1,072.6				
0510H008				0		Ldg	667				
	Flight Guidance, Autopilot Controller							RE (O/C)			
22 A/F				4		Mos	27-Apr-2012				
7021170-901						Hrs					
02021113						Ldg					
	Servo, Pitch Bracket							RE (O/C)			
22 A/F		0				Mos	13-Mar-2008				
4005842	New	0				Hrs	0				
0701H615		0				Ldg	0				
	Servo, Roll Bracket							RE (O/C)			
22 A/F		0				Mos	13-Mar-2008				
4005842	New	0				Hrs	0				
0612H579		0				Ldg	0				
	Servo, Yaw Bracket							RE (O/C)			
22 A/F		0				Mos	13-Mar-2008				
7012098-902	New	0				Hrs	0				
0705H060		0				Ldg	0				
	Yaw Force, Rudder Boost System Sensor							RE (O/C)			
22 A/F	Pilot					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Yaw Force, Rudder Boost System. Sensor							RE (O/C)			
22 A/F	Copilot					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Yaw Interface Unit							RE (O/C)			
22 A/F				0		Mos	06-Jul-2011				
4522108501-013	Repaired			0		Hrs	2,059.6				
884003				0		Ldg	1,239				
2000-05-24	**Honeywell KAP 140/KFC 225 Autopilot System**							RE (-)		Mandatory (Appliance AD)	
22 A/F						Mos	13-Mar-2008				
Eff: 12-Apr-2000 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
2001-10-09	**Automatic Flight Control Systems**							RE (-)		Mandatory (Appliance AD)	
22 A/F						Mos	31-Mar-2008				
Eff: 15-Jun-2001 Not Applicable						Hrs	11.6				
						Ldg	11				
2002-22-13	**Rockwell Collins, Inc. - Flight management computers (FMC)**							RE (-)		Mandatory (Appliance AD)	
22 A/F						Mos	31-Mar-2008				
Eff: 20-Dec-2002 Not Applicable						Hrs	11.6				
						Ldg	11				
45-22-1	**Auto Flight - Honeywell Phase II/IIA Software Upgrade**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-1 Rev 1	**Auto Flight - Honeywell Phase II/IIA Software Upgrade**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-1 Rev 2	**Auto Flight - Honeywell Phase II/IIA Software Upgrade**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-1 Rev 3	**Auto Flight - Honeywell Phase II/IIA Software Upgrade**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-1 Rev 4	**Auto Flight - Honeywell Phase II/IIA Software Upgrade**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-1 Rev 5	**Auto Flight - Honeywell Phase II/IIA Software Upgrade**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-1 Rev 6	**Auto Flight - Honeywell Phase II/IIA Software Upgrade**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-1 Rev 7	**Auto Flight - Honeywell Phase II/IIA Software Upgrade**							RE (-)		Optional	
22 A/F						Mos	29-Aug-2019				
Eff: 08-Dec-2000 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-22-10	**Auto Flight - Honeywell Phase VI Avionics Upgrade**							RE (-)		Recommended	
22 A/F						Mos	21-Sep-2009				
Complied With						Hrs	959.2				
						Ldg	607				
45-22-10 Rev 1	**Auto Flight - Honeywell Phase VI Avionics Upgrade**							RE (-)		Recommended	
22 A/F						Mos					
						Hrs					
						Ldg					
45-22-10 Rev 2	**Auto Flight - Honeywell Phase VI Avionics Upgrade**							RE (-)		Recommended	
22 A/F						Mos	21-Sep-2009				
Eff: 20-Apr-2009 Complied With						Hrs	959.2				
						Ldg	607				
45-22-11	**Auto Flight - Inspection/Replacement of Safety Wire or Cable on the Aileron Servo Cable Lower Quadrant**							RE (-)		Recommended	
22 A/F						Mos	29-Apr-2014				
Eff: 17-Mar-2014 Complied With						Hrs	3,155.3				
(AVG MAN HRS: 3)						Ldg	1,843				
45-22-12	**Auto Flight - Modification of Garmin Servo Actuator Mounts**							RE (-)		Recommended	
22 A/F						Mos	14-Dec-2020				
Eff: 18-Aug-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 6)						Ldg	2,822				
45-22-2	**Auto Flight - Installation of Yaw Damper Disconnect Resistor**							RE (-)		Optional	
22 A/F						Mos	29-Aug-2019				
Eff: 16-Apr-1999 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-22-3	**Auto Flight - Replacement of Autopilot Yaw Servo**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-3 Rev 1	**Auto Flight - Replacement of Autopilot Yaw Servo**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-3 Rev 2	**Auto Flight - Replacement of Autopilot Yaw Servo**							RE (-)		Optional	
22 A/F						Mos	29-Aug-2019				
Eff: 16-Feb-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-22-4	**Auto Flight - Honeywell Phase III Software Upgrade**							RE (-)		Recommended	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-4 Rev 1	**Auto Flight - Honeywell Phase III Software Upgrade**							RE (-)		Recommended	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-4 Rev 2	**Auto Flight - Honeywell Phase III Software Upgrade**							RE (-)		Recommended	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-4 Rev 3	**Auto Flight - Honeywell Phase III Software Upgrade**							RE (-)		Recommended	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-22-4 Rev 4	**Auto Flight - Honeywell Phase III Software Upgrade**							RE (-)		Recommended	
22 A/F						Mos	14-Dec-2020				
Eff: 17-May-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-22-5	**Auto Flight - Honeywell Phase IV Upgrade**							RE (-)		Recommended	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-5 Rev 1	**Auto Flight - Honeywell Phase IV Upgrade**							RE (-)		Recommended	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-5 Rev 2	**Auto Flight - Honeywell Phase IV Upgrade**							RE (-)		Recommended	
22 A/F						Mos	14-Dec-2020				
Eff: 29-Mar-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-22-6	**Flight Controls - Modification of Rudder Force Sensor Installation & Routing**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-6 Rev 1	**Flight Controls - Modification of Rudder Force Sensor Installation & Routing**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-6 Rev 2	**Flight Controls - Modification of Rudder Force Sensor Installation & Routing**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-6 Rev 3	**Flight Controls - Modification of Rudder Force Sensor Installation & Routing**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-6 Rev 4	**Flight Controls - Modification of Rudder Force Sensor Installation & Routing**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-6 Rev 5	**Flight Controls - Modification of Rudder Force Sensor Installation & Routing**							RE (-)		Optional	
22 A/F						Mos	29-Aug-2019				
Eff: 02-Aug-2010 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-22-7	**Auto Flight - Honeywell Phase V Avionics Upgrade (IC-600 Integrated Computer Replacement)**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-7 Rev 1	**Auto Flight - Honeywell Phase V Avionics Upgrade (IC-600 Integrated Computer Replacement)**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-7 Rev 2	**Auto Flight - Honeywell Phase V Avionics Upgrade (IC-600 Integrated Computer Replacement)**							RE (-)		Optional	
22 A/F						Mos					
Eff: 24-Nov-2008						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-22-8	**Auto Flight - Honeywell Brakes Fail CAS Inhibit Accessory Kit**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-8 Rev 1	**Auto Flight - Honeywell Brakes Fail CAS Inhibit Accessory Kit**							RE (-)		Optional	
22 A/F						Mos					
						Hrs					
						Ldg					
45-22-8 Rev 2	**Auto Flight - Honeywell Brakes Fail CAS Inhibit Accessory Kit**							RE (-)		Optional	
22 A/F						Mos					
Eff: 20-Dec-2010						Hrs					
						Ldg					
45-22-9	**Autoflight - Honeywell Phase V Avionics Upgrade (On Aircraft Software Load)**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-9 Rev 1	**Autoflight - Honeywell Phase V Avionics Upgrade (On Aircraft Software Load)**							RE (-)		Optional	
22 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-22-9 Rev 2	**Autoflight - Honeywell Phase V Avionics Upgrade (On Aircraft Software Load)**							RE (-)		Optional	
22 A/F						Mos					
Eff: 24-Nov-2008						Hrs					
						Ldg					
A2210033	**** Autopilot System - Perform Autopilot Disconnect Tone Test.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
22 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:22-10-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 22-10-00.))						Ldg	3,757				
AW 22-004	**Honeywell Primus 1000 as Installed In Model 45**							RE (-)		Advisory Wire	
22 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 22-005	**Honeywell Phase III Program Information**							RE (-)		Advisory Wire	
22 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 22-006	**Model 45 Airplane Flight Manual Yaw Damper Change**							RE (-)		Advisory Wire	
22 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
G2210030	**Pitch Servo Cables - Perform Cable Tension Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
22 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:22-10-03 (ZONE: 320EL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 22-10-03.))						Ldg	3,757				
G2210031	**Roll Servo Cables - Perform Cable Tension Check.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
22 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:22-10-05 (ZONE: 250CC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 22-10-05.))						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time / Remaining
G2210032	**Yaw Servo Cables - Perform Cable Tension Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
22 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:22-10-07 (ZONE: 320EL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 22-10-07.))					Ldg	3,757				
▼ 23 - COMMUNICATIONS											
	Garmin GDL-51R XM Data Receiver - EFB							RE (O/C)			
23 A/F						Mos	27-Sep-2023				
010-01561-55						Hrs	5,197.3				
4RF501535						Ldg	3,212				
	AFIS Configuration Module							RE (O/C)			
23 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	AIRSERV Transmitter Replace							RE (O/C)			
23 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	ARTU Tray							RE (O/C)			
23 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Audio Control Unit							RE (O/C)			
23 A/F	No.1		0			Mos	13-Mar-2008				
4523558501-003	New		0			Hrs	0				
0709C331			0			Ldg	0				
	Audio Control Unit							RE (O/C)			
23 A/F	No.2		0			Mos	13-Mar-2008				
4523558501-003	New		0			Hrs	0				
0709C332			0			Ldg	0				
	Audio Distribution Module							RE (O/C)			
23 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Audio/Video Controller							RE (O/C)			
23 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Bridging, HF Amplifier							RE (O/C)			
23 A/F	No.1					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Bridging, HF Amplifier							RE (O/C)			
23 A/F	No.2					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Cabin Assembly Phone							RE (O/C)			
23 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cabin Distribution Bus Repeater							RE (O/C)			
23 A/F	Unknown	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cabin Distribution Bus Repeater							RE (O/C)			
23 A/F	Unknown	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cabin Iridium Satcom Handset							RE (O/C)			
23 A/F	Unknown	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cabin Iridium Satcom Handset							RE (O/C)			
23 A/F	Unknown	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cabin Iridium Satcom Phone Cradle							RE (O/C)			
23 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Cabin Speaker							RE (O/C)			
23 A/F	EN-MT-45A	Aft - Left		0			Mos	13-Mar-2008				
	110700248	New		0			Hrs	0				
				0			Ldg	0				
		Cabin Speaker							RE (O/C)			
23 A/F	EN-MT-45A	Aft - Right		0			Mos	13-Mar-2008				
	070700121	New		0			Hrs	0				
				0			Ldg	0				
		Cabin Speaker							RE (O/C)			
23 A/F	EN-MT-45A	Fwd - Left		0			Mos	13-Mar-2008				
	090700434	New		0			Hrs	0				
				0			Ldg	0				
		Cabin Speaker							RE (O/C)			
23 A/F	EN-MT-45A	Fwd - Right		0			Mos	13-Mar-2008				
	070700122	New		0			Hrs	0				
				0			Ldg	0				
		Cabin Video Monitor							RE (O/C)			
23 A/F	Unknown	Aft					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Cabin Video Monitor							RE (O/C)			
	23 A/F	Fwd	0				Mos	26-Jun-2008				
	LCD-9121-101-2	New	0				Hrs	237				
	020800341		0				Ldg	182				
		Call Alerter (Cas) Switch							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cassette Tape Player							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Clearance Delivery Unit							RE (O/C)			
	23 A/F		0				Mos	13-Mar-2008				
	7513000-835	New	0				Hrs	0				
	07103574		0				Ldg	0				
		Cockpit Area Microphone							RE (O/C)			
	23 A/F		0				Mos	13-Mar-2008				
	980-6113-001	New	0				Hrs	0				
	04940MFR97896		0				Ldg	0				
		Cockpit Assembly Phone							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cockpit Iridium Satcom Base Unit							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cockpit Iridium Satcom Handset							RE (O/C)			
	23 A/F						Mos	10-Feb-2021				
	9L8810A-B	New					Hrs	4,610.5				
	500013						Ldg	2,822				
		Cockpit Iridium Satcom Phone Cradle							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cockpit Speaker							RE (O/C)			
	23 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cockpit Speaker							RE (O/C)			
	23 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Cockpit Voice Recorder							RE (O/C)			
	23 A/F	CVR	0				Mos	13-Mar-2008				
	980-6022-011	Tested/Inspected	0				Hrs	0				
	CVR120-63874		0				Ldg	0				
		Cockpit Voice Recorder Pre-Amplifier							RE (O/C)			
	23 A/F		0				Mos	13-Mar-2008				
	980-6118-001	New	0				Hrs	0				
	00715		0				Ldg	0				
		Cockpit Voice Recorder Underwater Locator Beacon							RE (O/C)			
	23 A/F	CVR					Mos	06-Feb-2022				
	DK120	Tested/Inspected					Hrs	4,859.6				
	ST11030						Ldg	2,992				
		Communication Strap Board							RE (O/C)			
	23 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Communication Strap Board							RE (O/C)			
	23 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		CVR Inertia Switch							RE (O/C)			
	23 A/F		0				Mos	13-Mar-2008				
	3LO-453/8	New	0				Hrs	0				
	82451		0				Ldg	0				
		DVD Player							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		GDC34 Converter Replace							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Headset							RE (O/C)			
	23 A/F	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Headset							RE (O/C)			
	23 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		HF (KCU-951) Control							RE (O/C)			
	23 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		HF (KCU-951) Control							RE (O/C)			
	23 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		HF SELCAL Antenna							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		HF SELCAL Receiver/Exciter							RE (O/C)			
	23 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		HF SELCAL Receiver/Exciter							RE (O/C)			
	23 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Infrared Remote Module Receiver							RE (O/C)			
	23 A/F		0				Mos	13-Mar-2008				
	IFR-485-05-1	New	0				Hrs	0				
	120700749		0				Ldg	0				
		Interphone Jack Box Assembly							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Iridium Phone System Base Unit							RE (O/C)			
	23 A/F	Aft					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Iridium Satcom Antenna							RE (O/C)			
	23 A/F	Aft					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Iridium Satcom Antenna							RE (O/C)			
	23 A/F	Fwd	0				Mos	13-Mar-2008				
	CI490-1/500644-1	New	0				Hrs	0				
	212556		0				Ldg	0				
		Iridium Satcom Sonalert							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		KHF-1050 High Frequency Communication System							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Lavatory Iridium Satcom Transceiver							RE (O/C)			
	23 A/F	Aft					Mos	09-Feb-2024				
	Not Installed						Hrs	5,253.5				
	Not Installed						Ldg	3,757				
		Lavatory Master Control Switch							RE (O/C)			
	23 A/F		0				Mos	13-Mar-2008				
	SP-45-55	New	0				Hrs	0				
	010800044		0				Ldg	0				
		Magnastar Antenna							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Master Control Switch							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Navigation Strap Board							RE (O/C)			
	23 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Navigation Strap Board							RE (O/C)			
	23 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		No. 1 Comm. Circuit Card Assembly							RE (O/C)			
	23 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		No. 2 Comm. Circuit Card Assembly							RE (O/C)			
	23 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		PA System Amplifer							RE (O/C)			
	23 A/F		0				Mos	13-Mar-2008				
	PA-7501-01-1	New	0				Hrs	0				
	120600356		0				Ldg	0				
		Panel Switch							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Interface Unit							RE (O/C)			
	23 A/F		0				Mos	13-Mar-2008				
	PIU-45-04-1	New	0				Hrs	0				
	120700713		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Phone Magnastar Transceiver							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Power Amplifier/Hf Antenna Coupler							RE (O/C)			
	23 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Power Amplifier/Hf Antenna Coupler							RE (O/C)			
	23 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Radio Altimeter Transmit Antenna							RE (O/C)			
	23 A/F	Aft					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Radio Altimeter Transmit Antenna							RE (O/C)			
	23 A/F	Fwd					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Radio Management (RMU) Unit							RE (O/C)			
	23 A/F	No.1					Mos	30-Aug-2018				
	7013270-985						Hrs	4,334.1				
	02083791						Ldg	2,548				
		Radio Management (RMU) Unit							RE (O/C)			
	23 A/F	No.2					Mos	30-Aug-2018				
	7013270-985						Hrs	4,334.1				
	05024728						Ldg	2,548				
		Satellite Data (SDU) Unit							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Selcal System Change							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Static Inverter							RE (O/C)			
	23 A/F		0				Mos	25-Jun-2009				
	SS120(C)	New	0				Hrs	818.5				
	256		0				Ldg	529				
		Subwoofer Speaker							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Unilink Antenna							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Unilink Processer							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Unit, VHF Datalink Radio, GDR 66							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		VHF Antenna							RE (O/C)			
	23 A/F	Lower	0				Mos	13-Mar-2008				
	DMC60-17-1	New	0				Hrs	0				
	15110		0				Ldg	0				
		VHF Antenna							RE (O/C)			
	23 A/F	Upper	0				Mos	20-Aug-2008				
	DMC60-17-1	New	0				Hrs	377.2				
	15243		0				Ldg	276				
		VHF Communications Transceiver Unit (ATC Transponder)							RE (O/C)			
	23 A/F	No.1					Mos	30-Aug-2018				
	7510733-666						Hrs	4,334.1				
	0607A792						Ldg	2,548				
		VHF Communications Transceiver Unit (ATC Transponder)							RE (O/C)			
	23 A/F	No.2					Mos	30-Aug-2018				
	7510733-666						Hrs	4,334.1				
	0701B150						Ldg	2,548				
		Weather XM Data Port							RE (O/C)			
	23 A/F		0				Mos	09-Aug-2008				
	XMDPRT-01	New	0				Hrs	369.3				
	807000967		0				Ldg	270				
		XM Radio Antenna							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		XM WX Antenna Replace							RE (O/C)			
	23 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
2006-19-04		**Honeywell International, Inc - COM unit and Mode S transponder**							RE (-)		Mandatory (Appliance AD)	
	23 A/F						Mos	31-Mar-2008				
	Eff: 17-Oct-2006 Not Applicable						Hrs	11.6				
	Brand A:9990-2006-19-04						Ldg	11				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2006-19-04 Paragraph (g)	**Honeywell International, Inc - Replacement of Identification Plates for certain Com units.**							RE (-)		Mandatory (Appliance AD)	
23 A/F						Mos	31-Mar-2008				
Eff: 17-Oct-2006 Not Applicable						Hrs	11.6				
						Ldg	11				
2014-17-02	**Communications - ELT Model RESCU 406AF and 406AFN (This AD Replaces AD 2013-18-09)**							RE (-)		Mandatory (Appliance AD)	
23 A/F						Mos	14-Dec-2020				
Eff: 09-Sep-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 1)						Ldg	2,822				
238501	**ATG-5000 (2.7.0 Software Config) Assembly**							RE (O/C)			
23 A/F						Mos	24-Mar-2021				
15864-001	Tested/Inspected					Hrs					
1586418675						Ldg					
238700	**Axcess Cabin Telecomm Router**							RE (O/C)			
23 A/F						Mos	24-Mar-2021				
P12083	Tested/Inspected					Hrs					
1208314711						Ldg					
45-23-1	**Communications - Reassignment of No. 2 Audio Panel Bus**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-1 Rev 1	**Communications - Reassignment of No. 2 Audio Panel Bus**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-1 Rev 2	**Communications - Reassignment of No. 2 Audio Panel Bus**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-1 Rev 3	**Communications - Reassignment of No. 2 Audio Panel Bus**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Eff: 18-Feb-2000 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-10	**Communications - Modification of Dual HF #2 Wiring**							RE (-)		Recommended	
23 A/F						Mos	14-Dec-2020				
Eff: 19-Feb-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-23-11	**Communications - Improvement of the Iridium Phone System**							RE (-)		Recommended	
23 A/F						Mos	14-Dec-2020				
Eff: 04-Sep-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-23-12	**Communications - Replacement of the Cockpit Speakers**							RE (-)		Optional	
23 A/F						Mos					
Eff: 15-Sep-2008						Hrs					
						Ldg					
45-23-13	**Communications - Modification Of The Cockpit Headphone Jack Wiring**							RE (-)		Optional	
23 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-23-13 Rev 1	**Communications - Modification Of The Cockpit Headphone Jack Wiring**							T (A/R)		Optional	
23 A/F						Mos					
Eff: 11-Mar-2013						Hrs					
						Ldg					
45-23-14	**Communications - GMA 36 Audio Processing Unit Mod 3 Upgrade**							RE (-)		Recommended	
23 A/F						Mos	18-Sep-2015				
Eff: 20-Jul-2015 Not Applicable						Hrs	3,601.1				
						Ldg	2,092				
						Hrs (APU)	1,175.5				
45-23-14 Rev 1	**Communications - GMA 36 Audio Processing Unit Mod 3 Upgrade**							RE (-)		Recommended	
23 A/F						Mos					
Eff: 28-Sep-2015						Hrs					
						Ldg					
45-23-14 Rev 2	**Communications - GMA 36 Audio Processing Unit Mod 3 Upgrade**							RE (-)		Recommended	
23 A/F						Mos	14-Dec-2020				
Eff: 07-Dec-2015 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-23-18	**Communications - Replacement of Obsolete Cockpit Voice Recorder**							T (-)		Optional	
23 A/F						Mos					
Eff: 05-Aug-2019						Hrs					
(AVG MAN HRS: 1.5) (NOTE: CONTROLLED EFFECTIVITY)						Ldg					
45-23-18 Rev 1	**Communications - Replacement of Obsolete Cockpit Voice Recorder**							T (A/R)		Optional	
23 A/F						Mos					
Eff: 01-Aug-2022						Hrs					
(AVG MAN HRS: 1.5) (NOTE: CONTROLLED EFFECTIVITY)						Ldg					
45-23-19	**Communications - GOGO Avance L5**							T (-)		Optional	
23 A/F						Mos					
Eff: 14-Oct-2019						Hrs					
(AVG MAN HRS: 347)						Ldg					
45-23-19 Rev 1	**Communications - GOGO Avance L5 (Superseded by SB 45-23-20)**							RE (-)		Optional	
23 A/F						Mos					
Eff: 04-Dec-2019						Hrs					
(NOTE: NOTE: Service Bulletin 45-23-19 has been canceled. Optional Service Bulletin 45-23-20, "Gogo Avance L5" supersedes all versions of this service bulletin.)						Ldg					
45-23-20	**Communications - Gogo Avance L5 (Supersedes SB 45-23-19 Rev 1)**							T (-)		Optional	
23 A/F						Mos					
Eff: 04-Dec-2019						Hrs					
(AVG MAN HRS: 347)						Ldg					
45-23-20 Rev 1	**Communications - Gogo Avance L5**							T (-)		Optional	
23 A/F						Mos					
Eff: 10-May-2021						Hrs					
(AVG MAN HRS: 347)						Ldg					
45-23-20 Rev 2	**Communications - Gogo Avance L5**							T (-)		Optional	
23 A/F						Mos					
Eff: 20-Dec-2021						Hrs					
(AVG MAN HRS: 347)						Ldg					
45-23-20 Rev 3	**Communications - Gogo Avance L5**							T (A/R)		Optional	
23 A/F						Mos					
Eff: 21-Feb-2022						Hrs					
(AVG MAN HRS: 347)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-23-27	**Inspection/Replacement Of Brake Hose Assemblies. Effective 45-306 Thru 45-326.**							RE (A/R)		Recommended	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-3	**Communications - Honeywell 8.33 KHz Radio Upgrade**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-3 Rev 1	**Communications - Honeywell 8.33 KHz Radio Upgrade**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Eff: 18-Feb-2000 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-4	**Communications - Modification of HF/SELCAL Installation**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-4 Rev 1	**Communications - Modification of HF/SELCAL Installation**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-4 Rev 2	**Communications - Modification of HF/SELCAL Installation**							RE (-)		Optional	
23 A/F						Mos	29-Aug-2019				
Eff: 14-Sep-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-23-5	**Communications - Installation of HF1 Communications at the Observer Station**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Eff: 15-Jun-2000 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-5 Rev 1	**Communications - Installation of HF1 Communications at the Observer Station**							RE (-)		Optional	
23 A/F						Mos	29-Aug-2019				
Eff: 12-Nov-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-23-6	**Communications - Increased FOD Protection-Installation of Antenna Protection**							RE (-)		Optional	
23 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-23-6 Rev 1	**Communications - Increased FOD Protection-Installation of Antenna Protection**							RE (-)		Optional	
23 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-23-6 Rev 2	**Communications - Increased FOD Protection-Installation of Antenna Protection**							RE (-)		Optional	
23 A/F						Mos	13-Mar-2008				
Not Applicable	RETROACTIVE ACTION HAS BEEN COMPLIED WITH, OR IS NOT REQUIRED					Hrs					
						Ldg					
45-23-6 Rev 3	**Communications - Increased FOD Protection-Installation of Antenna Protection**							RE (-)		Optional	
23 A/F						Mos	10-Jan-2020				
Eff: 24-Jun-2013 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-23-7	**Communications - Wire Upgrade for Dual HF System**							RE (-)		Recommended	
23 A/F						Mos	14-Dec-2020				
Eff: 10-Feb-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-23-8	**Communications - Cockpit Voice Recorder Area Microphone Wiring Correction**							RE (-)		Recommended	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-8 Rev 1	**Communications - Cockpit Voice Recorder Area Microphone Wiring Correction**							RE (-)		Recommended	
23 A/F						Mos	14-Dec-2020				
Eff: 28-Aug-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-23-9	**Communications - Wire Modification of the Video System Monitors**							RE (-)		Recommended	
23 A/F						Mos	08-Jun-2009				
Not Applicable	PER A/C S/N					Hrs	801				
						Ldg	521				
45-23-9 Rev 1	**Communications - Wire Modification of the Video System Monitors**							RE (-)		Recommended	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-9 Rev 2	**Communications - Wire Modification of the Video System Monitors**							RE (-)		Recommended	
23 A/F						Mos	14-Dec-2020				
Eff: 18-Aug-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
75-23-09	**Communications - Gogo AVANCE L5**							RE (-)		Optional	
23 A/F						Mos					
Eff: 14-Oct-2019						Hrs					
(AVG MAN HRS: 323)						Ldg					
75-23-09 Rev 1	**Communications - GOGO Avance L5 (Superseded by SB 75-23-13)**							RE (-)		Optional	
23 A/F						Mos					
Eff: 04-Dec-2019						Hrs					
(NOTE: NOTE: Service Bulletin 75-23-09 has been canceled. Optional Service Bulletin 75-23-13, "Gogo Avance L5" supersedes all versions of this service bulletin.)						Ldg					
75-23-10	**Communications - Garmin Avionics Upgrade Phase III - Fans 1/A+**							RE (-)		Optional	
23 A/F						Mos					
Eff: 30-Mar-2020						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-23-11	**Communications - Garmin Avionics Upgrade Phase III - ACARS**							RE (-)		Optional	
23 A/F						Mos					
Eff: 30-Mar-2020						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-23-12	**Communications - Garmin Avionics Upgrade Phase III - Flight Stream 510**							RE (-)		Optional	
23 A/F						Mos					
Eff: 30-Mar-2020						Hrs					
(AVG MAN HRS: 1.25)						Ldg					
75-23-13	**Communications - Gogo Avance L5 (Supersedes SB 75-23-09 Rev 1)**							RE (-)		Optional	
23 A/F						Mos					
Eff: 04-Dec-2019						Hrs					
(AVG MAN HRS: 323)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
75-23-13 Rev 1	**Communications - Gogo Avance L5**							RE (-)		Optional	
23 A/F						Mos					
Eff: 10-May-2021						Hrs					
(AVG MAN HRS: 323)						Ldg					
75-23-13 Rev 2	**Communications - Gogo Avance L5**							RE (-)		Optional	
23 A/F						Mos					
Eff: 20-Dec-2021						Hrs					
(AVG MAN HRS: 323)						Ldg					
75-23-13 Rev 3	**Communications - Gogo Avance L5**							RE (-)		Optional	
23 A/F						Mos					
Eff: 21-Feb-2022						Hrs					
(AVG MAN HRS: 323)						Ldg					
75-23-14	**Communications - SXM Receiver Installation**							RE (-)		Optional	
23 A/F						Mos					
Eff: 18-May-2022						Hrs					
						Ldg					
A2300000	**** Communications Systems - Perform Operational Check.**							RE	TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
23 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:23-00-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 23-00-00.))						Ldg	3,757				
A2300000-4A	**** Engine Indicating and Crew Alerting System (EICAS) - Perform Radio Management Units (RMU) Backup Engine Page Check.**							RE (N/A)	TLMC 04-10-00, Ch.5 Interval		
23 A/F						Mos					
						Hrs					
(ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg					
A2300000-4B	**** Engine Indicating and Crew Alerting System (EICAS) - Perform Radio Management Units (RMU) Power Supply Check.**							RE (N/A)	TLMC 04-10-00, Ch.5 Interval		
23 A/F						Mos					
						Hrs					
(ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg					
FAR 91.413	**ATC Transponder test and inspections per FAR 91.413 Appendix F of Part 43**							RE		FAR91, FAR 91	
23 A/F	No.1					Mos	09-Feb-2024	24	-/+14d	09-Feb-2026	1.7 Years (+14 Days)
7510733-666						Hrs	5,253.5				
0607A792						Ldg	3,757				
Certified Date 09-Feb-2024											
FAR 91.413	**ATC Transponder test and inspections per FAR 91.413 Appendix F of Part 43**							RE		FAR91, FAR 91	
23 A/F	No.2					Mos	09-Feb-2024	24	-/+14d	09-Feb-2026	1.7 Years (+14 Days)
7510733-666						Hrs	5,253.5				
0701B150						Ldg	3,757				
Certified Date 09-Feb-2024											
SIL 23-001	**8.33 Khz VHF Communication Channel Spacing**							RE (-)		Informational	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
SIL 23-002	**Flight Data Recorder (FDR Waiver Extension)**							RE (-)		Informational	
23 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
ST04030CH	**Installation of Aircell ATG-X000 High Speed Internet (AHSI) and Cabin Telecommunications Router (CTR) System**							RE (-)		STC	
23 A/F						Mos	25-Jan-2017				
Complied With						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
V2312003	**HF Antenna - Perform Visual Inspection. Check for proper tension of HF Antenna wire.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
23 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00, 23-12-04 (ZONE: 300) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00 and 23-12-04.))					Ldg	3,757				
Y2360020	**Aircraft Static Dischargers - Perform Functional Test.**							RE		TLMC 05-14-02	**≈12-Oct-2025**
23 A/F	05-14-02					Mos	31-Aug-2022	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	5,069	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:23-60-00 (ZONE: 320) (UPDATE NOTE: Aircraft Static Dischargers - Perform Functional Test C/W. NFF) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 23-60-00.))					Ldg	3,115				
Y2360023	**Aircraft Static Dischargers - Perform Functional Test.**							RE		TLMC 05-14-04	**≈12-Oct-2025**
23 A/F	05-14-04					Mos	31-Aug-2022	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	5,069	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Ref:23-60-00 (ZONE: 550/650) (UPDATE NOTE: Aircraft Static Dischargers - Perform Functional Test. C/W. NFF) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 23-60-00.))					Ldg	3,115				
▼ 24 - ELECTRICAL POWER											
	RH Battery Contactor							RE (O/C)			
24 A/F						Mos	25-Jul-2022				
420CC02	Tested/Inspected					Hrs	5,042				
2501						Ldg	3,101				
	#1 PCB 2							RE (O/C)			
24 A/F	Aft					Mos	25-Jul-2022				
785CE01Y04	Tested/Inspected					Hrs	5,042				
1934						Ldg	3,101				
	#2 PCB 2							RE (O/C)			
24 A/F	Aft					Mos	25-Jul-2022				
785CE01Y04	Tested/Inspected					Hrs	5,042				
1304						Ldg	3,101				
	AC 1200 Amp Inverter							RE (O/C)			
24 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	AC 5 KVA Alternator							RE (O/C)			
24 A/F	No.1					Mos	26-Sep-2022				
90278-2	Overhauled					Hrs	5,094.2				
455						Ldg	3,136				
	(UPDATE NOTE: No.1 ** Engine Alternator replaced with O/H assy. Ref Fliteline WO 2022-712 for details.)										
	AC 5 KVA Alternator							RE (O/C)			
24 A/F	No.2		1			Mos	16-Dec-2021				
90278-2	Overhauled		0			Hrs	4,831.3				
170			0			Ldg	2,975				
	(UPDATE NOTE: Alternator replaced with overhauled unit to c/w with scheduled bearing replacement.)										
	Ac Inverter							RE (O/C)			
24 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Ac Inverter							RE (O/C)			
24 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		AC/DC Volt Indicator							RE (O/C)			
24 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Aft Circuit Breaker Panel Assy							RE (O/C)			
24 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Apu Generator Control Unit Printed Circuit Board							RE (O/C)			
24 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		APU Starter/Generator							RE (O/C)			
24 A/F	6608458-010			2			Mos	23-Dec-2017				
	P1204						Hrs	4,076				
	(ZONE: 310JL, 310RR)						Ldg	2,402				
		Battery Temperature Switch							RE (O/C)			
24 A/F	Unknown	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Battery Temperature Switch							RE (O/C)			
24 A/F	Unknown	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Breaker, Optional Circuit							RE (O/C)			
24 A/F	Unknown	Aft					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Emergency (IRN AB2431063 for RG-443) Battery							RE			
24 A/F	RG-443		0				Mos	03-Mar-2022	60	-/+14d	03-Mar-2027	2.8 Years (+14 Days)
	41191156	New	0				Hrs	4,883	5,000	-/+25	9,883	4,608.2 Hrs (+25)
	(APX COST: 3,468.23)		0				Ldg	3,012				
		Generator Control Unit (GCU)							RE (O/C)			
24 A/F	Unknown	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Generator Control Unit (GCU)							RE (O/C)			
24 A/F	Unknown	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Generator Control Unit Printed Circuit Board							RE (O/C)			
24 A/F	790CE01Y04	Left					Mos	31-Aug-2022				
	1469						Hrs	5,069				
							Ldg	3,115				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Generator Control Unit Printed Circuit Board							RE (O/C)			
	24 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Logic Printed Circuit Board							RE (O/C)			
	24 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Logic Printed Circuit Board							RE (O/C)			
	24 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Battery							RE (O/C)			
	24 A/F	No.1					Mos	02-Dec-2022				
	RG-380E/40L	Tested/Inspected	527				Hrs	5,136.6				
	41084644		346				Ldg	3,167				
		Main Battery							RE (O/C)			
	24 A/F	No.2					Mos	02-Dec-2022				
	RG-380E/40L	Tested/Inspected	527				Hrs	5,136.6				
	41098350		346				Ldg	3,167				
		Power Distribution Panel							RE (O/C)			
	24 A/F	Aft - Left	0				Mos	13-Mar-2008				
	660GC02Y07	New	0				Hrs	0				
	599		0				Ldg	0				
		Power Distribution Panel							RE (O/C)			
	24 A/F	Aft - Right	0				Mos	13-Mar-2008				
	660GC02Y07	New	0				Hrs	0				
	628		0				Ldg	0				
		Power Distribution Panel							RE (O/C)			
	24 A/F	Fwd - Left					Mos	30-Jan-2014				
	650GC02Y03						Hrs	3,059.7				
	585						Ldg	1,794				
		Power Distribution Panel							RE (O/C)			
	24 A/F	Fwd - Right	0				Mos	13-Mar-2008				
	650GC02Y03	New	0				Hrs	0				
	461		0				Ldg	0				
		Remote Control Circuit Breaker							RE (O/C)			
	24 A/F		0				Mos	13-Mar-2008				
	SM600BA75N1/N936-9076	New	0				Hrs	0				
	94130		0				Ldg	0				
		Remote Control Circuit Breaker							RE (O/C)			
	24 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Remote Control Circuit Breaker							RE (O/C)			
24 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	RH PCB 1 (GCU)							RE (O/C)			
24 A/F						Mos	31-Aug-2022				
790CE01Y04						Hrs	5,069				
2943						Ldg	3,115				
(AVG MAN HRS: 0.5) (APX COST: 0) (UPDATE NOTE: PCBs swapped for Gen Load T/shooting.)											
	Starter/Generator							RE (O/C)			
24 A/F	No.1					Mos	15-Aug-2022				
23280-067	Overhauled		0			Hrs	5,052.3				
P1477/CA			0			Ldg	3,107				
(ZONE: 410) (UPDATE NOTE: STARTER S/N Y0507 REMOVED OFF A/C.. DEFECTIVE AND REPLACED WITH O/H ASSY P1477/CA)											
	Starter/Generator							RE (O/C)			
24 A/F	No.2					Mos	26-Sep-2022				
23280-067	Overhauled		0			Hrs	5,094.2				
Y0835			0			Ldg	3,136				
(ZONE: 410) (UPDATE NOTE: P/N: 23280-067 s/n: Y0835)											
2011-04-08	**Electrical power**							RE (-)		Mandatory	
24 A/F						Mos	11-Mar-2011				
Eff: 31-Mar-2011 Complied With	IAW THE SB					Hrs	1,857.4				
						Ldg	1,121				
2019-15-10 PARA (G)	**Safran Aerosystems Life Jackets with P/N 210225-2, P/N 216200-0, or P/N 216203-0 - Inspect/ Replace/ Repair**							RE (-)			
24 A/F						Mos	11-Sep-2019				
Not Applicable	BY EFFECTIVITY: NOT EFFECTIVE BY PART NUMBERS INSTALLED (P/N 63600-171,D21343-153 IS INSTALLED)					Hrs	4,339				
						Ldg	2,550				
24-30-67	**CONCORDE Lead Acid Battery Assembly Replacement (In Service)**							RE (N/A)		Life Limit, Vendor	
24 A/F	No.1					Mos					
RG-380E/40L						Hrs					
41084644						Ldg					
CMM:CBC-SB-09302014-1											
24-30-67	**CONCORDE Lead Acid Battery Assembly Replacement (In Service).**							RE (N/A)		Life Limit, Vendor	
24 A/F	No.2					Mos					
RG-380E/40L						Hrs					
41098350						Ldg					
CMM:CBC-SB-09302014-1											
45-24-1	**Electrical Power - Copilot's Circuit Breaker Bus Bar Installation**							RE (-)		Recommended	
24 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-24-1 Rev 1	**Electrical Power - Copilot's Circuit Breaker Bus Bar Installation**							RE (-)		Recommended	
24 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-24-1 Rev 2	**Electrical Power - Copilot's Circuit Breaker Bus Bar Installation**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 12-Apr-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-24-10	**Electrical Power - Replacement of the Emergency Battery Grounding Bracket**							RE (-)		Recommended	
24 A/F						Mos					
Eff: 29-Sep-2008						Hrs					
(AVG MAN HRS: 5)						Ldg					
45-24-10 Rev 1	**Electrical Power - Replacement of the Emergency Battery Grounding Bracket**							RE (-)		Recommended	
24 A/F						Mos					
Eff: 17-Nov-2008						Hrs					
(AVG MAN HRS: 5)						Ldg					
45-24-10 Rev 2	**Electrical Power - Replacement of the Emergency Battery Grounding Bracket**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 07-Jul-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 5)						Ldg	2,822				
45-24-11	**Electrical Power - Replacement of the Hawker Energy or Enersys Ltd. Emergency Battery**							RE (-)		Optional	
24 A/F						Mos	13-Mar-2008				
Eff: 21-Apr-2008 Complied With	INCORPORATED BY ST01173 WI					Hrs					
						Ldg					
45-24-12	**Electrical Power - DC Starter/Generator Upgrade to Ceramic Ball Bearings**							RE (-)		Optional	
24 A/F						Mos	14-Feb-2011				
Complied With						Hrs	1,801.5				
						Ldg	1,088				
45-24-12 Rev 1	**Electrical Power - DC Starter/Generator Upgrade to Ceramic Ball Bearings**							RE (-)		Optional	
24 A/F						Mos	10-Jan-2020				
Eff: 05-Mar-2008 Complied With	PREVIOUSLY COMPLIED WITH BY REMOVAL OF L/H AND R/H STARTER/GENERATOR P/N:6608458-005 AND INSTALLATION OF L/H AND R/H STARTER/GENERATOR P/N:6608458-012, SEE LOG ENTRY DATED FEBRUARY 12,2010 AT 1203.8 ACT. CURRENTLY INSTALLED L/H STARTER/GENERATOR P/N:6608458-012, S/N:991176. R/H STARTER/GENERATOR P/N:6608458-012, S/N:Y0507 - NO FURTHER ACTION REQUIRED					Hrs	4,590.8				
						Ldg	2,807				
45-24-13	**Electrical Power - Modification of the Tailcone Electrical Connectors**							RE (-)		Recommended	
24 A/F						Mos	28-Jan-2010				
Eff: 04-May-2009 Complied With						Hrs	1,172.9				
						Ldg	723				
45-24-14	**Electrical Power - Inspection/Modification of the Optional Aft Circuit Breaker Panel Wire Harness Routing**							RE (-)		Recommended	
24 A/F						Mos	28-Jan-2010				
Eff: 08-Sep-2009 Complied With						Hrs	1,172.9				
(AVG MAN HRS: 8)						Ldg	723				
45-24-14 Rev 1	**Electrical Power - Inspection/Modification of the Optional Aft Circuit Breaker Panel Wire Harness Routing**							RE (-)		Recommended	
24 A/F						Mos	10-Aug-2010				
Eff: 28-Jun-2010 Complied With	PREVIOUSLY					Hrs					
(AVG MAN HRS: 8)						Ldg					
45-24-15	**Electrical Power - Replacement of the Pitch TrimActuator Circuit Breaker**							RE (-)		Recommended	
24 A/F						Mos	30-Jul-2010				
Eff: 15-Mar-2010 Complied With						Hrs	1,499.8				
(AVG MAN HRS: 2.5)						Ldg	910				
45-24-15 Rev 1	**Electrical Power - Replacement of the Pitch TrimActuator Circuit Breaker**							RE (-)		Recommended	
24 A/F						Mos					
Eff: 08-Oct-2012						Hrs					
(AVG MAN HRS: 2.5)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-24-15 Rev 2	**Electrical Power - Replacement of the Pitch TrimActuator Circuit Breaker**							RE (-)		Recommended	
24 A/F						Mos	12-Mar-2013				
Eff: 11-Feb-2013 Complied With	REPLACEMENT OF THE PITCH TRIM ACTUATOR CIRCUIT BREAKER					Hrs	2,764.1				
(AVG MAN HRS: 2.5)						Ldg	1,630				
45-24-17	**Electrical Power - Replacement of 38/40 AHR Nicad Main Batteries with 38 AHR Lead Acid Main Batteries**							RE (-)		Optional	
24 A/F						Mos					
						Hrs					
						Ldg					
45-24-17 Rev 1	**Electrical Power - Replacement of 38/40 AHR Nicad Main Batteries with 38 AHR Lead Acid Main Batteries**							T (-)		Optional	
24 A/F						Mos					
Eff: 20-Aug-2012						Hrs					
						Ldg					
45-24-17 Rev 2	**Electrical Power - Replacement of 38/40 AHR NiCad Main Batteries with 38 AHR Lead Acid Main Batteries**							RE (-)		Optional	
24 A/F						Mos	21-May-2019				
Eff: 27-Feb-2017 Complied With						Hrs	4,461.2				
(AVG MAN HRS: 32)						Ldg	2,673				
45-24-18	**Electrical Power - Modification Of The Electronic Flight Instrument System (Efis) Ground Plugs**							RE (-)		Optional	
24 A/F						Mos	11-Feb-2011				
Complied With						Hrs	1,801.5				
						Ldg	1,088				
45-24-18 Rev 1	**Electrical Power - Modification Of The Electronic Flight Instrument System (Efis) Ground Plugs**							RE (-)		Optional	
24 A/F						Mos	10-Jan-2020				
Eff: 04-Mar-2013 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				
45-24-19	**Electrical Power - Installation of Additional Wiring Bundle Protection in Tailcone**							RE (-)		Recommended	
24 A/F						Mos	22-Apr-2011				
Eff: 21-Mar-2011 Complied With						Hrs	1,922.2				
(AVG MAN HRS: 2)						Ldg	1,155				
45-24-2	**Electrical Power - Inspect/Replace Flap Position Indication Circuit Breaker (CB88)**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 08-Dec-2000 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-24-21	**Electrical Power - Replacement of Quick Attach and Detach (QAD) Mounting Adapter Seal**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 04-Mar-2013 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 3)						Ldg	2,822				
45-24-22	**Electrical Power - AC Outlet Assembly Molex Connector Obsolescence**							T (A/R)		Optional	
24 A/F						Mos					
Eff: 25-Mar-2019						Hrs					
(AVG MAN HRS: 3)						Ldg					
45-24-3	**Electrical Power - Increase Fuse Amperage for Angle of Attack (AOA) Indicator Lighting**							RE (-)		Recommended	
24 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-24-3 Rev 1	**Electrical Power - Increase Fuse Amperage for Angle of Attack (AOA) Indicator Lighting**							RE (-)		Recommended	
24 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-24-3 Rev 2	**Electrical Power - Increase Fuse Amperage for Angle of Attack (AOA) Indicator Lighting**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 06-Sep-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-24-4	**Electrical Power - Replacement of the Flight Guidance Controller Back Lighting Fuses**							RE (-)		Recommended	
24 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-24-4 Rev 1	**Electrical Power - Replacement of the Flight Guidance Controller Back Lighting Fuses**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 22-Apr-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-24-5	**Electrical Power - Installation of a 115vac Cabin Inverter Outlet Current Limiter**							RE (-)		Recommended	
24 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-24-5 Rev 1	**Electrical Power - Installation of a 115vac Cabin Inverter Outlet Current Limiter**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 01-May-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-24-6	**Electrical Power - Replacement of Firewall Hydraulic Shutoff Valve Fuses**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 22-Apr-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-24-7	**Electrical Power - Inspection of Wire Harnesses in Tailcone Area for Proper Clearance with Flight Control Cables**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 24-Aug-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-24-8	**Electrical Power - Installation of Wire Harness Support Channels**							RE (-)		Recommended	
24 A/F						Mos	08-Jun-2009				
Not Applicable	PER A/C S/N					Hrs	801				
						Ldg	521				
45-24-8 Rev 1	**Electrical Power - Installation of Wire Harness Support Channels**							RE (-)		Recommended	
24 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-24-8 Rev 2	**Electrical Power - Installation of Wire Harness Support Channels**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 23-Jun-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-24-9	**Electrical Power - Installation of Concorde 38 AHR Batteries**							RE (-)		Recommended	
24 A/F						Mos	08-Jun-2009				
Eff: 29-Apr-2008 Not Applicable	PER A/C S/N					Hrs	801				
(AVG MAN HRS: 9.5)						Ldg	521				
45-24-9 Rev 1	**Electrical Power - Installation of Concorde 38 AHR Batteries**							RE (-)		Recommended	
24 A/F						Mos					
Eff: 16-Nov-2009						Hrs					
(AVG MAN HRS: 9.5)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-24-9 Rev 2	**Electrical Power - Installation of Concorde 38 AHR Batteries**							RE (-)		Recommended	
24 A/F						Mos	25-Apr-2012				
Eff: 05-Mar-2012 Not Applicable	PER AIRCRAFT SERIAL NUMBER AND THIS KIND OF BATTERY IS NOT INSTALLED ON THIS AIRCRAFT					Hrs	2,428.9				
(AVG MAN HRS: 9.5)						Ldg	1,449				
45-24-9 Rev 3	**Electrical Power - Installation of Concorde 38 AHR Batteries**							RE (-)		Recommended	
24 A/F						Mos	14-Dec-2020				
Eff: 11-Aug-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 9.5)						Ldg	2,822				
A45-24-16	**Electrical Power - Inspection of the Circuit Breaker Panel Wiring**							RE (-)		Alert	
24 A/F						Mos	13-Mar-2018				
Eff: 16-Nov-2009 Complied With						Hrs					
(AVG MAN HRS: 15)						Ldg					
AB2431062	**Emergency Battery (P/N RG-443), (if installed) - Perform Capacity Check.**							RE		TLMC 05-19-01	**≈22-Feb-2025**
24 A/F						Mos	09-Feb-2024	12	-/+1m	10-Mar-2025	9.7 Months (+31 Days)
RG-443											
41191156						Hrs	5,253.5	1,000	-/+100	6,253.5	978.7 Hrs (+100)
Inspected Date 09-Feb-2024						Ldg	3,757				
(ZONE: 120AR, 130AL) (Tol. Adjustment: 29d) (SOURCE: MM-104, MM-105)											
AB2431063	**Emergency Battery**							RE (O/C)		Life Limit, TLMC 05-19-01	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
Alias1:(Std)AB2431063, (EMP) 2431067 (ZONE: 120AR, 130AL) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
AC2460002	**Remove attaching parts securing circuit breaker panel to structure. Check for loose circuit breaker terminals, loose wire terminals, corroded terminals or bus bars, and evidence of wire insulation damage.**							RE		TLMC 05-14-01	**≈12-Oct-2025**
24 A/F	05-14-01					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
Ref:05-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg	2,822				
AW 24-011	**Ground Plug Assemblies**							RE (-)		Advisory Wire	
24 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 24-013	**Starter/Generator Bearing Replacement**							RE (-)		Advisory Wire	
24 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 24-014	**Possible Condition Of Emi Build Up and Discharge Resulting In Temporary Loss Of Electrical Power**							RE (-)		Advisory Wire	
24 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 24-015	**28 AMP Hour Concorde Batteries**							RE (-)		Advisory Wire	
24 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
B2450002	**** Electrical System Control - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-13-01, Ch.5 Interval		**≈24-Apr-2025**
24 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:24-00-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 24-00-00.))						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F2420000	**** Alternator - Perform Bearing Replacement.**							RE	TLMC 04-11-00, TLMC 05-19-01		**≈09-Mar-2025**
24 A/F	No.1					Mos	26-Sep-2022				
90278-2						Hrs	5,094.2	1,200	-/+25	6,303.2	1,028.4 Hrs (+25)
455						Ldg	3,136				
	(ZONE: 410) (Tol. Adjustment: 9 Hrs) (UPDATE NOTE: No.1 ** Engine Alternator replaced with O/H assy iaw Lr 45 AMM. Ops checked serviceable. Ref Fliteline WO 2022-712 for details.) (SOURCE: MM-104, MM-105)										
F2420000	**** Alternator - Perform Bearing Replacement.**							RE	TLMC 04-11-00, TLMC 05-19-01		**≈14-Dec-2024**
24 A/F	No.2					Mos	16-Dec-2021				
90278-2						Hrs	4,831.3	1,200	-/+25	6,021.8	747 Hrs (+25)
264						Ldg					
	(ZONE: 410) (Tol. Adjustment: -9.5 Hrs) (UPDATE NOTE: LOWER COWL REMOVED TO VERIFY S/N.) (SOURCE: MM-104, MM-105)										
H2450001	**** Auxiliary Power Supplies - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
24 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:24-00-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 24-00-00.))					Ldg	3,757				
H2450023	**** EMER BATT LOW and GEN AMPS HIGH Indication - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
24 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:24-00-00 (ZONE: 200) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 24-00-00.))					Ldg	3,757				
O1222000	**Main Battery (Ni-Cad) - Check or perform the following in accordance with battery manufacturer's service manual:** **a. Liquid level check.** **b. Perform complete discharge-recharge procedure.** **c. Functional test of battery 140 °F and 160 °F thermostats and thermistor.**							RE (N/A)		TLMC 05-19-00	
24 A/F	No.1					Mos					
RG-380E/40L						Hrs					
41084644						Ldg					
	(ZONE: 320/ 840AR) (SOURCE: MM-104, MM-105) (NOTE: Note: Interval is the normal allowable period between maintenance activities if no service interval is specifically recommended by the battery manufacturer. Because of varied flight profiles, certain servicing and maintenance activities may require a more frequent interval or may allow an extended interval, depending on environmental and operational requirements, and should be adjusted by individual operators. Operators should refer to their battery manufacturer's service manual for detailed maintenance instructions.)										
O1222000	**Main Battery (Ni-Cad) - Check or perform the following in accordance with battery manufacturer's service manual:** **a. Liquid level check.** **b. Perform complete discharge-recharge procedure.** **c. Functional test of battery 140 °F and 160 °F thermostats and thermistor.**							RE (N/A)		TLMC 05-19-00	
24 A/F	No.2					Mos					
RG-380E/40L						Hrs					
41098350						Ldg					
	(ZONE: 320/ 840AR) (SOURCE: MM-104, MM-105) (NOTE: Note: Interval is the normal allowable period between maintenance activities if no service interval is specifically recommended by the battery manufacturer. Because of varied flight profiles, certain servicing and maintenance activities may require a more frequent interval or may allow an extended interval, depending on environmental and operational requirements, and should be adjusted by individual operators. Operators should refer to their battery manufacturer's service manual for detailed maintenance instructions.)										
O2431002	**Emergency Battery (P/N 7624308001) - Perform Capacity Check.**							RE (N/A)		TLMC 05-19-00	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
	(ZONE: 120AR, 130AL) (SOURCE: MM-104, MM-105)										
P2430003	**Starter/Generator - Perform Overhaul.**							RE		TLMC 05-19-00	**≈22-Feb-2025**
24 A/F	No.1					Mos	15-Aug-2022				
23280-067						Hrs	5,052.3	1,200	-/+25	6,252.3	977.5 Hrs (+25)
P1477/CA						Ldg	3,107				
	(ZONE: 410) (UPDATE NOTE: O/H starter gen installed in No. 1 engine position. P1477/CA TSO: 0) (SOURCE: MM-104, MM-105)										

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P2430003	**Starter/Generator - Perform Overhaul.**							RE		TLMC 05-19-00	**≈06-Mar-2025**
24 A/F	No.2					Mos	26-Sep-2022				
23280-067						Hrs	5,094.2	1,200	-/+25	6,291.2	1,016.4 Hrs (+25)
Y0835						Ldg	3,136				
	(ZONE: 410) (Tol. Adjustment: -3 Hrs) (UPDATE NOTE: No.2 Starter/Generator replaced with O/H assy. Ops checked serviceable. P/N: 23280-067 s/n: Y0835. Ref Fliteline WO 2022-712 for details.) (SOURCE: MM-104, MM-105)										
P2430007	**Starter/Generator - Replace Bearings.**							RE (N/A)		TLMC 05-19-01	
24 A/F	No.1					Mos					
23280-067						Hrs					
P1477/CA						Ldg					
	(ZONE: 410) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-005 thru 45-366 not modified per SB 45-24-12 and 45-71-06.))										
P2430007	**Starter/Generator - Replace Bearings.**							RE (N/A)		TLMC 05-19-01	
24 A/F	No.2					Mos	26-Sep-2022				
23280-067						Hrs	5,094.2				
Y0835						Ldg	3,136				
	(ZONE: 410) (UPDATE NOTE: No.2 Starter/Generator replaced with O/H assy.) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-005 thru 45-366 not modified per SB 45-24-12 and 45-71-06.))										
Q2460001	**** Power Distribution System - Perform Squat Switch Check.**							RE	TLMC 04-10-00,	TLMC 05-13-05, Ch.5 Interval	**≈24-Apr-2025**
24 A/F	05-13-05					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:24-60-00 (ZONE: 720/730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 24-60-00.))					Ldg	3,757				
R2431003	**** Battery Warning System - Perform Functional Test.**							RE	TLMC 04-10-00,	TLMC 05-14-01, Ch.5 Interval	**≈12-Oct-2025**
24 A/F	05-14-01					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:24-31-00 (ZONE: 220) (Tol. Adjustment: -294d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 24-31-00.) (Effective on Aircraft with Ni-Cad batteries installed.))					Ldg	2,822				
T1222004/07	**Main Battery (Lead-Acid) - Perform battery capacity check.**							RE		TLMC 05-19-00	
24 A/F	No.1					Mos	09-Feb-2024	6	-/+1m	28-May-2024	4 Days (+31)
RG-380E/40L						Hrs	5,253.5	500	-/+100	5,753.5	478.7 Hrs (+100)
41084644						Ldg	3,757				
	(ZONE: 320/ 840AR) (Tol. Adjustment: -71d) (SOURCE: MM-104, MM-105)										
T1222004/07	**Main Battery (Lead-Acid) - Perform battery capacity check.**							RE		TLMC 05-19-00	
24 A/F	No.2					Mos	09-Feb-2024	6	-/+1m	28-May-2024	4 Days (+31)
RG-380E/40L						Hrs	5,253.5	500	-/+100	5,753.5	478.7 Hrs (+100)
41098350						Ldg	3,757				
	(ZONE: 320/ 840AR) (Tol. Adjustment: -71d) (SOURCE: MM-104, MM-105)										
W2450000	**** Generator Fail Indication - Perform Operational Check.**							RE	TLMC 04-10-00,	TLMC 05-12-01, Ch.5 Interval	**≈24-Oct-2024**
24 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:24-00-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 24-00-00.))					Ldg	3,757				
Y2400001	**Switch and Circuit Breaker Panels - Perform visual inspection.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
24 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2400002	**Electrical Wiring - Perform visual inspection for routing, security, clearances, chafing, and electrical components for security and general condition.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
24 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00, Ref:WM20-10-11 (ZONE: 120AR, 130AL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) Note: Refer to 20-10-01 of the Wiring Manual for wire routing clearance information.)					Ldg	3,757				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y2400025		**Electrical Wiring - Perform visual inspection for routing, security, clearances, chafing, and electrical components for security and general condition.**							RE		TLMC 05-12-02	**≈24-Oct-2024**
24 A/F		05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
							Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
		Alias1:5-10-00, Ref:WM20-10-11 (ZONE: 320CL, 320DL, 320ER) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.)					Ldg	3,757				
		Note: Refer to section 20-10-11 of the Wiring Manual for wire routing clearance information.)										
Y2430005		**Starter/Generator - Perform Grounding Lug Bonding Check.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
24 A/F		05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
							Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
		Alias1:24-30-01 (ZONE: 410) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 24-30-01.))					Ldg	3,757				
Y2430006		**Starter/Generator - Perform visual inspection of Grounding Lugs.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
24 A/F		05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
							Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
		Alias1:5-10-00 (ZONE: 410) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2431000		**Battery, Generator, and Bus-Tie Cables - Perform Visual Inspection.**							RE		TLMC 05-14-02	**≈12-Oct-2025**
24 A/F		05-14-02					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
		Alias1:5-10-00 (ZONE: 840AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
Y2431001		**Emergency Battery Cables - Perform visual inspection.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
24 A/F		05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
							Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
		Alias1:5-10-00 (ZONE: 120AR, 130AL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2431005		**Battery Cables and Receptacles - Perform Battery Connector Tolerance Check.**							RE		TLMC 05-19-00	**≈24-Jul-2024**
24 A/F							Mos	09-Feb-2024				
							Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
		Alias1:247-31-00 (ZONE: 300) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y2460000		**DC BUS Isolation - Perform Operational Check.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
24 A/F		05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
							Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
		Alias1:24-60-00 (ZONE: 200) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 24-60-00.))					Ldg	3,757				
▼ 25 - EQUIPMENT/FURNISHINGS												
		(ELT) Emergency Locator Transmitter							RE (O/C)			
25 A/F			171				Mos	24-Jun-2022				
453-5000-(366)		Tested/Inspected	5,022.3				Hrs	5,022.3				
170-02018			3,090				Ldg	3,090				
		(ELT) Emergency Locator Transmitter Battery							RE (Due)			
25 A/F							Mos	24-Jun-2022			01-May-2027	2.9 Years
453-500-(366)							Hrs	5,022.3				
170-02018							Ldg	3,090				
		Expiration Date 01-May-2027										
		AC Outlet							RE (O/C)			
25 A/F		No.1					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		AC Outlet							RE (O/C)			
25 A/F		No.2					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		AC Outlet							RE (O/C)			
	25 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Airshow Computer							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Airshow Switch							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Box Assem, Storage Change							RE (O/C)			
	25 A/F	Fwd - Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Box Assem, Storage Mid Change							RE (O/C)			
	25 A/F	Fwd - Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Box Assem, Storage, Change							RE (O/C)			
	25 A/F	Aft - Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Box Assem, Storage, Change							RE (O/C)			
	25 A/F	Aft - Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Box Assem, Storage, Change							RE (O/C)			
	25 A/F	Fwd - Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Box Assem, Storage, Fwd Change							RE (O/C)			
	25 A/F	Aft - Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Box Assem, Storage, Mid Change							RE (O/C)			
	25 A/F	Aft - Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Box Assem, Storage, Mid Change							RE (O/C)			
	25 A/F	Fwd - Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Cabin Airshow Display Computer Unit							RE (O/C)			
	25 A/F		0				Mos	13-Mar-2008				
	920055	New	0				Hrs	0				
	G01002638		0				Ldg	0				
		Cabin Seat Conduit Assembly							RE (O/C)			
	25 A/F	Aft - Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Clip Assy Control Wheel							RE (O/C)			
	25 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Closet Switch Panel Assembly							RE (O/C)			
	25 A/F		0				Mos	13-Mar-2008				
	SP-45-21	New	0				Hrs	0				
	110700927		0				Ldg	0				
		Coffee Pot							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Crew Seat							RE (O/C)			
	25 A/F	Copilot	79				Mos	02-Oct-2014				
	TALJ2-14CM01-02/4525103038-008		3,296				Hrs	3,296				
	909		1,927				Ldg	1,927				
		Crew Seat							RE (O/C)			
	25 A/F	Pilot	22				Mos	28-Jan-2010				
	TALJ2-14PM01-02/4525103038-007		1,172.9				Hrs	1,172.9				
	896		723				Ldg	723				
		CVR Underwater Locator Beacon - ULB Battery							RE (Due)	Replacement Schedule, TLMC 05-19-01		
	25 A/F	CVR					Mos	06-Feb-2022			28-Feb-2025	9.3 Months
	Unknown						Hrs	4,859.6				
	Unknown						Ldg	2,992				
	Expiration Date 28-Feb-2025											
	Alias1:(Std)D2566001, (EMP)2566001 (ZONE: 300) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: INTERVAL: Replace on or before battery replacement (expire) date.)											
		DL-1000 Data Loader							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		ELT Antenna							RE (O/C)			
	25 A/F		0				Mos	13-Mar-2008				
	110-337	New	0				Hrs	0				
	143179		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		ELT NAV Interface Unit							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		ELT Remote Switch							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		FDR Underwater Locator Beacon - ULB Battery							RE (N/A)	Replacement Schedule, TLMC 05-19-01		
	25 A/F	FDR					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
	Alias1:(Std)D2566001, (EMP)2566001 (ZONE: 300) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: FDR Not Installed)											
		Galley Drain Valve Solenoid							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Heated Water Container							RE (O/C)			
	25 A/F	No.1	0				Mos	03-Sep-2008				
	AR9061-3	New	0				Hrs	413.3				
	0251		0				Ldg	298				
		Heated Water Container							RE (O/C)			
	25 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Heated Water Switch							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		IR Sensor Change							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Jump Seat							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Lavatory Passenger Control Unit PCU							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Life Raft							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Life Vest							RE (O/C)			
	25 A/F	Copilot		7			Mos	12-May-2022				
	63600-101	New		0			Hrs	4,972.1				
	L5340345			0			Ldg	3,061				
		Life Vest							RE (O/C)			
	25 A/F	Infant - No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Life Vest							RE (O/C)			
	25 A/F	Infant - No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Life Vest							RE (O/C)			
	25 A/F	Lavatory		7			Mos	12-May-2022				
	63600-101	New		0			Hrs	4,972.1				
	L5340348			0			Ldg	3,061				
		Life Vest							RE (O/C)			
	25 A/F	No.1					Mos	12-May-2022				
	63600-101	New					Hrs	4,972.1				
	L5340347						Ldg	3,061				
		Life Vest							RE (O/C)			
	25 A/F	No.2					Mos	12-May-2022				
	63600-101	New					Hrs	4,972.1				
	L5340349						Ldg	3,061				
		Life Vest							RE (O/C)			
	25 A/F	No.3					Mos	12-May-2022				
	63600-101	New					Hrs	4,972.1				
	L5340340						Ldg	3,061				
		Life Vest							RE (O/C)			
	25 A/F	No.4					Mos	12-May-2022				
	63600-101	New					Hrs	4,972.1				
	L5340342						Ldg	3,061				
		Life Vest							RE (O/C)			
	25 A/F	No.5					Mos	12-May-2022				
	63600-101	New					Hrs	4,972.1				
	L5340344						Ldg	3,061				
		Life Vest							RE (O/C)			
	25 A/F	No.6					Mos	15-May-2022				
	63600-101	New		0			Hrs	4,972.1				
	L5340343			0			Ldg	3,061				
	(UPDATE NOTE: Vest replaced with new Expire Oct 01 2031 S/N:L5340343)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Life Vest							RE (O/C)			
	25 A/F	No.7					Mos	15-May-2022				
	63600-101	New		0			Hrs	4,972.1				
	2			0			Ldg	3,061				
	(UPDATE NOTE: Vest replaced with new Expire Oct 01 2031 S/N:L5461465)											
		Life Vest							RE (O/C)			
	25 A/F	No.8					Mos	15-May-2022				
	63600-101	New		0			Hrs	4,972.1				
	Unknown			0			Ldg	3,061				
	(UPDATE NOTE: Vest replaced with new Expire Oct 01 2031 S/N:L5340341)											
		Life Vest							RE (O/C)			
	25 A/F	Pilot					Mos	15-May-2022				
	Unknown	New		0			Hrs	4,972.1				
	Unknown			0			Ldg	3,061				
	(UPDATE NOTE: Vest replaced with new Expire Oct 01 2031 S/N:L5340346)											
		Microwave Oven							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Ordinance Sign							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Seat							RE (O/C)			
	25 A/F	No.1		0			Mos	13-Mar-2008				
	M6613100-001-T	New		0			Hrs	0				
	080103-05			0			Ldg	0				
		Passenger Seat							RE (O/C)			
	25 A/F	No.2		0			Mos	13-Mar-2008				
	M6613100-002-T	New		0			Hrs	0				
	080103-06			0			Ldg	0				
		Passenger Seat							RE (O/C)			
	25 A/F	No.3		0			Mos	13-Mar-2008				
	M6613100-001-T	New		0			Hrs	0				
	080103-04			0			Ldg	0				
		Passenger Seat							RE (O/C)			
	25 A/F	No.4		0			Mos	13-Mar-2008				
	M6613100-002	New		0			Hrs	0				
	080103-02			0			Ldg	0				
		Passenger Seat							RE (O/C)			
	25 A/F	No.5		0			Mos	13-Mar-2008				
	M6613100-001	New		0			Hrs	0				
	080103-01			0			Ldg	0				
		Passenger Seat							RE (O/C)			
	25 A/F	No.6		0			Mos	13-Mar-2008				
	M6613100-002-T	New		0			Hrs	0				
	080103-08			0			Ldg	0				

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Passenger Seat							RE (O/C)			
	25 A/F	No.7	0				Mos	13-Mar-2008				
	M6613100-001-T	New	0				Hrs	0				
	080103-03		0				Ldg	0				
		Passenger Seat							RE (O/C)			
	25 A/F	No.8	0				Mos	13-Mar-2008				
	M6613100-002-T	New	0				Hrs	0				
	080103-07		0				Ldg	0				
		Passenger Seat PCU							RE (O/C)			
	25 A/F	No.1	0				Mos	13-Mar-2008				
	SP-45-54	New	0				Hrs	0				
	010800060		0				Ldg	0				
		Passenger Seat PCU							RE (O/C)			
	25 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Seat PCU							RE (O/C)			
	25 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Seat PCU							RE (O/C)			
	25 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Seat PCU							RE (O/C)			
	25 A/F	No.5					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Seat PCU							RE (O/C)			
	25 A/F	No.6					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Seat PCU							RE (O/C)			
	25 A/F	No.7					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Seat PCU							RE (O/C)			
	25 A/F	No.8					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Power Port 110 Volt Outlet							RE (O/C)			
	25 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Power Port 110 Volt Outlet							RE (O/C)			
25 A/F		0				Mos	13-Mar-2008				
SP-45-26	New	0				Hrs	0				
120700936		0				Ldg	0				
	Power Port 110 Volt Outlet							RE (O/C)			
25 A/F		0				Mos	13-Mar-2008				
SP-45-26	New	0				Hrs	0				
090500769		0				Ldg	0				
	Power Port 110 Volt Outlet							RE (O/C)			
25 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Relay Module							RE (O/C)			
25 A/F		0				Mos	07-Apr-2009				
MSM9646-01-1	New	0				Hrs	728.1				
110800794		0				Ldg	483				
2000-18-04	**Inspect Aviointeriors Seats**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	13-Mar-2008				
Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
2002-21-01	**Electrical terminal contact pins - Britax Sell GmbH & Co. OHG Water Boilers, Coffee Makers, and Beverage Makers**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 27-Nov-2002 Not Applicable						Hrs	11.6				
						Ldg	11				
2003-26-06	**Anjou - Safety Belts and Restraint Systems**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 17-Feb-2004 Not Applicable						Hrs	11.6				
Brand A:9990-2003-26-06 (AVG MAN HRS: 1)						Ldg	11				
2004-03-01	**Emergency Evacuation Slide/Raft System**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	13-Mar-2008				
Eff: 11-Mar-2004 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
2005-07-27	**Aviointeriors S.p.A - Seat central crossmember**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 16-May-2005 Not Applicable						Hrs	11.6				
						Ldg	11				
2005-20-26	**AVIOINTERIORS S.P.A. (FORMERLY ALVEN), - Serises 312 Box Mounted Seats - Seat attachments.**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 16-Nov-2005 Not Applicable						Hrs	11.6				
						Ldg	11				
2006-08-03	**Bottom seat folding mechanisms**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 18-May-2006 Not Applicable						Hrs	11.6				
						Ldg	11				
2006-17-13	**Replacing the existing attachment bolts for the seat belts with longer attachment bolts**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 27-Sep-2006 Not Applicable						Hrs	11.6				
						Ldg	11				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2006-25-15	**Sicma Aero Seat - two headrest bushings**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 19-Jan-2007 Not Applicable						Hrs	11.6				
						Ldg	11				
2007-04-15	**Sicma Aero Seat - Installing new tab locks**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 23-Mar-2007 Not Applicable						Hrs	11.6				
						Ldg	11				
2007-19-12	**SICMA Aero Seat**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 26-Oct-2007 Not Applicable						Hrs	11.6				
						Ldg	11				
2007-19-13	**B/E AEROSPACE SKYLUXE II (AA2) PASSENGER SEATS - Hydrolok retaining pin**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 03-Oct-2007 Not Applicable						Hrs	11.6				
						Ldg	11				
2013-0020 Paragraph (1)	**AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 14-Feb-2013						Hrs					
						Ldg					
2013-0020R4 Paragraph (1)	**AMSAFE, ANJOU AERONAUTIQUE, DAVIS AIRCRAFT PRODUCTS Co., SCHROTH SAFETY PRODUCTS GmbH, PACIFIC SCIENTIFIC - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection**							T (A/R)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 11-Jul-2014						Hrs					
						Ldg					
2013-14-07	**Equipment/Furnishings**							RE (-)		Mandatory	
25 A/F						Mos	26-Jul-2013				
Eff: 26-Aug-2013 Complied With	METHOD OF COMPLIANCE - SB-45-25-35 REV-3					Hrs	2,900.6				
						Ldg	1,700				
2015-10-02	**Zodiac Seats France Passenger Seat Assemblies (This AD replaces AD 2014-20-11)**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	30-Dec-2015				
Eff: 12-Jun-2015 Complied With						Hrs	3,621.8				
Brand A:9990-2015-10-02 (AVG MAN HRS: 1)						Ldg	2,105				
2015-10-02 Par. 2(g)	**Zodiac Seats France Passenger Seat Assemblies - Repetitive Inspection**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	30-Dec-2015				
Eff: 12-Jun-2015 Not Applicable						Hrs	3,621.8				
(AVG MAN HRS: 1)						Ldg	2,105				
2015-10-02 Par. 2(h)	**Zodiac Seats France Passenger Seat Assemblies - Corrective Action - Replace Cracked Link**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	30-Dec-2015				
Not Applicable	PER MODEL					Hrs	3,621.8				
(AVG MAN HRS: 1)						Ldg	2,105				
2015-10-02 Par. 2(i)	**Zodiac Seats France Passenger Seat Assemblies - Replace Seat Backrest Links**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	30-Dec-2015				
Not Applicable						Hrs	3,621.8				
						Ldg	2,105				
2016-11-20 PARA (H.1)	**Replacement Of A Pbe Pouch, Found During The Inspection In Paragraph (G) Of This Ad, That Does Not Have An Intact Vacuum Seal. Superseded By Faa Ad 2017-18-12**							RE (-)			
25 A/F						Mos	29-Aug-2019				
Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2016-11-20 PARA (H.2)	**Replacement Of A Pbe Pouch, Found During The Inspection In Paragraph (G) Of This Ad, Where The Vacuum Seal Is Intact. Superseded By Faa Ad 2017-18-12**							RE (-)			
25 A/F						Mos	29-Aug-2019				
Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
2017-09-09	**Passenger Compartment Equipment - Zodiac Seats California LLC Seating Systems - Removal**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 28-Jun-2017 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 1)						Ldg	2,822				
2017-16-01	**Emergency Locator Beacon (Ameri-King Corporation) - Inspect/ Replace**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 24-Oct-2017 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 6)						Ldg	2,822				
2017-16-01 Par. 2(g)	**Emergency Locator Beacon (Ameri-King Corporation) - Inspect**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 24-Oct-2017 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 2)						Ldg	2,822				
2017-16-01 Par. 2(j)(1)(2)	**Emergency Locator Beacon (Ameri-King Corporation) - Replace (Terminating Action)**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 24-Oct-2017 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 4)						Ldg	2,822				
2017-16-04 Par. 2(e)(1)	**Cabin Equipment/Furnishings - Romtex Torso Restraint Systems with a Rotary Buckle Subassembly - Inspection**							T (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 22-Sep-2017						Hrs					
(AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to Anjou Aero Service Bulletin No. 358SB-14-101, Revision 1.)						Ldg					
2017-16-04 Par. 2(e)(1)(i)	**Cabin Equipment/Furnishings - Romtex Torso Restraint Systems with a Rotary Buckle Subassembly - Replacement**							T (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 22-Sep-2017						Hrs					
(AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to Anjou Aero Service Bulletin No. 358SB-14-101, Revision 1.)						Ldg					
2017-22-02	**Pilot and Co-Pilot Seats - Modification/ Re-Identification (This AD has been replaced by AD 2019-21-06)**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	29-Aug-2019				
Eff: 12-Dec-2017 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 2) (NOTE: APPLICABILITY: This AD applies to Ipeco Holdings Ltd. (Ipeco) pilot and co-pilot seats with a part number listed in the Planning Information section of Ipeco Service Bulletins (SBs) Number 063-25-08, Revision 00; Number 063-25-09, Revision 00; and Number 063-25-10, Revision 00; all dated May 31, 2016.)						Ldg	2,733				
2017-22-02 PARA (F)	**Modify And Re-Identify Affected Each Pilot And Co-Pilot Seat**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
2018-16-13	**Zodiac Seats France - 537-Series Cabin Attendant Seats - Safety Belt Webbing - Inspection/ Modification**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	27-Sep-2023				
Eff: 26-Oct-2018 Not Applicable	Equipment not installed					Hrs	5,197.3				
						Ldg	3,212				
(AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to Zodiac Seats France Service Information Letter 537-01, dated July 31, 2015, and the Accomplishment Instructions, paragraphs 2.A. through 2.B., of Zodiac Seats France Service Bulletin No. 537-25-003, Revision 1, dated August 29, 2016.)											
2018-19-15	**GEVEN S.p.A. (Geven) Type D1-02 and D1-03 In-Arm Table, Standard, and Last Row Seats - Modification**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 14-Nov-2018						Hrs					
(NOTE: NOTE: Refer to Geven SB No. D103-25-004, Revision 4, dated March 15, 2016.)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2018-23-01	**Zodiac Seats France Cabin Attendant Seats, 536 Series, P/N 53600 with Seat Pan P/N F0433453 - Inspection/ Modification/ Replacement**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 28-Dec-2018 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2018-23-01 Par. (g)	**Zodiac Seats France Cabin Attendant Seats, 536 Series, P/N 53600 with Seat Pan P/N F0433453 - Inspection/ Modification**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 28-Dec-2018 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2018-23-01 Par. (h)	**Zodiac Seats France Cabin Attendant Seats, 536 Series, P/N 53600 with Seat Pan P/N F0433453 - Replacement (Optional Terminating Action)**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 28-Dec-2018 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2018-23-12 Par. (g)	**Zodiac Aero Evacuation Systems (also known as Air Cruisers Company) Fusible Plugs Installed on Emergency Evacuation Equipment - Inspection**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 28-Dec-2018						Hrs					
(AVG MAN HRS: 4)						Ldg					
2018-23-12 Par. (h)	**Zodiac Aero Evacuation Systems (also known as Air Cruisers Company) Fusible Plugs Installed on Emergency Evacuation Equipment - Replacement**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 28-Dec-2018						Hrs					
(AVG MAN HRS: 1)						Ldg					
2019-0235 Par. (1)(2)	**ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Inspection / Testing**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
						Hrs					
						Ldg					
2019-0235 Par. (5)(6)	**ACR ELECTRONICS, Inc. - Emergency Locator Transmitter - Modification / Replacement (Terminating Action)**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 04-Oct-2019						Hrs					
						Ldg					
2019-07-03	**Zodiac Seats France 536-Series Cabin Attendant Seats - Inspection/ Modification**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	21-May-2019				
Eff: 16-May-2019 Not Applicable	EQUIPMENT NOT INSTALLED ON AIRCRAFT					Hrs					
						Ldg					
2019-07-03 Par. (g)(1)(3)(4)(h)	**Zodiac Seats France 536-Series Cabin Attendant Seats - Detailed Visual Inspection**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
						Hrs					
(NOTE: COMPLIANCE: Within 14 months after the first installation of the seat on an aircraft.)						Ldg					
2019-08-01	**RECARO Aircraft Seating GmbH & Co. KG (RECARO) Model 3510A and 3510D Passenger Seats - Modification**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	21-May-2019				
Eff: 21-May-2019 Not Applicable	EQUIPMENT NOT INSTALLED ON AIRCRAFT					Hrs					
						Ldg					
2019-08-01 PARA (G)	**Modify The Affected Passenger Seat And Re-Identify Each Modified Passenger Seat**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
2019-14-05 PARA (G)	**Review Each Affected B/E Aerospace Fischer Common Seat To Determine If Rework Has Already Been Performed. If The Rework Has Not Been Performed Rework The Affected Seats And Mark The Seat By Installing A Placard**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2019-15-10	**Safran Aerosystems Life Jackets with P/N 210225-2, P/N 216200-0, or P/N 216203-0 - Inspect/ Replace/ Repair**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	11-Sep-2019				
Eff: 19-Sep-2019 Not Applicable	BY EFFECTIVITY: NOT EFFECTIVE BY PART NUMBERS INSTALLED (P/N 63600-171,D21343-153 IS INSTALLED)					Hrs	4,339				
						Ldg	2,550				
	(NOTE: NOTE: Refer to Zodiac Aerospace Services Service Bulletin (SB) 25-65-33, Revision 02, dated March 15, 2019.)										
2019-15-10 PARA (H)	**Safran Aerosystems Life Jackets with P/N 210225-2, P/N 216200-0, or P/N 216203-0 - Inspect/ Replace/ Repair**							RE (-)			
25 A/F						Mos	11-Sep-2019				
Not Applicable	BY EFFECTIVITY: NOT EFFECTIVE BY PART NUMBERS INSTALLED (P/N 63600-171,D21343-153 IS INSTALLED)					Hrs	4,339				
						Ldg	2,550				
2019-21-06	**Ipeco Pilot and Co-Pilot Seats - Modification/ Re-Identification (This AD replaces AD 2017-22-02)**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 13-Dec-2019 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2019-21-06 Par. (g)(1)	**Ipeco Pilot and Co-Pilot Seats - Modify and Re-Identify**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 12-Dec-2017 Not Applicable						Hrs	4,610.5				
	(NOTE: APPLICABILITY: For seats that have not installed the tracklock spring modification kit.)					Ldg	2,822				
2019-21-06 Par. (g)(2)(i)	**Ipeco Pilot and Co-Pilot Seats - Inspect the Tracklock Spring of Each Seat**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 13-Dec-2019 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2019-21-06 PARA (H)	**Do Not Install Any Pilot Or Co-Pilot Seat Identified In Paragraph (C)(1)(I) Of This Ad Unless The Seat Is Modified And Re-Identified As Specified In Paragraph (G)(1) Of This Ad**							RE (-)			
25 A/F						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2019-21-06 Paragraph (g)(3)	**Ipeco Pilot and Co-Pilot Seats - Modification/ Re-Identification - Send the Inspection Results, Including No Findings, to IPECO at Technicalsupport@Ipeco.Com**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Days	14-Dec-2020				
Eff: 13-Dec-2019 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2019-21-09	**Aviointeriors S.p.A. (Aviointeriors) Centaurus Economy Class 13E, 13H, and 13K Passenger Seats with Life Vest Pouch, P/N 313907100004 - Inspection/ Replacement**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 18-Dec-2019 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2019-21-09 Par. (g)(1)	**Aviointeriors S.p.A. (Aviointeriors) Centaurus Economy Class 13E, 13H, and 13K Passenger Seats with Life Vest Pouch, P/N 313907100004 - Inspection**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	14-Dec-2020				
Eff: 18-Dec-2019 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2021-07-13	**Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	15-May-2022				
Eff: 11-May-2021 Complied With	NFF					Hrs	4,972.1				
						Ldg	3,061				
	(AVG MAN HRS: 1) (UPDATE NOTE: C/W. NFF)										
2021-07-13 Par. (e)(1)	**Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475 - Inspect the Buckle Handle for a Crack**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	21-Nov-2021				
Eff: 11-May-2021 Complied With						Hrs	4,818.2				
	(AVG MAN HRS: 0.5) (UPDATE NOTE: C/W. BUCKLES INSP, NO CRACKS EVIDENT)					Ldg	2,969				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2021-07-13 Par. (e)(2)	**Pacific Scientific Company Rotary Buckle Assembly, P/Ns 1111430 and 1111475 - Measure the Thickness of the Buckle Handle Vane**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	15-May-2022				
Eff: 11-May-2021 Complied With	NFF					Hrs	4,972.1				
						Ldg	3,061				
	(UPDATE NOTE: WITHIN MEASURED LIMITS) (NOTE: COMPLIANCE: Within 12 months, measure the thickness of the buckle handle vane as depicted in Figure 3 of SB 25-1111432. If the handle vane thickness is 0.125 inch or greater, before further flight, remove the buckle from service and replace it with an airworthy buckle.)										
2022-07-05	**Parachute - MARS A.S. ATL-88/90-1B (Commercially known as ATL-15 SL) Emergency Parachutes**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	25-Apr-2022				
Eff: 04-Apr-2022 Not Applicable	Not Applicable. Part not installed					Hrs					
						Ldg					
	(NOTE: APPLICABILITY: This AD applies to MARS A.S. ATL-88/90-1B (commercially known as ATL-15 SL) emergency parachutes that meet either of the criterion in paragraph (c)(1) or (2) of this AD: (1) The parachute has a date of manufacture of January 1, 2016, or later; or (2) The date of manufacture of the parachute is unknown.)										
2023-12-25	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets**							RE (-)		Mandatory	
25 A/F						Mos					
Eff: 23-Aug-2023						Hrs					
						Ldg					
	(NOTE: APPLICABILITY: This AD applies to Survitec Group Limited (RFD Beaufort Ltd.) life jackets identified in paragraphs (c) (1) and (2) of this AD, having a part number and serial number identified in tables 2 through 13 of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021, and a date of manufacture between October 1, 2018, and April 30, 2019, inclusive.)										
2023-12-25 Par. (g)	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection**							RE (-)		Mandatory	
25 A/F						Mos	09-Feb-2024				
Eff: 23-Aug-2023 Not Applicable	equipment not installed					Hrs	5,253.5				
						Ldg	3,757				
	(NOTE: COMPLIANCE: Within 4 months after the effective date of this AD, do a general visual inspection for a discrepancy (mismatch of the valise/container description and life jacket type) of the life jacket, in accordance with paragraphs 2.A. through 2.C. of the Accomplishment Instructions of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021.)										
2023-12-25 Par. (h)	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action**							T (A/R)		Mandatory	
25 A/F						Mos					
Eff: 23-Aug-2023						Hrs					
						Ldg					
	(NOTE: COMPLIANCE: Before further flight after accomplishing the requirements of paragraph (g) of this AD, do the applicable actions required by paragraph (h)(1) and (2) of this AD.)										
251000-0101	**First Aid Kit**							RE (O/C)			
25 A/F						Mos	10-Feb-2021				
500097 122320019	Overhauled					Hrs	4,610.5				
						Ldg	2,822				
25-CUS-005	**First Aid kit - Visually Inspect per Manufacturer instructions**							RE		Custom Task	
25 A/F						Mos	27-Mar-2024	12	-/+14d	03-Mar-2025	9.4 Months (+14 Days)
500097 122320019						Hrs	5,263.4				
(Tol. Adjustment: -26d)						Ldg	3,767				
25-CUS-LV	**Life Vests - Inspection**							RE			
25 A/F						Mos	09-Feb-2024	12		09-Feb-2025	8.7 Months
						Hrs	5,253.5				
						Ldg	3,757				
25-NOAA	**406 MHz ELT-NOAA Registration Renewal (25-NOAA)**							RE		NOAA Requirement	
25 A/F						Mos	06-Jul-2023	24		06-Jul-2025	1.1 Years
						Hrs					
						Ldg					
45-23-2	**Communications - Modification of Forward Quadrant Switch Panel Wiring**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-23-2 Rev 1	**Communications - Modification of Forward Quadrant Switch Panel Wiring**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-2 Rev 2	**Communications - Modification of Forward Quadrant Switch Panel Wiring**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-23-2 Rev 3	**Communications - Modification of Forward Quadrant Switch Panel Wiring**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 10-Jul-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-1	**Equipment/Furnishings - Modification of Cabin Seating**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 16-Apr-1999 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-10	**Equipment/Furnishings - Modification of the Crew Seats**							RE (-)		Optional	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-10 Rev 1	**Equipment/Furnishings - Modification of the Crew Seats**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-11	**Equipment/Furnishings - Replacement of Nose Wheel Well HIRF Screens**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 07-May-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-12	**Equipment/Furnishings - Installation of Insulation at the Emergency Exit Door**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 19-Feb-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-13	**Equipment and Furnishings - Hiller Lavatory Vanity Upgrade**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 08-May-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-14	**Equipment and Furnishings - Inspection/Replacement of the Cabin Seat Tracking Tubes**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-14 Rev 1	**Equipment and Furnishings - Inspection/Replacement of the Cabin Seat Tracking Tubes**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-14 Rev 2	**Equipment and Furnishings - Inspection/Replacement of the Cabin Seat Tracking Tubes**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 15-Jan-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-15	**Equipment/Furnishings -- Replacement of the Right Forward Galley Door Fold Up Hinge Mechanism**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 16-Jan-2006 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-25-16	**Equipment/Furnishings - Audio International Cabin Management System Software Replacement**							RE (-)		Recommended	
25 A/F						Mos	08-Jun-2009				
Not Applicable	PER A/C S/N					Hrs	801				
						Ldg	521				
45-25-16 Rev 1	**Equipment/Furnishings - Audio International Cabin Management System Software Replacement**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 05-Nov-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-17	**Equipment/Furnishings - Replacement of the Passenger and Toilet Seat Restraints**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 07-May-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-18	**Equipment/Furnishings - Upper Galley One Piece Door**							RE (-)		Optional	
25 A/F						Mos					
						Hrs					
						Ldg					
45-25-18 Rev 1	**Equipment/Furnishings - Upper Galley One Piece Door**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 13-Apr-2009 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-19	**Equipment and Furnishings - Replacement of the Cabin Inverter**							RE (-)		Optional	
25 A/F						Mos	25-Jun-2009				
Complied With						Hrs	818.5				
						Ldg	529				
45-25-19 Rev 1	**Equipment and Furnishings - Replacement of the Cabin Inverter**							RE (-)		Optional	
25 A/F						Mos					
						Hrs					
						Ldg					
45-25-19 Rev 2	**Equipment and Furnishings - Replacement of the Cabin Inverter**							RE (-)		Optional	
25 A/F						Mos	28-Jan-2010				
Complied With						Hrs	1,172.9				
						Ldg	723				
45-25-19 Rev 3	**Equipment and Furnishings - Replacement of the Cabin Inverter**							RE (-)		Optional	
25 A/F						Mos	10-Jan-2020				
Eff: 04-Mar-2013 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				
45-25-2	**Equipment/Furnishings - Replacement of Ice Compartment Drain Switch**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 14-Jul-2000 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-20	**Equipment/Furnishings - Replacement of the Rudder Pedal Forward Shroud Assembly Screws**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 20-Nov-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-21	**Equipment/Furnishings - Inspect/Remove Red RTV Sealant in the Aft Baggage Bay**							RE (-)		Recommended	
25 A/F						Mos	06-Aug-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	359.6				
						Ldg	264				
45-25-21 Rev 1	**Equipment/Furnishings - Inspect/Remove Red RTV Sealant in the Aft Baggage Bay**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 19-Jan-2009 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-25-22	**Equipment and Furnishings - Crew Seat Belt Buckle Replacement**							RE (-)		Recommended	
25 A/F						Mos	08-Jun-2009				
Not Applicable	PER A/C S/N					Hrs	801				
						Ldg	521				
45-25-22 Rev 1	**Equipment and Furnishings - Crew Seat Belt Buckle Replacement**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 28-Jan-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-23	**Equipment/Furnishings - Installation of Cockpit Overhead Insulation**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 10-Nov-2008 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-24	**Equipment and Furnishings - Installation of the Cabin Power Inverter Cover**							RE (-)		Recommended	
25 A/F						Mos	05-Jan-2009				
Eff: 20-Oct-2008 Complied With						Hrs					
(AVG MAN HRS: 5)						Ldg					
45-25-24 R01 12-1-08	**Equipment And Furnishings - Installation Of The Cabin Power Inverter Cover. Rework Required!!!! (Note: This Is 2Nd Release Of R1. Original Was Issued 11-10-08). (Effective: 45-005 Thru 45-370 When Equipped With Optional Cabin Power Inverter (P/N 2D1200-1A-1011 Or 3D1200-2A-1029).)**							RE (-)			
25 A/F						Mos					
Not Applicable	PREVIOUSLY C/W SB 45-25-19					Hrs					
						Ldg					
45-25-24 Rev 1	**Equipment and Furnishings - Installation of the Cabin Power Inverter Cover**							RE (-)		Recommended	
25 A/F						Mos	19-Apr-2010				
Eff: 01-Dec-2008 Not Applicable	BECAUSE I HAVE C/W SB 45-25-19					Hrs	1,299.5				
(AVG MAN HRS: 5)						Ldg	796				
45-25-24 Rev 2	**Equipment and Furnishings - Installation of the Cabin Power Inverter Cover**							RE (-)		Recommended	
25 A/F						Mos	17-Apr-2012				
Eff: 20-Oct-2008 Complied With	PREVIOUSLY COMPLIED WITH REVISION 1 ON 04/19/2010 ACTT 602					Hrs	2,413.2				
(AVG MAN HRS: 5)						Ldg	1,441				
45-25-26	**Equipment/Furnishins - Vanity Tissue Compartment Modification for Improved EGPWS Computer Access**							RE (-)		Optional	
25 A/F						Mos					
						Hrs					
						Ldg					
45-25-26 Rev 1	**Equipment/Furnishins - Vanity Tissue Compartment Modification for Improved EGPWS Computer Access**							T (A/R)		Optional	
25 A/F						Mos					
Eff: 04-Mar-2013						Hrs					
						Ldg					
45-25-27	**Equipment/Furnishings - Modification of the Entry Door Trim Track Installation**							RE (-)		Optional	
25 A/F						Mos					
Eff: 21-Dec-2009						Hrs					
(AVG MAN HRS: 8)						Ldg					
45-25-27 Rev 1	**Equipment/Furnishings - Modification of the Entry Door Trim Track Installation**							RE (-)		Optional	
25 A/F						Mos					
Eff: 08-Mar-2010						Hrs					
(AVG MAN HRS: 8)						Ldg					
45-25-27 Rev 2	**Equipment/Furnishings - Modification of the Entry Door Trim Track Installation**							RE (-)		Optional	
25 A/F						Mos					
Eff: 23-Jan-2014						Hrs					
(AVG MAN HRS: 8)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-25-27 Rev 3	**Equipment/Furnishings - Modification of the Entry Door Trim Track Installation**							T (-)		Optional	
25 A/F						Mos					
Eff: 08-Dec-2014						Hrs					
(AVG MAN HRS: 8)						Ldg					
45-25-27 Rev 4	**Equipment/Furnishings - Modification of the Entry Door Trim Track Installation**							T (A/R)		Optional	
25 A/F						Mos					
Eff: 24-Aug-2015						Hrs					
(AVG MAN HRS: 8)						Ldg					
45-25-28	**Equipment/Furnishings - Modification of the Emteq AC Power Outlet**							RE (-)		Recommended	
25 A/F						Mos	30-Jul-2010				
Eff: 17-May-2010 Complied With						Hrs	1,499.8				
(AVG MAN HRS: 2.5)						Ldg	910				
45-25-28 Rev 1	**Equipment/Furnishings - Modification of the Emteq AC Power Outlet**							RE (-)		Recommended	
25 A/F						Mos	07-Apr-2013				
Eff: 11-Mar-2013 Complied With						Hrs	2,797.6				
(AVG MAN HRS: 2.5)						Ldg	1,647				
45-25-28 Rev 2	**Equipment/Furnishings - Modification of the Emteq AC Power Outlet**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 28-May-2013 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 2.5)						Ldg	2,822				
45-25-29	**Equipment/Furnishings - Modification of the Toilet Shroud Forward Face**							RE (-)		Recommended	
25 A/F						Mos	28-Jan-2010				
Eff: 24-Dec-2009 Complied With						Hrs	1,172.9				
(AVG MAN HRS: 8)						Ldg	723				
45-25-29 Rev 1	**Equipment/Furnishings - Modification of the Toilet Shroud Forward Face**							RE (-)		Recommended	
25 A/F						Mos	26-May-2010				
Eff: 26-Apr-2010 Complied With	PREVIOUSLY					Hrs	1,378.1				
(AVG MAN HRS: 8)						Ldg	841				
45-25-29 Rev 2	**Equipment/Furnishings - Modification of the Toilet Shroud Forward Face**							RE (-)		Recommended	
25 A/F						Mos	07-Apr-2013				
Eff: 11-Mar-2013 Complied With	NO REWORK IF PREVIOUS COMPLIED WITH					Hrs	2,797.6				
(AVG MAN HRS: 8)						Ldg	1,647				
45-25-29 Rev 3	**Equipment/Furnishings - Modification of the Toilet Shroud Forward Face**							RE (-)		Recommended	
25 A/F						Mos	10-Jan-2020				
Eff: 25-Jan-2016 Not Applicable						Hrs	4,590.8				
(AVG MAN HRS: 8)						Ldg	2,807				
45-25-3	**Equipment/Furnishings - Installation of Oxygen Cup Stowage Bracket Striker Plate**							RE (-)		Optional	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-3 Rev 1	**Equipment/Furnishings - Installation of Oxygen Cup Stowage Bracket Striker Plate**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 16-Aug-2002 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-30	**Equipment/Furnishings - Replacement of the Aft Partition Door Guide**							RE (-)		Optional	
25 A/F						Mos	16-Oct-2010				
Complied With						Hrs	1,607.8				
						Ldg	973				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-25-30 Rev 1	**Equipment/Furnishings - Replacement of the Aft Partition Door Guide**							RE (-)		Optional	
25 A/F						Mos	10-Jan-2020				
Eff: 22-Jul-2013 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				
45-25-31	**Equipment/Furnishings - Maintenance Connector Access Improvement**							RE (-)		Optional	
25 A/F						Mos					
						Hrs					
						Ldg					
45-25-31 Rev 1	**Equipment/Furnishings - Maintenance Connector Access Improvement**							RE (-)		Optional	
25 A/F						Mos					
						Hrs					
						Ldg					
45-25-31 Rev 2	**Equipment/Furnishings - Maintenance Connector Access Improvement**							T (A/R)		Optional	
25 A/F						Mos					
Eff: 21-Jun-2010						Hrs					
						Ldg					
45-25-32	**Equipment/Furnishings - Modification of the Baggage Compartment for Improved Auxiliary Hydraulic Pump Access**							RE (-)		Optional	
25 A/F						Mos	14-Jun-2013				
Eff: 03-May-2010 Complied With						Hrs	2,871.6				
						Ldg	1,684				
45-25-33	**Equipment/Furnishings - Replacement of the Cabin Seat Swivel Assembly**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 19-Apr-2010 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-34	**Equipment and Furnishings - Toilet Placard Installation**							RE (-)		Recommended	
25 A/F						Mos	10-Sep-2010				
Eff: 21-Jun-2010 Complied With						Hrs	1,550.2				
(AVG MAN HRS: 0.5)						Ldg					
45-25-34 Rev 1	**Equipment and Furnishings - Toilet Placard Installation**							RE (-)		Recommended	
25 A/F						Mos	02-May-2013				
Eff: 18-Mar-2013 Complied With						Hrs	2,818.4				
(AVG MAN HRS: 0.5)						Ldg	1,658				
45-25-35	**Equipment and Furnishings - Baggage Door Fire Seal Relocation**							RE (-)		Recommended	
25 A/F						Mos					
						Hrs					
(AVG MAN HRS: 11)						Ldg					
45-25-35 Rev 1	**Equipment and Furnishings - Baggage Door Fire Seal Relocation**							RE (-)		Recommended	
25 A/F						Mos	16-Oct-2010				
Eff: 23-Aug-2010 Complied With						Hrs	1,607.8				
(AVG MAN HRS: 11)						Ldg	973				
45-25-35 Rev 2	**Equipment and Furnishings - Baggage Door Fire Seal Relocation**							RE (-)		Recommended	
25 A/F						Mos	22-Apr-2011				
Eff: 21-Feb-2011 Complied With	PREVIOUSLY					Hrs	1,922.2				
(AVG MAN HRS: 11)						Ldg	1,155				
45-25-35 Rev 3	**Equipment and Furnishings - Baggage Door Fire Seal Relocation**							RE (-)		Recommended	
25 A/F						Mos	26-Jul-2013				
Eff: 06-Feb-2012 Complied With						Hrs	2,900.6				
(AVG MAN HRS: 11)						Ldg	1,700				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-25-36	**Equipment/Furnishings - Replacement Of The Galley Ice Drawers**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 27-Sep-2010 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-37	**Equipment/Furnishings - Replacement of the Crew Seats**							RE (-)		Optional	
25 A/F						Mos					
Eff: 09-May-2011						Hrs					
(AVG MAN HRS: 12.5)						Ldg					
45-25-37 Rev 1	**Equipment/Furnishings - Replacement of the Crew Seats**							RE (-)		Optional	
25 A/F						Mos					
Eff: 11-Jun-2012						Hrs					
(AVG MAN HRS: 12.5)						Ldg					
45-25-37 Rev 2	**Equipment/Furnishings - Replacement of the Crew Seats**							T (A/R)		Optional	
25 A/F						Mos					
Eff: 06-Oct-2014						Hrs					
(AVG MAN HRS: 12.5)						Ldg					
45-25-38	**Equipment/Furnishings - Repositioning of Crew Seat Armrests**							RE (-)		Recommended	
25 A/F						Mos	30-Apr-2012				
Eff: 02-Apr-2012 Not Applicable	PER AIRCRAFT SERIAL NUMBER					Hrs	2,433.2				
(AVG MAN HRS: 6)						Ldg	1,452				
45-25-38 Rev 1	**Equipment/Furnishings - Repositioning of Crew Seat Armrests**							RE (-)		Recommended	
25 A/F						Mos	30-May-2012				
Eff: 30-Apr-2012 Not Applicable	PER A/C S/N					Hrs					
(AVG MAN HRS: 6)						Ldg					
45-25-38 Rev 2	**Equipment/Furnishings - Repositioning of Crew Seat Armrests**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 15-Oct-2012 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 6)						Ldg	2,822				
45-25-39	**Equipment/Furnishings - Ten Year Life Vest Upgrade**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 24-Sep-2012 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-39 Rev 1	**Equipment/Furnishings - Ten Year Life Vest Upgrade**							T (-)		Optional	
25 A/F						Mos					
Eff: 18-Sep-2023						Hrs					
(AVG MAN HRS: 0.5) (NOTE: EFFECTIVITY: Learjet 45-006 thru 45-367, 45-369 thru 45-445 and 45-447 thru 45-455 on aircraft with 7607052-1 life vest currently installed.)						Ldg					
45-25-39 Rev 2	**Equipment/Furnishings - Ten Year Life Vest Upgrade**							T (A/R)		Optional	
25 A/F						Mos					
Eff: 11-Mar-2024						Hrs					
(AVG MAN HRS: 0.5) (NOTE: EFFECTIVITY: Learjet 45-006 thru 45-367, 45-369 thru 45-445 and 45-447 thru 45-455 on aircraft with 7607052-1 life vest currently installed.)						Ldg					
45-25-40	**Equipment/Furnishings - Retractable Cup Holder Wire Chafing Modification**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 05-May-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 2.5)						Ldg	2,822				
45-25-41	**Equipment/Furnishings - Gas Spring Support And Height Adjustment Lever**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 02-Mar-2015 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 4)						Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-25-43	**Equipment/Furnishings - Spares Replacement of Pilot or Copilot Cupholder**							RE (-)		Optional	
25 A/F						Mos	26-Jul-2017				
Eff: 07-Dec-2015 Complied With						Hrs	3,891.2				
(AVG MAN HRS: 1)						Ldg					
45-25-44	**Equipment/Furnishings - Installation of Baggage Door Forward Seal Panel Protector Assembly**							T (A/R)		Optional	
25 A/F						Mos					
Eff: 05-Jul-2016						Hrs					
(AVG MAN HRS: 4.5)						Ldg					
45-25-45	**Equipment Furnishings - 230VAC Outlets - Residual Current Circuit Breaker (RCCB) Spares Replacement**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 11-Sep-2017 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 2)						Ldg	2,733				
45-25-46	**Equipment/Furnishings - Cabin Window Shade Replacement**							T (-)		Optional	
25 A/F						Mos					
Eff: 27-Aug-2018						Hrs					
(AVG MAN HRS: 32.5)						Ldg					
45-25-46 Rev 1	**Equipment/Furnishings - Cabin Window Shade Replacement**							T (-)		Optional	
25 A/F						Mos					
Eff: 06-Apr-2020						Hrs					
(AVG MAN HRS: 32.5)						Ldg					
45-25-46 Rev 2	**Equipment/Furnishings - Cabin Window Shade Replacement**							T (A/R)		Optional	
25 A/F						Mos					
Eff: 14-Nov-2022						Hrs					
(AVG MAN HRS: 32.5)						Ldg					
45-25-47	**Equipment/Furnishings - Installation of Crew Seat Bump Stops**							RE (-)		Optional	
25 A/F						Mos					
Eff: 19-Nov-2018						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-25-5	**Equipment/Furnishings - Modification of Baggage Door Threshold**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 16-Feb-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-6	**Equipment/Furnishings - Modification of Trim Caps Above Emergency Exit Door**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-6 Rev 1	**Equipment/Furnishings - Modification of Trim Caps Above Emergency Exit Door**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-6 Rev 2	**Equipment/Furnishings - Modification of Trim Caps Above Emergency Exit Door**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-6 Rev 3	**Equipment/Furnishings - Modification of Trim Caps Above Emergency Exit Door**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 14-Oct-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-25-8	**Equipment and Furnishing - Installation of Fire Seal Baggage Compartment Accessory Kit**							RE (-)		Optional	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-25-8 Rev 1	**Equipment and Furnishing - Installation of Fire Seal Baggage Compartment Accessory Kit**							RE (-)		Optional	
25 A/F						Mos	29-Aug-2019				
Eff: 22-Jun-2009 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-25-9	**Equipment/Furnishings - Replacement of the Rudder Pedal Shroud Assembly, Brush Retainer Assemblies, and Brush Seals**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-9 Rev 1	**Equipment/Furnishings - Replacement of the Rudder Pedal Shroud Assembly, Brush Retainer Assemblies, and Brush Seals**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-9 Rev 2	**Equipment/Furnishings - Replacement of the Rudder Pedal Shroud Assembly, Brush Retainer Assemblies, and Brush Seals**							RE (-)		Recommended	
25 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-25-9 Rev 3	**Equipment/Furnishings - Replacement of the Rudder Pedal Shroud Assembly, Brush Retainer Assemblies, and Brush Seals**							RE (-)		Recommended	
25 A/F						Mos	14-Dec-2020				
Eff: 25-Feb-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
70-22-04	**Wood Electric - Circuit Breakers**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	13-Mar-2008				
Eff: 19-May-1971 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
74-08-09	**Lavatory Paper Or Linen Waste Receptacle Fire Prevention (Superseded By Faa Ad 1974-08-09 R3)**							RE (A/R)		Mandatory	
25 A/F						Mos	20-Oct-2009				
Complied With						Hrs					
						Ldg					
74-08-09 R1	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles (SUPERSEDED)**							RE (-)		Mandatory	
25 A/F						Mos	13-Mar-2008				
Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
74-08-09 R2	**Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles**							RE (-)		Mandatory	
25 A/F						Mos	02-May-2011				
Eff: 06-Aug-1974 Complied With						Hrs	1,947.3				
						Ldg	1,169				
74-08-09 R2 Paragraph (g)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."**							RE (-)		Mandatory	
25 A/F						Mos					
Eff: 06-Aug-1974						Hrs					
						Ldg					
74-08-09 R2 Paragraph (h)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.**							RE (-)		Mandatory	
25 A/F						Mos					
Eff: 06-Aug-1974						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
74-08-09 R2 Paragraph (i)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
					Ldg					
74-08-09 R2 Paragraph (j)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
					Ldg					
74-08-09 R2 Paragraph (k)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
					Ldg					
74-08-09 R3	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 28-Mar-2012					Hrs					
					Ldg					
74-08-09 R3 Paragraph (g)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
					Ldg					
74-08-09 R3 Paragraph (h)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
					Ldg					
74-08-09 R3 Paragraph (i)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
					Ldg					
74-08-09 R3 Paragraph (j)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative**						T (A/R)		Mandatory	
25 A/F					Mos					
Eff: 28-Mar-2012					Hrs					
(NOTE: Note 1 to paragraph (j) of this AD: This AD permits a lavatory door ashtray to be missing, although the FAA-approved Master Minimum Equipment List (MMEL) may not allow such provision. In any case, the provisions of this AD prevail.)					Ldg					
74-08-09 R3 Paragraph (k)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.**						RE		Mandatory	**≈22-Feb-2025**
25 A/F					Mos	09-Feb-2024				
Eff: 06-Aug-1974 Complied With					Hrs	5,253.5	1,000		6,253.5	978.7 Hrs
					Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
74-20-10	**Emergency Locator Transmitter**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	13-Mar-2008				
Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
75-25-25	**Equipment/Furnishings - Installation of Crew Seat Bump Stops**							RE (-)		Optional	
25 A/F						Mos					
Eff: 19-Nov-2018						Hrs					
(AVG MAN HRS: 1)						Ldg					
77-02-08	**Narco ELT-10 77 Batteries**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	13-Mar-2008				
Eff: 01-Feb-1977 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
90-09-08	**Crew Seats Inspection/Modification**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 29-May-1990 Not Applicable						Hrs	11.6				
						Ldg	11				
98-25-10	**Aircraft Belts, Inc - Seat Restraint Systems (Superseded by FAA AD 98-25-10 R1)**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	13-Mar-2008				
Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
98-25-10 R1	**Aircraft Belts, Inc - Seat Restraint Systems**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos	31-Mar-2008				
Eff: 14-Jan-2000 Not Applicable						Hrs	11.6				
Brand A:9990-1998-25-10 R1						Ldg	11				
A45-25-7	**Equipment/Furnishings - Passenger Seat Belt Inspection**							RE (-)		Alert	
25 A/F						Mos	13-Mar-2008				
Eff: 10-Jul-2001 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 1)						Ldg					
A45-25-7 Rev 1	**Equipment/Furnishings - Passenger Seat Belt Inspection**							RE (-)		Alert	
25 A/F						Mos	14-Dec-2020				
Eff: 24-Aug-2001 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 1)						Ldg	2,822				
AA2560000	**Underwater Locator Beacon - Clean beacon switch, perform functional test of beacon, and perform test of ULB battery**							RE (N/A)		TLMC 05-19-00	
25 A/F	FDR					Mos					
Unknown						Hrs					
Unknown						Ldg					
Ref:25-61-01 (ZONE: 320CL) (SOURCE: MM-104, MM-105) (NOTE: FDR Not Installed)											
AA2560000	**Underwater Locator Beacon - Clean beacon switch, perform functional test of beacon, and perform test of ULB battery.**							RE		TLMC 05-19-00	
25 A/F	CVR					Mos	09-Feb-2024	24		09-Feb-2026	1.7 Years
DK120						Hrs	5,253.5				
ST11030						Ldg	3,757				
Ref:25-61-01 (ZONE: 320CL) (SOURCE: MM-104, MM-105) (NOTE: In accordance with manufacturer's instruction. 24 month requirement I/A/W Dukane Models DK100/DK120/DK130/DK140, Document No. 03-TM-0037. Verify requirement if not one of these models.)											
AW 25-016	**Emergency Exit Door Interference**							RE (-)		Advisory Wire	
25 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 25-019	**Flame Propagation Far 25.856 Thermal/Acoustic Insulation Materials**							RE (-)		Advisory Wire	
25 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 25-020	**Cabin Seat Tracking Issues**							RE (-)		Advisory Wire	
25 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 25-021	**Possible Interference Between Rudder Pedal Mechanism and Rudder Pedal Shroud Assembly**							RE (-)		Advisory Wire	
25 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 25-022	**Update - Possible Interference Between Rudder Pedal Mechanism and Rudder Pedal Shroud Assembly**							RE (-)		Advisory Wire	
25 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
CF-2013-25	**Honeywell ASCa Inc - Emergency Locator Transmitter - Battery Wiring Installation Discrepancies**							RE (-)		Mandatory (Appliance AD)	
25 A/F						Mos					
Eff: 26-Aug-2013						Hrs					
						Ldg					
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	Copilot					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
L5340345						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	Lavatory					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
L5340348						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	No.1					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
L5340347						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	No.2					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
L5340349						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	No.3					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
L5340340						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	No.4					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
L5340342						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	No.5					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
L5340344						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	No.6					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
L5340343						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	No.7					Mos	12-May-2022	60	-/+14d	12-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
2						Ldg	3,061				
(ZONE: 200) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	No.8					Mos	15-May-2022	60	-/+14d	15-May-2027	3 Years (+14 Days)
63600-101						Hrs	4,972.1				
Unknown						Ldg	3,061				
(ZONE: 200) (UPDATE NOTE: C/W) (SOURCE: MM-104, MM-105)											
E2561002	**Perform Inspection of Life Vests.**							RE		TLMC 05-19-00	
25 A/F	Pilot					Mos	15-May-2022	60	-/+14d	10-May-2027	3 Years (+14 Days)
						Hrs	4,972.1				
(ZONE: 200) (Tol. Adjustment: -5d) (UPDATE NOTE: C/W) (SOURCE: MM-104, MM-105)						Ldg	3,061				
FAR 91.207	**Emergency Locator Transmitter (ELT) Inspection and Test per FAR 91.207 (d)**							RE		FAR91, FAR 91	
25 A/F						Mos	02-Jun-2023	12		02-Jun-2024	9 Days
453-5000-(366)						Hrs	5,166.1				
170-02018						Ldg	3,185				
N2561004	**Dorne and Margolin ELT Remote Control Battery (P/N U264-1).**							RE (N/A)		TLMC 05-19-01	
25 A/F						Mos	25-Jun-2021				
453-5000-(366)						Hrs	4,694.8				
170-02018						Ldg	2,882				
Alias1:25-62-04 (ZONE: 200) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 25-62-04.) (Effective on aircraft equipped with remote switches.) Note: The battery must also be replaced after total of known time with switch in ON position exceeds 4 hours. This inspection is effective on ELT-14 systems only.)											
NZ DCA/RAD/54B PARA (2) (ex)	**Replace The Elt G-Switches With P/N A1-12-0135 Per Acr Electronics (Artex) Service Notice 32, Dated 23 August 2013**							RE (-)		Mandatory	
25 A/F						Mos					
						Hrs					
						Ldg					
Q2510003	**Portable Hand-Held Fire Extinguisher - Perform ICC Hydrostatic Test.**							RE (N/A)		TLMC 05-19-00	
25 A/F	Aft Lavatory					Mos					
Unknown						Hrs					
Unknown						Ldg					
(ZONE: 230) (SOURCE: MM-104, MM-105) (NOTE: Not Installed)											
Q2510003	**Portable Hand-Held Fire Extinguisher - Perform ICC Hydrostatic Test.**							RE		TLMC 05-19-00	
25 A/F	Cabin					Yrs	10-Feb-2021	12	-/+14d	31-Jan-2032	7.7 Years (+14 Days)
C352TS						Hrs	4,610.5				
F-75060905						Ldg	2,822				
Hydrostatic Tested Date 31-Jan-2020 (ZONE: 230) (SOURCE: MM-104, MM-105) (NOTE: Portable hand-held fire extinguishers may either be hydrostatically tested or replaced at this time. Initial time count for testing of this item shall commence from the manufacturing date stamped on the item.)											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Q2510003	**Portable Hand-Held Fire Extinguisher - Perform ICC Hydrostatic Test.**							RE		TLMC 05-19-00	
25 A/F	Copilot					Yrs	10-Feb-2021	12	-/+14d	31-Jan-2033	8.7 Years (+14 Days)
A344T						Hrs	4,610.5				
G-18293780						Ldg	2,822				
Hydrostatic Tested Date 31-Jan-2021											
(ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: Portable hand-held fire extinguishers may either be hydrostatically tested or replaced at this time. Initial time count for testing of this item shall commence from the manufacturing date stamped on the item.)											
Q2510003	**Portable Hand-Held Fire Extinguisher - Perform ICC Hydrostatic Test.**							RE		TLMC 05-19-00	
25 A/F	Pilot					Yrs	10-Feb-2021	12	-/+14d	31-Jan-2033	8.7 Years (+14 Days)
A344T						Hrs	4,610.5				
G-18293776						Ldg	2,822				
Hydrostatic Tested Date 31-Jan-2021											
(ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: Portable hand-held fire extinguishers may either be hydrostatically tested or replaced at this time. Initial time count for testing of this item shall commence from the manufacturing date stamped on the item.)											
ST04030CH_1	**Inspect ATG Antenna Exterior Condition and Security in Conjunction With 1200 Check**							RE		STC	**≈04-Oct-2024**
25 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8	1,200		5,790.8	516 Hrs
						Ldg	2,807				
ST04030CH_2	**Check Fuselage Fairing Skin for Cracks, Indentations, and Loose or Missing Rivets Around the Antennas in Conjunction With 4800 Check**							RE		STC	**≈14-Oct-2027**
25 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
						Ldg	2,822				
ST04030CH_3	**Inspect System Installation Components Including Wire Bundles, Cables, Racks, and Connector Condition and Security in Conjunction With B2 Check**							RE		STC	**≈24-Oct-2024**
25 A/F						Mos	09-Feb-2024	24	-/+14d	07-Jan-2026	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
(Tol. Adjustment: -31d)						Ldg	3,757				
UPK-1	**Universal Precaution Kit (UPK)**							RE (N/A)			
25 A/F	No.01					Mos	19-Nov-2022				
Not Installed						Hrs	5,136.6				
Not Installed						Ldg	3,167				
(UPDATE NOTE: Universal precaution kit permanently removed from aircraft.)											
UPK-2	**Universal Precaution Kit (UPK)**							RE (N/A)			
25 A/F	No.02					Mos	19-Nov-2022				
Not Installed						Hrs	5,136.6				
Not Installed						Ldg	3,167				
(UPDATE NOTE: Universal precaution kit permanently removed from aircraft.)											
Y2510000	**Glareshield, Headliner, and Trim Strips - Perform visual inspection.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
25 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y2510001	**Crew Seats and Seat Belts - Perform visual inspection.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
25 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y2520000	**Cabin - Perform visual inspection of the following: a. Cabin seats and seat belts. Ensure that the seats function correctly and lock in place. b. Stowage cabinets. c. Headliner. d. Side panels. e. Rug.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
25 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Alias1:5-10-00 (ZONE: 200, 230) (SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y2540000	**All lavatory paper and linen waste receptacle access doors and disposal doors for proper operation, fit, sealing, latching, and legibility of placard.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
25 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	(ZONE: 200) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y2540009	**Avionics Equipment and Wiring located in Lavatory Area - Perform General Visual Inspection.**							RE		TLMC 05-15-00	**≈14-Oct-2027**
25 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	(9,410.5)	4,135.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 230) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
▼ 26 - FIRE PROTECTION											
	Anti-Ice Bleed Air Leak (A77) Detection Unit							RE (O/C)			
26 A/F						Mos	22-May-2013				
6626100000-003						Hrs					
2785						Ldg					
	APU Engine Fire Extinguisher Container							RE (O/C)			
26 A/F						Mos	27-Sep-2023				
51600-2	Overhauled		0			Hrs	5,197.3				
0448			0			Ldg	3,212				
	APU Fire Warning Horn							RE (O/C)			
26 A/F						Mos	10-Feb-2021				
M6904/2-1	New					Hrs	4,610.5				
2904						Ldg	2,822				
	Apu Fire/Overheat Detector							RE (O/C)			
26 A/F		0				Mos	13-Mar-2008				
10-1093	New	0				Hrs	0				
07-0314		0				Ldg	0				
	Bleed Air Leak (A76) Detection Unit							RE (O/C)			
26 A/F						Mos	22-May-2013				
6626100000-003						Hrs					
2581						Ldg					
	Bleed Air Leak (A78) Detection Unit							RE (O/C)			
26 A/F						Mos	21-May-2013				
6626100000-003						Hrs	2,835.5				
1804						Ldg	1,666				
	Engine Accessory Gearbox Fire Detect Element							RE (O/C)			
26 A/F	No.1					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Accessory Gearbox Fire Detect Element							RE (O/C)			
26 A/F	No.2					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Fire Extinguisher Container							RE (O/C)			
26 A/F	No.1					Mos	26-Mar-2023				
33100021-1	Overhauled					Hrs	5,150.6				
80327B1						Ldg	3,174				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Fire Extinguisher Container							RE (O/C)			
	26 A/F	No.2					Mos	26-Sep-2022				
	33100021-1	Overhauled		0			Hrs	5,094.2				
	41230B1			0			Ldg	3,136				
	(UPDATE NOTE: No.2 Engine Fire Extinguisher Container replaced with O/H assy iaw Lr45 AMM. Ref Fliteline WO 2022-712 for details.)											
		Engine Firewall Fire Detect Element							RE (O/C)			
	26 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Engine Firewall Fire Detect Element							RE (O/C)			
	26 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Engine Hot Section Fire Detect Element							RE (O/C)			
	26 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Engine Hot Section Fire Detect Element							RE (O/C)			
	26 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Fire Detect Control Unit							RE (O/C)			
	26 A/F	No.1	0				Mos	13-Mar-2008				
	877-01032	New	0				Hrs	0				
	0731-375		0				Ldg	0				
		Fire Detect Control Unit							RE (O/C)			
	26 A/F	No.2	0				Mos	13-Mar-2008				
	877-01032	New	0				Hrs	0				
	0734-380		0				Ldg	0				
		No.1 Engine Fire Extinguisher Cartridge							RE	Replacement Schedule, TLMC 05-19-01		
	26 A/F	Lower					Yrs	26-Mar-2023	15	-/+14d	01-Nov-2034	10.4 Years (+14 Days)
	30903859	Serviceable					Hrs	5,150.6				
	2138WE						Ldg	3,174				
	Manufactured Date 01-Nov-2019											
	Alias1:(Std)D2620007,(Std)D2620008, (EMP) 2620007, (EMP) 2620008 (ZONE: 200) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
		No.1 Engine Fire Extinguisher Cartridge							RE	Replacement Schedule, TLMC 05-19-01		
	26 A/F	Upper					Yrs	26-Mar-2023	15	-/+14d	01-Feb-2038	13.7 Years (+14 Days)
	M30903856	New					Hrs	5,150.6				
	02890						Ldg	3,174				
	Manufactured Date 01-Feb-2023											
	Alias1:(Std)D2620007,(Std)D2620008, (EMP) 2620007, (EMP) 2620008 (ZONE: 200) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No.2 Engine Fire Extinguisher Cartridge							RE	Replacement Schedule, TLMC 05-19-01		
26 A/F		Lower					Yrs	26-Sep-2022	15	-/+14d	01-Oct-2033	9.4 Years (+14 Days)
30903859		Overhauled	0	0	0		Hrs	5,094.2				
3003WH			0	0	0		Ldg	3,136				
Manufactured Date 01-Oct-2018												
Alias1:(Std)D2620007,(Std)D2620008, (EMP) 2620007, (EMP) 2620008 (ZONE: 200) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												
		No.2 Engine Fire Extinguisher Cartridge							RE	Replacement Schedule, TLMC 05-19-01		
26 A/F		Upper					Yrs	26-Sep-2022	15	-/+14d	01-Oct-2033	9.4 Years (+14 Days)
30903856		New	0				Hrs	5,094.2				
3105WF			0				Ldg	3,136				
Manufactured Date 01-Oct-2018												
Alias1:(Std)D2620007,(Std)D2620008, (EMP) 2620007, (EMP) 2620008 (ZONE: 200) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												
		Portable Hand-Held Fire Extinguisher							RE (Srv)			
26 A/F		Aft Lavatory					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Portable Hand-Held Fire Extinguisher							RE (Srv)			
26 A/F		Cabin					Mos	10-Feb-2021				
C352TS		New					Hrs	4,610.5				
F-75060905							Ldg	2,822				
		Portable Hand-Held Fire Extinguisher							RE (Srv)			
26 A/F		Copilot					Mos	10-Feb-2021				
A344T		New					Hrs	4,610.5				
G-18293780							Ldg	2,822				
		Portable Hand-Held Fire Extinguisher							RE (Srv)			
26 A/F		Pilot					Mos	10-Feb-2021				
A344T		New					Hrs	4,610.5				
G-18293776							Ldg	2,822				
		Sensing, Engine Hot Section Element							RE (O/C)			
26 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Sensing, Engine Hot Section Element							RE (O/C)			
26 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
2001-22-14		**Overland Aviation Services - Fire Extinguishing System Bottle Cartridges - Check/ Replace**							RE (-)	Mandatory (Appliance AD)		
26 A/F							Mos	31-Mar-2008				
Eff: 10-Dec-2001 Not Applicable							Hrs	11.6				
(AVG MAN HRS: 8)							Ldg	11				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2003-26-14	**Kidde Aerospace - Hand-Held Halon Fire Extinguishers Removal**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	31-Mar-2008				
Eff: 20-Feb-2004 Not Applicable						Hrs	11.6				
Brand A:9990-2003-26-14 (AVG MAN HRS: 1) (APX COST: 60) (NOTE: This AD affects aircraft that are certificated in any category and incorporate hand-held halon fire extinguishers with the following: (1) Part number (P/N) 898052; and (2) A serial number in the range of V-432001 through W-389653 inclusive that were manufactured sometime from 1995-2002)						Ldg	11				
2006-04-04	**Meggitt Model 602 - Smoke Detectors Replacement**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	31-Mar-2008				
Eff: 24-Mar-2006 Not Applicable						Hrs	11.6				
(NOTE: This AD applies to Meggitt Model 602 smoke detectors having any P/N 8930-( ))						Ldg	11				
2010-01-03	**Fire Fighting Enterprises Limited - Fire Protection**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	14-Dec-2020				
Eff: 20-Jan-2010 Not Applicable						Hrs	4,610.5				
Brand A:9990-2010-01-03						Ldg	2,822				
2010-04-16	**SICLI - Identification & Removal of Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	14-Dec-2020				
Eff: 08-Mar-2010 Not Applicable						Hrs					
Brand A:9990-2010-04-16 (NOTE: Within 90 days after the effective date of this AD, replace all Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers manufactured by SICLI, having P/N 1708337B4 and having any serial number listed in Table 1 of this AD, with serviceable fire extinguishers)						Ldg					
2010-04-16 Par. (g)	**SICLI - Identification & Removal of Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers**							RE (A/R)		Mandatory (Appliance AD)	
26 A/F						Mos	15-Mar-2010				
Not Applicable						Hrs					
						Ldg					
2010-04-16 Par. (H)	**Return Type H1-10 Air Halon 1211 (Bcf) Portable Fire Extinguishers Manufactured By Sicli The Affected Fire Extinguisher To Manufacturer**							RE (A/R)		Mandatory (Appliance AD)	
26 A/F						Mos	15-Mar-2010				
Not Applicable						Hrs					
						Ldg					
2010-21-19	**Fire protection**							RE (-)		Mandatory	
26 A/F						Mos	23-Nov-2010				
Eff: 18-Nov-2010 Complied With	SB 45-26-9					Hrs	1,639				
						Ldg	995				
2015-16-04	**Fire Protection**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos					
Eff: 15-Sep-2015						Hrs					
						Ldg					
2017-19-05 Par. (f)(2.1)	**Replace Cargo Compartment Smoke Detectors, Identified In Paragraph (C)(1), Specified In Figures 2 And 3**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos					
						Hrs					
						Ldg					
2017-19-05 Par. (f)(2.2)	**Replace Passenger, Cabin Or Any Other Location Smoke Detectors, Identified In Paragraph (C)(1), Specified In Figure 4**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos					
Eff: 31-Oct-2017						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2017-19-05 Par. 2(f)(1)	**Smoke Detection - Inspection**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos					
Eff: 31-Oct-2017						Hrs					
	(AVG MAN HRS: 0.2) (NOTE: APPLICABILITY: This AD also applies to those smoke detectors with P/Ns and S/Ns listed in Figure 1 to paragraph (c) of this AD; installed on, but not limited to, any airplane, certificated in any category, listed in paragraphs (c)(2)(i) or (ii) of this AD. NOTE: Refer to Siemens Service Information Letter (SIL) No. PMC-26-002, Revision No. 1, dated January 2016; or Siemens SIL No. PMC-26-003, Revision No. 2, dated February 2016.)					Ldg					
2017-19-05 Par. 2(f)(2),(3)	**Smoke Detection - Replacement**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos					
Eff: 31-Oct-2017						Hrs					
	(AVG MAN HRS: 0.8) (NOTE: APPLICABILITY: P/N PMC1102-02 [Cargo compartments] with Manufacturing date (month/year) - 122010 to 112011 inclusive; and P/N PMC3100-00 Detectors [Cargo compartments] with Manufacturing date (month/year) - 032011 to 012012 inclusive. NOTE: Refer to Siemens Service Information Letter (SIL) No. PMC-26-002, Revision No. 1, dated January 2016; or Siemens SIL No. PMC-26-003, Revision No. 2, dated February 2016. This AD also applies to those smoke detectors with P/Ns and S/Ns listed in Figure 1 to paragraph (c) of this AD.)					Ldg					
2019-21-09 PARA (I)	**After The Effective Date Of This Ad, Do Not Install An Aviointeriors Centaurus Economy Class Passenger Seat With A P/N Identified In Paragraph (C) Of This Ad Unless The Affected Seat Life Vest Pouch Assembly Has Been Inspected In Accordance With Paragraph (G)(1) Of This Ad**							RE (-)			
26 A/F						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2020-21-02	**Fire protection - Kidde Aerospace & Defense - Cargo Fire Extinguisher Halon Bottles**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	14-Dec-2020				
Eff: 19-Nov-2020 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2020-21-02 PARA (H) & (I)	**Do an Inspection to Determine the Part Number and Serial Number of the Cargo Fire Extinguisher Halon Bottles Installed in the Cargo Compartment and Replace With a Serviceable Part as Required**							RE (-)		Mandatory	
26 A/F						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2020-21-02 PARA (J)	**No Person May Install on Any Airplane an Affected Part as Identified in Paragraph (G)(3) of this AD Unless that Part has a Circled Letter "G" Stamped at a Distance 8 of Approximately One Inch From the Left Edge of the Placard, Indicating that the Cargo Fire Extinguisher Halon Bottle Has Been Tested and Refilled**							RE (-)		Mandatory	
26 A/F						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2021-22-07	**Fire Protection - Impaired Fire Extinguisher**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Days	03-Mar-2022				
Eff: 17-Nov-2021 Not Applicable						Hrs	4,883				
	(AVG MAN HRS: 1) (UPDATE NOTE: NOT APPLICALE BY P/N INSTALLED ON A/C. NO FURTHER ACTION REQ'D.)					Ldg	3,012				
2022-01-03	**Fire Bottle, Portable - HAFEX (Halon-free) Hand-Held P3HAFEX Fire Extinguisher**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	01-Mar-2023				
Eff: 07-Mar-2022 Not Applicable						Hrs	5,150				
	(UPDATE NOTE: AD 2022-01-03 is not applicable do to part number of installed fire extinguishers.) (NOTE: Required Actions: (1) Within 12 months after the effective date of this AD, remove each fire extinguisher identified in the introductory text of paragraph (c) from service.)					Ldg	3,173				
45-26-1	**Fire Protection - Replacement of Engine Fire Bottles**							RE (-)		Optional	
26 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-26-1 Rev 1	**Fire Protection - Replacement of Engine Fire Bottles**							RE (-)		Optional	
26 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-26-1 Rev 2	**Fire Protection - Replacement of Engine Fire Bottles**							RE (-)		Optional	
26 A/F						Mos	29-Aug-2019				
Eff: 14-Apr-2000 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-26-10	**Fire Protection - Inspection/Modification of the APU Fire Extinguisher Squib Wiring**							RE (-)		Recommended	
26 A/F						Mos	03-Apr-2011				
Eff: 26-Jan-2011 Complied With	IAW THE SB					Hrs	1,919.3				
(AVG MAN HRS: 4)						Ldg	1,148				
45-26-10 Rev 1	**Fire Protection - Inspection/Modification of the APU Fire Extinguisher Squib Wiring**							RE (-)		Recommended	
26 A/F						Mos	06-Jan-2012				
Eff: 07-Nov-2011 Complied With						Hrs	2,290.3				
(AVG MAN HRS: 4)						Ldg	1,369				
45-26-12	**Fire Protection - Relocation Of The Portable Fire Extinguisher**							RE (-)		Optional	
26 A/F						Mos					
						Hrs					
						Ldg					
45-26-12 Rev 1	**Fire Protection - Relocation Of The Portable Fire Extinguisher**							T (A/R)		Optional	
26 A/F						Mos					
Eff: 08-Oct-2012						Hrs					
						Ldg					
45-26-13	**Fire Protection - Engine Fire Extinguisher Container Label Installation**							RE (-)		Recommended	
26 A/F						Mos	10-Aug-2012				
Eff: 18-Jun-2012 Complied With						Hrs	2,566.9				
(AVG MAN HRS: 5)						Ldg	1,526				
45-26-2	**Fire Protection - Inspection/Modification of the APU Bleed Air (E25) and Anti-ice (E27) Detection Elements**							RE (-)		Recommended	
26 A/F						Mos	14-Dec-2020				
Eff: 21-Jul-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-26-3	**Fire Protection - Modification of the Engine Fire Detection System**							RE (-)		Recommended	
26 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-26-3 Rev 1	**Fire Protection - Modification of the Engine Fire Detection System**							RE (-)		Recommended	
26 A/F						Mos	14-Dec-2020				
Eff: 20-Aug-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-26-4	**Fire Protection - Wire Modification of the APU Fire Detection System**							RE (-)		Recommended	
26 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-26-4 Rev 1	**Fire Protection - Wire Modification of the APU Fire Detection System**							RE (-)		Recommended	
26 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-26-4 Rev 2	**Fire Protection - Wire Modification of the APU Fire Detection System**							RE (-)		Recommended	
26 A/F						Mos	14-Dec-2020				
Eff: 21-Jul-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-26-5	**Fire Protection - Inspection/Replacement of the APU Fire Extinguisher Container Discharge Outlet Valve**							RE (-)		Recommended	
26 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-26-5 Rev 1	**Fire Protection - Inspection/Replacement of the APU Fire Extinguisher Container Discharge Outlet Valve**							RE (-)		Recommended	
26 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-26-5 Rev 2	**Fire Protection - Inspection/Replacement of the APU Fire Extinguisher Container Discharge Outlet Valve**							RE (-)		Recommended	
26 A/F						Mos	14-Dec-2020				
Eff: 24-Jul-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-26-6	**Fire Detect - Bleed Air and Anti-Ice Leak Detect Element Spacing and Standoff**							RE (-)		Optional	
26 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-26-6 Rev 1	**Fire Detect - Bleed Air and Anti-Ice Leak Detect Element Spacing and Standoff**							RE (-)		Optional	
26 A/F						Mos					
						Hrs					
						Ldg					
45-26-6 Rev 2	**Fire Detect - Bleed Air and Anti-Ice Leak Detect Element Spacing and Standoff**							T (A/R)		Optional	
26 A/F						Mos					
Eff: 12-May-2008						Hrs					
						Ldg					
45-26-7	**Fire Protection - Inspection/Replacement of Bleed Leak Detect Units**							RE (-)		Recommended	
26 A/F						Mos	14-Dec-2020				
Eff: 14-Jan-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-26-8	**Fire Protection - Inspection/Replacement of the Engine Fire Detect Elements**							RE (-)		Recommended	
26 A/F						Mos	14-Dec-2020				
Eff: 05-May-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-26-9	**Fire Protection - Replacement of Engine Fire Extinguisher Discharge Tubes**							RE (-)		Recommended	
26 A/F						Mos	28-Jan-2010				
Complied With						Hrs	1,172.9				
						Ldg	723				
45-26-9 Rev 1	**Fire Protection - Replacement of Engine Fire Extinguisher Discharge Tubes**							RE (-)		Recommended	
26 A/F						Mos	28-Jan-2010				
Complied With						Hrs	1,172.9				
						Ldg	723				
45-26-9 Rev 2	**Fire Protection - Replacement of Engine Fire Extinguisher Discharge Tubes**							RE (-)		Recommended	
26 A/F						Mos	28-Jan-2010				
Eff: 04-May-2009 Complied With						Hrs	1,172.9				
						Ldg	723				
99-04-10	**Prevent Fire in the Passenger Compartment Resulting from Failure of the Fluorescent Light Ballast of the Cabin Sidewall**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	31-Mar-2008				
Eff: 18-Mar-1999 Not Applicable						Hrs	11.6				
						Ldg	11				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 26-002	**APU Fire Extguishing System Check**							RE (-)		Advisory Wire	
26 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 26-003	**Wiring Behind The Pilot'S and Co-Pilot'S Circuit Breaker Panels**							RE (-)		Advisory Wire	
26 A/F						Mos	21-Sep-2009				
Complied With						Hrs	959.2				
						Ldg	607				
D-2012-237 R01 Par.(E)	**Fire Protection in Lavatories Inspections**							T (A/R)		Mandatory (Appliance AD)	
26 A/F						Mos					
Eff: 19-Apr-2013						Hrs					
						Ldg					
D2620007	**No.1 Engine Fire Extinguisher Cartridge (In Service Life Limit)**							RE		TLMC 05-19-01	
26 A/F	Lower					Yrs	26-Mar-2023	10	-/+14d	26-Mar-2033	8.8 Years (+14 Days)
30903859						Hrs	5,150.6				
2138WE						Ldg	3,174				
(ZONE: 320/ 840AR) (SOURCE: MM-104, MM-105) (NOTE: Note: Replacement time interval shall begin at the time of installation in the aircraft. Check date stamped on cartridge. The maximum service life shall not exceed 10 years. The maximum storage and installed service life shall not exceed 15 years.)											
D2620007	**No.1 Engine Fire Extinguisher Cartridge (In Service Life Limit)**							RE		TLMC 05-19-01	
26 A/F	Upper					Yrs	26-Mar-2023	10	-/+14d	26-Mar-2033	8.8 Years (+14 Days)
M30903856						Hrs	5,150.6				
02890						Ldg	3,174				
(ZONE: 320/ 840AR) (SOURCE: MM-104, MM-105) (NOTE: Note: Replacement time interval shall begin at the time of installation in the aircraft. Check date stamped on cartridge. The maximum service life shall not exceed 10 years. The maximum storage and installed service life shall not exceed 15 years.)											
D2620007	**No.2 Engine Fire Extinguisher Cartridge (In Service Life Limit)**							RE		TLMC 05-19-01	
26 A/F	Lower					Yrs	26-Sep-2022	10	-/+14d	26-Sep-2032	8.3 Years (+14 Days)
30903859						Hrs	5,094.2				
3003WH						Ldg	3,136				
(ZONE: 320/ 840AR) (SOURCE: MM-104, MM-105) (NOTE: Note: Replacement time interval shall begin at the time of installation in the aircraft. Check date stamped on cartridge. The maximum service life shall not exceed 10 years. The maximum storage and installed service life shall not exceed 15 years.)											
D2620007	**No.2 Engine Fire Extinguisher Cartridge (In Service Life Limit)**							RE		TLMC 05-19-01	
26 A/F	Upper					Yrs	26-Sep-2022	10	-/+14d	26-Sep-2032	8.3 Years (+14 Days)
30903856						Hrs	5,094.2				
3105WF						Ldg	3,136				
(ZONE: 320/ 840AR) (SOURCE: MM-104, MM-105) (NOTE: Note: Replacement time interval shall begin at the time of installation in the aircraft. Check date stamped on cartridge. The maximum service life shall not exceed 10 years. The maximum storage and installed service life shall not exceed 15 years.)											
D2620008	**No.1 Engine Fire Extinguisher Cartridge (In Service Life Limit)**							RE (N/A)		TLMC 05-19-01	
26 A/F	Lower					Mos					
30903859						Hrs					
2138WE						Ldg					
(ZONE: 320/ 840AR) (SOURCE: MM-104) (NOTE: Note: Replacement time interval shall begin at the time of installation in the aircraft. Check date stamped on cartridge. The maximum service life shall not exceed 4 years. The maximum storage and installed service life shall not exceed 6 years.)											
D2620008	**No.1 Engine Fire Extinguisher Cartridge (In Service Life Limit)**							RE (N/A)		TLMC 05-19-01	
26 A/F	Upper					Mos					
M30903856						Hrs					
02890						Ldg					
(ZONE: 320/ 840AR) (SOURCE: MM-104)											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D2620008	**No.2 Engine Fire Extinguisher Cartridge (In Service Life Limit)**							RE (N/A)		TLMC 05-19-01	
26 A/F	Lower					Mos	26-Sep-2022				
30903859						Hrs	5,094.2				
3003WH						Ldg	3,136				
	(ZONE: 320/ 840AR) (SOURCE: MM-104) (NOTE: Note: Replacement time interval shall begin at the time of installation in the aircraft. Check date stamped on cartridge. The maximum service life shall not exceed 4 years. The maximum storage and installed service life shall not exceed 6 years.)										
D2620008	**No.2 Engine Fire Extinguisher Cartridge (In Service Life Limit)**							RE (N/A)		TLMC 05-19-01	
26 A/F	Upper					Mos	26-Sep-2022				
30903856						Hrs	5,094.2				
3105WF						Ldg	3,136				
	(ZONE: 320/ 840AR) (SOURCE: MM-104) (NOTE: Note: Replacement time interval shall begin at the time of installation in the aircraft. Check date stamped on cartridge. The maximum service life shall not exceed 4 years. The maximum storage and installed service life shall not exceed 6 years.)										
J2620000	**** Engine Fire Extinguishing System Fire Switch - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
26 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	(9,410.5)	4,135.7 Hrs (+25)
	Alias1:26-21-01 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 26-21-00.))					Ldg	2,822				
O2610001	**(Left) Hot Section Fire Detector Element - Perform Visual Inspection.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
26 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	3,000	+100	6,000	725.2 Hrs (+100)
	Ref:5-10-00 (ZONE: 410) (Manual Adjustment: -11.7 Hrs) (SOURCE: MM-104, MM-105) (NOTE: During Major Engine Inspection/Unscheduled Engine Change.)					Ldg	1,768				
O2610001	**(Right) Hot Section Fire Detector Element - Perform Visual Inspection.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
26 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	3,000	+100	6,000	725.2 Hrs (+100)
	Ref:5-10-00 (AVG MAN HRS: 410) (Manual Adjustment: -11.7 Hrs) (SOURCE: MM-104, MM-105) (NOTE: During Major Engine Inspection/Unscheduled Engine Change.)					Ldg	1,768				
Q2620006	**Engine Fire Extinguisher Container - Perform ICC Hydrostatic Test.**							RE		TLMC 05-19-00	
26 A/F	No.1					Yrs	26-Mar-2023	5	-/+14d	22-Mar-2028	3.8 Years (+14 Days)
33100021-1						Hrs	5,150.6				
80327B1						Ldg	3,174				
	Hydrostatic Tested Date 22-Mar-2023										
	(ZONE: 840AR) (SOURCE: MM-104, MM-105) (NOTE: Note: Initial time count for testing of this item shall commence from the manufacturing date stamped on the item.)										
Q2620006	**Engine Fire Extinguisher Container - Perform ICC Hydrostatic Test.**							RE		TLMC 05-19-00	
26 A/F	No.2					Yrs	26-Sep-2022	5	-/+14d	27-Jul-2027	3.2 Years (+14 Days)
33100021-1						Hrs	5,094.2				
41230B1						Ldg	3,136				
	Hydrostatic Tested Date 27-Jul-2022										
	(ZONE: 840AR) (UPDATE NOTE: No.2 Engine Fire Extinguisher Container replaced with Hydro tested O/H containers iaw Lr45 AMM.) (SOURCE: MM-104, MM-105) (NOTE: Note: Initial time count for testing of this item shall commence from the manufacturing date stamped on the item.)										
Q4900014	**APU Engine Fire Extinguisher Container - Perform ICC Hydrostatic Test.**							RE		TLMC 05-19-00	
26 A/F						Yrs	27-Sep-2023	5	-/+14d	01-Sep-2028	4.3 Years (+14 Days)
51600-2						Hrs	5,197.3				
0448						Ldg	3,212				
	Hydrostatic Tested Date 01-Sep-2023										
	(ZONE: 310JL, 310QR) (SOURCE: MM-104) (NOTE: Note: Time count for testing of this item shall commence from the manufacturing date stamped on the item.)										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
T2620001	**** Firewall Shutoff Valves - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-13-01, Ch.5 Interval		**≈24-Apr-2025**
26 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:26-21-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 26-21-00.))					Ldg	3,757				
Y2610000	**Firewall and Accessory Compartment Fire Detector Elements - Perform visual inspection.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
26 A/F	05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 450/460) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2620002	**Engine Fire Extinguisher Containers - Perform visual inspection. Check containers for condition, cartridges and cartridge wiring for security and condition, container pressure gauge for proper pressures, and plumbing for security and condition.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
26 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 320/ 840AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y2620005	**Engine Fire Extinguishing System - Perform Operational Check.**							RE		TLMC 05-14-01	**≈12-Oct-2025**
26 A/F	05-14-01					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:26-21-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 26-21-00.))					Ldg	2,822				
Y2620009	**Inspect portable hand held fire extinguishers for condition and date of manufacture. Check operating pressure and weight per maintenance instructions on fire extinguisher bottle.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
26 A/F Unknown	Aft Lavatory05-11-01					Mos	09-Feb-2024	12	-/+14d	09-Feb-2025	8.7 Months (+14 Days)
Unknown						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
Weighed Date 09-Feb-2024						Ldg	3,757				
(ZONE: 230) (SOURCE: MM-104, MM-105)											
Y2620009	**Inspect portable hand held fire extinguishers for condition and date of manufacture. Check operating pressure and weight per maintenance instructions on fire extinguisher bottle.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
26 A/F C352TS	Cabin05-11-01					Mos	09-Feb-2024	12	-/+14d	25-Jan-2025	8.2 Months (+14 Days)
F-75060905						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
Weighed Date 25-Jan-2024						Ldg	3,757				
(ZONE: 230) (SOURCE: MM-104, MM-105)											
Y2620009	**Inspect portable hand held fire extinguishers for condition and date of manufacture. Check operating pressure and weight per maintenance instructions on fire extinguisher bottle.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
26 A/F A344T	Copilot05-11-01					Mos	09-Feb-2024	12	-/+14d	25-Jan-2025	8.2 Months (+14 Days)
G-18293780						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
Weighed Date 25-Jan-2024						Ldg	3,757				
(ZONE: 220) (SOURCE: MM-104, MM-105)											
Y2620009	**Inspect portable hand held fire extinguishers for condition and date of manufacture. Check operating pressure and weight per maintenance instructions on fire extinguisher bottle.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
26 A/F A344T	Pilot05-11-01					Mos	09-Feb-2024	12	-/+14d	25-Jan-2025	8.2 Months (+14 Days)
G-18293776						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
Weighed Date 25-Jan-2024						Ldg	3,757				
(ZONE: 220) (SOURCE: MM-104, MM-105)											
Z2620021	**Engine Fire Extinguisher Container Plumbing - Perform Detailed Inspection**							RE		TLMC 05-11-02	**≈24-Jul-2024**
26 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Ref:26-21-00 (ZONE: 300) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Z2620021	**No. 2 Engine Fire Extinguisher Container Plumbing - Perform Detailed Inspection**							RE			**≈24-Jul-2024**
26 A/F	05-11-02					Mos	09-Feb-2024	12		(09-Feb-2025)	8.7 Months (+14 Days)
						Hrs	5,253.5	300		(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
▼ 27 - FLIGHT CONTROLS											
	*** Flap Actuator Joint**							RE (O/C)	TLMC 04-11-00, TLMC 05-19-01		
27 A/F	Left Inboard	0				Mos	01-Mar-2013				
159174-1	New	0				Hrs	2,753.9				
Unknown		0				Ldg	1,625				
Alias1:27-50-06, (Std)W2750055, (EMP)2750055 (ZONE: 540/640) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 27-50-06.))											
	*** Flap Actuator Joint**							RE (O/C)	TLMC 04-11-00, TLMC 05-19-01		
27 A/F	Left Outboard	0				Mos	01-Mar-2013				
159174-1	New	0				Hrs	2,753.9				
Unknown		0				Ldg	1,625				
Alias1:27-50-06, (Std)W2750055, (EMP)2750055 (ZONE: 540/640) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 27-50-06.))											
	*** Flap Actuator Joint**							RE (O/C)	TLMC 04-11-00, TLMC 05-19-01		
27 A/F	Right Inboard	0				Mos	01-Mar-2013				
159174-1	New	0				Hrs	2,753.9				
Unknown		0				Ldg	1,625				
Alias1:27-50-06, (Std)W2750055, (EMP)2750055 (ZONE: 540/640) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 27-50-06.))											
	*** Flap Actuator Joint**							RE (O/C)	TLMC 04-11-00, TLMC 05-19-01		
27 A/F	Right Outboard	0				Mos	01-Mar-2013				
159174-1	New	0				Hrs	2,753.9				
Unknown		0				Ldg	1,625				
Alias1:27-50-06, (Std)W2750055, (EMP)2750055 (ZONE: 540/640) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 27-50-06.))											
	Aft Aileron Control Cable							RE (O/C)			
27 A/F	Left Outboard	0				Mos	13-Mar-2008				
4527103079-009	New	0				Hrs	0				
1072486-23		0				Ldg	0				
	Aft Aileron Control Cable							RE (O/C)			
27 A/F	Right Outboard	0				Mos	13-Mar-2008				
4527103079-009	New	0				Hrs	0				
1072486-15		0				Ldg	0				
	Aileron Control Cable							RE (O/C)			
27 A/F	Left Inboard	0				Mos	13-Mar-2008				
4527103077-011	New	0				Hrs	0				
1072483-6		0				Ldg	0				
	Aileron Control Cable							RE (O/C)			
27 A/F	Right Inboard	0				Mos	13-Mar-2008				
4527103076-015	New	0				Hrs	0				
1064601-5		0				Ldg	0				
	Aileron Control System Aft Cable Assembly							RE (O/C)			
27 A/F						Mos	02-Jan-2015				
7627102001-001	New	0				Hrs	3,355.7				
Unknown		0				Ldg	1,959				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Aileron Control System Cable							RE (O/C)			
	27 A/F	Left	0				Mos	02-Jan-2015				
	7627102004-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Aileron Control System Cable							RE (O/C)			
	27 A/F	Right					Mos	02-Jan-2015				
	7627102005-009	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Aileron Control System Crossover Cable							RE (O/C)			
	27 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Aileron Control System Crossover Cable							RE (O/C)			
	27 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Aileron Trim Tab Actuator							RE (O/C)			
	27 A/F		0				Mos	13-Mar-2008				
	4323338A	New	0				Hrs	0				
	0512		0				Ldg	0				
		Angle Of Attack (AOA) Indicator							RE (O/C)			
	27 A/F	Copilot	0				Mos	13-Mar-2008				
	C-38805-1	New	0				Hrs	0				
	83360		0				Ldg	0				
		Angle Of Attack (AOA) Indicator							RE (O/C)			
	27 A/F	Pilot	0				Mos	13-Mar-2008				
	C-38805-1	New	0				Hrs	0				
	83338		0				Ldg	0				
		Angle Of Attack (AOA) Sensor							RE (O/C)			
	27 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Angle Of Attack (AOA) Sensor							RE (O/C)			
	27 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Angle Of Attack (AOA) Transmitter							RE (O/C)			
	27 A/F	Left	0				Mos	13-Mar-2008				
	C-38817-1	New	0				Hrs	0				
	1207		0				Ldg	0				
		Angle Of Attack (AOA) Transmitter							RE (O/C)			
	27 A/F	Right	0				Mos	13-Mar-2008				
	C-38817-1	New	0				Hrs	0				
	1211		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Angle Of Attack (AOA) Vane							RE (O/C)			
	27 A/F	Left	0				Mos	13-Mar-2008				
	1714-115	New	0				Hrs	0				
	3534		0				Ldg	0				
		Angle Of Attack (AOA) Vane							RE (O/C)			
	27 A/F	Right	0				Mos	13-Mar-2008				
	1714-115	New	0				Hrs	0				
	3537		0				Ldg	0				
		Center Flap Track Assembly							RE (O/C)			
	27 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Center Flap Track Assembly							RE (O/C)			
	27 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Control Wheel RVDT							RE (O/C)			
	27 A/F		0				Mos	13-Mar-2008				
	3G4-211A	New	0				Hrs	0				
	0513/0734		0				Ldg	0				
		Disconnect Assem, Elevator Aft Change							RE (O/C)			
	27 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Elevator Disconnect (A83) Current Limiter							RE (O/C)			
	27 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Elevator Disconnect Actuator							RE (O/C)			
	27 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Elevator Override (L45) Actuator							RE (O/C)			
	27 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Flap Actuator							RE (O/C)			
	27 A/F	Left Inboard	0				Mos	28-Feb-2013				
	6627503000-031	New	0				Hrs	2,753.9				
	2033		0				Ldg	1,625				
		Flap Actuator							RE (O/C)			
	27 A/F	Left Outboard	0				Mos	27-Feb-2013				
	6627503000-033	New	0				Hrs	2,753.9				
	1430		0				Ldg	1,625				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Flap Actuator							RE (O/C)			
27 A/F	Right Inboard	0				Mos	27-Feb-2013				
6627503000-031	New	0				Hrs	2,753.9				
1347		0				Ldg	1,625				
	Flap Actuator							RE (O/C)			
27 A/F	Right Outboard	0				Mos	27-Feb-2013				
6627503000-033	New	0				Hrs	2,753.9				
1311		0				Ldg	1,625				
	Flap Actuator Joint							RE (O/C)			
27 A/F	Left Inboard	0				Mos	13-Mar-2008				
159174-1	New	0				Hrs	0				
Unknown		0				Ldg	0				
	Flap Actuator Joint							RE (O/C)			
27 A/F	Left Outboard	0				Mos	13-Mar-2008				
159174-1	New	0				Hrs	0				
Unknown		0				Ldg	0				
	Flap Actuator Joint							RE (O/C)			
27 A/F	Right Inboard	0				Mos	13-Mar-2008				
159174-1	New	0				Hrs	0				
Unknown		0				Ldg	0				
	Flap Actuator Joint							RE (O/C)			
27 A/F	Right Outboard	0				Mos	13-Mar-2008				
159174-1	New	0				Hrs	0				
Unknown		0				Ldg	0				
	Flap Control Module							RE (O/C)			
27 A/F		0				Mos	13-Mar-2008				
69013-17	New	0				Hrs	0				
498		0				Ldg	0				
	Flap Control Unit							RE (O/C)			
27 A/F				0		Mos	22-Jan-2010				
C144486-3-003	Repaired			0		Hrs	1,165.2				
1282				0		Ldg	719				
	Flap Drive Power Unit							RE (O/C)			
27 A/F				0		Mos	12-Sep-2011				
6627503000-029	Repaired			0		Hrs	2,154.2				
1198X				0		Ldg	1,294				
	Flap Drive RVDT							RE (O/C)			
27 A/F	Left	0				Mos	13-Mar-2008				
C144489-2	New	0				Hrs	0				
A0989		0				Ldg	0				
	Flap Drive RVDT							RE (O/C)			
27 A/F	Right	0				Mos	13-Mar-2008				
C144489-2	New	0				Hrs	0				
A0892		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Flap Hydraulic Motor							RE (O/C)			
	27 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Flap Position Indicator							RE (O/C)			
	27 A/F		0				Mos	13-Mar-2008				
	C145159-1	New	0				Hrs	0				
	1579		0				Ldg	0				
		Forward Aileron Control Cable							RE (O/C)			
	27 A/F	Left Outboard	0				Mos	13-Mar-2008				
	4527103078-009	New	0				Hrs	0				
	1072485-7		0				Ldg	0				
		Forward Aileron Control Cable							RE (O/C)			
	27 A/F	Right Outboard	0				Mos	13-Mar-2008				
	4527103078-009	New	0				Hrs	0				
	1072485-9		0				Ldg	0				
		Forward Elevator Control System Cable							RE (O/C)			
	27 A/F	Copilot					Mos	02-Jan-2015				
	7627302022-009	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Forward Elevator Control System Cable							RE (O/C)			
	27 A/F	Pilot					Mos	02-Jan-2015				
	7627302021-009	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Forward Interface Unit							RE (O/C)			
	27 A/F						Mos	04-May-2021				
	4527408503-027	Repaired					Hrs	4,667.6				
	A00805356-01						Ldg	2,867				
		Horizontal Stab Actuator Control Box Assembly							RE (O/C)			
	27 A/F					1	Mos	21-Nov-2021				
	6627401000-003	Repaired				0	Hrs	4,818.2				
	D0191					0	Ldg	2,969				
	(UPDATE NOTE: control box replaced with repaired serviceable assy. ops checks c/o on Prim and Sec trim. NFF. All work C/O IAW AMM 27-40-00. S/N off:D-0507)											
		Horizontal Stabilizer Actuator							RE (O/C)			
	27 A/F			0			Mos	12-Mar-2018				
	6627401000-009	Overhauled	5,764.9	0			Hrs	4,155.2				
	B0062			0			Ldg	2,448				
	(ZONE: 330AC /AR/BC/CC/CL/XL/WR/YL/XR)											
		IB Flap Track Assembly							RE (O/C)			
	27 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		IB Flap Track Assembly							RE (O/C)			
	27 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Rudder Control System Cable							RE (O/C)			
	27 A/F	Aft - Lower					Mos	02-Jan-2015				
	7627202005-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Left Rudder Control System Cable							RE (O/C)			
	27 A/F	Aft - Upper					Mos	02-Jan-2015				
	7627202003-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Lower Elevator Control System Cable							RE (O/C)			
	27 A/F	Aft - Left					Mos	02-Jan-2015				
	7627302026-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Lower Elevator Control System Cable							RE (O/C)			
	27 A/F	Aft - Right					Mos	02-Jan-2015				
	7627302025-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		OB Flap Track Assembly							RE (O/C)			
	27 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		OB Flap Track Assembly							RE (O/C)			
	27 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		PC Board Assembly, Wheel Master Disconnect Replace							RE (O/C)			
	27 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Right Rudder Control System Cable							RE (O/C)			
	27 A/F	Aft - Lower					Mos	02-Jan-2015				
	7627202006-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Right Rudder Control System Cable							RE (O/C)			
	27 A/F	Aft - Upper					Mos	02-Jan-2015				
	7627202004-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Rudder Control System Cable							RE (O/C)			
	27 A/F	Fwd - Lower					Mos	02-Jan-2015				
	7627202002-005	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Rudder Control System Cable							RE (O/C)			
27 A/F	Fwd - Upper					Mos	02-Jan-2015				
7627202001-005	New	0				Hrs	3,355.7				
Unknown		0				Ldg	1,959				
	Rudder Pedal Adjust Actuator							RE (O/C)			
27 A/F	Copilot	0				Mos	13-Mar-2008				
4389596	New	0				Hrs	0				
1110		0				Ldg	0				
	Rudder Pedal Adjust Actuator							RE (O/C)			
27 A/F	Pilot	0				Mos	13-Mar-2008				
4389596	New	0				Hrs	0				
1098		0				Ldg	0				
	Rudder Trim Tab Actuator							RE (O/C)			
27 A/F		0				Mos	13-Mar-2008				
4323322	New	0				Hrs	0				
0525		0				Ldg	0				
	Shaft, Flap Drive							RE (O/C)			
27 A/F	Left Inboard					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Shaft, Flap Drive							RE (O/C)			
27 A/F	Left Outboard					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Shaft, Flap Drive							RE (O/C)			
27 A/F	Right Inboard					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Shaft, Flap Drive							RE (O/C)			
27 A/F	Right Outboard					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Spoiler Actuator							RE (O/C)			
27 A/F	Left					Mos	10-Feb-2021				
6627602001-009	Serviceable					Hrs	4,610.5				
AAA129P455						Ldg	2,822				
	Spoiler Actuator							RE (O/C)			
27 A/F	Right					Mos	10-Feb-2021				
6627602001-009	Serviceable					Hrs	4,610.5				
AAA083P455						Ldg	2,822				
	Spoiler Control Module							RE (O/C)			
27 A/F					58	Mos	13-Jul-2017				
69014-9						Hrs	3,874.5				
259						Ldg	2,279				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Spoiler Low Pressure Assembly (L41) Switch							RE (O/C)			
27 A/F						Mos	10-Feb-2021				
6629101004-003	New					Hrs	4,610.5				
0780						Ldg	2,822				
	Spoiler RVDT							RE (O/C)			
27 A/F	Left					Mos	09-Sep-2009				
3A2-249A						Hrs	945.9				
A0250						Ldg	599				
	Spoiler RVDT							RE (O/C)			
27 A/F	Right		34			Mos	01-Sep-2017				
3A2249A						Hrs	3,914.5				
A0260						Ldg	2,310				
	Spoiler Shutoff Valve							RE (O/C)			
27 A/F		0				Mos	13-Mar-2008				
100291000-003	New	0				Hrs	0				
0219TK		0				Ldg	0				
	Spoileron Computer							RE (O/C)			
27 A/F						Mos	25-Aug-2017				
402800-07-01						Hrs					
00860						Ldg					
	Spoileron Controller Resistor Box Assembly							RE (O/C)			
27 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Stall Warning Computer							RE (O/C)			
27 A/F		0				Mos	13-Mar-2008				
C-38806-2	New	0				Hrs	0				
615		0				Ldg	0				
	Stick Shaker							RE (O/C)			
27 A/F	Copilot	0				Mos	13-Mar-2008				
72672-1	New	0				Hrs	0				
1745		0				Ldg	0				
	Stick Shaker							RE (O/C)			
27 A/F	Pilot	0				Mos	13-Mar-2008				
72672-1	New	0				Hrs	0				
1739		0				Ldg	0				
	Trim Switch Panel Assy							RE (O/C)			
27 A/F						Mos	17-Apr-2012				
4522208501-018	Repaired				0	Hrs	2,413.2				
MRP644697					0	Ldg	1,441				
	Trim, Toggle, And Push Button Switch							RE (O/C)			
27 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Trim-In-Motion Detector							RE (O/C)			
	27 A/F		0				Mos	13-Mar-2008				
	1625-1-1	New	0				Hrs	0				
	207350136		0				Ldg	0				
		Upper Elevator Control System Cable							RE (O/C)			
	27 A/F	Aft - Left					Mos	02-Jan-2015				
	7627302024-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
		Upper Elevator Control System Cable							RE (O/C)			
	27 A/F	Aft - Right					Mos	02-Jan-2015				
	7627302023-001	New	0				Hrs	3,355.7				
	Unknown		0				Ldg	1,959				
2000-08-13		**Crane Hydro--Aire Brake Control Unit**							RE (-)		Mandatory	
	27 A/F						Mos	11-Feb-2010				
	Eff: 15-May-2000 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
							Ldg	739				
2003-06-51		**Horizontal stabilizer actuator**							RE (-)		Mandatory	
	27 A/F						Mos	11-Feb-2010				
	Eff: 11-Apr-2003 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
							Ldg	739				
2003-16-19		**Horizontal Stabilizer Actuator Assembly (HSAA)**							RE (-)		Mandatory	
	27 A/F						Mos	13-Mar-2008				
	Eff: 13-Aug-2003 Not Applicable						Hrs	0				
							Ldg	0				
2010-06-13		**Flight Controls**							RE (-)		Mandatory	
	27 A/F						Mos	01-Mar-2013				
	Eff: 01-Apr-2010 Complied With						Hrs	2,753.9				
							Ldg	1,625				
2010-06-13 (I)		**Replace To Detect And Correct Cracked And Missing Ballscrew Assembly Sleeves**							RE (-)			
	27 A/F						Mos	01-Mar-2013				
	Complied With						Hrs	2,753.9				
							Ldg	1,625				
2010-06-13 Paragraph (g)		**Flight Controls - General Visual Inspection for cracked or missing ballscrew assembly sleeves of the flap actuator**							RE (-)		Mandatory	
	27 A/F						Mos	01-Mar-2013				
	Eff: 01-Apr-2010 Complied With						Hrs	2,753.9				
							Ldg	1,625				
2010-06-13 Paragraph (h)		**Flight Controls - Non-Destructive Liquid Penetrant Inspection (Sleeve Is Present and Not Cracked Along Its Entire Length)**							RE (-)		Mandatory	
	27 A/F						Mos	01-Mar-2013				
	Eff: 01-Apr-2010 Complied With						Hrs	2,753.9				
							Ldg	1,625				
45-27-10		**Flight Controls - Replacement of the Spoiler Actuator**							RE (-)		Optional	
	27 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-27-10 Rev 1		**Flight Controls - Replacement of the Spoiler Actuator**							RE (-)		Optional	
	27 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-27-10 Rev 2	**Flight Controls - Replacement of the Spoiler Actuator**							RE (-)		Optional	
27 A/F						Mos	29-Aug-2019				
Eff: 25-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-27-11	**Flight Controls - Replacement of the Rudder Pedal Adjustment Actuator Assembly**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-11 Rev 1	**Flight Controls - Replacement of the Rudder Pedal Adjustment Actuator Assembly**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-11 Rev 2	**Flight Controls - Replacement of the Rudder Pedal Adjustment Actuator Assembly**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 24-Sep-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-12	**Flight Controls - Inspection/Replacement of the Elevator Disconnect Pull Handle Assembly**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-12 Rev 1	**Flight Controls - Inspection/Replacement of the Elevator Disconnect Pull Handle Assembly**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-12 Rev 2	**Flight Controls - Inspection/Replacement of the Elevator Disconnect Pull Handle Assembly**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 12-Feb-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-13	**Flight Controls - Replacement of the Horizontal Stabilizer Upper and Lower Torque Link Assemblies**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-13 Rev 1	**Flight Controls - Replacement of the Horizontal Stabilizer Upper and Lower Torque Link Assemblies**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 15-Jan-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-14	**Flight Controls - Installation of Cable Retainer for Pitch Disconnect Cable Assembly**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 21-Jan-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-16	**Flight Controls - Inspection of the Rudder Torque Tube Assembly Bonding Jumpers**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 29-Oct-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-17	**Flight Controls - Repair of the Rudder Torque Tube Assembly Bonding Jumpers**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-17 Rev 1	**Flight Controls - Repair of the Rudder Torque Tube Assembly Bonding Jumpers**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 12-Dec-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-27-19	**Flight Controls - Inspection/Replacement of Spoiler Actuator Return Pressure Hose Assembly**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-19 Rev 1	**Flight Controls - Inspection/Replacement of Spoiler Actuator Return Pressure Hose Assembly**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 15-Aug-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-2	**Flight Controls - Installation of Elevator Disconnect Dual Locking Device**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-2 Rev 1	**Flight Controls - Installation of Elevator Disconnect Dual Locking Device**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-2 Rev 2	**Flight Controls - Installation of Elevator Disconnect Dual Locking Device**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 18-Feb-2000 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-20	**Flight Controls -- Modification of the Spoiler System Control Wheel Master Input**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 09-Feb-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-21	**Flight Controls - Modification of the Control Column Fittings**							RE (-)		Optional	
27 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-27-21 Rev 1	**Flight Controls - Modification of the Control Column Fittings**							T (A/R)		Optional	
27 A/F						Mos					
Eff: 18-Jun-2007						Hrs					
						Ldg					
45-27-23	**Flight Controls - Replacement of the Flap Actuator Gimbal Pin Retaining Rings**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 24-Jan-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-24	**Flight Controls - Inspection/Repair of the Rudder Torque Tube**							RE (-)		Recommended	
27 A/F						Mos	28-Sep-2010				
Eff: 12-Mar-2007 Not Applicable	BY EFFECTIVITY N/A PER A/C S/N					Hrs	1,567.7				
(AVG MAN HRS: 35.5)						Ldg	950				
45-27-24 Rev 1	**Flight Controls - Inspection/Repair of the Rudder Torque Tube**							RE (-)		Recommended	
27 A/F						Mos	08-Jun-2009				
Eff: 04-Jun-2007 Not Applicable	PER A/C S/N					Hrs	801				
(AVG MAN HRS: 35.5)						Ldg	521				
45-27-24 Rev 2	**Flight Controls - Inspection/Repair of the Rudder Torque Tube**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 22-Mar-2010 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 35.5)						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-27-25	**Flight Controls - Replacement of the Rudder Torque Tube**							RE (-)		Optional	
27 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-27-25 Rev 1	**Flight Controls - Replacement of the Rudder Torque Tube**							RE (-)		Optional	
27 A/F						Mos					
Not Applicable	NO ACTION REQUIRED SEE BASIC SB					Hrs					
						Ldg					
45-27-25 Rev 2	**Flight Controls - Replacement of the Rudder Torque Tube**							RE (-)		Optional	
27 A/F						Mos					
Eff: 21-Sep-2009 Not Applicable	NO ACTION REQUIRED SEE BASIC SB					Hrs					
						Ldg					
45-27-26	**Flight Controls - Inspection/Replacement of the Rudder Control Impedance Bushing**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 11-Jun-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-27	**Flight Controls - Spoileron Essential Power Input Correction**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-27 Rev 1	**Flight Controls - Spoileron Essential Power Input Correction**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 20-Oct-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-28	**Flight Controls - Inspection/Modification of the Spoileron Center Hinge Lug**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 04-Sep-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-3	**Flight Controls - Adjustment of Rudder Travel Tolerance**							RE (-)		Optional	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-3 Rev 1	**Flight Controls - Adjustment of Rudder Travel Tolerance**							RE (-)		Optional	
27 A/F						Mos	29-Aug-2019				
Eff: 15-Oct-1999 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-27-31	**Please refer to AW27-051 concerning this SB**							RE (-)		Optional	
27 A/F						Mos	21-Sep-2009				
Complied With						Hrs	959.2				
						Ldg	607				
45-27-31 Rev 1	**Please refer to AW27-051 concerning this SB**							RE (-)		Optional	
27 A/F						Mos	07-Jun-2011				
Eff: 14-Sep-2009	INFORMATION THIS AIRCRAFT IS NO LONGER IN COMPLIANCE WITH SB 45-27-31 R1 DUE TO APPLICATION OF GREASE MIL-PRE-81322 IN ACCORDANCE WITH AMM 12-21-03					Hrs	2,013.7				
						Ldg	1,207				
45-27-32	**Flight Controls - Removal of the Spoileron Computer Enclosure**							RE (-)		Optional	
27 A/F						Mos	29-Aug-2019				
Eff: 18-Aug-2008 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-27-33	**Flight Controls - Weight and Balance Change after Replacement of the Horizontal Stabilizer Trim Actuator**							RE (-)		Recommended	
27 A/F						Mos					
Eff: 11-Apr-2008						Hrs					
(AVG MAN HRS: 5)						Ldg					
45-27-33 Rev 1	**Flight Controls - Weight and Balance Change after Replacement of the Horizontal Stabilizer Trim Actuator**							RE (-)		Recommended	
27 A/F						Mos					
Eff: 30-Jun-2008						Hrs					
(AVG MAN HRS: 5)						Ldg					
45-27-33 Rev 2	**Flight Controls - Weight and Balance Change after Replacement of the Horizontal Stabilizer Trim Actuator**							RE (-)		Recommended	
27 A/F						Mos	08-Jan-2009				
Eff: 11-Aug-2008 Complied With						Hrs	601.9				
(AVG MAN HRS: 5)						Ldg	413				
45-27-33 Rev 3	**Flight Controls - Weight and Balance Change after Replacement of the Horizontal Stabilizer Trim Actuator**							RE (-)		Recommended	
27 A/F						Mos					
Eff: 15-Feb-2010						Hrs					
(AVG MAN HRS: 5)						Ldg					
45-27-33 Rev 4	**Flight Controls - Weight and Balance Change after Replacement of the Horizontal Stabilizer Trim Actuator**							RE (-)		Recommended	
27 A/F						Mos	27-Apr-2010				
Eff: 05-Apr-2010 Complied With	NO REWORK REQUIRED FOR AIRCRAFT WHICH HAVE PREVIOUS COMPLIED WITH					Hrs	1,312.5				
(AVG MAN HRS: 5)						Ldg	802				
45-27-35	**Flight Controls - Replacement of the Horizontal Stabilizer Trim Actuator**							RE (-)		Recommended	
27 A/F						Mos	08-Jan-2009				
Complied With						Hrs	601.9				
						Ldg	413				
45-27-35 Rev 1	**Flight Controls - Replacement of the Horizontal Stabilizer Trim Actuator**							RE (-)		Recommended	
27 A/F						Mos	08-Jan-2009				
Eff: 11-Aug-2008 Complied With						Hrs	601.9				
						Ldg	413				
45-27-36	**Flight Control - Replacement/Modification of The Aileron Quadrant/Spindle Assembly**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					
45-27-36 Rev 1	**Flight Control - Replacement/Modification of The Aileron Quadrant/Spindle Assembly**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					
45-27-36 Rev 2	**Flight Control - Replacement/Modification of The Aileron Quadrant/Spindle Assembly**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					
45-27-36 Rev 3	**Flight Control - Replacement/Modification of The Aileron Quadrant/Spindle Assembly**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					
45-27-36 Rev 4	**Flight Control - Replacement/Modification of The Aileron Quadrant/Spindle Assembly**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-27-36 Rev 5	**Flight Control - Replacement/Modification of The Aileron Quadrant/Spindle Assembly**							T (-)		Optional	
27 A/F						Mos					
Eff: 15-Apr-2013						Hrs					
						Ldg					
45-27-36 Rev 6	**Flight Controls - Replacement/Modification of the Aileron Quadrant/Spindle Assembly (Canceled)**							RE (-)		Optional	
27 A/F						Mos	29-Aug-2019				
Eff: 27-Apr-2015 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-27-37	**Flight Controls - Replacement of the Rudder Trim Tab Hinge Pin**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					
45-27-37 Rev 1	**Flight Controls - Replacement of the Rudder Trim Tab Hinge Pin**							T (A/R)		Optional	
27 A/F						Mos					
Eff: 11-Oct-2010						Hrs					
						Ldg					
45-27-38	**Flight Controls - Modification of the Flap Power Unit**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					
45-27-38 Rev 1	**Flight Controls - Modification of the Flap Power Unit**							RE (-)		Optional	
27 A/F						Mos	11-Apr-2012				
Eff: 27-Feb-2012 Not Applicable	PER PART NUMBER					Hrs	2,413.2				
						Ldg	1,441				
45-27-4	**Flight Controls - Installation of Spoileron Computer Access Door**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 13-Apr-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-41	**Flight Controls - Modification of the Flap Actuator Ballscrew Assembly Sleeves**							RE (-)		Optional	
27 A/F						Mos	16-Oct-2010				
Eff: 11-Jan-2010 Complied With	FOR THE LH INBOARD FLAP ACTUATOR ONLY					Hrs	1,607.8				
						Ldg	973				
45-27-42	**Flight Controls - Replacement Of The Spoiler Rotary Variable Differential Transducer (RVDT) Lever Assembly**							T (A/R)		Optional	
27 A/F						Mos					
Eff: 10-May-2010						Hrs					
						Ldg					
45-27-43	**Replacement of the Pitch Disconnect Sensor Switch (MT66) and Mounting Bracket**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					
45-27-43 Rev 1	**Replacement of the Pitch Disconnect Sensor Switch (MT66) and Mounting Bracket**							T (A/R)		Optional	
27 A/F						Mos					
Eff: 26-Sep-2011						Hrs					
						Ldg					
45-27-44	**Flight Controls - Installation Of Improved Fuselage Flight Control Cable Fairleads**							RE (-)		Optional	
27 A/F						Mos	02-Jan-2015				
Eff: 25-Jul-2011 Complied With						Hrs	3,355.7				
						Ldg	1,959				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-27-44 Rev 1	**Flight Controls - Installation Of Improved Fuselage Flight Control Cable Fairleads**							T (-)		Optional	
27 A/F						Mos					
Eff: 29-Feb-2016						Hrs					
(AVG MAN HRS: 97)						Ldg					
45-27-44 Rev 2	**Flight Controls - Installation Of Improved Fuselage Flight Control Cable Fairleads**							T (-)		Optional	
27 A/F						Mos					
Eff: 20-Feb-2017						Hrs					
(AVG MAN HRS: 97)						Ldg					
45-27-44 Rev 3	**Flight Controls - Installation of Improved Fuselage Flight Control Cable Fairleads**							RE (-)		Optional	
27 A/F						Mos	02-Jan-2015				
Eff: 08-May-2017 Complied With						Hrs					
(AVG MAN HRS: 97)						Ldg					
45-27-45	**Flight Controls - Replacement Of The Aileron Disconnect Clutch/Pulley Assembly**							T (-)		Optional	
27 A/F						Mos					
Eff: 17-Dec-2012						Hrs					
						Ldg					
45-27-45 Rev 1	**Flight Controls - Replacement Of The Aileron Disconnect Clutch/Pulley Assembly**							T (A/R)		Optional	
27 A/F						Mos					
Eff: 29-Feb-2016						Hrs					
(AVG MAN HRS: 9)						Ldg					
45-27-46	**Flight Controls - Installation of Improved Flap Track Assemblies**							RE (-)		Optional	
27 A/F						Mos					
						Hrs					
						Ldg					
45-27-46 Rev 1	**Flight Controls - Installation of Improved Flap Track Assemblies**							T (-)		Optional	
27 A/F						Mos					
Eff: 26-Jun-2013						Hrs					
						Ldg					
45-27-46 Rev 2	**Flight Controls - Installation of Improved Flap Track Assemblies**							T (-)		Optional	
27 A/F						Mos					
Eff: 04-May-2015						Hrs					
(AVG MAN HRS: 47.5)						Ldg					
45-27-46 Rev 3	**Flight Controls - Installation of Improved Flap Track Assemblies**							T (A/R)		Optional	
27 A/F						Mos					
Eff: 20-Dec-2021						Hrs					
(AVG MAN HRS: 47.5)						Ldg					
45-27-47	**Flight Controls - Installation of Improved Flap Actuators**							RE (-)		Recommended	
27 A/F						Mos					
Eff: 16-Apr-2012						Hrs					
(AVG MAN HRS: 18)						Ldg					
45-27-47 Rev 1	**Flight Controls - Installation of Improved Flap Actuators**							RE (-)		Recommended	
27 A/F						Mos	05-Aug-2014				
Eff: 18-Jun-2012 Complied With						Hrs					
(AVG MAN HRS: 18)						Ldg					
45-27-48	**Flight Controls - Replacement of the AFT Elevator Disconnect Assembly**							T (A/R)		Optional	
27 A/F						Mos					
Eff: 20-Feb-2012						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-27-49	**Flight Controls - Flap Power Unit Hydraulic Motor Torque Inspection**							RE (-)		Recommended	
27 A/F						Mos	11-Apr-2012				
Eff: 27-Feb-2012 Not Applicable	PER PART NUMBER					Hrs	2,413.2				
(AVG MAN HRS: 8.5)						Ldg	1,441				
45-27-49 Rev 1	**Flight Controls - Flap Power Unit Hydraulic Motor Torque Inspection**							RE (-)		Recommended	
27 A/F						Mos	07-Jul-2015				
Eff: 27-Feb-2012 Complied With	NO ACTION IF PREVIOUS C/W					Hrs	3,528.4				
(AVG MAN HRS: 8.5) (NOTE: Aircraft with Flap Power Unit p/n C144483-1 installed, and aircraft with Flap Power Unit C144483-3 with a serial number from S/N 1001 thru S/N 1639)						Ldg	2,053				
45-27-50	**Flight Controls - Replacement Of The Aileron Cable Pulley Drum (Shaft)**							T (A/R)		Optional	
27 A/F						Mos					
Eff: 17-Dec-2012						Hrs					
						Ldg					
45-27-51	**Flight Controls - Pitch Trim Bias Wiring Modification**							RE (-)		Recommended	
27 A/F						Mos	29-Apr-2014				
Eff: 17-Mar-2014 Complied With						Hrs	3,155.3				
(AVG MAN HRS: 2.5)						Ldg	1,843				
45-27-51 Rev 1	**Flight Controls - Pitch Trim Bias Wiring Modification**							T (-)		Recommended	
27 A/F						Mos					
Eff: 19-May-2014						Hrs					
(AVG MAN HRS: 2.5) (NOTE: at the next 600 hour inspection or less than 24 months from the initial distribution date of this publication)						Ldg					
45-27-51 Rev 2	**Flight Controls - Pitch Trim Bias Wiring Modification**							RE (-)		Recommended	
27 A/F						Mos	07-Jul-2015				
Eff: 17-Mar-2014 Complied With	NO REWORK IF PREVIOUS C/W					Hrs	3,528.4				
(AVG MAN HRS: 2.5)						Ldg	2,053				
45-27-52	**Flight Controls - Flap Power Unit (FPU) Hydraulic Motor Replacement**							T (-)		Recommended	
27 A/F						Mos					
Eff: 24-Jun-2019						Hrs					
(AVG MAN HRS: 8.5)						Ldg					
45-27-52 Rev 1	**Flight Controls - Flap Power Unit (FPU) Hydraulic Motor Replacement**							T (-)		Recommended	
27 A/F						Mos					
Eff: 05-Aug-2019						Hrs					
(AVG MAN HRS: 8.5) (NOTE: NOTE: Service bulletin may be purchased at special pricing if scheduled with ISIT within 12 months from the initial distribution date of this publication.)						Ldg					
45-27-52 Rev 2	**Flight Controls - Flap Power Unit (FPU) Hydraulic Motor Replacement**							T (A/R)		Recommended	
27 A/F						Mos					
Eff: 09-Nov-2020						Hrs					
(AVG MAN HRS: 8.5)						Ldg					
45-27-6	**Flight Controls - Inspection of Spoiler System**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-6 Rev 1	**Flight Controls - Inspection of Spoiler System**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-27-6 Rev 2	**Flight Controls - Inspection of Spoiler System**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 13-Jul-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-7	**Flight Controls - Installation of Spoileron RVDT Adjustment Rod**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 12-Oct-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-8	**Flight Controls - Replacement of Spoileron Computer (A19)**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-8 Rev 1	**Flight Controls - Replacement of Spoileron Computer (A19)**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 15-Aug-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-27-9	**Fuselage - Replacement of the Cabin Flight Control Fairleads**							RE (-)		Recommended	
27 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-27-9 Rev 1	**Fuselage - Replacement of the Cabin Flight Control Fairleads**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 24-Sep-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-34-19	**Navigation - Replacement of Glideslope Coaxial Cable Feed Thru Adapter**							RE (-)		Recommended	
27 A/F						Mos	14-Dec-2020				
Eff: 04-Sep-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
75-27-01	**Flight Controls - Installation of Improved Flap Track Assemblies**							RE (-)		Optional	
27 A/F						Mos					
Eff: 04-May-2015						Hrs					
(AVG MAN HRS: 47.5)						Ldg					
75-27-01 Rev 1	**Flight Controls - Installation of Improved Flap Track Assemblies**							RE (-)		Optional	
27 A/F						Mos					
Eff: 20-Dec-2021						Hrs					
(AVG MAN HRS: 47.5)						Ldg					
75-27-04	**Flight Controls - Flap Power Unit (FPU) Hydraulic Motor Replacement**							RE (-)		Recommended	
27 A/F						Mos					
Eff: 24-Jun-2019						Hrs					
(AVG MAN HRS: 8.5)						Ldg					
75-27-04 Rev 1	**Flight Controls - Flap Power Unit (FPU) Hydraulic Motor Replacement**							RE (-)		Recommended	
27 A/F						Mos					
Eff: 05-Aug-2019						Hrs					
						Ldg					
75-27-04 Rev 2	**Flight Controls - Flap Power Unit (FPU) Hydraulic Motor Replacement**							RE (-)		Recommended	
27 A/F						Mos					
Eff: 09-Nov-2020						Hrs					
(AVG MAN HRS: 8.5)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
A2711001	**** Aileron Trim Tab Control System - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
27 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:27-10-04 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-10-04.))						Ldg	3,757				
A2721001	**** Rudder Trim System - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
27 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:27-20-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-20-00.))						Ldg	3,757				
A2731002	**** Elevator Disconnect System - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-12-02, Ch.5 Interval		**≈24-Oct-2024**
27 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:27-30-00 (ZONE: 220/320) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-30-00.))						Ldg	3,757				
A2760001	**** Spoiler Actuator Check Valve - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-12-04, Ch.5 Interval		**≈24-Oct-2024**
27 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:27-60-04 (ZONE: 540/640) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-60-04.))						Ldg	3,757				
A2760002	**** Spoiler System - Perform Spoiler Authority with Flaps Check.**							RE	TLMC 04-10-00, TLMC 05-12-04, Ch.5 Interval		**≈24-Oct-2024**
27 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:27-60-00 (ZONE: 540/640) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-60-00.))						Ldg	3,757				
A45-27-15	**Flight Controls - Replacement of the Horizontal Stabilizer Actuator Assembly**							RE (-)		Alert	
27 A/F						Mos	14-Dec-2020				
Eff: 20-Mar-2003 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 8)						Ldg	2,822				
A45-27-18	**Flight Controls - Replacement of the Horizontal Stabilizer Actuator Assembly**							RE (-)		Alert	
27 A/F						Mos	14-Dec-2020				
Eff: 08-Sep-2003 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 8)						Ldg	2,822				
A45-27-29	**Flight Controls - Inspection of Flap Actuator Forward Attach Joints**							RE (-)		Alert	
27 A/F						Mos	13-Mar-2008				
Eff: 14-Sep-2007 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 4)						Ldg					
A45-27-29 Rev 1	**Flight Controls - Inspection of Flap Actuator Forward Attach Joints**							RE (-)		Alert	
27 A/F						Mos	14-Dec-2020				
Eff: 02-Oct-2007 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 4)						Ldg	2,822				
A45-27-30	**Flight Controls - Replacement of Flap Actuator Forward Attach Joints**							RE (-)		Alert	
27 A/F						Mos	13-Mar-2008				
Eff: 02-Jan-2008 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 17)						Ldg					
A45-27-30 Rev 1	**Flight Controls - Replacement of Flap Actuator Forward Attach Joints**							RE (-)		Alert	
27 A/F						Mos	13-Mar-2008				
Eff: 19-Feb-2008 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 17)						Ldg	8				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
A45-27-30 Rev 2	**Flight Controls - Replacement of Flap Actuator Forward Attach Joints**							RE (-)		Alert	
27 A/F						Mos					
Eff: 25-Aug-2008						Hrs					
(AVG MAN HRS: 17)						Ldg					
A45-27-30 Rev 3	**Flight Controls - Replacement of Flap Actuator Forward Attach Joints**							RE (-)		Alert	
27 A/F						Mos					
Eff: 15-Feb-2010						Hrs					
(AVG MAN HRS: 17)						Ldg					
A45-27-30 Rev 4	**Flight Controls - Replacement of Flap Actuator Forward Attach Joints**							RE (-)		Alert	
27 A/F						Mos	14-Dec-2020				
Eff: 23-Nov-2015 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 17)						Ldg	2,822				
A45-27-34	**Flight Controls - Replacement of Rudder Trim Tab Hinge Cotter Pins**							RE (-)		Alert	
27 A/F						Mos	08-Jan-2009				
Eff: 16-Jun-2008 Complied With						Hrs					
(AVG MAN HRS: 1)						Ldg					
A45-27-40	**Flight Controls - Inspection of the Flap Actuator Ballscrew Assembly Sleeves**							RE (-)		Alert	
27 A/F						Mos	01-Mar-2013				
Eff: 11-Jan-2010 Complied With	TERMINATED BY SB 45-27-47.					Hrs					
(AVG MAN HRS: 5.5)						Ldg					
AA2700000	**Aileron Control Cable System - With Cockpit and Cabin Floorboards Removed, Perform Visual Inspection of Cables**							RE		TLMC 05-12-01	**≈24-Oct-2024**
27 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Ref:27-00-00 (ZONE: 220BL, 220BR, 220CL, 220CR, 220DL, 220DR, 220EL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: More Zones : 220ER, 230AC, 230BC, 230CC, 230DC, 230EC.)						Ldg	3,757				
AA2700001	**Rudder Control Cable System - With Cockpit and Cabin Floorboards Removed, Perform Visual Inspection of Cables**							RE		TLMC 05-12-01	**≈24-Oct-2024**
27 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Ref:27-00-00 (ZONE: 220BL, 220BR, 220CL, 220CR, 220DL, 220DR, 220EL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: More Zones: 220ER, 230AC, 230BC, 230CC, 230DC, 230EC)						Ldg	3,757				
AA2700002	**Elevator Control Cable System - With Cockpit and Cabin Floorboards Removed, Perform Visual Inspection of Cables**							RE		TLMC 05-12-01	**≈24-Oct-2024**
27 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Ref:27-00-00 (ZONE: 220BL, 220BR, 220CL, 220CR, 220DL, 220DR, 220EL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: More Zones: 220ER, 230AC, 230BC, 230CC, 230DC, 230EC)						Ldg	3,757				
AA2760021	**Left No. 1 Spoiler Hydraulic Swivel - Replacement**							RE		TLMC 05-19-01	**≈04-Oct-2024**
27 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8	1,200	-/+25	5,790.8	516 Hrs (+25)
(ZONE: 540DL) (SOURCE: MM-104, MM-105) (NOTE: NOTE: For Aircraft with more than 1,200 Hours on April 20, 2018 Replace Swivel at the next 600 Hour Inspection)						Ldg	2,807				
AA2760021	**Left No. 2 Spoiler Hydraulic Swivel - Replacement**							RE		TLMC 05-19-01	**≈04-Oct-2024**
27 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8	1,200	-/+25	5,790.8	516 Hrs (+25)
(ZONE: 540DL) (SOURCE: MM-104, MM-105) (NOTE: NOTE: For Aircraft with more than 1,200 Hours on April 20, 2018 Replace Swivel at the next 600 Hour Inspection)						Ldg	2,807				
AA2760021	**Right No. 1 Spoiler Hydraulic Swivel - Replacement**							RE		TLMC 05-19-01	**≈04-Oct-2024**
27 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8	1,200	-/+25	5,790.8	516 Hrs (+25)
(ZONE: 640DR) (SOURCE: MM-104, MM-105) (NOTE: NOTE: For Aircraft with more than 1,200 Hours on April 20, 2018 Replace Swivel at the next 600 Hour Inspection)						Ldg	2,807				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AA2760021	**Right No. 2 Spoiler Hydraulic Swivel - Replacement**							RE		TLMC 05-19-01	**≈04-Oct-2024**
27 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8	1,200	-/+25	5,790.8	516 Hrs (+25)
	(ZONE: 640DR) (SOURCE: MM-104, MM-105) (NOTE: NOTE: For Aircraft with more than 1,200 Hours on April 20, 2018 Replace Swivel at the next 600 Hour Inspection)					Ldg	2,807				
AD2760085	**Spoiler Lever Arm - Perform detailed visual inspection to ensure spoiler lever arm is properly seated and secured on spoiler RVDT shaft.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
27 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Ref:27-60-05 (ZONE: 540DL, 640DR) (SOURCE: MM-104, MM-105)					Ldg	3,757				
AW 27-012	**Uncommanded Asymmetric Spoiler Actuation**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-013	**Uncommanded Asymmetric Spoiler Actuation Update**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-015	**Uncommanded Asymmetric Spoiler Actuation Follow-Up**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-016	**Model 45 Rudder Pedal Adjustment Actuator Failure**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-017	**Uncommanded Asymmetric Spoiler Actuation Follow Up**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-019	**Horizontal Stabilizer Actuator Update**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-020	**Horizontal Stabilizer Actuator**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-021	**Horizontal Stabilizer Actuator Shipments**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-022	**Horizontal Stabilizer Actuator Status**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-024	**Horizontal Stabilizer Actuator Update #2**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 27-025	**Horizontal Stabilizer Actuator Update #3**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-026	**Horizontal Stabilizer Actuator Update #4**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-027	**Learjet 45 Horizontal Stabilizer Actuator Update #5**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-028	**Learjet 45 Horizontal Stabilizer Actuator Update #6**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-029	**Learjet 45 Horizontal Stabilizer Actuator Update #7**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-030	**Learjet 45 Horizontal Stabilizer Actuator Update #8**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-031	**Learjet 45 Horizontal Stabilizer Actuator Update #9**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-032	**Learjet 45 Horizontal Stabilizer Actuator Update**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-033	**Learjet 45 Horizontal Stabilizer Actuator Update #11**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-035	**Learjet 45 Horizontal Stabilizer Actuator Adjustment**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-036	**Learjet 45 Horizontal Stabilizer Actuator Update #13**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-037	**Spoiler Reset Function**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-038	**Spoiler Actuator Return Hose**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 27-039	**Removal of The Control Wheel Master Input To The Spoiler System**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-042	**Proper Installation of Horizontal Stabilizer Torque Links**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-044	**Model 40/45 Flap Actuator Joint Pintle Cracking**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-045	**Model 45 Flap Actuator Joint Pintle Cracking Update**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-046	**Horizontal Stabilizer Primary and Secondary Bolt Installation**							RE (-)		Advisory Wire	
27 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 27-051	**Suspend SB 45-27-31. For Aircraft 45-005 Thru 45-407 Not In Compliance With SB 45-27-31**							RE (-)		Advisory Wire	
27 A/F						Mos	28-Dec-2009				
Not Applicable	WE ARE NOT GOING BACK TO THE GREASE. WE ARE STAYING WITH S/B 45-27-31 & 40-27-16.					Hrs	1,130.1				
						Ldg	702				
D2740003	**** Horizontal Stabilizer Actuator Secondary Trim - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-19-00		**≈24-Oct-2024**
27 A/F						Mos	09-Feb-2024				
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
Alias1:27-42-02 (ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg	3,757				
D2740004	**** Horizontal Stabilizer Actuator Primary Trim - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-19-00		**≈24-Oct-2024**
27 A/F						Mos	09-Feb-2024				
						Hrs	5,253.5	600	-/+25	5,853.5	578.7 Hrs (+25)
Alias1:27-42-02 (ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg	3,757				
G2710003	**Aileron Control System Cables (located in wing area) - Perform Cable Tension Check.**							RE		TLMC 05-13-04	**≈24-Apr-2025**
27 A/F	05-13-04					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:27-10-00 (ZONE: 540/640) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-10-00.))						Ldg	3,757				
G2710004	**Aileron Control System Cables (located in fuselage area) - Perform Cable Tension Check.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
27 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:27-10-00 (ZONE: 230AC, 230BC, 230CC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-10-00.))						Ldg	3,757				
G2720003	**Rudder Control Cables - Perform Tension Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
27 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:27-20-00 (ZONE: 230AC, 230BC, 230CC, 230DC, 230EC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-20-00.))						Ldg	3,757				
G2720004	**Rudder Pedals, Pedal Pushrods, Adjustment Actuator, and Sectors - Perform Visual Inspection. Check during full travel of rudder.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
27 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 220BL, 220CL, 220BR, 220CR, 220AC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
G2730003	**Elevator Control Cables - Perform Tension Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
27 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:27-30-00 (ZONE: 230AC, 230BC, 230CC, 230DC, 230EC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-30-00.))					Ldg	3,757				
K2700007	*** Aileron Control System Primary Cables - Remove from aircraft and perform detailed visual inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈14-Oct-2027**
27 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
	Alias1:27-00-00 (ZONE: 230AC, 230BC, 230CC, 230DC, 230EC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	2,822				
K2700008	*** Elevator Control System Primary Cables - Remove from aircraft and perform detailed visual inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈14-Oct-2027**
27 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
	Alias1:27-00-00 (ZONE: 230AC, 230BC, 230CC, 230DC, 230EC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	2,822				
K2700009	*** Rudder Control System Primary Cables - Remove from aircraft and perform detailed visual inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈14-Oct-2027**
27 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
	Alias1:27-00-00 (ZONE: 230AC, 230BC, 230CC, 230DC, 230EC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	2,822				
K2700010	*** Elevator Control System Primary Cables - Remove from aircraft and perform detailed visual inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈14-Oct-2027**
27 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
	Alias1:27-00-00 (ZONE: 310CC, 310DC, 310HL, 310JL, 310QR, 310RR, 840AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	2,822				
K2700012	*** Rudder Control System Primary Cables - Remove from aircraft and perform detailed visual inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈14-Oct-2027**
27 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
	Alias1:27-00-00 (ZONE: 310CC, 310DC, 310HL, 310JL, 310QR, 310RR, 840AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	2,822				
K2700014	*** Aileron Control System Primary Cables - Remove from aircraft and perform detailed visual inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈14-Oct-2027**
27 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
	Alias1:27-00-00 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	2,822				
N2720030	**Rudder Torque Tube and Spindle - Perform Detailed Visual Inspection.**							RE		TLMC 05-19-00	
27 A/F						Yrs	22-May-2020	6	-/+14d	22-May-2026	2 Years (+14 Days)
						Hrs	4,593.2				
	Alias1:27-20-01 (ZONE: 320BL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-20-01.) Effective 6 years from C of A compliance or compliance with SB 45-27-24, then every 6 years thereafter.)					Ldg	2,809				
N2740023	*** Horizontal Stabilizer Actuator ACME Screw (P/N 2A94568008) - Replace.**							RE (N/A)	TLMC 04-11-00, TLMC 05-19-01		
27 A/F						Mos					
6627401000-009						Hrs					
B0062						Ldg					
	(ZONE: 330AC, 330BC, 330CC, 330CL, 330BR) (SOURCE: MM-104, MM-105) (NOTE: (Effective on aircraft equipped with 6627401000-007 Horizontal Stabilizer Actuators.))										
N2740024	*** Horizontal Stabilizer Actuator ACME Nut (P/N 2A94567005) - Replace.**							RE (N/A)	TLMC 04-11-00, TLMC 05-19-01		
27 A/F						Mos					
6627401000-009						Hrs					
B0062						Ldg					
	(ZONE: 330AC, 330BC, 330CC, 330CL, 330BR) (SOURCE: MM-104, MM-105) (NOTE: (Effective on aircraft equipped with 6627401000-007 Horizontal Stabilizer Actuators.))										
N2740025	*** Horizontal Stabilizer Actuator (6627401000-007) - Perform Detailed Structural Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
27 A/F						Mos					
6627401000-009						Hrs					
B0062						Ldg					
	(ZONE: 330AC /AR/BC/CC/CL/XL/WR/YL/XR) (SOURCE: MM-104, MM-105) (NOTE: Note: Remove Horizontal Stabilizer Actuator from aircraft. Send actuator to Learjet on a Parts Return Claim Form so unit can be exchanged with serviceable unit and returned to vendor for overhaul and structural inspection. Refer to Replacement Schedule section 5- 19-01 for life limited components (IRN #'s N2740023 and N2740024).)										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
P2740032	*** Horizontal Stabilizer Actuator (6627401000-009) - Perform Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈24-May-2024**
27 A/F						Mos	12-Mar-2018				
6627401000-009						Hrs	4,155.2	1,200		5,355.2	80.4 Hrs
B0062						Ldg	2,448				
	Alias1:27-40-00 (ZONE: 330AC /AR/BC/CC/CL/XL/WR/YL/XR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-40-00.) Note: Remove Horizontal Stabilizer Actuator from aircraft. Send actuator to Learjet on a parts return claim form so unit can be exchanged with serviceable unit and returned to vendor for overhaul. Interval is calculated from time since new or from the Time Since Overhaul (TSO) hours.)										
P2740033	*** Horizontal Stabilizer Actuator (6627401000-009) - Perform Detailed Structural Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈02-Jun-2024**
27 A/F						Mos	12-Mar-2018				
6627401000-009					1,173	Hrs	4,155.2	2,400		5,382.2	107.4 Hrs
B0062						Ldg	2,448				
	(ZONE: 330AC /AR/BC/CC/CL/XL/WR/YL/XR) (SOURCE: MM-104, MM-105) (NOTE: Note: Remove Horizontal Stabilizer Actuator from aircraft. Send actuator to Learjet on a Parts Return Claim Form so unit can be exchanged with serviceable unit and returned to vendor for overhaul and structural inspection. Interval is calculated from time since new or from the Time Since Structural Inspection (TSSI) hours.)										
R2710041	*** Aileron Spindle (P/N 4527102103-001) - Replace.**							RE (N/A)	TLMC 04-11-00, TLMC 05-19-01		
27 A/F						Yrs	12-Mar-2018				
						Hrs	4,155.2				
	(ZONE: 230AC, 230BC, 230CC, 250CC, 540AL, 640AR) (SOURCE: MM-104, MM-105)					Ldg	2,448				
S2750057	*** Flap Actuator Ballnut Sleeve (Flap Actuator Assembly Learjet P/N 6627503000- 009, 6627503000-011, 6627503000-021, 6627503000-023, 6627503000-025 and 6627503000-027, Flap Actuator Assembly Microtecnica P/N C144487-1, C144488-1, C144487-2, C144488-2, C144487-3 and C144488-3) - Perform Fluorescent Penetrant Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
27 A/F						Mos	25-Oct-2012				
						Hrs	2,671.3				
	Alias1:27-50-01, 27-50-02 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual (NDI-104), Part 8, Part 8, 27-50-01 or 27-50-02.) Note: On Aircraft modified per SB 45-27-41, "Flight Controls - Modification of the Flap Actuator Ballscrew Assembly Sleeves", inspect modification half sleeve surrounding original sleeve. On Aircraft not modified per SB 45-27-41, "Flight Controls - Modification of the Flap Actuator Ballscrew Assembly Sleeves", inspect original sleeve.)					Ldg	1,577				
T2740002	*** Horizontal Stabilizer Actuator (6627401000-007) - Perform Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
27 A/F						Mos					
6627401000-009						Hrs					
B0062						Ldg					
	(ZONE: 330AC /AR/BC/CC/CL/XL/WR/YL/XR) (SOURCE: MM-104, MM-105) (NOTE: Note: Remove Horizontal Stabilizer Actuator from aircraft. Send actuator to Learjet on a parts return claim form so unit can be ex- changed with serviceable unit and returned to vendor for overhaul. Refer to Replacement Schedule section 5- 19-01 for life-limited components (IRN #'s N2740023 and N2740024). The 24 Month interval is calculated from September 6, 2011.)										
V2712000	**** Roll Disconnect Switches - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
27 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:27-60-09 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-60-09.))					Ldg	3,757				
W2731001	**** Pitch Trim - Perform Operational Check of Elevator Override Actuator.**							RE	TLMC 04-10-00, TLMC 05-12-02, Ch.5 Interval		**≈24-Oct-2024**
27 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:27-30-14 (ZONE: 330) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-30-14.))					Ldg	3,757				
W2750056	*** Flap Actuator Joint (P/N 145673-1) - Perform Detailed Visual Inspection. Apply Corrosion Preventive Compound (CPC) to joint.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
27 A/F						Mos	18-Sep-2012				
						Hrs	2,631.6				
	Alias1:12-21-03, 27-50-06 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-50-06.) Apply Corrosion Preventive Compound (CPC) to joint. (Refer to 12-21-03.))					Ldg	1,558				
Y2700003	**Aileron Control Cable System - Perform visual inspection of cables within wing.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
27 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:27-00-00 (ZONE: 540/640) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y2700004	**Rudder Control Cable System - Perform visual inspection of accessible upper and lower cables.**							RE		TLMC 05-12-02	**≈24-Oct-2024**
27 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:27-00-00 (ZONE: 310CC/DC/HL/JL/QR/RR/3290CL/DL/EL, 840AR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	3,757				
Y2700005	**Elevator Control Cable System - Perform visual inspection of accessible upper and lower cables.**							RE		TLMC 05-12-02	**≈24-Oct-2024**
27 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:27-00-00 (ZONE: 310CC/DC/HL/JL/QR/RR/320CL/DL/EL, 840AR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	3,757				
Y2700006	**Rudder and Elevator Control Cables and associated pulleys, located in Aft Pressure Bulkhead Support Channel - Perform visual inspection.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
27 A/F	05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:27-00-00 (ZONE: 510CL, 610CR, 310AC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	3,757				
Y2710000	**Ailerons, Aileron Trim Tab and Visible Portion of Rods - Perform visual inspection.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
27 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 540/640) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2710001	**Aileron Balance Weight Installation and Supporting Structure - Perform visual inspection.**							RE		TLMC 05-13-04	**≈24-Apr-2025**
27 A/F	05-13-04					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 540GL, 640GR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2710002	**Aileron Control System - Perform Operational Check.**							RE		TLMC 05-13-04	**≈24-Apr-2025**
27 A/F	05-13-04					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:27-10-00 (ZONE: 540/640) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	3,757				
Y2710048	**Aileron Trim Tab Installation - Perform Free Play Check.**							RE		TLMC 05-14-04	**≈12-Oct-2025**
27 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:27-10-04 (ZONE: 500/600) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-10-04.) NOTE: Initial inspection to be performed at 9,600 flight hours with no calendar restrictions, and subsequent inspections performed every 2,400 hours/96 months thereafter. On aircraft with over 9,600 hours from C of A, perform inspection at next scheduled Phase D4 inspection.)					Ldg	2,822				
Y2720000	**Rudder - Perform visual inspection.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
27 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y2720001	**Rudder Balance Weight Installation and Supporting Structure - Perform Visual Inspection.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
27 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 330) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2720002	**Rudder Control System - Perform Operational Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
27 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:27-20-00 (ZONE: 330) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-20-00.))					Ldg	3,757				
Y2721000	**Rudder Trim Tab and Visible Rods - Perform visual inspection.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
27 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: On Aircraft 45-005 thru 45-364 not modified by SB 45-27-34 and Aircraft 45-005 thru 45-428 not modified by SB 45-27-37, replace the rudder trim tab hinge lower cotter pin during this inspection.)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y2730000	**Control Columns - Perform Visual Inspection. Pay particular attention to aileron control wheel cable drum and bottom crossover pulleys.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
27 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2730001	**Elevators - Perform visual inspection.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
27 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 300) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y2730002	**Elevator Control System - Perform Operational Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
27 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:27-30-00 (ZONE: 330) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	3,757				
Y2730004	**Control Columns - Perform Inspection. Inspect cable, pulleys, bearings, and electrical wiring.**							RE		TLMC 05-14-01	**≈12-Oct-2025**
27 A/F	05-14-01					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:27-00-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-00-00.))					Ldg	2,822				
Y2730007	**Aft Elevator Disconnect - Perform detailed visual inspection.**							RE		TLMC 05-14-02	**≈12-Oct-2025**
27 A/F	05-14-02					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
Y2740000	**Primary Pitch Trim System - Perform Operational Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
27 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:27-40-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-40-00.))					Ldg	3,757				
Y2740001	**Secondary Pitch Trim System - Perform Operational Check.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
27 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:27-40-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 27-40-00.))					Ldg	3,757				
Y2750000	**Flap Drive Installation - Perform visual inspection with flaps lowered.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
27 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 250CC, 540AL/BL/CL/DL/JL/KL, 640AR/BR/CR/DR/JR/KR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2750001	**Flaps - Perform visual inspection.**							RE		TLMC 05-11-04	**≈24-Jul-2024**
27 A/F	05-11-04					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00, Ref:SRM-104/51-71-07/P201 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) NOTE: If the inboard lower leading edge of flap is chafing. (Refer to Learjet 40 Series Structural Repair Manual (SRM-104), Section 51-71-07, page 201).)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y2750053	**Flap Drive Actuators - Perform a visual inspection of the actuator attachment, paying particular attention to the gimbal pin retaining rings.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
27 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 540JL, 540KL, 640JR, 640KR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y2760000	**Spoiler and Spoiler Actuator - Perform visual inspection with flaps lowered and access panels opened.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
27 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 540DL, 640DR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 28 - FUEL												
		APU Fuel Shutoff Valve							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
	7086048-1	New	0				Hrs	0				
	072203001216C		0				Ldg	0				
		Check, Motive Flow Valve							RE (O/C)			
28 A/F		Left	0				Mos	13-Mar-2008				
	6628200106-003	New	0				Hrs	0				
	31070822		0				Ldg	0				
		Check, Motive Flow Valve							RE (O/C)			
28 A/F		Right	0				Mos	13-Mar-2008				
	6628200106-003	New	0				Hrs	0				
	13072107		0				Ldg	0				
		Control - Refueling Panel							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
	4528408000V5-001	New	0				Hrs	0				
	07100996BA		0				Ldg	0				
		Dual Fuel Flow Convertor (DFFC)							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
	10540B08F07	New	0				Hrs	0				
	07101077A		0				Ldg	0				
		Flex Fuel Hose Assy							RE (O/C)			
28 A/F		Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Flex Fuel Hose Assy							RE (O/C)			
28 A/F		Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Float, Fuel (S19 & S20) Switch							RE (O/C)			
28 A/F		Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Float, Fuel (S19 & S20) Switch							RE (O/C)			
28 A/F		Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Fuel C1 Probe							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
	10665T01Y00	New	0				Hrs	0				
	MN12196		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fuel C10 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T03Y00	New	0				Hrs	0				
	MN12502		0				Ldg	0				
		Fuel C11 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T04Y00	New	0				Hrs	0				
	MN12024		0				Ldg	0				
		Fuel C12 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T05Y00	New	0				Hrs	0				
	MN10174		0				Ldg	0				
		Fuel C13 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T06Y00	New	0				Hrs	0				
	MN09808		0				Ldg	0				
		Fuel C14 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T01Y00	New	0				Hrs	0				
	MN11800		0				Ldg	0				
		Fuel C15 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T01Y00	New	0				Hrs	0				
	MN11802		0				Ldg	0				
		Fuel C16 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T06Y00	New	0				Hrs	0				
	MN08979		0				Ldg	0				
		Fuel C17 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T06Y00	New	0				Hrs	0				
	MN08983		0				Ldg	0				
		Fuel C2 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10665T03Y00	New	0				Hrs	0				
	MN12311		0				Ldg	0				
		Fuel C3 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T03Y00	New	0				Hrs	0				
	MN12499		0				Ldg	0				
		Fuel C4 Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10552T04Y00	New	0				Hrs	0				
	MN12017		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fuel C5 Probe							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
10552T05Y00		New	0				Hrs	0				
MN12552			0				Ldg	0				
		Fuel C6 Probe							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
10552T06Y00		New	0				Hrs	0				
MN08981			0				Ldg	0				
		Fuel C8 Probe							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
10665T01Y00		New	0				Hrs	0				
MN12199			0				Ldg	0				
		Fuel C9 Probe							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
10665T03Y00		New	0				Hrs	0				
MN12316			0				Ldg	0				
		Fuel Crossflow Shutoff Valve							RE (O/C)			
28 A/F							Mos	20-Jan-2012				
6628200101-003							Hrs	2,307				
0098							Ldg	1,379				
		Fuel Main Ejector Pump Assembly							RE (O/C)			
28 A/F		Left	0				Mos	13-Mar-2008				
HTE230009		New	0				Hrs	0				
34071911			0				Ldg	0				
		Fuel Main Ejector Pump Assembly							RE (O/C)			
28 A/F		Right	0				Mos	13-Mar-2008				
HTE230009		New	0				Hrs	0				
33071361			0				Ldg	0				
		Fuel Quantity Signal Conditioner							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
10551B08Y09		New	0				Hrs	0				
1011			0				Ldg	0				
		Fuel Supply (Defuel)(B24) Shutoff Valve Assembly							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
EM91-102-2		New	0				Hrs	0				
1712			0				Ldg	0				
		Fuel Supply Check Valve							RE (O/C)			
28 A/F		Left No.1	0				Mos	13-Mar-2008				
HTE460071		New	0				Hrs	0				
34072304			0				Ldg	0				
		Fuel Supply Check Valve							RE (O/C)			
28 A/F		Left No.2	0				Mos	13-Mar-2008				
HTE460071		New	0				Hrs	0				
34072302			0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fuel Supply Check Valve							RE (O/C)			
	28 A/F	Right No.1	0				Mos	13-Mar-2008				
	HTE460071	New	0				Hrs	0				
	25070857		0				Ldg	0				
		Fuel Supply Check Valve							RE (O/C)			
	28 A/F	Right No.2	0				Mos	13-Mar-2008				
	HTE460071	New	0				Hrs	0				
	34072308		0				Ldg	0				
		Fuel Supply Shut-Off (B23) Valve Assembly							RE (O/C)			
	28 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Fuel Supply Shut-Off (L10) Valve Assembly							RE (O/C)			
	28 A/F				0		Mos	20-Jan-2012				
	EM91-102-2	Repaired			0		Hrs	2,307				
	0098				0		Ldg	1,379				
		Fuel Supply Shut-Off (L11) Valve Assembly							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	EM91-102-2	New	0				Hrs	0				
	1724		0				Ldg	0				
		Fuel Transfer Check Valve							RE (O/C)			
	28 A/F	Left					Mos	23-Jan-2012				
	7628200104-001						Hrs	2,307				
	31070742						Ldg	1,379				
		Fuel Transfer Check Valve							RE (O/C)			
	28 A/F	Right	0				Mos	23-Jan-2012				
	7628200104-001	New	0				Hrs	2,307				
	08100350		0				Ldg	1,379				
		Fuel, Fuselage Cell							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	506878	New	0				Hrs	0				
	107792		0				Ldg	0				
		Fuel, Low Level Sensor							RE (O/C)			
	28 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Fuel, Low Level Sensor							RE (O/C)			
	28 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Fuel, Low Pressure (S21) Switch							RE (O/C)			
	28 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fuel, Low Pressure (S21) Switch							RE (O/C)			
	28 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Fuel, Standby Pump							RE (O/C)			
	28 A/F	Left	0				Mos	13-Mar-2008				
	1C12-39	New	0				Hrs	0				
	9BC81		0				Ldg	0				
		Fuel, Standby Pump							RE (O/C)			
	28 A/F	Right	0				Mos	13-Mar-2008				
	1C12-39	New	0				Hrs	0				
	9BC80		0				Ldg	0				
		Fuselage Fuel Probe							RE (O/C)			
	28 A/F		0				Mos	13-Mar-2008				
	10554T02Y00	New	0				Hrs	0				
	DT63724		0				Ldg	0				
		Left Fuel Shutoff Valve							RE (O/C)			
	28 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left No. 1 Fuel, Ejector Scavenge Pump							RE (O/C)			
	28 A/F	Left No.1	0				Mos	13-Mar-2008				
	HTE230008	New	0				Hrs	0				
	39071455		0				Ldg	0				
		Left No. 2 Fuel, Ejector Scavenge Pump							RE (O/C)			
	28 A/F	Left No.2	0				Mos	13-Mar-2008				
	HTE230008	New	0				Hrs	0				
	39071443		0				Ldg	0				
		Left No. 3 Fuel, Ejector Scavenge Pump							RE (O/C)			
	28 A/F	Left No.3	0				Mos	13-Mar-2008				
	HTE230008	New	0				Hrs	0				
	39071428		0				Ldg	0				
		Left No. 4 Fuel, Ejector Scavenge Pump							RE (O/C)			
	28 A/F	Left No.4	0				Mos	13-Mar-2008				
	HTE230008	New	0				Hrs	0				
	39071477		0				Ldg	0				
		Left No. 5 Fuel, Ejector Scavenge Pump							RE (O/C)			
	28 A/F	Left No.5	0				Mos	13-Mar-2008				
	HTE230008	New	0				Hrs	0				
	39071426		0				Ldg	0				
		Motorized Shutoff Valve							RE (O/C)			
	28 A/F	Left No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Motorized Shutoff Valve							RE (O/C)			
28 A/F		Left No.2					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Pilot, SPPR Valve							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
61087-2		New	0				Hrs	0				
478			0				Ldg	0				
		Pre-Check, SPPR Valve							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
HTE940032-1		New	0				Hrs	0				
38071305			0				Ldg	0				
		Refuel Check Valve							RE (O/C)			
28 A/F							Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Right Fuel Shutoff Valve							RE (O/C)			
28 A/F		Right	0				Mos	13-Mar-2008				
EM91-102-2		New	0				Hrs	0				
1735			0				Ldg	0				
		Right No. 1 Fuel, Ejector Scavenge Pump							RE (O/C)			
28 A/F		Right No.1	0				Mos	13-Mar-2008				
HTE230008		New	0				Hrs	0				
39071473			0				Ldg	0				
		Right No. 2 Fuel, Ejector Scavenge Pump							RE (O/C)			
28 A/F		Right No.2	0				Mos	13-Mar-2008				
HTE230008		New	0				Hrs	0				
39071474			0				Ldg	0				
		Right No. 3 Fuel, Ejector Scavenge Pump							RE (O/C)			
28 A/F		Right No.3	0				Mos	13-Mar-2008				
HTE230008		New	0				Hrs	0				
39011467			0				Ldg	0				
		Right No. 4 Fuel, Ejector Scavenge Pump							RE (O/C)			
28 A/F		Right No.4	0				Mos	13-Mar-2008				
HTE230008		New	0				Hrs	0				
39071429			0				Ldg	0				
		Right No. 5 Fuel, Ejector Scavenge Pump							RE (O/C)			
28 A/F		Right No.5	0				Mos	13-Mar-2008				
HTE230008		New	0				Hrs	0				
39071432			0				Ldg	0				
		Shutoff - Refuel Valve							RE (O/C)			
28 A/F			0				Mos	13-Mar-2008				
980056-2		New	0				Hrs	0				
40070844			0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Single Point Pressure Refueling (SPPR) Adapter							RE (O/C)			
	28 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Single Point Pressure Refueling Adapter							RE (O/C)			
	28 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Surge Tank Float Valve							RE (O/C)			
	28 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Wheel Well Fuel Hose							RE (O/C)			
	28 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Wheel Well Fuel Hose							RE (O/C)			
	28 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
2006-10-15		**Inspection reference numbers (IRNs)**							RE (-)		Mandatory	
	28 A/F						Mos	11-Feb-2010				
	Eff: 31-May-2006 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
							Ldg	739				
2007-04-18		**Left and Right-hand Standby Fuel Pump Switches**							RE (-)		Mandatory	
	28 A/F						Mos	13-Mar-2008				
	Eff: 23-Mar-2007 Complied With	AT MANUFACTURE					Hrs	8.7				
							Ldg	8				
45-27-5		**Flight Controls - Dual Locking Control Wheel Modification**							RE (-)		Recommended	
	28 A/F						Mos	08-Jun-2009				
	Not Applicable	PER A/C S/N					Hrs	801				
							Ldg	521				
45-27-5 Rev 1		**Flight Controls - Dual Locking Control Wheel Modification**							RE (-)		Recommended	
	28 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-27-5 Rev 2		**Flight Controls - Dual Locking Control Wheel Modification**							RE (-)		Recommended	
	28 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-27-5 Rev 3		**Flight Controls - Dual Locking Control Wheel Modification**							RE (-)		Recommended	
	28 A/F						Mos	14-Dec-2020				
	Eff: 14-Jun-2002 Not Applicable						Hrs	4,610.5				
							Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-28-1	**Fuel - Deactivate Crew Alert System Low Fuel Quantity Indication**							RE (-)		Recommended	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-1 Rev 1	**Fuel - Deactivate Crew Alert System Low Fuel Quantity Indication**							RE (-)		Recommended	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-1 Rev 2	**Fuel - Deactivate Crew Alert System Low Fuel Quantity Indication**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 16-Feb-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-28-11	**Fuel - Inspection/Replacement of the C2 and C9 Wing Fuel Probes**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 26-Feb-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-28-12	**Fuel - Reactivation of the Auxiliary Power Unit (APU) and APU Fuel Shutoff Valve Replacement**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 25-Sep-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-28-14	**Fuel - Inspection/Replacement of the APU Fuel Shutoff Valve**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 06-Dec-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-28-15	**Fuel - Conversion of Fuel Quantity Indication from Metric to U.S. Measurements**							RE (-)		Optional	
28 A/F						Mos					
Eff: 03-Oct-2008						Hrs					
(AVG MAN HRS: 30)						Ldg					
45-28-15 Rev 1	**Fuel - Conversion of Fuel Quantity Indication from Metric to U.S. Measurements**							RE (-)		Optional	
28 A/F						Mos					
Eff: 27-Jun-2011						Hrs					
(AVG MAN HRS: 30)						Ldg					
45-28-15 Rev 2	**Fuel - Conversion of Fuel Quantity Indication from Metric to U.S. Measurements**							RE (-)		Optional	
28 A/F						Mos	29-Aug-2019				
Eff: 29-Oct-2012 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 30)						Ldg	2,733				
45-28-16	**Fuel - Fuel Vent System Modification**							T (-)		Optional	
28 A/F						Mos					
Eff: 22-Feb-2016						Hrs					
(AVG MAN HRS: 9)						Ldg					
45-28-16 Rev 1	**Fuel - Fuel Vent System Modification**							RE (-)		Optional	
28 A/F						Mos	16-Apr-2019				
Eff: 06-Sep-2016 Complied With						Hrs					
(AVG MAN HRS: 9)						Ldg					
45-28-2	**Fuel - Relocation of the Single Point Pressure Refueling (SPPR) Pilot Valve**							RE (-)		Optional	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-2 Rev 1	**Fuel - Relocation of the Single Point Pressure Refueling (SPPR) Pilot Valve**							RE (-)		Optional	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-28-2 Rev 2	**Fuel - Relocation of the Single Point Pressure Refueling (SPPR) Pilot Valve**							RE (-)		Optional	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-2 Rev 3	**Fuel - Relocation of the Single Point Pressure Refueling (SPPR) Pilot Valve**							RE (-)		Optional	
28 A/F						Mos	29-Aug-2019				
Eff: 14-Sep-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-28-3	**Fuel - Inspection/Modification of Wing Sealing Installation**							RE (-)		Recommended	
28 A/F						Mos	29-Aug-2019				
Eff: 18-May-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-28-4	**Fuel - Removal of Low Level Fuel Sensor**							RE (-)		Recommended	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-4 Rev 1	**Fuel - Removal of Low Level Fuel Sensor**							RE (-)		Recommended	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-4 Rev 2	**Fuel - Removal of Low Level Fuel Sensor**							RE (-)		Recommended	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-4 Rev 3	**Fuel - Removal of Low Level Fuel Sensor**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 04-Mar-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-28-5	**Fuel - Fuel Quantity Indication System Improvement**							RE (-)		Recommended	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-5 Rev 1	**Fuel - Fuel Quantity Indication System Improvement**							RE (-)		Recommended	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-5 Rev 2	**Fuel - Fuel Quantity Indication System Improvement**							RE (-)		Recommended	
28 A/F						Mos	08-Jun-2009				
Eff: 30-Jun-2008 Not Applicable						Hrs	801				
						Ldg	521				
45-28-5 Rev 3	**Fuel - Fuel Quantity Indication System Improvement**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 20-Mar-2017 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 98)						Ldg	2,822				
45-28-6	**Fuel - Inspection of Fuel Tubes Adjacent to the Toilet Servicing Panel**							RE (-)		Recommended	
28 A/F						Mos	08-Jun-2009				
Not Applicable	PER A/C S/N					Hrs	801				
						Ldg	521				
45-28-6 Rev 1	**Fuel - Inspection of Fuel Tubes Adjacent to the Toilet Servicing Panel**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 22-Jun-2009 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-28-7	**Fuel - Installation of Corrosion Protected Fuel Tube Assemblies**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 02-Jul-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-28-8	**Fuel - Modification of the Fuel Imbalance CAS Message Logic**							RE (-)		Recommended	
28 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-28-8 Rev 1	**Fuel - Modification of the Fuel Imbalance CAS Message Logic**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 15-Sep-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-28-9	**Fuel - Modification of Fuel Bay Drainage and Sumping**							RE (-)		Recommended	
28 A/F						Mos	14-Dec-2020				
Eff: 27-Apr-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
A45-28-10	**Fuel - Inspection of the Wing Fuel Tanks for Foreign Object Contaminates**							RE (-)		Alert	
28 A/F						Mos	13-Mar-2008				
Eff: 27-Apr-2006 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 7)						Ldg					
A45-28-10 Rev 1	**Fuel - Inspection of the Wing Fuel Tanks for Foreign Object Contaminates**							RE (-)		Alert	
28 A/F						Mos	14-Dec-2020				
Eff: 08-May-2006 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 7)						Ldg	2,822				
AW 28-007	**APU Fuel Line**							RE (-)		Advisory Wire	
28 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 28-008	**Single Point Pressure Refueling Placard**							RE (-)		Advisory Wire	
28 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 28-010	**APU Fuel Supply Drain Line. M45 With APU Installed**							RE (-)		Advisory Wire	
28 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 28-011	**40/45/45XR Wing Fuel Tanks**							RE (-)		Advisory Wire	
28 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 28-012	**Learjet 40/45/45XR Aircraft That Have Not Complied With The Initial 600-Hour B4 Phase Inspection**							RE (-)		Advisory Wire	
28 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
D200906000007 Rev 2	**Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
28 ENG1						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D200906000007 Rev 2	**Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
28 ENG2						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D201907000030	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG1						Mos					
Eff: 13-Aug-2019						Hrs					
						Enc					
D201907000030	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG2						Mos					
Eff: 13-Aug-2019						Hrs					
						Enc					
D201907000030 Rev 1	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG1						Mos					
Eff: 07-May-2020						Hrs					
						Enc					
D201907000030 Rev 1	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG2						Mos					
Eff: 07-May-2020						Hrs					
						Enc					
D201907000030 Rev 2	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
28 ENG1						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D201907000030 Rev 2	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
28 ENG2						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D2820013	**Perform Initial cleaning and leak check of low pressure fuel filters.**							RE (-)		TLMC 05-19-00	
28 A/F						Mos	15-Apr-2008				
						Hrs	48.7		-/+25		
Alias1:28-20-15 (ZONE: 510AL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 28-20-15.)						Ldg	48				
Note: The repeat inspection of the low pressure fuel filter is located in the Phase B4 Inspection/Checks, 5-12-04.)											
F2840003	**** Fuel Quantity Signal Conditioner - Perform functional test to verify Weight-on-Wheels (WOW) inputs.**							RE	TLMC 04-10-00, TLMC 05-13-02, Ch.5 Interval		**≈24-Apr-2025**
28 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Ref:28-40-00 (ZONE: 200) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 28-40-00.))						Ldg	3,757				
H2840001	*** Dual Fuel Flow Convertor (DFFC) (P/N 10540B06F07) - Perform Acceptance Test and Low Temperature Screening.**							RE (N/A)	TLMC 04-10-00, TLMC 05-19-00		
28 A/F						Mos					
10540B08F07						Hrs					
07101077A						Ldg					
(ZONE: 320) (SOURCE: MM-104) (NOTE: Note: Removal and replacement of DFFC is required for these tests. After removal, return DFFC to Learjet with a Parts Return Claim Form so unit can be exchanged with serviceable unit and returned to vendor for testing.)											
Y2810001	**Wing Tanks - Remove fuel tank access panels and perform Visual Inspection.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
28 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Ref:5-10-00/p201 (ZONE: 520AL,520DL,520GL,520ML, 620AR,620DR,620GR,620MR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	3,757				
Y2810002	**Wing Tanks - Remove Fuel Tank Access panels and perform Visual Inspection.**							RE		TLMC 05-14-04	**≈12-Oct-2025**
28 A/F	05-14-04					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
REf:5-10-00/p201 (ZONE: 520AL thru 520ML and 620AR thru 620MR) (SOURCE: MM-104, MM-105)						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
Y2820000	**Low Pressure Fuel Filter - Remove and inspect for contamination. Clean if necessary.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
28 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:28-20-15 (ZONE: 510AL, 610AR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 28-20-15.))					Ldg	3,757				
▼ 29 - HYDRAULIC POWER											
	Auxiliary Filter Manifold Assembly							RE (O/C)			
29 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Auxiliary Hudraulic Pressure Check Valve							RE (O/C)			
29 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Auxiliary Hydraulic Pump							RE (O/C)			
29 A/F			7			Mos	14-Apr-2014				
66158-02						Hrs	3,131.8				
K0058						Ldg	1,831				
	Auxiliary Hydraulic Pump Assembly							RE (O/C)			
29 A/F			12			Mos	14-Nov-2013				
66158-02						Hrs	3,011.7				
K0177						Ldg	1,768				
	Auxiliary Hydraulic Pump Electric Motor							RE (O/C)			
29 A/F			0			Mos	14-Jun-2013				
48-16-1/24470	Overhauled		0			Hrs	2,871.6				
ELE0727A			0			Ldg	1,684				
	Auxiliary Hydraulic Pump Low Pressure Switch							RE (O/C)			
29 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Auxiliary Pressure, Hydraulic System (S29) Switch							RE (O/C)			
29 A/F						Mos	30-Jul-2010				
6629101004-001						Hrs	1,499.8				
0278						Ldg	910				
	Ground Service Control Box							RE (O/C)			
29 A/F		0				Mos	13-Mar-2008				
4529308000-013	New	0				Hrs	0				
AS0213		0				Ldg	0				
	Hydraulic Low (S8, S9) Pressure Switch							RE (O/C)			
29 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Hydraulic Low (S8, S9) Pressure Switch							RE (O/C)			
29 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Hydraulic Pressure Transducer							RE (O/C)			
	29 A/F	No.1	0				Mos	13-Mar-2008				
	7629301001-001	New	0				Hrs	0				
	7304-4-215		0				Ldg	0				
		Hydraulic Pressure Transducer							RE (O/C)			
	29 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Hydraulic Reservoir							RE (O/C)			
	29 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Hydraulic System Shut-Off Valve							RE (O/C)			
	29 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Hydraulic System Shut-Off Valve							RE (O/C)			
	29 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Hydraulic, Engine Driven Pump							RE (O/C)			
	29 A/F	No.1	0				Mos	13-Mar-2008				
	848888	New	0				Hrs	0				
	MX715256A		0				Ldg	0				
		Hydraulic, Engine Driven Pump							RE (O/C)			
	29 A/F	No.2	0				Mos	13-Mar-2008				
	848888	New	0				Hrs	0				
	MX715254A		0				Ldg	0				
		L8 Hydraulic Shutoff Valve							RE (O/C)			
	29 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		L9 Hydraulic Shutoff Valve							RE (O/C)			
	29 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Hydraulic Filter Manifold							RE (O/C)			
	29 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Hydraulic System Accumulator							RE (O/C)			
	29 A/F		0				Mos	13-Mar-2008				
	88746-1	New	0				Hrs	0				
	478		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Pressure, Main Hydraulic System Switch							RE (O/C)			
29 A/F	6629101004-001 0305	No.1					Mos	30-Jul-2010				
							Hrs	1,499.8				
							Ldg	910				
		Pressure, Main Hydraulic System Switch							RE (O/C)			
29 A/F	6629101004-001 0279	No.2					Mos	30-Jul-2010				
							Hrs	1,499.8				
							Ldg	910				
		Reservoir Fluid Level Sensor							RE (O/C)			
29 A/F	3L14F-17 716	New	0				Mos	13-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
		Reservoir Pressurization Control Module							RE (O/C)			
29 A/F	ZVM11-2 07-0813144	New	0				Mos	13-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
		Thermal Shutoff Valve							RE (O/C)			
29 A/F	98050 0795	New	0				Mos	13-Mar-2008				
			0				Hrs	0				
			0				Ldg	0				
2009-11-13		**Hydraulic Power (Superseded by AD 2011-13-10)**							RE (-)		Mandatory	
29 A/F	Eff: 17-Jun-2009 Complied With						Mos	28-Jan-2010				
							Hrs	1,172.9				
							Ldg	723				
2009-11-13 PARAGRAPH (G)		**Detailed Inspection Chafed Hydraulic Tubes In The Left-Hand Engine. (Superseded By Ad 2011-13-10) Case Drain Tube**							RE (-)			
29 A/F							Mos					
							Hrs					
							Ldg					
2009-11-13 PARAGRAPH (H)		**Detailed Inspection Chafed Hydraulic Tubes In The Left-Hand Engine. (Superseded By Ad 2011-13-10) Nacelle Tubing**							RE (-)			
29 A/F	Complied With						Mos	28-Jan-2010				
							Hrs	1,172.9				
							Ldg	723				
2009-11-13 PARAGRAPH (I)		**Detailed Inspection Chafed Hydraulic Tubes In The Left-Hand Engine. (Superseded By Ad 2011-13-10) For Fluid Leakage And Inadequate Clearance (Remove Clamp)**							RE (-)			
29 A/F	Complied With						Mos	28-Jan-2010				
							Hrs	1,172.9				
							Ldg	723				
2009-11-13 PARAGRAPH (J)		**Replace Chafed Hydraulic Tubes In The Left-Hand Engine. (Superseded By Ad 2011-13-10) Clamp**							RE (-)		Mandatory	
29 A/F	Complied With						Mos	28-Jan-2010				
							Hrs	1,172.9				
							Ldg	723				
45-29-1		**Hydraulic Power - Installation of Hydraulic Servicing Union**							RE (-)		Recommended	
29 A/F	Not Applicable	BY SERIAL NUMBER					Mos	13-Mar-2008				
							Hrs	8.7				
							Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-29-1 Rev 1	**Hydraulic Power - Installation of Hydraulic Servicing Union**							RE (-)		Recommended	
29 A/F						Mos	14-Dec-2020				
Eff: 11-Jan-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-29-10	**Hydraulic Power - Inspection and Replacement of Hydraulic Line Chafing**							RE (-)		Recommended	
29 A/F						Mos	14-Dec-2020				
Eff: 13-Jul-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-29-11	**Hydraulic Power - Inspection/Modification of Hydraulic Line Chafing**							RE (-)		Recommended	
29 A/F						Mos	14-Dec-2020				
Eff: 06-Dec-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-29-12	**Hydraulic Power - Modification of the Hydraulic Reservoir Quantity Indication**							RE (-)		Recommended	
29 A/F						Mos	14-Dec-2020				
Eff: 30-Apr-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-29-14	**Hydraulic Power - Modification of the Emergency/Park Brake Accumulator Hydraulic Line**							T (-)		Optional	
29 A/F						Mos					
Eff: 20-Oct-2008						Hrs					
						Ldg					
45-29-14 Rev 1	**Hydraulic Power - Modification of the Emergency/Park Brake Accumulator Hydraulic Line**							T (A/R)		Optional	
29 A/F						Mos					
Eff: 16-Aug-2021						Hrs					
(AVG MAN HRS: 8.5)						Ldg					
45-29-16	**Hydraulic Power - Inspection/Replacement of the Left Engine Hydraulic Tubes at Nacelle Station 183.77**							RE (-)		Recommended	
29 A/F						Mos	08-Jan-2009				
Eff: 09-Apr-2008 Complied With	L/H ENGINE INSPECTION/REPLACEMENT OF HYD LINE					Hrs	601.9				
						Ldg	413				
45-29-17	**Hydraulic Power - Replacement of the Hydraulic System Low Pressure Switch Assemblies**							RE (-)		Recommended	
29 A/F						Mos					
Eff: 29-Jan-2010						Hrs					
(AVG MAN HRS: 9)						Ldg					
45-29-17 Rev 1	**Hydraulic Power - Replacement of the Hydraulic System Low Pressure Switch Assemblies**							RE (-)		Recommended	
29 A/F						Mos	30-Jul-2010				
Eff: 29-Mar-2010 Complied With						Hrs	1,499.8				
(AVG MAN HRS: 9)						Ldg	910				
45-29-17 Rev 2	**Hydraulic Power - Replacement of the Hydraulic System Low Pressure Switch Assemblies**							RE (-)		Recommended	
29 A/F						Mos	01-Mar-2013				
Eff: 28-Jan-2013 Complied With	HYDRAULIC REPLACEMENT OF HYD SYSTEM LOW PRESS SWITCH ASSEMBLIES					Hrs	2,753.9				
(AVG MAN HRS: 9)						Ldg	1,625				
45-29-18	**Hydraulic Power - Eaton Hydraulic Pump Sealing Screw Inspection**							RE (-)		Recommended	
29 A/F						Mos					
Eff: 14-Oct-2019 Deferred	PER BOB FOX TASK SUPPRESSED; WILL NOT DO ANY TIME SOON.					Hrs					
(AVG MAN HRS: 4.5)						Ldg					
45-29-2	**Hydraulic Power - Installation of Hydraulic Pressure Line Brackets and Clamps**							RE (-)		Recommended	
29 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ	Description / PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-29-2 Rev 1	**Hydraulic Power - Installation of Hydraulic Pressure Line Brackets and Clamps**								RE (-)		Recommended	
29 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				
45-29-2 Rev 2	**Hydraulic Power - Installation of Hydraulic Pressure Line Brackets and Clamps**								RE (-)		Recommended	
29 A/F							Mos	14-Dec-2020				
Eff: 13-Apr-2001 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-29-3	**Hydraulics - Modification of Aft Fuselage Hydraulic Line**								RE (-)		Recommended	
29 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				
45-29-3 Rev 1	**Hydraulics - Modification of Aft Fuselage Hydraulic Line**								RE (-)		Recommended	
29 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				
45-29-3 Rev 2	**Hydraulics - Modification of Aft Fuselage Hydraulic Line**								RE (-)		Recommended	
29 A/F							Mos	14-Dec-2020				
Eff: 15-Jan-2007 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-29-4	**Hydraulics - Modification of Engine Hydraulic Line Clearance**								RE (-)		Recommended	
29 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				
45-29-4 Rev 1	**Hydraulics - Modification of Engine Hydraulic Line Clearance**								RE (-)		Recommended	
29 A/F							Mos	14-Dec-2020				
Eff: 17-Mar-2000 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-29-6	**Hydraulic Power - Hydraulic Reservoir Quantity Indication**								RE (-)		Optional	
29 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				
45-29-6 Rev 1	**Hydraulic Power - Hydraulic Reservoir Quantity Indication**								RE (-)		Optional	
29 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				
45-29-6 Rev 2	**Hydraulic Power - Hydraulic Reservoir Quantity Indication**								RE (-)		Optional	
29 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				
45-29-6 Rev 3	**Hydraulic Power - Hydraulic Reservoir Quantity Indication**								RE (-)		Optional	
29 A/F							Mos	29-Aug-2019				
Eff: 30-May-2003 Not Applicable							Hrs	4,516.2				
							Ldg	2,733				
45-29-7	**Hydraulics Power - Installation of Hydraulic Bleeder Fittings**								RE (-)		Optional	
29 A/F							Mos	29-Aug-2019				
Eff: 22-Dec-2004 Not Applicable							Hrs	4,516.2				
							Ldg	2,733				
45-29-8	**Hydraulics - Replacement of Titanium Hydraulic Tube Assemblies**								RE (-)		Recommended	
29 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-29-8 Rev 1	**Hydraulics - Replacement of Titanium Hydraulic Tube Assemblies**							RE (-)		Recommended	
29 A/F						Mos	14-Dec-2020				
Eff: 12-Nov-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-29-9	**Hydraulics - Installation of Auxiliary Hydraulic Pump Drain Accessory Kit**							RE (-)		Recommended	
29 A/F						Mos	14-Dec-2020				
Eff: 15-Feb-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
75-29-01	**Hydraulic Power - Eaton Hydraulic Pump Sealing Screw Inspection**							RE (-)		Recommended	
29 A/F						Mos					
Eff: 14-Oct-2019						Hrs					
(AVG MAN HRS: 3.5)						Ldg					
A45-29-15	**Hydraulic Power - Inspection/Replacement of the Left Hydraulic Pump Case Drain Tube**							RE (-)		Alert	
29 A/F						Mos	14-Dec-2020				
Eff: 26-Dec-2006 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 4)						Ldg	2,822				
AW 29-008	**Engine-Driven Hydraulic Pump Pressure Port**							RE (-)		Advisory Wire	
29 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
D2910017	**Main Hydraulic Filter Manifold elements.**							RE (-)		TLMC 05-19-01	
29 A/F						Mos					
						Hrs			-/+25		
Alias1:29-10-03 (ZONE: 310DL, 310LR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 29-10-03.))						Ldg					
D2910018	**Main Hydraulic Filter Manifold elements - Replace.**							RE		TLMC 05-19-01	**≈24-Jul-2024**
29 A/F						Mos	09-Feb-2024				
						Hrs	5,253.5	300	-/+25	5,553.5	278.7 Hrs (+25)
Alias1:29-10-03 (ZONE: 310DL, 310LR) (SOURCE: MM-104, MM-105)						Ldg	3,757				
H2920002	**Hydraulic System Ground Service LEDs - Perform Functional Test.**							RE (N/A)		TLMC 05-13-01	
29 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8				
Ref:29-30-00 (ZONE: 200) (SOURCE: MM-104) (NOTE: (Refer to 29-30-00.))						Ldg	2,807				
O2910005	**Auxiliary Hydraulic Filter Manifold Elements - Replace.**							RE		TLMC 05-19-01	**≈25-Apr-2026**
29 A/F						Mos	09-Feb-2024				
						Hrs	5,253.5	2,400	-/+25	7,653.5	2,378.7 Hrs (+25)
(ZONE: 310DL, 310LR) (SOURCE: MM-104, MM-105)						Ldg	3,757				
T2910026	**Relief Function of the Hydraulic Reservoir Pres- surization Control Module - Perform Functional Test.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
29 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:29-10-06 (ZONE: 310JR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 29-10-06.))						Ldg	3,757				
Y2910001	**Hydraulic Components and Associated Plumbing (Aft of Fuselage Fuel Cell, FS 495 to FS 512) - Perform Visual Inspection.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
29 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 310DL, 310LR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) Note: For minimum clearance of hydraulic tubing, refer to 20-30-00.)						Ldg	3,757				
Y2910002	**Hydraulic Components and Associated Plumbing (Wheel Well and Forward Area of Rear Spar) - Perform Visual Inspection.**							RE		TLMC 05-13-05	**≈24-Apr-2025**
29 A/F	05-13-05					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 720AL/ 720BL/ 730AR/ 730BR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y2910003	**Hydraulic Components and Associated Plumbing (Aft Area of Rear Spar) - Perform Visual Inspection.**							RE		TLMC 05-14-01	**≈12-Oct-2025**
29 A/F	05-14-01					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Ref:5-10-00, Ref:20-30-00 (ZONE: 250CC, 250FL, 250GR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) Note: For minimum clearance of hydraulic tubing, refer to 20-30-00.)					Ldg	2,822				
Y2920001	**Auxiliary Hydraulic System - Perform Operational Check.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
29 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:29-20-00 (ZONE: 200) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 29-20-00.))					Ldg	3,757				
▼ 30 - ICE AND RAIN PROTECTION											
	Anti-Ice Duct Assembly							RE (O/C)			
30 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Anti-Ice Manifold Assembly							RE (O/C)			
30 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Anti-Ice Pressure Regulating Shutoff (PRSOV L12) Valve							RE (O/C)			
30 A/F		0				Mos	13-Mar-2008				
3215616-2	New	0				Hrs	0				
1154		0				Ldg	0				
	Anti-Ice Pressure Regulating Shutoff (PRSOV L13) Valve							RE (O/C)			
30 A/F		0				Mos	13-Mar-2008				
3215616-2	New	0				Hrs	0				
1157		0				Ldg	0				
	Anti-Ice Tube Assembly							RE (O/C)			
30 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Anti-Ice Tube Assembly							RE (O/C)			
30 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Check, Anti-Ice (2.0 Diameter) Valve							RE (O/C)			
30 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Check, Anti-Ice (2.0 Diameter) Valve							RE (O/C)			
30 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Horizontal Stabilizer Control (MT46) Sensor							RE (O/C)			
30 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Ice Detection Probe							RE (O/C)			
30 A/F	0871HN2	New	0				Mos	13-Mar-2008				
0500			0				Hrs	0				
			0				Ldg	0				
		Nacelle Anti-Ice Pressure Switch							RE (O/C)			
30 A/F	No.1						Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Nacelle Anti-Ice Pressure Switch							RE (O/C)			
30 A/F	No.2						Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Nacelle Inlet Anti-Ice Shutoff Valve							RE (O/C)			
30 A/F	No.1						Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Nacelle Inlet Anti-Ice Shutoff Valve							RE (O/C)			
30 A/F	No.2						Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Nose Relay (P15) Box							RE (O/C)			
30 A/F							Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Nose Relay (P16) Box							RE (O/C)			
30 A/F							Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Relay (P40) - Anti-Ice Vertical Stabilizer. Panel Assy							RE (O/C)			
30 A/F							Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Right Horizontal Stabilizer Control (MT47) Sensor							RE (O/C)			
30 A/F							Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Shuttle, Anti-Ice Valve							RE (O/C)			
30 A/F	Left						Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Shuttle, Anti-Ice Valve							RE (O/C)			
30 A/F	Right						Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Slide, Flex, Joint							RE (O/C)			
30 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Slide, Flex, Joint							RE (O/C)			
30 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Stab, Anti-Ice Elbow Duct							RE (O/C)			
30 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Windshield Anti-Ice Controller							RE (O/C)			
30 A/F					2	Mos	01-Sep-2017				
90825-9						Hrs	3,914.5				
516						Ldg	2,310				
	Wing Surface Temperature (MT42) Sensor							RE (O/C)			
30 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Wing Surface Temperature (MT43) Sensor							RE (O/C)			
30 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Wing Surface Temperature (MT44) Sensor							RE (O/C)			
30 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Wing Surface Temperature (MT45) Sensor							RE (O/C)			
30 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Wing Tube Assembly (Anti-Ice)							RE (O/C)			
30 A/F	Right Outboard					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
2001-03-05	**Anti-ice Manifold Assembly**							RE (-)		Mandatory	
30 A/F						Mos	11-Feb-2010				
Eff: 20-Feb-2001 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
						Ldg	739				
2001-03-05 PARA (A)	**Revise Afm**							RE (A/R)		Mandatory	
30 A/F						Mos	11-Feb-2010				
Not Applicable						Hrs	1,203.8				
						Ldg	739				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2001-03-05 PARA (B)	**Replace Anti-Ice Manifold**							RE (A/R)		Mandatory	
30 A/F						Mos	11-Feb-2010				
Not Applicable						Hrs	1,203.8				
						Ldg	739				
2001-03-05 PARA (C)	**Anti-Ice Manifold**							RE (A/R)		Mandatory	
30 A/F						Mos	11-Feb-2010				
Not Applicable						Hrs	1,203.8				
						Ldg	739				
45-30-09	**Ice and Rain Protection - Tailcone Avionics Bay Vent Adapter Replacement**							T (A/R)		Optional	
30 A/F						Mos					
Eff: 15-Aug-2016						Hrs					
(AVG MAN HRS: 9.5)						Ldg					
45-30-1	**Ice and Rain Protection - Improvement of Wing/Stab Anti-Ice System**							RE (-)		Optional	
30 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-30-1 Rev 1	**Ice and Rain Protection - Improvement of Wing/Stab Anti-Ice System**							RE (-)		Optional	
30 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-30-1 Rev 2	**Ice and Rain Protection - Improvement of Wing/Stab Anti-Ice System**							RE (-)		Optional	
30 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-30-1 Rev 3	**Ice and Rain Protection - Improvement of Wing/Stab Anti-Ice System**							RE (-)		Optional	
30 A/F						Mos	29-Aug-2019				
Eff: 16-Feb-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-30-3	**Fuselage - Inspection/Replacement of Honeywell Anti-ice Shuttle Valve**							RE (-)		Recommended	
30 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-30-3 Rev 1	**Fuselage - Inspection/Replacement of Honeywell Anti-ice Shuttle Valve**							RE (-)		Recommended	
30 A/F						Mos	14-Dec-2020				
Eff: 29-Sep-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-30-4	**Ice and Rain Protection - Inspection/Replacement of PerkinElmer Bleed Air Couplings in the Anti-Ice System**							RE (-)		Recommended	
30 A/F						Mos	14-Dec-2020				
Eff: 12-Apr-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-30-5	**Ice and Rain Protection - Modification of the Windshield Heat Circuit Wiring**							RE (-)		Recommended	
30 A/F						Mos	26-Jun-2008				
Not Applicable	PER A/C S/N					Hrs	237				
						Ldg	182				
45-30-5 Rev 1	**Ice and Rain Protection - Modification of the Windshield Heat Circuit Wiring**							RE (-)		Recommended	
30 A/F						Mos					
						Hrs					
						Ldg					
45-30-5 Rev 2	**Ice and Rain Protection - Modification of the Windshield Heat Circuit Wiring**							RE (-)		Recommended	
30 A/F						Mos	14-Dec-2020				
Eff: 19-Jan-2009 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-30-6	**Ice and Rain Protection - Inspection/Modification of the Horizontal Stabilizer Overheat Sensors**							RE (-)		Optional	
30 A/F						Mos					
						Hrs					
						Ldg					
45-30-6 Rev 1	**Ice and Rain Protection - Inspection/Modification of the Horizontal Stabilizer Overheat Sensors**							RE (-)		Optional	
30 A/F						Mos	29-Aug-2019				
Eff: 29-Mar-2010 Not Applicable	SUPERSEDED BY LEARJET SERVICE BULLETIN 45-30-8, "MODIFICATION OF THE HORIZONTAL STABILIZER PICCOLO TUBE ASSEMBLY".					Hrs	4,516.2				
						Ldg	2,733				
45-30-7	**Ice and Rain Protection - Inspection/Modification of the Wing Overheat and Temperature Control Sensors**							RE (-)		Optional	
30 A/F						Mos					
						Hrs					
						Ldg					
45-30-7 Rev 1	**Ice and Rain Protection - Inspection/Modification of the Wing Overheat and Temperature Control Sensors**							T (A/R)		Optional	
30 A/F						Mos					
Eff: 29-Mar-2010						Hrs					
						Ldg					
45-30-8	**Ice and Rain Protection - Modification of The Horizontal Stabilizer Piccolo Tube Assembly**							RE (-)		Optional	
30 A/F						Mos	30-Jul-2010				
Complied With						Hrs	1,499.8				
						Ldg	910				
45-30-8 Rev 1	**Ice and Rain Protection - Modification of The Horizontal Stabilizer Piccolo Tube Assembly**							RE (-)		Optional	
30 A/F						Mos	14-Jun-2013				
Eff: 02-Aug-2010 Complied With						Hrs	2,871.6				
						Ldg	1,684				
A3020000	**** Nacelle Anti-ice System - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-13-03, Ch.5 Interval		**≈24-Apr-2025**
30 A/F	05-13-03					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:30-20-00 (ZONE: 430/440) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 30-20-00.))						Ldg	3,757				
A3030000	**** Pitot/Static Heat System - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-14-01, Ch.5 Interval		**≈12-Oct-2025**
30 A/F	05-14-01					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
Alias1:30-30-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 30-30-00.))						Ldg	2,822				
A45-30-10	**Ice And Rain Protection - Nacelle Anti-Ice Tube Inspection**							RE (-)		Alert	
30 A/F						Mos	24-Feb-2017				
Eff: 25-Apr-2016 Complied With						Hrs	3,678				
(AVG MAN HRS: 3.5)						Ldg	2,147				
A45-30-2	**Ice and Rain Protection - Replacement of Anti-Ice Manifold Assembly**							RE (-)		Alert	
30 A/F						Mos	13-Mar-2008				
Eff: 18-Dec-2000 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 63)						Ldg					
A45-30-2 Rev 1	**Ice and Rain Protection - Replacement of Anti-Ice Manifold Assembly**							RE (-)		Alert	
30 A/F						Mos	14-Dec-2020				
Eff: 16-Jan-2001 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 63)						Ldg	2,822				
AC3010006	**** Anti-Ice Manifold - Perform Borescope Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈27-Sep-2024**
30 A/F						Mos	02-Jun-2023				
						Hrs	5,166.1	600	-/+25	5,766.1	491.3 Hrs (+25)
AMM:30-10-07 (ZONE: 310QR, 310HL) (SOURCE: MM-104, MM-105)						Ldg	3,185				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 30-006	**Replacement Of Anti-Ice Manifold Assembly**							RE (-)		Advisory Wire	
30 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 30-006 R1	**Replacement Of Anit-Ice Manifold Assembly**							RE (-)		Advisory Wire	
30 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 30-007	**Replacement Of Anti-Ice Manifold Assembly Update**							RE (-)		Advisory Wire	
30 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 30-008	**Progress Report On Replacement Of Model 45 Anti-Ice Manifold Assembly**							RE (-)		Advisory Wire	
30 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 30-009	**M45 Thermally Tempered Replacement Windshields**							RE (-)		Advisory Wire	
30 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 30-010	**Wing Anti-Ice Piccolo Tube Inspection**							RE (-)		Advisory Wire	
30 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 30-014 R01	**GKN Windshield Heat Terminals, Advisory Wire**							RE (-)		Informational	
30 A/F						Mos	28-Feb-2014				
Complied With						Hrs	3,094.2				
						Ldg	1,810				
H3010000	**** Wing/Stab Anti-Ice Switch - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
30 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:30-10-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 30-10-00.))						Ldg	3,757				
T3040000	**** Windshield Anti-ice - Perform Functional Test of the Windshield Anti-ice System**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
30 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:30-40-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 30-40-00.))						Ldg	3,757				
Y3010007	**Wing Anti-ice Piccolo Tube - Perform detailed visual inspection for cracks at W.S. 43 and W.S. 176.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
30 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
(ZONE: 530BL, 530CL, 630BR, 630CR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)						Ldg	3,757				
Y3080000	**Ice Detection System - Perform Functional Test.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
30 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:30-80-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 30-80-00.))						Ldg	3,757				
Z3020005	*** Power Plants, Nacelles and Thrust Reversers - Perform Detailed Visual/Borescope Inspection of the Left Engine Inlet Anti-ice Tube Assembly from the Aft Inlet Bulkhead Connection Point Forward to Spray Ring Connection, of the Welds Inside and Outside of the Tube at both Forward and Aft ends**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈08-Jul-2024**
30 A/F						Mos	09-Feb-2024				
						Hrs	5,253.5	250		5,503.5	228.7 Hrs
Ref:30-20-00 (ZONE: 430) (SOURCE: MM-104, MM-105)						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
Z3020005	*** Power Plants, Nacelles and Thrust Reversers - Perform Detailed Visual/Borescope Inspection of the Right Engine Inlet Anti-ice Tube Assembly from the Aft Inlet Bulkhead Connection Point Forward to Spray Ring Connection, of the Welds Inside and Outside of the Tube at both Forward and Aft ends**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈08-Jul-2024**
30 A/F						Mos	09-Feb-2024				
						Hrs	5,253.5	250		5,503.5	228.7 Hrs
Ref:30-20-00 (ZONE: 440) (SOURCE: MM-104, MM-105)						Ldg	3,757				
Z3020006	**Power Plants, Nacelles and Thrust Reversers - Left Engine - Perform Detailed Visual/Borescope Inspection of the Welds Inside and Outside of the Tube at Both Forward and aft ends of the Inlet Anti-ice Tube Assembly from the aft Inlet Bulkhead Connection Point Forward to Spray Ring Connection**							RE (N/A)		TLMC 05-19-00	
30 A/F						Mos	12-Mar-2018				
						Hrs	4,155.2				
Ref:30-20-00 (ZONE: 430) (SOURCE: MM-104, MM-105)						Ldg					
Z3020006	**Power Plants, Nacelles and Thrust Reversers - Right Engine Perform Detailed Visual/Borescope Inspection of the Welds Inside and Outside of the Tube at Both Forward and aft ends of the Inlet Anti-ice Tube Assembly from the aft Inlet Bulkhead Connection Point Forward to Spray Ring Connection**							RE (N/A)		TLMC 05-19-00	
30 A/F						Mos	12-Mar-2018				
						Hrs	4,155.2				
Ref:30-20-00 (ZONE: 440) (SOURCE: MM-104, MM-105)						Ldg					
▼ 31 - INDICATING / RECORDING SYSTEM											
	Circuit Breaker Panel Assy							RE (O/C)			
31 A/F	Copilot					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Circuit Breaker Panel Assy							RE (O/C)			
31 A/F	Pilot					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Clock							RE (O/C)			
31 A/F	Copilot					Mos	03-Mar-2022				
6420093-3	New	0	0	0		Hrs	4,883				
LT21-13227		0	0	0		Ldg	3,012				
(ZONE: 200)											
	Clock							RE (O/C)			
31 A/F	Pilot					Mos	03-Mar-2022				
6420093-3	New	0	0	0		Hrs	4,883				
LT21-13228		0	0	0		Ldg	3,012				
(ZONE: 200)											
	Crew Warning Panel Assembly							RE (O/C)			
31 A/F		0				Mos	13-Mar-2008				
90-42801-8	New	0				Hrs	0				
546		0				Ldg	0				
	Data Acquisition (DAU) Unit							RE (O/C)			
31 A/F	No.1					Mos	18-Sep-2012				
7013348-938						Hrs	2,631.6				
07096617						Ldg	1,558				
	Data Acquisition (DAU) Unit							RE (O/C)			
31 A/F	No.2					Mos	18-Sep-2012				
7013348-938						Hrs	2,631.6				
07096620						Ldg	1,558				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Data Transfer, AFIS Unit							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Data Unit Controller							RE (O/C)			
	31 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Data Unit Controller							RE (O/C)			
	31 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		DU870 Display Unit							RE (O/C)			
	31 A/F	No.1				0	Mos	11-Mar-2011				
	7014300-901	Repaired				0	Hrs	1,857.4				
	97112591					0	Ldg	1,121				
		DU870 Display Unit							RE (O/C)			
	31 A/F	No.2	36				Mos	11-Mar-2011				
	7014300-901		1,857.4				Hrs	1,857.4				
	0710G690		1,121				Ldg	1,121				
		DU870 Display Unit							RE (O/C)			
	31 A/F	No.3				0	Mos	04-Dec-2008				
	7014300-901	Repaired				0	Hrs	557.8				
	01048995					0	Ldg	391				
		DU870 Display Unit							RE (O/C)			
	31 A/F	No.4	0				Mos	13-Mar-2008				
	7014300-901	New	0				Hrs	0				
	0710G692		0				Ldg	0				
		EFIS Display Controller							RE (O/C)			
	31 A/F	Copilot				2	Mos	05-Mar-2021				
	7016986-733	Repaired				0	Hrs	4,624.8				
	08077320					0	Ldg	2,834				
		EFIS Display Controller							RE (O/C)			
	31 A/F	Pilot	0				Mos	13-Mar-2008				
	7016986-733	New	0				Hrs	0				
	07107041		0				Ldg	0				
		Engine Fuel Control (P7) Panel Assy							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Engine/Fuel Control Panel Overlay							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		FDR Accelerometer							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		FDR Inertia Switch							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Flight Data Recorder							RE (O/C)			
	31 A/F	FDR					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Flight Data Recorder Underwater Locator Beacon							RE (O/C)			
	31 A/F	FDR					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Forward Quadrant Switch Panel (P6) Overlay							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Gear Up/Down S47 Switch							RE (O/C)			
	31 A/F		0				Mos	02-Jun-2012				
	A3-1295	New	0				Hrs	2,486.4				
	Unknown		0				Ldg	1,480				
		Inclinometer Assembly							RE (O/C)			
	31 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Inclinometer Assembly							RE (O/C)			
	31 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Integrated Avionics (IC-600) Computer							RE (O/C)			
	31 A/F	No.1					Mos	21-Sep-2009				
	7017000-82224						Hrs	959.2				
	07108234						Ldg	607				
		Integrated Avionics (IC-600) Computer							RE (O/C)			
	31 A/F	No.2				4	Mos	04-Nov-2014				
	7017000-82224						Hrs	3,314				
	1107A361						Ldg	1,937				
		Mfd Controller Bezel							RE (O/C)			
	31 A/F	Copilot - Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Mfd Controller Bezel							RE (O/C)			
	31 A/F	Copilot - Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Mfd Controller Bezel							RE (O/C)			
	31 A/F	Pilot - Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Mfd Controller Bezel							RE (O/C)			
	31 A/F	Pilot - Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		No. 1 Central Computing Im-600 Memory Module							RE (O/C)			
	31 A/F	No.1	0				Mos	13-Mar-2008				
	7025973-04214	New	0				Hrs	0				
	06114409		0				Ldg	0				
		No. 2 Central Computing Im-600 Memory Module							RE (O/C)			
	31 A/F	No.2	0				Mos	13-Mar-2008				
	7025973-04214	New	0				Hrs	0				
	07055111		0				Ldg	0				
		Panel, Center Switch Replace							RE (O/C)			
	31 A/F						Mos	07-Jul-2017				
	4525108065-017						Hrs	3,874.5				
	Unknown						Ldg	2,279				
		Rudder Boost (DS48) Switch							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Selcal Decoder							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Switch, Reversion, Pilot (V91812), (S135)							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
2002-20-09		**Rockwell Collins - AFD-3010 Adaptive Flight Display Units**							RE (-)	Mandatory (Appliance AD)		
	31 A/F						Mos	31-Mar-2008				
	Eff: 12-Nov-2002 Not Applicable						Hrs	11.6				
	Brand A:9990-2002-20-09						Ldg	11				
310000-0101		**Hobbs Meter**							RE (O/C)			
	31 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-31-1	**Indicating/Recording - Modification of MCOS II Maintenance Connector Wiring**							RE (-)		Optional	
31 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-31-1 Rev 1	**Indicating/Recording - Modification of MCOS II Maintenance Connector Wiring**							RE (-)		Optional	
31 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-31-1 Rev 2	**Indicating/Recording - Modification of MCOS II Maintenance Connector Wiring**							RE (-)		Optional	
31 A/F						Mos	29-Aug-2019				
Eff: 12-Jan-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-31-2	**Indicating/Recording Systems - Installation of Flight Data Recorder (FDR) 128 Word Upgrade**							RE (-)		Optional	
31 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-31-2 Rev 1	**Indicating/Recording Systems - Installation of Flight Data Recorder (FDR) 128 Word Upgrade**							RE (-)		Optional	
31 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-31-2 Rev 2	**Indicating/Recording Systems - Installation of Flight Data Recorder (FDR) 128 Word Upgrade**							RE (-)		Optional	
31 A/F						Mos	29-Aug-2019				
Eff: 22-Jul-2005 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-31-3	**Indicating/Recording Systems - Modification of the Engine/Fuel Control Switches**							RE (-)		Optional	
31 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-31-3 Rev 1	**Indicating/Recording Systems - Modification of the Engine/Fuel Control Switches**							RE (-)		Optional	
31 A/F						Mos	29-Aug-2019				
Eff: 30-Apr-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-31-4	**Indicating/Recording Systems - Improved Removal/Installation of the #1 Data Acquisition Unit (DAU)**							RE (-)		Optional	
31 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-31-4 Rev 1	**Indicating/Recording Systems - Improved Removal/Installation of the #1 Data Acquisition Unit (DAU)**							RE (-)		Optional	
31 A/F						Mos	29-Aug-2019				
Eff: 22-Jun-2009 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-31-5	**Indicating/Recording Systems - Modification of the Right Switch Panel Wiring**							RE (-)		Optional	
31 A/F						Mos	02-Jun-2008				
Not Applicable	PER A/C S/N					Hrs					
						Ldg					
45-31-5 Rev 1	**Indicating/Recording Systems - Modification of the Right Switch Panel Wiring**							RE (-)		Optional	
31 A/F						Mos	29-Aug-2019				
Eff: 17-Nov-2008 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-31-6	**Landing Gear - Landing Gear Switch Quick Disconnect Installation**							T (A/R)		Optional	
31 A/F						Mos					
Eff: 03-Feb-2014						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-31-7	**Indicating/ Recording Systems - Hour Meter Relocation**							RE (-)		Optional	
31 A/F						Mos	29-Aug-2019				
Eff: 06-Jun-2016 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 10)						Ldg	2,733				
75-31-06	**Indicating/ Recording Systems - Garmin Phase IIC Baseline Software Upgrade**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 13-Jun-2016						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-06 Rev 1	**Indicating/ Recording Systems - Garmin Phase IIC Baseline Software Upgrade**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 01-Aug-2016						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-06 Rev 2	**Indicating/ Recording Systems - Garmin Phase IIC Baseline Software Upgrade**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 15-Aug-2016						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-06 Rev 3	**Indicating/ Recording Systems - Garmin Phase IIC Baseline Software Upgrade**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 19-Sep-2016						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-06 Rev 4	**Indicating/ Recording Systems - Garmin Phase IIC Baseline Software Upgrade**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 28-Sep-2016						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-06 Rev 5	**Indicating/ Recording Systems - Garmin Phase IIC Baseline Software Upgrade**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 06-Dec-2016						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-06 Rev 6	**Indicating/ Recording Systems - Garmin Phase IIC Baseline Software Upgrade**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 20-May-2019						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-08	**Indicating/Recording Systems - Garmin Phase IIC+ Baseline Software Update for Flight Director Mode Change**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 31-Mar-2017						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-08 Rev 1	**Indicating/Recording Systems - Garmin Phase IIC+ Baseline Software Update for Flight Director Mode Change**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 12-Jun-2017						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-08 Rev 2	**Indicating/Recording Systems - Garmin Phase IIC+ Baseline Software Update for Flight Director Mode Change**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 20-May-2019						Hrs					
(AVG MAN HRS: 4)						Ldg					
75-31-09	**Indicating/Recording Systems - Garmin Phase IID Baseline Software Update for Engine Chip Detection**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 21-Dec-2017						Hrs					
(AVG MAN HRS: 5)						Ldg					
75-31-09 Rev 1	**Indicating/Recording Systems - Garmin Phase IID Baseline Software Update for Engine Chip Detection**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 20-May-2019						Hrs					
(AVG MAN HRS: 5)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
75-31-09 Rev 2	**Indicating/Recording Systems - Garmin Phase IID Baseline Software Update for Engine Chip Detection**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 19-Dec-2019						Hrs					
(AVG MAN HRS: 5)						Ldg					
75-31-11	**Indicating/Recording Systems - Garmin Phase III Software Upgrade - Baseline**							RE (-)		Optional	
31 A/F						Mos					
Eff: 30-Mar-2020						Hrs					
(AVG MAN HRS: 9)						Ldg					
75-31-12	**Indicating/Recording Systems - Garmin Phase III Upgrade - TOLD**							RE (-)		Optional	
31 A/F						Mos					
Eff: 30-Mar-2020						Hrs					
(AVG MAN HRS: 1.25)						Ldg					
75-31-13	**Indicating/Recording Systems - Phase III Link 2000-Accessory Kit**							RE (-)		Optional	
31 A/F						Mos					
Eff: 30-Mar-2020						Hrs					
(AVG MAN HRS: 1.25)						Ldg					
75-31-13 Rev 1	**Indicating/Recording Systems - Garmin Phase III Link 2000-Accessory Kit**							RE (-)		Optional	
31 A/F						Mos					
Eff: 10-Aug-2020						Hrs					
(AVG MAN HRS: 1.25)						Ldg					
75-31-14	**Indicating/Recording Systems - Garmin Phase IID+ Software Upgrade**							RE (-)		Recommended	
31 A/F						Mos					
Eff: 15-Nov-2021						Hrs					
(AVG MAN HRS: 4)						Ldg					
B3100000	**** Indicating/Recording System - Perform Operational Check.**							RE	TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
31 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:31-00-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 31-00-00.))						Ldg	3,757				
B3100000-4A	**** Integrated Avionics Computer - Perform Symbol Generation Reversion Check.**							RE (N/A)	TLMC 04-10-00, Ch.5 Interval		
31 A/F						Mos					
						Hrs					
(ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg					
B3100000-4B	**** Engine Indicating and Crew Alerting System (EICAS) - Perform Data Acquisition Units (DAU) Reversion Check.**							RE (N/A)	TLMC 04-10-00, Ch.5 Interval		
31 A/F						Mos					
						Hrs					
(ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg					
P3121000	**Davtron M850 Digital Clock Battery - Replace.**							RE		TLMC 05-19-01	
31 A/F	Copilot					Yrs	03-Mar-2022	10		03-Mar-2032	7.8 Years
6420093-3						Hrs	4,883				
LT21-13227						Ldg	3,012				
Alias1:31-21-02 (ZONE: 200) (UPDATE NOTE: Battery replaced new.) (SOURCE: MM-104, MM-105)											
P3121000	**Davtron M850 Digital Clock Battery - Replace.**							RE		TLMC 05-19-01	
31 A/F	Pilot					Yrs	03-Mar-2022	10		03-Mar-2032	7.8 Years
6420093-3						Hrs	4,883				
LT21-13228						Ldg	3,012				
Alias1:31-21-02 (ZONE: 200) (UPDATE NOTE: Battery Replaced new) (SOURCE: MM-104, MM-105)											
▼ 32 - LANDING GEAR											
	(M69) Pressure Brake Transducer Assembly							RE (O/C)			
32 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		(M70) Pressure Brake Transducer Assembly							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		(MT56) Pressure Brake Transducer Assembly							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		(MT57) Pressure Brake Transducer Assembly							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		(MT58) Pressure Brake Transducer Assembly							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		(MT59) Pressure Brake Transducer Assembly							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		*** Main Landing Gear Actuator Cylinder**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈29-Oct-2035**
	32 A/F	Left					Mos	01-Feb-2018				
	200-0302-101						Hrs					
	Unknown		2,387				Ldg	2,422	17,000		17,035	13,763 Ldg
	Alias1:(Std)N3220104, (EMP)3220104, (EMP) 3220066, EASA IRN:Q3220066, JAA IRN:Q3220066 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Main Landing Gear Actuator Cylinder**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈29-Oct-2035**
	32 A/F	Right					Mos	01-Feb-2018				
	200-0302-101						Hrs					
	Unknown		2,387				Ldg	2,422	17,000		17,035	13,763 Ldg
	Alias1:(Std)N3220104, (EMP)3220104, (EMP) 3220066, EASA IRN:Q3220066, JAA IRN:Q3220066 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Main Landing Gear Actuator End Cap**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Aug-2025**
	32 A/F	Left	0				Mos	01-Feb-2018				
	200-0303-001	New	0				Hrs	4,114.8				
	H2771		0				Ldg	2,422	2,387		4,809	1,537 Ldg
	Alias1:(Std)T3220105, (EMP)3220105, (EMP) 3220067, EASA IRN:T3220067, JAA IRN:T3220067 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA) (NOTE: (Removal of the End Cap from the Side Brace Actuator Assembly can only be performed by a Learjet Authorized Component Repair and Overhaul facility).)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		*** Main Landing Gear Actuator End Cap**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈12-Aug-2025**
32 A/F		Right	0				Mos	01-Feb-2018				
200-0303-001		New	0				Hrs	4,114.8				
H2756			0				Ldg	2,422	2,387		4,809	1,537 Ldg
Alias1:(Std)T3220105, (EMP)3220105, (EMP) 3220067, EASA IRN:T3220067, JAA IRN:T3220067 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA) (NOTE: (Removal of the End Cap from the Side Brace Actuator Assembly can only be performed by a Learjet Authorized Component Repair and Overhaul facility).)												
		*** Main Landing Gear Actuator Housing**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈29-Oct-2035**
32 A/F		Left					Mos	01-Feb-2018				
200-0304							Hrs	4,114.8				
Unknown			2,387				Ldg	2,422	17,000		17,035	13,763 Ldg
Alias1:(Std)N3220106, (EMP)3220106, (EMP) 3220068, EASA IRN:Q3220068, JAA IRN:Q3220068 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)												
		*** Main Landing Gear Actuator Housing**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈29-Oct-2035**
32 A/F		Right					Mos	01-Feb-2018				
200-0304							Hrs	4,114.8				
Unknown			2,387				Ldg	2,422	17,000		17,035	13,763 Ldg
Alias1:(Std)N3220106, (EMP)3220106, (EMP) 3220068, EASA IRN:Q3220068, JAA IRN:Q3220068 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)												
		*** Main Landing Gear Actuator Lower Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	
32 A/F		Left	0				Mos	07-Apr-2016	96		07-Apr-2024	OVD
200-0217-101		New					Hrs	3,621.8				
H3276							Ldg	2,105				
Alias1:32-31-01, (Std)T3220038, (EMP)3220038 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 32-31-01.))												
		*** Main Landing Gear Actuator Lower Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	
32 A/F		Right	0				Mos	07-Apr-2016	96		07-Apr-2024	OVD
200-0217-101		New					Hrs	3,621.8				
H3278							Ldg	2,105				
Alias1:32-31-01, (Std)T3220038, (EMP)3220038 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 32-31-01.))												
		*** Main Landing Gear Actuator Piston**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈29-Oct-2035**
32 A/F		Left					Mos	01-Feb-2018				
200-0301							Hrs					
Unknown			2,387				Ldg	2,422	17,000		17,035	13,763 Ldg
Alias1:(Std)N3220103, (EMP)3220103, (EMP) 3220065, EASA IRN:Q3220065, JAA IRN:Q3220065 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)												
		*** Main Landing Gear Actuator Piston**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈29-Oct-2035**
32 A/F		Right					Mos	01-Feb-2018				
200-0301							Hrs					
Unknown			2,387				Ldg	2,422	17,000		17,035	13,763 Ldg
Alias1:(Std)N3220103, (EMP)3220103, (EMP) 3220065, EASA IRN:Q3220065, JAA IRN:Q3220065 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		*** Main Landing Gear Actuator Upper Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	
32 A/F		Left	0				Mos	07-Apr-2016	96		07-Apr-2024	OVD
200-0325-101		New					Hrs	3,621.8				
H2517							Ldg	2,105				
Alias1:32-31-01, (Std)T3220014, (EMP)3220014 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 32-31-01.))												
		*** Main Landing Gear Actuator Upper Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	
32 A/F		Right	0				Mos	07-Apr-2016	96		07-Apr-2024	OVD
200-0325-101		New					Hrs	3,621.8				
H2495							Ldg	2,105				
Alias1:32-31-01, (Std)T3220014, (EMP)3220014 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 32-31-01.))												
		*** Main Landing Gear Aft Trunnion Shear Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈09-Oct-2025**
32 A/F		Lower - Left	0				Mos	13-Mar-2008				
4532103203-001		New	0				Hrs	0				
CMI-1038			0				Ldg	0	5,000		5,000	1,728 Ldg
Alias1:(Std)N3220141, (EMP)3220141, (Std)N3220043, (EMP)3220043, (EMP) 3220144, EASA IRN:Q3220144, JAA IRN:Q3220144 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)												
		*** Main Landing Gear Aft Trunnion Shear Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈09-Oct-2025**
32 A/F		Lower - Right	0				Mos	13-Mar-2008				
4532103203-001		New	0				Hrs	0				
CMI-751			0				Ldg	0	5,000		5,000	1,728 Ldg
Alias1:(Std)N3220141, (EMP)3220141, (Std)N3220043, (EMP)3220043, (EMP) 3220144, EASA IRN:Q3220144, JAA IRN:Q3220144 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)												
		*** Main Landing Gear Aft Trunnion Shear Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈09-Oct-2025**
32 A/F		Upper - Left	0				Mos	13-Mar-2008				
4532103202-001		New	0				Hrs	0				
CMI-788			0				Ldg	0	5,000		5,000	1,728 Ldg
Alias1:(Std)N3220042, (EMP)3220042, (Std)N3220140, (EMP)3220140, (EMP) 3220143, EASA IRN:Q3220143, JAA IRN:Q3220143 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)												
		*** Main Landing Gear Aft Trunnion Shear Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈09-Oct-2025**
32 A/F		Upper - Right	0				Mos	13-Mar-2008				
4532103202-001		New	0				Hrs	0				
CMI-872			0				Ldg	0	5,000		5,000	1,728 Ldg
Alias1:(Std)N3220042, (EMP)3220042, (Std)N3220140, (EMP)3220140, (EMP) 3220143, EASA IRN:Q3220143, JAA IRN:Q3220143 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)												
		*** Main Landing Gear Axle Beam**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈12-Dec-2029**
32 A/F		Left					Mos	01-Mar-2020				
200-0203-001			4,610.5				Hrs	4,610.5				
H1073			2,822				Ldg	2,822	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220036, (EMP)3220036 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												
		*** Main Landing Gear Axle Beam**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈12-Dec-2029**
32 A/F		Right	0				Mos	13-Mar-2008				
200-0203-001		New	0				Hrs	0				
H1077			0				Ldg	0	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220036, (EMP)3220036 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		*** Main Landing Gear Forward Trunnion Shear Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈09-Oct-2025**
	32 A/F	Lower - Left	0				Mos	13-Mar-2008				
	4532103201-001	New	0				Hrs	0				
	CMI-1592		0				Ldg	0	5,000		5,000	1,728 Ldg
	Alias1:(Std)N3220041, (EMP)3220041, (Std)N3220139, (EMP)3220139 ,(EMP) 3220142, EASA IRN:Q3220142, JAA IRN:Q3220142 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Main Landing Gear Forward Trunnion Shear Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈09-Oct-2025**
	32 A/F	Lower - Right	0				Mos	13-Mar-2008				
	4532103201-001	New	0				Hrs	0				
	CMI-2076		0				Ldg	0	5,000		5,000	1,728 Ldg
	Alias1:(Std)N3220041, (EMP)3220041, (Std)N3220139, (EMP)3220139, (EMP) 3220142, EASA IRN:Q3220142, JAA IRN:Q3220142 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Main Landing Gear Forward Trunnion Shear Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈09-Oct-2025**
	32 A/F	Upper - Left	0				Mos	13-Mar-2008				
	4532103201-001	New	0				Hrs	0				
	CMI-1614		0				Ldg	0	5,000		5,000	1,728 Ldg
	Alias1:(Std)N3220041, (EMP)3220041, (Std)N3220139, (EMP)3220139, (EMP) 3220142, EASA IRN:Q3220142, JAA IRN:Q3220142 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Main Landing Gear Forward Trunnion Shear Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈09-Oct-2025**
	32 A/F	Upper - Right	0				Mos	13-Mar-2008				
	4532103201-001	New	0				Hrs	0				
	CMI-2015		0				Ldg	0	5,000		5,000	1,728 Ldg
	Alias1:(Std)N3220041, (EMP)3220041, (Std)N3220139, (EMP)3220139, EASA IRN:Q3220142, JAA IRN:Q3220142 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Main Landing Gear Link Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈16-Sep-2031**
	32 A/F	Lower - Left	0				Mos	24-Mar-2016				
	200-0214	New	0				Hrs					
	Unknown		0				Ldg	2,107	10,000		12,107	8,835 Ldg
	Alias1:(Std)N3220101, (EMP)3220101 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
		*** Main Landing Gear Link Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈16-Sep-2031**
	32 A/F	Lower - Right	0				Mos	24-Mar-2016				
	200-0214	New	0				Hrs					
	Unknown		0				Ldg	2,107	10,000		12,107	8,835 Ldg
	Alias1:(Std)N3220101, (EMP)3220101 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
		*** Main Landing Gear Link Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈16-Sep-2031**
	32 A/F	Upper - Left	0				Mos	24-Mar-2016				
	200-0214	New	0				Hrs					
	Unknown		0				Ldg	2,107	10,000		12,107	8,835 Ldg
	Alias1:(Std)N3220101, (EMP)3220101 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
		*** Main Landing Gear Link Pin**								RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01	**≈16-Sep-2031**
	32 A/F	Upper - Right	0				Mos	24-Mar-2016				
	200-0214	New	0				Hrs					
	Unknown		0				Ldg	2,107	10,000		12,107	8,835 Ldg
	Alias1:(Std)N3220101, (EMP)3220101 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		*** Main Landing Gear Piston Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
32 A/F		Left	0				Mos	13-Mar-2008				
200-0215-101		New	0				Hrs	0				
H1012			0				Ldg	0	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220102, (EMP)3220102 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												
		*** Main Landing Gear Piston Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
32 A/F		Right	0				Mos	13-Mar-2008				
200-0215-101		New	0				Hrs	0				
H1037			0				Ldg	0	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220102, (EMP)3220102 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												
		*** Main Landing Gear Shock Strut Cylinder**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
32 A/F		Left					Mos	28-Jan-2010				
200-0201-109			1,172.9				Hrs	1,172.9				
0595			723				Ldg	723	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220116, (Std)Q3220128, (Std)Q3220137, (EMP)3220116, (EMP)3220128, (EMP)3220137 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: Note: On Aircraft equipped with the -105 thru - 108 Main Landing Gear Shock Strut Cylinder, Learjet recommends replacement of the MLG Trunnion Pins (P/N 200-0212, 200-0213), MLG Shock Strut Piston (P/N 200-0202), MLG Axle Beam (P/N 200-0203), MLG Shock Strut Link (P/N 200-0204), MLG Link Pin (P/N 200-0214), and MLG Piston Pin (P/N 200- 0215) when the cylinder is replaced at 6,600 Landings. This will allow the Main Landing Gear to stay in service with no time-life component replacements until the next Main Landing Gear replacement.)											
		*** Main Landing Gear Shock Strut Cylinder**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
32 A/F		Right					Mos	28-Jan-2010				
200-0201-110			1,172.9				Hrs	1,172.9				
H0597			723				Ldg	723	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220116, (Std)Q3220128, (Std)Q3220137, (EMP)3220116, (EMP)3220128, (EMP)3220137 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: Note: On Aircraft equipped with the -105 thru - 108 Main Landing Gear Shock Strut Cylinder, Learjet recommends replacement of the MLG Trunnion Pins (P/N 200-0212, 200-0213), MLG Shock Strut Piston (P/N 200-0202), MLG Axle Beam (P/N 200-0203), MLG Shock Strut Link (P/N 200-0204), MLG Link Pin (P/N 200-0214), and MLG Piston Pin (P/N 200- 0215) when the cylinder is replaced at 6,600 Landings. This will allow the Main Landing Gear to stay in service with no time-life component replacements until the next Main Landing Gear replacement.)											
		*** Main Landing Gear Shock Strut Link**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
32 A/F		Left	0				Mos	13-Mar-2008				
200-0204-001		New	0				Hrs	0				
H1177			0				Ldg	0	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220037, (EMP)3220037 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												
		*** Main Landing Gear Shock Strut Link**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
32 A/F		Right	0				Mos	13-Mar-2008				
200-0204-001		New	0				Hrs	0				
H1315			0				Ldg	0	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220037, (EMP)3220037 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												
		*** Main Landing Gear Shock Strut Piston**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
32 A/F		Left	0				Mos	13-Mar-2008				
200-0202-003		New	0				Hrs	0				
H1033			0				Ldg	0	10,000		10,000	6,728 Ldg
Alias1:(Std)N3220035, (EMP)3220035 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)												

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		*** Main Landing Gear Shock Strut Piston**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
	32 A/F	Right	0				Mos	13-Mar-2008				
	200-0202-003	New	0				Hrs	0				
	H1623		0				Ldg	0	10,000		10,000	6,728 Ldg
	Alias1:(Std)N3220035, (EMP)3220035 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
		*** Main Landing Gear Side Brace Actuator Assembly**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈29-Oct-2035**
	32 A/F	Left			0		Mos	01-Feb-2018				
	200-0300-003	Repaired	4,047.7		0		Hrs	4,114.8				
	H0472		2,387		0		Ldg	2,422	17,000		17,035	13,763 Ldg
	easa:W3220150, EASA IRN:T3220064, W3220150, EMP:(All) 3220013, 3220046, (FAA)(Brazilian) 3220149, (EASA) 3220150, (EASA) 3220063, (EASA) 3220064, JAA IRN:T3220063, T3220064, W3220150, Ref:32-31-01, Std:T3220013, T3220046, W3220149 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA, MM-105-BRS) (NOTE: (Refer to 32-31-01.) Note: The replacement of the MLG Side Brace Actuator Assembly includes the replacement of the MLG Actuator Piston (P/N 200-0301), MLG Actuator Cylinder (P/N 200-0302), and MLG Actuator Housing (P/N 200-0304). Refer to IRN T3220105 for the replacement interval of the End Cap.)											
		*** Main Landing Gear Side Brace Actuator Assembly**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈29-Oct-2035**
	32 A/F	Right			1		Mos	01-Feb-2018				
	200-0300-004		4,047.7				Hrs	4,114.8				
	H1518		2,387				Ldg	2,422	17,000		17,035	13,763 Ldg
	EASA IRN:T3220064, W3220150, EMP:(All) 3220013, 3220046, (FAA)(Brazilian) 3220149, (EASA) 3220150, (EASA) 3220063, (EASA) 3220064, JAA IRN:T3220063, T3220064, W3220150, Ref:32-31-01, Std:T3220013, T3220046, W3220149 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA, MM-105-BRS) (NOTE: (Refer to 32-31-01.) Note: The replacement of the MLG Side Brace Actuator Assembly includes the replacement of the MLG Actuator Piston (P/N 200-0301), MLG Actuator Cylinder (P/N 200-0302), and MLG Actuator Housing (P/N 200-0304). Refer to IRN T3220105 for the replacement interval of the End Cap.)											
		*** Main Landing Gear Side-Stay Actuator Fitting**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈19-Apr-2038**
	32 A/F	Left	0				Mos	13-Mar-2008				
	4532103041-009PP	New	0				Hrs	0				
	17611/11-03		0				Ldg	0	20,000		20,000	16,728 Ldg
	Alias1:(Std)N3220126, (EMP)3220126, (EMP) 3220132, EASA IRN:Q3220132, JAA IRN:Q3220132 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Main Landing Gear Side-Stay Actuator Fitting**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈19-Apr-2038**
	32 A/F	Right	0				Mos	13-Mar-2008				
	4532103041-010PP	New	0				Hrs	0				
	17612/7-03		0				Ldg	0	20,000		20,000	16,728 Ldg
	Alias1:(Std)N3220126, (EMP)3220126, (EMP) 3220132, EASA IRN:Q3220132, JAA IRN:Q3220132 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Main Landing Gear Strut Assembly**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
	32 A/F	Left	97				Mos	06-Apr-2016				
	200-0200-013		3,623.9				Hrs	3,623.9				
	H0477		2,107				Ldg	2,107	10,000		10,000	6,728 Ldg
	(Std):N3220012, Alias2:(EMP)3220012 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
		*** Main Landing Gear Strut Assembly**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
	32 A/F	Right	97				Mos	06-Apr-2016				
	200-0200-014		3,623.9				Hrs	3,623.9				
	H1482		2,107				Ldg	2,107	10,000		10,000	6,728 Ldg
	(Std):N3220012, Alias2:(EMP)3220012 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		*** Main Landing Gear Trunnion Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
	32 A/F	Aft - Left	0				Mos	13-Mar-2008				
	200-0213-103	New	0				Hrs	0				
	H0981		0				Ldg	0	10,000		10,000	6,728 Ldg
	Alias1:32-10-01, (Std)N3220023, (EMP)3220023 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 32-10-01.))											
		*** Main Landing Gear Trunnion Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
	32 A/F	Aft - Right	0				Mos	13-Mar-2008				
	200-0213-103	New	0				Hrs	0				
	H0962		0				Ldg	0	10,000		10,000	6,728 Ldg
	Alias1:32-10-01, (Std)N3220023, (EMP)3220023 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 32-10-01.))											
		*** Main Landing Gear Trunnion Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
	32 A/F	Fwd - Left	0				Mos	13-Mar-2008				
	200-0212-103	New	0				Hrs	0				
	H1222		0				Ldg	0	10,000		10,000	6,728 Ldg
	Alias1:32-10-01, (Std)N3220023, (EMP)3220023 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 32-10-01.))											
		*** Main Landing Gear Trunnion Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈12-Dec-2029**
	32 A/F	Fwd - Right	0				Mos	13-Mar-2008				
	200-0212-103	New	0				Hrs	0				
	H1156		0				Ldg	0	10,000		10,000	6,728 Ldg
	Alias1:32-10-01, (Std)N3220023, (EMP)3220023 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Refer to 32-10-01.))											
		*** Nose Landing Gear Actuator Assembly**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈02-Jul-2039**
	32 A/F				3		Mos	14-Nov-2013				
	6632201000-005		244				Hrs	3,011.7				
	TASV747		329				Ldg	1,768	20,000		21,439	18,167 Ldg
	Alias1:(Std)O3220010, (EMP)3220010, (EMP) 3220073, EASA IRN:E3220073, JAA IRN:E3220073 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Nose Landing Gear Actuator Upper Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈19-Apr-2038**
	32 A/F		0				Mos	13-Mar-2008				
	4532302043-007	New	0				Hrs	0				
	413		0				Ldg	0	20,000		20,000	16,728 Ldg
	Alias1:(Std)O3220011, (EMP)3220011, (EMP) 3220070, EASA IRN:E3220070, JAA IRN:E3220070 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Nose Landing Gear Strut Assembly**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈19-Apr-2038**
	32 A/F		0				Mos	13-Mar-2008				
	4532201000V16-005	New	0				Hrs	0				
	434		0				Ldg	0	20,000		20,000	16,728 Ldg
	Alias1:(Std)O3220009, (EMP)3220009, (EMP) 3220069, EASA IRN:E3220069, JAA IRN:E3220069 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Nose Landing Gear Trunnion Axle**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈19-Apr-2038**
	32 A/F		0				Mos	13-Mar-2008				
	2342110-003	New	0				Hrs	0				
	R735		0				Ldg	0	20,000		20,000	16,728 Ldg
	Alias1:(Std)O3220029, (EMP)3220029, (EMP) 3220072, EASA IRN:E3220072, JAA IRN:E3220072 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		*** Nose Landing Gear Trunnion Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈19-Apr-2038**
	32 A/F	Left	0				Mos	13-Mar-2008				
	2342108-003	New	0				Hrs	0				
	E491		0				Ldg	0	20,000		20,000	16,728 Ldg
	Alias1:(Std)O3220028, (EMP)3220028, (EMP) 3220071, EASA IRN:E3220071, JAA IRN:E3220071 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		*** Nose Landing Gear Trunnion Pin**							RE	Replacement Schedule, TLMC 04-11-00, TLMC 05-19-01		**≈19-Apr-2038**
	32 A/F	Right	0				Mos	13-Mar-2008				
	2342108-003	New	0				Hrs	0				
	E473		0				Ldg	0	20,000		20,000	16,728 Ldg
	Alias1:(Std)O3220028, (EMP)3220028, EASA IRN:E3220071, JAA IRN:E3220071 (ZONE: 700) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR, MM-105-EASA)											
		Access NLG Aft Panel							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Anti-Skid Control Valve							RE (O/C)			
	32 A/F	Left		0			Mos	20-Aug-2008				
	6632401001-009	Overhauled		0			Hrs	377.2				
	439			0			Ldg	276				
		Anti-Skid Control Valve							RE (O/C)			
	32 A/F	Right					Mos	09-May-2008				
	39-787						Hrs	125.6				
	590						Ldg	102				
		Anti-Skid Shutoff Valve							RE (O/C)			
	32 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Anti-Skid Shutoff Valve							RE (O/C)			
	32 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Brake Accumulator Assembly							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Brake Control Unit							RE (O/C)			
	32 A/F					0	Mos	13-Aug-2008				
	42-933-3	Repaired				0	Hrs	374.6				
	524A					0	Ldg	273				
		Brake Shuttle Valve							RE (O/C)			
	32 A/F	No.1	0				Mos	13-Mar-2008				
	5116-1	New	0				Hrs	0				
	1826		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Brake Shuttle Valve							RE (O/C)			
	32 A/F	No.2	0				Mos	13-Mar-2008				
	5116-1	New	0				Hrs	0				
	1760		0				Ldg	0				
		Brake Shuttle Valve							RE (O/C)			
	32 A/F	No.3	0				Mos	13-Mar-2008				
	5116-1	New	0				Hrs	0				
	1760		0				Ldg	0				
		Brake Shuttle Valve							RE (O/C)			
	32 A/F	No.4	0				Mos	13-Mar-2008				
	5116-1	New	0				Hrs	0				
	1826		0				Ldg	0				
		Co-Pilot Brake Transducer							RE (O/C)			
	32 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Co-Pilot Brake Transducer							RE (O/C)			
	32 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Down And Locked (S100) Switch							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Down And Locked (S96) Switch							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Emer/Park Brake Accumulator							RE (O/C)			
	32 A/F		0				Mos	13-Mar-2008				
	88744-1	New	0				Hrs	0				
	514		0				Ldg	0				
		Emergency Parking Brake Check Valve							RE (O/C)			
	32 A/F		0				Mos	02-Jun-2008				
	1C4124	New	0				Hrs	194.8				
	Unknown		0				Ldg	147				
		Emergency/Park Brake Fuse							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Emergency/Park Brake Valve							RE (O/C)			
	32 A/F				0		Mos	11-Jun-2008				
	6632401002-011	Repaired			0		Hrs	223				
	0396				0		Ldg	167				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Hydraulic, Brake Fuse							RE (O/C)			
	32 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Hydraulic, Brake Fuse							RE (O/C)			
	32 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Hydraulic, Brake Fuse							RE (O/C)			
	32 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Hydraulic, Brake Fuse							RE (O/C)			
	32 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Inboard Brake Swivel							RE (O/C)			
	32 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Inboard Brake Swivel							RE (O/C)			
	32 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Inboard Brake Swivel							RE (O/C)			
	32 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Inboard Brake Swivel							RE (O/C)			
	32 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Landing Gear Control Valve							RE (O/C)			
	32 A/F						Mos	21-May-2019				
	6632302001-003						Hrs	4,461.2				
	1639						Ldg	2,673				
		Main Gear Squat Switch							RE (O/C)			
	32 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Gear Squat Switch							RE (O/C)			
	32 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Main Gear Squat Switch							RE (O/C)			
	32 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Gear Squat Switch							RE (O/C)			
	32 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Landing Gear Chassis							RE (O/C)			
	32 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Landing Gear Chassis							RE (O/C)			
	32 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Main Landing Gear Door							RE (O/C)			
	32 A/F	Left Inboard	0				Mos	13-Mar-2008				
	4552803004-003	New	0				Hrs	0				
	011780100456		0				Ldg	0				
		Main Landing Gear Door							RE (O/C)			
	32 A/F	Left Outboard	0				Mos	13-Mar-2008				
	4552803003-003	New	0				Hrs	0				
	856578000455		0				Ldg	0				
		Main Landing Gear Door							RE (O/C)			
	32 A/F	Right Inboard	0				Mos	13-Mar-2008				
	4552803004-004	New	0				Hrs	0				
	981105300456		0				Ldg	0				
		Main Landing Gear Door							RE (O/C)			
	32 A/F	Right Outboard	0				Mos	13-Mar-2008				
	4552803003-004	New	0				Hrs	0				
	691707300455		0				Ldg	0				
		Main Landing Gear Inboard Door Actuator							RE (O/C)			
	32 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Alias2:323311											
		Main Landing Gear Inboard Door Actuator							RE (O/C)			
	32 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Alias2:323312											
		Main Landing Gear Oleo Assembly							RE (O/C)			
	32 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Main Landing Gear Oleo Assembly							RE (O/C)			
32 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Main Landing Gear Side Brace Actuator Displacement Tube							RE (O/C)			
32 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Main Landing Gear Side Brace Actuator Displacement Tube							RE (O/C)			
32 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Main Landing Gear Side Stay Actuator Pin							RE (O/C)			
32 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Main Landing Gear Side Stay Actuator Pin							RE (O/C)			
32 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Main Landing Gear Uplock Mechanism							RE (O/C)			
32 A/F		Left	0				Mos	04-Oct-2013				
3000H000-006		New	0				Hrs	2,969.1				
2317			0				Ldg	1,743				
		Main Landing Gear Uplock Mechanism							RE (O/C)			
32 A/F		Right	0				Mos	13-Mar-2008				
3000H000-006		New	0				Hrs	0				
2031			0				Ldg	0				
		Main Landing Gear Wheel							RE (O/C)			
32 A/F		No.1					Mos	03-Mar-2022				
3-1545-1		Overhauled	292	0	0		Hrs	4,883				
2758			204	0	0		Ldg	3,012				
		Main Landing Gear Wheel							RE (O/C)			
32 A/F		No.2					Mos	03-Mar-2022				
3-1545-1		Overhauled	551.1	0	0		Hrs	4,883				
0096			465	0	0		Ldg	3,012				
		Main Landing Gear Wheel							RE (O/C)			
32 A/F		No.3					Mos	03-Mar-2022				
3-1545-1			286	0	0		Hrs	4,883				
4019			200	0	0		Ldg	3,012				
(UPDATE NOTE: C/W BY Q1 AVIATION.)												
		Main Landing Gear Wheel							RE (O/C)			
32 A/F		No.4					Mos	03-Mar-2022				
3-1545-1		Overhauled	551.1	0	0		Hrs	4,883				
2159			551	0	0		Ldg	3,012				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		MLG Actuator Gimbal Assembly							RE (O/C)			
32 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		MLG Actuator Gimbal Assembly							RE (O/C)			
32 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		MLG Door Uplock Switch							RE (O/C)			
32 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		MLG Door Uplock Switch							RE (O/C)			
32 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		MLG Inboard Door Gimbal Bracket Assembly							RE (O/C)			
32 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		MLG Inboard Door Gimbal Bracket Assembly							RE (O/C)			
32 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		MLG Shaft Gimbal Assembly							RE (O/C)			
32 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		MLG Shaft Gimbal Assembly							RE (O/C)			
32 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		No. 1 Assembly, Main Landing Gear Brake							RE (O/C)			
32 A/F			36		0		Mos	11-Mar-2011				
2-1579-2		Repaired	1,857.4		0		Hrs	1,857.4				
2196			1,121		0		Ldg	1,121				
		No. 1 Main Landing Gear Tire							RE (O/C)			
32 A/F		No.1					Mos	27-Sep-2023				
226K08-4		New	0				Hrs	5,197.3				
31070572			0				Ldg	3,212				
		No. 2 Assembly, Main Landing Gear Brake							RE (O/C)			
32 A/F			0				Mos	13-Mar-2008				
2-1579-2		New	0				Hrs	0				
2197			0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 2 Main Landing Gear Tire							RE (O/C)			
32 A/F		No.2					Mos	27-Sep-2023				
226K08-4		New	0				Hrs	5,197.3				
31110884			0				Ldg	3,212				
		No. 3 Assembly, Main Landing Gear Brake							RE (O/C)			
32 A/F							Mos	10-Feb-2021				
6632401000-002		Overhauled					Hrs	4,610.5				
0451							Ldg	2,822				
		No. 3 Main Landing Gear Tire							RE (O/C)			
32 A/F		No.3					Mos	09-Feb-2024				
226K08-4							Hrs	5,253.5				
20830396							Ldg	3,757				
		No. 4 Assembly, Main Landing Gear Brake							RE (O/C)			
32 A/F				0			Mos	18-Sep-2015				
2-1579-2		Overhauled		0			Hrs	3,601.1				
1629				0			Ldg	2,092				
							Hrs (APU)	1,175.5				
		No. 4 Main Landing Gear Tire							RE (O/C)			
32 A/F		No.4					Mos	09-Feb-2024				
226K08-4							Hrs	5,253.5				
21020405							Ldg	3,757				
		Nose Gear Wheel Assembly							RE (O/C)			
32 A/F							Mos	06-Dec-2022				
2342003-077		Tested/Inspected					Hrs	5,136.6				
MAY12-11169							Ldg	3,167				
		Nose Landing Gear Actuator Bracket							RE (O/C)			
32 A/F			0				Mos	13-Mar-2008				
2342111		New	0				Hrs	0				
R409			0				Ldg	0				
		Nose Landing Gear Chassis Assembly							RE (O/C)			
32 A/F							Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Nose Landing Gear Cylinder							RE (O/C)			
32 A/F			0				Mos	13-Mar-2008				
2342102		New	0				Hrs	0				
T649			0				Ldg	0				
		Nose Landing Gear Door							RE (O/C)			
32 A/F		Left	0				Mos	13-Mar-2008				
4552800001-007		New	0				Hrs	0				
477			0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Nose Landing Gear Door							RE (O/C)			
	32 A/F	Right	0				Mos	13-Mar-2008				
	4552800002-007	New	0				Hrs	0				
	473		0				Ldg	0				
		Nose Landing Gear Down-Lock (S139) Switch							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Nose Landing Gear Fork							RE (O/C)			
	32 A/F		0				Mos	13-Mar-2008				
	2342116	New	0				Hrs	0				
	R637		0				Ldg	0				
		Nose Landing Gear Piston							RE (O/C)			
	32 A/F		0				Mos	13-Mar-2008				
	2342104	New	0				Hrs	0				
	F461		0				Ldg	0				
		Nose Landing Gear Piston/Axle Assembly							RE (O/C)			
	32 A/F		0				Mos	13-Mar-2008				
	2342117	New	0				Hrs	0				
	R677		0				Ldg	0				
		Nose Landing Gear SQUAT/WOW (S178) Switch							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Nose Landing Gear Tire							RE (O/C)			
	32 A/F						Mos	06-Dec-2022				
	031-613-8	Overhauled					Hrs	5,136.6				
	2173T00296						Ldg	3,167				
		Nose Landing Gear Uplock Mechanism							RE (O/C)			
	32 A/F		0				Mos	13-Mar-2008				
	2269H000-003	New	0				Hrs	0				
	1525		0				Ldg	0				
		Nose Wheel Steering Computer							RE (O/C)			
	32 A/F		0				Mos	13-Mar-2008				
	498000-03-02	New	0				Hrs	0				
	00606		0				Ldg	0				
		Nose Wheel Steering Gearbox							RE (O/C)			
	32 A/F		0				Mos	13-Mar-2008				
	2W3201D	New	0				Hrs	0				
	C0517		0				Ldg	0				
		Nose Wheel Steering Power Supply							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Nose Wheel Steering Servo Actuator							RE (O/C)			
32 A/F			0				Mos	13-Mar-2008				
JR5208C		New	0				Hrs	0				
A0521			0				Ldg	0				
		Nose Wheel Steering Transducer							RE (O/C)			
32 A/F		Left	0				Mos	13-Mar-2008				
19710/3A1-279A		New	0				Hrs	0				
A1014			0				Ldg	0				
		Nose Wheel Steering Transducer							RE (O/C)			
32 A/F		Right	0				Mos	13-Mar-2008				
19710/3A1-279A		New	0				Hrs	0				
A1018			0				Ldg	0				
		Outboard Brake Swivel							RE (O/C)			
32 A/F		No.1					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Outboard Brake Swivel							RE (O/C)			
32 A/F		No.2					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Outboard Brake Swivel							RE (O/C)			
32 A/F		No.3					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Outboard Brake Swivel							RE (O/C)			
32 A/F		No.4					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Pilot Brake Transducer							RE (O/C)			
32 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Pilot Brake Transducer							RE (O/C)			
32 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Pressure, Emergency/Park Brake Transducer							RE (O/C)			
32 A/F			0				Mos	13-Mar-2008				
7629301001-001		New	0				Hrs	0				
7375-10-102			0				Ldg	0				
		Shuttle Module, Anti-Skid, Brake							RE (O/C)			
32 A/F							Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Squat Switch P21 Relay Box							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Trunnion Assembly							RE (O/C)			
	32 A/F	Aft - Left	0				Mos	13-Mar-2008				
	4532103021-009	New	0				Hrs	0				
	CMI-159		0				Ldg	0				
		Trunnion Assembly							RE (O/C)			
	32 A/F	Aft - Right	0				Mos	13-Mar-2008				
	4532103021-010	New	0				Hrs	0				
	CMI-126		0				Ldg	0				
		Trunnion Assembly							RE (O/C)			
	32 A/F	Fwd - Left	0				Mos	13-Mar-2008				
	4532103011-011	New	0				Hrs	0				
	CMI-116		0				Ldg	0				
		Trunnion Assembly							RE (O/C)			
	32 A/F	Fwd - Right	0				Mos	13-Mar-2008				
	4532103011-012	New	0				Hrs	0				
	CMI-174		0				Ldg	0				
		Up, Locked (VU1605) (S98) Switch							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Up, Locked (VU1605), (S102), Rh Switch							RE (O/C)			
	32 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Uplock Actuator Assembly							RE (O/C)			
	32 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Uplock Actuator Assembly							RE (O/C)			
	32 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Wheel Speed - Anti-Skid Transducer							RE (O/C)			
	32 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Wheel Speed - Anti-Skid Transducer							RE (O/C)			
	32 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Wheel Speed - Anti-Skid Transducer							RE (O/C)			
	32 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Wheel Speed - Anti-Skid Transducer							RE (O/C)			
	32 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
2000-22-04		**Grease to the rotating disk assembly of the nose landing gear (NLG) squat switch mechanism(Superseded by 2003-17-08)**							RE (-)		Mandatory	
	32 A/F						Mos	13-Mar-2008				
	Eff: 06-Dec-2000 Complied With	AT MANUFACTURE					Hrs	8.7				
							Ldg	8				
2001-07-11		**Main Landing Gear Tires**							RE (-)		Mandatory	
	32 A/F						Mos	31-Mar-2008				
	Eff: 01-May-2001 Not Applicable						Hrs	11.6				
							Ldg	11				
2001-18-05		**Flight Eagle Tires**							RE (-)		Mandatory (Appliance AD)	
	32 A/F						Mos	31-Mar-2008				
	Eff: 24-Sep-2001 Not Applicable						Hrs	11.6				
							Ldg	11				
2003-16-09		**Main Landing Gears (MLG)**							RE (-)		Mandatory	
	32 A/F						Mos	16-Aug-2013				
	Eff: 27-Aug-2003 Not Applicable	TO AIRCRAFT SERIAL NUMBER					Hrs	2,912.5				
							Ldg	1,706				
2003-16-09 PART A		**Accomplish Replacement Of The Main Landing Gear Trunnion Shear Pins -Revise The Airworthiness Limitations (Awl) Section Of The Instructions For Continued Airworthiness**							RE (-)		Mandatory	
	32 A/F						Mos	16-Aug-2013				
	Not Applicable	TO AIRCRAFT SERIAL NUMBER					Hrs	2,912.5				
							Ldg	1,706				
2003-16-09 PART B		**Accomplish Replacement Of The Main Landing Gear Trunnion Shear Pins Replace The Shear Pins**							RE (-)		Mandatory	
	32 A/F						Mos	16-Aug-2013				
	Not Applicable	TO AIRCRAFT SERIAL NUMBER					Hrs	2,912.5				
							Ldg	1,706				
2003-17-08		**Nose landing gear (NLG) squat switch camrod**							RE (-)		Mandatory	
	32 A/F						Mos	11-Feb-2010				
	Eff: 24-Sep-2003 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
							Ldg	739				
2006-18-08		**Goodyear Aviation - Nosewheel tires**							RE (-)		Mandatory (Appliance AD)	
	32 A/F						Mos	31-Mar-2008				
	Eff: 11-Oct-2006 Not Applicable						Hrs	11.6				
	Brand A:9990-2006-18-08						Ldg	11				
2011-25-03		**Landing Gear- Potential for Fatigue Cracking of the End Cap of the Main Landing Gear (MLG)**							RE (-)		Mandatory	
	32 A/F						Mos	30-Nov-2018				
	Eff: 23-Jan-2012 Complied With						Hrs					
							Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2011-25-03 (G)(1)	**Revise Fatigue Cracking Of The End Cap Of The Main Landing Gear Maintenance Program**							RE (-)			
32 A/F						Mos	17-Apr-2012				
Complied With	VERIFIED THE AIRCRAFT MAINTENANCE TRACKING SYSTEM HAS BEEN UPDATED TO INCLUDE IRN T3220105 LEFT AND RIGHT MAIN LANDING GEAR ACTUATOR END CAP (PN 200-030) AS SPECIFIED IN LEARJET 45 TEMPORARY REVISION 4-34 DATED 01/24/11					Hrs	2,413.2				
						Ldg	1,441				
32-NDI-01	**Main Landing Gear Wheel - Non destructive test**							RE (A/R)			
32 A/F	No.2					Mos	25-Sep-2020				
3-1545-1						Hrs	4,597				
0096						Ldg	2,812				
32-NDI-01	**Main Landing Gear Wheel - Non destructive test**							RE (A/R)			
32 A/F	No.3					Mos	03-Mar-2022				
3-1545-1						Hrs	4,883				
4019						Ldg	3,012				
32-NDI-01	**Main Landing Gear Wheel - Non destructive test**							RE (A/R)			
32 A/F	No.4					Mos	06-Jul-2018				
3-1545-1						Hrs	4,331.9				
0096						Ldg	2,547				
45-32-10	**Landing Gear - Installation of Brake Line Insulation**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-10 Rev 1	**Landing Gear - Installation of Brake Line Insulation**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-10 Rev 2	**Landing Gear - Installation of Brake Line Insulation**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 14-Jun-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-11	**Landing Gear - Main Landing Gear Free-Fall System Extension Modification**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-11 Rev 1	**Landing Gear - Main Landing Gear Free-Fall System Extension Modification**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 15-Sep-2000 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-12	**Landing Gear - Installation of Nose Wheel Weight-On-Wheel (WOW) Switch Quick Disconnect**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-12 Rev 1	**Landing Gear - Installation of Nose Wheel Weight-On-Wheel (WOW) Switch Quick Disconnect**							RE (-)		Optional	
32 A/F						Mos	29-Aug-2019				
Eff: 20-Oct-2008 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-32-13	**Superceded by SB45-32-17**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-32-13 Rev 1	**Superceded by SB45-32-17**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-13 Rev 2	**Superceded by SB45-32-17**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 17-May-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-14	**Landing Gear - Rerouting of Hydraulic Brake Lines**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 18-May-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-15	**Landing Gear - Landing Gear Control Switch Replacement**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-15 Rev 1	**Landing Gear - Landing Gear Control Switch Replacement**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 12-Jul-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-16	**Landing Gear - Installation of Spiral Wrap on the Nose Down-and-Lock Switch Wire Bundle**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-16 Rev 1	**Landing Gear - Installation of Spiral Wrap on the Nose Down-and-Lock Switch Wire Bundle**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 17-May-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-17	**Landing gear - Modification of Ground Plug Bracket**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-17 Rev 1	**Landing gear - Modification of Ground Plug Bracket**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 03-Dec-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-19	**Main Landing Gear Door Actuator Improvement/Saddle Installation**							RE (-)		Recommended	
32 A/F						Mos	06-Aug-2008				
Complied With	A/C S/N 45-359 HAS DOOR ACTUATOR P/N 7469-1					Hrs	359.6				
						Ldg	264				
45-32-19 Rev 1	**Main Landing Gear Door Actuator Improvement/Saddle Installation**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-19 Rev 2	**Main Landing Gear Door Actuator Improvement/Saddle Installation**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 14-Jun-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-2	**Landing Gear - Replacement of Main Landing Gear Brakes**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-32-2 Rev 1	**Landing Gear - Replacement of Main Landing Gear Brakes**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 06-Jan-1999 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-20	**Landing Gear - Inspection of the Main Landing Gear Door Actuator Gimbal**							RE (-)		Recommended	
32 A/F						Mos	02-Oct-2014				
Not Applicable	BY S/N ONLY APPLIES TO 45-0005 THRU 45-279					Hrs	3,296				
						Ldg	1,927				
45-32-20 Rev 1	**Landing Gear - Inspection of the Main Landing Gear Door Actuator Gimbal**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-20 Rev 2	**Landing Gear - Inspection of the Main Landing Gear Door Actuator Gimbal**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 10-Nov-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-21	**Landing Gear - Improved Removal of Brake Control Unit (BCU)**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-21 Rev 1	**Landing Gear - Improved Removal of Brake Control Unit (BCU)**							RE (-)		Optional	
32 A/F						Mos	29-Aug-2019				
Eff: 04-Sep-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-32-22	**Landing Gear - Nose Landing Gear (NLG) Uplock Support Rivet Upgrade**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-22 Rev 1	**Landing Gear - Nose Landing Gear (NLG) Uplock Support Rivet Upgrade**							RE (-)		Optional	
32 A/F						Mos	29-Aug-2019				
Eff: 10-Apr-2006 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-32-23	**Landing Gear - Replacement of the Nose Landing Gear Seal Retainer**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Eff: 21-Dec-2006 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 12)						Ldg	8				
45-32-23 Rev 1	**Landing Gear - Replacement of the Nose Landing Gear Seal Retainer**							RE (-)		Recommended	
32 A/F						Mos	08-Jun-2009				
Eff: 07-Jan-2008 Not Applicable	PER A/C S/N					Hrs	801				
(AVG MAN HRS: 12)						Ldg	521				
45-32-23 Rev 2	**Landing Gear - Replacement of the Nose Landing Gear Seal Retainer**							RE (-)		Recommended	
32 A/F						Mos	11-Jan-2013				
Eff: 10-Dec-2012 Not Applicable	PER A/C S/N					Hrs	2,729.9				
(AVG MAN HRS: 12)						Ldg	1,611				
45-32-23 Rev 3	**Landing Gear - Replacement of the Nose Landing Gear Seal Retainer**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 14-Jan-2013 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 12)						Ldg	2,822				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-32-24	**Landing Gear - Replacement of the Outboard Door Link Push Rod Assembly**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 02-Jul-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-25	**Landing Gear - Replacement of MLG Inboard Door Actuator Gimbal**							RE (-)		Recommended	
32 A/F						Mos	26-Jun-2008				
Not Applicable	PER A/C S/N					Hrs	237				
						Ldg	182				
45-32-25 Rev 1	**Landing Gear - Replacement of MLG Inboard Door Actuator Gimbal**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 12-May-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-26	**Landing Gear - Replacement of the Emergency/Parking Brake Control Hardware**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 24-Sep-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-27	**Landing Gear - Inspection/Replacement of Brake Hose Assemblies**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 12-Mar-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-28	**Landing Gear - Inspection/Reroute of Nose Wheel Steering Wiring Harness**							RE (-)		Recommended	
32 A/F						Mos					
Eff: 13-Apr-2009						Hrs					
						Ldg					
45-32-28 Rev 1	**Landing Gear - Inspection/Reroute of Nose Wheel Steering Wiring Harness**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 23-Mar-2015 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 12.5)						Ldg	2,822				
45-32-29	**Landing Gear - Installation of Teflon Overbraid on Wheel Speed Transducer Wire Cables**							RE (-)		Recommended	
32 A/F						Mos					
Eff: 14-Nov-2008						Hrs					
(AVG MAN HRS: 25)						Ldg					
45-32-29 Rev 1	**Landing Gear - Installation of Teflon Overbraid on Wheel Speed Transducer Wire Cables**							RE (-)		Recommended	
32 A/F						Mos					
Eff: 02-Mar-2009						Hrs					
(AVG MAN HRS: 25)						Ldg					
45-32-29 Rev 2	**Landing Gear - Installation of Teflon Overbraid on Wheel Speed Transducer Wire Cables**							RE (-)		Recommended	
32 A/F						Mos	22-Apr-2011				
Eff: 26-Apr-2010 Complied With						Hrs	1,922				
(AVG MAN HRS: 25)						Ldg	1,155				
45-32-29 Rev 3	**Landing Gear - Installation of Teflon Overbraid on Wheel Speed Transducer Wire Cables**							RE (-)		Recommended	
32 A/F						Mos	29-Aug-2019				
Eff: 23-Aug-2010 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 25)						Ldg	2,733				
45-32-3	**Landing Gear - Nose Wheel Steering Upgrade**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-3 Rev 1	**Landing Gear - Nose Wheel Steering Upgrade**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-32-3 Rev 2	**Landing Gear - Nose Wheel Steering Upgrade**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-3 Rev 3	**Landing Gear - Nose Wheel Steering Upgrade**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-3 Rev 4	**Landing Gear - Nose Wheel Steering Upgrade**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-3 Rev 5	**Landing Gear - Nose Wheel Steering Upgrade**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-3 Rev 6	**Landing Gear - Nose Wheel Steering Upgrade**							RE (-)		Optional	
32 A/F						Mos	29-Aug-2019				
Eff: 12-Dec-2011 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-32-30	**Landing Gear - NonDestructive Inspection (NDI) of the Main Landing Gear Shock Strut Cylinders**							RE (-)		Recommended	
32 A/F						Mos	20-Nov-2017				
Eff: 18-May-2009 Complied With						Hrs	4,047.7				
(AVG MAN HRS: 6)						Ldg	2,387				
45-32-30 Rev 1	**Landing Gear - NonDestructive Inspection (NDI) of the Main Landing Gear Shock Strut Cylinders**							RE (-)		Recommended	
32 A/F						Mos	17-Apr-2012				
Eff: 31-Oct-2011 Not Applicable						Hrs					
(AVG MAN HRS: 6)						Ldg					
45-32-31	**Landing Gear - Inspection/Replacement of the Nose Gear Wheel Assembly**							RE (-)		Recommended	
32 A/F						Mos	22-Jan-2010				
Eff: 18-Jan-2010 Complied With						Hrs	1,165.2				
(AVG MAN HRS: 3)						Ldg	719				
45-32-32	**Landing Gear - AFT Landing Gear Control Valve Freefall Cable and AFT Emergency/Parking Brake Cable Clamp Installation**							RE (-)		Recommended	
32 A/F						Mos	17-Mar-2010				
Eff: 01-Mar-2010 Complied With						Hrs	1,264.3				
(AVG MAN HRS: 2.5)						Ldg	773				
45-32-32 Rev 1	**Landing Gear - AFT Landing Gear Control Valve Freefall Cable and AFT Emergency/Parking Brake Cable Clamp Installation**							RE (-)		Recommended	
32 A/F						Mos	10-Jan-2020				
Eff: 22-Mar-2010 Not Applicable						Hrs	4,590.8				
(AVG MAN HRS: 2.5)						Ldg	2,807				
45-32-33	**Landing Gear - Landing Gear Free Fall System Replacement**							RE (-)		Optional	
32 A/F						Mos	29-Aug-2019				
Eff: 23-Jul-2012 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-32-34	**Landing Gear - Main Landing Gear Side Brace Actuator End Cap Replacement**							RE (-)		Optional	
32 A/F						Mos	20-Nov-2017				
Eff: 30-Mar-2015 Complied With						Hrs	4,047.7				
(AVG MAN HRS: 26)						Ldg	2,387				
45-32-34 Rev 1	**Landing Gear - Main Landing Gear Side Brace Actuator End Cap Replacement**							T (A/R)		Optional	
32 A/F						Mos					
Eff: 11-May-2015						Hrs					
(AVG MAN HRS: 26)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-32-35	**Landing Gear - Main Landing Gear (MLG) Strut Brake Hose Replacement**							T (A/R)		Optional	
32 A/F						Mos					
Eff: 14-Sep-2015						Hrs					
(ZONE: 4.5)						Ldg					
45-32-36	**Landing Gear - Landing Gear Retraction Brake Pressure - Pulse Test Modification**							T (-)		Recommended	
32 A/F						Mos					
Eff: 06-Jul-2015						Hrs					
(AVG MAN HRS: 12)						Ldg					
45-32-36 Rev 1	**Landing Gear - Landing Gear Extension Brake Pressure - Pulse Test Modification**							T (A/R)		Recommended	
32 A/F						Mos					
Eff: 03-Aug-2015						Hrs					
(AVG MAN HRS: 6)						Ldg					
45-32-36 Rev 2	**Landing Gear - Landing Gear Extension Brake Pressure - Pulse Test Modification**							T (A/R)		Recommended	
32 A/F						Mos					
Eff: 07-Dec-2015						Hrs					
(AVG MAN HRS: 6)						Ldg					
45-32-37	**Landing Gear - Nose Wheel Wire Harness Protection**							T (-)		Recommended	
32 A/F						Mos					
Eff: 03-Oct-2016						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-32-37 Rev 1	**Landing Gear - Nose Wheel Wire Harness Protection**							T (A/R)		Recommended	
32 A/F						Mos					
Eff: 13-Feb-2017						Hrs					
(AVG MAN HRS: 0.75)						Ldg					
45-32-38	**Landing Gear - Wheel Speed Transducer Harness Labeling Improvement**							T (A/R)		Recommended	
32 A/F						Mos					
Eff: 31-Mar-2017						Hrs					
(AVG MAN HRS: 3)						Ldg					
45-32-4	**Landing Gear - Replacement of Main Landing Gear Brake Hoses**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-4 Rev 1	**Landing Gear - Replacement of Main Landing Gear Brake Hoses**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 18-Aug-2000 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-40	**Landing Gear - Parking/Emergency Brake Pulley Guard Pin**							T (-)		Recommended	
32 A/F						Mos					
Eff: 20-Sep-2021						Hrs					
(AVG MAN HRS: 3.5) (NOTE: COMPLIANCE: Bombardier Learjet Inc. recommends these instructions are completed before or at the same time of the next scheduled maintenance activity.)						Ldg					
45-32-40 Rev 1	**Landing Gear - Parking/Emergency Brake Pulley Guard Pin**							T (A/R)		Recommended	
32 A/F						Mos					
Eff: 06-Jun-2022						Hrs					
(AVG MAN HRS: 2.5) (NOTE: COMPLIANCE: Bombardier Learjet Inc. recommends these instructions are completed before or at the same time of the next scheduled maintenance activity.)						Ldg					
45-32-42	**Landing Gear - Nose Wheel Actuator Connector Backshell Replacement**							T (A/R)		Optional	
32 A/F						Mos					
Eff: 29-Aug-2022						Hrs					
(AVG MAN HRS: 6.5)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-32-5	**Landing Gear - Improved Main Landing Gear Shock Strut Lower Bearings**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-5 Rev 1	**Landing Gear - Improved Main Landing Gear Shock Strut Lower Bearings**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-5 Rev 2	**Landing Gear - Improved Main Landing Gear Shock Strut Lower Bearings**							RE (-)		Optional	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-5 Rev 3	**Landing Gear - Improved Main Landing Gear Shock Strut Lower Bearings**							RE (-)		Optional	
32 A/F						Mos	29-Aug-2019				
Eff: 02-Jun-1999 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-32-6	**Leading Gear - Modification of Landing Gear Free-Fall Cable Retainer**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-6 Rev 1	**Leading Gear - Modification of Landing Gear Free-Fall Cable Retainer**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 16-Jun-1999 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-7	**Landing Gear - Replacement of Emergency Park Brake Handle Screw**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-7 Rev 1	**Landing Gear - Replacement of Emergency Park Brake Handle Screw**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 14-Jul-2000 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-32-8	**Landing Gear - Replacement of Nose Landing Gear Squat Switch Camrod**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Eff: 18-Oct-2000 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 5)						Ldg	8				
45-32-8 Rev 1	**Landing Gear - Replacement of Nose Landing Gear Squat Switch Camrod**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Eff: 06-Mar-2001 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 5)						Ldg	8				
45-32-8 Rev 2	**Landing Gear - Replacement of Nose Landing Gear Squat Switch Camrod**							RE (-)		Recommended	
32 A/F						Mos	08-Jun-2009				
Eff: 06-Apr-2001 Not Applicable	PER A/C S/N					Hrs	801				
(AVG MAN HRS: 5)						Ldg	521				
45-32-8 Rev 3	**Landing Gear - Replacement of Nose Landing Gear Squat Switch Camrod**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 23-Jun-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 5)						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-32-9	**Landing Gear - Replacement of Brake Control Unit**							RE (-)		Recommended	
32 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-32-9 Rev 1	**Landing Gear - Replacement of Brake Control Unit**							RE (-)		Recommended	
32 A/F						Mos	14-Dec-2020				
Eff: 15-Sep-2000 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
75-32-07	**Landing Gear - Parking/Emergency Brake Pulley Guard Pin**							RE (-)		Recommended	
32 A/F						Mos					
Eff: 20-Sep-2021						Hrs					
(AVG MAN HRS: 3.5)						Ldg					
A3230001	**** Landing Gear - Perform Emergency Gear Extension Functional Test.**							RE	TLMC 04-10-00, TLMC 05-12-05, Ch.5 Interval		**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:32-33-00 (ZONE: 710/720/ 730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-33-00.))						Ldg	3,757				
A3240005	**** Brake Hydraulic Fuses - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-13-05, Ch.5 Interval		**≈24-Apr-2025**
32 A/F	05-13-05					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:32-41-09 (ZONE: 720/730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-41-09.))						Ldg	3,757				
A3240006	**** Brake Shuttle Module - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-13-05, Ch.5 Interval		**≈24-Apr-2025**
32 A/F	05-13-05					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:32-41-04 (ZONE: 720/730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-41-04.))						Ldg	3,757				
A3240007	**** Brake Shuttle Valves - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-14-05, Ch.5 Interval		**≈12-Oct-2025**
32 A/F	05-14-05					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
Alias1:32-42-04 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-42-04.))						Ldg	2,822				
A3240009	**** Brake Pressure Transducers - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-15-00		**≈14-Oct-2027**
32 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	(9,410.5)	4,135.7 Hrs (+25)
Alias1:32-41-08 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-41-08.))						Ldg	2,822				
A45-32-41	**Landing Gear - Main Landing Gear Actuator Upper Pin Inspection**							RE (-)		Alert	
32 A/F						Mos	23-Nov-2021				
Eff: 05-Oct-2021 Not Applicable						Hrs	4,820.5				
(AVG MAN HRS: 6) (NOTE: COMPLIANCE: Alert - Bombardier recommends these instructions are completed within the next 25 flight hours or 3 months, whichever occurs first, from the initial distribution date of this publication.)						Ldg	2,972				
A75-32-08	**Landing Gear - Main Landing Gear Actuator Upper Pin Inspection**							RE (-)		Alert	
32 A/F						Mos					
Eff: 05-Oct-2021						Hrs					
(AVG MAN HRS: 6)						Ldg					
AA3220018	**Perform Special Detailed Inspection on Main Landing Gear Shock Struts**							RE		TLMC 05-19-00	
32 A/F	Left					Yrs	07-Apr-2016	8	-/+14d	07-Apr-2024	OVD
200-0200-013						Hrs	3,621.8				
H0477						Ldg	2,105	6,600	-/+25	8,705	5,433 Ldg (+25)
Ref:NDI-104 Part 8/32-10-03, Ref:NDI-104 Part 8/32-10-02, Ref:NDI-104 Part 8/32-10-01, Ref:NDI-104 Part 7/32-10-06, Ref:NDI-104 Part 7/32-10-05, Ref:NDI-104 Part 7/32-10-04, Ref:NDI-104 Part 7/32-10-03, Ref:NDI-104 Part 7/32-10-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: NOTE: Contact Learjet Component Repair and Overhaul or your Learjet Field Support Representative for inspection instructions)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
AA3220018	**Perform Special Detailed Inspection on Main Landing Gear Shock Struts**							RE		TLMC 05-19-00	
32 A/F	Right					Yrs	07-Apr-2016	8	-/+14d	07-Apr-2024	OVD
200-0200-014						Hrs	3,621.8				
H1482						Ldg	2,105	6,600	-/+25	8,705	5,433 Ldg (+25)
	Ref:NDI-104 Part 7/32-10-06, Ref:NDI-104 Part 7/32-10-05, Ref:NDI-104 Part 7/32-10-04, Ref:NDI-104 Part 7/32-10-03, Ref:NDI-104 Part 7/32-10-01, Ref:NDI-104 Part 8/32-10-03, Ref:NDI-104 Part 8/32-10-02, Ref:NDI-104 Part 8/32-10-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: NOTE: Contact Learjet Component Repair and Overhaul or your Learjet Field Support Representative for inspection instructions)										
AA3220111	**(Left) Main Landing Gear Side-Stay Actuator - Disassemble actuator and perform detailed visual inspection.**							RE		TLMC 05-19-00	
32 A/F	Left					Yrs	20-Nov-2017	8	-/+14d	20-Nov-2025	1.5 Years (+14 Days)
200-0300-003						Hrs	4,047.7				
H0472						Ldg	2,387	10,000	-/+25	12,387	9,115 Ldg (+25)
	Alias1:32-29-10 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: NOTE: Contact Learjet Component Repair and Overhaul or your Learjet Field Support Representative for inspection instructions)										
AA3220111	**(Right) Main Landing Gear Side-Stay Actuator - Disassemble actuator and Perform Detailed Visual Inspection**							RE		TLMC 05-19-00	
32 A/F	Right					Yrs	20-Nov-2017	8	-/+14d	20-Nov-2025	1.5 Years (+14 Days)
200-0300-004						Hrs	4,047.7				
H1518						Ldg	2,387	10,000	-/+25	12,387	9,115 Ldg (+25)
	Alias1:32-29-10 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: NOTE: Contact Learjet Component Repair and Overhaul or your Learjet Field Support Representative for inspection instructions)										
AB3220016	**Nose Landing Gear Strut Assembly - Perform Special Detailed Inspection.**							RE		TLMC 05-17-00	**≈12-Dec-2029**
32 A/F	05-17-00					Mos					
						Hrs					
	(ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 32-20-01, 32-20-02, 32-20-03, and 32-20-04, and Part 8, 32-20-01, 32-20-02, 32-20-03, 32-20-04, and 32-20-05.))					Ldg		10,000	-/+25	(10,000)	6,728 Ldg (+25)
AW 32-019	**Brake Control Unit Availability**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-020	**Model 45 Nose Landing Gear Squat Switch Camrod Lubrication**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-023	**Mlg Brake Assembly Adjuster Valve Seal Improvement**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-025	**Main Landing Gear Squat Switches**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-026	**Main Landing Gear Inboard Door Actuator**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-028	**Side Brace Actuator Attach Pin**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-029	**Learjet 45 Main Landing Gear (Mlg) Side Brace Actuator Attach Update**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 32-030	**Learjet 40 & 45 Nose Landing Gear Shock Strut Servicing**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-031	**Learjet 40 & 45 Brake Assembly Water And Ice Contamination**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-032	**Lerjet 45 Main Landing Gear Side Brace Actuator Attach Pin Life Limit Extension**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-033	**Learjet 45 Main Landing Gear Side Brace Actuator Attach Pin Anti-Rotation Plate Breaking**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-041	**Learjet 40 & 45 Hydraulic Brake Fuses**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 32-042	**Emergency/Parking Brake Cable Hardware Interferance**							RE (-)		Advisory Wire	
32 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
D3260006	**Nose Landing Gear Squat Switch Rotating Disk Assembly - Lubricate.**							RE (N/A)		TLMC 05-19-00	
32 A/F						Mos					
						Hrs					
Alias1:12-21-01 (ZONE: 700) (SOURCE: MM-104) (NOTE: (Refer to 12-21-01.))						Ldg					
F3220045	**Nose Landing Actuator Attachment Fitting (Zinc coated) - Replace. (Aircraft 45-002 thru 45-039.)**							RE (N/A)		TLMC 05-19-01	
32 A/F						Mos					
						Hrs					
(ZONE: 710) (SOURCE: MM-104)						Ldg					
H3220017	**Nose Landing Gear Trunnion Axle - Perform Visual Inspection. If corrosion is found, remove axle from cylinder and perform fluorescent penetrant inspection of lug area and magnetic particle inspection of axle. If corrosion is not found, conduct fluorescent penetrant inspection of axle portion that is exposed from cylinder. (Refer to 5-10-00.)**							RE		TLMC 05-17-00	**≈12-Dec-2029**
32 A/F	05-17-00					Mos					
						Hrs					
Alias1:5-10-00 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))						Ldg		10,000	-/+25	(10,000)	6,728 Ldg (+25)
J3220120	*** Main Landing Gear Trunnion Shear Pin Bushing - Perform Visual Inspection for Bushing Migration.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F						Mos					
						Hrs					
Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104) (NOTE: (Refer to 57-10-05.))						Ldg					
L3220019	**Nose Landing Gear Actuator Attachment Pin - Remove pin and perform magnetic particle inspection.**							RE		TLMC 05-17-00	**≈12-Dec-2029**
32 A/F	05-17-00					Mos					
						Hrs					
Ref:NDI-104/Part7/32-30-02 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 32-10-10.))						Ldg		10,000	-/+25	(10,000)	6,728 Ldg (+25)
L3220020	*** Main Landing Gear Trunnion Fittings on Mid and Rear Spar - Perform Eddy Current Inspection.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈12-Dec-2029**
32 A/F						Mos					
						Hrs					
Alias1:32-11-00 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 32-11-00.))						Ldg		10,000		10,000	6,728 Ldg

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
L3220109	**Nose Landing Gear Actuator Assembly - Disassemble actuator and perform detailed visual inspection.**							RE		TLMC 05-17-00	**≈12-Dec-2029**
32 A/F	05-17-00					Mos					
						Hrs					
	(ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to EMCO Fluid Systems Component Maintenance Manual P/N 30460.))					Ldg		10,000	-/+25	(10,000)	6,728 Ldg (+25)
L3220118	*** Main Landing Gear Shock Strut Cylinder (P/N 200- 0201-105, 200-0201-106) - Perform Ultrasonic Inspection of the Lower Service Port and Forging Parting Line.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Left					Mos					
200-0201-109						Hrs					
0595						Ldg					
	(ZONE: 720/730) (SOURCE: MM-104) (NOTE: (Refer to Learjet 40 Series Nondestructive Inspection Manual [NDI- 104], Part 4, 32-10-00 and 32-10-01.))										
L3220118	*** Main Landing Gear Shock Strut Cylinder (P/N 200- 0201-105, 200-0201-106) - Perform Ultrasonic Inspection of the Lower Service Port and Forging Parting Line.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Right					Mos					
200-0201-110						Hrs					
H0597						Ldg					
	(ZONE: 720/730) (SOURCE: MM-104) (NOTE: (Refer to Learjet 40 Series Nondestructive Inspection Manual [NDI- 104], Part 4, 32-10-00 and 32-10-01.))										
L3231024	*** Main Landing Gear Inboard Door Actuator (P/N 7469-1) Cap Screws - Replace.**							RE	TLMC 04-11-00, TLMC 05-19-01		**≈12-Oct-2025**
32 A/F	Left					Mos	10-Feb-2021				
Unknown						Hrs	4,610.5	2,400		7,010.5	1,735.7 Hrs
Unknown						Ldg	2,822				
	(ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-005 thru 45-276 modified per SB 45-32-19, "Main Landing Gear Door Actuator Improvement/Saddle Installation" and 45- 277 and subsequent.))										
L3231024	*** Main Landing Gear Inboard Door Actuator (P/N 7469-1) Cap Screws - Replace.**							RE	TLMC 04-11-00, TLMC 05-19-01		**≈11-Oct-2025**
32 A/F	Right					Mos	10-Feb-2021				
Unknown						Hrs	4,610.5	2,400		7,008.5	1,733.7 Hrs
Unknown						Ldg	2,822				
	(ZONE: 720/730) (Manual Adjustment: -2 Hrs) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-005 thru 45-276 modified per SB 45-32-19, "Main Landing Gear Door Actuator Improvement/Saddle Installation" and 45- 277 and subsequent.))										
M3220136	*** Main Landing Gear Shock Strut Cylinder (P/N 200- 0201-101, 200-0201-102, 200-0201-103, 200-0201- 104, 200-0201-107, 200-0201-108) - Perform Ultrasonic Inspection of the Lower Service Port and Forging Parting Line.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Left					Mos	20-Nov-2017				
200-0201-109						Hrs	4,047.7				
0595					2,387	Ldg	2,387				
	JAA IRN:L3220122 (ZONE: 720/730) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 32-10-00 and 32-10-01.))										
M3220136	*** Main Landing Gear Shock Strut Cylinder (P/N 200- 0201-101, 200-0201-102, 200-0201-103, 200-0201- 104, 200-0201-107, 200-0201-108) - Perform Ultrasonic Inspection of the Lower Service Port and Forging Parting Line.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Right					Mos	20-Nov-2017				
200-0201-110						Hrs	4,047.7				
H0597					2,387	Ldg	2,387				
	JAA IRN:L3220122 (ZONE: 720/730) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 32-10-00 and 32-10-01.))										
P3220146	*** Main Landing Gear Shock Strut Cylinder (P/N 200-0201-109 and 200-0201-110) - Perform Ultrasonic Inspection of the Forging Parting Line.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈09-Aug-2025**
32 A/F	Left					Mos					
200-0201-109						Hrs					
0595						Ldg		4,800		4,800	1,528 Ldg
	Alias1:32-10-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 4, 32-10- 01.))										
P3220146	*** Main Landing Gear Shock Strut Cylinder (P/N 200-0201-109 and 200-0201-110) - Perform Ultrasonic Inspection of the Forging Parting Line.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈09-Aug-2025**
32 A/F	Right					Mos					
200-0201-110						Hrs					
H0597						Ldg		4,800		4,800	1,528 Ldg
	Alias1:32-10-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 4, 32-10- 01.))										

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P3231020	**Main Landing Gear Door Actuator Gimbal Assembly - Perform Eddy Current Inspection.**							RE (N/A)		TLMC 05-19-00	
32 A/F						Mos	23-May-2008				
						Hrs	166.8				
	Alias1:32-13-00 (ZONE: 700) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 32-13-00.) (Effective on Aircraft 45-005 thru 45-354 not modified per SB 45-32-25, "Landing Gear - Replacement of MLG Inboard Door Actuator Gimbal."))					Ldg	132				
P3231021	**Main Landing Gear Door Actuator Gimbal Shaft - Perform Fluorescent Penetrant Inspection.**							RE (N/A)		TLMC 05-19-00	
32 A/F						Mos	23-May-2008				
						Hrs	166.8				
	Alias1:32-13-02 (ZONE: 700) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 8, 32-13-02.) (Effective on Aircraft 45-005 thru 45-354 not modified per SB 45-32-25, "Landing Gear - Replacement of MLG Inboard Door Actuator Gimbal."))					Ldg	132				
T3220007	*** Main Landing Gear Axles - Perform Main Landing Gear Axle Beam Assembly (P/N 200-203-001) Boroscope Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Left					Mos	01-Mar-2023	48		01-Mar-2027	2.8 Years
200-0203-001						Hrs	5,150				
H1073						Ldg	3,173				
	Alias1:32-10-01 (ZONE: 720/730) (UPDATE NOTE: Main landing gear axle beam borescope inspection completed.) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-10-01.) Note: Performing IRN 3220018 is an acceptable alternative means of compliance with this inspection. IRN T3220007 has no tolerance and must be complied with no later than 48 months, however IRN 3220018 may be accomplished early in order to allign with the 48 month borescope requirement.)										
T3220007	*** Main Landing Gear Axles - Perform Main Landing Gear Axle Beam Assembly (P/N 200-203-001) Boroscope Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Right					Mos	01-Mar-2023	48		01-Mar-2027	2.8 Years
200-0203-001						Hrs	5,150				
H1077						Ldg	3,173				
	Alias1:32-10-01 (ZONE: 720/730) (UPDATE NOTE: Main landing gear axle beam borescope inspection completed.) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-10-01.) Note: Performing IRN 3220018 is an acceptable alternative means of compliance with this inspection. IRN T3220007 has no tolerance and must be complied with no later than 48 months, however IRN 3220018 may be accomplished early in order to allign with the 48 month borescope requirement.)										
T3220024	*** Main Landing Gear Side-Stay Actuator Lower Pins - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Left					Mos	22-May-2020	48		22-May-2024	OVD
200-0217-101						Hrs	4,593.2				
H3276						Ldg	2,809				
	Alias1:32-10-62, 32-30-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105)										
T3220024	*** Main Landing Gear Side-Stay Actuator Lower Pins - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Right					Mos	22-May-2020	48		22-May-2024	OVD
200-0217-101						Hrs	4,593.2				
H3278						Ldg	2,809				
	Alias1:32-10-02, 32-30-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105)										
T3220024	*** Main Landing Gear Side-Stay Actuator Upper Pins - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Left					Mos	22-May-2020	48		22-May-2024	OVD
200-0325-101						Hrs	4,593.2				
H2517						Ldg	2,809				
	Alias1:32-10-02, 32-30-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 32-10-02 and 32 - 30-01.))										
T3220024	*** Main Landing Gear Side-Stay Actuator Upper Pins - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Right					Mos	22-May-2020	48		22-May-2024	OVD
200-0325-101						Hrs	4,593.2				
H2495						Ldg	2,809				
	Alias1:32-10-02, 32-30-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105)										
T3220135	*** Main Landing Gear Side-Stay Actuator Lower Pins - Perform Detailed Visual Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Left					Mos	22-May-2020	48		22-May-2024	OVD
200-0217-101						Hrs	4,593.2				
H3276						Ldg	2,809				
	Alias1:5-10-00 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
T3220135	*** Main Landing Gear Side-Stay Actuator Lower Pins - Perform Detailed Visual Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Right					Mos	22-May-2020	48		22-May-2024	OVD
200-0217-101						Hrs	4,593.2				
H3278						Ldg	2,809				
Alias1:5-10-00 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))											
T3220135	*** Main Landing Gear Side-Stay Actuator Upper Pins - Perform Detailed Visual Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Left					Mos	22-May-2020	48		22-May-2024	OVD
200-0325-101						Hrs	4,593.2				
H2517						Ldg	2,809				
Alias1:5-10-00 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))											
T3220135	*** Main Landing Gear Side-Stay Actuator Upper Pins - Perform Detailed Visual Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Right					Mos	22-May-2020	48		22-May-2024	OVD
200-0325-101						Hrs	4,593.2				
H2495						Ldg	2,809				
Alias1:5-10-00 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))											
T3220147	*** Main Landing Gear Aft Trunnion Shear Pin - Perform Visual Inspection for Pin Migration**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Lower - Left					Mos					
4532103203-001						Hrs					
CMI-1038						Ldg					
Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-10-05.) (Effective on Aircraft 45-005 thru 45-425 not modified per SB 45-57-11.))											
T3220147	*** Main Landing Gear Aft Trunnion Shear Pin - Perform Visual Inspection for Pin Migration**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Lower - Right					Mos					
4532103203-001						Hrs					
CMI-751						Ldg					
Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-10-05.) (Effective on Aircraft 45-005 thru 45-425 not modified per SB 45-57-11.))											
T3220147	*** Main Landing Gear Aft Trunnion Shear Pin - Perform Visual Inspection for Pin Migration**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Upper - Left					Mos					
4532103202-001						Hrs					
CMI-788						Ldg					
Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-10-05.) (Effective on Aircraft 45-005 thru 45-425 not modified per SB 45-57-11.))											
T3220147	*** Main Landing Gear Aft Trunnion Shear Pin - Perform Visual Inspection for Pin Migration**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Upper - Right					Mos					
4532103202-001						Hrs					
CMI-872						Ldg					
Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-10-05.) (Effective on Aircraft 45-005 thru 45-425 not modified per SB 45-57-11.))											
T3220147	*** Main Landing Gear Forward Trunnion Shear Pin - Perform Visual Inspection for Pin Migration**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Lower - Left					Mos					
4532103201-001						Hrs					
CMI-1592						Ldg					
Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-10-05.) (Effective on Aircraft 45-005 thru 45-425 not modified per SB 45-57-11.))											
T3220147	*** Main Landing Gear Forward Trunnion Shear Pin - Perform Visual Inspection for Pin Migration**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Lower - Right					Mos					
4532103201-001						Hrs					
CMI-2076						Ldg					
Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-10-05.) (Effective on Aircraft 45-005 thru 45-425 not modified per SB 45-57-11.))											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
T3220147	*** Main Landing Gear Forward Trunnion Shear Pin - Perform Visual Inspection for Pin Migration**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Upper - Left					Mos					
4532103201-001						Hrs					
CMI-1614						Ldg					
	Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-10-05.) (Effective on Aircraft 45-005 thru 45-425 not modified per SB 45-57-11.))										
T3220147	*** Main Landing Gear Forward Trunnion Shear Pin - Perform Visual Inspection for Pin Migration**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
32 A/F	Upper - Right					Mos					
4532103201-001						Hrs					
CMI-2015						Ldg					
	Alias1:57-10-05 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-10-05.) (Effective on Aircraft 45-005 thru 45-425 not modified per SB 45-57-11.))										
V3220022	**Main Landing Gear Trunnion Pins - Perform magnetic particle inspection.**							RE		TLMC 05-19-00	
32 A/F	Aft - Left					Yrs	06-Apr-2016	8	-/+14d	06-Apr-2024	OVD
200-0213-103						Hrs	3,623.9				
H0981						Ldg	2,107				
	Alias1:32-10-07, 32-10-08 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 32-10-07 and 32-10-08.))										
V3220022	**Main Landing Gear Trunnion Pins - Perform magnetic particle inspection.**							RE		TLMC 05-19-00	
32 A/F	Aft - Right					Yrs	06-Apr-2016	8	-/+14d	06-Apr-2024	OVD
200-0213-103						Hrs	3,623.9				
H0962						Ldg	2,107				
	Alias1:32-10-07, 32-10-08 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 32-10-07 and 32-10-08.))										
V3220022	**Main Landing Gear Trunnion Pins - Perform magnetic particle inspection.**							RE		TLMC 05-19-00	
32 A/F	Fwd - Left					Yrs	06-Apr-2016	8	-/+14d	06-Apr-2024	OVD
200-0212-103						Hrs	3,623.9				
H1222						Ldg	2,107				
	Alias1:32-10-07, 32-10-08 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 32-10-07 and 32-10-08.))										
V3220022	**Main Landing Gear Trunnion Pins - Perform magnetic particle inspection.**							RE		TLMC 05-19-00	
32 A/F	Fwd - Right					Yrs	06-Apr-2016	8	-/+14d	06-Apr-2024	OVD
200-0212-103						Hrs	3,623.9				
H1156						Ldg	2,107				
	Alias1:32-10-07, 32-10-08 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 32-10-07 and 32-10-08.))										
V3240004	**** Emergency/Parking Brake Switch - Verify that "Emergency/Parking Brake" message illuminates on EICAS when parking brake is set and throttles are moved above MCR detent.**							RE	TLMC 04-10-00, TLMC 05-12-05, Ch.5 Interval		**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:32-42-01 (ZONE: 720/730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-42-01.))					Ldg	3,757				
V3240008	**** Emergency/Parking Brake Control System - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-12-05, Ch.5 Interval		**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:32-42-02 (ZONE: 720/730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-42-02.))					Ldg	3,757				
W3231022	**Main Landing Gear Inboard Door Gimbal Bracket (P/N 4532103150-001) - Perform Eddy Current Inspection.**							RE (N/A)		TLMC 05-19-00	
32 A/F						Mos	23-May-2008				
						Hrs	166.8				
	Alias1:32-13-01 (ZONE: 700) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 32-13-01.) (Effective on Aircraft 45-005 thru 45-354 not modified per SB 45-32-25, "Landing Gear - Replacement of MLG Inboard Door Actuator Gimbal Failure (Phase 2).""))					Ldg	132				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y3220000	**Nose Landing Gear Assembly - Perform visual inspection.**							RE		TLMC 05-12-05	**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 710) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y3220001	**Main Landing Gear Assembly - Perform visual inspection. Inspection to include actuator, fasteners, support structure, and squat switches.**							RE		TLMC 05-12-05	**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 720/730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y3220002	**Nose Landing Gear Actuator Pressure and Return Lines - Perform visual inspection. Lower actuator dust boot to inspect lines.**							RE		TLMC 05-12-05	**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 710) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y3220003	**Nose Gear Shock Strut - Remove and replace re tainer ring lockscrew.**							RE		TLMC 05-12-05	**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Ref:20-40-00, Ref:20-20-00 (ZONE: 710) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 20-40-00 and 20-20-00.))					Ldg	3,757				
Y3220004	**Main Landing Gear Actuator and Gear Inboard Door Actuator Attach Points - Perform visual inspection.**							RE		TLMC 05-12-05	**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 720/730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y3220006	**Landing Gear Electrical Wiring - Perform visual inspection (that portion visible inside wheel/well).**							RE		TLMC 05-12-05	**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 710/720/ 730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y3220008	**Nose Landing Gear Axle - Remove nose landing gear wheel and perform inspection. Inspect both inside and outside of axle.**							RE		TLMC 05-13-05	**≈24-Apr-2025**
32 A/F	05-13-05					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:32-40-01 (ZONE: 710) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-40-01.))					Ldg	3,757				
Y3220124	**Nose Landing Gear - Perform detailed visual inspection of the nose landing gear uplock roller bracket.**							RE		TLMC 05-12-05	**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 710) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y3230002	**Main Landing Gear Free Fall Roller - Perform visual inspection. Pay particular attention to binding of rollers.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
32 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y3231023	**Main Landing Gear Inboard Door Actuator (P/N 7469) End Cap Screws - Perform Detailed inspection.**							RE (N/A)		TLMC 05-11-05	
32 A/F	05-11-05					Mos	09-Feb-2024				
						Hrs	5,253.5				
	Ref:32-31-02 (ZONE: 720/730) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y3240000	**Nose and Main Tires - Perform Visual Inspection.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
32 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:12-10-04 (ZONE: 710/720/ 730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 12-10-04.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y3240001	**Brake Lines - Perform visual inspection. Inspect all brake lines visible in wheel wells and on struts.**							RE		TLMC 05-12-05	**≈24-Oct-2024**
32 A/F	05-12-05					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 720/730) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y3240002	**Brake Assemblies - Perform Visual Inspection with parking brake set. Worn brakes are visually indicated when the wear indicator pins become even with the outer surface of the wear indicator sleeve.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
32 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:32-41-01 (ZONE: 720/730) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 32-41-01.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y3240003	**Brake Control System Linear Variable Differential Transformer (LVDT) - Perform Visual Inspection.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
32 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 220CL, 220CR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y3260005	**Nose Landing Gear Squat Switch Rotating Disk Assembly - Lubricate.**							RE		TLMC 05-11-05	**≈24-Jul-2024**
32 A/F	05-11-05					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Ref:12-21-01 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft 45-001 thru 45-114 modified by SB 45-32-8 and Aircraft 45-115 and subsequent.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
▼ 33 - LIGHTS											
	Aft Circuit Breaker Panel Overlay							RE (O/C)			
33 A/F Unknown Unknown	Copilot					Mos Hrs Ldg	13-Mar-2008 0 0				
	Aft Circuit Breaker Panel Overlay							RE (O/C)			
33 A/F Unknown Unknown	Pilot					Mos Hrs Ldg	13-Mar-2008 0 0				
	Aft ELS Activation Assembly (A82) Module							RE (O/C)			
33 A/F Unknown Unknown						Mos Hrs Ldg	13-Mar-2008 0 0				
	Anti-Collision Light							RE (O/C)			
33 A/F GE16386-12-1 2167326	Lower					Mos Hrs Ldg	20-Aug-2013 2,921.9 1,710				
	Anti-Collision Light							RE (O/C)			
33 A/F GE16386-12-1 2167325	Upper New	0 0 0				Mos Hrs Ldg	26-Jul-2017 3,891.2				
	Center Switch (P5) Panel Assembly							RE (O/C)			
33 A/F Unknown Unknown						Mos Hrs Ldg	13-Mar-2008 0 0				
	Center Switch Panel (P5) Overlay							RE (O/C)			
33 A/F Unknown Unknown						Mos Hrs Ldg	13-Mar-2008 0 0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Center Switch Panel Diode (P12) Box							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Chart Holder							RE (O/C)			
	33 A/F	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Chart Holder							RE (O/C)			
	33 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cockpit Light Control Unit							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Cockpit Misc Relay Box							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Copilot Lighting Control Module							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Dimmer Control Box							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	LT-48(G)	New	0				Hrs	0				
	2124		0				Ldg	0				
		Entryway Control Light Panel							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	SP-45-52	New	0				Hrs	0				
	110701009		0				Ldg	0				
		Forward Switch Panel Assy							RE (O/C)			
	33 A/F	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Forward Switch Panel Assy							RE (O/C)			
	33 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Forward Switch Panel Overlay							RE (O/C)			
	33 A/F	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Forward Switch Panel Overlay							RE (O/C)			
	33 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Fwd Circuit Breaker Panel Overlay							RE (O/C)			
	33 A/F	Copilot		1			Mos	24-Apr-2017				
	7624608502-031						Hrs	3,777.4				
	926						Ldg	2,211				
		Fwd Circuit Breaker Panel Overlay							RE (O/C)			
	33 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Fwd ELS Activation Assembly (A81) Module							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Glareshield Floodlight Power Supply							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Glareshield Floor Floodlights Inverter							RE (O/C)			
	33 A/F			0			Mos	13-Mar-2008				
	6900135-001	New		0			Hrs	0				
	645			0			Ldg	0				
		Inverter Supply Pwr							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Inverter Supply Pwr							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Landing/Recognition Light							RE (O/C)			
	33 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Landing/Recognition Light							RE (O/C)			
	33 A/F	Right					Mos	18-May-2017				
	4587						Hrs					
	Unknown						Ldg					
		Lavatory No Smoking / Return To Seat Sign (DS138) Control Unit							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Left Inverter (PS5006) Supply Pwr							RE (O/C)			
	33 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Inverter (PS5007) Supply Pwr							RE (O/C)			
	33 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Inverter (PS5008) Supply Pwr							RE (O/C)			
	33 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Inverter (PS5009) Supply Pwr							RE (O/C)			
	33 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Inverter (PS5011) Lav Supply Pwr							RE (O/C)			
	33 A/F	No.5					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Navigation (DS37) Light							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Light Assembly, NAV Empennage							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Lighting Control (A5038) Unit							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	SP-45-53-2	New	0				Hrs	0				
	120700943		0				Ldg	0				
		Lighting Control (A5039) Unit							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	SP-45-53-2	New	0				Hrs	0				
	010800050		0				Ldg	0				
		Lighting Control (A5040) Unit							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	SP-45-53-2	New	0				Hrs	0				
	120700944		0				Ldg	0				
		Lighting Control (A5041) Unit							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	SP-45-53-2	New	0				Hrs	0				
	010800236		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Lighting Control (A5042) Unit							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Lighting Control (A5043) Unit							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	SP-45-53-2	New	0				Hrs	0				
	010800237		0				Ldg	0				
		Lighting Control (A5044) Unit							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	SP-45-53-2	New	0				Hrs	0				
	010800051		0				Ldg	0				
		Lighting Control (A5045) Unit							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	SP-45-53-2	New	0				Hrs	0				
	010800049		0				Ldg	0				
		Lighting Control Unit							RE (O/C)			
	33 A/F	Aft - Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Lighting Control Unit							RE (O/C)			
	33 A/F	No.1	52				Mos	10-Jul-2012				
	RDC4-1		2,518.8				Hrs	2,518.8				
	0972		1,501				Ldg	1,501				
		Lighting Control Unit							RE (O/C)			
	33 A/F	No.2	73				Mos	29-Apr-2014				
	RDC4-1		3,155.3				Hrs	3,155.3				
	0973		1,843				Ldg	1,843				
		Map Light							RE (O/C)			
	33 A/F	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Map Light							RE (O/C)			
	33 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Modified Pulse Controller							RE (O/C)			
	33 A/F		0				Mos	13-Mar-2008				
	2401S	New	0				Hrs	0				
	AR01262		0				Ldg	0				
		No. 1 Right Inverter (PS5003) Supply Pwr							RE (O/C)			
	33 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 2 Right Inverter (PS5004) Supply Pwr							RE (O/C)			
	33 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		No. 3 Right Inverter (PS5005) Supply Pwr							RE (O/C)			
	33 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		No. 4 Right Inverter (PS5010) Lav Supply Pwr							RE (O/C)			
	33 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Overlay Assembly, Copilot Outbd Switch (DS58) Panel							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		P35 Fuse Panel Assy							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Pressurization Panel							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Relay Options Panel Assy							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Reversion Panel (DS55) Overlay							RE (O/C)			
	33 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Reversion Panel (DS56) Overlay							RE (O/C)			
	33 A/F	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Right Navigation (DS38) Light							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Service Comp Light Assy							RE (O/C)			
	33 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Tail Cone Maintenance Light Change							RE (O/C)			
33 A/F							Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Tail Navigation (DS39) Light							RE (O/C)			
33 A/F			0				Mos	30-Mar-2010				
MS3476L8-33 PW		New	0				Hrs	1,280.2				
N/A			0				Ldg	783				
		Taxi Light							RE (O/C)			
33 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Taxi Light							RE (O/C)			
33 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Throttle Quadrant Overlay Panel							RE (O/C)			
33 A/F			0				Mos	09-Sep-2011				
7676108500-007		New	0				Hrs	2,150.3				
Unknown			0				Ldg	1,292				
45-33-1		**Lights - Modification of External Baggage and SPPR Floodlight Moisture Seal**							RE (-)		Recommended	
33 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-33-1 Rev 1		**Lights - Modification of External Baggage and SPPR Floodlight Moisture Seal**							RE (-)		Recommended	
33 A/F							Mos	28-Sep-2009				
Not Applicable							Hrs	970.5				
							Ldg	612				
45-33-1 Rev 2		**Lights - Modification of External Baggage and SPPR Floodlight Moisture Seal**							RE (-)		Recommended	
33 A/F							Mos	14-Dec-2020				
Eff: 03-Aug-2009 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-33-2		**Lights - Modification of Strobe Light Switch**							RE (-)		Optional	
33 A/F							Mos	01-Apr-2008				
Not Applicable		NO ACTION REQUIRED SB SUPERCEDED					Hrs					
							Ldg					
45-33-2 Rev 1		**Lights - Modification of Strobe Light Switch**							RE (-)		Optional	
33 A/F							Mos	01-Apr-2008				
Not Applicable		NO ACTION REQUIRED SB SUPERCEDED					Hrs					
							Ldg					
45-33-2 Rev 2		**Lights - Modification of Strobe Light Switch**							RE (-)		Optional	
33 A/F							Mos	01-Apr-2008				
Not Applicable		NO ACTION REQUIRED SB SUPERCEDED					Hrs					
							Ldg					
45-33-2 Rev 3		**Lights - Modification of Strobe Light Switch**							RE (-)		Optional	
33 A/F							Mos					
							Hrs					
							Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-33-2 Rev 4	**Lights - Modification of Strobe Light Switch**							T (-)		Optional	
33 A/F						Mos					
Eff: 04-Mar-2013						Hrs					
						Ldg					
45-33-2 Rev 5	**Lights - Modification of Strobe Light Switch**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 15-Jun-2015						Hrs					
(AVG MAN HRS: 5.5)						Ldg					
45-33-3	**Lights - Replacement of the Landing/Recognition Light Lens**							RE (-)		Optional	
33 A/F						Mos	30-Jul-2010				
Complied With						Hrs	1,499.8				
						Ldg	910				
45-33-3 Rev 1	**Lights - Replacement of the Landing/Recognition Light Lens**							RE (-)		Optional	
33 A/F						Mos	10-Jan-2020				
Eff: 21-Jan-2013 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				
45-33-4	**Lights - Galley/Closet Kick Panel Accent Light Dimming**							RE (-)		Optional	
33 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-33-4 Rev 1	**Lights - Galley/Closet Kick Panel Accent Light Dimming**							RE (-)		Optional	
33 A/F						Mos	29-Aug-2019				
Eff: 05-May-2008 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-33-5	**Lights - Installation of LED Wing Navigation Light Assemblies**							RE (-)		Optional	
33 A/F						Mos	28-Jan-2010				
Eff: 26-May-2009 Complied With						Hrs	1,172.9				
						Ldg	723				
45-33-6	**Lights - Installation of LED Tail Navigation Light Assembly**							RE (-)		Optional	
33 A/F						Mos	28-Jan-2010				
Eff: 26-May-2009 Complied With						Hrs	1,172.9				
						Ldg	723				
90-07-08 R1	**S.E.L.A. LABORATOIRE ABADIE (SELA) Fluorescent Lighting Lamp Connectors, Part Number (P/N) 3185-1A, and Remote Power Units (RPU), P/Ns TR 992, TR 992A, TR 992-1, TR 992-3, TR 992-4, and TR 992-5, manufactured by SELA**							RE (-)		Mandatory (Appliance AD)	
33 A/F						Mos	31-Mar-2008				
Eff: 02-Jul-1990 Not Applicable						Hrs	11.6				
						Ldg	11				
95-22-01	**Aerospace Lighting Corporation Power Units and Power Supplies - Fluorescent Lighting System**							RE (-)		Mandatory (Appliance AD)	
33 A/F						Mos	31-Mar-2008				
Eff: 04-Dec-1995 Not Applicable						Hrs	11.6				
						Ldg	11				
AW 33-001	**Anti-Collision Light**							RE (-)		Advisory Wire	
33 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
Y3310000	**Flight Compartment Lighting - Perform operation of the following: a. Map lights. b. Instrument panel fluorescent lights. c. Instrument/indicator lights. d. Light dimming switches. e. Crew warning panel. f. Panel overlays.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
33 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
(ZONE: 220) (SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y3340000	**Exterior Lighting Systems - Perform operation of the following: a. Taxi lights. b. Anti-collision beacons. c. Navigation lights. d. Strobe lights. e. Landing/Recognition lights. f. Wing ice inspection lights. g. Emergency door egress lights.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
33 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
(SOURCE: MM-104, MM-105)						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y3350003	**Emergency Lighting System - Perform Operational Check**							RE		TLMC 05-13-02	**≈24-Apr-2025**
33 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:33-50-00 (ZONE: 200) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 33-50-00.))						Ldg	3,757				
▼ 34 - NAVIGATION											
	GPS / XM Antenna							RE (O/C)			
34 A/F						Mos	27-Sep-2023				
10710						Hrs	5,197.3				
6515						Ldg	3,212				
	(TAT) Total Air Temperature Probe							RE (O/C)			
34 A/F		0				Mos	13-Mar-2008				
102AU1AG	New	0				Hrs	0				
A74860		0				Ldg	0				
	ADF Antenna							RE (O/C)			
34 A/F	No.1	0				Mos	13-Mar-2008				
7510300-901	New	0				Hrs	0				
0707C805		0				Ldg	0				
	ADF Antenna							RE (O/C)			
34 A/F	No.2					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	AFIS (Flight Information System) Antenna							RE (O/C)			
34 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	AFIS Data Management Unit							RE (O/C)			
34 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Airserve Computer							RE (O/C)			
34 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Altimeter							RE (O/C)			
34 A/F	StandBy					Mos	12-Apr-2012				
16650-1142						Hrs	2,413.2				
175579B						Ldg	1,441				
Ref:AMM 34-15-01											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Altimeter, Standby Indicator							RE (O/C)			
34 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		ATC Antenna							RE (O/C)			
34 A/F	DMN150-2-2	Aft	0				Mos	13-Mar-2008				
	107659	New	0				Hrs	0				
			0				Ldg	0				
		ATC Antenna							RE (O/C)			
34 A/F	DMN150-2-2	Fwd	18				Mos	22-May-2020				
	143625						Hrs	4,593.2				
							Ldg	2,809				
		Attitude Heading Reference Computer (AHRS)							RE (O/C)			
34 A/F	145130-6000	No.1					Mos	01-Mar-2013				
	4484						Hrs	2,753.9				
							Ldg	1,625				
		Attitude Heading Reference Computer (AHRS)							RE (O/C)			
34 A/F	145130-6000	No.2				5	Mos	01-Mar-2013				
	1500						Hrs	2,753.9				
							Ldg	1,625				
		Attitude Heading Reference Computer (AHRS) Fan							RE (O/C)			
34 A/F	140691-0000	No.1	0				Mos	13-Mar-2008				
	4525	New	0				Hrs	0				
			0				Ldg	0				
		Attitude Heading Reference Computer (AHRS) Fan							RE (O/C)			
34 A/F	140691-0000	No.2	0				Mos	13-Mar-2008				
	4547	New	0				Hrs	0				
			0				Ldg	0				
		Attitude Heading Reference System (AHRS) Memory Module							RE (O/C)			
34 A/F	Unknown	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Attitude Heading Reference System (AHRS) Memory Module							RE (O/C)			
34 A/F	Unknown	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Attitude Heading Reference System (AHRS) Computer Tray							RE (O/C)			
34 A/F	Unknown	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Attitude Heading Reference System (AHRS) Computer Tray							RE (O/C)			
34 A/F	Unknown	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Computer, Air Data							RE (O/C)			
34 A/F	7030700-71704	No.1	0				Mos	13-Mar-2008				
	07101648	New	0				Hrs	0				
			0				Ldg	0				
		Computer, Air Data							RE (O/C)			
34 A/F	7030700-71704	No.2	0				Mos	13-Mar-2008				
	07101649	New	0				Hrs	0				
			0				Ldg	0				
		DME Antenna							RE (O/C)			
34 A/F	DMN150-2-2	Aft	0				Mos	13-Mar-2008				
	110333	New	0				Hrs	0				
			0				Ldg	0				
		DME Antenna							RE (O/C)			
34 A/F	DMN150-9-2	Fwd	0				Mos	13-Mar-2008				
	9424	New	0				Hrs	0				
			0				Ldg	0				
		DME Indicator							RE (O/C)			
34 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Dual Angle Of Attack Indicator							RE (O/C)			
34 A/F	Unknown						Mos	13-Mar-2008				
	Unknown						Hrs	0				
							Ldg	0				
		Enhanced Ground Proximity Warning (EGPWS) Computer							RE (O/C)			
34 A/F	965-0976-040-218-218						Mos	11-Mar-2011				
	26690						Hrs	1,857.4				
							Ldg	1,121				
		Flight Management Configuration Module							RE (O/C)			
34 A/F	30171	No.1					Mos	27-Sep-2023				
	3655						Hrs	5,197.3				
							Ldg	3,212				
		Flight Management Configuration Module							RE (O/C)			
34 A/F	30171	No.2					Mos	27-Sep-2023				
	3654						Hrs	5,197.3				
							Ldg	3,212				
		Flight Management Control Display CDU							RE (O/C)			
34 A/F	3017-41-221	Copilot					Mos	27-Sep-2023				
	3624						Hrs	5,197.3				
							Ldg	3,212				
		Flight Management Control Display CDU							RE (O/C)			
34 A/F	3017-41-221	Pilot					Mos	27-Sep-2023				
	3615						Hrs	5,197.3				
							Ldg	3,212				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Flux Valve							RE (O/C)			
	34 A/F	Left	0				Mos	13-Mar-2008				
	7010133	New	0				Hrs	0				
	0703H337		0				Ldg	0				
		Flux Valve							RE (O/C)			
	34 A/F	Right	0				Mos	13-Mar-2008				
	7010133	New	0				Hrs	0				
	0708H657		0				Ldg	0				
		FMS Antenna							RE (O/C)			
	34 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		FMS Antenna							RE (O/C)			
	34 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		FMS Control Unit							RE (O/C)			
	34 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		FMS Control Unit							RE (O/C)			
	34 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		FMS Data (DTU) Transfer Unit							RE (O/C)			
	34 A/F		0				Mos	10-Jan-2020				
	1406-01-1	New	0				Hrs	4,590.8				
	4697		0				Ldg	2,807				
		Glidescope (E11) Antenna							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Glidescope (E12) Antenna							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		GPS Antenna							RE (O/C)			
	34 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		GPS Antenna							RE (O/C)			
	34 A/F	No.2					Mos	27-Sep-2023				
	10708						Hrs	5,197.3				
	14246						Ldg	3,212				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		GPS Antenna							RE (O/C)			
	34 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		GPWS Control Panel							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Integrated Navigation Unit							RE (O/C)			
	34 A/F	No.1	0				Mos	13-Mar-2008				
	7510100-631	New	0				Hrs	0				
	0709B372		0				Ldg	0				
		Integrated Navigation Unit							RE (O/C)			
	34 A/F	No.2	0				Mos	13-Mar-2008				
	7510100-633	New	0				Hrs	0				
	0709B359		0				Ldg	0				
		Lightning Detection Processor							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Marker Beacon Antenna							RE (O/C)			
	34 A/F		0				Mos	13-Mar-2008				
	DMN27-3	New	0				Hrs	0				
	16455		0				Ldg	0				
		Marker Beacon Antenna Coupler							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
	Ref:AMM 34-31-03											
		Marker Beacon Antenna Splitter							RE (O/C)			
	34 A/F		0				Mos	13-Mar-2008				
	DMH21-1	New	0				Hrs	0				
	34845		0				Ldg	0				
		Nav VHF (A42) Duplexer							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Navigation Receiver Module							RE (O/C)			
	34 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Navigation Receiver Module							RE (O/C)			
	34 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Phasing Coupler							RE (O/C)			
	34 A/F		0				Mos	13-Mar-2008				
	DMN4-17-2	New	0				Hrs	0				
	20614		0				Ldg	0				
		Pitot Static Probe							RE (O/C)			
	34 A/F	StandBy					Mos	14-Feb-2019				
	0856TJ4						Hrs	4,395.3				
	310221						Ldg	2,600				
		Primary Pitot Static Probe							RE	Replacement Schedule, TLMC 05-19-01		**≈17-Feb-2036**
	34 A/F	Left	0				Mos	14-Feb-2019				
	6634100000-001	New	0				Hrs	4,402.9	15,000		19,402.9	14,128.1 Hrs
	310221		0				Ldg	2,608				
		Alias1:(Std)P3411053, (EMP)3411053 (ZONE: 200) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Effective on aircraft certified and maintained for Reduced Vertical Separation Minimum operations.))										
		Primary Pitot Static Probe							RE	Replacement Schedule, TLMC 05-19-01		**≈13-Jun-2032**
	34 A/F	Right	0				Mos	13-Mar-2008				
	0856TJ2	New	0				Hrs	0	15,000		15,000	9,725.2 Hrs
	246559		0				Ldg	0				
		Alias1:(Std)P3411054, (EMP3411054 (ZONE: 200) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Effective on aircraft certified and maintained for Reduced Vertical Separation Minimum operations.))										
		Radar Altimeter Antenna							RE (O/C)			
	34 A/F	Aft	0				Mos	13-Mar-2008				
	S67-2002-4	New	0				Hrs	0				
	552-14837		0				Ldg	0				
		Radar Altimeter Antenna							RE (O/C)			
	34 A/F	Fwd	0				Mos	13-Mar-2008				
	S67-2002-4	New	0				Hrs	0				
	552-14828		0				Ldg	0				
		Radar Altimeter Receiver							RE (O/C)			
	34 A/F		0				Mos	13-Mar-2008				
	7001840-936	New	0				Hrs	0				
	0710E135		0				Ldg	0				
		RS-232 Converter							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Standby Airspeed Indicator							RE (O/C)			
	34 A/F		0				Mos	13-Mar-2008				
	26240-1129	New	0				Hrs	0				
	284595		0				Ldg	0				
		Standby Attitude Indicator							RE (O/C)			
	34 A/F				0		Mos	03-Jun-2010				
	501-1648-02	Repaired			0		Hrs	1,392.6				
	1646				0		Ldg	850				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Standby Compass							RE (O/C)			
	34 A/F		0				Mos	13-Mar-2008				
	PAI700-5V	New	0				Hrs	0				
	63441A		0				Ldg	0				
		TAWS Relay Box							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Adapter Assembly							RE (O/C)			
	34 A/F	Lower					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Adapter Assembly							RE (O/C)			
	34 A/F	Upper					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Antenna							RE (O/C)			
	34 A/F	Lower	0				Mos	13-Mar-2008				
	7514081-913	New	0				Hrs	0				
	ANE28139		0				Ldg	0				
		TCAS Antenna							RE (O/C)			
	34 A/F	Upper	0				Mos	13-Mar-2008				
	7514081-913	New	0				Hrs	0				
	ANE28234		0				Ldg	0				
		TCAS Computer							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Configuration Module							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Lower Antenna Cable							RE (O/C)			
	34 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Lower Antenna Cable							RE (O/C)			
	34 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Lower Antenna Cable							RE (O/C)			
	34 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		TCAS Lower Antenna Cable							RE (O/C)			
	34 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Processor							RE (O/C)			
	34 A/F	Pilot	49				Mos	17-Apr-2012				
	7517900-55004		2,413.2				Hrs	2,413.2				
	20009421		1,441				Ldg	1,441				
		TCAS Relay Box Assembly							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Upper Antenna Cable							RE (O/C)			
	34 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Upper Antenna Cable							RE (O/C)			
	34 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Upper Antenna Cable							RE (O/C)			
	34 A/F	No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		TCAS Upper Antenna Cable							RE (O/C)			
	34 A/F	No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Terrain Awareness Warning (TAWS) Computer							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Terrain Awarness Warning (TAWS) Configuration Module							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Upper Mode S ATC Antenna							RE (O/C)			
	34 A/F	Left	0				Mos	13-Mar-2008				
	DMN150-2-2	New	0				Hrs	0				
	114148		0				Ldg	0				
		Upper Mode S ATC Antenna							RE (O/C)			
	34 A/F	Right	0				Mos	13-Mar-2008				
	DMN150-2-2	New	0				Hrs	0				
	110322		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		VOR/Localizer Antenna							RE (O/C)			
	34 A/F	Left	0				Mos	13-Mar-2008				
	DMN4-17-1/N	New	0				Hrs	0				
	25182		0				Ldg	0				
		VOR/Localizer Antenna							RE (O/C)			
	34 A/F	Right	0				Mos	13-Mar-2008				
	DMN4-17-1/N	New	0				Hrs	0				
	25183		0				Ldg	0				
		Weather Radar Controller							RE (O/C)			
	34 A/F		0				Mos	13-Mar-2008				
	7008471-407	New	0				Hrs	0				
	06119304		0				Ldg	0				
		Weather Radar Lightning Sensor Antenna							RE (O/C)			
	34 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Weather Radar Receiver/Transmitter/Antenna							RE (O/C)			
	34 A/F		0				Mos	13-Mar-2008				
	7021450-801	New	0				Hrs	0				
	07107872		0				Ldg	0				
		Weather Radar Transceiver							RE (O/C)			
	34 A/F		149				Mos	26-Aug-2020				
	7021450-801		4,597				Hrs	4,597				
	0707872		2,812				Ldg	2,812				
050A10N		**Navigation Database Update**							RE (A/R)			
	34 A/F						Days	21-Jun-2023				
	(AVG MAN HRS: 1)						Hrs					
							Ldg					
1XXX.XX.( )-34-3706(ex)		**Procedures for Correcting Erroneous Date Expired Database Message in the Flight Management System**							RE (-)			
	34 A/F						Mos	30-Aug-2018				
	Complied With						Hrs	4,334.1				
							Ldg	2,548				
2000-07-27		**Honeywell - Prevent Loss Of Air Data Sources**							RE (-)	Mandatory (Appliance AD)		
	34 A/F						Mos	31-Mar-2008				
	Not Applicable						Hrs	11.6				
							Ldg	11				
2001-14-51		**UPS Aviation Technologies, Inc., Model Apollo SL30 VHF NAV/COMM Radio**							RE (-)	Mandatory (Appliance AD)		
	34 A/F						Mos	31-Mar-2008				
	Eff: 30-Jul-2001 Not Applicable						Hrs	11.6				
							Ldg	11				
2001-15-17		**Rockwell Collins. CTL-92 - Transponder Control Panels**							RE (-)	Mandatory (Appliance AD)		
	34 A/F						Mos	31-Mar-2008				
	Eff: 20-Aug-2001 Not Applicable						Hrs	11.6				
	Brand A:9990-2001-15-17						Ldg	11				
2001-23-17		**Garmin GNS 430 units**							RE (-)	Mandatory (Appliance AD)		
	34 A/F						Mos	31-Mar-2008				
	Eff: 28-Dec-2001 Not Applicable						Hrs	11.6				
	Brand A:9990-2001-23-17						Ldg	11				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2002-06-05	**Mode C 621A-3 Air Traffic Control (ATC) Transponders**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 26-Apr-2002 Not Applicable						Hrs	11.6				
						Ldg	11				
2002-06-06	**Rockwell Collins TDR-94 and TDR-94D Mode S transponders**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 03-May-2002 Not Applicable						Hrs	11.6				
Brand A:9990-2002-06-06						Ldg	11				
2002-13-07	**Honeywell - Inertial Reference Units (IRU)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 09-Aug-2002 Not Applicable						Hrs	11.6				
						Ldg	11				
2002-14-19	**Rockwell Collins, Inc. ADC-85, ADC-85A, ADC-850D, and ADC-850F Air Data Computers**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 23-Aug-2002 Not Applicable						Hrs	11.6				
Brand A:9990-2002-14-19 (AVG MAN HRS: 6) (APX COST: 1,040)						Ldg	11				
2003-04-06	**Inspect Primus Integrated Nav Unit/Revise AFM (SUPERSEDED BY AD 2006- 22-05)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Mar-2008				
Eff: 11-Mar-2003 Complied With	AT MANUFACTURE					Hrs	8.7				
Brand A:9990-2003-04-06						Ldg	8				
2003-13-08	**Goodrich - TAWS8000 Terrain Awareness Warning System (TAWS)**				**(SUPERSEDED BY FAA AD 2004-08-15)**			RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Mar-2008				
Complied With	AT MANUFACTURE					Hrs	8.7				
Brand A:9990-2003-13-08						Ldg	8				
2004-08-15	**Goodrich Avionics Systems, Inc - TAWS8000 terrain awareness warning systems (TAWS)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 07-Jun-2004 Not Applicable						Hrs	11.6				
Brand A:9990-2004-08-15 (AVG MAN HRS: 3) (APX COST: 195)						Ldg	11				
2004-08-16	**Narco - AT150 Transponder Modification**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 01-Jun-2004 Not Applicable						Hrs	11.6				
						Ldg	11				
2004-10-15	**Garmin Transponder Software (SUPERSEDED BY AD 2005- 01-19)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Mar-2008				
Eff: 08-Aug-2004 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
2004-13-20	**GPS navigation units**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 03-Aug-2004 Not Applicable						Hrs	11.6				
						Ldg	11				
2004-16-14	**Thales Avionics TA/RA VSI-TCAS Indicators**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 13-Sep-2004 Not Applicable						Hrs	11.6				
						Ldg	11				
2004-21-04	**Becker Flugfunkwerk AR-4201 Very High Frequency (VHF) AM Transceiver - Aircraft flight manual (AFM)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 11-Dec-2001 Not Applicable						Hrs	11.6				
						Ldg	11				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2005-01-19	**GARMIN International Inc. - Mode S Transponders**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 23-Feb-2005 Not Applicable						Hrs	11.6				
Brand A:9990-2005-01-19						Ldg	11				
2005-25-08	**Shadin ADC-2000 Air Data Computers - Electronic Flight Information System (EFIS)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 23-Jan-2006 Not Applicable						Hrs	11.6				
						Ldg	11				
2006-16-18	**Sandel Avionics Incorporated - Installing a warning placard on the TAWS/RMI**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Mar-2008				
Eff: 25-Sep-2006 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
Brand A:9990-2006-16-18											
2006-22-05	**Honeywell Primus II RNZ-850/-851 Integrated Navigation Unit (INU) - CANCELLED(SUPERCEDED BY AD 2010-07-02)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 01-Dec-2006 Complied With						Hrs					
						Ldg					
2007-07-12	**Honeywell NZ-2000, IC-800, or IC-800E Navigation Computers**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Mar-2008				
Eff: 02-May-2007 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
2007-14-06	**ACAS II SYSTEM - Isolation diode**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 16-Aug-2007 Not Applicable						Hrs	11.6				
						Ldg	11				
2009-05-08	**Trimble or FreeFlight Systems 2101 I/O Approach Plus global positioning system (GPS))**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	20-Oct-2009				
Eff: 20-Apr-2009 Not Applicable						Hrs	1,013.2				
						Ldg	635				
2010-07-02	**Integrated Navigation Units (INUs) - Honeywell Primus II RNZ-850( )/-851( ) (This AD supersedes AD 2006-22-05)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	29-Nov-2012				
Eff: 03-May-2010 Complied With						Hrs	2,697.6				
						Ldg	1,592				
2012-02-08	**Aviation Communication & Surveillance Systems (ACSS) Traffic Alert and Collision Avoidance System (TCAS) Units - Navigation**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	14-Dec-2020				
Eff: 13-Mar-2012 Not Applicable						Hrs	4,610.5				
Brand A:9990-2012-02-08 (AVG MAN HRS: 2) (APX COST: 3,040)						Ldg	2,822				
2012-26-15	**Honeywell International Inc. - Air Data Pressure Transducers**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	11-Jan-2013				
Eff: 24-Jan-2013 Not Applicable	NOT APPLICBLE ON PER HONEYWELL ALERT SB ADM/ADC/ADAHRS-34-A01 REVISION 0 DATED 11/06/2012					Hrs	2,729.9				
						Ldg	1,611				
Brand A:9990-2012-26-15											
2012-26-15 (G) (1)	**Remove Identify Out Of Spec Adc, Adm, Adahrs, And Dadc. (Rescinded By Faa 2012-26-15 R1) Affected Adc, Adm, Adahrs, Or Dadc**							RE (-)		Mandatory	
34 A/F						Mos	11-Jan-2013				
Not Applicable	NOT APPLICBLE ON PER HONEYWELL ALERT SB ADM/ADC/ADAHRS-34-A01 REVISION 0 DATED 11/06/2012					Hrs	2,729.9				
						Ldg	1,611				
2012-26-15 (G) (2)	**Perform Identify Out Of Spec Adc, Adm, Adahrs, And Dadc. (Rescinded By Faa 2012-26-15 R1) Pitot-Static Certification Test**							RE (-)			
34 A/F						Mos	11-Jan-2013				
Not Applicable	NOT APPLICBLE ON PER HONEYWELL ALERT SB ADM/ADC/ADAHRS-34-A01 REVISION 0 DATED 11/06/2012					Hrs	2,729.9				
						Ldg	1,611				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2012-26-15 R1	**Honeywell International Inc. - Air Data Pressure Transducers (This action rescinds AD 2012-26-15, Amendment 39-17310 (78 FR 1735, January 9, 2013).)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos					
Eff: 03-Dec-2014 Not Applicable	THIS REVISION RESCINDS THE PREVIOUS VERSION OF AD 2012-26-15 EFFECTIVE DATE JANUARY 24, 2013 MAKING THIS AD NO LONGER APPLICABLE					Hrs					
						Ldg					
2014-05-27	**Rockwell Collins, Inc - Navigation - TPR-720 and TPR-900 Mode S transponders test and calibration**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	14-Dec-2020				
Eff: 02-May-2014 Not Applicable						Hrs	4,610.5				
Brand A:9990-2014-05-27						Ldg	2,822				
2014-18-01	**Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	14-Dec-2020				
Eff: 14-Oct-2014 Not Applicable						Hrs	4,610.5				
Brand A:9990-2014-18-01 (AVG MAN HRS: 4) (APX COST: 85)						Ldg	2,822				
2015-10-51	**Avidyne Integrated Flight Display (IFD) - Navigation - Incorporate Operational Limitations into Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation.**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
Brand A:9990-2015-10-51						Ldg	2,822				
2017-04-06	**Altimeter - United Instruments Model 5934 Series - Slow Diaphragm Leak**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	12-Mar-2018				
Eff: 07-Apr-2017 Not Applicable	AEROSONIC STANDBY ALTIMETER INSTALLED					Hrs	4,155.2				
						Ldg	2,448				
(AVG MAN HRS: 1) (NOTE: APPLICABILITY: This AD applies to United Instruments, Inc. 5934 series altimeters that were manufactured between January 2015 and February 2016 and installed in airplanes and helicopters. NOTE: Refer to United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016.)											
2017-11-11	**ATC Transponder System - Automatic Dependent Surveillance Broadcast (ADS-B) Universal Access Transceiver Units**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos					
Eff: 11-Jul-2017						Hrs					
(AVG MAN HRS: 1) (NOTE: APPLICABILITY: This AD applies to the following NavWorx, Inc., Automatic Dependent Surveillance-Broadcast (ADS-B) Universal Access Transceiver units (unit) installed on aircraft certificated in any category, including experimental: (1) Model ADS600-B part number (P/N) 200-0012; (2) Model ADS600-B P/N 200-0013; and (3) Model ADS600-EXP P/N 200-8013.)						Ldg					
2017-22-14	**Navigation - Upgrade the Rockwell Collins, Inc. TSSA-4100 FLS to RCPN 810-0052-013 or 810-0052-102**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos					
Eff: 20-Dec-2017						Hrs					
(AVG MAN HRS: 1) (NOTE: NOTE: Refer to Rockwell Collins Service Information Letter, TSSA-4100-SIL-10-1, Revision No. 9, dated March 31, 2017; or Rockwell Collins Service Information Letter TSSA-4100-SIL-10-1, Revision No. 10, dated July 10, 2017.)						Ldg					
2018-03-04	**Airspeed/Mach Indicator - Pitot Probe - Inspect/ Replace**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	30-Nov-2018				
Eff: 16-Mar-2018 Not Applicable	BY MANUFACTURE OF INSTALLED COMPONENT					Hrs	4,336.4				
(AVG MAN HRS: 2)						Ldg	2,549				
2018-03-04 Par. 2(g)	**Airspeed/Mach Indicator - Pitot Probe - Determine Number of Affected Pitot Probes Installed**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	30-Nov-2018				
Eff: 16-Mar-2018 Not Applicable	BY MANUFACTURE OF INSTALLED COMPONENT					Hrs	4,336.4				
						Ldg	2,549				
(AVG MAN HRS: 1) (NOTE: APPLICABILITY: This AD applies to Rosemount Aerospace, Inc. Model 851AK pitot probes that were repaired by CSI Aerospace Inc. and have a serial number listed in paragraph (c)(1) of this AD that are known to be installed on but not limited to the airplanes listed in paragraph (c)(2) of this AD. Pitot probes that were repaired by CSI Aerospace Inc. that have a repair date of August 1, 2014, or later, are excluded from the applicability.)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2018-03-04 Par. H1	**Replace Affected Pitot Probes (Mandatory)**							RE (-)		Mandatory	
34 A/F						Mos	30-Nov-2018				
Not Applicable	BY MANUFACTURE OF INSTALLED COMPONENT					Hrs	4,336.4				
						Ldg	2,549				
2018-03-04 PARA (H)(2)	**Do Not Install On Any Airplane A Pitot Probe Having A Serial Number Listed In Para (C)(1) Of This Ad, Unless It Has Been Properly Repaired, And If Repaired By Csi Aerospace, Inc., Has A Repair Date Of August 1, 2014, Or Later**							RE (-)			
34 A/F						Mos	30-Nov-2018				
Not Applicable	BY MANUFACTURE OF INSTALLED COMPONENT					Hrs	4,336.4				
						Ldg	2,549				
2019-01-02	**Attitude and Direction Data System - Automatic Dependent Surveillance-Broadcast (ADS-B) IN Function - Disable/ Revise AFM Supplement**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	29-Aug-2019				
Eff: 06-Feb-2019 Not Applicable	DOES NOT APPLY					Hrs	4,516.2				
						Ldg	2,733				
(NOTE: COMPLIANCE: Before the next flight in IMC or at night.)											
2019-07-10	**Attitude and Directional Data System**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	21-May-2019				
Eff: 29-May-2019 Not Applicable	EQUIPMENT NOT INSTALLED ON AIRCRAFT					Hrs					
						Ldg					
2019-07-10 Paragraph (f)(1)	**Attitude and Directional Data System - Remove the AHRS unit from service**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos					
Eff: 29-May-2019						Hrs					
						Ldg					
2019-12-09	**Navigation - Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500 - Revise AFM/ Fabricate Placard**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	16-Aug-2019				
Eff: 23-Jul-2019 Not Applicable	AFFECTED EQUIPMENT NOT INSTALLED ON AIRCRAFT					Hrs					
						Ldg					
(NOTE: NOTE: This AD applies to Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500, P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, and 810-0234-4B0001.)											
2019-13-03	**ATC Transponder System - Trig Avionics Limited TT31 Mode S Transponders/ Avidyne Corporation AXP340 Mode S Transponders / BendixKing/Honeywell International KT74 Mode S Transponders - Inspection**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	29-Aug-2019				
Eff: 27-Aug-2019 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
(NOTE: This AD applies to: (1) Trig Avionics Limited TT31 Mode S transponders, part number (P/N) 00220-00-01 and P/N 00225-00-01, with a serial number (S/N) from 05767 to S/N 09715 inclusive, and Modification (Mod) Level 6 or below, installed. (2) Avidyne Corporation AXP340 Mode S transponders, P/N 200-00247-0000, also marked with Trig Avionics P/N 01155-00-01, with a S/N from 00801 to S/N 01377 inclusive, and Mod Level 0, installed. (3) BendixKing/Honeywell International KT74 Mode S transponders, P/N 89000007-002001, also marked with Trig Avionics P/N 01157-00-01, with a S/N from 01143 to S/N 02955 inclusive, and Mod Level 0, installed.)											
2019-13-03 PARA (G)	**Inspect The Transponder Installation To Determine If The Transponder Is Installed In A Conventional Aft-Facing Avionics Rack**							RE (-)			
34 A/F						Mos	29-Aug-2019				
Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
2019-13-03 PARA (H)	**Do Not Install An Affected Transponder On Any Aircraft, Unless The Transponder Is Installed In A Conventional Aft-Facing Avionics Rack As Defined In This Ad**							RE (-)			
34 A/F						Mos	29-Aug-2019				
Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2021-08-07	**Navigation System - GPS-4000S Global Positioning System**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	26-Mar-2023				
Eff: 12-May-2021 Not Applicable	by P/N. No further action required.					Hrs	5,150.6				
						Ldg	3,174				
(NOTE: Applicability: This AD applies to Rockwell Collins, Inc. GPS-4000S Global Positioning System (GPS) part number (P/N) 822-2189-100 installed on airplanes, certificated in any category.)											
2021-23-12	**Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	03-Mar-2022				
Eff: 03-Jan-2022 Complied With						Hrs	4,883				
(AVG MAN HRS: 1) (UPDATE NOTE: Airworthiness Directive 2021-23-12 Reviewed and email copy sent to crew for awareness and compliance requirements.) (NOTE: COMPLIANCE: On or before January 4, 2022: Revise the Limitations Section of the existing AFM by incorporating the limitations specified in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of this AD into the existing AFM.)						Ldg	3,012				
340000-0201	**TCAS Omni Directional Antenna**							RE (O/C)			
34 A/F	Fwd					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
34-00-CUS-9003	**EGPWS Computer Software Terrain Database Update**							RE		Custom Task	
34 A/F						Mos	21-Dec-2023	6		21-Jun-2024	28 Days
						Hrs	5,233.2				
(AVG MAN HRS: 0.5)						Ldg	3,238				
342000-0202	**TCAS Omni Directional Antenna**							RE (O/C)			
34 A/F	Aft					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
34-CUS-001	**Standby Compass - Calibration Check**							RE (A/R)			
34 A/F						Mos	26-Mar-2023				
PAI700-5V						Hrs	5,150.6				
63441A						Ldg	3,174				
45-34-1	**Navigation - Activation of GPWS Computer with Windshear**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 28-Aug-1999 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-34-10	**Navigation - Incorporation of P12562 Software Kit for UNS-1C Navigational Computer Unit Flight Management System (FMS)**							RE (-)		Recommended	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-10 Rev 1	**Navigation - Incorporation of P12562 Software Kit for UNS-1C Navigational Computer Unit Flight Management System (FMS)**							RE (-)		Recommended	
34 A/F						Mos	14-Dec-2020				
Eff: 31-Mar-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-34-11	**Navigation - Identification/Upgrade of the Integrated Navigation Units**							RE (-)		Recommended	
34 A/F						Mos	14-Dec-2020				
Eff: 09-Sep-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-34-12	**Navigation - EGPWS Steep Approach Landing Wiring Installation**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 28-Sep-2004 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 25)						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-12 Rev 1	**Navigation - EGPWS Steep Approach Landing Wiring Installation**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 28-Feb-2005 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 25)						Ldg	8				
45-34-12 Rev 2	**Navigation - EGPWS Steep Approach Landing Wiring Installation**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 28-Aug-2006 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 25)						Ldg	8				
45-34-12 Rev 3	**Navigation - EGPWS Steep Approach Landing Wiring Installation**							RE (-)		Optional	
34 A/F						Mos					
Eff: 11-Jan-2010						Hrs					
(AVG MAN HRS: 25)						Ldg					
45-34-12 Rev 4	**Navigation - EGPWS Steep Approach Landing Wiring Installation**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 08-Dec-2014						Hrs					
(AVG MAN HRS: 25) (NOTE: Aircraft registered in EASA Country)						Ldg					
45-34-13	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 02-Oct-2006 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-13 Rev 1	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 08-Jan-2007 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-13 Rev 2	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 14-May-2007 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-13 Rev 3	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 08-Oct-2007 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-13 Rev 4	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							RE (-)		Optional	
34 A/F						Mos					
Eff: 17-Nov-2008						Hrs					
						Ldg					
45-34-13 Rev 5	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							RE (-)		Optional	
34 A/F						Mos					
Eff: 20-Jul-2009						Hrs					
						Ldg					
45-34-13 Rev 6	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							RE (-)		Optional	
34 A/F						Mos					
Eff: 09-Aug-2010						Hrs					
						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-13 Rev 7	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 13-Oct-2014						Hrs					
						Ldg					
45-34-13 Rev 8	**Navigation - Installation of Enhanced Surveillance Mode S Transponder**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 17-Aug-2015						Hrs					
	(NOTE: Effectivity: A/C that were not equipped with Enhanced Surveillance Mode S Transponder in production. NOTE: Rework is required on Learjet 45-299 thru 45-367, 45-369 thru 45-445 and 45-447 thru 45-455 that have completed Revisions 5, 6, or 7 of this service bulletin. (See Paragraph 3.B.(2) of this service bulletin.) Aircraft that have completed revisions 4 or earlier of this service bulletin do not require rework.)					Ldg					
45-34-14	**Navigation - Installation of Mode S Elementary Surveillance**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-14 Rev 1	**Navigation - Installation of Mode S Elementary Surveillance**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-14 Rev 2	**Navigation - Installation of Mode S Elementary Surveillance**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-14 Rev 3	**Navigation - Installation of Mode S Elementary Surveillance**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 09-Aug-2010 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-34-15	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 06-May-2022 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-15 Rev 1	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos					
Eff: 07-Jan-2008						Hrs					
						Ldg					
45-34-15 Rev 2	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos					
Eff: 07-Feb-2011						Hrs					
						Ldg					
45-34-15 Rev 3	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos					
Eff: 04-Mar-2013						Hrs					
						Ldg					
45-34-15 Rev 4	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos					
Eff: 13-Jan-2014						Hrs					
						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-15 Rev 5	**Navigation - Flight Management System (FMS) Performance Database Update**							T (-)		Optional	
34 A/F						Mos					
Eff: 28-Jul-2014						Hrs					
						Ldg					
45-34-15 Rev 6	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 07-Aug-2017 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 2) (NOTE: NOTE: Aircraft that have completed STC ST01226WI-D, configuration 3 (UNS-1C+/1E), and configuration 6 (UNS-1Ew) already meet the intent of this service bulletin. Aircraft must be equipped with a Single or Dual UNS-1C+ or UNS-1E Flight Management System with a Software Control Number (SCN) 802.X (X=2 thru 9), or UNS-1Ew with a Software Control Number (SCN) 1000.X (X=2 thru 9).)						Ldg	2,733				
45-34-15 Rev 7	**Navigation - Flight Management System (FMS) Performance Database Update**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 28-Apr-2021						Hrs					
(AVG MAN HRS: 2) (NOTE: NOTE: Aircraft that have completed STC ST01226WI-D, configuration -003 (UNS-1C+/1E), or configuration -006 (UNS-1Ew) already meet the intent of this service bulletin. Aircraft must be equipped with a Single or Dual UNS-1C+ or UNS-1E Flight Management System with a Software Control Number (SCN) 802.X (X=2 thru 9), or UNS-1Ew with a Software Control Number (SCN) 1000.2, 1000.5 or 1002.3.)						Ldg					
45-34-16	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-16 Rev 1	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-16 Rev 2	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-16 Rev 3	**Navigation - Flight Management System (FMS) Performance Database Update**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 13-Jan-2014 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-34-16 Rev 4	**Navigation - Flight Management System (FMS) Performance Database Update**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 28-Apr-2021						Hrs					
(AVG MAN HRS: 2)						Ldg					
45-34-17	**Navigation - Modification of Attitude and Heading Reference System Electrical Connectors**							RE (-)		Recommended	
34 A/F						Mos	14-Dec-2020				
Eff: 30-Nov-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-34-18	**Navigation - Nose Avionics Compartment Wire Routing Modification**							RE (-)		Recommended	
34 A/F						Mos	14-Dec-2020				
Eff: 22-Jan-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-34-2	**Navigation - Relocation of Automatic Direction Finder (ADF), High Frequency (HF), and Transponder (ATC) Antennas.**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 18-Apr-2003 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-20	**Navigation - Installation of EGPWS Computer Software Upgrade (965-0976-040-218-218)**							RE (-)		Recommended	
34 A/F						Mos					
Eff: 29-Jun-2009						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-34-20 Rev 1	**Navigation - Installation of EGPWS Computer Software Upgrade (965-0976-040-218-218)**							RE (-)		Recommended	
34 A/F						Mos					
Eff: 30-Jul-2009						Hrs					
(AVG MAN HRS: 1)						Ldg					
45-34-20 Rev 2	**Navigation - Installation of EGPWS Computer Software Upgrade (965-0976-040-218-218)**							RE (-)		Recommended	
34 A/F						Mos	11-Mar-2011				
Eff: 28-Jun-2010 Complied With						Hrs	1,857.4				
(AVG MAN HRS: 1)						Ldg	1,121				
45-34-20 Rev 3	**Navigation - Installation of EGPWS Computer Software Upgrade (965-0976-040-218-218)**							RE (-)		Recommended	
34 A/F						Mos	06-May-2013				
Eff: 25-Mar-2013 Complied With	NO REWORK IS REQUIRED IF PREVIOUSLY COMPLIED WITH					Hrs	2,818.4				
(AVG MAN HRS: 1)						Ldg	1,658				
45-34-22	**Navigation - Relocation of the Slip/Skid Indicators**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-22 Rev 1	**Navigation - Relocation of the Slip/Skid Indicators**							RE (-)		Optional	
34 A/F						Mos	21-Sep-2009				
Complied With						Hrs	959.2				
						Ldg	607				
45-34-22 Rev 2	**Navigation - Relocation of the Slip/Skid Indicators**							RE (-)		Optional	
34 A/F						Mos	10-Jan-2020				
Eff: 04-Mar-2013 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				
45-34-23	**Navigation - Installation of EGPWS Computer Software Upgrade (965-0976-040-226 MOD 1- 226 MOD 1)**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-23 Rev 1	**Navigation - Installation of EGPWS Computer Software Upgrade (965-0976-040-226 MOD 1- 226 MOD 1)**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-23 Rev 2	**Navigation - Installation of EGPWS Computer Software Upgrade (965-0976-040-226 MOD 1- 226 MOD 1)**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 22-Apr-2013						Hrs					
						Ldg					
45-34-24	**Navigation - EGPWS Computer Relocation**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 11-Jan-2010						Hrs					
						Ldg					
45-34-25	**Navigation - Solid State Data Transfer Unit Upgrade**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-25 Rev 1	**Navigation - Solid State Data Transfer Unit Upgrade**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-25 Rev 2	**Navigation - Solid State Data Transfer Unit Upgrade**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-25 Rev 3	**Navigation - Solid State Data Transfer Unit Upgrade**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-25 Rev 4	**Navigation - Solid State Data Transfer Unit Upgrade**							RE (-)		Optional	
34 A/F						Mos	10-Jan-2020				
Eff: 18-Mar-2013 Not Applicable	DUE TO THE INSTALLATION OF STC ST04064CH "INSTALLATION OF AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST OUT (ADS-B OUT) SYSTEM", IN ACCORDANCE WITH MASTER DATA LIST 45-001-002 ON AUGUST 30, 2018					Hrs	4,590.8				
						Ldg	2,807				
45-34-25 Rev 5	**Navigation - Solid State Data Transfer Unit Upgrade**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 03-Dec-2019						Hrs					
(NOTE: NOTE: UNS-1C, UNS-1C+, UNS-1E OR UNS-1EW equipment is a prior or concurrent requirement installed in production or by STC.)						Ldg					
45-34-26	**Navigation Unit - Replacement of The Attitude Heading Reference System (AHRS)**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-26 Rev 1	**Navigation Unit - Replacement of The Attitude Heading Reference System (AHRS)**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-26 Rev 2	**Navigation Unit - Replacement of The Attitude Heading Reference System (AHRS)**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-26 Rev 3	**Navigation Unit - Replacement of The Attitude Heading Reference System (AHRS)**							RE (-)		Optional	
34 A/F						Mos	01-Mar-2013				
Complied With						Hrs	2,753.9				
						Ldg	1,625				
45-34-26 Rev 4	**Navigation Unit - Replacement of The Attitude Heading Reference System (AHRS)**							RE (-)		Optional	
34 A/F						Mos	10-Jan-2020				
Eff: 25-Mar-2013 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				
45-34-26 Rev 5	**Navigation Unit - Replacement of The Attitude Heading Reference System (AHRS)**							T (-)		Optional	
34 A/F						Mos					
Eff: 31-Jan-2022						Hrs					
(AVG MAN HRS: 115)						Ldg					
45-34-26 Rev 6	**Navigation - Replacement of the Attitude Heading Reference System (AHRS) Units**							T (-)		Optional	
34 A/F						Mos					
Eff: 22-Jun-2022						Hrs					
(AVG MAN HRS: 115)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-26 Rev 7	**Navigation - Replacement of the Attitude Heading Reference System (AHRS) Units**							T (-)		Optional	
34 A/F						Mos					
Eff: 23-Jan-2023						Hrs					
(AVG MAN HRS: 115)						Ldg					
45-34-26 Rev 8	**Navigation - Replacement of the Attitude Heading Reference System (AHRS) Units**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 18-Dec-2023						Hrs					
(AVG MAN HRS: 115)						Ldg					
45-34-27	**Navigation - Cap and Stowing of Flux Valve Unused Wire**							RE (-)		Recommended	
34 A/F						Mos	28-Jan-2010				
Eff: 17-Aug-2009 Complied With						Hrs	1,172.9				
						Ldg	723				
45-34-28	**Navigation - Installation of Runway Awareness and Advisory System (RAAS)**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-28 Rev 1	**Navigation - Installation of Runway Awareness and Advisory System (RAAS)**							RE (-)		Optional	
34 A/F						Mos	17-Mar-2011				
Eff: 28-Jul-2014 Complied With	INCORPORATED BY STC ST00195BO					Hrs					
						Ldg					
45-34-29	**Navigation - 802.7 Software Upgrade for the Flight Management System (FMS)**							RE (-)		Recommended	
34 A/F						Mos					
Eff: 16-Nov-2009						Hrs					
(AVG MAN HRS: 2.5)						Ldg					
45-34-29 Rev 1	**Navigation - 802.7 Software Upgrade for the Flight Management System (FMS)**							RE (-)		Recommended	
34 A/F						Mos					
Eff: 23-Nov-2009						Hrs					
(AVG MAN HRS: 2.5)						Ldg					
45-34-29 Rev 2	**Navigation - 802.7 Software Upgrade for the Flight Management System (FMS)**							RE (-)		Recommended	
34 A/F						Mos	23-Feb-2015				
Eff: 09-Dec-2013 Complied With	SB 45-34-29 R2 NAVIGATION - 802.7 SOFTWARE UPGRADE FOR THE FLIGHT MANAGMENT SYSTEM (FMS)					Hrs	3,387.2				
(AVG MAN HRS: 2.5)						Ldg	1,976				
45-34-3	**Navigation - Installation of Enhanced Ground Proximity Warning System Upgrade**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-3 Rev 1	**Navigation - Installation of Enhanced Ground Proximity Warning System Upgrade**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-3 Rev 2	**Navigation - Installation of Enhanced Ground Proximity Warning System Upgrade**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-3 Rev 3	**Navigation - Installation of Enhanced Ground Proximity Warning System Upgrade**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-3 Rev 4	**Navigation - Installation of Enhanced Ground Proximity Warning System Upgrade**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-3 Rev 5	**Navigation - Installation of Enhanced Ground Proximity Warning System Upgrade**							RE (-)		Optional	
34 A/F						Mos					
Eff: 13-Dec-2010						Hrs					
						Ldg					
45-34-3 Rev 6	**Navigation - Installation of Enhanced Ground Proximity Warning System Upgrade**							RE (-)		Optional	
34 A/F						Mos					
Eff: 07-Dec-2015						Hrs					
(AVG MAN HRS: 168)						Ldg					
45-34-30	**Navigation - Replacement Of The Global Positioning System (GPS) Antenna**							RE (-)		Optional	
34 A/F						Mos					
						Hrs					
						Ldg					
45-34-30 Rev 1	**Navigation - Replacement Of The Global Positioning System (GPS) Antenna**							RE (-)		Optional	
34 A/F						Mos					
Eff: 08-Nov-2010						Hrs					
						Ldg					
45-34-31	**Navigation - TCAS Interference Limiting Improvement**							RE (-)		Recommended	
34 A/F						Mos	01-Mar-2013				
Eff: 23-Jul-2012 Complied With						Hrs	2,753.9				
						Ldg	1,625				
45-34-31 Rev 1	**Navigation - TCAS Interference Limiting Improvement**							RE (-)		Recommended	
34 A/F						Mos	13-Jun-2014				
Eff: 13-Mar-2012 Complied With	NO REWORK REQUIRED IF PREVIOUS COMPLIED WITH					Hrs	3,195.4				
						Ldg	1,869				
45-34-32	**Navigation - TCAS 7.1 Software Upgrade**							T (-)		Optional	
34 A/F						Mos					
Eff: 29-Sep-2014						Hrs					
						Ldg					
45-34-32 Rev 1	**Navigation - TCAS 7.1 Software Upgrade**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 11-May-2015						Hrs					
(AVG MAN HRS: 5.5)						Ldg					
45-34-33	**Navigation - UNS-1E Auto-Tune Wiring Modification**							RE (-)		Optional	
34 A/F						Mos					
Eff: 07-Jan-2013						Hrs					
						Ldg					
45-34-34	**Navigation - UNS-1E Flight Management System (FMS) Upgrade**							RE (-)		Optional	
34 A/F						Mos					
Eff: 27-Jan-2014 Not Applicable	NOT THIS AIRCRAFT.					Hrs					
						Ldg					
45-34-35	**Navigation - Flight Management System (FMS) Upgrade To UNS-1Ew**							T (-)		Optional	
34 A/F						Mos					
Eff: 06-Mar-2014						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-35 Rev 1	**Navigation - Flight Management System (FMS) Upgrade To UNS-1Ew**							T (-)		Optional	
34 A/F						Mos					
Eff: 29-Feb-2016						Hrs					
(AVG MAN HRS: 80) (NOTE: Note : A/C not equipped with UNS-1Ew flight management system (FMS). Also Aircraft must be equipped with dual UNS-1C, UNS-1C+ or UNS-1E flight management systems in order for this modification to be installed.)						Ldg					
45-34-35 Rev 2	**Navigation - Flight Management System (FMS) Upgrade To UNS-1Ew**							T (-)		Optional	
34 A/F						Mos					
Eff: 15-Aug-2016						Hrs					
(AVG MAN HRS: 80) (NOTE: NOTE: Aircraft must be equipped with dual UNS-1C, UNS-1C+ or UNS-1E flight management systems in order for this modification to be installed. On aircraft 45-005 thru 45-243 configured with dual GPS antennas installed in line along the fuselage centerline that do not have XM radio, it is acceptable to use the existing in line location to install new GPS antennas if the aircraft is equipped with dual FMS systems.)						Ldg					
45-34-35 Rev 3	**Navigation - Flight Management System (FMS) Upgrade To UNS-1EW**							T (-)		Optional	
34 A/F						Mos					
Eff: 17-Oct-2016						Hrs					
(AVG MAN HRS: 80) (NOTE: NOTE: Aircraft must be equipped with dual UNS-1C, UNS-1C+ or UNS-1E flight management systems in order for this modification to be installed. On aircraft 45-005 thru 45-243 configured with dual GPS antennas installed in line along the fuselage centerline that do not have XM radio, it is acceptable to use the existing in line location to install new GPS antennas if the aircraft is equipped with dual FMS systems.)						Ldg					
45-34-35 Rev 4	**Navigation - Flight Management System (FMS) Upgrade to UNS-1EW**							RE (-)		Optional	
34 A/F						Mos	27-Sep-2023				
Eff: 24-Sep-2018 Complied With						Hrs	5,197.3				
(AVG MAN HRS: 80) (NOTE: NOTE: Aircraft must be equipped with dual UNS-1C, UNS-1C+ or UNS-1E flight management systems in order for this modification to be installed. On aircraft 45-005 thru 45-243 configured with dual GPS antennas installed in line along the fuselage centerline that do not have XM radio, it is acceptable to use the existing in line location to install new GPS antennas if the aircraft is equipped with dual FMS systems.)						Ldg	3,212				
45-34-36	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							RE (-)		Optional	
34 A/F						Mos					
Eff: 06-Mar-2014						Hrs					
(AVG MAN HRS: 141)						Ldg					
45-34-36 Rev 1	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							RE (-)		Optional	
34 A/F						Mos					
Eff: 13-Oct-2014						Hrs					
(AVG MAN HRS: 141)						Ldg					
45-34-36 Rev 10	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							RE (-)		Optional	
34 A/F						Mos					
Eff: 28-Apr-2021						Hrs					
(AVG MAN HRS: 141)						Ldg					
45-34-36 Rev 11	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							RE (-)		Optional	
34 A/F						Mos					
Eff: 01-Sep-2021						Hrs					
(AVG MAN HRS: 141)						Ldg					
45-34-36 Rev 12	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							RE (-)		Optional	
34 A/F						Mos					
Eff: 30-Jun-2023						Hrs					
(AVG MAN HRS: 141)						Ldg					
45-34-36 Rev 2	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							T (-)		Optional	
34 A/F						Mos					
Eff: 10-Nov-2014						Hrs					
(AVG MAN HRS: 141)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-36 Rev 3	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							T (-)		Optional	
34 A/F						Mos					
Eff: 16-Mar-2015						Hrs					
(AVG MAN HRS: 141)						Ldg					
45-34-36 Rev 4	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 21-Sep-2015						Hrs					
(AVG MAN HRS: 141)						Ldg					
45-34-36 Rev 5	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							T (-)		Optional	
34 A/F						Mos					
Eff: 25-Jan-2016						Hrs					
(AVG MAN HRS: 141) (NOTE: Control Effectivity)						Ldg					
45-34-36 Rev 6	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							T (-)		Optional	
34 A/F						Mos					
Eff: 02-May-2016						Hrs					
(AVG MAN HRS: 141) (NOTE: Controlled effectivity. NOTE: UNS-1Ew FMS units must have SCN 1000.5 software for ADS-B operation.)						Ldg					
45-34-36 Rev 7	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							RE (-)		Optional	
34 A/F						Mos					
Eff: 16-Jan-2017						Hrs					
(AVG MAN HRS: 141)						Ldg					
45-34-36 Rev 8	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							T (-)		Optional	
34 A/F						Mos					
Eff: 15-Jan-2018						Hrs					
(AVG MAN HRS: 141) (NOTE: CONTROLLED EFFECTIVITY						Ldg					
NOTE: UNS-1Ew FMS units must have SCN 1000.5 software for ADS-B operation.											
EFFECTIVITY: Refer to RIL 45-34-36.)											
45-34-36 Rev 9	**Navigation - Upgrade to Automatic Dependent Surveillance - Broadcast (ADS-B) Operation**							RE (-)		Optional	
34 A/F						Mos	30-Aug-2018				
Eff: 30-Apr-2018 Not Applicable	INCORPORATION OF STC ST04064CH					Hrs					
(AVG MAN HRS: 141) (NOTE: CONTROLLED EFFECTIVITY. NOTE: UNS-1Ew FMS units must have SCN 1000.5 software for ADS-B operation. EFFECTIVITY: Refer to RIL 45-34-36.)						Ldg					
45-34-37	**Navigation - Global Positioning System (GPS) - Antenna Relocation**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 06-Mar-2014 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-34-38	**Navigation - EGPWS Fail Annunciation With Single FMS**							RE (-)		Recommended	
34 A/F						Mos	14-Dec-2020				
Eff: 28-Jul-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 11.5)						Ldg	2,822				
45-34-39	**Navigation - Conductive Antenna Gasket Installation**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 26-Mar-2018						Hrs					
(AVG MAN HRS: 1.5)						Ldg					
45-34-4	**Navigation - Installation of Honeywell Integrated Navigation Units**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-4 Rev 1	**Navigation - Installation of Honeywell Integrated Navigation Units**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-4 Rev 2	**Navigation - Installation of Honeywell Integrated Navigation Units**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-4 Rev 3	**Navigation - Installation of Honeywell Integrated Navigation Units**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 14-Sep-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-34-40	**Navigation - Flight Management System (FMS) Dual UNS-1Ew Software Upgrade**							T (-)		Recommended	
34 A/F						Mos					
Eff: 28-Apr-2021						Hrs					
(AVG MAN HRS: 2) (NOTE: CONTROLLED EFFECTIVITY: Only the aircraft serial numbers that appear in the table of RIL 45-34-40 are authorized to incorporate the subject service bulletin. COMPLIANCE: Recommended - Bombardier Learjet Inc. recommends these instructions are completed in less than 900 flight hours or less than 36 months (whichever comes first) from the initial distribution date of this publication.)						Ldg					
45-34-40 Rev 1	**Navigation - Flight Management System (FMS) Dual UNS-1Ew Software Upgrade**							T (-)		Recommended	
34 A/F						Mos					
Eff: 28-Apr-2021						Hrs					
(AVG MAN HRS: 2) (NOTE: CONTROLLED EFFECTIVITY: Only the aircraft serial numbers that appear in the table of RIL 45-34-40 are authorized to incorporate the subject service bulletin. COMPLIANCE: Recommended - Bombardier Learjet Inc. recommends these instructions are completed in less than 900 flight hours or less than 36 months (whichever comes first) from the initial distribution date of this publication.)						Ldg					
45-34-40 Rev 2	**Navigation - Flight Management System (FMS) Dual UNS-1Ew Software Upgrade**							RE (-)		Recommended	
34 A/F						Mos					
Eff: 16-Aug-2021						Hrs					
(AVG MAN HRS: 2)						Ldg					
45-34-40 Rev 3	**Navigation - Flight Management System (FMS) Dual UNS-1Ew Software Upgrade**							RE (-)		Recommended	
34 A/F						Mos					
Eff: 01-Sep-2021						Hrs					
(AVG MAN HRS: 2)						Ldg					
45-34-40 Rev 4	**Navigation - Flight Management System (FMS) Dual UNS-1Ew Software Upgrade**							RE (-)		Recommended	
34 A/F						Mos	27-Sep-2023				
Eff: 21-Nov-2022 Complied With						Hrs	5,197.3				
(AVG MAN HRS: 2)						Ldg	3,212				
45-34-6	**Navigation - UNS-1C Navigational Computer Unit Flight Management Sytem (FMS) Performance Database Upgrade**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-6 Rev 1	**Navigation - UNS-1C Navigational Computer Unit Flight Management Sytem (FMS) Performance Database Upgrade**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-6 Rev 2	**Navigation - UNS-1C Navigational Computer Unit Flight Management Sytem (FMS) Performance Database Upgrade**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-34-6 Rev 3	**Navigation - UNS-1C Navigational Computer Unit Flight Management Sytem (FMS) Performance Database Upgrade**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 31-Mar-2005 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-34-8	**Navigation - Rework of Enhanced Ground Proximity Warning System Upgrade**							RE (-)		Recommended	
34 A/F						Mos	14-Dec-2020				
Eff: 17-May-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-34-9	**Navigation - Upgrade of the TCAS II Computer System Processor**							RE (-)		Optional	
34 A/F						Mos	13-Mar-2008				
Eff: 07-Nov-2003 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-34-9 Rev 1	**Navigation - Upgrade of the TCAS II Computer System Processor**							RE (-)		Optional	
34 A/F						Mos	29-Aug-2019				
Eff: 23-Feb-2015 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
86-05-02	**Altimeters**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Mar-2008				
Eff: 28-May-1986 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
98-14-03	**ALLIEDSIGNAL, INC. - KT 76A Transponders**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 16-Aug-1998 Not Applicable						Hrs	11.6				
						Ldg	11				
99-12-06	**AlliedSignal - VHF Navigation Receiver Mod**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 23-Jul-1999 Not Applicable						Hrs	11.6				
						Ldg	11				
99-23-22	**Mode C Transponder(s) with Single Gillham Code Altitude Input**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	13-Mar-2008				
Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
99-23-22 R1	**Mode C Transponder(s) with Single Gillham Code Altitude Input**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Not Applicable						Hrs	11.6				
						Ldg	11				
99-23-22 R2	**Mode C Transponder(s) with Single Gillham Code Altitude Input**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 20-Apr-2000 Not Applicable						Hrs	11.6				
(NOTE: RESCINDED)						Ldg	11				
99-23-24	**ALLIEDSIGNAL, INC. - RIA-32A Navigation Receivers**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	31-Mar-2008				
Eff: 06-Dec-1999 Not Applicable						Hrs	11.6				
						Ldg	11				
A3400000	**** Navigation Systems - Perform Operational Check.**							RE	TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
34 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:34-00-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 34-00-00.))						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
A3400000-4A	**** Air Data Computers - Perform Reversion Check.**							RE (N/A)	TLMC 04-10-00, Ch.5 Interval		
34 A/F						Mos					
						Hrs					
(ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg					
A3400000-4B	**** Attitude Heading Reference System (AHRS) - Perform Power Supply Check.**							RE (N/A)	TLMC 04-10-00, Ch.5 Interval		
34 A/F						Mos					
						Hrs					
(ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg					
A3400000-4C	**** Attitude Heading Reference System (AHRS) - Perform AHRS Reversion Check.**							RE (N/A)	TLMC 04-10-00, Ch.5 Interval		
34 A/F						Mos					
						Hrs					
(ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg					
A45-34-21	**Navigation - Functional Test of the Attitude Heading Reference System (AHRS) Computers**							RE (-)		Alert	
34 A/F						Mos	22-Oct-2008				
Eff: 25-Aug-2008 Complied With						Hrs	497				
(AVG MAN HRS: 12)						Ldg	352				
A45-34-21 Rev 1	**Navigation - Functional Test of the Attitude Heading Reference System (AHRS) Computers**							RE (-)		Alert	
34 A/F						Mos	22-Oct-2008				
Eff: 02-Sep-2008 Complied With						Hrs	497				
(AVG MAN HRS: 12)						Ldg	352				
A45-34-21 Rev 2	**Navigation - Functional Test of the Attitude Heading Reference System (AHRS) Computers**							RE (-)		Alert	
34 A/F						Mos	26-Jun-2009				
Eff: 22-Sep-2008 Complied With	NO REWORK FOR A/C THAT HAVE PREVIOUS C/W S/B					Hrs	820				
(AVG MAN HRS: 12)						Ldg	531				
A45-34-7	**Navigation - UNS Performance Database Restriction Placard**							RE (-)		Alert	
34 A/F						Mos	13-Mar-2008				
Eff: 07-Dec-2001 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 1)						Ldg					
A45-34-7 Rev 1	**Navigation - UNS Performance Database Restriction Placard**							RE (-)		Alert	
34 A/F						Mos	13-Mar-2008				
Eff: 14-Jun-2002 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 1)						Ldg					
A45-34-7 Rev 2	**Navigation - UNS Performance Database Restriction Placard**							RE (-)		Alert	
34 A/F						Mos	14-Dec-2020				
Eff: 09-Oct-2003 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 1)						Ldg	2,822				
AW 34-005	**Flux Valve Bracket**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-006	**Reduced Vertical Separation Minimum (Rvsm) Operations**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-006 R1	**Reduced Vertical Seperation Minimum Operations**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 34-007	**Egpws Computer Upgrade**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-008	**Uns Performance Database Software Upgrade**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-015	**#1 Glideslope Display, Check Coax Length And Bonding**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-018	**Reduced Verticle Separation Minimum (RVSM) For Learjet 45 Aircraft With 731-20BR Engines**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-019	**Integrated Comm Unit Update Affecting TCAS Functionality**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-020	**Flight Management System (FMS) Compliance With Faa Advisory Circular 90-100**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-022	**Possible Erroneous Glide Slope Indications**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-023	**Transponder Erroneously Going Into Standyby Mode**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-024	**Compliance With AD2006-22-05**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 34-025	**FAA Approval For Ac90-100A On Uns-1() With 600.X Through 801.X Software**							RE (-)		Advisory Wire	
34 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
CF-2021-52		**Navigation - Aeroplane - Prohibition of Operations Requiring Radio Altimeter in the Presence of 5G C-Band Wireless Broadband Interference**							RE (-)		Mandatory (Appliance AD)	
34 A/F		Eff: 03-Jan-2022 Complied With (AVG MAN HRS: 0.5) (UPDATE NOTE: Airworthiness Directive CF-2021-52 C/W iaw AFM Rev and Limitations.) (NOTE: Applicability: This AD applies to all transport and commuter category aeroplanes for which the design approval document holder is identified below: 1) Airbus SAS 2) Bombardier Inc. 3) Embraer S.A. 4) Gulfstream Aerospace LP 5) Pilatus Aircraft Limited 6) Fokker Services B.V. 7) Saab AB, Support and Services 8) De Havilland Aircraft of Canada Limited 9) Airbus Canada Limited Partnership 10) ATR-GIE Avions de Transport Régional 11) Yaborã Indústria Aeronáutica S.A. 12) MHI RJ Aviation ULC. 13) BAE Systems (Operations) Limited 14) Viking Air Limited 15) Dassault Aviation and equipped with a radio (also known as radar) altimeter.)					Mos Hrs Ldg	03-Mar-2022 4,883 3,012				
FAR 91.411		**Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43**							RE		FAR91, FAR 91	
34 A/F	7030700-71704 07101648	No.1 Inspected Date 09-Feb-2024					Mos Hrs Ldg	09-Feb-2024 5,253.5 3,757	24		09-Feb-2026	1.7 Years
FAR 91.411		**Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43**							RE		FAR91, FAR 91	
34 A/F	7030700-71704 07101649	No.2 Inspected Date 09-Feb-2024					Mos Hrs Ldg	09-Feb-2024 5,253.5 3,757	24		09-Feb-2026	1.7 Years
FAR 91.411		**Altimeter Standby Indicator tests and inspections per FAR 91.411**							RE		FAR91, FAR 91	
34 A/F	16650-1142 175579B	StandBy					Mos Hrs Ldg	09-Feb-2024 5,253.5 3,757	24		09-Feb-2026	1.7 Years
FAR 91.411		**Pitot/ Static Systems Leak check per FAR 91.411 Appendix E of Part 43**							RE		FAR91, FAR 91	
34 A/F	6634100000-001 310221	Left Inspected Date 09-Feb-2024					Mos Hrs Ldg	09-Feb-2024 5,253.5 3,757	24		09-Feb-2026	1.7 Years
FAR 91.411		**Pitot/ Static Systems Leak check per FAR 91.411 Appendix E of Part 43**							RE		FAR91, FAR 91	
34 A/F	0856TJ2 246559	Right Certified Date 09-Feb-2024					Mos Hrs Ldg	09-Feb-2024 5,253.5 3,757	24		09-Feb-2026	1.7 Years
FAR 91.411		**Pitot/ Static Systems Leak check per FAR 91.411 Appendix E of Part 43**							RE		FAR91, FAR 91	
34 A/F	0856TJ4 310221	StandBy Certified Date 09-Feb-2024					Mos Hrs Ldg	09-Feb-2024 5,253.5 3,757	24		09-Feb-2026	1.7 Years

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
L3411062	**Pitot-Static Probe - Perform Detailed Visual Inspection.**							RE		TLMC 05-19-02	
34 A/F						Mos	09-Feb-2024	24	-/+14d	09-Feb-2026	1.7 Years (+14 Days)
						Hrs	5,253.5				
(ZONE: 220) (SOURCE: MM-104, MM-105)						Ldg	3,757				
M3411052	**Primary Pitot-Static Probes - Verify pitch, roll, and yaw alignment.**							RE		TLMC 05-19-02	
34 A/F						Mos	09-Feb-2024	24	-/+14d	09-Feb-2026	1.7 Years (+14 Days)
						Hrs	5,253.5				
(ZONE: 100) (SOURCE: MM-104, MM-105)						Ldg	3,757				
ST04064CH	**Installation of Automatic Dependent Surveillance - Broadcast (ADS-B) Out System in Accordance with Flightstar Corp Master Data List Doc # 45-001-002 Rev J., Supplemental Type Certificate**							RE (-)		STC	
34 A/F						Mos	30-Aug-2018				
Complied With						Hrs					
						Ldg					
U3411060	**Air Data System - Perform Functional Test. (Effective on Aircraft certified and maintained for Reduced Vertical Separation Minimum Operations.)**							RE		TLMC 05-19-02, RVSM	
34 A/F						Mos	09-Feb-2024	24	-/+14d	09-Feb-2026	1.7 Years (+14 Days)
						Hrs	5,253.5				
Alias1:34-17-00 (ZONE: 200) (SOURCE: MM-104, MM-105)						Ldg	3,757				
V3420000	**Attitude Heading Reference Unit (AHRU) Mounting Tray Fan Filter - Perform visual inspection. Ensure filter is free of obstructions.**							RE (N/A)		TLMC 05-12-01	
34 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8				
Ref:5-10-00 (ZONE: 120AR, 130AL) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft 45-001 thru 45-174, not modified per SB 45-34-26, Navigation Unit - Replacement of the Attitude Heading Reference System (AHRS)).)						Ldg	2,807				
Y3411000	**Pitot-Static Probe - Perform visual inspection. Ensure drain holes are clear of obstructions.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
34 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:5-10-00, 34-11-01 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00 and 34-11-01.))						Ldg	3,757				
Y3440000	**Radome Structure and Antenna Installation - Perform Visual Inspection.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
34 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 110AC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	3,757				
▼ 35 - OXYGEN											
	Altitude Compensating Regulator							RE (O/C)			
35 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Crew Oxygen Mask							RE (O/C)			
35 A/F	Copilot					Mos	03-Mar-2022				
MC10-15-166	Overhauled		0		0	Hrs	4,883				
SE17882			0		0	Ldg	3,012				
	Crew Oxygen Mask							RE (O/C)			
35 A/F	Pilot					Mos	03-Mar-2022				
MC10-15-166	Overhauled		0		0	Hrs	4,883				
84005			0		0	Ldg	3,012				
(UPDATE NOTE: REPLACED WITH O/H MASK)											
	Crew Oxygen Outlet							RE (O/C)			
35 A/F	Copilot					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Crew Oxygen Outlet							RE (O/C)			
	35 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Crewmember Protective Breathing Equipment							RE (N/A)	Life Limit, Replacement Schedule, TLMC 05-19-01		
	35 A/F	Copilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
	Alias1:(Std)A3510008, (EMP)3510008 (ZONE: 200) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
		Crewmember Protective Breathing Equipment							RE (N/A)	Life Limit, Replacement Schedule, TLMC 05-19-01		
	35 A/F	Pilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
	Alias1:(Std)A3510008, (EMP)3510008 (ZONE: 200) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR)											
		Lavatory Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Lavatory Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Oxygen Bottle Shutoff Valve							RE (O/C)			
	35 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Oxygen Control Valve							RE (O/C)			
	35 A/F			0			Mos	11-Mar-2011				
	6635000000-025	Overhauled		0			Hrs	1,857.4				
	0194			0			Ldg	1,121				
		Oxygen Cylinder (composite)							RE		TLMC 05-19-01	
	35 A/F			0			Yrs	13-Sep-2022	15	-/+14d	01-Nov-2036	12.4 Years (+14 Days)
	806385-14	Overhauled										
	ALT280-8537			0			Hrs	5,073.3				
	Manufactured Date 01-Nov-2021			0			Ldg	3,121				
	Alias1:(Std)O3510007, (EMP)3510007 (ZONE: 120) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: Note: Time count for the oxygen bottle shall commence from the manufacture date on the bottle.)											
		Oxygen Cylinder Low Pressure Relief Valve							RE (O/C)			
	35 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Oxygen Cylinder Regulator							RE (O/C)			
	35 A/F			0			Mos	13-Sep-2022				
	806370-07	Overhauled		0			Hrs	5,073.3				
	C07060104			0			Ldg	3,121				
	(ZONE: 120AR , 130AL)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Oxygen Fill (Post Sb 45-12-1) Valve							RE (O/C)			
	35 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Oxygen Flex Hose							RE (O/C)			
	35 A/F	Copilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Oxygen Flex Hose							RE (O/C)			
	35 A/F	Pilot					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Oxygen Pressure Indicator							RE (O/C)			
	35 A/F		0				Mos	13-Mar-2008				
	P24071-3	New	0				Hrs	0				
	532		0				Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Left No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Left No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Left No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Left No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Left No.5					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Right No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Right No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Right No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Right No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Right No.5					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Passenger Oxygen Assembly Mask							RE (O/C)			
	35 A/F	Right No.6					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Portable oxygen cylinder							RE (O/C)			
	35 A/F						Mos	10-Jan-2020				
	5500-C1W-BF23A	New					Hrs	4,590.8				
	P20011615						Ldg	2,807				
		Remote Oxygen Pressure Indicator							RE (O/C)			
	35 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Temp/Pressure Transducer							RE (O/C)			
	35 A/F			0			Mos	26-Oct-2012				
	10008789-M	Overhauled		0			Hrs	2,671.3				
	7337-7-107			0			Ldg	1,577				
119003-35-009		**Oxygen - Crewmember Protective Breathing Equipment - 119003-11 PBE Replacement**							T (-)		Mandatory	
	35 A/F						Mos					
	Eff: 09-Nov-2015						Hrs					
							Ldg					
119003-35-009 Rev 1		**Oxygen - Crewmember Protective Breathing Equipment - 119003-11 PBE Replacement**							T (Due)		Mandatory	
	35 A/F						Mos					
	Eff: 28-Feb-2017						Hrs					
							Ldg					
2009-21-10 Rev.01		**AVOX Systems and B/E Aerospace Oxygen Cylinder Assemblies**							RE (-)		Mandatory (Appliance AD)	
	35 A/F						Mos	14-Dec-2020				
	Eff: 04-Feb-2010 Not Applicable						Hrs	4,610.5				
							Ldg	2,822				
2010-11-05		**AVOX Systems and B/E Aerospace - Type 2HT Oxygen Cylinders**							RE (-)		Mandatory (Appliance AD)	
	35 A/F						Mos	14-Dec-2020				
	Eff: 06-Jul-2010 Not Applicable						Hrs	4,610.5				
	Brand A:9990-2010-11-05 (AVG MAN HRS: 0.5) (APX COST: 42.5) (NOTE: Within 60 days after the effective date of this AD, inspect the oxygen cylinder installed in the airplane to determine the serial number and replace if needed)						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2011-01-09	**B/E Aerospace - Oxygen - PBE units having PN 119003-11- Inspection / Replacement**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	14-Dec-2020				
Eff: 09-Feb-2011 Not Applicable						Hrs	4,610.5				
Brand A:9990-2011-01-09 (AVG MAN HRS: 1) (APX COST: 85) (NOTE: (PBE) units having part number (P/N) 119003-11 and has a serial number from 003-50730M to 003-51329M inclusive)						Ldg	2,822				
2011-04-09	**Chemical oxygen generator deactivation (Superseded by FAA AD 2012-11-09)**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	22-Apr-2011				
Eff: 14-Mar-2011 Not Applicable	NOT INSTALLED IN AIRCRAFT					Hrs	1,922.2				
						Ldg	1,155				
2011-14-08	**B/E Aerospace, Continuous Flow Passenger Oxygen Mask Assembly**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	14-Dec-2020				
Eff: 19-Aug-2011 Not Applicable						Hrs	4,610.5				
Brand A:9990-2011-14-08 (AVG MAN HRS: 0.5) (APX COST: 48.5)						Ldg	2,822				
2011-14-08 Par. (g)	**B/E Aerospace, Continuous Flow Passenger Oxygen Mask Assembly - Record Check/Inspection**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	14-Dec-2020				
Eff: 19-Aug-2011 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2011-14-08 Par. (h)	**B/E Aerospace, Continuous Flow Passenger Oxygen Mask Assembly - Modification/Replacement**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	14-Dec-2020				
Eff: 19-Aug-2011 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2012-11-09 R1	**Chemical Oxygen Generator Installation**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	14-Dec-2020				
Eff: 27-Jul-2015 Not Applicable						Hrs	4,610.5				
Brand A:9990-2012-11-09R1						Ldg	2,822				
2012-11-09 R1 Para (g)	**Chemical Oxygen Generator Installation**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	14-Dec-2020				
Eff: 14-Mar-2011 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2012-11-09 R1 Para (l)	**Chemical Oxygen Generator Installation**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	14-Dec-2020				
Eff: 10-Aug-2012 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
2015-08-07	**Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	02-Jan-2015				
Eff: 16-Jun-2015 Complied With						Hrs	3,492				
						Ldg	2,031				
2015-08-07 Paragraph (g)	**Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators - Inspection**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	02-Jun-2015				
Not Applicable						Hrs	3,492				
(NOTE: [24 MOS Initial Req.])						Ldg	2,033				
2015-08-07 Paragraph (h)	**Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators - Replacement**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	02-Jun-2015				
Not Applicable						Hrs	3,492				
(NOTE: [24 MOS Initial Req.])						Ldg	2,033				
2015-23-09	**Oxygen - Zodiac Aerotechnics (Formerly Intertechnique Aircraft Systems) Flight Crew Oxygen Mask Regulators - Inspection / Replacement Of Oxygen Mask Regulators**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	30-Dec-2015				
Eff: 28-Dec-2015 Not Applicable	PER PART NUMBER AND SERIAL NUMBER INSTALLED					Hrs	3,621.8				
						Ldg	2,105				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2015-23-09 Para (g)	**Oxygen - Inspect Each Flightcrew Oxygen Mask Regulator To Identify The Part Number And Serial Number**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	30-Dec-2015				
Eff: 28-Dec-2015 Complied With	PER PART NUMBER AND SERIAL NUMBER INSTALLED					Hrs	3,621.8				
						Ldg	2,105				
2015-23-09 Para (h)(1)	**Replace Each Affected Flightcrew Oxygen Mask With A Part Identified In Paragraph (H)(1)(I) Or (H)(1)(Ii).**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	30-Dec-2015				
Not Applicable	PER PART NUMBER AND SERIAL NUMBER INSTALLED					Hrs	3,621.8				
						Ldg	2,105				
2015-23-09 Para (h)(2)(i)	**Revise The Emergency Procedures Section Of The Airplane Flight Manual (AFM) By Inserting The Statement Provided In Figure 1**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	30-Dec-2015				
Not Applicable	PER PART NUMBER AND SERIAL NUMBER INSTALLED					Hrs	3,621.8				
						Ldg	2,105				
2015-23-09 Para (h)(2)(ii)	**Fabricate And Install A Placard On The Flightcrew Oxygen Mask Container That States: "Use Selector On 100% Or Emergency Only."**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	30-Dec-2015				
Not Applicable	PER PART NUMBER AND SERIAL NUMBER INSTALLED					Hrs	3,621.8				
						Ldg	2,105				
2015-23-09 Para (i)	**Oxygen - Regulator Replacement**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	30-Dec-2015				
Eff: 28-Dec-2015 Not Applicable	PER PART NUMBER AND SERIAL NUMBER INSTALLED					Hrs	3,621.8				
						Ldg	2,105				
2016-11-20	**Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	29-Aug-2019				
Eff: 15-Jul-2016 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
2016-11-20 Paragraph (g)	**Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11 - Inspection**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	29-Aug-2019				
Eff: 15-Jul-2016 Not Applicable						Hrs	4,516.2				
Brand A:9990-2016-11-20(g) (NOTE: Applicability: This AD applies to B/E Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11, that is installed on airplanes)						Ldg	2,733				
2017-18-12	**Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units, P/N 119003-11 and 119003-21 - Inspect/ Replace (This AD replaces AD 2016-11-20)**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	12-Mar-2018				
Eff: 16-Oct-2017 Not Applicable	NO PBE INSTALLED IN AIRCRAFT					Hrs	4,155.2				
(AVG MAN HRS: 2)						Ldg	2,448				
2017-18-12 Par. (g)	**Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - Inspection Retained From AD 2016-11-20 for Airplanes With PBE, P/N 119003-11, Installed**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	12-Mar-2018				
Eff: 15-Oct-2017 Not Applicable	NO PBE INSTALLED IN AIRCRAFT					Hrs	4,155.2				
(AVG MAN HRS: 0.5) (NOTE: SCHEDULING/COMPLIANCE REVIEW NEEDED. This paragraph retains the requirements of AD 2016-11-20, which was due 3 months from July 15, 2016. Refer to B/E Aerospace Service Bulletin (SB) No. 119003-35-011, Rev. 000, dated February 4, 2015.)						Ldg	2,448				
2017-18-12 Par. (h)	**Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - Replacement Retained from AD 2016-11-20 for Airplanes with PBE, P/N 119003-11, Installed**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	12-Mar-2018				
Eff: 16-Oct-2017 Not Applicable	NO PBE INSTALLED IN AIRCRAFT					Hrs	4,155.2				
(AVG MAN HRS: 0.5) (NOTE: APPLICABILITY: If a PBE pouch is found that does not have an intact vacuum seal. NOTE: Refer to B/E Aerospace SB No. 119003-35-009, Rev. 001, dated April 12, 2016.)						Ldg	2,448				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2017-18-12 Par. (i)	**Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - New Inspection for Airplanes With PBE, P/N 119003-21, Installed**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	12-Mar-2018				
Eff: 16-Oct-2017 Not Applicable	NO PBE INSTALLED IN AIRCRAFT					Hrs	4,155.2				
						Ldg	2,448				
	(AVG MAN HRS: 0.5) (NOTE: NOTE: REfer to B/E Aerospace SB No. 119003-35-013, Rev. 002, dated July 19, 2017.)										
2017-18-12 Par. (j)	**Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - New Replacement for Airplanes With PBE, P/N 119003-21, Installed**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	12-Mar-2018				
Eff: 16-Oct-2017 Not Applicable	NO PBE INSTALLED IN AIRCRAFT					Hrs	4,155.2				
						Ldg	2,448				
	(AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to B/E Aerospace SB No. 119003-35-013, Rev. 002, dated July 19, 2017.)										
2018-21-14	**MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Inspection/ Replacement**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	01-Mar-2019				
Eff: 27-Mar-2019 Not Applicable	EQUIPMENT NOT INSTALLED ON AIRCRAFT					Hrs					
						Ldg					
2018-21-14 Par. (g)(1)	**MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Inspection**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	01-Mar-2019				
Eff: 27-Mar-2019 Not Applicable						Hrs	4,402.9				
	(NOTE: NOTE: Refer to Zodiac Aerospace Service Bulletin (SB) MC10-35-274, Revision 02, dated June 25, 2014.)					Ldg	2,608				
2018-21-14 Par.(h)	**MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Installation Prohibition**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	01-Mar-2019				
Eff: 27-Mar-2019 Not Applicable						Hrs	4,402.9				
	(NOTE: This AD applies to Zodiac Aerotechnics (Zodiac) MC10 series crew oxygen mask regulators fitted with an inflatable harness assembly, part number (P/N) MXH20-1 or MXH21-1.)					Ldg	2,608				
2022-04-09	**Valve Assembly Vent - AVOX Systems Inc. Oxygen Cylinder and Valve Assemblies**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Days	15-May-2022				
Eff: 04-Apr-2022 Not Applicable	NFF					Hrs	4,972.1				
						Ldg	3,061				
	(UPDATE NOTE: CYCLINDER AND VALVE P/N NOT APPLICABLE.) (NOTE: COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review. (1) AVOX Systems Inc. Alert Service Bulletin 10015804-35-01, Revision 02, dated October 16, 2019. (2) AVOX Systems Inc. Alert Service Bulletin 10015804-35-02, Revision 2, dated October 31, 2019. (3) AVOX Systems Inc. Alert Service Bulletin 10015804-35-03, Revision 02, dated October 15, 2019.)										
2023-13-11	**Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09)**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Days	27-Sep-2023				
Eff: 05-Sep-2023 Not Applicable	Equipment not installed.					Hrs	5,197.3				
						Ldg	3,212				
	(NOTE: APPLICABILITY: This AD applies to AVOX Systems Inc. (formerly Scott Aviation) oxygen cylinder and valve assemblies having part number (P/N) 89794077, 89794015, 891511-14, 806835-01, 807982-01, 808433-01, or 891311-14; and oxygen valve assemblies (body and gage assemblies) having P/N 807206–01. These assemblies might be installed on, but not limited to, the aircraft identified in paragraphs (c)(1) through (12) of this AD, certificated in any category. COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1 or Appendix 2, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review.)										
350001C	**Functional Test Oxygen Cylinder ** Low Pressure Relief Valve (IRN Q3510005 - Standard Capacity; Q3510018 - Increased Capacity)**							RE			
35 A/F						Mos	10-Jan-2020	60		10-Jan-2025	7.7 Months
Unknown						Hrs	4,590.8	5,000		9,590.8	4,316 Hrs
Unknown						Ldg	2,807				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-35-1	**Oxygen - Extended Duration of Oxygen System**							RE (-)		Optional	
35 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-35-1 Rev 1	**Oxygen - Extended Duration of Oxygen System**							RE (-)		Optional	
35 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-35-1 Rev 2	**Oxygen - Extended Duration of Oxygen System**							RE (-)		Optional	
35 A/F						Mos					
Eff: 22-Sep-2008						Hrs					
						Ldg					
45-35-1 Rev 3	**Oxygen - Extended Duration of Oxygen System**							RE (-)		Optional	
35 A/F						Mos	29-Aug-2019				
Eff: 04-Apr-2016 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 52)						Ldg	2,733				
45-35-1 Rev 4	**Oxygen - Extended Duration of Oxygen System**							RE (-)		Optional	
35 A/F						Mos					
Eff: 14-Nov-2022						Hrs					
(AVG MAN HRS: 52)						Ldg					
45-35-2	**Oxygen - Modification of the Oxygen System at FS 271.88 to Prevent Chafing**							RE (-)		Recommended	
35 A/F						Mos	14-Dec-2020				
Eff: 08-Dec-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-35-3	**Oxygen - Remote Oxygen Switch Replacement**							RE (-)		Optional	
35 A/F						Mos					
						Hrs					
						Ldg					
45-35-3 Rev 1	**Oxygen - Remote Oxygen Switch Replacement**							RE (-)		Optional	
35 A/F						Mos	29-Aug-2019				
Eff: 26-Sep-2011 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-35-4	**Oxygen - Inspection/Replacement of the Oxygen Cylinder Regulator**							RE (-)		Recommended	
35 A/F						Mos	14-Dec-2020				
Eff: 29-Nov-2010 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 4)						Ldg	2,822				
45-35-5	**Oxygen - Remote Oxygen Servicing Line**							RE (-)		Optional	
35 A/F						Mos					
Eff: 19-Jan-2015						Hrs					
(AVG MAN HRS: 3)						Ldg					
45-35-5 Rev 1	**Oxygen - Remote Oxygen Servicing Line**							RE (-)		Optional	
35 A/F						Mos	29-Aug-2019				
Eff: 21-Sep-2015 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 3)						Ldg	2,733				
99-08-21	**Puritan-Bennett Aero Systems Company C351-2000 Series Passenger Oxygen Masks and Portable Oxygen Masks - Passenger Oxygen Masks**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	31-Mar-2008				
Eff: 02-Jun-1999 Not Applicable						Hrs	11.6				
Brand A:9990-1999-08-21						Ldg	11				
A45-35-6	**Oxygen - Protective Breathing Equipment Inspection**							T (-)		Alert	
35 A/F						Mos					
Eff: 14-Mar-2016						Hrs					
(NOTE: Note: Effectivity applies to aircrafts with PBE 119003-11 installed.)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
A45-35-6 Rev 1	**Oxygen - Protective Breathing Equipment Inspection**							RE (-)		Alert	
35 A/F						Mos					
Eff: 17-Oct-2016						Hrs					
						Ldg					
A45-35-6 Rev 1a	**Oxygen - Protective Breathing Equipment Inspection - P/N 119003-21**							T (-)		Alert	
35 A/F						Mos					
Eff: 17-Oct-2016						Hrs					
						Ldg					
A45-35-6 Rev 1b	**Oxygen - Protective Breathing Equipment Inspection - P/N 119003-11**							T (-)		Alert	
35 A/F						Mos					
Eff: 17-Oct-2016						Hrs					
						Ldg					
A45-35-6 Rev 2	**Oxygen - Protective Breathing Equipment Inspection**							RE (-)		Alert	
35 A/F						Mos	14-Dec-2020				
Eff: 23-Jan-2017 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
A45-35-6 Rev 2a	**Oxygen - Protective Breathing Equipment Inspection - P/N 119003-21**							T (A/R)		Alert	
35 A/F						Mos					
Eff: 23-Jan-2017						Hrs					
						Ldg					
A45-35-6 Rev 2b	**Oxygen - Protective Breathing Equipment Inspection - P/N 119003-11**							RE (-)		Alert	
35 A/F						Mos					
Eff: 23-Jan-2017						Hrs					
						Ldg					
K3500021	**** Oxygen System Low Pressure Supply Hoses - Perform Operational Check. Ensure that hoses are free of obstructions.**							RE (N/A)	TLMC 04-10-00, TLMC 05-19-00		
35 A/F						Mos					
						Hrs					
Alias1:35-00-00 (ZONE: 200) (SOURCE: MM-104) (NOTE: (Refer to 35-00-00.))						Ldg					
L3510016	**B/E Aerospace (Puritan-Bennett) Crew Oxygen Masks - Comply with Factory Overhaul.**							RE (N/A)		TLMC 05-19-00	
35 A/F	Copilot					Mos	03-Mar-2022				
MC10-15-166					0	Hrs	4,883				
SE17882					0	Ldg	3,012				
(ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: Note: On masks with more than six years in service, comply with factory overhaul at next 300 Hour Phase A inspection.)											
L3510016	**B/E Aerospace (Puritan-Bennett) Crew Oxygen Masks - Comply with Factory Overhaul.**							RE (N/A)		TLMC 05-19-00	
35 A/F	Pilot					Mos	03-Mar-2022				
MC10-15-166					0	Hrs	4,883				
84005					0	Ldg	3,012				
(ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: Note: On masks with more than six years in service, comply with factory overhaul at next 300 Hour Phase A inspection.)											
N3510013	**** Oxygen Cylinder and Remote Oxygen Fill Valves - Perform Periodic Check.**							RE	TLMC 04-10-00, TLMC 05-19-00		**≈25-Nov-2024**
35 A/F						Mos	21-May-2019				
						Hrs	4,461.2	1,500	-/+25	5,961.2	686.4 Hrs (+25)
Ref:35-00-01 (ZONE: 120) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 35-00- 01.) (Effective on Aircraft 45-005 thru 45-244 modified per SB 45-12-1 and Aircraft 45-245 and Subsequent.))						Ldg	2,673				
N3510019	**** Oxygen Cylinder and Remote Oxygen Fill Valves - Perform periodic check.**							RE (N/A)	TLMC 04-10-00, TLMC 05-19-00		
35 A/F						Mos	30-Jul-2010				
						Hrs	1,499.8				
(ZONE: 230) (SOURCE: MM-104, MM-105) (NOTE: (Effective on aircraft equipped with increased capacity oxygen system.))						Ldg	910				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
O3510003	**** Cabin Low Pressure Oxygen Distribution Flex Hoses - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
35 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:35-20-00 (ZONE: 220, 230) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 35-20-00.))					Ldg	3,757				
O3510006	**E.R.O.S. Crew Oxygen Masks - Comply with Factory Overhaul.**							RE		TLMC 05-19-00	
35 A/F	Copilot					Yrs	03-Mar-2022	6	-/+14d	15-Dec-2027	3.6 Years (+14 Days)
MC10-15-166					0	Hrs	4,883				
SE17882					0	Ldg	3,012				
	Overhaul Date 15-Dec-2021										
	(ZONE: 220) (SOURCE: MM-104, MM-105)										
O3510006	**E.R.O.S. Crew Oxygen Masks - Comply with Factory Overhaul.**							RE		TLMC 05-19-00	
35 A/F	Pilot					Yrs	03-Mar-2022	6	-/+14d	08-Dec-2027	3.5 Years (+14 Days)
MC10-15-166					0	Hrs	4,883				
84005					0	Ldg	3,012				
	Overhaul Date 08-Dec-2021										
	(ZONE: 220) (SOURCE: MM-104, MM-105)										
Q3500024	**Perform ICC Hydrostatic Test on portable oxygen cylinder (Steel, DOT3AA1800) (If installed).**							RE		TLMC 05-19-00	
35 A/F						Yrs	10-Jan-2020	5	-/+14d	01-Jan-2025	7.4 Months (+14 Days)
5500-C1W-BF23A											
P20011615						Hrs	4,590.8				
	Hydrostatic Tested Date 01-Jan-2020					Ldg	2,807				
	(ZONE: 200) (SOURCE: MM-104, MM-105) (NOTE: Note: Initial time count for testing of this item shall commence from the manufacturing date stamped on the item.)										
Q3510005	****Oxygen Cylinder (composite) and Low Pressure Relief Valve - Perform ICC Hydrostatic Test on cylinder (per DOT Exemption E8162) and functionally test oxygen cylinder low pressure relief valve.**							RE	TLMC 04-10-00, TLMC 05-19-00, Ch.5 Interval		
35 A/F					0	Yrs	13-Sep-2022	5	-/+14d	13-Sep-2027	3.3 Years (+14 Days)
806385-14					0	Hrs	5,073.3	5,000	-/+25	10,073.3	4,798.5 Hrs (+25)
ALT280-8537					0	Ldg	3,121				
	Hydrostatic Tested Date 13-Sep-2022										
	(ZONE: 120) (UPDATE NOTE: Oxygen cylinder replaced with overhauled unit. See work package for details.) (SOURCE: MM-104, MM-105)										
Q3510018	**** Oxygen Cylinder (composite) and Low Pressure Relief Valve - Perform ICC hydrostatic test on cylinder (per DOT Exemption E8162) and functionally test oxygen cylinder low pressure relief valve.**							RE (N/A)	TLMC 04-10-00, TLMC 05-19-00		
35 A/F					0	Yrs	13-Sep-2022				
806385-14					0	Hrs	5,073.3				
ALT280-8537					0	Ldg	3,121				
	13-Sep-2022										
	(ZONE: 230) (SOURCE: MM-104, MM-105)										
Q3510022	**Oxygen Cylinder Regulator - Perform Overhaul.**							RE		TLMC 05-19-00	
35 A/F					0	Yrs	13-Sep-2022	5	-/+14d	01-Nov-2026	2.4 Years (+14 Days)
806370-07					0	Hrs	5,073.3	5,000	-/+25	10,073.3	4,798.5 Hrs (+25)
C07060104					0	Ldg	3,121				
	Overhaul Date 01-Nov-2021										
	(ZONE: 120AR , 130AL) (UPDATE NOTE: Oxygen cylinder regulator replaced with overhauled unit. See work package for details.) (SOURCE: MM-104, MM-105)										
Q3510023	**Oxygen Cylinder Regulator - Perform Overhaul.**							RE (N/A)		TLMC 05-19-00	
35 A/F					0	Mos	13-Sep-2022				
806370-07					0	Hrs	5,073.3				
C07060104					0	Ldg	3,121				
	(ZONE: 230) (UPDATE NOTE: Oxygen cylinder regulator replaced with overhauled unit. See work package for details.) (SOURCE: MM-104, MM-105)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
S3510014		**** Oxygen System Altitude Compensating Regulator - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
35 A/F		05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
							Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
		Ref:35-20-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 35-20- 00.) (Effective on Aircraft 45-170 and Subsequent and prior Aircraft modified by SB45-35-1 extended duration oxygen system installed))					Ldg	3,757				
W3510002		**** Oxygen System - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
35 A/F		05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
							Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
		Alias1:35-00-00 (ZONE: 230) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 35-00-00.))					Ldg	3,757				
Y3510000		**Oxygen Cylinder Installation - Perform visual inspection. Check plumbing for routing, security, and condition.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
35 A/F		05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
							Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
		Alias1:5-10-00 (ZONE: 120AR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y3510001		**Crew Seat Oxygen Hoses - Perform visual inspection. Pay particular attention to area where oxygen hoses enter crew seats above cockpit floor.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
35 A/F		05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
		Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
							Ldg	3,757				
Y3510017		**Oxygen Cylinder Installation - Perform Visual Inspection. Check Plumbing for routing, security, and condition.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
35 A/F		05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
							Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
		Alias1:5-10-00 (ZONE: 200) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft equipped with Increased Capacity Oxygen System))					Ldg	3,757				
▼ 36 - PNEUMATIC												
		APU Servo Air Check Valve							RE (O/C)		TLMC 05-19-01	
36 A/F			0				Mos	12-Feb-2010				
6608295-3		New	0				Hrs	1,203.8				
3250			0				Ldg	739				
		Alias1:(Std)K3610013, (EMP)3610013 (ZONE: 310HL, 310JL, 310QR, 310RR) (SOURCE: MM-104, Learjet eINSPECTOR) (NOTE: (Effective on check valve S/N 0001 thru 1486.))										
		Assembly, HP Nacelle Bleed Air Manifold							RE (O/C)			
36 A/F		Left	0				Mos	13-Mar-2008				
LJ01212-001		New	0				Hrs	0				
081107-003			0				Ldg	0				
		Assembly, HP Nacelle Bleed Air Manifold							RE (O/C)			
36 A/F		Right	0				Mos	13-Mar-2008				
LJ01212-002		New	0				Hrs	0				
111107-005			0				Ldg	0				
		Bleed Air (HP) Pressure Switch							RE (O/C)			
36 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Bleed Air (HP) Pressure Switch							RE (O/C)			
36 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Ecs Controller							RE (O/C)			
	36 A/F						Mos	03-Jun-2013				
	1151830-3						Hrs	2,863.3				
	1151830-00838						Ldg	1,680				
		ECS Shutoff (L37) Valve							RE (O/C)			
	36 A/F		0				Mos	13-Mar-2008				
	3215468-1	New	0				Hrs	0				
	1045		0				Ldg	0				
		ECS Shutoff (L38) Valve							RE (O/C)			
	36 A/F		0				Mos	13-Mar-2008				
	3215468-1	New	0				Hrs	0				
	1056		0				Ldg	0				
		Ecs Shutoff Valve							RE (O/C)			
	36 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Ecs Shutoff Valve							RE (O/C)			
	36 A/F	No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Engine Servo Air Check Valve							RE (O/C)		TLMC 05-19-01	
	36 A/F	Left	8				Mos	17-Apr-2012				
	6C1005						Hrs	2,413.2				
	3859						Ldg	1,441				
	Alias1:(Std)K3610012, (EMP)3610012 (ZONE: 310HL, 310JL, 310QR, 310RR) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Effective on check valve S/N 0001 thru 1486.))											
		Engine Servo Air Check Valve							RE (O/C)		TLMC 05-19-01	
	36 A/F	Right	8				Mos	17-Apr-2012				
	6C1005						Hrs	2,413.2				
	3857						Ldg	1,441				
	Alias1:(Std)K3610012, (EMP)3610012 (ZONE: 310HL, 310JL, 310QR, 310RR) (SOURCE: MM-104, MM-105, Learjet eINSPECTOR) (NOTE: (Effective on check valve S/N 0001 thru 1486.))											
		HP Bleed Air Tube Assembly							RE (O/C)			
	36 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		HP Bleed Air Tube Assembly							RE (O/C)			
	36 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		HP Over-Temp Switch							RE (O/C)			
	36 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		HP Over-Temp Switch							RE (O/C)			
	36 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Inboard HPBA Manifold Assembly							RE (O/C)			
	36 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Inboard HPBA Manifold Assembly							RE (O/C)			
	36 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Assembly, Anti-Ice Outboard Manifold							RE (O/C)			
	36 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Left Assembly, HP Tailcone Outboard Manifold							RE (O/C)			
	36 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Load Control (Shutoff (L5003) Valve							RE (O/C)			
	36 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Manifold Assembly, Center							RE (O/C)			
	36 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Pressure (S79) Switch							RE (O/C)			
	36 A/F		0				Mos	23-Nov-2011				
	6621000000-091	New	0				Hrs	2,232.2				
	0959		0				Ldg	1,338				
		Pressure (S88) Switch							RE (O/C)			
	36 A/F		0				Mos	13-Mar-2008				
	642019-5	New	0				Hrs	0				
	0256		0				Ldg	0				
		Pylon Low Pressure Temperature Sensor							RE (O/C)			
	36 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Pylon Low Pressure Temperature Sensor							RE (O/C)			
	36 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Pylon Overheat Thermostat (S145) Switch							RE (O/C)			
36 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Pylon Overheat Thermostat (S146) Switch							RE (O/C)			
36 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Pylon Overheat Thermostat (S147) Switch							RE (O/C)			
36 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Pylon Overheat Thermostat (S148) Switch							RE (O/C)			
36 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Right Assembly, Anti-Ice Outboard Manifold							RE (O/C)			
36 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Right Assembly, Hp Tailcone Outboard Manifold							RE (O/C)			
36 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Tailcone High Pressure Shut-Off (L39) Valve							RE (O/C)			
36 A/F	Left				0	Mos	09-Dec-2010				
3291216-3	Repaired				0	Hrs	1,690.7				
1046C					0	Ldg	1,027				
	Tailcone High Pressure Shut-Off (L40) Valve							RE (O/C)			
36 A/F	Right		0			Mos	13-Mar-2008				
3291216-2	New		0			Hrs	0				
133C			0			Ldg	0				
	Tailcone Low Pressure (2.0 Diameter) Check Valve							RE (O/C)			
36 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Tailcone Low Pressure (2.0 Diameter) Check Valve							RE (O/C)			
36 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Valve, APU Bleed Air Check							RE (O/C)			
36 A/F			0			Mos	13-Mar-2008				
4011-14	New		0			Hrs	0				
0269			0			Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2023-01-05	**Pneumatic - Metal Fragments Breaking Off the Anti-ice Manifold Assembly**							RE (-)		Mandatory	
36 A/F						Mos	02-Jun-2023				
Eff: 09-Mar-2023 Complied With						Hrs	5,166.1				
						Ldg	3,185				
2023-01-05 Par. (g)(1)(2)	**Pneumatic - Metal Fragments Breaking Off the Anti-ice Manifold Assembly - Revise Existing Inspection Program**							RE (-)		Mandatory	
36 A/F						Days	02-Jun-2023				
Eff: 09-Mar-2023 Complied With						Hrs	5,166.1				
						Ldg	3,185				
2023-01-05 Par. (g)(1)(i)(ii), (2)(i)(ii)	**Pneumatic - Metal Fragments Breaking Off the Anti-ice Manifold Assembly - Inspection**							RE (-)		Mandatory	
36 A/F						Days	02-Jun-2023				
Eff: 09-Mar-2023 Complied With						Hrs	5,166.1				
						Ldg	3,185				
45-36-2	**Pneumatic - Replacement of High Pressure Bleed Air Manifold Assembly**							RE (-)		Optional	
36 A/F						Mos	14-Dec-2010				
Complied With						Hrs	1,704.2				
						Ldg	1,036				
45-36-2 Rev 1	**Pneumatic - Replacement of High Pressure Bleed Air Manifold Assembly**							RE (-)		Optional	
36 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-36-2 Rev 2	**Pneumatic - Replacement of High Pressure Bleed Air Manifold Assembly**							RE (-)		Optional	
36 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-36-2 Rev 3	**Pneumatic - Replacement of High Pressure Bleed Air Manifold Assembly**							RE (-)		Optional	
36 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-36-2 Rev 4	**Pneumatic - Replacement of High Pressure Bleed Air Manifold Assembly**							RE (-)		Optional	
36 A/F						Mos	14-Dec-2010				
Eff: 31-Mar-2005 Complied With						Hrs					
						Ldg					
45-36-3	**Pneumatic - Replacement of High Pressure Bleed Air Center Manifold Assembly**							RE (-)		Recommended	
36 A/F						Mos	14-Dec-2020				
Eff: 16-Mar-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-36-4	**Pneumatic - Replacement of the Environmental Control System (ECS) Controller**							RE (-)		Recommended	
36 A/F						Mos	14-Dec-2020				
Eff: 17-Jan-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-36-5	**Pneumatic - Replacement of the Pylon High Pressure Bleed Air Manifold Switch**							RE (-)		Recommended	
36 A/F						Mos	14-Dec-2020				
Eff: 16-Jul-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-36-6	**Pneumatic - Installation Of In-Line Filter To The High Pressure Bleed Air Shutoff Valve Assembly**							T (A/R)		Optional	
36 A/F						Mos					
Eff: 12-Apr-2010						Hrs					
						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-36-7	**Pneumatic - High Pressure Pylon Duct Replacement**							T (-)		Optional	
36 A/F						Mos					
Eff: 02-Dec-2013						Hrs					
						Ldg					
45-36-7 Rev 1	**Pneumatic - High Pressure Pylon Duct Replacement**							T (A/R)		Optional	
36 A/F						Mos					
Eff: 06-Jun-2022						Hrs					
(AVG MAN HRS: 27)						Ldg					
45-36-8	**Pneumatic - Replacement Of The Pylon Heat Blankets**							RE (-)		Optional	
36 A/F						Mos					
Eff: 19-Nov-2012						Hrs					
(AVG MAN HRS: 6.5)						Ldg					
45-36-8 Rev 1	**Pneumatic - Replacement Of The Pylon Heat Blankets**							RE (-)		Optional	
36 A/F						Mos					
Eff: 07-Jan-2013						Hrs					
(AVG MAN HRS: 6.5)						Ldg					
45-36-8 Rev 2	**Pneumatic - Replacement Of The Pylon Heat Blankets**							RE (-)		Optional	
36 A/F						Mos					
Eff: 22-Jul-2013						Hrs					
(AVG MAN HRS: 6.5)						Ldg					
45-36-8 Rev 3	**Pneumatic - Replacement Of The Pylon Heat Blankets**							RE (-)		Optional	
36 A/F						Mos					
Eff: 07-Oct-2103						Hrs					
(AVG MAN HRS: 6.5)						Ldg					
45-36-8 Rev 4	**Pneumatic - Replacement Of The Pylon Heat Blankets**							RE (-)		Optional	
36 A/F						Mos					
Eff: 21-Jul-2014						Hrs					
(AVG MAN HRS: 6.5)						Ldg					
45-36-8 Rev 5	**Pneumatic - Replacement Of The Pylon Heat Blankets**							T (A/R)		Optional	
36 A/F						Mos					
Eff: 03-Nov-2014						Hrs					
(AVG MAN HRS: 6.5)						Ldg					
45-36-9	**Pneumatic - Removal of the Nacelle Anti-Ice Valve Heat Blankets**							RE (-)		Recommended	
36 A/F						Mos	14-Dec-2020				
Eff: 21-Jul-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 0.5)						Ldg	2,822				
A3610000	**** Bleed Air System - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-12-01, Ch.5 Interval		**≈24-Oct-2024**
36 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:36-10-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 36-10-00.))						Ldg	3,757				
A3610001	**** Pylon Overheat Thermostat and Electrical System - Perform Functional Test.**							RE	TLMC 04-10-00, TLMC 05-12-02, Ch.5 Interval		**≈24-Oct-2024**
36 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:36-20-01 (ZONE: 340) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 36- 20-01.))						Ldg	3,757				
D3610002	**HP Bleed Air Manifold Assembly - Perform Boroscope inspection of attach bracket assembly for cracks at weld.**							RE (N/A)		TLMC 05-19-00	
36 A/F						Mos					
						Hrs					
Alias1:36-10-07 (ZONE: 410/420) (SOURCE: MM-104) (NOTE: (Refer to 36-10-07.) Note: If a crack indication is detected, confirm the indication with fluorescent penetrant inspection.)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P3610048	**(Left) HP Bleed Manifold Assembly - Perform Visual Inspection.**							RE		TLMC 05-19-00	**≈06-Apr-2026**
36 A/F						Mos	09-Jan-2020				
						Hrs	4,590.8	3,000	+100	7,590.8	2,316 Hrs (+100)
	Ref:5-10-00 (ZONE: 410/420) (SOURCE: MM-104, MM-105) (NOTE: During Engine Major Periodic Inspection.)					Ldg					
P3610048	**(Right) HP Bleed Manifold Assembly - Perform Visual Inspection.**							RE		TLMC 05-19-00	**≈06-Apr-2026**
36 A/F						Mos	09-Jan-2020				
						Hrs	4,590.8	3,000	+100	7,590.8	2,316 Hrs (+100)
	Ref:5-10-00 (ZONE: 410/420) (SOURCE: MM-104, MM-105) (NOTE: During Engine Major Periodic Inspection.)					Ldg					
U3610075	**ECS Bleed Air "Y" Manifold (P/N 12945-054-019, 12945-054-025, 12945-054-031, 12945-054- 037,12945-054V1-001, 12945-054V2-001, 12945-054V6-001) - Perform Boroscope Inspection.**							RE		TLMC 05-15-00	**≈14-Oct-2027**
36 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	(9,410.5)	4,135.7 Hrs (+25)
	(ZONE: 300) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 36-10-00)					Ldg	2,822				
	Note: On Aircraft with more than 4,800 Hours from C of A, perform inspection at next scheduled B Phase Inspection.)										
Y3610061	**High Pressure Bleed Air Shut-off Valve In-Line Filter - Perform Cleaning Procedures**							RE		TLMC 05-12-02	**≈24-Oct-2024**
36 A/F	Left05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
3291216-3						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
1046C						Ldg	3,757				
	Alias1:36-10-02 (ZONE: 300) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)										
Y3610061	**High Pressure Bleed Air Shut-off Valve In-Line Filter - Perform Cleaning Procedures**							RE			**≈24-Oct-2024**
36 A/F	Right05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
3291216-2						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
133C						Ldg	3,757				
	Ref:36-10-02 (Tol. Adjustment: -58d) (SOURCE: MM-104, MM-105) (NOTE: NOTE: The filter can either be cleaned or replaced at this time.)										
▼ 37 - VACUUM											
2005-11-05	**Standby vacuum systems (SVS)**							RE (-)		Mandatory (Appliance AD)	
37 A/F						Mos	13-Mar-2008				
Eff: 18-Jul-2005 Complied With	AT MANUFACTURE					Hrs	8.7				
						Ldg	8				
▼ 38 - WATER/WASTE											
	Assembly Toilet							RE (O/C)			
38 A/F		0				Mos	13-Mar-2008				
9600-1B	New	0				Hrs	0				
U3689		0				Ldg	0				
	Box Assembly, Timer-Toilet							RE (O/C)			
38 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Drain Mast							RE (O/C)			
38 A/F	Aft					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Lavatory Sink Shut Off Valve							RE (O/C)			
38 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Tank Float Switch, Toilet							RE (O/C)			
	38 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Toilet Clean Water Pump							RE (O/C)			
	38 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Toilet Heated Drain Mast Assy							RE (O/C)			
	38 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Toilet Macerator							RE (O/C)			
	38 A/F		8				Mos	17-Jun-2018				
	5300-1		336.5				Hrs	4,312.4				
	M5448		187				Ldg	2,535				
		Toilet Pump							RE (O/C)			
	38 A/F		0				Mos	10-Jan-2020				
	5250-11A	New	0				Hrs	4,590.8				
	P10694		0				Ldg	2,807				
		Toilet Service Panel							RE (O/C)			
	38 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Toilet Timer							RE (O/C)			
	38 A/F		0				Mos	13-Mar-2008				
	9600-12D	New	0				Hrs	0				
	T4494		0				Ldg	0				
		Water Tank Assembly							RE (O/C)			
	38 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
45-38-2		**Water/Waste - Replacement of the Toilet Servicing Hoses**							RE (-)		Recommended	
	38 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-38-2 Rev 1		**Water/Waste - Replacement of the Toilet Servicing Hoses**							RE (-)		Recommended	
	38 A/F						Mos	14-Dec-2020				
	Eff: 20-Aug-2007 Not Applicable						Hrs	4,610.5				
							Ldg	2,822				
45-38-3		**Water/Waste - Toilet Service Line Improvement**							RE (-)		Optional	
	38 A/F						Mos	29-Aug-2019				
	Eff: 24-Sep-2012 Not Applicable						Hrs	4,516.2				
							Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
A45-38-1	**Water/Waste - Modification of the Toilet Servicing Hoses**							RE (-)		Alert	
38 A/F						Mos	13-Mar-2008				
Eff: 10-Feb-2006 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 4.5)						Ldg					
A45-38-1 Rev 1	**Water/Waste - Modification of the Toilet Servicing Hoses**							RE (-)		Alert	
38 A/F						Mos	14-Dec-2020				
Eff: 24-Apr-2006 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 4.5)						Ldg	2,822				
AW 38-003	**Toilet Servicing Deactivation**							RE (-)		Advisory Wire	
38 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 38-004	**Toilet Servicing Deactivation Update**							RE (-)		Advisory Wire	
38 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 38-005	**Learjet 40 & 45 Toilet Serviceing Hoses**							RE (-)		Advisory Wire	
38 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 38-006	**Learjet 40 & 45 Galley Hot Liquid Warmer**							RE (-)		Advisory Wire	
38 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
▼ 44 - CABIN SYSTEMS											
75-44-01	**Cabin Systems - Cabin Management System Software Upgrade**							RE (-)		Optional	
44 A/F						Mos					
Eff: 08-Jul-2019						Hrs					
						Ldg					
75-44-01 Rev 1	**Cabin Systems - Cabin Management System Software Upgrade**							RE (-)		Optional	
44 A/F						Mos					
Eff: 12-Jul-2019						Hrs					
(AVG MAN HRS: 1.5)						Ldg					
75-44-01 Rev 2	**Cabin Systems - Cabin Management System Software Upgrade**							RE (-)		Optional	
44 A/F						Mos					
Eff: 19-Dec-2019						Hrs					
(AVG MAN HRS: 1.5)						Ldg					
75-44-01 Rev 3	**Cabin Systems - Cabin Management System Software Upgrade**							RE (-)		Optional	
44 A/F						Mos					
Eff: 24-May-2021						Hrs					
(AVG MAN HRS: 1.5)						Ldg					
75-44-01 Rev 4	**Cabin Systems - Cabin Management System Software Upgrade**							RE (-)		Optional	
44 A/F						Mos					
Eff: 23-Aug-2021						Hrs					
(AVG MAN HRS: 3)						Ldg					
75-44-01 Rev 5	**Cabin Systems - Cabin Management System Software Upgrade**							RE (-)		Optional	
44 A/F						Mos					
Eff: 31-Jan-2022						Hrs					
(AVG MAN HRS: 3)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 45 - DIAGNOSTIC AND MAINTENANCE SYSTEM											
AW 45-013	**Apu Fuel Supply Shut-Off Valve**							RE (-)		Advisory Wire	
45 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
▼ 49 - AIRBORNE AUXILIARY POWER											
	(Low Voltage) Igniter Plug							RE (O/C)			
49 APU1						Mos	12-Dec-2023				
304634-2	New	0				Hrs	2,101.7				
NSN		0				APUS	4,026				
	(Low Voltage) Ignition Unit							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	APU - Engine Fuel Filter							RE (H/T)			
49 APU1						Mos	12-Dec-2023				
3882440-1	New	0				Hrs	2,101.7				
Unknown		0				APUS	4,026				
	APU - Engine Oil Filter							RE (H/T)			
49 APU1						Mos	12-Dec-2023				
3609088-1	New	0				Hrs	2,101.7				
Unknown		0				APUS	4,026				
	APU Bite Indicator							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	APU Engine Fire Extinguisher Container Cartridge							RE	Life Limit, Replacement Schedule, TLMC 05-19-01		
49 A/F						Yrs	27-Sep-2023	15	-/+14d	01-Jul-2038	14.1 Years (+14 Days)
30600-22	New										
Unknown		0				Hrs	5,197.3				
Manufactured Date 01-Jul-2023		0				Ldg	3,212				
Alias1:(Std)L4900015, (EMP)4900015 (ZONE: 300) (SOURCE: MM-104, Learjet eINSPECTOR) (NOTE: The maximum service life shall not exceed 12 years. The maximum storage and installed service life shall not exceed 15 years. Check date stamped on cartridge.)											
	APU Fuel Line							RE		TLMC 05-19-01	**≈14-Oct-2027**
49 A/F		0				Mos	10-Feb-2021				
4549058032-001	New	0				Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
Unknown		0				Ldg	2,822				
Alias1:(Std)AA4900039, (EMP)4900039 (ZONE: 300) (SOURCE: MM-104, Learjet eINSPECTOR)											
	APU Inlet Screen							RE (O/C)			
49 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	APU, Cockpit Control Panel							RE (O/C)			
49 APU1				3		Mos	17-Apr-2012				
7088000-2						Hrs					
DB384						APUS					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Assembly, Fuel Control							RE (O/C)			
	49 APU1						Mos	08-May-2008				
	3883900-1						Hrs					
	0601305						APUS					
		Assembly, Lube Oil-Pump							RE (O/C)			
	49 APU1		0				Mos	29-Sep-2007				
	3881825-1	New	0				Hrs	0				
	P-1285		0				APUS	0				
		Auxiliary Power Unit Compressor Rotor							RE	Replacement Schedule, TLMC 05-19-01		**≈20-Nov-2030**
	49 APU1		0				Mos	29-Sep-2007				
	3822523-003	New	0				Hrs	0				
	070350104756		0				APUS	0	12,000		12,000	7,964 APUS
	Alias1:(Std)H4900019, (Std)H4900020, (EMP)4900019, (EMP)4900020 (ZONE: 300) (SOURCE: MM-104, Learjet eINSPECTOR) (NOTE: Note: Cumulative cycle life information and component replacement should be recorded in the APU log book and serial data card.)											
		Auxiliary Power Unit Turbine Rotor							RE		TLMC 05-19-01	**≈27-Jul-2027**
	49 APU1						Mos	12-Dec-2023				
	70722360-1	New	0				Hrs	2,101.7				
	22-156101-07122		0				APUS	4,026	4,000		8,026	3,990 APUS
	Alias1:(Std)H4900018, (EMP)4900018 (ZONE: 310) (SOURCE: MM-104, Learjet eINSPECTOR) (NOTE: Note: Cumulative cycle life information and component replacement should be recorded in the APU log book and serial data card.)											
		Battery Contactor							RE (O/C)			
	49 A/F	APU					Mos	25-Jul-2022				
	420CC02	Tested/Inspected					Hrs	5,042				
	2058						Ldg	3,101				
		Bleed Air Shutoff Valve							RE (O/C)			
	49 APU1				18		Mos	09-Apr-2018				
	4714-18						Hrs					
	0352						APUS					
		Cool Rear Compartment R/H Fan							RE (O/C)			
	49 APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Cooling, Tailcone APU (B31) Fan							RE (O/C)			
	49 APU1		0				Mos	13-Mar-2008				
	011809500	New	0				Hrs	0				
	107401709		0				APUS	0				
		Differential Pressure Indicator							RE (O/C)			
	49 APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Differential Pressure Valve							RE (O/C)			
	49 APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		EGT Thermocouple							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Electronic Control Unit, (ECU)							RE (O/C)			
49	APU1			0			Mos	13-Mar-2008				
	2119560-3	New					Hrs					
	67-M0031						APUS					
		Filter Bypass Valve							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Flow Divider Valve							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Fuel Line Replace							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Fuel Pump							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Fuel Solenoid Valve							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Ground Control Unit							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Ignition Exciter							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Ignition Lead							RE (O/C)			
49	APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Ignition, APU Unit							RE (O/C)			
49	APU1			0			Mos	13-Mar-2008				
	3888000-7	New					Hrs					
	070218079966						APUS					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Inlet Temp Sensor							RE (O/C)			
49 APU1		0				Mos	09-Apr-2018				
MS28034-1	New	0				Hrs					
240267		0				APUS					
	Isolation Valve							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	Low Oil Pressure Sensor							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	Maintenance Control, APU Panel							RE (O/C)			
49 APU1		0				Mos	13-Mar-2008				
7088001-2	New					Hrs					
DC382						APUS					
	Manifold And Primary Atomizer							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	Manifold And Secondary Atomizer							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	Oil Level Sensor							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	Oil Pressure Switch							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	Oil Temperature Bulb							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	Pressure Relief Valve							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				
	Pressurizing Valve							RE (O/C)			
49 APU1						Mos	29-Sep-2007				
Unknown						Hrs	0				
Unknown						APUS	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Remotely Located (ECU) Controller							RE (O/C)			
	49 APU1		0				Mos	29-Sep-2007				
	2119560-3	New	0				Hrs	0				
	67-M0031		0				APUS	0				
		Seal							RE (O/C)			
	49 APU1						Mos	09-Jan-2020				
	3863504-1						Hrs	1,682.1				
	Unknown						APUS	3,254				
		Seal Rotor							RE (O/C)			
	49 APU1						Mos	09-Jan-2020				
	3861042-2						Hrs	1,682.1				
	Unknown						APUS	3,254				
		Speed Sensor							RE (O/C)			
	49 APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Strut Support Assembly							RE (O/C)			
	49 APU1	No.1	0				Mos	13-Mar-2008				
	7630102001-001	New					Hrs					
	0034						APUS					
		Strut Support Assembly							RE (O/C)			
	49 APU1	No.2	0				Mos	13-Mar-2008				
	7630102001-001	New					Hrs					
	0037						APUS					
		Tailcone Access Door Cooling (B30) Fan							RE (O/C)			
	49 APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Thermostat (S175) Switch							RE (O/C)			
	49 APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Thermostat (S176) Switch							RE (O/C)			
	49 APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
		Ultimate Relief Valve							RE (O/C)			
	49 APU1						Mos	29-Sep-2007				
	Unknown						Hrs	0				
	Unknown						APUS	0				
2007-09-03		**Auxiliary power unit (APU)**							RE (-)		Mandatory	
	49 APU1						Mos	11-Feb-2010				
	Eff: 11-May-2007 Not Applicable	BY AIRCRAFT SERIAL NUMBER					Hrs					
							APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
3615880-49-8149	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 12-Jun-2015						Hrs					
						APUS					
3615880-49-8149 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs**							T (-)		Recommended	
49 APU1						Mos					
						Hrs					
						APUS					
3615880-49-8149 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos					
						Hrs					
						APUS					
3615880-49-8149 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 15-Dec-2017						Hrs					
(AVG MAN HRS: 1.5)						APUS					
3822101-49-8148	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 10-Jul-2015						Hrs					
						APUS					
3822101-49-8148 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							T (-)		Recommended	
49 APU1						Mos					
Eff: 20-Oct-2015						Hrs					
						APUS					
3822101-49-8148 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 10-Jan-2017						Hrs					
						APUS					
3822101-49-8148 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 27-Nov-2017						Hrs					
(AVG MAN HRS: 1)						APUS					
3822523-49-8305	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair Of Compressor Rotor Pn 3822523-003 On Re100 Auxiliary Power Units (APU)**							RE (-)		Service Bulletin	
49 APU1						Mos	12-Dec-2023				
Complied With						Hrs	2,101.7				
						APUS	4,026				
3881800-49-7523	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 01-Feb-2000						Hrs					
(AVG MAN HRS: 2)						APUS					
3881800-49-7523 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 05-May-2000						Hrs					
(AVG MAN HRS: 2)						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
3881800-49-7523 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 26-Oct-2001						Hrs					
(AVG MAN HRS: 2)						APUS					
3881800-49-7523 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 22-Feb-2002						Hrs					
(AVG MAN HRS: 2)						APUS					
3881800-49-7523 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Low Oil Pressure Switch PN 3876255-2 with PN 3876351-1 and Re-Identify Lube Pump From PN 3881800-1 to PN 3881825-1 on Re100[XL] And RE100[LJ] APUS**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 30-Oct-2014 Not Applicable						Hrs	1,612.5				
(AVG MAN HRS: 2)						APUS	3,165				
3883900-49-7700	**Airborne Auxiliary Power - Fuel Control Unit - Authorize The Use of Packing, PN S9412-508 to the Fuel Control Unit (FCU), PN 3883900-1**							RE (-)		Optional	
49 APU1						Mos					
Eff: 22-Aug-2002						Hrs					
						APUS					
3883900-49-7976	**Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 25-Feb-2009						Hrs					
(AVG MAN HRS: 1)						APUS					
3883900-49-7976 Rev 1	**Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit**							T (-)		Recommended	
49 APU1						Mos					
Eff: 10-Apr-2009						Hrs					
(AVG MAN HRS: 1)						APUS					
3883900-49-7976 Rev 2	**Airborne Auxiliary Power - Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1, on the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next Auxiliary Power Unit (APU) Shop Visit**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 11-May-2019						Hrs					
(AVG MAN HRS: 1)						APUS					
3883900-49-8297	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Seal, PN 3883905-1, with PN 70722907-1 on the Fuel Control Unit (FCU), PN 3883900-1 for the RE100 APU**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 24-Feb-2020						Hrs					
(NOTE: COMPLIANCE: This service bulletin, recommended by Honeywell, is done on an attritional basis, oil seal to be replaced if a high leakage rate is present.)						APUS					
45-49-1	**Airborne Auxiliary Power - Activation of Auxiliary Power Unit**							RE (-)		Optional	
49 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-49-1 Rev 1	**Airborne Auxiliary Power - Activation of Auxiliary Power Unit**							RE (-)		Optional	
49 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-49-1 Rev 2	**Airborne Auxiliary Power - Activation of Auxiliary Power Unit**							RE (-)		Optional	
49 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-49-1 Rev 3	**Airborne Auxiliary Power - Activation of Auxiliary Power Unit**							RE (-)		Optional	
49 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-49-1 Rev 4	**Airborne Auxiliary Power - Activation of Auxiliary Power Unit**							RE (-)		Optional	
49 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-49-1 Rev 5	**Airborne Auxiliary Power - Activation of Auxiliary Power Unit**							RE (-)		Optional	
49 A/F						Mos	29-Aug-2019				
Eff: 27-Sep-2010 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-49-10	**Airborne Auxiliary Power - Inspection of the APU Main Body Cooling Duct**							RE (-)		Recommended	
49 A/F						Mos	14-Dec-2020				
Eff: 08-Feb-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-49-12	**Airborne Auxiliary Power - Installation of Improved APU Fire Switch Guard**							RE (-)		Optional	
49 A/F						Mos	21-Sep-2009				
Complied With						Hrs	959.2				
						Ldg	607				
45-49-12 Rev 1	**Airborne Auxiliary Power - Installation of Improved APU Fire Switch Guard**							RE (-)		Optional	
49 A/F						Mos	10-Jan-2020				
Eff: 04-Mar-2013 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				
45-49-13	**Airborne Auxiliary Power - Inspection / Replacement Of Apu Wiring Harness Connector Backshells**							RE (-)		Recommended	
49 A/F						Mos					
Eff: 21-May-2012						Hrs					
(AVG MAN HRS: 16)						Ldg					
45-49-13 Rev 1	**Airborne Auxiliary Power - Inspection / Replacement Of Apu Wiring Harness Connector Backshells**							RE (-)		Recommended	
49 A/F						Mos	15-Jun-2012				
Eff: 04-Jun-2012 Complied With						Hrs	2,501.8				
(AVG MAN HRS: 16)						Ldg	1,492				
45-49-14	**Airborne Auxiliary Power - APU Maintenance Panel Wire Harness Inspection**							RE (-)		Recommended	
49 A/F						Mos	12-Jul-2013				
Eff: 28-May-2013 Complied With						Hrs	2,891.6				
(AVG MAN HRS: 6)						Ldg	1,695				
45-49-15	**Airborne Auxiliary Power - Installation Of Auxiliary Power Unit (APU) Ground Bracket**							RE (-)		Recommended	
49 A/F						Mos	28-Apr-2015				
Eff: 09-Mar-2015 Not Applicable	BY S/N					Hrs	3,446.5				
(AVG MAN HRS: 2)						Ldg	2,007				
45-49-15 Rev 1	**Airborne Auxiliary Power - Installation Of Auxiliary Power Unit (APU) Ground Bracket**							RE (-)		Recommended	
49 A/F						Mos	14-Dec-2020				
Eff: 07-Dec-2015 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 6)						Ldg	2,822				
45-49-16	**Airborne Auxiliary Power - Installation Of Auxiliary Power Unit (APU) Ground Bracket Inspection**							RE (-)		Recommended	
49 A/F						Mos	19-Mar-2015				
Eff: 09-Mar-2015 Complied With	APU GROUND BRACKET INSPECTION					Hrs	3,423.5				
(AVG MAN HRS: 2)						Ldg	1,995				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-49-16 Rev 1	**Airborne Auxiliary Power - Installation Of Auxiliary Power Unit (APU) Ground Bracket Inspection**							RE (-)		Recommended	
49 A/F						Mos	10-Jan-2020				
Eff: 07-Dec-2015 Not Applicable						Hrs	4,590.8				
(AVG MAN HRS: 8) (NOTE: When equipped with APU)						Ldg	2,807				
45-49-17	**Airborne Auxiliary Power - Auxiliary Power Unit (APU) Electronic Control Unit (ECU) Upgrade**							T (-)		Optional	
49 A/F						Mos					
Eff: 08-Oct-2018						Hrs					
(AVG MAN HRS: 1.5) (NOTE: EFFECTIVITY: For aircraft that are equipped with an Auxiliary Power Unit (APU) that is equipped with Electronic Control Unit (ECU), PN 2119560-3 Series 4, and PN 2119560-3 Series 3 units with serial numbers 67-B0026, 67-B0028, and 35-G0125.)						Ldg					
45-49-17 Rev 1	**Airborne Auxiliary Power - Auxiliary Power Unit (APU) Electronic Control Unit (ECU) Upgrade**							T (-)		Optional	
49 A/F						Mos					
Eff: 15-Oct-2018						Hrs					
(AVG MAN HRS: 1.5) (NOTE: EFFECTIVITY: For aircraft that are equipped with an Auxiliary Power Unit (APU) that is equipped with Electronic Control Unit (ECU), PN 2119560-3 Series 4, and PN 2119560-3 Series 3 units with serial numbers 67-B0026, 67-B0028, and 35-G0125.)						Ldg					
45-49-17 Rev 2	**Airborne Auxiliary Power - Auxiliary Power Unit (APU) Electronic Control Unit (ECU) Upgrade**							T (A/R)		Optional	
49 A/F						Mos					
Eff: 03-Apr-2023						Hrs					
(AVG MAN HRS: 1.5) (NOTE: EFFECTIVITY: Learjet 45-002 thru 45-367, and 45-369 thru 45-445 and 45-447 thru 45-455, for aircraft that are equipped with an Auxiliary Power Unit (APU) that is equipped with Electronic Control Unit (ECU), PN 2119560-3 Series 4, and PN 2119560-3 Series 3 units with serial numbers 67-B0026, 67- B0028, and 35-G0125.)						Ldg					
45-49-3	**Airborne Auxiliary Power - Improved Auxiliary Power Unit (APU) Electrical Grounding**							RE (-)		Recommended	
49 A/F						Mos	13-Mar-2008				
Not Applicable BY SERIAL NUMBER						Hrs	8.7				
						Ldg	8				
45-49-3 Rev 1	**Airborne Auxiliary Power - Improved Auxiliary Power Unit (APU) Electrical Grounding**							RE (-)		Recommended	
49 A/F						Mos	13-Mar-2008				
Not Applicable BY SERIAL NUMBER						Hrs	8.7				
						Ldg	8				
45-49-3 Rev 2	**Airborne Auxiliary Power - Improved Auxiliary Power Unit (APU) Electrical Grounding**							RE (-)		Recommended	
49 A/F						Mos	13-Mar-2008				
Not Applicable BY SERIAL NUMBER						Hrs	8.7				
						Ldg	8				
45-49-3 Rev 3	**Airborne Auxiliary Power - Improved Auxiliary Power Unit (APU) Electrical Grounding (Superseded by SB 45-49-4)**							RE (-)		Recommended	
49 A/F						Mos	29-Aug-2019				
Eff: 26-Feb-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-49-4	**Airborne Auxiliary Power Unit - Installation of Auxiliary Power Unit (APU) Ground Bracket**							RE (-)		Recommended	
49 A/F						Mos	13-Mar-2008				
Not Applicable BY SERIAL NUMBER						Hrs	8.7				
						Ldg	8				
45-49-4 Rev 1	**Airborne Auxiliary Power Unit - Installation of Auxiliary Power Unit (APU) Ground Bracket**							RE (-)		Recommended	
49 A/F						Mos	13-Mar-2008				
Not Applicable BY SERIAL NUMBER						Hrs	8.7				
						Ldg	8				
45-49-4 Rev 2	**Airborne Auxiliary Power Unit - Installation of Auxiliary Power Unit (APU) Ground Bracket**							RE (-)		Recommended	
49 A/F						Mos	08-Jun-2009				
Eff: 26-Feb-2007 Not Applicable PER A/C S/N						Hrs	801				
						Ldg	521				

Task No / SEQ	Description / PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-49-4 Rev 3	**Airborne Auxiliary Power - Installation of Auxiliary Power Unit (APU) Ground Bracket**								RE (-)		Recommended	
49 A/F							Mos	28-Apr-2015				
Eff: 03-Mar-2009 Not Applicable		BY S/N					Hrs	3,446.5				
(AVG MAN HRS: 12)							Ldg	2,007				
45-49-4 Rev 4	**Airborne Auxiliary Power - Installation of Auxiliary Power Unit (APU) Ground Bracket**								RE (-)		Recommended	
49 A/F							Mos	14-Dec-2020				
Eff: 07-Dec-2015 Not Applicable							Hrs	4,610.5				
(AVG MAN HRS: 12)							Ldg	2,822				
45-49-5	**Airborne Auxiliary Power - Inspection/Installation of Sealant at APU Inlet Duct Spacers**								RE (-)		Recommended	
49 A/F							Mos	14-Dec-2020				
Eff: 12-Apr-2002 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-49-6	**Airborne Auxiliary Power - APU Fuel Line Inspection and Routing**								RE (-)		Recommended	
49 A/F							Mos	14-Dec-2020				
Eff: 04-Jan-2005 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-49-7	**Airborne Auxiliary Power - Installation of APU Tailcone Ventilation Fan Thermostats**								RE (-)		Optional	
49 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-49-7 Rev 1	**Airborne Auxiliary Power - Installation of APU Tailcone Ventilation Fan Thermostats**								RE (-)		Optional	
49 A/F							Mos	13-Mar-2008				
Eff: 17-Apr-2006 Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-49-9	**Airborne Auxiliary Power - Modification of the APU Bleed Air Duct Boot Attachment**								RE (-)		Recommended	
49 A/F							Mos	14-Dec-2020				
Eff: 27-Mar-2006 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
491000	**Apu - Download Apu Ecu (Times/Cycles)**								RE (A/R)			
49 APU1							Mos	27-Sep-2023				
							Hrs	2,095.5				
							APUS	3,981				
496011	**Fuel Shutoff Valve**								RE (O/C)			
49 APU1			0				Mos	29-Sep-2007				
3876322-1 0351		New	0				Hrs	0				
			0				APUS	0				
49-7933 Rev 10	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**								T (A/R)		Service Bulletin	
49 APU1							Mos					
Eff: 18-Jan-2022							Hrs					
							APUS					
49-7933 Rev 5	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**								T (-)		Service Bulletin	
49 APU1							Mos					
Eff: 23-Oct-2014							Hrs					
							APUS					
49-7933 Rev 6	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**								RE (-)		Service Bulletin	
49 APU1							Mos					
							Hrs					
							APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-7933 Rev 7	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 09-Feb-2017						Hrs					
						APUS					
49-7933 Rev 8	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 27-Jul-2017						Hrs					
						APUS					
49-7933 Rev 9	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 03-Apr-2020						Hrs					
						APUS					
49-7997	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 16-Sep-2009						Hrs					
						APUS					
49-7997 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 11-Feb-2010						Hrs					
						APUS					
49-7997 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 22-Dec-2010						Hrs					
						APUS					
49-7997 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 16-Jan-2014						Hrs					
						APUS					
49-7997 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 12-Jan-2015						Hrs					
						APUS					
49-7997 Rev 5	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 03-Feb-2017						Hrs					
						APUS					
49-7997 Rev 6	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos	12-Dec-2023				
Eff: 05-Nov-2020 Complied With						Hrs	2,101.7				
						APUS	4,026				
49-8252	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (-)			
49 APU1						Mos					
Eff: 31-Aug-2018						Hrs					
						APUS					
49-8252 Rev 1	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (-)			
49 APU1						Mos					
Eff: 07-Mar-2019						Hrs					
						APUS					
49-8252 Rev 2	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (A/R)		Service Bulletin	
49 APU1						Mos					
Eff: 13-Oct-2020						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
70721597-49-8166	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**						RE (-)		Recommended	
49 APU1					Mos					
Eff: 02-Jul-2015					Hrs					
					APUS					
70721597-49-8166 Rev 1	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**						RE (-)		Recommended	
49 APU1					Mos					
Eff: 31-Aug-2015					Hrs					
					APUS					
70721597-49-8166 Rev 2	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**						RE (-)		Recommended	
49 APU1					Mos					
Eff: 25-Oct-2016					Hrs					
					APUS					
70721597-49-8166 Rev 3	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**						T (A/R)		Recommended	
49 APU1					Mos					
Eff: 13-Oct-2017					Hrs					
(AVG MAN HRS: 1) (NOTE: COMPLIANCE: Honeywell recommends this service bulletin be done for the balance repair of the compressor rotor, PN 70721597-1.)					APUS					
70721598-49-8168	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs**						RE (-)		Recommended	
49 APU1					Mos					
Eff: 02-Jul-2015					Hrs					
					APUS					
70721598-49-8168 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs**						T (-)		Recommended	
49 APU1					Mos					
Eff: 20-Oct-2015					Hrs					
					APUS					
70721598-49-8168 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs**						T (-)		Recommended	
49 APU1					Mos					
Eff: 10-Jan-2017					Hrs					
					APUS					
70721598-49-8168 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs**						T (A/R)		Recommended	
49 APU1					Mos					
Eff: 14-Dec-2017					Hrs					
(AVG MAN HRS: 1)					APUS					
70721725-49-8152	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**						RE (-)		Recommended	
49 APU1					Mos					
Eff: 27-May-2015					Hrs					
					APUS					
70721725-49-8152 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**						T (-)		Recommended	
49 APU1					Mos					
Eff: 27-May-2015					Hrs					
					APUS					
70721725-49-8152 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**						T (-)		Recommended	
49 APU1					Mos					
					Hrs					
					APUS					
70721725-49-8152 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**						T (-)		Recommended	
49 APU1					Mos					
Eff: 27-Nov-2017					Hrs					
					APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
70721725-49-8152 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 19-Dec-2017						Hrs					
						APUS					
70722360-49-8306	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair Of Turbine Rotor Pn 70722360-1 On Re100 Auxiliary Power Units (APU)**							RE (-)		Service Bulletin	
49 APU1						Mos	12-Dec-2023				
Complied With						Hrs	2,101.7				
						APUS	4,026				
A45-49-11	**Airborne Auxilliary Power - Deactivation of the Auxiliary Power Unit (APU) with APU Fuel Shutoff Valve Removal**							RE (-)		Alert	
49 A/F						Mos	14-Dec-2020				
Eff: 26-Mar-2007 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 11.5)						Ldg	2,822				
A45-49-2	**Airborne Auxiliary Power - Inspection and Rework of APU Firebox Inlet Duct Seal**							RE (-)		Alert	
49 A/F						Mos	13-Mar-2008				
Eff: 28-Aug-2000 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 32)						Ldg					
A45-49-2 Rev 1	**Airborne Auxiliary Power - Inspection and Rework of APU Firebox Inlet Duct Seal**							RE (-)		Alert	
49 A/F						Mos	14-Dec-2020				
Eff: 12-Jan-2001 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 32)						Ldg	2,822				
A45-49-8	**Airborne Auxiliary Power - Inspection of the APU Bleed Air Duct Boot Attachment**							RE (-)		Alert	
49 A/F						Mos	13-Mar-2008				
Eff: 27-Mar-2006 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 5)						Ldg					
A45-49-8 Rev 1	**Airborne Auxiliary Power - Inspection of the APU Bleed Air Duct Boot Attachment**							RE (-)		Alert	
49 A/F						Mos	14-Dec-2020				
Eff: 03-Jul-2006 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 5)						Ldg	2,822				
APU 1	**Honeywell - RE100[LJ] APU**							RE (-)			
49 A/F						Mos	15-Feb-2024				
3800726-1	Time at install: 2101.7 Hrs, 4026 APUS					Hrs	5,254.1				
P-393						Ldg	3,758				
AW 49-006	**Auxiliary Power Unit (APU) Bonding**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
AW 49-007	**Auxiliary Power Unit (APU) Bleed Duct Boot**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 49-008	**Left Aft PDP Wire Harness Routing**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 49-009	**APU Fuel Supply Shut-Off Valve**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AW 49-010	**APU Fuel Supply Shut-Off Valve**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 49-011	**APU Fuel Supply Shut-Off Valve**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 49-012	**APU Fuel Supply Shut-Off Valve**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 49-013	**APU Fuel Supply Shut-Off Valve**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 49-014	**APU Fuel Supply Shut-Off Valve**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 49-015	**Update - APU Fuel Supply Shut-Off Valve, (Effective: Learjet 45 With Optional APU Installed)**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 49-016	**Update - APU Fuel Supply Shut-Off Valve, (Effective: Learjet 45 With Optional APU Installed)**							RE (-)		Advisory Wire	
49 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
D201107000024 Rev 1	**Approved Use of Biofuel Blends for All Honeywell Commercial and Military Auxiliary Power Units (APU)**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 03-Jun-2020						Hrs					
						APUS					
D201112000050	**Acceptance Criteria for On-Wing Borescope Inspections**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 13-Jan-2012						Hrs					
						APUS					
D201112000050 Rev 1	**Acceptance Criteria for On-Wing Borescope Inspections**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 14-Aug-2012						Hrs					
						APUS					
D202207002674	**Procedure to Determine if Hydro Pad Compressor Seal is Damaged and Evaluate if it was the Cause for Oil Leaks on the RE100 Series and 36-150 Series APUs**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 16-Aug-2022						Hrs					
(NOTE: EFFECTIVITY: Please see Par. B for more details.)						APUS					
H4900011	**** APU Generator - Perform Overvoltage Protection Check.**							RE	TLMC 04-10-00, TLMC 05-13-01, Ch.5 Interval		**≈24-Apr-2025**
49 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:49-40-01 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104) (NOTE: (Refer to 49-40-01.))						Ldg	3,757				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
K4900005	**APU Engine Fuel Filter - Replace.**							RE		TLMC 05-19-01	**≈09-Nov-2024**
49 APU1						Mos	12-Dec-2023				
						Hrs	2,101.7	750	-/+25	2,851.7	744.7 Hrs (+25)
(ZONE: 310JL, 310QR)						APUS	4,026				
L4900015	**APU Engine Fire Extinguisher Container Cartridge. (In Service Life limit)**							RE		TLMC 05-19-01	
49 A/F						Yrs	27-Sep-2023	12	-/+14d	27-Sep-2035	11.4 Years (+14 Days)
30600-22											
Unknown						Hrs	5,197.3				
(ZONE: 310JL, 310QR) (SOURCE: MM-104) (NOTE: The maximum service life must not exceed 12 years. The maximum storage and installed service life must not exceed 15 years. Check date stamped on cartridge.)						Ldg	3,212				
O4900006	**APU Engine Starter/Generator Gear Box Drive Splines - Perform Visual Inspection.**							RE		TLMC 05-19-00	**≈25-Mar-2025**
49 A/F						Mos	12-Dec-2023				
						Hrs					
Alias1:5-10-00 (ZONE: 310JL, 310RR) (SOURCE: MM-104) (NOTE: At Starter/Generator Overhaul.)						Ldg					
						Hrs (APU)	2,098.8	1,200		3,298.8	1,191.8 Hrs(APU)
O4900008	**APU Engine Chip Detector - Inspect for contamination.**							RE		TLMC 05-19-00	**≈03-Jul-2024**
49 APU1						Mos	20-May-2020				
						Hrs	1,682.1	750	-/+25	2,432.1	325.1 Hrs (+25)
(ZONE: 310JL, 310RR)						APUS	3,254				
P4900009	**APU Engine - Perform Oil Change.**							RE		TLMC 05-19-00	**≈03-Aug-2024**
49 APU1						Mos	15-Aug-2021				
						Hrs	1,800.1	750	-/+25	2,530.2	423.2 Hrs (+25)
AMM:12-10-10 (ZONE: 310JL, 310RR) (Tol. Adjustment: -19.9 Hrs) (NOTE: This requirement is not applicable for operators enrolled in the Spectrometric Oil and Filter Analysis Program (SOAP) system per Honeywell SIL# APU-49.)						APUS	3,451				
RE100-49-7400	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881739-2 with PN 3881800-1, Gearbox Housing, PN 3863409-4 with PN 3863409-2, and O-Ring, PN M83248/1-115 with PN M83248/1-116**							RE (-)		Optional	
49 APU1						Mos					
Eff: 01-Feb-2000						Hrs					
						APUS					
RE100-49-7400 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, Part No. 3881739-2 with Part No. 3881800-1, Gearbox Housing, Part No. 3863409-1/-2 with Part No. 3863409-3/-4 (Respectively), and O-ring, Part No. M83248/1-116 with Part No. M83248/1-115**							T (A/R)		Optional	
49 APU1						Mos					
Eff: 14-Jun-2000						Hrs					
						APUS					
RE100-49-7447	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Compressor Rotor, PN 3822523-2 with PN 3822523-003**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 29-Jan-2003 Not Applicable						Hrs	1,612.5				
						APUS	3,165				
RE100-49-7456	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Thermocouple, PN 3876315-1 with Thermocouple, PN 3876315-2**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 25-Feb-1999 Not Applicable						Hrs	1,612.5				
						APUS	3,165				
RE100-49-7457	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Turbine Plenum, PN 3846734-1 with Turbine Plenum, PN 3846743-1**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 25-Feb-1999 Not Applicable						Hrs	1,612.5				
						APUS	3,165				
RE100-49-7489	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Oil Filler Neck And Cap, PN 2A1126 (527-510-9001) With Oil Filler Neck and Dipstick Cap, PN 2A7732 (361-530-9354)**							RE (-)		Optional	
49 APU1						Mos					
Eff: 02-Feb-2000						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
RE100-49-7530	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 01-Feb-2000						Hrs					
						APUS					
RE100-49-7530 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1**							RE (-)		Recommended	
49 APU1						Mos					
						Hrs					
						APUS					
RE100-49-7530 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Lube Pump, PN 3881800-1 with PN 3881825-1**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 22-Feb-2002 Not Applicable						Hrs	1,612.5				
						APUS	3,165				
RE100-49-7535	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Flow Divider Tee, PN 3883921-1 with PN 3883921-2**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 01-Oct-1999 Not Applicable						Hrs	1,612.5				
						APUS	3,165				
RE100-49-7563	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Generator Seal, PN 3863387-1 with PN 3863504-1**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 11-May-2000						Hrs					
						APUS					
RE100-49-7563 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Generator Seal, PN 3863387-1 with PN 3863504-1**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 22-May-2002 Not Applicable						Hrs	1,612.5				
						APUS	3,165				
RE100-49-7576	**Airborne Auxiliary Power - Gas Turbine Engine - Inspect and Remove Applicable Serial Number Low Oil Pressure Switch, PN 3876351-1**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 20-Mar-2000						Hrs					
(AVG MAN HRS: 0.5)						APUS					
RE100-49-7576 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Inspect and Remove Applicable Serial Number Low Oil Pressure Switch, PN 3876351-1**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 01-Jan-2029 Not Applicable						Hrs	1,612.5				
(AVG MAN HRS: 0.5)						APUS	3,165				
RE100-49-7715	**Airborne Auxiliary Power - Gas Turbine Engine - One Time Inspection/Replacement of the Coupling Clamp, PN 234-511-9059, T-Bolt (Fuel Control To Lube Pump Flanges)**							RE (-)		Recommended	
49 APU1						Mos	29-Aug-2019				
Eff: 25-Sep-2002 Not Applicable						Hrs	1,612.5				
						APUS	3,165				
RE100-49-7787	**Replace Low Oil Level Switch, Part No. 3876318-1 with Part No. 3876318-2**							RE (-)		Optional	
49 APU1						Mos					
Eff: 21-Jun-2004						Hrs					
						APUS					
RE100-49-7855	**Replace Low Oil Level Switch, Part No. 3876318-1 or Part No. 3876318-2 with Part No. 3876318-3**							RE (-)		Optional	
49 APU1						Mos					
Eff: 09-Aug-2005						Hrs					
						APUS					
RE100-49-8139	**Airborne Auxiliary Power - Gas Turbine Engine - Increase the Installation Torque and add the Use of Locking Compound During Carbon Seal Assembly on the RE100 APU**							RE (-)		Recommended	
49 APU1						Mos	12-Dec-2023				
Eff: 15-Aug-2014 Complied With						Hrs	2,101.7				
						APUS	4,026				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
RE100-49-8276	**Airborne Auxiliary Power - Gas Turbine Engine - Remove and Replace Electronic Control Unit, PN 2119560-3 Series 4 with PN 2119560-3 Series 5.**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 04-Sep-2018						Hrs					
(AVG MAN HRS: 1.5)						APUS					
RE100-49-8303	**Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)**							T (-)		Optional	
49 APU1						Mos					
Eff: 24-Feb-2020						Hrs					
(NOTE: EFFECTIVITY: Applicable component PN 3800726-1)						APUS					
RE100-49-8303 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)**							RE (-)		Optional	
49 APU1						Mos					
Eff: 01-Jul-2020						Hrs					
						APUS					
RE100-49-8303 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)**							RE (-)		Optional	
49 APU1						Mos					
Eff: 28-Aug-2020						Hrs					
						APUS					
RE100-49-8303 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)**							T (-)		Optional	
49 APU1						Mos					
Eff: 01-Sep-2020						Hrs					
						APUS					
RE100-49-8303 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine for Incorporation of Improved Compressor Carbon Seal and Related Components on the RE100 Auxiliary Power Unit (APU)**							RE (-)		Optional	
49 APU1						Mos	12-Dec-2023				
Eff: 18-May-2022 Complied With						Hrs	2,101.7				
						APUS	4,026				
RE100-49-8333	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Branched Wiring Harness, PN 3888411-3, with Branched Wiring Harness, PN 3888411-4 on Re100 [LJ] Auxiliary Power Unit (APU) Model**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 25-Aug-2020						Hrs					
(NOTE: COMPLIANCE: This service bulletin, recommended by Honeywell, is done on an attritional basis when the repair of the replaced part is not possible.)						APUS					
RE100-49-8360 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with PN 627-504-9209 on Engines RE100[CS], RE100[LJ], and RE100[XL]**							T (-)		Cat. 2 - Recommended	
49 APU1						Mos					
Eff: 23-Feb-2022						Hrs					
(AVG MAN HRS: 1)						APUS					
RE100-49-8360 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with PN 627-504-9209 on RE100 Engine Models**							RE (-)		Cat. 2 - Recommended	
49 APU1						Mos	12-Dec-2023				
Eff: 29-Mar-2022 Complied With						Hrs	2,101.7				
(AVG MAN HRS: 1)						APUS	4,026				
RE100-49-8363	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing PN 3810880-1/-2 with PN 70724596-1 or PN 70724596-2, Gearbox Housing PN 3863409-6 with PN 70724597-1, Gearbox Housing PN 3863409-5 with PN 70724597-2 and Gearbox Housing PN 3863409-4 with PN 70724597-3 on the RE100 Auxiliary Power Unit (APU)**							RE (-)		Optional	
49 APU1						Mos					
Eff: 10-May-2022						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
RE100-49-8363 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Replace Inlet Housing PN 3810880-1/-2 with PN 70724596-1 or PN 70724596-2, Gearbox Housing PN 3863409-6 with PN 70724597-1, Gearbox Housing PN 3863409-5 with PN 70724597-2 and Gearbox Housing PN 3863409-4 with PN 70724597-3 on the RE100 Auxiliary Power Unit (APU)**						T (A/R)		Optional	
49 APU1					Mos					
Eff: 04-Aug-2022					Hrs					
(NOTE: EFFECTIVITY: Refer to Par. 1.A. of this SB for more information.)					APUS					
SIL APU-152	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 18-Jul-2008					Hrs					
					APUS					
SIL APU-152 Rev 1	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 24-Jul-2009					Hrs					
					APUS					
SIL APU-152 Rev 2	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 30-Nov-2010					Hrs					
					APUS					
SIL APU-152 Rev 3	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 19-Feb-2015					Hrs					
					APUS					
SIL APU-152 Rev 4	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 08-Feb-2018					Hrs					
					APUS					
SIL APU-49	**APU - First And Subsequent Oil and Filter Sample (MSP Engines)**						RE (-)		Informational	
49 APU1					Mos	20-May-2020				
Complied With					Hrs	1,682.1				
					APUS	3,254				
SIL APU-7	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**						RE (-)		Service Information Letter	
49 APU1					Mos					
					Hrs					
					APUS					
SIL APU-7 Rev 1	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 03-Mar-1988					Hrs					
					APUS					
SIL APU-7 Rev 2	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 02-Mar-2015					Hrs					
					APUS					
SIL APU-95 Rev 1	**Uncommanded Protective Shutdown of the Auxiliary Power Unit (APU) with High Oil Temperature (HOT) Identified**						RE (-)		Cancelled	
49 APU1					Mos					
Eff: 13-Jul-2020					Hrs					
					APUS					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL D201701000026	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 30-Jan-2017					Hrs					
					APUS					
SIL D201701000026 Rev 1	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs**						T (-)		Service Information Letter	
49 APU1					Mos					
Eff: 23-Jan-2018					Hrs					
					APUS					
SIL D201701000026 Rev 2	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine worksheet for 36-100, 36-150, RE100, and RE220 APUs**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 21-Mar-2018					Hrs					
					APUS					
SIL No. APU-49 Rev 10	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**						RE (-)		Service Information Letter	
49 APU1					Mos	20-May-2020				
Complied With	PERFORMED BY TURBINE SPECIALISTS (TES) W / O : 2748 DATED : 05/20/2020				Hrs	1,682.1				
	(NOTE: COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).)				APUS	3,254				
SIL No. APU-49 Rev 11	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units(APUs)**						RE (-)		Service Information Letter	
49 APU1					Mos					
					Hrs					
	(NOTE: Analyst/operator will need to manually set the calendar start. COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).)				APUS					
SIL No. APU-49 Rev 12	**Implementation of the Honeywell Spectrometric Oil and Filter AnalysisProgram (SOAP) for Honeywell Auxiliary Power Units(APUs)**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 02-Jun-2022					Hrs					
					APUS					
SIL No. APU-49 Rev 13	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APU)**						T (A/R)		Service Information Letter	
49 APU1					Mos					
Eff: 23-Nov-2023					Hrs					
					APUS					
SIL No. APU-49 Rev 7	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 05-May-2003					Hrs					
					APUS					
SIL No. APU-49 Rev 8	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**						RE (-)		Service Information Letter	
49 APU1					Mos					
Eff: 11-Apr-2008					Hrs					
					APUS					
SIL No. APU-49 Rev 9	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**						RE (-)		Service Information Letter	
49 APU1					Mos					
					Hrs					
	(NOTE: The SOAP and filter analysis program was initially limited to the operators of the GTCP36-100/-150 Series Auxiliary Power Units enrolled in the Honeywell Engines, Systems & Services APU Maintenance Service Plan (MSP). The program is now offered to all operators of the Honeywell GTCP36-100/-150, RE100 and RE220 Series APUs.)				APUS					
T4900004	**APU Engine Oil Filter - Replace.**						RE		TLMC 05-19-01	**≈09-Nov-2024**
49 APU1					Mos	12-Dec-2023				
					Hrs	2,101.7	750	-/+25	2,851.7	744.7 Hrs (+25)
	Alias1:49-90-04 (ZONE: 310JL, 310QR) (NOTE: (Refer to 49-90-04.) Note: This requirement is not applicable for operators enrolled in the Spectrometric Oil and Filter Analysis Program (SOAP) system per Honeywell SIL# APU-49.)				APUS	4,026				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
V4900003	**APU Starter/Generator - Perform Overhaul. Replace starter/generator brushes.**							RE		TLMC 05-19-00	**≈08-Aug-2024**
49 A/F						Mos	23-Dec-2017				
6608458-010						Hrs	4,076				
P1204						Ldg	2,402				
	(ZONE: 310JL, 310RR) (SOURCE: MM-104) (NOTE: (Effective on aircraft modified per Goodrich SB 23080-XXX-24- 8. with the "A" and "B" mod box marked on I.D. tag))					Hrs (APU)	1,346.5	1,200	-/+25	2,546.5	439.5 Hrs(APU) (+ 25)
V4900021	**APU Starter/Generator - Perform Overhaul. Replace starter/generator brushes.**							RE (N/A)		TLMC 05-19-00	
49 A/F						Mos					
6608458-010						Hrs					
P1204						Ldg					
	(ZONE: 310JL, 310RR) (SOURCE: MM-104) (NOTE: (Effective on aircraft not modified per Goodrich SB 23080-XXX- 24-8. with the "B" mod box not marked on I.D. tag))										
Y4900000	**Auxiliary Power Unit - Perform visual inspection of external firebox installation and attaching components.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
49 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 310JL, 310RR) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y4900002	**Auxiliary Power Unit Fire Extinguisher Container - Perform Functional Test of wiring.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
49 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:26-22-00 (ZONE: 220) (Tol. Adjustment: -30d) (SOURCE: MM-104) (NOTE: (Refer to 26-22-00.))					Ldg	3,757				
Y4900010	**APU Engine Fire Extinguisher Container - Check container pressure gauge for proper pressure.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
49 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:26-22-00 (ZONE: 310/ 840AR) (SOURCE: MM-104) (NOTE: (Refer to 26-22-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y4900012	**APU Inlet Screen and Opening - Perform visual inspection.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
49 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 310) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y4900013	**APU Exhaust Duct Area, Including Forward and Aft APU Exhaust Fairings - Perform visual inspection.**							RE		TLMC 05-11-02	**≈24-Jul-2024**
49 A/F	05-11-02					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 310) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
▼ 51 - STANDARD PRACTICES AND STRUCTURES - GENERAL											
AW 51-001	**Reports of Hi-Lite HST79 Shear Pin Collar Cracking**							RE (-)		Advisory Wire	
51 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 51-002	**Hi-Lite HST79 Shear Pin Collars Cracking**							RE (-)		Advisory Wire	
51 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
▼ 52 - DOORS											
	Door Assy							RE (O/C)			
52 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Door Cable Assembly							RE (O/C)			
	52 A/F	Lower					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Emergency Exit Door Assembly							RE (O/C)			
	52 A/F		0				Mos	13-Mar-2008				
	4552200076-V43-001	New	0				Hrs	0				
	0359		0				Ldg	0				
		Gas, Lower Entry Door Damper Assembly							RE (O/C)			
	52 A/F	Aft	0				Mos	21-Apr-2010				
	6652102002-003	New	0				Hrs	1,301.8				
	NA		0				Ldg	798				
		Gas, Lower Entry Door Damper Assembly							RE (O/C)			
	52 A/F	Fwd	0				Mos	30-Jul-2010				
	6652102002-003	New	0				Hrs	1,499.8				
	NA		0				Ldg	910				
		Main Cabin Door Assembly							RE (O/C)			
	52 A/F	Lower	0				Mos	13-Mar-2008				
	4552100050V107-001	New	0				Hrs	0				
	W442		0				Ldg	0				
		Main Cabin Door Assembly							RE (O/C)			
	52 A/F	Upper	0				Mos	13-Mar-2008				
	4552101000-003	New	0				Hrs	0				
	W455		0				Ldg	0				
		Passenger/Crew Door Cable Assy							RE (O/C)			
	52 A/F	Lower					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		SPPR Door Assy							RE (O/C)			
	52 A/F		0				Mos	23-May-2008				
	4553448001-801	New	0				Hrs	166.8				
	Unknown		0				Ldg	132				
		Tailcone Access Door							RE (O/C)			
	52 A/F		0				Mos	13-Mar-2008				
	4552405151-009	New	0				Hrs	0				
	481		0				Ldg	0				
		Tailcone Baggage Door Assembly							RE (O/C)			
	52 A/F		0				Mos	13-Mar-2008				
	12045-558V2-001	New	0				Hrs	0				
	475		0				Ldg	0				
2009-24-22		**Equipment/Furnishings**							RE (-)		Mandatory	
	52 A/F						Mos	19-Apr-2018				
	Eff: 08-Jan-2010 Not Applicable	DUE TO AIRCRAFT SERIAL NUMBER.					Hrs	4,204.3				
							Ldg	2,478				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2009-24-22 PARA G	**Inspect/Replace To Prevent The Use Of Door Seals And Sealant That Do Not Meet Flammability Requirements The Red Room Temperature Vulcanizing (Rtv) Sealant In Aft Baggage Bay**							RE (-)			
52 A/F						Mos	19-Apr-2018				
Not Applicable	DUE TO AIRCRAFT SERIAL RELATED TO SB 45-25-21 WHICH WAS LOOKED AT ON 816/2008 AND FOUND TO BE MOC: NOT APPLICABLE - BY SERIAL NUMBER					Hrs	4,204.3				
						Ldg	2,478				
2009-24-22 PARA H	**Inspection To Prevent The Use Of Door Seals And Sealant That Do Not Meet Flammability Requirements Of Baggage Bay Door Fire Barrier Seal**							RE (-)		Mandatory	
52 A/F						Mos	19-Apr-2018				
Not Applicable	RELATED TO SB 45-52-16 WHICH WAS LOOKED AT ON 81612008 AND FOUND TO BE MOC: NOT APPLICABLE-BY SERIAL NUMBER AND SB 45-52-16 ROL LOOKED AT ON 618109 AND FOUND TO BE MOC: NOT APPLICABLE - NIA PER AIC SIN AND AGAIN WITH SB 45- 52-16 R02 LOOKED AT ON 512111 AND FOUND TO BE AND SB 45-52-16 R01 LOOKED AT ON 618109 AND FOUND TO BE MOC: NOT APPLICABLE - N/A PER A/C S/N					Hrs	4,204.3				
						Ldg	2,478				
45-52-1	**Doors - Replacement of Passenger/Crew Lower Door Gas Damper**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-1 Rev 1	**Doors - Replacement of Passenger/Crew Lower Door Gas Damper**							RE (-)		Optional	
52 A/F						Mos	29-Aug-2019				
Eff: 17-Mar-2008 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-52-11	**Door - Replacement of the Emergency Exit Door Latch Springs**							RE (-)		Recommended	
52 A/F						Mos	14-Dec-2020				
Eff: 30-Jul-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-52-12	**Doors - Replacement of Lower Cabin Door Strut Brackets**							RE (-)		Optional	
52 A/F						Mos	21-Sep-2009				
Complied With						Hrs	959.2				
						Ldg	607				
45-52-12 Rev 1	**Doors - Replacement of Lower Cabin Door Strut Brackets**							RE (-)		Optional	
52 A/F						Mos	10-Jan-2020				
Eff: 16-Jan-2012 Not Applicable						Hrs	4,590.8				
						Ldg	2,807				
45-52-13	**Doors- Replacement of Hi-Lite Collars in the Upper Passenger Entrance Door**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-13 Rev 1	**Doors- Replacement of Hi-Lite Collars in the Upper Passenger Entrance Door**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-13 Rev 2	**Doors- Replacement of Hi-Lite Collars in the Upper Passenger Entrance Door**							RE (-)		Optional	
52 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-52-14	**Doors - Installation of the Tailcone Access Door Scuppers**							RE (-)		Optional	
52 A/F						Mos	29-Aug-2019				
Eff: 23-Apr-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-52-15	**Doors - Environmental Sealing of the Passenger/Crew Door**							RE (-)		Optional	
52 A/F						Mos	29-Aug-2019				
Eff: 12-Mar-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-52-15 Rev 1	**Doors - Environmental Sealing of the Passenger/Crew Door**							T (A/R)		Optional	
52 A/F						Mos					
Eff: 06-Mar-2023						Hrs					
(AVG MAN HRS: 26)						Ldg					
45-52-16	**Doors - Inspection/Replacement of the Baggage Bay Door Fire Barrier Seal**							RE (-)		Recommended	
52 A/F						Mos	06-Aug-2008				
Eff: 16-Jun-2008 Not Applicable	BY SERIAL NUMBER					Hrs	359.6				
(AVG MAN HRS: 6)						Ldg	264				
45-52-16 Rev 1	**Doors - Inspection/Replacement of the Baggage Bay Door Fire Barrier Seal**							RE (-)		Recommended	
52 A/F						Mos	08-Jun-2009				
Eff: 21-Jul-2008 Not Applicable	PER A/C S/N					Hrs	801				
(AVG MAN HRS: 6)						Ldg	521				
45-52-16 Rev 2	**Doors - Inspection/Replacement of the Baggage Bay Door Fire Barrier Seal**							RE (-)		Recommended	
52 A/F						Mos	14-Dec-2020				
Eff: 04-Apr-2011 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 6)						Ldg	2,822				
45-52-17	**Doors - Replacement of the Upper Cabin Door Inner Skin Tension Strap**							RE (-)		Recommended	
52 A/F						Mos					
Eff: 20-Oct-2008						Hrs					
(AVG MAN HRS: 8)						Ldg					
45-52-17 Rev 1	**Doors - Replacement of the Upper Cabin Door Inner Skin Tension Strap**							RE (-)		Recommended	
52 A/F						Mos	14-Dec-2020				
Eff: 26-Sep-2011 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 8)						Ldg	2,822				
45-52-18	**Doors - Replacement of the Main Entry Door Handle Retaining Screws**							RE (-)		Recommended	
52 A/F						Mos	28-Jan-2010				
Eff: 16-Nov-2009 Complied With						Hrs	1,172.9				
						Ldg	723				
45-52-2	**Doors - Installation of Emergency Exit Door Latch Mechanism Pin Retainer**							RE (-)		Recommended	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-2 Rev 1	**Doors - Installation of Emergency Exit Door Latch Mechanism Pin Retainer**							RE (-)		Recommended	
52 A/F						Mos	14-Dec-2020				
Eff: 10-Mar-1999 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-52-20	**Doors - Replacement of the Main Passenger/Crew Exterior Door Handle Sub-Assembly**							RE (-)		Optional	
52 A/F						Mos	25-Jun-2021				
Eff: 20-Dec-2017 Complied With						Hrs					
(AVG MAN HRS: 4)						Ldg					
45-52-21	**Doors - Lower Cabin Door Damper and Attachment Modification**							T (A/R)		Recommended	
52 A/F						Mos					
Eff: 07-Jul-2020						Hrs					
(AVG MAN HRS: 9)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-52-22	**Doors - Vent Door Bellcrank Assembly Modification**							T (A/R)		Recommended	
52 A/F						Mos					
Eff: 26-Sep-2022						Hrs					
(AVG MAN HRS: 40)						Ldg					
45-52-3	**Doors - Installation of Tailcone Access Door Latch Seals**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-3 Rev 1	**Doors - Installation of Tailcone Access Door Latch Seals**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-3 Rev 2	**Doors - Installation of Tailcone Access Door Latch Seals**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-3 Rev 3	**Doors - Installation of Tailcone Access Door Latch Seals**							RE (-)		Optional	
52 A/F						Mos	29-Aug-2019				
Eff: 09-Nov-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-52-4	**Doors - Installation of Take-Up Reel Rub Block**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-4 Rev 1	**Doors - Installation of Take-Up Reel Rub Block**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-4 Rev 2	**Doors - Installation of Take-Up Reel Rub Block**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-4 Rev 3	**Doors - Installation of Take-Up Reel Rub Block**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-4 Rev 4	**Doors - Installation of Take-Up Reel Rub Block**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-4 Rev 5	**Doors - Installation of Take-Up Reel Rub Block**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Eff: 07-May-2007 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-4 Rev 6	**Doors - Installation of Take-Up Reel Rub Block**							RE (-)		Optional	
52 A/F						Mos	29-Aug-2019				
Eff: 07-Dec-2015 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 12)						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-52-5	**Doors - Passenger/Crew Door Noise Reduction**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-5 Rev 1	**Doors - Passenger/Crew Door Noise Reduction**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-5 Rev 2	**Doors - Passenger/Crew Door Noise Reduction**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-5 Rev 3	**Doors - Passenger/Crew Door Noise Reduction**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-5 Rev 4	**Doors - Passenger/Crew Door Noise Reduction**							RE (-)		Optional	
52 A/F						Mos	29-Aug-2019				
Eff: 14-Jan-2008 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-52-6	**Doors - Lower Entry Door Damper Replacement**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-6 Rev 1	**Doors - Lower Entry Door Damper Replacement**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-6 Rev 2	**Doors - Lower Entry Door Damper Replacement**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-6 Rev 3	**Doors - Lower Entry Door Damper Replacement**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-6 Rev 4	**Doors - Lower Entry Door Damper Replacement**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Eff: 11-Jun-2007 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-7	**Doors - Modification of the Baggage Bay Door Restraint Mechanism**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-7 Rev 1	**Doors - Modification of the Baggage Bay Door Restraint Mechanism**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-52-7 Rev 2	**Doors - Modification of the Baggage Bay Door Restraint Mechanism**							RE (-)		Optional	
52 A/F						Mos	13-Mar-2008				
Eff: 11-Feb-2008 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-52-9	**Doors - Passenger Lower Door Secondary Latch Arm Installation**							RE (-)		Optional	
52 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-52-9 Rev 1	**Doors - Passenger Lower Door Secondary Latch Arm Installation**							RE (-)		Optional	
52 A/F						Mos					
						Hrs					
						Ldg					
45-52-9 Rev 2	**Doors - Passenger Lower Door Secondary Latch Arm Installation**							RE (-)		Optional	
52 A/F						Mos	29-Aug-2019				
Eff: 11-Aug-2008 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
75-52-03	**Doors - Lower Cabin Door Damper and Attachment Modification**							RE (-)		Recommended	
52 A/F						Mos					
Eff: 07-Jul-2020						Hrs					
(AVG MAN HRS: 9)						Ldg					
A5210009	*** Emergency Exit Door Retainers - Perform visual inspection. Inspect door stop fittings on emergency exit door frames in flange radii (FS 374 and 394).**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
52 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 820AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg					
A5210012	*** Lower Passenger Door Hinge - Perform visual inspection. Inspect piano hinge lugs and fasteners.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
52 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 810) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg					
A5210014	*** Upper Passenger Door Tension Fittings - Perform visual inspection. Inspect the following: a.Tension studs at retaining flanges b. Radii around flange periphery.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
52 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 810) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))						Ldg					
AA5210055	**Cabin Door Handle Ramp Roller Wheel - Lubrication**							RE		TLMC 05-13-06	**≈24-Apr-2025**
52 A/F	05-13-06					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Ref:12-21-02 (ZONE: 200) (SOURCE: MM-104, MM-105)						Ldg	3,757				
D5210015	*** Emergency Exit Door - Perform visual inspection. Pay particular attention to flanges and fastener holes of door stop fittings.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
52 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 820AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))						Ldg	2,822				
E5210013	*** Upper and Lower Passenger Door Latch Arms and Door Attachments - Perform visual inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
52 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 810) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F5210016	*** Upper Passenger Door Hinge - Perform visual inspection. Inspect upper surface of hinge fingers at base of lug.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
52 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 810AL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
M5240004	**Avionic Access Doors - Perform Avionics Door Gap and Mismatch Inspection.**							RE		TLMC 05-19-02	
52 A/F						Mos	09-Feb-2024	24	-/+14d	09-Feb-2026	1.7 Years (+14 Days)
						Hrs	5,253.5				
	(ZONE: 200) (SOURCE: MM-104, MM-105)					Ldg	3,757				
N5210010	*** Lower Passenger Door Tension Bolts, Bolt Retainers, Tension Fittings, and Door Attachments - Perform visual inspection.**							RE	TLMC 04-10-01, TLMC 05-14-06, Ch.5 Interval		**≈12-Oct-2025**
52 A/F	05-14-06					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 810) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
N5210011	*** Upper and Lower Passenger Door Latch Pins - Perform visual inspection. Inspect bolts and door end rib structure at lock pins.**							RE	TLMC 04-10-01, TLMC 05-14-06, Ch.5 Interval		**≈12-Oct-2025**
52 A/F	05-14-06					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 810) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
N5210017	*** Upper Passenger Door Tension Bolts, Bolt Retainers, Tension Fittings, and Door Attachments - Perform visual inspection.**							RE	TLMC 04-10-01, TLMC 05-14-06, Ch.5 Interval		**≈12-Oct-2025**
52 A/F	05-14-06					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 810AL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
T5210003	**External Lower Passenger/Crew Door Cables - Perform Visual Inspection of visible portion of cables and handle area.**							RE		TLMC 05-13-06	**≈24-Apr-2025**
52 A/F	05-13-06					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 810) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y5210000	**Avionics Compartment Access Doors and Seals - Perform visual inspection.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
52 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 120/130) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y5210001	**Tailcone Access Door and Seal - Perform visual inspection of door, seals, and latches.**							RE		TLMC 05-12-06	**≈24-Oct-2024**
52 A/F	05-12-06					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 840) (Tol. Adjustment: -31d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y5210002	**Baggage Compartment Door - Perform visual inspection of doors, seals, and latches.**							RE		TLMC 05-12-06	**≈24-Oct-2024**
52 A/F	05-12-06					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 830) (Tol. Adjustment: -31d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y5210004	**Upper and Lower Passenger/Crew Door - Perform Visual Inspection of door structure, tension fittings, and hinge area for cracks and corrosion.**							RE		TLMC 05-13-06	**≈24-Apr-2025**
52 A/F	05-13-06					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 810) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y5210005	**Internal Lower Passenger/Crew Door Cables - Perform Visual Inspection. Remove step skin to gain access to cables.**							RE		TLMC 05-13-06	**≈24-Apr-2025**
52 A/F	05-13-06					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 810BL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y5210006	**Upper Passenger/Crew Door Vent Door Springs - Perform Visual Inspection.**							RE		TLMC 05-12-06	**≈24-Oct-2024**
52 A/F	05-12-06					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 810AL) (Tol. Adjustment: -31d) (SOURCE: MM-104, MM-105)					Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
Y5210008	**Emergency Exit Door Internal and External Handle Latching Mechanism - Perform Operational Check.**							RE		TLMC 05-12-06	**≈24-Oct-2024**
52 A/F	05-12-06					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:52-20-07 (ZONE: 820AR) (Tol. Adjustment: -31d) (SOURCE: MM-104, MM-105)					Ldg	3,757				
Y5240000	**Oxygen System Servicing Door and Latches - Perform visual inspection for condition and security. Check decal for condition and legibility.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
52 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 120BR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y5240003	**Single Point Refueling Access Door - Perform visual inspection.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
52 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 310HR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Z5210053	**Cabin Door Handle - Replace**							RE (N/A)	Replacement Schedule, TLMC 05-19-01		
52 A/F						Mos	25-Jun-2021				
						Hrs	4,694.8				
	(ZONE: 810AL) (Tol. Adjustment: -56d) (SOURCE: MM-104)					Ldg	2,882				
Z5210053	**Cabin Door Handle Ramp Kit**							RE (-)			
52 A/F		0	0	0		Mos	25-Jun-2021				
AR51410-1 NSN	New	0	0	0		Hrs	4,694.8				
		0	0	0		Ldg	2,882				
(APX COST: 0)											
▼ 53 - FUSELAGE											
	Bulkhead Assembly, Pressure, Aft							RE (O/C)			
53 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Delta, Fin							RE (O/C)			
53 A/F	Left	0				Mos	13-Mar-2008				
4555501000-015 A0221	New	0				Hrs	0				
		0				Ldg	0				
	Delta, Fin							RE (O/C)			
53 A/F	Right	0				Mos	13-Mar-2008				
4555501000-016 A0229	New	0				Hrs	0				
		0				Ldg	0				
	End Rods - Tie Rod Assembly							RE (O/C)			
53 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	End Rods - Tie Rod Assembly							RE (O/C)			
53 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Fuselage Assembly							RE (O/C)			
53 A/F		0				Mos	13-Mar-2008				
4553000010-001 L359	New	0				Hrs	0				
		0				Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Radome							RE (O/C)			
53 A/F				1		Mos	04-Apr-2018				
6634408000-005						Hrs	4,195.1				
527						Ldg	2,469				
2015-12-06	**Fuselage**							RE (-)		Mandatory	
53 A/F						Mos	07-Jul-2015				
Eff: 21-Jul-2015 Complied With						Hrs	3,528.4				
						Ldg	2,053				
2015-12-06 Paragraph (g)	**Fuselage - Inspections and Corrective Actions**							RE (-)		Mandatory	
53 A/F						Mos	07-Jul-2015				
Eff: 21-Jul-2015 Complied With	S/B 45-56-3R1 ON MAR-1-2013					Hrs	3,528.4				
						Ldg	2,053				
2015-12-06 Paragraph (h)	**Fuselage - Maintenance/Inspection Program Revision**							RE (-)		Mandatory	
53 A/F						Mos	19-Jun-2015				
Eff: 21-Jul-2015 Complied With						Hrs	3,518.6				
						Ldg	2,047				
2017-11-09	**Fuselage - Upper Fuselage Skin Corrosion - Inspect/ Report (This AD supersedes (AD) 2017-08-07) (This AD has been replaced by AD 2019-17-01)**							RE (-)		Mandatory	
53 A/F						Mos					
Eff: 30-May-2017						Hrs					
(AVG MAN HRS: 47)						Ldg					
45-53-1	**Fuselage - Installation of Flame Retardant Tape on Cabin Floor Panels**							RE (-)		Recommended	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-1 Rev 1	**Fuselage - Installation of Flame Retardant Tape on Cabin Floor Panels**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 18-Mar-1999 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-10	**Fuselage - Modification of Starter/Generator Ground Bracket**							RE (-)		Recommended	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-10 Rev 1	**Fuselage - Modification of Starter/Generator Ground Bracket**							RE (-)		Recommended	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-10 Rev 2	**Fuselage - Modification of Starter/Generator Ground Bracket**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 24-Sep-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-11	**Fuselage - Inspection/Repair of Coupe Rail**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 11-Jul-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-12	**Fuselage - Inspection/Repair of the Seat Rail and Floorboard Corrosion**							RE (-)		Recommended	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-53-12 Rev 1	**Fuselage - Inspection/Repair of the Seat Rail and Floorboard Corrosion**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 11-Dec-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-13	**Modification of Engine Pylon Starter/Generator Ground Strap**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 24-Sep-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-14	**Fuselage - Reinforcement and Repair of the Seat Track Shear Webs**							RE (-)		Optional	
53 A/F						Mos					
						Hrs					
						Ldg					
45-53-14 Rev 1	**Fuselage - Reinforcement and Repair of the Seat Track Shear Webs**							RE (-)		Optional	
53 A/F						Mos					
						Hrs					
						Ldg					
45-53-14 Rev 2	**Fuselage - Reinforcement and Repair of the Seat Track Shear Webs**							T (A/R)		Optional	
53 A/F						Mos					
Eff: 23-Jun-2008						Hrs					
						Ldg					
45-53-15	**Fuselage - Inspection of AFT Pressure Bulkhead for Corrosion**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 22-Dec-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-16	**Fuselage - Installation of Drain Holes in the Tailcone**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 13-Sep-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-17	**Fuselage - Replacement of Hi-Lite Collars in the Flight Deck Assembly, Windshield and Canopy**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-17 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Flight Deck Assembly, Windshield and Canopy**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-17 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Flight Deck Assembly, Windshield and Canopy**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-18	**Fuselage - Replacement of Hi-Lite Collars in the Flight Deck Assembly, Windshield Structure**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-18 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Flight Deck Assembly, Windshield Structure**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-18 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Flight Deck Assembly, Windshield Structure**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-53-19	**Fuselage - Replacement of Hi-Lite Collars in the Lower Flight Deck, Pitot Static Tube Structure, Left and Right Sides**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-19 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Lower Flight Deck, Pitot Static Tube Structure, Left and Right Sides**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-19 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Lower Flight Deck, Pitot Static Tube Structure, Left and Right Sides**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-2	**Fuselage - Installation of Rivets in Tailcone Structure**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 30-Apr-1999 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-20	**Fuselage - Replacement of Hi-Lite Collars in the Aft Cabin, Nose-Constant-Fuel Cell**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-20 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Aft Cabin, Nose-Constant-Fuel Cell**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-20 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Aft Cabin, Nose-Constant-Fuel Cell**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-21	**Fuselage - Replacement of Hi-Lite Collars in Aft Cabin, Aux Pressure Skin Assembly**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-21 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in Aft Cabin, Aux Pressure Skin Assembly**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-21 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in Aft Cabin, Aux Pressure Skin Assembly**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-22	**Fuselage - Replacement of Hi-Lite Collars in the Forward Engine Beam Assembly, External of the Fuselage, Left and Right Sides**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-22 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Forward Engine Beam Assembly, External of the Fuselage, Left and Right Sides**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-22 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Forward Engine Beam Assembly, External of the Fuselage, Left and Right Sides**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-53-22 Rev 3	**Fuselage - Replacement of Hi-Lite Collars in the Forward Engine Beam Assembly, External of the Fuselage, Left and Right Sides**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-23	**Fuselage - Replacement of Hi-Lite Collars in the Forward Engine Beam Drag Strut Fitting, Baggage Bay Structure**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-23 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Forward Engine Beam Drag Strut Fitting, Baggage Bay Structure**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-23 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Forward Engine Beam Drag Strut Fitting, Baggage Bay Structure**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-24	**Fuselage - Replacement of Hi-Lite Collars in the Aft Lower Fuel Cell Canted Bulkhead-Frame Structure**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-24 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Aft Lower Fuel Cell Canted Bulkhead-Frame Structure**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-24 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Aft Lower Fuel Cell Canted Bulkhead-Frame Structure**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-25	**Fuselage - Replacement of Hi-Lite Collars in the Forward and Aft Fuel Cell Bay Structure (Subpart 1)**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-25 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Forward and Aft Fuel Cell Bay Structure (Subpart 1)**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-25 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Forward and Aft Fuel Cell Bay Structure (Subpart 1)**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-26	**Fuselage - Replacement of Hi-Lite Collars in the Lower Panel Assembly Fuel Cell Structure (Subpart 1)**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-26 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Lower Panel Assembly Fuel Cell Structure (Subpart 1)**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-26 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Lower Panel Assembly Fuel Cell Structure (Subpart 1)**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-53-27	**Fuselage - Replacement of Hi-Lite Collars in the Forward and Aft Fuel Cell Bay Structure (Subpart 2)**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-27 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Forward and Aft Fuel Cell Bay Structure (Subpart 2)**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-27 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Forward and Aft Fuel Cell Bay Structure (Subpart 2)**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-28	**Fuselage - Replacement of Hi-Lite Collars in the Lower Panel Assembly Fuel Cell Structure (Subpart 2 and 3)**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-28 Rev 1	**Fuselage - Replacement of Hi-Lite Collars in the Lower Panel Assembly Fuel Cell Structure (Subpart 2 and 3)**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-28 Rev 2	**Fuselage - Replacement of Hi-Lite Collars in the Lower Panel Assembly Fuel Cell Structure (Subpart 2 and 3)**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-29	**Fuselage - Inspection/Replacement of Hi-Lite Collars in the Forward Engine Beam Assembly, External of the Fuselage, Left and Right Sides**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-3	**Fuselage - Installation of Fuel Filler Grounding Bracket**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-3 Rev 1	**Fuselage - Installation of Fuel Filler Grounding Bracket**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-3 Rev 2	**Fuselage - Installation of Fuel Filler Grounding Bracket**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-3 Rev 3	**Fuselage - Installation of Fuel Filler Grounding Bracket**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Eff: 11-Jun-2004 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-30	**Fuselage - Repair of Cracking and Gaps at Frame 2**							RE (-)		Optional	
53 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-53-30 Rev 1	**Fuselage - Repair of Cracking and Gaps at Frame 2**							RE (-)		Optional	
53 A/F						Mos					
						Hrs					
						Ldg					
45-53-30 Rev 2	**Fuselage - Repair of Cracking and Gaps at Frame 2**							RE (-)		Optional	
53 A/F						Mos	29-Aug-2019				
Eff: 22-Mar-2010 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-53-31	**Fuselage - Fuel Cell Access Panel Installation**							RE (-)		Optional	
53 A/F						Mos					
Eff: 13-Sep-2010						Hrs					
						Ldg					
45-53-32	**Fuselage - Single Point Pressure Refueling Door Latch Improvement**							RE (-)		Recommended	
53 A/F						Mos	30-Jul-2010				
Eff: 26-Apr-2010 Complied With						Hrs	1,499.8				
(AVG MAN HRS: 4.5)						Ldg	910				
45-53-33	**Fuselage - Single Point Pressure Refueling Door Striker Plate Installation**							RE (-)		Optional	
53 A/F						Mos	30-Jul-2010				
Complied With						Hrs	1,499.8				
						Ldg	910				
45-53-33 Rev 1	**Fuselage - Single Point Pressure Refueling Door Striker Plate Installation**							RE (-)		Optional	
53 A/F						Mos	09-May-2011				
Complied With						Hrs	1,961				
						Ldg	1,176				
45-53-33 Rev 2	**Fuselage - Single Point Pressure Refueling Door Striker Plate Installation**							T (-)		Optional	
53 A/F						Mos					
Eff: 20-Jun-2011						Hrs					
						Ldg					
45-53-33 Rev 3	**Fuselage - Single Point Pressure Refueling Door Striker Plate Installation**							RE (-)		Optional	
53 A/F						Mos	10-Jan-2020				
Eff: 30-May-2017 Not Applicable						Hrs	4,590.8				
(AVG MAN HRS: 10)						Ldg	2,807				
45-53-34	**Fuselage - Emergency Battery Access Improvement**							RE (-)		Optional	
53 A/F						Mos					
						Hrs					
						Ldg					
45-53-34 Rev 1	**Fuselage - Emergency Battery Access Improvement**							T (A/R)		Optional	
53 A/F						Mos					
Eff: 25-Mar-2013						Hrs					
						Ldg					
45-53-35	**Fuselage - LH Overwing Fairing Modification**							RE (-)		Recommended	
53 A/F						Mos	19-Mar-2015				
Eff: 23-Feb-2015 Complied With	FUSELAGE L/H OVERWING FAIRING MOD					Hrs	3,423.5				
						Ldg	1,995				
(AVG MAN HRS: 15) (NOTE: at the next 2400 flight hour inspection or within 12 months from the initial distribution date of this publication.)											
45-53-35 Rev 1	**Fuselage - LH Overwing Fairing Modification**							RE (-)		Recommended	
53 A/F						Mos	10-Jan-2020				
Eff: 23-Feb-2015 Not Applicable						Hrs	4,590.8				
(AVG MAN HRS: 15)						Ldg	2,807				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-53-36	**Single Point Pressure Refuelling (SPPR) Door Latch Plate Replacement Accessory Kit**							T (-)		Optional	
53 A/F						Mos					
Eff: 16-Jan-2017						Hrs					
(AVG MAN HRS: 5.5)						Ldg					
45-53-36 Rev 1	**Single Point Pressure Refuelling (SPPR) Door Latch Plate Replacement Accessory Kit**							T (A/R)		Recommended	
53 A/F						Mos					
Eff: 04-Feb-2019						Hrs					
(AVG MAN HRS: 5.5)						Ldg					
45-53-37	**Fuselage - Lower Quadrant Bulkhead Fastener Inspection**							RE (-)		Recommended	
53 A/F						Mos					
Eff: 19-Mar-2018 Deferred	TASK SUPPRESSED PER BOB FOX; WILL NOT ACCOMPLISH ANY TIME SOON					Hrs					
(AVG MAN HRS: 4) (NOTE: NOTE: This Service Bulletin is effective for aircraft not enrolled in the Learjet evolved maintenance program.)						Ldg					
45-53-4	**Fuselage - Installation of Entry Door Gutter**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-4 Rev 1	**Fuselage - Installation of Entry Door Gutter**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-4 Rev 2	**Fuselage - Installation of Entry Door Gutter**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-4 Rev 3	**Fuselage - Installation of Entry Door Gutter**							RE (-)		Optional	
53 A/F						Mos	13-Mar-2008				
Eff: 12-Oct-2001 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-5	**Fuselage - Installation of Improved Single Point Pressure Refueling (SPPR) Door**							RE (-)		Recommended	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-5 Rev 1	**Fuselage - Installation of Improved Single Point Pressure Refueling (SPPR) Door**							RE (-)		Recommended	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-5 Rev 2	**Fuselage - Installation of Improved Single Point Pressure Refueling (SPPR) Door**							RE (-)		Recommended	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-53-5 Rev 3	**Fuselage - Installation of Improved Single Point Pressure Refueling (SPPR) Door**							RE (-)		Recommended	
53 A/F						Mos	14-Dec-2020				
Eff: 15-Feb-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-53-8	**Fuselage - Modification of Nose Landing Gear Aft Access Panel**							RE (-)		Recommended	
53 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-53-8 Rev 1	**Fuselage - Modification of Nose Landing Gear Aft Access Panel**							RE (-)		Recommended	
53 A/F	Eff: 14-Jun-2002 Not Applicable					Mos	14-Dec-2020				
						Hrs	4,610.5				
						Ldg	2,822				
45-53-9	**Fuselage - Installation of Moisture Drains in the Forward Belly Fairings**							RE (-)		Recommended	
53 A/F	Not Applicable BY SERIAL NUMBER					Mos	13-Mar-2008				
						Hrs	8.7				
						Ldg	8				
45-53-9 Rev 1	**Fuselage - Installation of Moisture Drains in the Forward Belly Fairings**							RE (-)		Recommended	
53 A/F	Not Applicable BY SERIAL NUMBER					Mos	13-Mar-2008				
						Hrs	8.7				
						Ldg	8				
45-53-9 Rev 2	**Fuselage - Installation of Moisture Drains in the Forward Belly Fairings**							RE (-)		Recommended	
53 A/F	Eff: 17-May-2002 Not Applicable					Mos	14-Dec-2020				
						Hrs	4,610.5				
						Ldg	2,822				
A5310005	*** Fuselage Fuel Cell Canted Bulkhead (FS 495) - Perform visual inspection, paying particular attention to main crossmember. Inspect flanges and attachments for cracking.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 360) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))					Ldg	2,822				
A5310007	*** Aft Pressure Bulkhead Bottom Shear Diaphragm - Perform Detailed Visual Inspection. Inspect bulkhead post attachment fastener holes and control cable slot.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 270) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))					Ldg					
A5323022	*** Nose Landing Gear Aft Wheelbox Closing Structure (FS 150 to FS 162) - Perform Visual Inspection. Inspect the following: a. Panel b. Channel Stiffeners c. Support Angle d. Angle Stiffener e. Zee Stiffener.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 710AL, 710AR) (SOURCE: MM-104) (NOTE: (Refer to 5-10- 00.))					Ldg					
A5323023	*** Drag Link Attachment Lug - Perform visual inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 250DL, 250ER) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))					Ldg	2,822				
A5360001	**Delta Fins - With delta fins removed, visually inspect the following: a. Delta fin aft spar. b. Delta fin support angle. c. Inspect stiffeners connecting to attach fittings.**							RE		TLMC 05-16-00	**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600	-/+25	(9,600)	4,325.2 Hrs (+25)
	Alias1:5-10-00 (ZONE: 320DL, 320EL, 320CR, 320DR, 840AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))					Ldg					
D5323039	*** Machined Fuselage Frame at FS 466 - Perform detailed visual inspection of the lower frame section between stringer 13 left and right, paying particular attention to the BL 10 splices. Confirm any crack indications with eddy current procedures.**							RE (N/A)	TLMC 04-10-01, TLMC 05-15-00		
53 A/F						Mos	14-Dec-2020				
						Hrs	4,610.5				
	Alias1:5-10-00 (ZONE: 230) (SOURCE: MM-104)					Ldg	2,822				
E5310001	*** Longeron, Internal (between FS 384 and FS 433) - Perform visual inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 230CL, 230DL, 230EL, 230CR, 230DR, 230ER) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
E5310002	*** Flight Deck Longeron (FS 149 - FS 196) - Perform visual inspection. Inspect flight deck longeron stiffeners, webs, and cutouts.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 220AL, 220BL, 220DL, 220AR, 220BR, 220DR) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Ldg					
E5310017	*** Aft Pressure Bulkhead Bottom Crossmember (FS 457) - Perform Detailed Visual Inspection. Inspect tee-section at FS 457 flange at attachment to pressure floor.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 270) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5310018	*** Aft Pressure Bulkhead Panel Facing Sheets (FS 457) - Perform visual inspection. Inspect both front and aft of facing sheets.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 270) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5323025	*** Forward/Aft Wheelbox Joint (FS 150) - Perform visual inspection. Inspect splice strap aft of forward pressure bulkhead at intersection of attachment angle and flight deck longeron.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Ldg					
E5323050	*** Aft Post/Windshield Retainer Attachment - Perform Eddy Current Inspection. Inspect windshield aft post at windshield retainer fastener holes.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-04 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-04.))					Ldg	2,822				
E5323053	*** Frame Attachments to Upper and Lower Coupe Rails (FS 171 to FS 204) - Perform visual inspection. Inspect the following: a. Frame attachments to lower coupe rails at FS 171, FS 182, FS 196, and FS 204. b. Frame attachments to upper coupe rails at FS 196 and FS 204. c. Gussets at fastener holes.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Ldg					
E5323054	*** Tie-Rod Assembly (FS 162) (Aluminum ends) - Perform visual inspection. Inspect tie-rod ends, tie-rod tubes, and tie-rod bolts.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
E5323055	*** Tie-Rod Assembly (FS 162) (Titanium ends) - Perform visual inspection. Inspect tie-rod ends, tie-rod tubes, and tie-rod bolts.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.))					Ldg					
E5323068	*** Stringer 1 RH between FS 533 and FS 543 - Perform visual inspection. Inspect stringer 1 flange and skin along stringer 1 between FS 533 and FS 543.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 310) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5323073	*** Fuselage Bottom Skin Panel - Perform visual inspection. Inspect corner radius at junction of external longeron and mid spar frame (FS 435).**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
E5323074		*** Auxiliary Skin Panel - Perform visual inspection. Inspect corner radius at junction of keelbeam and rear spar frame (FS 466).**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	53 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5350000		*** Bottom Keelbeam End Pads (FS 384 - FS 486) - Perform visual inspection. Inspect end pads around bolt holes and in radii at FS 433.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	53 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:5-10-00 (ZONE: 240) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
F5323056		*** Tie-Rod Fork Ends (Aluminum) - Perform Fluorescent Penetrant Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-15-00		
	53 A/F						Mos	14-Dec-2020				
							Hrs	4,610.5				
		Alias1:53-10-01 (ZONE: 220) (SOURCE: MM-104)					Ldg	2,822				
F5323081		*** Tie-Rod Fork Ends (Titanium, P/N R24889) - Perform Fluorescent Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	53 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:53-10-01 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 8, 53-10-01.) (Effective on Aircraft 45-059 and Subsequent and prior Aircraft with titanium rod assembly installed.))					Ldg					
F5331021		*** Forward Canted Bulkhead (FS 630) - Perform visual inspection. Inspect at front spar upper attachment fasteners.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
	53 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Alias1:5-10-00 (ZONE: 320CL, 320BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
F5331022		*** Mid Canted Bulkhead (FS 657) - Perform visual inspection at mid spar upper attachment fasteners.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	53 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:5-10-00 (ZONE: 320DL, 320CR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
F5331023		*** Aft Canted Bulkhead (FS 682) - Perform visual inspection. Inspect at rear spar attachment fasteners.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	53 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:5-10-00 (ZONE: 320BL, 320EL, 320DR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
F5331024		*** Vertical Stabilizer Front Spar Root Bulkhead Attachment (FS 630) - Perform visual inspection. Inspect front spar root bulkhead attachment at fastener holes.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	53 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:5-10-00 (ZONE: 320) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
F5331025		*** Vertical Stabilizer Mid Spar Root Bulkhead Attachment (FS 657) - Perform visual inspection. Inspect mid spar root bulkhead attachment at fastener holes.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	53 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:5-10-00 (ZONE: 320) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
F5331026		*** Vertical Stabilizer Rear Spar Root Bulkhead Attachment (FS 682) - Perform visual inspection. Inspect rear spar root bulkhead attachment at fastener holes.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	53 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:5-10-00 (ZONE: 320) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
H5323032	*** Exterior Cabin Window Coamings (Unpainted) - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00, Ch.5 Interval		
53 A/F						Mos	09-Feb-2024	24		09-Feb-2026	1.7 Years
						Hrs	5,253.5	2,400		7,653.5	2,378.7 Hrs
Alias1:56-20-01 (ZONE: 230) (SOURCE: MM-104, MM-105)						Ldg	3,757				
H5323092	*** Exterior Cabin Window Coamings (Painted) - Perform Eddy Current Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
53 A/F						Mos					
						Hrs					
Alias1:56-20-01 (ZONE: 230) (SOURCE: MM-104, MM-105) (NOTE: For Unpainted Coamings Only)						Ldg					
L5311002	*** Nose Landing Gear Actuator Attachment on Forward Pressure Bulkhead - Perform Eddy Current Inspection. Inspect actuator attachment bracket lugs, radii, and fastener holes.**							RE	TLMC 04-10-01, TLMC 05-17-00, Ch.5 Interval		**≈12-Dec-2029**
53 A/F	05-17-00					Mos					
						Hrs					
NDI Part 6:32-12-00 (ZONE: 210) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 32-12-00.))						Ldg		10,000		(10,000)	6,728 Ldg (+25)
L5311004	*** Nose Landing Gear Trunnion Fittings - Perform visual inspection of the trunnion fittings and attachment bolts.**							RE	TLMC 04-10-01, TLMC 05-17-00, Ch.5 Interval		**≈12-Dec-2029**
53 A/F	05-17-00					Mos					
						Hrs					
Alias1:5-10-00 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))						Ldg		10,000		(10,000)	6,728 Ldg (+25)
L5311005	*** Nose Landing Gear Trunnion Fittings and Support Structure - Perform Eddy Current Inspection of the trunnion support structure at the forward pressure bulkhead flange.**							RE	TLMC 04-10-01, TLMC 05-17-00, Ch.5 Interval		**≈12-Dec-2029**
53 A/F	05-17-00					Mos					
						Hrs					
NDI Part 6:32-12-05 (ZONE: 710) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104] Part 6, 32-12-05.))						Ldg		10,000		(10,000)	6,728 Ldg (+25)
M5313001	**Forward Fuselage Skin - Perform Pitot-Static Probe Zone Skin Contour Check.**							RE		TLMC 05-19-02	
53 A/F						Mos	09-Feb-2024	24	-/+14d	09-Feb-2026	1.7 Years (+14 Days)
						Hrs	5,253.5				
(ZONE: 200) (SOURCE: MM-104, MM-105)						Ldg	3,757				
M5323021	*** External longeron, fastener locations, and area around wing attachments - Perform Visual Inspection. Inspect longeron between FS 398 and FS 486, stringer 13 LHS & RHS.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 250DL, 250ER) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg					
M5323034	*** Upper and Lower Coupe Rail and Center Post/ Windshield Retainer Attachment - Perform Eddy Current inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:53-30-03 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI- 104], Part 6, 53-30-03.))						Ldg					
N5314000	*** Emergency Exit Door Skin Cutout Corners and Doublers (FS 370 - FS 398) - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-01, Ch.5 Interval		**≈12-Oct-2025**
53 A/F	05-14-01					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
Alias1:53-30-01 (ZONE: 820) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 53-30-01.))						Ldg	2,822				
N5323026	*** Upper and Lower Passenger/Crew Door Skin Cutout Corners (FS 224 - FS 256) - Perform Eddy Current Inspection. Inspect skin at corners of passenger/crew door cutout.**							RE	TLMC 04-10-01, TLMC 05-14-01, Ch.5 Interval		**≈12-Oct-2025**
53 A/F	05-14-01					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
Alias1:53-30-02 (ZONE: 230) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 53-30-02.))						Ldg	2,822				
P5310003	*** Aft Pressure Bulkhead Support Post (FS 457) - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:53-30-18 (ZONE: 270BC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-18.))						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P5310004	*** Aft Pressure Bulkhead Frame Periphery - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-21 (ZONE: 270) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-21.))					Ldg	2,822				
P5310006	*** Forward Pressure Bulkhead - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:53-30-07 (ZONE: 120AR, 130AL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI- 104], Part 6, 53-30-07.))					Ldg					
P5320001	*** Fuselage Pressure Floor Step (FS 433 - FS 457) - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:53-20-01 (ZONE: 230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-20-01.))					Ldg					
P5323024	*** Fuselage Skin Cut-outs Above Fuel Cell - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-12 (ZONE: 310AC, 310BC, 310AL, 310BL, 310AR, 310BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-12.))					Ldg	2,822				
P5323027	*** Fuselage Frame at F.S. 412 - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-20 (ZONE: 230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI- 104], Part 6, 53-30-20.))					Ldg	2,822				
P5323029	*** Machined Spar Frames Systems Cutouts (FS 398, FS 412, FS 432, FS 466) - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-15 (ZONE: 230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI- 104], Part 6, 53-30-15.))					Ldg	2,822				
P5323033	*** Fuselage Skin at Emergency Door Egress Light and Wing Inspection Light - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:53-40-02 (ZONE: 230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-40-02.))					Ldg					
P5323037	*** Windshield Coupe Rail Tie Rod Bracket - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:53-30-09 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-09.))					Ldg					
P5323038	*** Windshield Centerpost to Upper Coupe Rail Joint Attachment - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-22 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 53-30-22.))					Ldg	2,822				
P5323047	*** Pressure Cabin Fuselage Crown Skin - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-01, Ch.5 Interval		**≈12-Oct-2025**
53 A/F	05-14-01					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:53-10-04 (ZONE: 220/230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104] Part 6, 53-10-04.))					Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P5323049	*** Fuselage Skin at Upper and Lower Coupe Rail Run-out Joints - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:53-30-11 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53- 30-11.))					Ldg					
P5323057	*** Pressure Cabin Skin at Fuselage Station 451 - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-01, Ch.5 Interval		**≈12-Oct-2025**
53 A/F	05-14-01					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:53-30-06 (ZONE: 220/230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104] Part 6, 53-30-06.))					Ldg	2,822				
P5323058	*** Fuselage Skin at F.S. 504 - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-13 (ZONE: 220/230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-13.))					Ldg	2,822				
P5323069	*** Circumferential Skin Joint at Forward Pressure Bulkhead - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:53-30-08 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30- 08.))					Ldg					
P5323164	*** Fuselage Skin and Doubler around ECS Duct Cutout - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:53-40-01 (ZONE: 200) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-40-01.))					Ldg					
P5323165	*** Windshield Center Post to Lower Coupe Rail Joint Attachment - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:53-30-10 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-10.))					Ldg					
P5360006	**Delta Fin Attach Bolt - Perform Liquid Penetrant Inspection.**							RE		TLMC 05-16-00	**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600	-/+25	(9,600)	4,325.2 Hrs (+25)
	Alias1:53-10-02 (ZONE: 320DL, 320EL, 320CR, 320DR, 840AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 8, 53-10-02.))					Ldg					
Q5310023	**Forward and Aft Fuel Cell Bay Structure, Angle Reinforcement, Stringer 1, LH & RH - Perform Detailed Visual Inspection of Hi-Lite Collars.**							RE		TLMC 05-16-00	**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600	-/+25	(9,600)	4,325.2 Hrs (+25)
	(ZONE: 300) (SOURCE: MM-104, MM-105) (NOTE: (Refer to Learjet Document RSIP-HST79-104-2.) Note: Instructions defining criteria for the inspection can be found on the CIC Website under Technical Library, General Publications, Learjet 45, Repetitive Special In-spection Program Hi-Lite HST79 Collars.)					Ldg					
Q5310025	**Aft Fuselage Keelbeam Longeron (LH & RH, BL 5.15, FS 466.30 - 495.12) and Aft Fuselage Keel- beam Lower Frame (FS 466.30, BL 9.55 LH thru BL 9.55 RH) - Perform Detailed Visual Inspection of Hi-Lite Collars.**							RE		TLMC 05-16-00	**≈10-Dec-2027**
53 A/F	05-16-00					Mos					
						Hrs		9,600	-/+25	(9,600)	4,325.2 Hrs (+25)
	(ZONE: 200) (SOURCE: MM-104, MM-105) (NOTE: (Refer to Learjet Document RSIP-HST79-104-3.) Note: Instructions defining criteria for the inspection can be found on the CIC Website under Technical Library, General Publications, Learjet 45, Repetitive Special Inspection Program Hi-Lite HST79 Collars.)					Ldg					
Q5323048	*** Fuselage (Pressure Cabin) - Perform Eddy Current Inspection. Inspect pressure cabin skin (longitudinal skin cracking).**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-05 (ZONE: 220/230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30- 05.))					Ldg	2,822				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
Q5323051		*** Longitudinal Joints inside Pressure Cabin (FS 220 - FS 457) and skin within one stringer bay of joint - Perform Eddy Current inspection. Inspect skin fastener holes along joints at stringer 10 LH and RH, stringer 2 RH, and stringer 18 RH.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F		05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Alias1:53-30-05 (ZONE: 220/230) (SOURCE: MM-104) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30- 05.))					Ldg	2,822				
Q5323059		*** Stringer to Frame Joints (FS 162 to FS 213) - Perform Eddy Current Inspection. Inspect skin, stringers, and frames at joints.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F		05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:53-30-05 (ZONE: 220) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 53-30- 05.))					Ldg					
T5310027		*** Aft Pressure Bulkhead Top Mounting Structure - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
53 A/F		05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:53-30-17 (ZONE: 270BC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-17.))					Ldg					
T5321089		**Seat Rails - Perform Detailed Inspection of Seat Rail (track) Shear Webs for cracking.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
53 A/F		05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
							Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
		Alias1:53-20-01 (ZONE: 230AC, 230BC, 230CC) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 53-20-01). (Effective on Aircraft 45-005 thru 45-394 not modified per SB 45-53-14 "Fuselage - Reinforcement and Repair of the Seat Track Shear Webs".))					Ldg	3,757				
T5323028		*** Fuselage to Wing Attach Fittings - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
53 A/F		05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Alias1:53-30-16 (ZONE: 250/ 310DL, 310LR, 360AL, 360AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI- 104], Part 6, 53-30-16.) Note: Initial inspection to be performed at 9,600 flight hours, and subsequent inspections performed every 4,800 flight hours thereafter.)					Ldg	2,822				
T5323166		*** External Skin Cut-outs/Penetrations (Pressure Cabin) - Perform Detailed Visual Inspection. Inspect skin and doublers at antennas, electrical components, and access panels (excluding pitot/ static probes, AOA stall vanes, and wing inspection light).**							RE	TLMC 04-10-01, TLMC 05-19-00, Ch.5 Interval		**≈12-Oct-2031**
53 A/F							Yrs	22-May-2020	12		22-May-2032	8 Years
							Hrs	4,593.2	9,600		14,193.2	8,918.4 Hrs
		Alias1:5-10-00 (ZONE: 200) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) Note: Removal of antennas, electrical components and access panels is necessary for completion of this inspection. On Aircraft that have exceeded 12 years from C of A, perform inspection within 12 months from September 20, 2010.)					Ldg	2,809				
U5323167		*** Left Coupe Rails (P/N 4553002003V7000-001, 4553002003V7001-002) - Replace.**							RE (N/A)	TLMC 04-11-00, TLMC 05-19-01		
53 A/F							Mos	01-Mar-2013				
							Hrs	2,753.9				
		(ZONE: 220) (SOURCE: MM-104, MM-105)					Ldg	1,625				
U5323167		*** Right Coupe Rails (P/N 4553002003V7000-001, 4553002003V7001-002) - Replace.**							RE (N/A)	TLMC 04-11-00, TLMC 05-19-01		
53 A/F							Mos	01-Mar-2013				
							Hrs	2,753.9				
		(ZONE: 220) (SOURCE: MM-104, MM-105)					Ldg	1,625				
V5323168		*** LH & RH Lower Coupe Rail Radius/Windscreen Retainer Attach (P/N's 4553130001-802 thru 4553130001-809) - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈26-May-2026**
53 A/F							Mos	01-Mar-2013				
							Hrs	2,753.9	5,000		7,753.9	2,479.1 Hrs
		Alias1:53-30-23, 53-30-24 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-23 & 53-30 -24.) (Effective on aircraft that have complied with SB 45-56-03, "Windows - Windshield Coupe Rail Inspections."))					Ldg	1,625				
Y5311001		**Nose Landing Gear Actuator Attach Fitting and Surrounding Structure - Perform Visual Inspection.**							RE		TLMC 05-13-05	**≈24-Apr-2025**
53 A/F		05-13-05					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
							Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
		Alias1:5-10-00 (ZONE: 710) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y5311003	**Nose Landing Gear Trunnion Fitting and Surrounding Structure - Perform Visual Inspection.**							RE		TLMC 05-13-05	**≈24-Apr-2025**
53 A/F	05-13-05					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 710) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y5320000	**Center Pedestal - Perform visual inspection.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
53 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y5321010	**Floorboards around Galley, Lavatory, and Water Tank - Perform Visual Inspection.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
53 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00, Ref:53-20-01 (ZONE: 230/240/ 260) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
	Note: If evidence of spillage is visible, perform inspection of the Galley and Lavatory areas for spills and corrosion. (Refer to 53-20-01.))					Ldg	3,757				
Y5321011	**Tailcone Baggage Compartment - Perform visual inspection.**							RE		TLMC 05-12-02	**≈24-Oct-2024**
53 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 310) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y5321088	**Seat Rails - Remove floorboard 230AL and perform visual inspection of seat rails.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
53 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	(ZONE: 230AL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: Note: If corrosion is detected, remove all floorboards and inspect all seat rails.)					Ldg	3,757				
Y5323020	**External Fuselage (Pressure Cabin) - Perform visual inspection of all cabin skins from F.S. 100 to F.S.458.(Refer to 5-10-00.) Pay particular attention to all cutouts and skin joints. No fairing access required.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
53 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (Tol. Adjustment: -30d) (SOURCE: MM-104)					Ldg	3,757				
Y5323031	**Exterior Cabin Window Coamings and Surrounding Fuselage Skin - Perform visual inspection using 10X magnification and adequate lighting.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
53 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 230) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y5340007	**Wing Attach Fittings - Perform visual inspection.**							RE		TLMC 05-14-01	**≈12-Oct-2025**
53 A/F	05-14-01					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 250DL, 250ER) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
Y5360000	**Delta Fins - Perform visual inspection.**							RE		TLMC 05-12-02	**≈24-Oct-2024**
53 A/F	05-12-02					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 320) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Z5323172	*** Skin Cut-Out for Iridium Antennas FS283.88 to FS308.39 - Perform Eddy Current Inspection**							RE (N/A)	TLMC 04-10-01, TLMC 05-15-00		
53 A/F						Mos	14-Dec-2020				
						Hrs	4,610.5				
	Ref:NDI-104, Part 6, 53-10-05 (ZONE: 200) (SOURCE: MM-104)					Ldg	2,822				
▼ 54 - NACELLES/PYLONS											
2007-17-17	**Unsealed gaps on the pylon side of the engine firewall**							RE (-)		Mandatory	
54 A/F						Mos	11-Feb-2010				
Eff: 02-Oct-2007 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
						Ldg	739				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-54-1		**Nacelles/Pylons - Application of Pylon Trailing Edge Firewall Sealant - Superseded by SB45-54-3**							RE (-)		Recommended	
54 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-54-1 Rev 1		**Nacelles/Pylons - Application of Pylon Trailing Edge Firewall Sealant - Superseded by SB45-54-3**							RE (-)		Recommended	
54 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-54-1 Rev 2		**Nacelles/Pylons - Application of Pylon Trailing Edge Firewall Sealant - Superseded by SB45-54-3**							RE (-)		Recommended	
54 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-54-1 Rev 3		**Nacelles/Pylons - Application of Pylon Trailing Edge Firewall Sealant - Superseded by SB45-54-3**							RE (-)		Recommended	
54 A/F							Mos	14-Dec-2020				
Eff: 13-Jul-2001 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-54-2		**Superceded by SB45-54-5**							RE (-)		Recommended	
54 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-54-2 Rev 1		**Superceded by SB45-54-5**							RE (-)		Recommended	
54 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-54-2 Rev 2		**Superceded by SB45-54-5**							RE (-)		Recommended	
54 A/F							Mos	14-Dec-2020				
Eff: 20-Oct-2005 Not Applicable		SUPERSEDED BY SB 45-54-5					Hrs	4,610.5				
							Ldg	2,822				
45-54-3		**Nacelles/Pylons - Firewall Sealing Modification/Application of Pylon Trailing Edge Sealant**							RE (-)		Recommended	
54 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-54-3 Rev 1		**Nacelles/Pylons - Firewall Sealing Modification/Application of Pylon Trailing Edge Sealant**							RE (-)		Recommended	
54 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-54-3 Rev 2		**Nacelles/Pylons - Firewall Sealing Modification/Application of Pylon Trailing Edge Sealant**							RE (-)		Recommended	
54 A/F							Mos	14-Dec-2020				
Eff: 15-Aug-2003 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-54-4		**Nacelles/Pylons - Installation of Protective Boots on Starter/Generator and Alternator Inlet Scoops**							RE (-)		Recommended	
54 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-54-4 Rev 1		**Nacelles/Pylons - Installation of Protective Boots on Starter/Generator and Alternator Inlet Scoops**							RE (-)		Recommended	
54 A/F							Mos	14-Dec-2020				
Eff: 13-Jun-2003 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-54-5	**Nacelles/Pylons - Replacement of Forward Engine Mount Firewall Screws**							RE (-)		Recommended	
54 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-54-5 Rev 1	**Nacelles/Pylons - Replacement of Forward Engine Mount Firewall Screws**							RE (-)		Recommended	
54 A/F						Mos	14-Dec-2020				
Eff: 12-Dec-2005 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-54-6	**Nacelles/Pylons - Modification of the Pylon Leading Edge Seal Installation**							RE (-)		Optional	
54 A/F						Mos					
Eff: 23-Nov-2009						Hrs					
(AVG MAN HRS: 5.5)						Ldg					
45-54-6 Rev 1	**Nacelles/Pylons - Modification of the Pylon Leading Edge Seal Installation**							RE (-)		Optional	
54 A/F						Mos					
Eff: 22-Feb-2010						Hrs					
(AVG MAN HRS: 5.5)						Ldg					
45-54-6 Rev 2	**Nacelles/Pylons - Modification of the Pylon Leading Edge Seal Installation**							RE (-)		Optional	
54 A/F						Mos					
Eff: 18-Aug-2014						Hrs					
(AVG MAN HRS: 5.5)						Ldg					
45-54-6 Rev 3	**Nacelles/Pylons - Modification of the Pylon Leading Edge Seal Installation**							RE (-)		Optional	
54 A/F						Mos	29-Aug-2019				
Eff: 22-Dec-2014 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 5.5)						Ldg	2,733				
A5450022	*** (Left) Aft Engine Mount to End Fitting Attach Bolt - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-01, Ch.5 Interval		**≈16-Jun-2030**
54 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	9,600		12,611.7	7,336.9 Hrs
(ZONE: 450/460) (SOURCE: MM-104, MM-105)						Ldg					
A5450022	*** (Right) Aft Engine Mount to End Fitting Attach Bolt - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-01, Ch.5 Interval		**≈16-Jun-2030**
54 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	9,600		12,611.7	7,336.9 Hrs
(ZONE: 450/460) (SOURCE: MM-104, MM-105)						Ldg					
A5450026	*** Engine Drag Strut - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
(ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 54-50-01.))						Ldg	2,822				
A5450028	**Aft Engine Beam Assembly End Fittings (4553500201-001/-002) - Replace. (Aircraft 45-002 thru 45- 025.)**							RE (N/A)		TLMC 05-19-01	
54 A/F						Mos					
						Hrs					
(ZONE: 450/460) (SOURCE: MM-104)						Ldg					
AB5450054	**(Left) Forward Engine Beam and Beam Fitting - Perform visual inspection, paying particular attention of the following: a. Upper capping plate at fastener holes, and channel flange at fastener holes. b. Bolt holes, especially upper bolt hole on aft flange.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
54 A/F						Mos					
						Hrs		6,000	+200	6,000	725.2 Hrs (+200)
Alias1:5-10-00 (ZONE: 340) (SOURCE: MM-104, MM-105) (NOTE: During Engine CZI not to exceed 7,200 Hours (Refer to 5-10-00.))						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AB5450054	**(Right) Forward Engine Beam and Beam Fitting - Perform visual inspection, paying particular attention of the following: a. Upper capping plate at fastener holes, and channel flange at fastener holes. b. Bolt holes, especially upper bolt hole on aft flange.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
54 A/F						Mos					
						Hrs		6,000	+200	6,000	725.2 Hrs (+200)
Alias1:5-10-00 (ZONE: 340) (SOURCE: MM-104, MM-105) (NOTE: During Engine CZI not to exceed 7,200 Hours (Refer to 5-10-00.))						Ldg					
E5450029	*** Aft Engine Beam - Perform visual inspection. Inspect upper capping plate, around fastener holes in the capping plate, and channel flange.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 310HL,310RR,340FL,340GL,340HL,340FR,340GR,340HR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	2,822				
F5450019	*** Aft Engine Beam Attachment to Frames - Perform visual inspection. Inspect aft engine beam attachment to frames.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	2,822				
H5450012	*** Frames 39/40 (FS 512/518) at Engine Beam Attachment - Perform Eddy Current Inspection. Inspect outer flange and frame web at engine beam attachment.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:54-50-03 (ZONE: 310HL, 310JL, 310QR, 310RR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 54-50-03.))						Ldg	2,822				
M5450015	*** Forward Engine Beam, Spar Cap and Web - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:54-50-05 (ZONE: 300, 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 54-50-05.))						Ldg	2,822				
M5450018	*** Forward Engine Mount Attach Bolts - Perform Fluorescent Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:71-20-01 (ZONE: 400) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 8, 71-20-01.))						Ldg	2,822				
M5450027	**Forward Engine Beam Assembly End Fittings (4553500101-003/-004) - Replace.**							RE (N/A)		TLMC 05-19-01	
54 A/F						Mos					
						Hrs					
(ZONE: 450/460) (SOURCE: MM-104) (NOTE: (Aircraft 45-002 thru 45-029.))						Ldg					
P5450011	*** Drag Strut Attachment Fittings - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:53-10-03 (ZONE: 450, 460, 340CL, 340CR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI- 104], Part 6, 53-10-03.))						Ldg	2,822				
P5450016	*** Forward Engine Beam End Fitting - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:54-50-02 (ZONE: 340AR/BR/CR/DR/ER/FR/AL/BL/CL/DL/EL/FL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 54-50-02.))						Ldg	2,822				
P5450017	*** Forward Engine Beam to Frame Attach Bolts - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:53-40-01 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 8, 53-40-01.))						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P5450020	*** (Left) Aft Engine Beam to Frame Attachment Bolt - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-01, Ch.5 Interval		**≈10-Dec-2027**
54 A/F						Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	(ZONE: 450/460) (SOURCE: MM-104, MM-105)					Ldg					
P5450020	*** (Right) Aft Engine Beam to Frame Attachment Bolt - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-01, Ch.5 Interval		**≈10-Dec-2027**
54 A/F						Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	(ZONE: 450/460) (SOURCE: MM-104, MM-105)					Ldg					
P5450021	*** Engine Aft Isolator Mount Fittings - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Ref:NDI-104/Part6/71-20-03 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 8, 71-20-02.))					Ldg	2,822				
P5450023	*** (Left) Engine to Aft Engine Mount Attach Bolts - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-01, Ch.5 Interval		**≈16-Jun-2030**
54 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	9,600		12,611.7	7,336.9 Hrs
	(ZONE: 450/460) (SOURCE: MM-104, MM-105)					Ldg					
P5450023	*** (Right) Engine to Aft Engine Mount Attach Bolts - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-01, Ch.5 Interval		**≈16-Jun-2030**
54 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	9,600		12,611.7	7,336.9 Hrs
	(ZONE: 450/460) (SOURCE: MM-104, MM-105)					Ldg					
P5450024	*** Fuselage Frames at FS 543.55 and 546.15 to Aft Engine Beam Attachment - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:53-30-14 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 53-30-14.))					Ldg	2,822				
P5450025	*** Forward Engine Beam and Frames at Attach Holes - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:54-50-03 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 54-50-03.))					Ldg	2,822				
P5450030	*** Aft Engine Beam End Fitting - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
54 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Ref:NDI-104, Part 6, 54-50-04 (ZONE: 310HL,310RR,340FL,340GL,340HL,340FR,340GR,340HR) (SOURCE: MM-104, MM-105) (NOTE: Initial inspection to be performed at 9,600 flight hours, and subsequent inspections performed every 4,800 flight hours thereafter)					Ldg	2,822				
Y5410002	**Pylons - Perform Visual Inspection. Inspect HiLite collars common to main engine beam external to fuselage.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
54 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00, 54-00-01 (ZONE: 340DL, 340EL, 340FL, 340DR, 340ER, 340FR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00 and 54-00-01.))					Ldg	3,757				
▼ 55 - STABILIZERS											
	Horizontal Stabilizer Assembly							RE (O/C)			
55 A/F		0				Mos	13-Mar-2008				
4555101001V45-001 S7549A0200	New	0				Hrs	0				
		0				Ldg	0				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Left Elevator Assembly							RE (O/C)			
55 A/F	Left	0				Mos	13-Mar-2008				
4555201005-007	New	0				Hrs	0				
S7549A0208		0				Ldg	0				
	Right Elevator Assembly							RE (O/C)			
55 A/F	Right	0				Mos	13-Mar-2008				
4555201005-008	New	0				Hrs	0				
S7549A0207		0				Ldg	0				
	Rudder Assembly							RE (O/C)			
55 A/F		0				Mos	13-Mar-2008				
4555401000-021	New	0				Hrs	0				
S7549A0209		0				Ldg	0				
	Tailcone/Vertical Stabilizer Assembly							RE (O/C)			
55 A/F		0				Mos	13-Mar-2008				
4555301001-001	New	0				Hrs	0				
A198		0				Ldg	0				
45-55-10	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Forward Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-10 Rev 1	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Forward Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-10 Rev 2	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Forward Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-10 Rev 3	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Forward Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	29-Aug-2019				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-55-11	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Mid Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-11 Rev 1	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Mid Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-11 Rev 2	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Mid Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-11 Rev 3	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Mid Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	29-Aug-2019				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-55-12	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Aft Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-12 Rev 1	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Aft Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-12 Rev 2	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Aft Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-12 Rev 3	**Stabilizers - Replacement of Hi-Lite Collars in the Lower Aft Spar Assembly-Vertical Stabilizer-Tail Cone**							RE (-)		Optional	
55 A/F						Mos	29-Aug-2019				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-55-13	**Stabilizers - Replacement of Hi-Lite Collars in the Horizontal Stabilizer Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-13 Rev 1	**Stabilizers - Replacement of Hi-Lite Collars in the Horizontal Stabilizer Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-13 Rev 2	**Stabilizers - Replacement of Hi-Lite Collars in the Horizontal Stabilizer Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-13 Rev 3	**Stabilizers - Replacement of Hi-Lite Collars in the Horizontal Stabilizer Structure**							RE (-)		Optional	
55 A/F						Mos	29-Aug-2019				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-55-14	**Stabilizers - Replacement of Hi-Lite Collars in the Upper Tail Cone/Vertical Stabilizer Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-14 Rev 1	**Stabilizers - Replacement of Hi-Lite Collars in the Upper Tail Cone/Vertical Stabilizer Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-14 Rev 2	**Stabilizers - Replacement of Hi-Lite Collars in the Upper Tail Cone/Vertical Stabilizer Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-14 Rev 3	**Stabilizers - Replacement of Hi-Lite Collars in the Upper Tail Cone/Vertical Stabilizer Structure**							RE (-)		Optional	
55 A/F						Mos	29-Aug-2019				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-55-15	**Stabilizers - Replacement of Hi-Lite Collars in the Upper Vertical Stabilizer, Pivot Fitting Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-55-15 Rev 1	**Stabilizers - Replacement of Hi-Lite Collars in the Upper Vertical Stabilizer, Pivot Fitting Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-15 Rev 2	**Stabilizers - Replacement of Hi-Lite Collars in the Upper Vertical Stabilizer, Pivot Fitting Structure**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-15 Rev 3	**Stabilizers - Replacement of Hi-Lite Collars in the Upper Vertical Stabilizer, Pivot Fitting Structure**							RE (-)		Optional	
55 A/F						Mos	29-Aug-2019				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-55-16	**Stabilizers - Modification of the Vertical Stabilizer Bullet Fairing Center Skins**							RE (-)		Recommended	
55 A/F						Mos	08-Jun-2009				
Eff: 05-May-2008 Not Applicable	PER A/C S/N					Hrs	801				
(AVG MAN HRS: 1)						Ldg	521				
45-55-16 Rev 1	**Stabilizers - Modification of the Vertical Stabilizer Bullet Fairing Center Skins**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 11-Jan-2010 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 1)						Ldg	2,822				
45-55-18	**Stabilizers -- Inspection/Replacement of Hi-Lite Collars in the Horizontal Stabilizer Structure**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 10-Sep-2007 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-55-2	**Stabilizers - Installation of Delta Fin Drain Holes and Fairings**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-2 Rev 1	**Stabilizers - Installation of Delta Fin Drain Holes and Fairings**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 10-Nov-2000 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-55-20	**Stabilizers - Replacement of the Horizontal Stabilizer Gap Fairing**							RE (-)		Optional	
55 A/F						Mos					
						Hrs					
						Ldg					
45-55-20 Rev 1	**Stabilizers - Replacement of the Horizontal Stabilizer Gap Fairing**							T (A/R)		Optional	
55 A/F						Mos					
Eff: 17-Oct-2011						Hrs					
						Ldg					
45-55-21	**Stabilizers - Installation of Replacement Bushings for Vertical Stabilizer**							T (A/R)		Optional	
55 A/F						Mos					
Eff: 09-Jan-2023						Hrs					
(AVG MAN HRS: 20)						Ldg					
45-55-3	**Fuselage - Installation of Dorsal Inlet Drain Pan**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-55-3 Rev 1	**Fuselage - Installation of Dorsal Inlet Drain Pan**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Eff: 09-Aug-2000 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-3 Rev 2	**Fuselage - Installation of Dorsal Inlet Drain Pan**							RE (-)		Recommended	
55 A/F						Mos	08-Jun-2009				
Eff: 13-Jul-2001 Not Applicable	PER A/C S/N					Hrs	801				
						Ldg	521				
45-55-3 Rev 3	**Stabilizers - Installation of Dorsal Inlet Drain Pan**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 19-Jun-2017 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 17)						Ldg	2,822				
45-55-4	**Stabilizers - Inspection/Installation of Bullet Fairing Reinforcement**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-4 Rev 1	**Stabilizers - Inspection/Installation of Bullet Fairing Reinforcement**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-4 Rev 2	**Stabilizers - Inspection/Installation of Bullet Fairing Reinforcement**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 17-May-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-55-5	**Stabilizers - Modification of the Bullet Fairing and Vertical Stabilizer SUPERCEDED by SB45-55-9**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-5 Rev 1	**Stabilizers - Modification of the Bullet Fairing and Vertical Stabilizer SUPERCEDED by SB45-55-9**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-5 Rev 2	**Stabilizers - Modification of the Bullet Fairing and Vertical Stabilizer SUPERCEDED by SB45-55-9**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 18-Sep-2006 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-55-6	**Stabilizers - Modification of the Rudder and Rudder Trim Tab Assembly Trailing Edge**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-6 Rev 1	**Stabilizers - Modification of the Rudder and Rudder Trim Tab Assembly Trailing Edge**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 01-Oct-2002 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-55-7	**Stabilizers - Installation of the Bullet Fairing Support Bracket**							RE (-)		Optional	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-55-7 Rev 1	**Stabilizers - Installation of the Bullet Fairing Support Bracket**							RE (-)		Optional	
55 A/F						Mos	29-Aug-2019				
Eff: 30-Apr-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-55-8	**Stabilizers - Inspection of the Horizontal Stabilizer Actuator - Lower Attach Fitting**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 08-Sep-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-55-9	**Stabilizers - Improved Modification of the Bullet Fairing and Vertical Stabilizer**							RE (-)		Recommended	
55 A/F						Mos	08-Jun-2009				
Not Applicable	PER A/C S/N					Hrs	801				
						Ldg	521				
45-55-9 Rev 1	**Stabilizers - Improved Modification of the Bullet Fairing and Vertical Stabilizer**							RE (-)		Recommended	
55 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-55-9 Rev 2	**Stabilizers - Improved Modification of the Bullet Fairing and Vertical Stabilizer**							RE (-)		Recommended	
55 A/F						Mos	14-Dec-2020				
Eff: 20-Apr-2009 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
A45-55-1	**INSPECTION OF ELEVATOR/HORIZONTAL STABILIZER CLEARANCE**							RE (-)			
55 A/F						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
A45-55-17	**Avionics - Installation of Bonding Jumper on Dorsal Inlet Drain Pan**							RE (-)		Alert	
55 A/F						Mos	14-Dec-2020				
Eff: 23-Jul-2007 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 1)						Ldg	2,822				
A45-55-19	**Stabilizers - Inspect the Horizontal Stabilizer Hinge Primary and Secondary Attaching Hardware**							RE (-)		Alert	
55 A/F						Mos	14-Dec-2020				
Eff: 15-Oct-2007 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 2)						Ldg	2,822				
A5510014	*** Vertical Stabilizer Pivot Fitting Bottom Plate - Perform Detailed Visual Inspection. Inspect aft portion of bottom plate through lightening hole in top plate, forward portion of bottom plate through top plate cutouts, and bottom of outside exposed surface of pivot fitting.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))						Ldg					
A5510021	*** Horizontal Mid Spar from Canted Rib #2 to Canted Rib #3 - Perform Detailed Visual Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))						Ldg					
A5540000	*** Rudder Root Rib Cap (FS 698) - Perform visual inspection. Inspect around fastener holes and lightening holes.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10- 00.))						Ldg					
AA5510034	**Horizontal Stabilizer Primary and Secondary Bolts and Bushings - Perform Detailed Inspection**							RE	05-19-00, Special Inspections		**≈14-Oct-2027**
55 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	9,410.5	4,135.7 Hrs (+25)
Ref:55-10-00 (ZONE: 330FL/330ER) (SOURCE: MM-104) (NOTE: For Aircraft between 4,800 and 9,600 Hours on April 30, 2018, perform the inspection at the next 1,200 Hour inspection. For Aircraft with more than 9,600 Hours on April 30, 2018, perform the inspection at 14,400 Hours.)						Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
E5510074	*** Horizontal Stabilizer Rear Spar from Canted Rib #2 to Canted Rib #3 - Perform visual inspection. Inspect rear spar cap and fasteners.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 330WL, 330VR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5510075	*** Horizontal Stabilizer Outboard Spars and Skins Outboard of Canted Rib #3 - Perform visual inspection. Inspect spar caps and fasteners.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 330WL, 330VR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5510076	*** Horizontal Stabilizer Front Spar from Canted Rib #2 to Canted Rib #3 - Perform visual inspection. Inspect front spar cap and fasteners.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 330WL, 330VR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5520003	*** Elevator Front Spar - Perform visual inspection. Inspect spar cap at fastener holes.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5520004	*** Elevator Rib #1 Cap - Perform visual inspection of rib #1 cap cross section and rib cap flanges at torque tube.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 330CC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
G5510000	*** Horizontal Stabilizer Actuator Attachment Fittings - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
55 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:55-10-01 (ZONE: 330AC,330BC,330CL,330XL,330WR,330AR,330XR,330YL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-10-01.))					Ldg	2,822				
G5510023	*** Horizontal Stabilizer Actuator Vertical Tail Attachment - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
55 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:55-30-01 (ZONE: 330AC,330BC,330CL,330XL,330WR,330AR,330XR,330YL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-30-01.))					Ldg	2,822				
H5510033	*** Horizontal Stabilizer Actuator Attachment Bolts - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
55 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:27-40-01 (ZONE: 330CL, 330BR, 330XL, 330WR, 330YL, 330XR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 8, 27-40-01.))					Ldg	2,822				
M5510010	*** Horizontal Stabilizer Aft Root Rib - Perform Eddy Current Inspection. Inspect aft root rib internal between mid spar and aft spar and upper and lower skins external at attachment fasteners.**							RE	TLMC 04-10-01, TLMC 05-19-00	**≈11-Oct-2024**	
55 A/F						Mos	10-Feb-2021				
						Hrs	4,610.5	1,200		5,810.5	535.7 Hrs
	Alias1:55-10-03 (ZONE: 330FL, 330ER, 330XL, 330WR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-10-03.))					Ldg	2,822				
M5540022	**Rudder Torque Tube - Perform Borescope Inspection.**							RE (N/A)	TLMC 05-19-00		
55 A/F						Mos					
						Hrs					
	Alias1:05-10-00 (ZONE: 320BL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 05-10-00.) (Effective on Aircraft with light surface corrosion discovered during compliance of SB 45-27-24, Part C and not modified per SB 45-27-25.))					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
N5510005	*** Horizontal Stabilizer Rear Spar Cap - Perform Eddy Current Inspection. Inspect rear spar cap and web at center splice.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval	**≈12-Oct-2025**	
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:55-10-05 (ZONE: 330CC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI- 104], Part 6, 55-10-05.))					Ldg	2,822				
N5510015	*** Vertical Stabilizer Pivot Fitting Top Plate - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval	**≈12-Oct-2025**	
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:55-30-02 (ZONE: 330WR, 330XL, 330CC, 330XR, 330YL, 330DL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Man- ual [NDI-104], Part 6, 55-30-02.))					Ldg	2,822				
N5510016	*** Vertical Stabilizer Pivot Fitting Tower Section Forward Radius - Perform Eddy Current Inspection. Inspect pivot fitting at tower section radius, pivot fitting and top plate around adjacent fasteners, and pivot fitting sides at tower section radius.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval	**≈12-Oct-2025**	
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:53-30-03 (ZONE: 330BL,330BR,330CC,330XL,330WR,330YL,330XR,330DL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-30- 03.))					Ldg	2,822				
N5510069	*** Horizontal Stabilizer Mid Spar Flange Root Rib Attachment - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval	**≈12-Oct-2025**	
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:55-10-02 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-10- 02.))					Ldg	2,822				
N5510082	*** Horizontal Stabilizer Rear Spar Flange Root Rib Attachment - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval	**≈12-Oct-2025**	
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:55-10-04 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-10- 04.))					Ldg	2,822				
P5510006	*** Vertical Stabilizer Front Spar and Mid Spar- Perform Radiographic Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-30-01 (ZONE: 320CL, 320BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 2, 55-30-01.))					Ldg					
P5510008	*** Horizontal Stabilizer Primary and Secondary Attach Bolts - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-30-02, 55-30-03 (ZONE: 330FL, 330ER) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 7, 55-30-02 and 55-30-03.))					Ldg					
P5510009	*** Horizontal Stabilizer Mid Spar Upper Cap B.L. 0.0 to B.L. 4.0 - Perform X-ray Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval	**≈12-Oct-2025**	
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:55-10-03 (ZONE: 330AC, 330BC, 330CC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 2, 55-10-03.))					Ldg	2,822				
P5510011	*** Horizontal Stabilizer Mid Spar and Rear Spar Upper Flange at Root Rib - Perform Radiographic Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-10-01 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 2, 55-10-01.))					Ldg					
P5510017	*** Vertical Stabilizer Pivot Fitting Tower Section - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval	**≈12-Oct-2025**	
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:55-30-05 (ZONE: 330BL,330BR,330CC,330XL,330WR,330YL,330XR,330DL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-30-05.))					Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P5510018	*** Vertical Stabilizer Pivot Fitting Lugs - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-30-04 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manu- al [NDI-104], Part 6, 55-30-04.))					Ldg					
P5510019	*** Elevator Hinges on Horizontal Stabilizer - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-20-02 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 55-20-02.))					Ldg					
P5510020	*** Horizontal Mid Spar Upper Cap - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-10-07 (ZONE: 330FL, 330ER) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 55-10-07.))					Ldg					
P5510024	*** Elevator Control Horn - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-20-01 (ZONE: 330XL, 330WR, 330CC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 55-20-01.))					Ldg					
P5510070	*** Horizontal Stabilizer Front Spar - Perform Radiographic Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-10-02 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 2, 55-10-02.))					Ldg					
P5510073	*** Horizontal Stabilizer Rear Spar Upper Cap - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-10-07 (ZONE: 330FL, 330ER) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 55-10-07.))					Ldg					
P5510092	*** Horizontal Stabilizer Upper Spar Splice Doubler - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval		**≈12-Oct-2025**
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:55-10-06 (ZONE: 330AC, 330BC, 330CC) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-10-06.))					Ldg	2,822				
P5520001	*** Elevator Hinge Attach Bolt - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:27-30-01 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 7, 27-30-01.))					Ldg					
P5520002	*** Elevator Hinge Pin - Perform Liquid Penetrant Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-16-00		
55 A/F						Mos					
						Hrs					
	Alias1:55-30-01 (ZONE: 330ML, 330PL, 330LR, 330NR) (SOURCE: MM-104) (NOTE: (Effective on Aircraft 45-001 thru 45-014.))					Ldg					
P5520021	*** Elevator Hinge Fittings - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-30-07 (ZONE: 330UL, 330VL, 330JL, 330TR, 330UR, 330HR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 55-30-07.) (Effective on aircraft 45-015 and subsequent.))					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P5520022	*** Elevator Hinge Primary and Secondary Attach Bolts - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:27-30-01, 27-30-02 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 8, 27-30-01 and 27-30-02.))					Ldg					
P5540001	*** Rudder Spar - Perform Detailed Visual Inspection. Inspect spar caps and fasteners.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 330QL,330RL,330SL,330TL,330PR,330QR,330RR,330SR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
P5540002	*** Rudder Attach Bolts - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-30-02 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 8, 55-30-02.))					Ldg					
Q5510007	*** Vertical Stabilizer Skin and Lower Aft Spar Cap - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:55-30-06 (ZONE: 320EL, 320DR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 55-30-06.))					Ldg					
Q5530011	*** Vertical Stabilizer Skin and Upper Aft Spar Cap - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-02, Ch.5 Interval	**≈12-Oct-2025**	
55 A/F	05-14-02					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:55-30-06 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 55-30-06.))					Ldg	2,822				
T5510004	*** Rudder Hinge Fittings - Perform Visual Inspection. Control surface removal not required.**							RE	TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
55 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 330) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
T5510004-4A	*** Rudder Top Hinge Fitting - Perform visual inspection. Inspect lug (FS 721).**							RE (N/A)	TLMC 04-10-01, Ch.5 Interval		
55 A/F						Mos					
						Hrs					
	(ZONE: 330) (SOURCE: MM-104, MM-105)					Ldg					
T5510004-4B	*** Rudder Mid Hinge Fitting - Perform visual inspection. Inspect lug (FS 721).**							RE (N/A)	TLMC 04-10-01, Ch.5 Interval		
55 A/F						Mos					
						Hrs					
	(ZONE: 330) (SOURCE: MM-104, MM-105)					Ldg					
T5510004-4C	*** Rudder Lower Hinge Fitting - Perform visual inspection. Inspect lug (FS 709).**							RE (N/A)	TLMC 04-10-01, Ch.5 Interval		
55 A/F						Mos					
						Hrs					
	(ZONE: 330) (SOURCE: MM-104, MM-105)					Ldg					
W5510091	***Horizontal Stabilizer Hinge Primary and Secondary Pivot Pin Installation and Attaching Hardware - Perform Detailed Visual Inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00	**≈03-Jul-2024**	
55 A/F						Mos	06-Feb-2022				
						Hrs	4,859.6	625		5,484.6	209.8 Hrs
	Alias1:55-10-00 (ZONE: 330ER, 330FL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 55-10-00.))					Ldg	2,992				
Y5510001	**Horizontal Stabilizer - Perform External Visual Inspection.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
55 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 330) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y5510002	**Elevator Hinges on Horizontal Stabilizer - Perform Visual Inspection. Inspect hinge lugs on horizontal tail side of joint. Inspect HiLite collars at BL 0.0 and outboard elevator hinge.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
55 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00, 55-00-01 (ZONE: 330) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00 and 55-00-01.))					Ldg	3,757				
Y5510003	**Vertical Stabilizer Pivot Fitting - Perform Visual Inspection. Inspect HiLite collars common to the pivot fitting (mid spar, aft spar, top plate, and up/ down spring bracket).**							RE		TLMC 05-13-02	**≈24-Apr-2025**
55 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00, 55-00-01 (ZONE: 330AC, 330BC, 330CC, 330BR, 330BL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00 and 55-00-01.))					Ldg	3,757				
Y5510093	**Horizontal Stabilizer - Perform Visual Inspection of HiLite collars in the following areas: - Forward Spar to BL 0.0 Rib. - Center Spar to BL 0.0 Rib. - Center Spar Splice Plate. - Aft Spar Splice Plate. - Root Ribs at BL 3.70 (Right and Left). - Upper Doubler Spar Splice, BL 0.0. - HSTA Upper Attach Fitting Structure.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
55 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Ref:55-00-01 (ZONE: 330AC/BC/CC/DR/EL/ER/FL/BR/BL/WR/XL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 55-00-01.))					Ldg	3,757				
Y5510094	**Lower Bracket, Horizontal Stabilizer Trim Actuator - Perform Borescope Inspection of HiLite collars common to Rib # 6 and Mid Spar.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
55 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:55-10-00 (ZONE: 330AC, 330BC, 330CC, 330BR, 330BL) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 55-10-00.))					Ldg	3,757				
Y5540012	**Rudder Torque Tube - Loosen torque tube bonding clamp and perform detailed visual inspection of area around bonding clamp for corrosion.**							RE (N/A)		TLMC 05-11-02	
55 A/F	05-11-02					Mos	09-Feb-2024				
						Hrs	5,253.5				
	Ref:20-10-01 (ZONE: 320BL) (SOURCE: MM-104, MM-105)					Ldg	3,757				
▼ 56 - WINDOWS											
	Emergency Exit Window Cabin							RE (O/C)			
56 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Window Cabin							RE (O/C)			
56 A/F	Left No.1					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Window Cabin							RE (O/C)			
56 A/F	Left No.2					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Window Cabin							RE (O/C)			
56 A/F	Left No.3					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Window Cabin							RE (O/C)			
56 A/F	Left No.4					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Window Cabin							RE (O/C)			
	56 A/F	Left No.5					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Left No.6					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Left No.7					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Left No.8					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Right No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Right No.2					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Right No.3					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Right No.4					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Right No.5					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Right No.6					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Window Cabin							RE (O/C)			
	56 A/F	Right No.7					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Windshield							RE (O/C)			
56 A/F	Left		0			Mos	15-Feb-2009				
6656100001-001	New		0			Hrs	662.2				
0757			0			Ldg	448				
	Windshield							RE (O/C)			
56 A/F	Right		1			Mos	13-May-2011				
665610001-002						Hrs	1,965.2				
1130						Ldg	1,178				
45-56-1	**Windows - Installation of the GKN Windshield**							RE (-)		Optional	
56 A/F						Mos					
						Hrs					
						Ldg					
45-56-1 Rev 1	**Windows - Installation of the GKN Windshield**							RE (-)		Optional	
56 A/F						Mos					
						Hrs					
						Ldg					
45-56-1 Rev 2	**Windows - Installation of the GKN Windshield**							RE (-)		Optional	
56 A/F						Mos					
						Hrs					
						Ldg					
45-56-1 Rev 3	**Windows - Installation of the GKN Windshield**							RE (-)		Optional	
56 A/F						Mos					
						Hrs					
						Ldg					
45-56-1 Rev 4	**Windows - Installation of the GKN Windshield**							RE (-)		Optional	
56 A/F						Mos					
						Hrs					
						Ldg					
45-56-1 Rev 5	**Windows - Installation of the GKN Windshield**							RE (-)		Optional	
56 A/F						Mos					
Eff: 16-Jun-2014						Hrs					
						Ldg					
45-56-1 Rev 6	**Windows - Installation of the GKN Windshield**							RE (-)		Optional	
56 A/F						Mos					
Eff: 11-Jan-2016						Hrs					
(AVG MAN HRS: 25.5)						Ldg					
45-56-1 Rev 7	**Windows - Installation of the GKN Windshield**							RE (-)		Optional	
56 A/F						Mos	29-Aug-2019				
Eff: 25-Jul-2016 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 25.5)						Ldg	2,733				
45-56-2	**Windows - Modification of the GKN Windshield Heat Terminal Lug Installation**							RE (-)		Recommended	
56 A/F						Mos	11-Aug-2010				
Eff: 21-Jun-2010 Not Applicable						Hrs					
						Ldg					
45-56-2 Rev 1	**Windows - Modification of the GKN Windshield Heat Terminal Lug Installation**							RE (-)		Recommended	
56 A/F						Mos	14-Dec-2020				
Eff: 16-Jun-2014 Not Applicable						Hrs	4,610.5				
(NOTE: Service bulletin 45-56-2 has been deactivated. Service Bulletin 45-56-5 fulfills the same requirements for the affected aircraft)						Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-56-3	**Windows - Windshield Coupe Rail Inspection**							RE (-)		Recommended	
56 A/F						Mos					
Eff: 30-Apr-2012						Hrs					
(AVG MAN HRS: 54)						Ldg					
45-56-3 Rev 1	**Windows - Windshield Coupe Rail Inspection**							RE (-)		Recommended	
56 A/F						Mos	19-Jun-2015				
Eff: 15-Oct-2012 Complied With						Hrs					
(AVG MAN HRS: 54)						Ldg					
45-56-3 Rev 1 Par. 3.A,B,C,D L/H	**Windows - Windshield Coupe Rail Inspection, L/H**							RE (-)		Recommended	
56 A/F						Mos	19-Jun-2015				
Eff: 15-Oct-2012 Complied With						Hrs					
						Ldg					
45-56-3 Rev 1 Par. 3.A,B,C,D R/H	**Windows - Windshield Coupe Rail Inspection, R/H**							RE (-)		Recommended	
56 A/F						Mos	19-Jun-2015				
Eff: 15-Oct-2012 Complied With						Hrs					
						Ldg					
45-56-3 Rev 1 Par. 3.B(9) L/H	**Windows - Windshield Coupe Rail Inspection - Eddy Current Inspection, L/H**							RE (-)		Recommended	
56 A/F						Mos	19-Jun-2015				
Eff: 15-Oct-2012 Complied With						Hrs					
						Ldg					
45-56-3 Rev 1 Par. 3.B(9) R/H	**Windows - Windshield Coupe Rail Inspection - Eddy Current Inspection, R/H**							RE (-)		Recommended	
56 A/F						Mos	19-Jun-2015				
Eff: 15-Oct-2012 Complied With						Hrs					
						Ldg					
45-56-5	**Windows - GKN Windshield Heat Terminal Lug Inspection**							RE (-)		Recommended	
56 A/F						Mos	05-Aug-2014				
Eff: 16-Jun-2014 Complied With						Hrs	3,243.9				
(AVG MAN HRS: 10)						Ldg	1,896				
45-56-5 Rev 1	**Windows - GKN Windshield Heat Terminal Lug Inspection**							RE (-)		Recommended	
56 A/F						Mos	19-Nov-2014				
Eff: 20-Oct-2014 Complied With	NO WORK IS REQUIRED COMPLIED WITH PREVIOUS ISSUE ON 8/05/2014					Hrs	3,322.6				
(AVG MAN HRS: 10)						Ldg	1,941				
45-56-6	**Windows - Installation of the PPG (Sierracin) Windshield**							T (A/R)		Optional	
56 A/F						Mos					
Eff: 20-Feb-2023						Hrs					
(AVG MAN HRS: 24)						Ldg					
L5600010	*** Cabin Windows (including the emergency exit windows) - Perform Detailed Visual Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
56 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 220/230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	2,822				
N5600003	*** Windshields - Perform ultrasonic inspection of the structural plies.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
56 A/F	Left					Mos					
6656100001-001						Hrs					
0757						Ldg					
Alias1:56-10-01 (ZONE: 220/230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI- 104], Part 4, 56-10-01.) (Effective on Aircraft with Sierracin windshields installed.))											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
N5600003	*** Windshields - Perform ultrasonic inspection of the structural plies.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
56 A/F	Right					Mos					
665610001-002						Hrs					
1130						Ldg					
	Alias1:56-10-01 (ZONE: 220/230) (SOURCE: MM-104, MM-105)										
N5600012	*** Windshields - Perform bolt hole inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈22-Jul-2027**
56 A/F	Left					Mos	12-Dec-2018				
6656100001-001						Hrs	4,337.9	4,800		9,137.9	3,863.1 Hrs
0757						Ldg					
	Alias1:56-10-01 (ZONE: 220/230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 56-10-01.) (Effective on Aircraft with GKN windshields installed.))										
N5600012	*** Windshields - Perform bolt hole inspection.**							RE	TLMC 04-10-01, TLMC 05-19-00		**≈29-Jul-2025**
56 A/F	Right					Mos	13-May-2011				
665610001-002						Hrs	1,965.2	4,800		6,765.2	1,490.4 Hrs
1130						Ldg	1,178				
	Alias:56-10-01 (ZONE: 220/230) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 56-10-01.) (Effective on Aircraft with GKN windshields installed.))										
W5600002	**** Windshield - Perform Rain Removal Coating Effectiveness Test.**							RE	TLMC 04-10-00, TLMC 05-19-00		
56 A/F						Mos	19-Aug-2023	12	-/+14d	04-Aug-2024	72 Days (+14)
						Hrs	5,196.7				
	Alias1:56-10-01 (ZONE: 220) (Tol. Adjustment: -14d) (SOURCE: MM-104, MM-105) (NOTE: Note: If repairs to the seal are needed, refer to 56-10-01.)					Ldg	3,211				
Y5600000	**Windshields - Perform visual inspection (interior and exterior).**							RE		TLMC 05-11-01	**≈24-Jul-2024**
56 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y5600001	**Cabin Windows - Perform visual inspection.**							RE		TLMC 05-12-01	**≈24-Oct-2024**
56 A/F	05-12-01					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 230) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y5600013	**Windshields - Perform visual inspection of the aerodynamic seal.**							RE		TLMC 05-11-01	**≈24-Jul-2024**
56 A/F	05-11-01					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 220) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) NOTE: If repairs to the seal are needed, refer to 56-10-01.)					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
▼ 57 - WINGS											
	Aileron							RE (O/C)			
57 A/F	Left	0				Mos	13-Mar-2008				
4557600003-001	New	0				Hrs	0				
820334600455		0				Ldg	0				
	Aileron							RE (O/C)			
57 A/F	Right	0				Mos	13-Mar-2008				
4557600003-002	New	0				Hrs	0				
935916500455		0				Ldg	0				
	Aileron Quadrant Assembly							RE (O/C)			
57 A/F	Lower					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Aileron Quadrant Assembly							RE (O/C)			
	57 A/F	Upper					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Assembly, Spoiler							RE (O/C)			
	57 A/F	Left	0				Mos	13-Mar-2008				
	4557700003-043	New	0				Hrs	0				
	689351500454		0				Ldg	0				
		Assembly, Spoiler							RE (O/C)			
	57 A/F	Right	0				Mos	13-Mar-2008				
	4557700003-044	New	0				Hrs	0				
	955718700454		0				Ldg	0				
		Balance, Tab Assembly - Aileron							RE (O/C)			
	57 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Balance, Tab Assembly - Aileron							RE (O/C)			
	57 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Flap Assembly							RE (O/C)			
	57 A/F	Left	39				Mos	07-Jun-2011				
	4557500006-009		2,013.7				Hrs	2,013.7				
	979594100455		1,207				Ldg	1,207				
		Flap Assembly							RE (O/C)			
	57 A/F	Right	39				Mos	07-Jun-2011				
	4557500006-010		2,013.7				Hrs	2,013.7				
	660322100434		1,207				Ldg	1,207				
		Leading Edge							RE (O/C)			
	57 A/F	Left Inboard	0				Mos	13-Mar-2008				
	4557400005-039	New	0				Hrs	0				
	011809700455		0				Ldg	0				
		Leading Edge							RE (O/C)			
	57 A/F	Left Outboard	0				Mos	13-Mar-2008				
	4557400005-043	New	0				Hrs	0				
	450601500455		0				Ldg	0				
		Leading Edge							RE (O/C)			
	57 A/F	Middle - Left	0				Mos	13-Mar-2008				
	4557400005-041	New	0				Hrs	0				
	011812900455		0				Ldg	0				
		Leading Edge							RE (O/C)			
	57 A/F	Middle - Right	0				Mos	13-Mar-2008				
	4557400005-042	New	0				Hrs	0				
	973219000455		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Leading Edge							RE (O/C)			
	57 A/F	Right Inboard	0				Mos	13-Mar-2008				
	4557400005-040	New	0				Hrs	0				
	973217200456		0				Ldg	0				
		Leading Edge							RE (O/C)			
	57 A/F	Right Outboard	0				Mos	13-Mar-2008				
	4557400005-046	New	0				Hrs	0				
	011817500455		0				Ldg	0				
		Leading Edge Access Section							RE (O/C)			
	57 A/F	Left Inboard	0				Mos	13-Mar-2008				
	4557400005-037	New	0				Hrs	0				
	282570400455		0				Ldg	0				
		Leading Edge Access Section							RE (O/C)			
	57 A/F	Left Outboard	0				Mos	13-Mar-2008				
	4557400005-045	New	0				Hrs	0				
	930074500455		0				Ldg	0				
		Leading Edge Access Section							RE (O/C)			
	57 A/F	Right Inboard	0				Mos	13-Mar-2008				
	4557400005-038	New	0				Hrs	0				
	608563800455		0				Ldg	0				
		Leading Edge Access Section							RE (O/C)			
	57 A/F	Right Outboard	0				Mos	13-Mar-2008				
	4557400005-044	New	0				Hrs	0				
	951682900455		0				Ldg	0				
		Mlg Side-Stay Actuator Attach Fitting							RE (O/C)			
	57 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Mlg Side-Stay Actuator Attach Fitting							RE (O/C)			
	57 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Rear Trunnion Break Out Block							RE (O/C)			
	57 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Surface Temp Control Sensor							RE (O/C)			
	57 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Surface Temp Control Sensor							RE (O/C)			
	57 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Surface Temp Overheat Control Sensor							RE (O/C)			
	57 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Surface Temp Overheat Control Sensor							RE (O/C)			
	57 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Wing Assembly							RE (O/C)			
	57 A/F		0				Mos	13-Mar-2008				
	4557000004-001	New	0				Hrs	0				
	719500200455		0				Ldg	0				
		Winglet							RE (O/C)			
	57 A/F	Left	0				Mos	13-Mar-2008				
	4557300006-001/00	New	0				Hrs	0				
	764654000455		0				Ldg	0				
		Winglet							RE (O/C)			
	57 A/F	Right	0				Mos	13-Mar-2008				
	4557300006-002/00	New	0				Hrs	0				
	987134200455		0				Ldg	0				
		Winglet Filler							RE (O/C)			
	57 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Winglet Filler							RE (O/C)			
	57 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Winglet Leading Edge Assembly							RE (O/C)			
	57 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Winglet Leading Edge Assembly							RE (O/C)			
	57 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
2021-23-08		**Wings - Center Box - Wing Center Spar Inspection**							RE		Mandatory	
	57 A/F						Yrs	19-Nov-2022	8		19-Nov-2030	6.5 Years
	Eff: 10-Jan-2022 Complied With						Hrs	5,136.6				
	(AVG MAN HRS: 7.5) (NOTE: APPLICABILITY: For airplanes that have accumulated more than 8 years since the date of issuance of the original airworthiness certificate or the date of issuance of the original export certificate of airworthiness, whichever date is earlier. COMPLIANCE: Within 12 months after the effective date of this AD, thereafter at intervals not to exceed 8 years.)						Ldg	3,167				
45-57-10		**Wings - Installation of Longer Body/Wing Rub Strips**							RE (-)		Recommended	
	57 A/F						Mos	28-Jan-2010				
	Eff: 08-Sep-2009 Complied With						Hrs	1,172.9				
	(AVG MAN HRS: 15.5)						Ldg	723				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-57-10 Rev 1	**Wings - Installation of Longer Body/Wing Rub Strips**							RE (-)		Recommended	
57 A/F						Mos	10-Jan-2020				
Eff: 11-Jan-2010 Not Applicable	C/W BASIC SB. NO REWORK REQUIRED					Hrs	4,590.8				
(AVG MAN HRS: 15.5)						Ldg	2,807				
45-57-11	**Wings - Installation of Main Landing Gear Aft Trunnion Fitting Upper Shear Pin Spacers**							RE (-)		Recommended	
57 A/F						Mos	22-Apr-2011				
Eff: 21-Feb-2011 Complied With						Hrs	1,922.2				
(AVG MAN HRS: 10.5)						Ldg	1,155				
45-57-11 Rev 1	**Wings - Installation of Main Landing Gear Aft Trunnion Fitting Upper Shear Pin Spacers**							RE (-)		Recommended	
57 A/F						Mos	29-Nov-2012				
Eff: 29-Oct-2012 Complied With	NO REWORK REQUIRED IF PREVIOUS COMPLIED WITH					Hrs	2,697.6				
(AVG MAN HRS: 10.5)						Ldg	1,592				
45-57-11 Rev 2	**Wings - Installation of Main Landing Gear Aft Trunnion Fitting Upper Shear Pin Spacers**							RE (-)		Recommended	
57 A/F						Mos	20-Jul-2014				
Eff: 07-Jul-2014 Complied With	NO REWORK REQUIRED PREVIOUSLY COMPLIED WITH SB 45-57-11 R1 DATED 29-NOV-2012					Hrs	3,225.3				
(AVG MAN HRS: 10.5)						Ldg	1,885				
45-57-11 Rev 3	**Wings - Installation of Main Landing Gear Aft Trunnion Fitting Upper Shear Pin Spacers**							RE (-)		Recommended	
57 A/F						Mos	10-Mar-2015				
Eff: 09-Mar-2015 Complied With	NO REWORK REQUIRED PREVIOUSLY COMPLIED WITH SB 45-57-11 R2 DATED 20-JUL-2014					Hrs	3,410.4				
(AVG MAN HRS: 10.5) (NOTE: A/C 45-005 to 45-208, 45-210 to 45-222, 45-224, 45-225, 45-229, 45-230 when modified by Learjet Service Bulletin 45-57-7)						Ldg	1,987				
45-57-12	**Wings - Main Landing Gear Aft Trunnion Fitting Replacement**							T (-)		Optional	
57 A/F						Mos					
Eff: 22-Jul-2013						Hrs					
						Ldg					
45-57-12 Rev 1	**Wings - Main Landing Gear Aft Trunnion Fitting Replacement**							T (A/R)		Optional	
57 A/F						Mos					
Eff: 29-Aug-2022						Hrs					
(AVG MAN HRS: 23)						Ldg					
45-57-13	**Wings - Wing Spar Inspection**							T (-)		Recommended	
57 A/F						Mos					
Eff: 25-Feb-2019						Hrs					
(AVG MAN HRS: 7.4) (NOTE: COMPLIANCE: This SB is recommended for aircraft with more than 8 years time in service from Certificate of Airworthiness date.)						Ldg					
45-57-13 Rev 1	**Wings - Wing Spar Inspection**							RE (-)		Recommended	
57 A/F						Mos	19-Nov-2022				
Eff: 25-Feb-2019 Complied With						Hrs	5,136.6				
(AVG MAN HRS: 7.4) (NOTE: COMPLIANCE: The time compliance for this inspection is for aircraft that are eight years from Certificate of Airworthiness. Aircraft with greater than eight years from Certificate of Airworthiness have 12 months from February 25, 2019 to comply.)						Ldg	3,167				
45-57-13 Rev 2	**Wings - Wing Spar Inspection**							RE (-)		Recommended	
57 A/F						Mos					
Eff: 22-Jun-2022						Hrs					
(AVG MAN HRS: 27.4)						Ldg					
45-57-14	**Wings - Installation of Fairing Protection Accessory Kit**							T (A/R)		Optional	
57 A/F						Mos					
Eff: 26-Apr-2021						Hrs					
(AVG MAN HRS: 13)						Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-57-2		**Wings - Installation of Body/Wing Rub Strip**							RE (-)		Recommended	
57 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-57-2 Rev 1		**Wings - Installation of Body/Wing Rub Strip**							RE (-)		Recommended	
57 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-57-2 Rev 2		**Wings - Installation of Body/Wing Rub Strip**							RE (-)		Recommended	
57 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-57-2 Rev 3		**Wings - Installation of Body/Wing Rub Strip**							RE (-)		Recommended	
57 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-57-2 Rev 4		**Wings - Installation of Body/Wing Rub Strip**							RE (-)		Recommended	
57 A/F							Mos	08-Jun-2009				
Not Applicable		PER A/C S/N					Hrs	801				
							Ldg	521				
45-57-2 Rev 5		**Wings - Installation of Body/Wing Rub Strip**							RE (-)		Recommended	
57 A/F							Mos	14-Dec-2020				
Eff: 08-Sep-2009 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-57-3		**Wings - Modification of Wing and Main Landing Gear Hydraulic Tubes**							RE (-)		Recommended	
57 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-57-3 Rev 1		**Wings - Modification of Wing and Main Landing Gear Hydraulic Tubes**							RE (-)		Recommended	
57 A/F							Mos	14-Dec-2020				
Eff: 11-Jan-2002 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-57-4		**Wings - Installation of Flux Valve Reinforcement Kit**							RE (-)		Recommended	
57 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-57-4 Rev 1		**Wings - Installation of Flux Valve Reinforcement Kit**							RE (-)		Recommended	
57 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-57-4 Rev 2		**Wings - Installation of Flux Valve Reinforcement Kit**							RE (-)		Recommended	
57 A/F							Mos	14-Dec-2020				
Eff: 11-Jan-2002 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-57-5		**Wings - Inspection/Replacement of Flux Valve Bracket**							RE (-)		Recommended	
57 A/F							Mos	13-Mar-2008				
Not Applicable		BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-57-5 Rev 1		**Wings - Inspection/Replacement of Flux Valve Bracket**							RE (-)		Recommended	
57 A/F							Mos	14-Dec-2020				
Eff: 11-Jan-2002 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-57-6	**Wings - Replacement of the Main Landing Gear Trunnion Shear Pins**							RE (-)		Recommended	
57 A/F						Mos	13-Mar-2008				
Eff: 09-Jun-2003 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 22)						Ldg	8				
45-57-6 Rev 1	**Wings - Replacement of the Main Landing Gear Trunnion Shear Pins**							RE (-)		Recommended	
57 A/F						Mos	13-Mar-2008				
Eff: 19-Sep-2003 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 22)						Ldg	8				
45-57-6 Rev 2	**Wings - Replacement of the Main Landing Gear Trunnion Shear Pins**							RE (-)		Recommended	
57 A/F						Mos	08-Jun-2009				
Eff: 18-Sep-2006 Not Applicable	PER A/C S/N					Hrs	801				
(AVG MAN HRS: 22)						Ldg	521				
45-57-6 Rev 3	**Wings - Replacement of the Main Landing Gear Trunnion Shear Pins**							RE (-)		Recommended	
57 A/F						Mos	14-Dec-2020				
Eff: 02-Sep-2014 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 22)						Ldg	2,822				
45-57-7	**Wings - Modification of Main Landing Gear Trunnion Assemblies**							RE (-)		Recommended	
57 A/F						Mos	13-Mar-2008				
Eff: 19-Sep-2003 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 60)						Ldg	8				
45-57-7 Rev 1	**Wings - Modification of Main Landing Gear Trunnion Assemblies**							RE (-)		Recommended	
57 A/F						Mos	13-Mar-2008				
Eff: 19-Mar-2004 Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
(AVG MAN HRS: 60)						Ldg	8				
45-57-7 Rev 2	**Wings - Modification of Main Landing Gear Trunnion Assemblies**							RE (-)		Recommended	
57 A/F						Mos	08-Jun-2009				
Eff: 18-Sep-2006 Not Applicable	PER A/C S/N					Hrs	801				
(AVG MAN HRS: 60)						Ldg	521				
45-57-7 Rev 3	**Wings - Modification of Main Landing Gear Trunnion Assemblies**							RE (-)		Recommended	
57 A/F						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 60)						Ldg	2,822				
45-57-8	**Structures - Installation of Wing Attachment Link Assembly Phenolic Washer**							RE (-)		Optional	
57 A/F						Mos	29-Aug-2019				
Eff: 06-Apr-2009 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-57-9	**Wings - Flap/Spoiler Shroud Hinged Panel Stiffener Inspection/Replacement**							RE (-)		Recommended	
57 A/F						Mos	14-Dec-2020				
Eff: 16-Jun-2008 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
75-57-01	**Wings - Wing Spar Inspection**							RE (-)		Recommended	
57 A/F						Mos					
Eff: 25-Feb-2019						Hrs					
(AVG MAN HRS: 7.4)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
75-57-01 Rev 1	**Wings - Wing Spar Inspection**							RE (-)		Recommended	
57 A/F						Mos					
Eff: 26-Oct-2020						Hrs					
(AVG MAN HRS: 7.4)						Ldg					
75-57-01 Rev 2	**Wings - Wing Spar Inspection**							RE (-)		Recommended	
57 A/F						Mos	19-Nov-2022				
Eff: 19-Apr-2021 Complied With						Hrs	5,136.6				
(AVG MAN HRS: 7.4)						Ldg	3,167				
75-57-02	**Wings - Installation of Fairing Protection Accessory Kit**							RE (-)		Optional	
57 A/F						Mos					
Eff: 26-Apr-2021						Hrs					
(AVG MAN HRS: 13)						Ldg					
A45-57-1	**Wings - Modification of Aileron Pile Seals**							RE (-)		Alert	
57 A/F						Mos	13-Mar-2008				
Eff: 02-Feb-1999 Not Applicable	BY SERIAL NUMBER					Hrs					
(AVG MAN HRS: 5)						Ldg					
A45-57-1 Rev 1	**Wings - Modification of Aileron Pile Seals**							RE (-)		Alert	
57 A/F						Mos	14-Dec-2020				
Eff: 31-Aug-1999 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 5)						Ldg	2,822				
A5760004	*** (Left) Aileron Bolts (P/N NAS6204-16H) - Replacement**							RE	TLMC 05-19-01, Ch.5 Interval		**≈10-Dec-2027**
57 A/F						Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
(ZONE: 540) (SOURCE: MM-104, MM-105)						Ldg					
A5760004	*** (Right) Aileron Bolts (P/N NAS6204-16H) - Replacement**							RE	TLMC 05-19-01, Ch.5 Interval		**≈10-Dec-2027**
57 A/F						Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
(ZONE: 640) (SOURCE: MM-104, MM-105)						Ldg					
AC5710190	*** Wing Center Section (Panels 510AC, 510BC, 510BL & 610BR removed and panels 510AL, 610AR, 720BL, & 730BR lowered) - Perform Visual Inspection. Inspect structure for corrosion or deterioration of protective treatment.**							RE	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Yrs	25-Jun-2021	8		25-Jun-2029	5.1 Years
						Hrs	4,694.8				
						Ldg	2,882				
Eff: 25-Feb-2019											
Ref:57-10-00 (ZONE: 510AC,510AL,510BC,510BL,610AR,610BR,720BL,730BR) (SOURCE: MM-104, MM-105) (NOTE: For Aircraft with more than 8 years from C of A on February 25, 2019, perform inspection within 12 months.)											
AW 57-004	**Change In The Replacement Schedule Of Main Landing Gear Trunnion Assembly Block Shear Pins**							RE (-)		Advisory Wire	
57 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
E5710005	*** Wing Center Section Spar Upper Caps - Perform visual inspection. Inspect front, mid, and rear spar upper caps from centerline to skin termination at WS 33.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg					
E5710019	*** Wing Box, Upper Skin, Skin/Stringer and Spar Caps - Perform visual inspection. Inspect upper wing spar caps, skin panel, and stringers of outer wing.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
Alias1:5-10-00 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
E5710020	*** Wing Box Ribs - Perform visual inspection. Inspect all wing box ribs except closing rib between front and mid spars and closing rib between mid and rear spar.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5750051	*** Flap Main Track Rollers - Perform visual inspection with flaps removed.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Apr-2028**
57 A/F						Mos					
						Hrs		10,000		10,000	4,725.2 Hrs
	Alias1:5-10-00 (ZONE: 540BL, 540CL, 540JL, 540KL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5750052	*** Flap Nose Rollers - Perform visual inspection with flaps removed.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈08-Dec-2025**
57 A/F						Mos					
						Hrs		7,200		7,200	1,925.2 Hrs
	Alias1:5-10-00 (ZONE: 540BL, 540CL, 540JL, 540KL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
E5760006	*** Aileron Basic Structure - Perform visual inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg					
L5710124	*** Aileron Drive Support - Perform Ultrasonic Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:27-10-01 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 27-10-01.))					Ldg	2,822				
N5710002	*** Wing Box Mid Spar Lower Cap, Outboard of Joint at WS 137 between Rib #7 and 8 - Perform Directed Visual Inspection. Inspect mid spar lower cap and lower skin panels.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Dec-2027**
57 A/F						Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:5-10-00 (ZONE: 520GL, 620GR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).""))					Ldg					
N5710004	*** Wing Center Section Rear Spar - Perform Eddy Current Inspection. Inspect rear spar lower cap from centerline to WS 33.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	NDI-104:Part 6 / 57-20-02 (ZONE: 250CC, 250FL, 250GR, 510BC) (SOURCE: MM-104, MM-105)					Ldg	2,822				
N5710006	*** Wing Center Section Forward and Aft Ribs at WS 6 and Forward Ribs at WS 17 - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	NDI-104:Part 6, 57-10-06 (ZONE: 510AC, 510AL, 610AR, 510BC) (SOURCE: MM-104, MM-105)					Ldg	2,822				
N5710008	*** Wing Box Mid Spar Lower Cap - Perform Ultrasonic Inspection. Inspect mid spar lower cap and lower skin panels between WS 99 and WS 137.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Dec-2027**
57 A/F						Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-30-03 (ZONE: 520EL, 520FL, 620ER, 620GR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 57- 30-03.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).""))					Ldg					
N5710009	*** Wing Box Mid Spar Lower Cap Joint at WS 137 - Perform X-ray Inspection. Inspect mid spar center/outer joint.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Dec-2027**
57 A/F						Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-02 (ZONE: 520FL, 520GL, 620FR, 620GR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 2, 57-10-02.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).""))					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
N5710010		*** Wing Box Rear Spar Lower Cap Inboard of Joint at WS 81 - Perform Ultrasonic Inspection. Inspect rear spar lower cap between skin termination at WS 48 and closing rib at WS 60.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Dec-2027**
	57 A/F						Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:57-30-01 (ZONE: Remove flaps) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 57-30-01.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))"					Ldg					
N5710011		*** Wing Box Rear Spar Lower Cap Joint at WS 81 - Perform X-ray Inspection. Inspect center and outer rear spars, lower splice plate, and lower skin between WS 60 and WS 90.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
	57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		Alias1:57-10-03 (ZONE: 510AZ/ 610AZ, 520CL/ 620CR, 520DL/ 620DR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104] Part 2, 57-10-03.) (Effective on aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))"					Ldg	2,822				
N5710012		*** Wing Box Rear Spar Lower Cap Outboard of Joint at WS 81 to Rib #6 - Perform Detailed Visual Inspection. Inspect outer rear spar lower cap and aft lower skin panel outboard of rear splice at WS 90.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Dec-2027**
	57 A/F						Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:5-10-00 (ZONE: 520DL, 620DR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))"					Ldg					
N5710013		*** Wing Box Rear Spar Lower Cap Skin Termination at MS 48 - Perform Eddy Current Inspection. Inspect rear spar lower cap between WS 33 and WS 48.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Apr-2028**
	57 A/F						Mos					
							Hrs		10,000		10,000	4,725.2 Hrs
		Alias1:57-20-04 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-20- 04.) (Effective on Aircraft not modified per SB 45- 11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))"					Ldg					
N5710014		*** Wing Box Rear Spar Flap Track Cutouts - Perform Eddy Current Inspection. Inspect flap track cutouts at WS 65, WS 126, and WS 184 on rear spar.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		NDI-104:Part 6, 57-20-01 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-20-01.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))"					Ldg	2,822				
N5710016		*** Wing Box Basic Skin/Stringer, Lower Skin - Perform Visual Inspection. Inspect outboard wing forward and aft lower skin panels and stringers.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Ref:5-10-00 (ZONE: 520AL thru 520ML, and 620AR thru 620MR) (SOURCE: MM-104, MM-105)					Ldg	2,822				
N5710017		*** Wing Box Basic Skin/Stringer at Stringer Run-Out, Lower Skin - Perform Visual Inspection. Inspect stringer run-outs in forward and aft lower skin panels.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
	57 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Ref:5-10-00 (ZONE: 520AL thru 520ML, and 620AR thru 620MR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")					Ldg					
N5710021		*** Center Section Mid Spar Lower Cap - Perform Eddy Current Inspection. Inspect mid spar from centerline splice plate to skin termination at MS 33.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
	57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		NDI-104:Part 6, 57-10-02 (ZONE: 520AL, 520BL, 520CL, 620AR, 620BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-10- 02.) (Effective on aircraft not modified per SB 45- 11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))"					Ldg	2,822				
N5710022		*** Center Section Mid Spar Centerline Joint - Perform Eddy Current Inspection. Inspect center mid spar (centerline to WS 17), lower splice plate, and center mid spar joint fitting lower cap.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
	57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		NDI-104: Part 6, 57-10-08, NDI-104:Part 6, 57-10-10 (ZONE: 520AL, 520BL, 520CL, 620AR, 620BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-10-08 and 57- 10-10.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))"					Ldg	2,822				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
N5710023		*** Center Section Front Spar Lower Cap - Perform Eddy Current Inspection. Inspect center wing front spar lower cap between skin terminations (WS 31 left to WS 31 right).**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
	57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		NDI-104:Part 6, 57-10-03 (ZONE: 250BC,250BL,250CR,510AC,520AL,520BL,620AR,620BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI- 104], Part 6, 57-10-03.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg	2,822				
N5710026		*** Wing Box Mid Spar Lower Cap - Perform Ultrasonic Inspection. Inspect mid spar lower cap outboard of root rib at WS 33 to WS 99.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Apr-2028**
	57 A/F						Mos					
							Hrs		10,000		10,000	4,725.2 Hrs
		Alias1:57-30-03 (ZONE: 520AL thru 520DL, and 620AR thru 620DR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 57-30-03.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710028		*** Wing Box Mid Spar Lower Cap, Skin Termination at WS 33 - Perform Bolt Hole Eddy Current Inspection. Inspect mid spar lower cap underneath root rib (WS 33) at point of skin termination.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		NDI-104:Part 6, 57-10-11 (ZONE: 520AL/ 620AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-10-11.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")					Ldg	2,822				
N5710031		*** Wing Box Skin Access Cover Holes - Perform Eddy Current Inspection. Inspect access holes in forward and aft lower skin panels.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		NDI-104:Part 6, 57-30-01 (ZONE: 520AL thru 520ML, 620AR thru 620MR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-30-01.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")					Ldg	2,822				
N5710037		*** Wing Box Front Spar Lower Cap - Perform Visual Inspection. Inspect front spar lower cap and lower forward skin outboard of Mid-Spar Station (MS) 55.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
	57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		Ref:5-10-00 (ZONE: 520BL thru 520ML and 620BR thru 620MR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg	2,822				
N5710084		**Spoiler, Center Hinge Spoiler Side - Perform NDI Inspection.**							RE	TLMC 05-14-04		**≈12-Oct-2025**
	57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		Alias1:57-40-01 (ZONE: 500/600) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, Section 57-40-01.))					Ldg	2,822				
N5710121		*** Wing Box Mid Spar, Outboard of Rib #8 - Perform Visual Inspection at WS 156 and outboard to WS 260.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Ref:5-10-00 (ZONE: 520HL thru 520ML and 620HR thru 620MR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg	2,822				
N5710122		*** Wing Box Rear Spar, Outboard of Rib #6 - Perform Visual Inspection at WS 118 and outboard to WS 260.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Ref:5-10-00 (ZONE: 520FL thru 520ML and 620FR thru 620MR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg	2,822				
N5710123		*** Wing Box Mid Spar Lower Cap - Perform Eddy Current Inspection at trunnion fitting.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Dec-2027**
	57 A/F						Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:57-10-01 (ZONE: 520/620) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-10-01.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
N5710137		*** Mid Spar at Rib #2 near WS 48 - Perform Bolt Hole Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F		05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		9,410.5	4,135.7 Hrs
		NDI-104:Part 6, 57-10-11 (ZONE: 520BL, 620BR) (SOURCE: MM-104, MM-105)					Ldg	2,822				
N5710138		*** Mid Spar at Rib #3 near WS 60 - Perform Bolt Hole Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F		05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		NDI-104:Part 6 / 57-10-11 (ZONE: 520CL, 620CR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-10-11.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")					Ldg	2,822				
N5710139		*** Forward Flange Fasteners at Rear Spar between WS 52 and WS 60 - Perform Bolt Hole Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
57 A/F		05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		NDI-104:Part 6 / 57-20-03 (ZONE: 510AZ, 610AZ) (SOURCE: MM-104, MM-105) (NOTE: (Effective on Aircraft not modified per SB 45- 11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg	2,822				
N5710148		*** Wing Center Section Rear Spar - Perform Eddy Current Inspection. Inspect rear spar lower cap from centerline to WS 33.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F							Mos	21-May-2019				
							Hrs	4,461.2				
		Alias1:57-20-02 (ZONE: 250CC, 250FL, 250GR, 510BC) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-20-02.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg	2,673				
N5710149		*** Wing Center Section Forward and Aft Ribs at WS 6 and Forward Ribs at WS 17 - Perform Eddy Current Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F							Mos					
							Hrs					
		Alias1:57-10-06 (ZONE: 510AC, 510AL, 610AR, 510BC) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI- 104], Part 6, 57-10-06.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710150		*** Wing Box Mid Spar Lower Cap - Perform Ultrasonic Inspection. Inspect mid spar lower cap and lower skin panels between WS 99 and WS 137.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F							Mos					
							Hrs					
		Alias1:57-30-03 (ZONE: 520EL, 520GL, 620ER, 620GR) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 57- 30-03.) (Effective on Aircraft modified per SB 45- 11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710151		*** Wing Box Mid Spar Lower Cap Joint at WS 137 - Perform X-ray Inspection. Inspect mid spar center/ outer joint.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F							Mos					
							Hrs					
		Alias1:57-10-02 (ZONE: 520FL, 520GL, 620FR, 620GR) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 2, 57-10-02.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710152		*** Wing Box Rear Spar Lower Cap Inboard of Joint at WS 81 - Perform Ultrasonic Inspection. Inspect rear spar lower cap between skin termination at WS 48 and closing rib at WS 60.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F							Mos					
							Hrs					
		Alias1:57-30-01 (ZONE: 500/600) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 57-30-01.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710153		*** Wing Box Rear Spar Lower Cap Joint at WS 81 - Perform X-ray Inspection. Inspect center and outer rear spars, lower splice plate, and lower skin be- tween WS 60 and WS 90.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F							Mos					
							Hrs					
		Alias1:57-10-03 (ZONE: 510AZ, 520CL, 520DL, 610AZ, 620CR, 620DR) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 2, 57-10-03.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710155		*** Wing Box Rear Spar Lower Cap Skin Termination at MS 48 - Perform Eddy Current Inspection. Inspect rear spar lower cap between WS 33 and WS 48.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F							Mos					
							Hrs					
		Alias1:57-20-04 (ZONE: 510/610) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-20- 04.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
N5710157	*** Wing Box Basic Skin/Stringer Run-Out, Lower Skin - Perform Visual Inspection. Inspect Stringer run-outs in forward and aft lower skin panels.**							RE (N/A)	TLMC 04-10-01, TLMC 05-15-00		
57 A/F						Mos	14-Dec-2020				
						Hrs	4,610.5				
	Alias1:5-10-00 (ZONE: 520AL thru 520ML and 620AR thru 620MR) (SOURCE: MM-104) (NOTE: (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")) Ldg 2,822					Ldg	2,822				
N5710158	*** Center Section Front Spar Lower Cap - Perform Eddy Current Inspection. Inspect center wing front spar lower cap between skin terminations (WS 31 left to WS 31 right).**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-10-03 (ZONE: 250BC,250BL,250CR,510AC,520AL,520BL,620AR,620BR) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-10-03.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")) Ldg					Ldg					
N5710159	*** Wing Box Mid Spar Lower Cap - Perform Ultrasonic Inspection. Inspect mid spar lower cap outboard of root rib at WS 33 to WS 99.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-30-03 (ZONE: 520AL,520BL,520CL,520DL,620AR,620BR,620CR,620DR) (SOURCE: MM-104) (NOTE: (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")) Ldg					Ldg					
N5710160	*** Wing Box Mid Spar Lower Cap, Skin Termination at WS 33 - Perform Bolt Hole Eddy Current Inspection. Inspect mid spar lower cap underneath root rib (WS 33) at point of skin termination.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-10-11 (ZONE: 520AL, 620AR) (SOURCE: MM-104) (NOTE: (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")) Ldg					Ldg					
N5710161	*** Wing Box Skin Access Cover Holes - Perform Eddy Current Inspection. Inspect access holes in forward and aft lower skin panels.**							RE (N/A)	TLMC 05-14-04		
57 A/F						Mos	14-Dec-2020				
						Hrs	4,610.5				
	Alias1:57-30-01 (ZONE: 520AL thru 520ML and 620AR thru 620MR) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-30-01.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds), and Effective on Aircraft not modified per SB 45-5-1 "Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program")) Ldg 2,822					Ldg	2,822				
N5710163	*** Center Section Mid Spar Centerline Joint - Perform Eddy Current Inspection. Inspect center mid spar (centerline to WS 17), lower splice plate, and center mid spar joint fitting lower cap.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-10-10 (ZONE: 520AL, 520BL, 520CL, 620AR, 620BR) (SOURCE: MM-104) (NOTE: (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")) Ldg					Ldg					
N5710164	*** Center Section Mid Spar Lower Cap - Perform Eddy Current Inspection. Inspect mid spar from centerline splice plate to skin termination at MS 33.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-10-02 (ZONE: 520AL, 520BL, 520CL, 620AR, 620BR) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-10-02.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")) Ldg					Ldg					
N5710165	*** Wing Box Rear Spar Flap Track Cut-outs - Perform Eddy Current Inspection. Inspect flap track cut-outs at WS 65, WS 126, and WS 184 on rear spar.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-20-01 (ZONE: 500/600) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-20-01.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")) Ldg					Ldg					
N5710168	*** Wing Box Mid Spar Lower Cap - Perform Eddy Current Inspection at trunnion fitting.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-10-01 (ZONE: 520/620) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104] Part 6, 57-10-01.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")) Ldg					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
N5710169	*** Mid Spar at Rib #2 near WS 48 - Perform Bolt Hole Eddy Current Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	NDI-104:Part 6, 57-10-11A (ZONE: 520BL, 620BR) (SOURCE: MM-104) (NOTE: Effective on Aircraft modified by SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")					Ldg					
N5710170	*** Mid Spar at Rib #3 near WS 60 - Perform Bolt Hole Eddy Current Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	NDI-104:Part 6, 57-10-11A (ZONE: 520CL, 620CR) (SOURCE: MM-104) (NOTE: Effective on Aircraft modified by SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).")					Ldg					
N5710171	*** Forward Flange Fasteners at Rear Spar between WS 52 and WS 60 - Perform Bolt Hole Eddy Current Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-20-03 (ZONE: 510AZ, 610AZ) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI- 104] Part 6, 57-20-03.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710172	*** Wing Box Mid Spar Lower Cap - Perform Ultrasonic Inspection at trunnion fitting.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Dec-2027**
57 A/F						Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-00 (ZONE: 520/620) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104] Part 4, 57-10-00.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710173	*** Wing Box Mid Spar Lower Cap - Perform Ultrasonic Inspection at trunnion fitting.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-10-00 (ZONE: 520/620) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104] Part 4, 57-10-00.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710174	*** Wing Box Rear Spar Lower Cap Skin Termination at MS 48 - Perform Ultrasonic Inspection. Inspect rear spar lower cap between WS 33 and WS 48.**							T	TLMC 04-10-01, TLMC 05-19-00		**≈10-Apr-2028**
57 A/F						Mos					
						Hrs		10,000		10,000	4,725.2 Hrs
	Alias1:57-30-04 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104] Part 4, 57-30-04.) (Effective on Aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710175	*** Wing Box Rear Spar Lower Cap Skin Termination at MS 48 - Perform Ultrasonic Inspection. Inspect rear spar lower cap between WS 33 and WS 48.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-30-04 (ZONE: 510/610) (SOURCE: MM-104) (NOTE: (Refer to NDI Manual [NDI-104], Part 4, 57-30-04.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5710176	*** Wing Mid Spar (Center Section) Lower Cap and Center Joint Fitting - Perform Ultrasonic Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:57-30-05 (ZONE: 520AL, 520BL, 520CL, 620AR, 620BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual, [NDI-104], Part 4, 57-30-05.) (Effective on aircraft not modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg	2,822				
N5710177	*** Wing Mid Spar (Center Section) Lower Cap and Center Joint Fitting - Perform Ultrasonic Inspection.**							RE (N/A)	TLMC 04-10-01, TLMC 05-19-00		
57 A/F						Mos					
						Hrs					
	Alias1:57-30-05 (ZONE: 520AL, 520BL, 520CL, 620AR, 620BR) (SOURCE: MM-104) (NOTE: (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)."))					Ldg					
N5750005	*** Flap Main Track Hinge Fittings, Track, and Flap Box Sides - Perform visual inspection. Inspect main track hinge fittings on track and flap box sides.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 540BL,540CL,540JL,540KL,640BR,640CR,640JR,640KR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P5710001		*** Wing Drag Link Attach Fitting - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval	**≈12-Oct-2025**	
	57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		Ref:NDI-104, Part 7, 57-30-02 (ZONE: 250DL, 250CL, 250ER, 250DR, 510BL, 610BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI- 104], Part 7, 57-30-00.))					Ldg	2,822				
P5710007		*** Wing to Fuselage Attach Fittings and Links - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Alias1:57-10-12 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-10-12.))					Ldg	2,822				
P5710015		*** Wing Box Rear Spar at Aileron Hinge - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Alias1:57-10-20 (ZONE: 540DZ,540EZ,540FZ,540GZ,640DZ,640EZ,640FZ,640GZ) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI- 104], Part 6, 57-10-20.))					Ldg	2,822				
P5710018		*** Wing Lower Skin at Mid Spar Span Wise Joint - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
	57 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:57-10-09 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-09.))					Ldg					
P5710024		*** Wing Rear Spar Side Stay Fitting Support Structure - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Alias1:57-20-06 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-20-06.))					Ldg	2,822				
P5710025		*** Wing Front Spar Lower Cap from WS 33.0 to WS 60.0 - Perform Radiographic Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval	**≈12-Oct-2025**	
	57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
							Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
		Alias1:57-10-01 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 2, 57-10-01.))					Ldg	2,822				
P5710029		*** Wing Mid Spar Vertical Web - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
	57 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:57-10-07 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-07.))					Ldg					
P5710030		*** Wing Rear Spar Vertical Web - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval	**≈10-Dec-2027**	
	57 A/F	05-16-00					Mos					
							Hrs		9,600		9,600	4,325.2 Hrs
		Alias1:57-20-05 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-20-05.))					Ldg					
P5710032		*** Wing Rib Upper Aft Flange Fillet Radius at WS 33.0 - Perform Ultrasonic Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Alias1:57-30-02 (ZONE: 520AL, 620AR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 4, 57-30-02.))					Ldg	2,822				
P5710033		*** Wing Access Hole in Closing Rib between Mid Spar and Rear Spar - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval	**≈14-Oct-2027**	
	57 A/F	05-15-00					Mos	10-Feb-2021				
							Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
		Alias1:57-10-05 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-05.))					Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
P5710034	*** Wing Box Joint to Winglet - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-10-13 (ZONE: 550CL, 650CR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-13.))					Ldg	2,822				
P5710035	*** Wing Lower Skin at Drain Hole - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-30-02 (ZONE: 520/620) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI- 104], Part 6, 57-30-02.))					Ldg	2,822				
P5710083	*** Flap Box Basic Structure - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-40-02 (ZONE: 550/650) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-40-02.))					Ldg	2,822				
P5710085	**Spoiler Upper Skin - Perform Eddy Current Inspection.**							RE		TLMC 05-15-00	**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-10-16 (ZONE: 550/650) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-16.))					Ldg	2,822				
P5710086	**Spoiler Bolts and Hinge Pins - Perform Magnetic Particle Inspection.**							RE		TLMC 05-15-00	**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	(9,410.5)	4,135.7 Hrs (+25)
	Alias1:27-10-01 (ZONE: 550/650) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI- 104], Part 7, 27-10-01.))					Ldg	2,822				
P5710181	*** Wing Drag Link Tube - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:57-30-01 (ZONE: 250DL, 250CL, 250ER, 250DR, 510BL, 610BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 7, 57-30-01.))					Ldg	2,822				
P5710182	*** Wing Drag Link Attach Bolts - Perform Liquid Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:57-10-01 (ZONE: 250DL, 250CL, 250ER, 250DR, 510BL, 610BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 8, 57-10-01.))					Ldg	2,822				
P5710183	*** Wing Drag Link Attach Clevis - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:57-10-01 (ZONE: 250DL, 250CL, 250ER, 250DR, 510BL, 610BR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 57-10-01.))					Ldg	2,822				
P5710184	*** Wing Attach Bolts - Perform Fluorescent Penetrant Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-10-02 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 8, 57-10-02.))					Ldg	2,822				
P5710185	*** Wing Attach Links - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-10-03 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 7, 57-10-03.))					Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
P5710186	*** Wing Attach Fittings at Mid Spar and Rear Spar - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-10-02 (ZONE: 510/610) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 7, 57-10-02.))					Ldg	2,822				
P5750002	*** Flap Front-Spar Cutouts - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:57-10-15 (ZONE: 540BL,540CL,540JL,540KL,640BR,640CR,640JR,640KR) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-15.))					Ldg	2,822				
P5750003	*** Flap Nose Roller Ribs - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-10-14 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-14.))					Ldg	2,822				
P5750004	*** Flap Actuator Support Ribs - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-21 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI- 104], Part 6, 57-10-21.))					Ldg					
P5750048	*** Flap Tracks - Perform Magnetic Particle Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-71-01 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 7, 57-71-01.))					Ldg					
P5750049	*** Flap Nose Roller Tracks - Perform Magnetic Particle Inspection with flaps removed.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-04 (ZONE: 540BL, 540CL, 540JL, 540KL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 7, 57-10-04.))					Ldg					
P5750053	*** Flap Track Support Ribs - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-17 (ZONE: 540BL, 540CL, 540JL, 540KL) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-17.))					Ldg					
P5750068	*** Flap Front Spar Rib Support Structure - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-10-26 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-26.))					Ldg	2,822				
P5760000	*** Aileron Actuator Hinge Fitting - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-25 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-25.))					Ldg					
P5760001	*** Aileron Skin - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-19 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10- 19.))					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
P5760002	*** Aileron Balance Tab Hinge Fittings - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-14-04, Ch.5 Interval		**≈12-Oct-2025**
57 A/F	05-14-04					Mos	10-Feb-2021	96		(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400		(7,010.5)	1,735.7 Hrs (+25)
	Alias1:57-60-01 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 57-60-01.))					Ldg	2,822				
P5760003	*** Aileron Trim and Balance Tab Front Spars - Perform Radiographic Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-60-01 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI-Manual [NDI-104], Part 2, 57-60-01.))					Ldg	2,822				
P5760005	*** Aileron Hinge Lugs and Fittings - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-24 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-24.))					Ldg					
P5760014	*** Aileron Hinge Support Structure - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-16-00, Ch.5 Interval		**≈10-Dec-2027**
57 A/F	05-16-00					Mos					
						Hrs		9,600		9,600	4,325.2 Hrs
	Alias1:57-10-23 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-23.))					Ldg					
P5770000	**Spoiler Hinge Assemblies and Actuator Fitting - Perform Eddy Current Inspection.**							RE		TLMC 05-15-00	**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	(9,410.5)	4,135.7 Hrs (+25)
	Alias1:57-10-22 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10-22.))					Ldg	2,822				
Q5710156	*** Wing Box Basic Skin/Stringer, Lower Skin - Perform Visual Inspection. Inspect outboard wing forward and aft lower skin panels and stringers.**							RE (N/A)	TLMC 04-10-01, TLMC 05-14-04		
57 A/F						Mos	14-Dec-2020				
						Hrs	4,610.5				
	Ref:5-10-00 (ZONE: 520AL thru 520ML and 620AR thru 620MR) (SOURCE: MM-104) (NOTE: (Effective on aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).""))					Ldg	2,822				
Q5710162	*** Wing Box Front Spar Lower Cap - Perform Visual Inspection. Inspect front spar lower cap and lower forward skin outboard of Mid-Spar Station (MS) 55.**							RE (N/A)		TLMC 05-14-04	
57 A/F						Mos	14-Dec-2020				
						Hrs	4,610.5				
	Alias1:5-10-00 (ZONE: 520BL thru 520ML and 620BR thru 620MR) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds), and Effective on Aircraft not modified per SB 45-5-1 "Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program"))					Ldg	2,822				
Q5710166	*** Wing Box Mid Spar, Outboard of Rib #8 - Perform Visual Inspection at WS 156 and outboard to WS 260.**							RE (N/A)		TLMC 05-14-04	
57 A/F						Mos	14-Dec-2020				
						Hrs	4,610.5				
	Alias1:5-10-00 (ZONE: 520HL thru 520ML and 620HR thru 620MR) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds), and Effective on Aircraft not modified per SB 45-5-1 "Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program"))					Ldg	2,822				
Q5710167	*** Wing Box Rear Spar, Outboard of Rib #6 - Perform Visual Inspection at WS 118 and outboard to WS 260.**							RE (N/A)		TLMC 05-14-04	
57 A/F						Mos	14-Dec-2020				
						Hrs	4,610.5				
	Alias1:5-10-00 (ZONE: 520FL thru 520ML and 620FR thru 620MR) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds), and Effective on Aircraft not modified per SB 45-5-1 "Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program"))					Ldg	2,822				
U5710147	*** Wing Box Mid Spar Lower Cap, Outboard of Joint at WS 137 between Rib #7 and 8 - Perform Detailed Visual Inspection. Inspect mid spar lower cap and lower skin panels.**							RE (N/A)		TLMC 04-10-01	
57 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8				
	(ZONE: 520GL, 620GR) (SOURCE: MM-104) (NOTE: (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds).""))					Ldg	2,807				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
U5710147	**** Wing Box Mid Spar Lower Cap, Outboard of Joint at WS 137 between Rib #7 and 8 - Perform Detailed Visual Inspection. Inspect mid spar lower cap and lower skin panels.**							RE (N/A)		TLMC 05-12-04	
57 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8				
Alias1:5-10-00 (ZONE: 520GL, 620GR) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds), and Effective on Aircraft not modified per SB 45-5-1 "Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program"))						Ldg	2,807				
U5710154	*** Wing Box Rear Spar Lower Cap Outboard of Joint at WS 81 to Rib #6 - Perform Detailed Visual Inspection. Inspect outer rear spar lower cap and aft lower skin panel outboard of rear splice at WS 90.**							RE (N/A)		TLMC 04-10-01	
57 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8				
(ZONE: 520DL, 620DR) (SOURCE: MM-104) (NOTE: (Effective on aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds)".))						Ldg	2,807				
U5710154	**** Wing Box Rear Spar Lower Cap Outboard of Joint at WS 81 to Rib #6 - Perform Detailed Visual Inspection. Inspect outer rear spar lower cap and aft lower skin panel outboard of rear splice at WS 90.**							RE (N/A)		TLMC 05-12-04, Ch.5 Interval	
57 A/F						Mos	10-Jan-2020				
						Hrs	4,590.8				
Alias1:5-10-00 (ZONE: 520DL, 620DR) (SOURCE: MM-104) (NOTE: (Refer to 5-10-00.) (Effective on Aircraft modified per SB 45-11-5, "Increase Maximum Zero Fuel Weight (16,500 pounds), and Effective on Aircraft not modified per SB 45-5-1 "Time Limits/Maintenance Checks - Transition To Evolved Maintenance Program"))						Ldg	2,807				
V5710039	**Winglet Skin - Perform Eddy Current Inspection.**							RE		TLMC 05-15-00	**≈14-Oct-2027**
57 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800	-/+25	(9,410.5)	4,135.7 Hrs (+25)
Alias1:57-10-18 (ZONE: 550/650) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 57-10- 18.))						Ldg	2,822				
Y5700001	**Winglet - Perform visual inspection.**							RE		TLMC 05-11-04	**≈24-Jul-2024**
57 A/F	05-11-04					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Alias1:5-10-00 (ZONE: 550/650) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y5700002	**Flux Valve Bracket - Visually inspect for cracks.**							RE (N/A)		TLMC 05-11-04	
57 A/F						Mos	20-Oct-2016				
						Hrs	3,654.8				
(ZONE: 550BL, 650BR) (SOURCE: MM-104)						Ldg	2,132				
Y5710000	**Wing - Perform External Visual Inspection from BL 0.00 to WS 260.**							RE		TLMC 05-13-04	**≈24-Apr-2025**
57 A/F	05-13-04					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 510/ 610,530/ 630) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	3,757				
Y5710180	**External Lower Wing Skin - Perform Visual Inspection.**							RE		TLMC 05-12-04	**≈24-Oct-2024**
57 A/F	05-12-04					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 520/620) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	3,757				
Y5730013	**Aileron Brush Seals - Perform Detailed Inspection.**							RE		TLMC 05-11-04	**≈24-Jul-2024**
57 A/F	05-11-04					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
Alias1:57-60-01 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 57-60-01.))						Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y5750067	**Flap Brackets (P/N A159019-1 and A159022-1) - Perform Detailed Visual Inspection.**							RE		TLMC 05-14-04	**≈12-Oct-2025**
57 A/F	05-14-04					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 540/640) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.) NOTE: On flap brackets with over 2400 hours /96 months since Aircraft C of A or last flap bracket replacement, perform at next scheduled inspection.)						Ldg	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y5750069	**Flaps - Perform visual inspection of flap nose rollers, flap tracks, flap nose roller tracks, and flap main track rollers.**							RE		TLMC 05-11-04	**≈24-Jul-2024**
57 A/F	05-11-04					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 500/600) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
Y5750071	**Flaps - With flaps removed, perform Detailed Visual Inspection of flap nose rollers, flap tracks, flap nose roller tracks, and flap main track rollers.**							RE		TLMC 05-13-04	**≈24-Apr-2025**
57 A/F	05-13-04					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 500/600) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
▼ 71 - POWER PLANT											
	Engine - Main Engine Wiring Harness Assembly							RE (O/C)			
71 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Engine - Main Engine Wiring Harness Assembly							RE (O/C)			
71 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Engine Aft Mount Isolator Assembly							RE (O/C)			
71 A/F	Left	0				Mos	13-Mar-2008				
LM-833-SA18	New	0				Hrs	0				
LK1324		0				Ldg	0				
	Engine Aft Mount Isolator Assembly							RE (O/C)			
71 A/F	Right	0				Mos	13-Mar-2008				
LM-833-SA18	New	0				Hrs	0				
LK1351		0				Ldg	0				
	Engine Forward Lower Mount Isolator Assembly							RE (O/C)			
71 A/F	Left	0				Mos	13-Mar-2008				
LM-833-45	New	0				Hrs	0				
LK6202		0				Ldg	0				
	Engine Forward Lower Mount Isolator Assembly							RE (O/C)			
71 A/F	Right	0				Mos	13-Mar-2008				
LM-833-45	New	0				Hrs	0				
LK6115		0				Ldg	0				
	Engine Forward Mount							RE (O/C)			
71 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Forward Mount							RE (O/C)			
71 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Forward Upper Mount Isolator Assembly							RE (O/C)			
71 A/F	Left	0				Mos	13-Mar-2008				
LM-833-45	New	0				Hrs	0				
LK6088		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Forward Upper Mount Isolator Assembly							RE (O/C)			
	71 A/F	Right	0				Mos	13-Mar-2008				
	LM-833-45	New	0				Hrs	0				
	LK6042		0				Ldg	0				
		Engine Inlet Nacelle							RE (O/C)			
	71 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Engine Inlet Nacelle							RE (O/C)			
	71 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Mount, Engine Aft Arm							RE (O/C)			
	71 A/F	Left	0				Mos	13-Mar-2008				
	4571200011-003	New	0				Hrs	0				
	CDF1143		0				Ldg	0				
		Mount, Engine Aft Arm							RE (O/C)			
	71 A/F	Right	0				Mos	13-Mar-2008				
	4571200011-003	New	0				Hrs	0				
	CDF1147		0				Ldg	0				
2005-24-13		**Electrical wire bundle for the alternator on the left-hand engine**							RE (-)		Mandatory	
	71 A/F						Mos	11-Feb-2010				
	Eff: 20-Dec-2005 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
							Ldg	739				
2008-02-19		**High pressure (HP) turbine rotor assemblies**							RE (-)		Mandatory	
	71 ENG1						Mos	11-Nov-2013				
	Eff: 06-Mar-2008 Complied With						Hrs	3,011.7				
							Enc	1,768				
2008-02-19		**High pressure (HP) turbine rotor assemblies**							RE (-)		Mandatory	
	71 ENG2						Mos	11-Nov-2013				
	Eff: 06-Mar-2008 Not Applicable	PER SB A72-5185					Hrs	3,011.7				
							Enc	1,768				
2011-13-10		**Powerplant - Chafed Hydraulic Tubes in the Left-Hand Engine**							RE (-)		Mandatory	
	71 A/F						Mos	20-Jul-2011				
	Eff: 01-Aug-2011 Complied With	AD 2011-13-10 BY C/W SB 45-71-7 ON 1-28-2010					Hrs	2,085.4				
							Ldg	1,254				
2011-13-10 Par. (g)(h)(i)		**Powerplant - Chafed Hydraulic Tubes in the Left-Hand Engine - Repetitive Inspections: Case Drain Tube/Nacelle Tubing/Fluid Leakage**							RE (-)		Mandatory	
	71 A/F						Mos	28-Jan-2010				
	Eff: 01-Aug-2011 Complied With						Hrs	1,172.9				
							Ldg	723				
2011-13-10 Para (G)		**Detailed Inspection Chafed Hydraulic Tubes In The Left-Hand Engine For Chafing And Other Damage Of The Case Drain Tube From The Hydraulic Pump Case Installed On The Left-Hand Engine (Mandatory)**							RE (-)		Mandatory	
	71 A/F						Mos	20-Jul-2011				
	Complied With						Hrs	2,085.4				
							Ldg	1,254				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2011-13-10 Para (H)	**Detailed Inspection Chafed Hydraulic Tubes In The Left-Hand Engine For Discrepancies Of The Left Engine'S Nacelle To Include Damaged Tubing, And Inadequate Clearance Between Any Unsupported Section Of The Tube Or Other Tubing And Surrounding Components (Mandatory)**							RE (-)		Mandatory	
71 A/F						Mos	20-Jul-2011				
Complied With						Hrs	2,085.4				
						Ldg	1,254				
2011-13-10 Para (I)	**Detailed Inspection Chafed Hydraulic Tubes In The Left-Hand Engine For Evidence Of Engine Oil, Hydraulic Fluid, Or Fuel Leakage Within The Left Engine Accessory Compartment, And Clean And Remove All Evidence Of Fluid Leakage (Mandatory)**							RE (-)		Mandatory	
71 A/F						Mos	20-Jul-2011				
Complied With						Hrs	2,085.4				
						Ldg	1,254				
2011-13-10 Para (J)	**Replace Chafed Hydraulic Tubes In The Left-Hand Engine Each Clamp Associated With The Fluid Leakage Or Inadequate Clearance With A New Clamp, In Accordance With The Applicable Maintenance Manual (Mandatory)**							RE (-)		Mandatory	
71 A/F						Mos	20-Jul-2011				
Complied With						Hrs	2,085.4				
						Ldg	1,254				
2011-13-10 Para (l)	**Powerplant - Chafed Hydraulic Tubes in the Left-Hand Engine - Terminating Action**							RE (-)		Mandatory	
71 A/F						Mos	20-Jul-2011				
Eff: 01-Aug-2011 Complied With	AD 2011-13-10 BY C/W SB 45-71-7 ON 1-28-2010					Hrs	2,085.4				
						Ldg	1,254				
2011-13-10 Para (m)	**Powerplant - Chafed Hydraulic Tubes in the Left-Hand Engine - Terminating Action**							RE (-)		Mandatory	
71 A/F						Mos	20-Jul-2011				
Eff: 01-Aug-2011 Complied With	AD 2011-13-10 BY C/W SB 45-71-7 ON 1-28-2010					Hrs	2,085.4				
						Ldg	1,254				
2012-16-14	**LPT2 Rotor Blades**							RE (-)		Mandatory	
71 ENG1						Mos	06-Sep-2017				
Eff: 01-Oct-2012 Not Applicable						Hrs					
(NOTE: Not to exceed 3,000 hours time-since-new)						Enc					
2012-16-14	**LPT2 Rotor Blades**							RE (-)		Mandatory	
71 ENG2						Mos	06-Sep-2017				
Eff: 01-Oct-2012 Not Applicable						Hrs					
(NOTE: Not to exceed 3,000 hours time-since-new)						Enc					
2014-12-52	**Engines**							RE (-)		Mandatory	
71 ENG1						Mos	05-Aug-2014				
Eff: 28-Jul-2014 Complied With						Hrs	3,243.9				
(NOTE: Engines with 2nd stage low-pressure turbine (LPT2) blades, part number (P/N) 3075424-1, -2, or -3, installed.)						Enc	1,896				
2014-12-52	**Engines**							RE (-)		Mandatory	
71 ENG2						Mos	05-Aug-2014				
Eff: 28-Jul-2014 Complied With						Hrs	3,243.9				
(NOTE: Engines with 2nd stage low-pressure turbine (LPT2) blades, part number (P/N) 3075424-1, -2, or -3, installed.)						Enc	1,896				
2014-12-52-E	**Emergency AD -2nd Stage Low-Pressure Turbine (LPT2) Blade**							RE (-)		Mandatory	
71 ENG1						Mos	13-Jun-2014				
Complied With	REVIEWED ENGINE LOGBOOK MAINTENANCE RECORDS, NO LPT2 BLADES AFFECTED ON SECTION (E) OF THE AD. NO FURTHER ACTION REQUIRED AT THIS TIME.					Hrs	3,195.4				
						Enc	1,869				
2014-12-52-E	**Emergency AD -2nd Stage Low-Pressure Turbine (LPT2) Blade**							RE (-)		Mandatory	
71 ENG2						Mos	13-Jun-2014				
Complied With	REVIEWED ENGINE LOGBOOK MAINTENANCE RECORDS, NO LPT2 BLADES AFFECTED ON SECTION (E) OF THE AD. NO FURTHER ACTION REQUIRED AT THIS TIME.					Hrs	3,195.4				
						Enc	1,869				

Task No / SEQ	Description / PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2021-23-11	**Powerplant - Fuel Flow Transducer Bracket - Replacement**								RE (-)		Mandatory	
71 A/F							Mos	19-Nov-2022				
Eff: 10-Jan-2022 Complied With							Hrs	5,136.6				
(NOTE: COMPLIANCE:Within 12 months after the effective date of this AD or 750 hours TIS after the effective date of this AD, whichever occurs first)							Ldg	3,167				
45-71-2	**Power Plant - Installation of Lower Cowling Channel Boot - Superseded by SB45-71-3**								RE (-)		Optional	
71 A/F							Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER						Hrs	8.7				
							Ldg	8				
45-71-2 Rev 1	**Power Plant - Installation of Lower Cowling Channel Boot - Superseded by SB45-71-3**								RE (-)		Optional	
71 A/F							Mos	29-Aug-2019				
Eff: 30-Jul-2004 Not Applicable							Hrs	4,516.2				
							Ldg	2,733				
45-71-3	**Power Plant - Installation of Lower Engine Cowling Skid Plate**								RE (-)		Optional	
71 A/F							Mos	29-Aug-2019				
Eff: 30-Jul-2004 Not Applicable							Hrs	4,516.2				
							Ldg	2,733				
45-71-5	**Powerplant - Modification of the Left and Right Engine Wire Routing and Clamping**								RE (-)		Recommended	
71 A/F							Mos	14-Dec-2020				
Eff: 13-Feb-2007 Not Applicable							Hrs	4,610.5				
							Ldg	2,822				
45-71-6	**Powerplant - Installation of Starter/Generator Exhaust Scupper**								RE (-)		Recommended	
71 A/F							Mos	30-Nov-2011				
Eff: 05-Feb-2008 Not Applicable	PER A/C S/N						Hrs	2,240.7				
(AVG MAN HRS: 13)							Ldg	1,342				
45-71-6 Rev 1	**Powerplant - Installation of Starter/Generator Exhaust Scupper**								RE (-)		Recommended	
71 A/F							Mos	14-Dec-2020				
Eff: 19-Sep-2011 Not Applicable							Hrs	4,610.5				
(AVG MAN HRS: 13)							Ldg	2,822				
45-71-7	**Powerplant - Replacement of the Left Engine Fuel and Hydraulic Tubing and Installation of Tubing Support Channel**								RE (-)		Recommended	
71 A/F							Mos	28-Jan-2010				
Eff: 07-Dec-2009 Complied With							Hrs	1,172.9				
							Ldg	723				
710130	**Inspect Tailpipe/LPT 3 Rotor Assembly - Visually Inspect For Foreign Object Damage, Thermal Distress, And Leaks**								RE		EMM - Requirement, EMM	**≈24-Dec-2024**
71 ENG1	057140						Mos	09-Feb-2024				
							Hrs	5,253.5	800	-300/+50	(6,053.5)	778.7 Hrs (+50)
							Enc	3,756				
710130	**Inspect Tailpipe/LPT 3 Rotor Assembly - Visually Inspect For Foreign Object Damage, Thermal Distress, And Leaks**								RE		EMM - Requirement, EMM	**≈24-Dec-2024**
71 ENG2	057140						Mos	09-Feb-2024				
							Hrs	5,253.5	800	-300/+50	(6,053.5)	778.7 Hrs (+50)
							Enc	3,756				
710140	**Inspect Inlet/Fan Area- Inspect For Foreign Object Damage And Leakage (Refer to Paragraph 4.B)**								RE		EMM - Requirement, EMM	**≈24-Dec-2024**
71 ENG1	057140						Mos	09-Feb-2024				
							Hrs	5,253.5	800	-300/+50	(6,053.5)	778.7 Hrs (+50)
							Enc	3,756				
710140	**Inspect Inlet/Fan Area- Inspect For Foreign Object Damage And Leakage (Refer to Paragraph 4.B)**								RE		EMM - Requirement, EMM	**≈24-Dec-2024**
71 ENG2	057140						Mos	09-Feb-2024				
							Hrs	5,253.5	800	-300/+50	(6,053.5)	778.7 Hrs (+50)
							Enc	3,756				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
714010	**Check Electrical Wires And Connections- Visually Inspect For Security And Damage**							RE		EMM - Requirement, EMM	**≈24-Dec-2024**
71 ENG1	057140					Mos	09-Feb-2024				
						Hrs	5,253.5	800	-300/+50	(6,053.5)	778.7 Hrs (+50)
						Enc	3,756				
714010	**Check Electrical Wires And Connections- Visually Inspect For Security And Damage**							RE		EMM - Requirement, EMM	**≈24-Dec-2024**
71 ENG2	057140					Mos	09-Feb-2024				
						Hrs	5,253.5	800	-300/+50	(6,053.5)	778.7 Hrs (+50)
						Enc	3,756				
715010	**Check Plumbing Lines And Connections- Visually Inspect For Security, Loose Or Broken Clamps Or Brackets, Leaks, Cracks, Cuts, Or Rubbing**							RE		EMM - Requirement, EMM	**≈24-Dec-2024**
71 ENG1	057140					Mos	09-Feb-2024				
						Hrs	5,253.5	800	-300/+50	(6,053.5)	778.7 Hrs (+50)
						Enc	3,756				
715010	**Check Plumbing Lines And Connections- Visually Inspect For Security, Loose Or Broken Clamps Or Brackets, Leaks, Cracks, Cuts, Or Rubbing**							RE		EMM - Requirement, EMM	**≈24-Dec-2024**
71 ENG2	057140					Mos	09-Feb-2024				
						Hrs	5,253.5	800	-300/+50	(6,053.5)	778.7 Hrs (+50)
						Enc	3,756				
A45-71-4	**Power Plant - Modification of the Left Engine Alternator Wire Routing**							RE (-)		Alert	
71 A/F						Mos	14-Dec-2020				
Eff: 29-Sep-2005 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 3)						Ldg	2,822				
AA7120069	**(Left) Engine Mount Isolators - Perform visual inspection of forward and aft isolators and associated parts.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
71 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	3,000	+100	6,000	725.2 Hrs (+100)
Ref:71-20-00 (ZONE: 450) (Manual Adjustment: -11.7 Hrs) (SOURCE: MM-104, MM-105) (NOTE: Effective on Aircraft with 2,500 hour or 3,000 Hour MPI engines. Note: Perform During Engine Major Periodic Inspection not to exceed 3100 Hrs)						Ldg	1,768				
AA7120069	**(Right) Engine Mount Isolators - Perform visual inspection of forward and aft isolators and associated parts.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
71 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	3,000	+100	6,000	725.2 Hrs (+100)
Ref:71-20-00 (ZONE: 460) (Manual Adjustment: -11.7 Hrs) (SOURCE: MM-104, MM-105) (NOTE: Effective on Aircraft with 2,500 hour or 3,000 Hour MPI engines. Note: Perform During Engine Major Periodic Inspection not to exceed 3100 Hrs)						Ldg	1,768				
AD7120005	**(Left) Engine Mount Isolator Forward Bonded Mounting - Replacement**							RE (N/A)		TLMC 05-19-01	
71 A/F						Mos					
						Hrs					
(ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: Refer to Lord Corporation Component Maintenance Manual APE97-008. Effective on Aircraft with 5,000 hour CZI modified engines. If required, a tolerance of 200 flight hours may be added to interval to coincide replacement with engine manufacturer's compressor zone inspection (CZI) tolerance.)						Ldg					
AD7120005	**(Right) Engine Mount Isolator Forward Bonded Mounting - Replacement**							RE (N/A)		TLMC 05-19-01	
71 A/F						Mos					
						Hrs					
(ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: Refer to Lord Corporation Component Maintenance Manual APE97-008. Effective on Aircraft with 5,000 hour CZI modified engines. If required, a tolerance of 200 flight hours may be added to interval to coincide replacement with engine manufacturer's compressor zone inspection (CZI) tolerance.)						Ldg					
AD7120006	**(Left) Engine Mount Isolator Forward Bonded Mounting - Replacement**							RE (N/A)		TLMC 05-19-01	
71 A/F						Mos					
						Hrs					
(ZONE: 450) (SOURCE: MM-104, MM-105)						Ldg					
AD7120006	**(Right) Engine Mount Isolator Forward Bonded Mounting - Replacement**							RE (N/A)		TLMC 05-19-01	
71 A/F						Mos					
						Hrs					
(ZONE: 460) (SOURCE: MM-104, MM-105)						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
AD7120070	**(Left) Engine Mount Isolator Forward Bonded Mounting - Replacement**							RE		TLMC 05-19-01	**≈07-Dec-2024**
71 A/F						Mos					
						Hrs		6,000	-/+25	6,000	725.2 Hrs (+25)
	(ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to Lord Corporation Component Maintenance Manual APE97-008.) (Effective on Aircraft with 6,000 hour CZI modified engines.) NOTE: If required, a tolerance of 200 flight hours may be added to interval to coincide replacement with engine manufacturer's compressor zone inspection (CZI) tolerance.)					Ldg					
AD7120070	**(Right) Engine Mount Isolator Forward Bonded Mounting - Replacement**							RE		TLMC 05-19-01	**≈07-Dec-2024**
71 A/F						Mos					
						Hrs		6,000	-/+25	6,000	725.2 Hrs (+25)
	(ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to Lord Corporation Component Maintenance Manual APE97-008.) (Effective on Aircraft with 6,000 hour CZI modified engines.) NOTE: If required, a tolerance of 200 flight hours may be added to interval to coincide replacement with engine manufacturer's compressor zone inspection (CZI) tolerance.)					Ldg					
AD7120075	**(Left) Engine Mount Isolators - Perform detailed inspection of aft mount isolator assembly and associated parts.**							RE		TLMC 05-19-00	**≈08-Jun-2025**
71 A/F						Mos					
						Hrs		3,600	-/+25	[6,600]	1,325.2 Hrs (+25)
	Ref:71-20-00 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: Engine Major Periodic Inspection not to exceed 3,600 Hours.)					Ldg					
AD7120075	**(Right) Engine Mount Isolators - Perform detailed inspection of aft mount isolator assembly and associated parts.**							RE		TLMC 05-19-00	**≈08-Jun-2025**
71 A/F						Mos					
						Hrs		3,600	-/+25	[6,600]	1,325.2 Hrs (+25)
	Ref:71-20-00 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: Engine Major Periodic Inspection not to exceed 3,600 Hours.)					Ldg					
AW 71-003	**Honeywell Engine Life Bracket Replacement**							RE (-)		Advisory Wire	
71 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
D200808000038	**New N2 Monopole Resistance Values**							RE (-)		Service Information Letter	
71 ENG1						Mos					
Eff: 20-Oct-2008						Hrs					
						Enc					
D200808000038	**New N2 Monopole Resistance Values**							RE (-)		Service Information Letter	
71 ENG2						Mos					
Eff: 20-Oct-2008						Hrs					
						Enc					
D200808000038 Rev 1	**New N2 Monopole Resistance Values**							T (-)		Service Information Letter	
71 ENG1						Mos					
Eff: 30-Oct-2018						Hrs					
						Enc					
D200808000038 Rev 1	**New N2 Monopole Resistance Values**							T (-)		Service Information Letter	
71 ENG2						Mos					
Eff: 30-Oct-2018						Hrs					
						Enc					
D200808000038 Rev 2	**New N2 Monopole Resistance Values**							T (A/R)		Service Information Letter	
71 ENG1						Mos					
Eff: 08-Nov-2018						Hrs					
						Enc					
D200808000038 Rev 2	**New N2 Monopole Resistance Values**							T (A/R)		Service Information Letter	
71 ENG2						Mos					
Eff: 08-Nov-2018						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D201304000013	**TFE731 and HTF7000 Electronic Engine Interface (EEI) Software and Windows 10 Certification Date**							RE (-)		Service Information Letter	
71 ENG1						Mos					
Eff: 30-May-2013						Hrs					
						Enc					
D201304000013	**TFE731 and HTF7000 Electronic Engine Interface (EEI) Software and Windows 10 Certification Date**							RE (-)		Service Information Letter	
71 ENG2						Mos					
Eff: 30-May-2013						Hrs					
						Enc					
D201304000013 Rev 1	**TFE731 and HTF7000 Electronic Engine Interface (EEI) Software and Windows 10 Certification Date**							T (A/R)		Service Information Letter	
71 ENG1						Mos					
Eff: 06-Dec-2018						Hrs					
						Enc					
D201304000013 Rev 1	**TFE731 and HTF7000 Electronic Engine Interface (EEI) Software and Windows 10 Certification Date**							T (A/R)		Service Information Letter	
71 ENG2						Mos					
Eff: 06-Dec-2018						Hrs					
						Enc					
K7120004	**Forward and Aft Engine Mount Isolator Housing.**							RE		TLMC 05-19-01	**≈13-Jun-2032**
71 A/F						Mos					
						Hrs		15,000	-/+25	15,000	9,725.2 Hrs (+25)
(ZONE: 450/460) (SOURCE: MM-104, MM-105)						Ldg					
P7120001	*** Forward Engine Mount - Perform Eddy Current Inspection.**							RE	TLMC 04-10-01, TLMC 05-15-00, Ch.5 Interval		**≈14-Oct-2027**
71 A/F	05-15-00					Mos	10-Feb-2021				
						Hrs	4,610.5	4,800		(9,410.5)	4,135.7 Hrs (+25)
Alias1:71-10-01 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to the NDI Manual [NDI-104], Part 6, 71-10-01.))						Ldg	2,822				
Q7110004	**(Left) Engine Inlets - Perform Tap-Test.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
71 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	3,000	+100	6,000	725.2 Hrs (+100)
Alias1:71-10-01 (ZONE: 430/440) (Manual Adjustment: -11.7 Hrs) (SOURCE: MM-104, MM-105) (NOTE: On Aircraft with over 1200 hours from C of A or that have already performed an engine MPI, perform tap-test at next scheduled inspection interval. Initial 1,200 Hours, Every Engine Major Periodic Inspection Repeat.)						Ldg	1,768				
Q7110004	**(Right) Engine Inlets - Perform Tap-Test.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
71 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7	3,000	+100	6,000	725.2 Hrs (+100)
Alias1:71-10-01 (ZONE: 430/440) (Manual Adjustment: -11.7 Hrs) (SOURCE: MM-104, MM-105) (NOTE: On Aircraft with over 1200 hours from C of A or that have already performed an engine MPI, perform tap-test at next scheduled inspection interval. Initial 1,200 Hours, Every Engine Major Periodic Inspection Repeat.)						Ldg	1,768				
Q7120002	**(Left) Engine Mount Isolators - Perform detailed inspection of forward and aft isolators and associated parts.**							RE (N/A)		TLMC 05-19-00	
71 A/F						Mos					
						Hrs					
Alias1:71-20-00 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 71-20-00.) (Effective on Aircraft with 5,000 hour CZI modified engines.))						Ldg					
Q7120002	**(Right) Engine Mount Isolators - Perform detailed inspection of forward and aft isolators and associated parts.**							RE (N/A)		TLMC 05-19-00	
71 A/F						Mos					
						Hrs					
Alias1:71-20-00 (ZONE: 450/460) (SOURCE: MM-104, MM-105)						Ldg					
Q7120073	**(Left) Engine Mount Isolators - Perform detailed inspection of forward and aft isolators and associated parts.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
71 A/F						Mos					
						Hrs		6,000	-/+25	6,000	725.2 Hrs (+25)
Alias1:71-20-00 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 71-20-00.) (Effective on Aircraft with 6,000 hour CZI modified engines.) Note: If required, a tolerance of 200 flight hours may be added to interval to coincide inspection with engine manufacturer's compressor zone inspection (CZI) tolerance.)						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Q7120073	**(Right) Engine Mount Isolators - Perform detailed inspection of forward and aft isolators and associated parts.**							RE		TLMC 05-19-00	**≈07-Dec-2024**
71 A/F						Mos					
						Hrs		6,000	-/+25	6,000	725.2 Hrs (+25)
	Alias1:71-20-00 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 71-20-00.) (Effective on Aircraft with 6,000 hour CZI modified engines.) Note: If required, a tolerance of 200 flight hours may be added to interval to coincide inspection with engine manufacturer's compressor zone inspection (CZI) tolerance.)					Ldg					
R7100032	**L/H Engine Nacelle Tubes - Perform Detailed Visual Inspection.**							RE (N/A)		TLMC 05-19-00	
71 A/F						Mos	28-Jan-2010				
						Hrs	1,172.9				
	Alias1:71-10-03 (ZONE: 430) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 71-10-03.))					Ldg	723				
V7120074	*** (Left) Aft Engine Mount Bolt (P/N 4571408525-001) - Replace.**						RE (Engine Change)		TLMC 04-11-00, TLMC 05-19-01		
71 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7				
	Alias1:71-00-01 (ZONE: 410/420) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 71-00-01.) (Perform at next engine removal) Note: Do not Replace with same P/N bolt. Use P/N 4571408525-003.)					Ldg	1,768				
V7120074	*** (Right) Aft Engine Mount Bolt (P/N 4571408525-001) - Replace.**						RE (Engine Change)		TLMC 04-11-00, TLMC 05-19-01		
71 A/F						Mos	14-Nov-2013				
						Hrs	3,011.7				
	Alias1:71-00-01 (ZONE: 410/420) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 71-00-01.) (Perform at next engine removal) Note: Do not Replace with same P/N bolt. Use P/N 4571408525-003.)					Ldg	1,768				
Y7100002	**Lower Engine Cowling - Visually inspect latch channels for chafing.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
71 A/F	05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 450CL, 460CR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7110000	**Engine Nacelle - Perform visual inspection. Inspect inlet bulkhead, structure, plumbing, skin spot welds, anti-ice outlet screen, and fasteners for security, cracks, and general condition.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
71 A/F	05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 430/440) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7110001	**Engine Inlet Lip and Duct - Perform visual inspection.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
71 A/F	05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 430/440) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7110002	**Engine Starter/Generator Inlet and Exhaust Duct and Seals - Perform visual inspection.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
71 A/F	05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 450CL, 460CR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7110003	**Engine Alternator Exhaust Duct and Seals - Perform visual inspection.**							RE		TLMC 05-12-03	**≈24-Oct-2024**
71 A/F	05-12-03					Mos	09-Feb-2024	24	-/+14d	(09-Jan-2026)	1.6 Years (+14 Days)
						Hrs	5,253.5	600	-/+25	(5,853.5)	578.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 450CL/ 450CR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7120000	**Forward Engine Mounts - Perform visual inspection.**							RE		TLMC 05-11-03	**≈24-Jul-2024**
71 A/F	05-11-03					Mos	09-Feb-2024	12	-/+14d	(09-Feb-2025)	8.7 Months (+14 Days)
	Alias1:5-10-00 (ZONE: 450/460) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Hrs	5,253.5	300	-/+25	(5,553.5)	278.7 Hrs (+25)
						Ldg	3,757				
▼ 72 - ENGINE											
	1st-Stage Low Pressure Compressor (LPC) Disc							RE		Life Limit	**≈13-Dec-2029**
72 ENG1		0				Mos	12-Feb-2008				
3060372-1	New	0				Hrs	0				
060316004249		0				Enc	0	10,000		10,000	6,729 Enc

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		1st-Stage Low Pressure Compressor (LPC) Disc							RE		Life Limit	**≈13-Dec-2029**
72 ENG2			0				Mos	15-Feb-2008				
3060372-1		New	0				Hrs	0				
060316004244			0				Enc	0	10,000		10,000	6,729 Enc
		1st-Stage Low Pressure Turbine (LPT) Disc							RE		Life Limit	**≈15-Aug-2031**
72 ENG1			0				Mos	12-Feb-2008				
3060625-1		New	0				Hrs	0				
070322904253			0				Enc	0	12,000		12,000	8,729 Enc
		1st-Stage Low Pressure Turbine (LPT) Disc							RE		Life Limit	**≈15-Aug-2031**
72 ENG2			0				Mos	15-Feb-2008				
3060625-1		New	0				Hrs	0				
070322903071			0				Enc	0	12,000		12,000	8,729 Enc
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
72 ENG1		No.01					Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
72 ENG2		No.01					Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
72 ENG1		No.02					Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
72 ENG2		No.02					Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
72 ENG1		No.03					Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
72 ENG2		No.03					Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
72 ENG1		No.04					Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
72 ENG2		No.04					Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.05					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.05					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.06					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.06					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.07					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.07					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.08					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.08					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.09					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.09					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.10					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.10					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.11					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.11					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.12					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.12					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.13					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.13					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.14					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.14					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.15					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.15					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.16					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.16					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.17					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.17					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.18					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.18					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.19					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.19					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.20					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.20					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.21					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.21					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.22					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.22					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.23					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.23					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.24					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.24					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.25					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.25					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.26					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.26					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.27					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.27					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG1	No.28					Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd Stage Low Pressure Turbine Blade							RE (O/C)			
	72 ENG2	No.28					Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd-Stage Low Pressure Compressor (LPC) Disc							RE		Life Limit	**≈20-Apr-2038**
	72 ENG1		0				Mos	12-Feb-2008				
	3075839-1	New	0				Hrs	0				
	070316001362		0				Enc	0	20,000		20,000	16,729 Enc
		2nd-Stage Low Pressure Compressor (LPC) Disc							RE		Life Limit	**≈20-Apr-2038**
	72 ENG2		0				Mos	15-Feb-2008				
	3075839-1	New	0				Hrs	0				
	070316001266		0				Enc	0	20,000		20,000	16,729 Enc
		2nd-Stage Low Pressure Turbine (LPT) Disc							RE		Life Limit	**≈15-Aug-2031**
	72 ENG1		0				Mos	12-Feb-2008				
	3060611-1	New	0				Hrs	0				
	070322900852		0				Enc	0	12,000		12,000	8,729 Enc
		2nd-Stage Low Pressure Turbine (LPT) Disc							RE		Life Limit	**≈15-Aug-2031**
	72 ENG2		0				Mos	15-Feb-2008				
	3060611-1	New	0				Hrs	0				
	070322900842		0				Enc	0	12,000		12,000	8,729 Enc
		2nd-Stage LPT Nozzle Retainer							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd-Stage LPT Nozzle Retainer							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		2nd-Stage LPT Nozzle Shroud							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		2nd-Stage LPT Nozzle Shroud							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		3rd-Stage Low Pressure Compressor (LPC) Disc							RE		Life Limit	**≈20-Apr-2038**
72 ENG1			0				Mos	12-Feb-2008				
3060374-1		New	0				Hrs	0				
070316004007			0				Enc	0	20,000		20,000	16,729 Enc
		3rd-Stage Low Pressure Compressor (LPC) Disc							RE		Life Limit	**≈20-Apr-2038**
72 ENG2			0				Mos	15-Feb-2008				
3060374-1		New	0				Hrs	0				
070316004004			0				Enc	0	20,000		20,000	16,729 Enc
		3rd-Stage Low Pressure Turbine (LPT) Disc							RE		Life Limit	**≈15-Aug-2031**
72 ENG1			0				Mos	12-Feb-2008				
3060671-2		New	0				Hrs	0				
070322902662			0				Enc	0	12,000		12,000	8,729 Enc
		3rd-Stage Low Pressure Turbine (LPT) Disc							RE		Life Limit	**≈15-Aug-2031**
72 ENG2			0				Mos	15-Feb-2008				
3060671-2		New	0				Hrs	0				
070322902657			0				Enc	0	12,000		12,000	8,729 Enc
		3rd-Stage LPT Blades							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		3rd-Stage LPT Blades							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		4th-Stage Low Pressure Compressor (LPC) Disc							RE		Life Limit	**≈20-Apr-2038**
72 ENG1			0				Mos	12-Feb-2008				
3075326-5		New	0				Hrs	0				
070350103272			0				Enc	0	20,000		20,000	16,729 Enc
		4th-Stage Low Pressure Compressor (LPC) Disc							RE		Life Limit	**≈20-Apr-2038**
72 ENG2			0				Mos	15-Feb-2008				
3075326-5		New	0				Hrs	0				
070350109406			0				Enc	0	20,000		20,000	16,729 Enc
		A-4 Nozzle Assembly							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		A-4 Nozzle Assembly							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Accessory Gearbox							RE (O/C)			
72 ENG1		0				Mos	12-Feb-2008				
3060827-2	New	0				Hrs	0				
S-2939		0				Enc	0				
	Accessory Gearbox							RE (O/C)			
72 ENG2		0				Mos	15-Feb-2008				
3060827-2	New	0				Hrs	0				
S-2940		0				Enc	0				
	Aft Air-Oil Separator Annular Ball Bearing							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Aft Air-Oil Separator Annular Ball Bearing							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Aft Alternator Spu Annular Bearing							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Aft Alternator Spu Annular Bearing							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Aft High Pressure Turbine (HPT) Shaft Coupling							RE (O/C)			
72 ENG1		0				Mos	12-Feb-2008				
3060599-2	New	0				Hrs	0				
08P02461		0				Enc	0				
	Aft High Pressure Turbine (HPT) Shaft Coupling							RE (O/C)			
72 ENG2		0				Mos	15-Feb-2008				
3060599-2	New	0				Hrs	0				
08P02458		0				Enc	0				
	Aft Oil Pump Spur Annular Ball Bearing							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Aft Oil Pump Spur Annular Ball Bearing							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Aft Starter/Generator Spu Annular Bearing							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No SEQ PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
	Aft Starter/Generator Spu Annular Bearing							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing Ball							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing Ball							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing Ball N02							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing Ball N02							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing Ball Thr Rtr							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing Ball Thr Rtr							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing Housing, Rear - No. 6							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing Housing, Rear - No. 6							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Ball							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Ball							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Bearing, Ball, Thrust							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Ball, Thrust							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Bearing, Roller Cylindrical-Hp Rotor							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Bearing, Roller Cylindrical-Hp Rotor							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Bellows Regulating,Pcd Limiter							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Bellows Regulating,Pcd Limiter							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Bellows Regulating,Servo Valve							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Bellows Regulating,Servo Valve							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Bellows Sensor,Compressor Dischar							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Bellows Sensor,Compressor Dischar							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Body Fuel Control							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Body Fuel Control							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Bypass Duct Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Bypass Duct Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Bypass Fan Stator							RE (O/C)			
72 ENG1					0		Mos	30-Nov-2009				
3060163-5		Repaired			0		Hrs	1,072.6				
08P02816					0		Enc	667				
		Bypass Fan Stator							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Case And Vane Assy Stage 4							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Case And Vane Assy Stage 4							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Case Hp Turbine							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Case Hp Turbine							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Circuit Card Assembly Em I/Flex							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Circuit Card Assembly Em I/Flex							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Circuit Card Assembly, Power Supply							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Circuit Card Assembly, Power Supply							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Combustion Chamber Plenum Case							RE (O/C)			
72 ENG1			0				Mos	12-Feb-2008				
3060534-4		New	0				Hrs	0				
08P00699			0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Combustion Chamber Plenum Case							RE (O/C)			
72 ENG2			0				Mos	15-Feb-2008				
3060534-4		New	0				Hrs	0				
08P00807			0				Enc	0				
		Combustion Liner							RE (O/C)			
72 ENG1							Mos	11-Nov-2013				
3060766-1							Hrs	3,011.7				
00P22950							Enc	1,768				
		Combustion Liner							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Compressor Assembly							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Compressor Assembly							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Compressor Stator Assembly, Third Stage							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Compressor Stator Assembly, Third Stage							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Compressor Stator Assy, 2Nd Stage - Low							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Compressor Stator Assy, 2Nd Stage - Low							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Compressor, Rotor, Centrifugal							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Compressor, Rotor, Centrifugal							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Compressurestatorassy, 1St Stage Low							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Compressurestatorassy, 1St Stage Low							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Control Assembly,Servo Valve							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Control Assembly,Servo Valve							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Core Assembly, Oil Cooler							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Core Assembly, Oil Cooler							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Core Ay							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Core Ay							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Digital Electronic Engine Control							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Digital Electronic Engine Control							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Digital Electronic Engine Control							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Digital Electronic Engine Control							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Duct, Bypass - Upper							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Duct, Bypass - Upper							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Fan Disc							RE		Life Limit	**≈20-Apr-2038**
	72 ENG1				0		Mos	30-Nov-2009				
	3060155-6	Repaired			0		Hrs	1,072.6				
	07-13651-06148		667		0		Enc	667	20,000		20,000	16,729 Enc
	(ZONE: .)											
		Fan Disc							RE		Life Limit	**≈20-Apr-2038**
	72 ENG2		0				Mos	15-Feb-2008				
	3060287-2	New	0				Hrs	0				
	07-13651-06144		0				Enc	0	20,000		20,000	16,729 Enc
	(ZONE: .)											
		Fan Drive Shaft							RE (O/C)			
	72 ENG1		0				Mos	12-Feb-2008				
	3060180-2	New	0				Hrs	0				
	070339002042		0				Enc	0				
		Fan Drive Shaft							RE (O/C)			
	72 ENG2		0				Mos	15-Feb-2008				
	3060180-2	New	0				Hrs	0				
	070339002046		0				Enc	0				
		Fan Inlet Housing Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Fan Inlet Housing Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Fan Roller Bearing							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Fan Roller Bearing							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fan Rotor Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Fan Rotor Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Fan Spinner							RE		Life Limit	**≈20-Apr-2038**
	72 ENG1		0				Mos	12-Feb-2008				
	3060156-2	New	0				Hrs	0				
	072784300564		0				Enc	0	20,000		20,000	16,729 Enc
		Fan Spinner							RE		Life Limit	**≈20-Apr-2038**
	72 ENG2		0				Mos	15-Feb-2008				
	3060156-2	New	0				Hrs	0				
	082784300019		0				Enc	0	20,000		20,000	16,729 Enc
		Filter Plate Valve							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Filter Plate Valve							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Flyweight Assy Governor							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Flyweight Assy Governor							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Forging Gear Ring							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Forging Gear Ring							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Forging, Rotating							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Forging, Rotating							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Forward Air-Oil Separator Annular Ball Bearing							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Forward Air-Oil Separator Annular Ball Bearing							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Forward Alternator Spu Annular Ball Bearing							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Forward Alternator Spu Annular Ball Bearing							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Forward Oil Pump Spur Annular Ball Bearing							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Forward Oil Pump Spur Annular Ball Bearing							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Forward Shaft High Pressure Turbine (HPT) Coupling							RE (O/C)			
72 ENG1		0				Mos	12-Feb-2008				
3060502-2	New	0				Hrs	0				
08P02130		0				Enc	0				
	Forward Shaft High Pressure Turbine (HPT) Coupling							RE (O/C)			
72 ENG2		0				Mos	15-Feb-2008				
3060502-2	New	0				Hrs	0				
08P02128		0				Enc	0				
	Forward Starter/Generator Spu Annular Ball Bearing							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Forward Starter/Generator Spu Annular Ball Bearing							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Frame Assy, Front - 9 Strut Machining							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Frame Assy, Front - 9 Strut Machining							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Front Frame Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Front Frame Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Fuel Control Assy Main Turbine Engine							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Fuel Control Assy Main Turbine Engine							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Gear Helical Ring							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Gear Helical Ring							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Gearbox Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Gearbox Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Gearshaft, Bevel							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Gearshaft, Bevel							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		High Pressure Compressor Rotor Impeller							RE		Life Limit	**≈11-Apr-2028**
72 ENG1			0				Mos	12-Feb-2008				
3060371-1		New	0				Hrs	0				
070322904720			0				Enc	0	8,000		8,000	4,729 Enc
		High Pressure Compressor Rotor Impeller							RE		Life Limit	**≈11-Apr-2028**
72 ENG2			0				Mos	15-Feb-2008				
3060371-1		New	0				Hrs	0				
070322905434			0				Enc	0	8,000		8,000	4,729 Enc
		High Pressure Compressor Shouldered Shaft							RE (O/C)			
72 ENG1			0				Mos	12-Feb-2008				
3060366-3		New	0				Hrs	0				
08P01714			0				Enc	0				
		High Pressure Compressor Shouldered Shaft							RE (O/C)			
72 ENG2			0				Mos	15-Feb-2008				
3060366-3		New	0				Hrs	0				
08P01707			0				Enc	0				
		High Pressure Turbine (HPT) Assy							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		High Pressure Turbine (HPT) Assy							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		High Pressure Turbine (HPT) Disc							RE		Life Limit	**≈13-Dec-2029**
72 ENG1			0				Mos	12-Feb-2008				
3060841-1		New	0				Hrs	0				
071217200646			0				Enc	0	10,000		10,000	6,729 Enc
		High Pressure Turbine (HPT) Disc							RE		Life Limit	**≈13-Dec-2029**
72 ENG2			0				Mos	15-Feb-2008				
3060841-1		New	0				Hrs	0				
071217200745			0				Enc	0	10,000		10,000	6,729 Enc
		High Pressure Turbine (HPT) Nozzle Assembly							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		High Pressure Turbine (HPT) Nozzle Assembly							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		High Pressure Turbine Forward Seal Plate							RE		Life Limit	**≈13-Dec-2029**
	72 ENG1		0				Mos	12-Feb-2008				
	3060514-1	New	0				Hrs	0				
	070322903476		0				Enc	0	10,000		10,000	6,729 Enc
		High Pressure Turbine Forward Seal Plate							RE		Life Limit	**≈13-Dec-2029**
	72 ENG2		0				Mos	15-Feb-2008				
	3060514-1	New	0				Hrs	0				
	070322901722		0				Enc	0	10,000		10,000	6,729 Enc
		HPT Forward Rotating Air Seal							RE		Life Limit	**≈11-Jun-2027**
	72 ENG1		0				Mos	12-Feb-2008				
	3060698-1	New	0				Hrs	0				
	070350103765		0				Enc	0	7,000		7,000	3,729 Enc
		HPT Forward Rotating Air Seal							RE		Life Limit	**≈11-Jun-2027**
	72 ENG2		0				Mos	15-Feb-2008				
	3060698-1	New	0				Hrs	0				
	070350103773		0				Enc	0	7,000		7,000	3,729 Enc
		HPT Shroud Sleeve							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		HPT Shroud Sleeve							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Lever Assembly,Power							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Lever Assembly,Power							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Low Pressure Compressor Tie Rod							RE (O/C)			
	72 ENG1		0				Mos	12-Feb-2008				
	3074744-1	New	0				Hrs	0				
	07P33583		0				Enc	0				
		Low Pressure Compressor Tie Rod							RE (O/C)			
	72 ENG2		0				Mos	15-Feb-2008				
	3074744-1	New	0				Hrs	0				
	07P33576		0				Enc	0				
		Low Pressure Turbine (LPT) 1 Nozzle Assembly							RE (O/C)			
	72 ENG1		0				Mos	12-Feb-2008				
	3060666-7	New	0				Hrs	0				
	08P02801		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Low Pressure Turbine (LPT) 1 Nozzle Assembly							RE (O/C)			
72 ENG2			0				Mos	15-Feb-2008				
3060666-7		New	0				Hrs	0				
08P02797			0				Enc	0				
		Low Pressure Turbine (LPT) 1 Nozzle Seal Support							RE (O/C)			
72 ENG1			0				Mos	12-Feb-2008				
3060693-1		New	0				Hrs	0				
07-17565-02456			0				Enc	0				
		Low Pressure Turbine (LPT) 1 Nozzle Seal Support							RE (O/C)			
72 ENG2			0				Mos	15-Feb-2008				
3060693-1		New	0				Hrs	0				
07-17565-02560			0				Enc	0				
		Lower Fan Duct Assembly							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Lower Fan Duct Assembly							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Lpc Stack							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Lpc Stack							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Lpt1 Shroud Assembly							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Lpt1 Shroud Assembly							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Machined Forging Sha							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Machined Forging Sha							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Module Assy							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Module Assy							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Bearing Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Bearing Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Carbon Seal Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Carbon Seal Runner							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Carbon Seal Runner							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Planet Gear Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Planet Gear Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 2 Planet Gear Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 2 Planet Gear Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 3 Ball Bearing							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 3 Ball Bearing							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 3 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 3 Carbon Seal Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 3 Planet Gear Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 3 Planet Gear Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 4 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 4 Carbon Seal Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 4 Carbon Seal Runner							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 4 Carbon Seal Runner							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 4 Planet Gear Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 4 Planet Gear Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Carbon Seal Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Carbon Seal Runner							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Carbon Seal Runner							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Planet Gear Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Planet Gear Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 6 Bearing Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 6 Bearing Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 6 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 6 Carbon Seal Assembly							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Nozzle Low Pressure Turbine (LPT) (A5) Seal							RE (O/C)			
72 ENG1			0				Mos	12-Feb-2008				
3073765-12		New	0				Hrs	0				
07-17565-02618			0				Enc	0				
		Nozzle Low Pressure Turbine (LPT) (A5) Seal							RE (O/C)			
72 ENG2			0				Mos	15-Feb-2008				
3073765-12		New	0				Hrs	0				
07-17565-02694			0				Enc	0				
		Nozzle Turbine Lp, Stage 1							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Nozzle Turbine Lp, Stage 1							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Outer Transition Liner							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Outer Transition Liner							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Planet Gear Assembly							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Planet Gear Assembly							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Planet Housing Assembly							RE (O/C)			
72 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Planet Housing Assembly							RE (O/C)			
72 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Plenum Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Plenum Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Power Section Assemb							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Power Section Assemb							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Resistor Var,Lin,Precision							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Resistor Var,Lin,Precision							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Ring Gear							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Ring Gear							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Rotating, Air 2nd Stage Seal							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Rotating, Air 2nd Stage Seal							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Seal Hydraulic Rotor							RE (O/C)			
	72 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Seal Hydraulic Rotor							RE (O/C)			
	72 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Seal Rotor Lpt 3Stg							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Seal Rotor Lpt 3Stg							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Seal, Air, Stationary							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Seal, Air, Stationary							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Servo Press Reg Valve Set, Matched							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Servo Press Reg Valve Set, Matched							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Set Flyweight,Gov,Mtchd							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Set Flyweight,Gov,Mtchd							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Set Valve,Mtchd-Relief							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Set Valve,Mtchd-Relief							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Shaft And Housing Assy, Fan Support							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Shaft And Housing Assy, Fan Support							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Shaft Shouldered							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Shaft Shouldered							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Shaft, Shouldered, Low Pressure Compressy							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Shaft, Shouldered, Low Pressure Compressy							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Shaft, Shouldered, Lp Compressor Fwd							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Shaft, Shouldered, Lp Compressor Fwd							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Solenoid And Valve							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Solenoid And Valve							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Solenoid And Valve,Installation Of							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Solenoid And Valve,Installation Of							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Starter/Generator Air/Oil Seal							RE (O/C)			
	72 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Starter/Generator Air/Oil Seal							RE (O/C)			
	72 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Sub Fadec							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Sub Fadec							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Sub, Deec:							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Sub, Deec:							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Sub, Fadec Subassembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Sub, Fadec Subassembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Sun Gear							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Sun Gear							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Support, Bearing Housing, Rear - No. 6							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Support, Bearing Housing, Rear - No. 6							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Support, Stationary Seal, Air							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Support, Stationary Seal, Air							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Thermostat Oil Temp							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Thermostat Oil Temp							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Tie Rod, Threaded Ends							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Tie Rod, Threaded Ends							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Torque Motor							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Torque Motor							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Transducer							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Transducer							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Transfer Gearbox Assembly							RE (O/C)			
	72 ENG1		0				Mos	12-Feb-2008				
	3070093-16	New	0				Hrs	0				
	08P02992		0				Enc	0				
		Transfer Gearbox Assembly							RE (O/C)			
	72 ENG2		118				Mos	22-Dec-2017				
	3070093-16		4,076				Hrs	4,076				
	08P02993		2,402				Enc	2,402				
		Turbine Interstage Transition Duct							RE (O/C)			
	72 ENG1			0			Mos	11-Nov-2013				
	3060694-6	Overhauled		0			Hrs	3,011.7				
	00P05567			0			Enc	1,768				
		Turbine Interstage Transition Duct							RE (O/C)			
	72 ENG2		0				Mos	15-Feb-2008				
	3060694-6	New	0				Hrs	0				
	07P32890		0				Enc	0				
		Turbine Rotor Assy - Lp, First Stage							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Turbine Rotor Assy - Lp, First Stage							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Turbine Rotor Assy - Lp, Third Stage							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Turbine Rotor Assy - Lp, Third Stage							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Turbine/Rear Mount Assy							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Turbine/Rear Mount Assy							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Upper Fan Duct Assembly							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Upper Fan Duct Assembly							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Valve Assembly Body & Hsg							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Valve Assembly Body & Hsg							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Valve Assembly Metering (MTCHD)							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Valve Assembly Metering (MTCHD)							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Valve Assembly Rotary-Matched Set							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Valve Assembly Rotary-Matched Set							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Valve Assembly,Metering							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Valve Assembly,Metering							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Vane Assembly, Fan Stator							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Vane Assembly, Fan Stator							RE (O/C)			
	72 ENG2		0				Mos	19-Dec-2019				
	3060378-1	New	0				Hrs	4,590.8				
	Unknown		0				Enc	2,807				
1		**Bearing, Roller Planet-Aft**							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
1		**Bearing, Roller Planet-Aft**							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
1		**Bearing, Roller Planet-Fwd**							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
1		**Bearing, Roller Planet-Fwd**							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
1		**Gear, Helical Planet**							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
1		**Gear, Helical Planet**							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
2		**Bearing, Roller Planet-Aft**							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
2		**Bearing, Roller Planet-Aft**							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
2		**Bearing, Roller Planet-Fwd**							RE (O/C)			
	72 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
2		**Bearing, Roller Planet-Fwd**							RE (O/C)			
	72 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2	**Gear, Helical Planet**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
2	**Gear, Helical Planet**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
2001-23-09	**Fan Rotor Discs**							T (A/R)		Mandatory	
72 ENG1						Mos					
Eff: 21-Dec-2001						Hrs					
						Enc					
2001-23-09	**Fan Rotor Discs**							T (A/R)		Mandatory	
72 ENG2						Mos					
Eff: 21-Dec-2001						Hrs					
						Enc					
2017-20-01	**Turbine Engine Compressor Section - Fan Disk - Replacement (This AD has been replaced by AD 2019-05-07)**							RE (-)		Mandatory	
72 ENG1						Mos	13-Mar-2008				
Eff: 02-Nov-2017 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
(AVG MAN HRS: 35) (NOTE: APPLICABILITY: Fan Disks with 9,000 cycles-since-new (CSN) or more on the effective date of this AD. COMPLIANCE: Within 100 cycles-in-service (CIS), or at the next engine shop visit, or at next access, whichever occurs first, after the effective date of this AD.)											
2017-20-01	**Turbine Engine Compressor Section - Fan Disk - Replacement (This AD has been replaced by AD 2019-05-07)**							RE (-)		Mandatory	
72 ENG2						Mos	13-Mar-2008				
Eff: 02-Nov-2017 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
(AVG MAN HRS: 35) (NOTE: APPLICABILITY: Fan Disks with 9,000 cycles-since-new (CSN) or more on the effective date of this AD. COMPLIANCE: Within 100 cycles-in-service (CIS), or at the next engine shop visit, or at next access, whichever occurs first, after the effective date of this AD.)											
2019-05-07	**Turbine Engine Compressor Section - Fan Disk - Replacement (This AD replaces AD 2017-20-01)**							RE (-)		Mandatory	
72 ENG1						Mos	01-Apr-2019				
Eff: 25-Apr-2019 Not Applicable	BY SN INSTALLEED					Hrs					
						Enc					
(NOTE: APPLICABILITY: Fan disks with 9,000 cycles since new (CSN) or more as of the effective date of this AD.)											
2019-05-07	**Turbine Engine Compressor Section - Fan Disk - Replacement (This AD replaces AD 2017-20-01)**							RE (-)		Mandatory	
72 ENG2						Mos	01-Apr-2019				
Eff: 25-Apr-2019 Not Applicable	BY SN INSTALLED					Hrs					
						Enc					
(NOTE: APPLICABILITY: Fan disks with 9,000 cycles since new (CSN) or more as of the effective date of this AD.)											
2019-05-07 PARA (G)	**Remove The Affected Fan Disk**							RE (-)			
72 ENG1						Mos	01-Apr-2019				
Not Applicable	BY SN INSTALLEED					Hrs					
						Enc					
2019-05-07 PARA (G)	**Remove The Affected Fan Disk**							RE (-)			
72 ENG2						Mos	01-Apr-2019				
Not Applicable	BY SN INSTALLED					Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2019-05-07 PARA (H)	**Do Not Install An Affected Fan Disk, P/N 3060287-2, Unless "T43374" Is Marked Adjacent To The Fan Disk P/N Or S/N Onto Any Engine Identified In The Applicability Para Of This Ad**							RE (-)			
72 ENG1						Mos	01-Apr-2019				
Not Applicable	BY SN INSTALLEED					Hrs					
						Enc					
2019-05-07 PARA (H)	**Do Not Install An Affected Fan Disk, P/N 3060287-2, Unless "T43374" Is Marked Adjacent To The Fan Disk P/N Or S/N Onto Any Engine Identified In The Applicability Para Of This Ad**							RE (-)			
72 ENG2						Mos	01-Apr-2019				
Not Applicable	BY SN INSTALLED					Hrs					
						Enc					
3	**Bearing, Roller Planet-Aft**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
3	**Bearing, Roller Planet-Aft**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
3	**Bearing, Roller Planet-Fwd**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
3	**Bearing, Roller Planet-Fwd**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
3	**Gear, Helical Planet**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
3	**Gear, Helical Planet**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
3727214-SB-001	**Diskbal Blade Mapping Software PN 3727214 - Release of DiskBal Blade Mapping Software Version 2.7, PN 3727214-2, with Improved Fan Balance Process**							T (A/R)		Optional	
72 ENG1						Mos					
Eff: 28-Jan-2016						Hrs					
						Enc					
3727214-SB-001	**Diskbal Blade Mapping Software PN 3727214 - Release of DiskBal Blade Mapping Software Version 2.7, PN 3727214-2, with Improved Fan Balance Process**							T (A/R)		Optional	
72 ENG2						Mos					
Eff: 28-Jan-2016						Hrs					
						Enc					
4	**Bearing, Roller Planet-Aft**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
4	**Bearing, Roller Planet-Aft**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
4	**Bearing, Roller Planet-Fwd**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
4	**Bearing, Roller Planet-Fwd**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
4	**Gear, Helical Planet**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
4	**Gear, Helical Planet**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
45-72-1	**Engine - TFE731-20BR-1B Engine Upgrade**							RE (-)		Optional	
72 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-72-1 Rev 1	**Engine - TFE731-20BR-1B Engine Upgrade**							RE (-)		Optional	
72 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-72-1 Rev 2	**Engine - TFE731-20BR-1B Engine Upgrade**							RE (-)		Optional	
72 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-72-1 Rev 3	**Engine - TFE731-20BR-1B Engine Upgrade**							RE (-)		Optional	
72 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-72-1 Rev 4	**Engine - TFE731-20BR-1B Engine Upgrade**							RE (-)		Optional	
72 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-72-1 Rev 5	**Engine - TFE731-20BR-1B Engine Upgrade**							RE (-)		Optional	
72 A/F						Mos	13-Mar-2008				
Complied With						Hrs					
						Ldg					
45-72-1 Rev 6	**Engine - TFE731-20BR-1B Engine Upgrade**							RE (-)		Optional	
72 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-72-1 Rev 7	**Engine - TFE731-20BR-1B Engine Upgrade**							T (-)		Optional	
72 A/F						Mos					
Eff: 29-Oct-2012						Hrs					
						Ldg					
45-72-1 Rev 8	**Engine - TFE731-20BR-1B Engine Upgrade**							RE (-)		Optional	
72 A/F						Mos	10-Jan-2020				
Eff: 09-Nov-2015 Not Applicable						Hrs	4,590.8				
(AVG MAN HRS: 17.5)						Ldg	2,807				
45-72-2	**Power Plant - Composite By-Pass Fan Duct Hardware Kit**							RE (-)		Optional	
72 A/F						Mos	29-Aug-2019				
Eff: 23-Jan-2007 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-72-3	**Engine Inlet Anti-Ice Improvements**							T (-)		Optional	
72 A/F						Mos					
Eff: 19-Jun-2017						Hrs					
(AVG MAN HRS: 31) (NOTE: NOTE: Accomplishment of this service bulletin will move the recurring inspection requirement from 250 flight hours to 1200 flight hours for the Engine Inlet.)						Ldg					
45-72-3 Rev 1	**Engine Inlet Anti-Ice Improvements**							T (-)		Optional	
72 A/F						Mos					
Eff: 27-Jun-2017						Hrs					
(AVG MAN HRS: 31) (NOTE: NOTE: Accomplishment of this service bulletin will move the recurring inspection requirement from 250 flight hours to 1200 flight hours for the Engine Inlet.)						Ldg					
45-72-3 Rev 2	**Engine Inlet Anti-Ice Improvement**							T (-)		Optional	
72 A/F						Mos					
Eff: 16-Aug-2017						Hrs					
(AVG MAN HRS: 40) (NOTE: NOTE: Accomplishment of this service bulletin will move the recurring inspection requirement from 250 flight hours to 1200 flight hours for the Engine Inlet.)						Ldg					
45-72-3 Rev 3	**Engine - Engine Inlet Anti-Ice Improvements**							T (-)		Optional	
72 A/F						Mos					
Eff: 12-Feb-2018						Hrs					
(AVG MAN HRS: 40) (NOTE: NOTE: Accomplishment of this service bulletin will move the recurring inspection requirement from 250 flight hours to 1200 flight hours for the Engine Inlet.)						Ldg					
45-72-3 Rev 4	**Engine - Engine Inlet Anti-Ice Improvements**							T (A/R)		Optional	
72 A/F						Mos					
Eff: 18-Dec-2023						Hrs					
(AVG MAN HRS: 40) (NOTE: NOTE: Accomplishment of this service bulletin will move the recurring inspection requirement from 250 flight hours to 1200 flight hours for the Engine Inlet.)						Ldg					
5	**Bearing, Roller Planet-Aft**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
5	**Bearing, Roller Planet-Aft**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
5	**Bearing, Roller Planet-Fwd**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
5	**Bearing, Roller Planet-Fwd**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
5	**Gear, Helical Planet**							RE (O/C)			
72 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
5	**Gear, Helical Planet**							RE (O/C)			
72 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
720005	**Major Periodic Inspection (MPI)**							RE	EMM - Requirement, EMM		**≈08-May-2025**
72 ENG1						Mos	11-Nov-2013				
						Hrs	3,011.7	3,500	+100	6,500	1,225.2 Hrs (+100)
(Manual Adjustment: -11.7 Hrs) (NOTE: A Major Periodic Inspection (MPI) operating period of 3,500 hours and a Compressor Zone Periodic Inspection (CZI) operating period of 7,000 hours is allowed for an engine which meets the following conditions: To qualify for the first use of these operating periods prior to the next MPI or CZI, the engine must be in compliance with all the conditions of NOTE 1, as applicable, and all the service bulletins listed in Table 3, as applicable. To qualify for subsequent use of these operating periods, the engine must be brought into compliance with all the service bulletins listed in Table 4, as applicable, following the first use of these operating periods (see LMM 72-03-06).)					Enc	1,768				
720005	**Major Periodic Inspection (MPI)**							RE	EMM - Requirement, EMM		**≈08-May-2025**
72 ENG2						Mos	14-Nov-2013				
						Hrs	3,011.7	3,500	+100	6,500	1,225.2 Hrs (+100)
(Manual Adjustment: -11.7 Hrs) (NOTE: A Major Periodic Inspection (MPI) operating period of 3,500 hours and a Compressor Zone Periodic Inspection (CZI) operating period of 7,000 hours is allowed for an engine which meets the following conditions: To qualify for the first use of these operating periods prior to the next MPI or CZI, the engine must be in compliance with all the conditions of NOTE 1, as applicable, and all the service bulletins listed in Table 3, as applicable. To qualify for subsequent use of these operating periods, the engine must be brought into compliance with all the service bulletins listed in Table 4, as applicable, following the first use of these operating periods (see LMM 72-03-06).)					Enc	1,768				
720007	**Compressor Zone Periodic Inspection (CZI)**							RE	EMM - Requirement, EMM		**≈08-Oct-2025**
72 ENG1						Mos					
						Hrs		7,000	+200	7,000	1,725.2 Hrs (+200)
						Enc					
720007	**Compressor Zone Periodic Inspection (CZI)**							RE	EMM - Requirement, EMM		**≈08-Oct-2025**
72 ENG2						Mos					
						Hrs		7,000	+200	7,000	1,725.2 Hrs (+200)
						Enc					
720010	**Analysis Oil And Filter (Baseline/Special Requirement)**							RE (-)	EMM - Requirement, EMM		
72 ENG1						Mos	31-Mar-2008				
						Hrs	8.7		-/+5		
						Enc	8				
720010	**Analysis Oil And Filter (Baseline/Special Requirement)**							RE (-)	EMM - Requirement, EMM		
72 ENG2						Mos	31-Mar-2008				
						Hrs	8.7		-/+5		
						Enc	8				
720011	**Replace Fuel Filter Element (25-Hr Initial)**							RE (A/R)	EMM - Requirement, EMM		
72 ENG1						Mos	31-Mar-2008				
						Hrs	8.7		-/+5		
						Enc	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
720011	**Replace Fuel Filter Element (25-Hr Initial)**							RE (A/R)		EMM - Requirement, EMM	
72 ENG2						Mos	31-Mar-2008				
						Hrs	8.7		-/+5		
						Enc	8				
723010	**Check Carbon Seal Health**							RE		EMM - Requirement, EMM	**≈05-Feb-2025**
72 ENG1	057160					Mos	20-May-2020				
						Hrs	4,593.2	1,600	-100/+50	(6,193.2)	918.4 Hrs (+50)
						Enc	2,809				
723010	**Check Carbon Seal Health**							RE		EMM - Requirement, EMM	**≈05-Feb-2025**
72 ENG2	057160					Mos	20-May-2020				
						Hrs	4,593.2	1,600	-100/+50	(6,193.2)	918.4 Hrs (+50)
						Enc	2,809				
72-5112	**Engine - Bank Engine Conversions**							RE (-)		Service Bulletin	
72 ENG1						Mos					
Eff: 06-Mar-1998						Hrs					
						Enc					
72-5112	**Engine - Bank Engine Conversions**							RE (-)		Service Bulletin	
72 ENG2						Mos					
Eff: 06-Mar-1998						Hrs					
						Enc					
72-5112 Rev 1	**Engine - Bank Engine Conversions**							RE (-)		Service Bulletin	
72 ENG1						Mos					
						Hrs					
						Enc					
72-5112 Rev 1	**Engine - Bank Engine Conversions**							RE (-)		Service Bulletin	
72 ENG2						Mos					
						Hrs					
						Enc					
72-5112 Rev 2	**Engine - Bank Engine Conversions**							RE (-)		Service Bulletin	
72 ENG1						Mos					
						Hrs					
						Enc					
72-5112 Rev 2	**Engine - Bank Engine Conversions**							RE (-)		Service Bulletin	
72 ENG2						Mos					
						Hrs					
						Enc					
72-5112 Rev 3	**Engine - Bank Engine Conversions**							T (A/R)		Service Bulletin	
72 ENG1						Mos					
Eff: 07-Jun-2007						Hrs					
						Enc					
72-5112 Rev 3	**Engine - Bank Engine Conversions**							T (A/R)		Service Bulletin	
72 ENG2						Mos					
Eff: 07-Jun-2007						Hrs					
						Enc					
72-5116	**Engine - By-Pass - Install Hp Bleed Air Gasket, Part No. 3071953-1**							RE (-)			
72 ENG1						Mos					
Eff: 12-Nov-1997						Hrs					
						Enc					
72-5116	**Engine - By-Pass - Install Hp Bleed Air Gasket, Part No. 3071953-1**							RE (-)			
72 ENG2						Mos					
Eff: 12-Nov-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
72-5116 Rev 1	**Engine - By-Pass Section - Install HP Bleed Air Gasket, Part Number 3071953-1**						T (A/R)		Category 3, Recommended	
72 ENG1					Mos					
Eff: 30-Jan-2008					Hrs					
					Enc					
72-5116 Rev 1	**Engine - By-Pass Section - Install HP Bleed Air Gasket, Part Number 3071953-1**						T (A/R)		Category 3, Recommended	
72 ENG2					Mos					
Eff: 30-Jan-2008					Hrs					
					Enc					
72-5118	**Engine - Convert Engine Model TFE731-20R-1B, Engine Part No. 3060020-7 to Engine Part No. 3060020-8**						T (A/R)			
72 ENG1					Mos					
Eff: 12-Nov-1997					Hrs					
					Enc					
72-5118	**Engine - Convert Engine Model TFE731-20R-1B, Engine Part No. 3060020-7 to Engine Part No. 3060020-8**						T (A/R)			
72 ENG2					Mos					
Eff: 12-Nov-1997					Hrs					
					Enc					
72-5123	**Replacement Of Combustion Chamber On Specific Engines**						RE (-)			
72 ENG1					Mos					
Eff: 17-Mar-1998					Hrs					
					Enc					
72-5123	**Replacement Of Combustion Chamber On Specific Engines**						RE (-)			
72 ENG2					Mos					
Eff: 17-Mar-1998					Hrs					
					Enc					
72-5123 Rev 1	**Replacement Of Combustion Chamber On Specific Engines**						T (A/R)			
72 ENG1					Mos					
Eff: 11-Jun-2007					Hrs					
					Enc					
72-5123 Rev 1	**Replacement Of Combustion Chamber On Specific Engines**						T (A/R)			
72 ENG2					Mos					
Eff: 11-Jun-2007					Hrs					
					Enc					
72-5125	**Engine - Bank/Spare Engine Conversions**						T (A/R)			
72 ENG1					Mos					
Eff: 02-Oct-1998					Hrs					
					Enc					
72-5125	**Engine - Bank/Spare Engine Conversions**						T (A/R)			
72 ENG2					Mos					
Eff: 02-Oct-1998					Hrs					
					Enc					
72-5143	**Engine - Convert Engine Model Tfe731-20R-1B To Tfe731-20Ar-1B**						RE (-)			
72 ENG1					Mos					
Eff: 10-Sep-2002					Hrs					
					Enc					
72-5143	**Engine - Convert Engine Model Tfe731-20R-1B To Tfe731-20Ar-1B**						RE (-)			
72 ENG2					Mos					
Eff: 10-Sep-2002					Hrs					
					Enc					
72-5143 Rev 1	**Engine - Convert Engine Model Tfe731-20R-1B To Tfe731-20Ar-1B**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-5143 Rev 1	**Engine - Convert Engine Model Tfe731-20R-1B To Tfe731-20Ar-1B**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
72-5143 Rev 2	**Engine - Convert Engine Model Tfe731-20R-1B To Tfe731-20Ar-1B**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
72-5143 Rev 2	**Engine - Convert Engine Model Tfe731-20R-1B To Tfe731-20Ar-1B**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
72-5143 Rev 3	**Engine - Convert Engine Model Tfe731-20R-1B To Tfe731-20Ar-1B**							T (A/R)			
72 ENG1						Mos					
Eff: 27-Aug-2010						Hrs					
						Enc					
72-5143 Rev 3	**Engine - Convert Engine Model Tfe731-20R-1B To Tfe731-20Ar-1B**							T (A/R)			
72 ENG2						Mos					
Eff: 27-Aug-2010						Hrs					
						Enc					
72-5144 Rev 1	**Engine - Compressor Section - Install Water Wash Tube Assembly, Pn 3061180-1**							RE (-)			
72 ENG1						Mos	11-Nov-2013				
Eff: 11-Jun-2007 Complied With						Hrs					
						Enc					
72-5144 Rev 1	**Engine - Compressor Section - Install Water Wash Tube Assembly, Pn 3061180-1**							RE (-)			
72 ENG2						Mos	11-Nov-2013				
Eff: 11-Jun-2007 Complied With	PREVIOUSLY					Hrs	3,011.7				
						Enc	1,768				
72-5149	**Engine - By-Pass Section - Install Fan Duct Set (Matched Set), Pn 3072420-13, On Specific Identified Engine Serial Numbers**							T (A/R)		Service Bulletin	
72 ENG1						Mos					
Eff: 18-Oct-2001						Hrs					
						Enc					
72-5149	**Engine - By-Pass Section - Install Fan Duct Set (Matched Set), Pn 3072420-13, On Specific Identified Engine Serial Numbers**							T (A/R)		Service Bulletin	
72 ENG2						Mos					
Eff: 18-Oct-2001						Hrs					
						Enc					
72-5158	**Engine - By-Pass Section - Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention**							RE (-)			
72 ENG1						Mos	12-Feb-2010				
Eff: 13-Dec-2002 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
						Enc	739				
72-5158	**Engine - By-Pass Section - Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention**							RE (-)			
72 ENG2						Mos	12-Feb-2010				
Eff: 13-Dec-2002 Not Applicable	BY SERIAL NUMBER					Hrs	1,203.8				
						Enc	739				
72-5158 Rev 1	**Engine - By-Pass Section - Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-5158 Rev 1	**Engine - By-Pass Section - Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
72-5158 Rev 2	**Engine - By-Pass Section - Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
72-5158 Rev 2	**Engine - By-Pass Section - Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
72-5169	**Engine - Convert Engine Model Tfe731-20Ar-1B To Engine Model Tfe731-20Br-1B**							RE (-)			
72 ENG1						Mos					
Eff: 27-May-2004						Hrs					
						Enc					
72-5169	**Engine - Convert Engine Model Tfe731-20Ar-1B To Engine Model Tfe731-20Br-1B**							RE (-)			
72 ENG2						Mos					
Eff: 27-May-2004						Hrs					
						Enc					
72-5169 Rev 1	**Engine - Convert Engine Model Tfe731-20Ar-1B To Engine Model Tfe731-20Br-1B**							RE (-)			
72 ENG1						Mos	12-Feb-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
72-5169 Rev 1	**Engine - Convert Engine Model Tfe731-20Ar-1B To Engine Model Tfe731-20Br-1B**							RE (-)			
72 ENG2						Mos	15-Feb-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
72-5169 Rev 2	**Engine - Convert Engine Model Tfe731-20Ar-1B To Engine Model Tfe731-20Br-1B**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
72-5169 Rev 2	**Engine - Convert Engine Model Tfe731-20Ar-1B To Engine Model Tfe731-20Br-1B**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
72-5169 Rev 3	**Engine - Convert Engine Model Tfe731-20Ar-1B To Engine Model Tfe731-20Br-1B**							RE (-)			
72 ENG1						Mos	11-Nov-2013				
Eff: 29-Sep-2005 Complied With	PCW					Hrs	3,011.7				
						Enc	1,768				
72-5169 Rev 3	**Engine - Convert Engine Model Tfe731-20Ar-1B To Engine Model Tfe731-20Br-1B**							RE (-)			
72 ENG2						Mos	11-Nov-2013				
Eff: 29-Sep-2005 Complied With	PREVIOUSLY					Hrs	3,011.7				
						Enc	1,768				
72-5173 Rev 1	**Replace Specific Identified Helical Ring Gears, Part No.3060277-2, And Inspect Associated Parts**							RE (-)			
72 ENG1						Mos	29-Aug-2019				
Eff: 14-Nov-2005 Not Applicable						Hrs	4,516.2				
						Enc	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-5173 Rev 1	**Replace Specific Identified Helical Ring Gears, Part No.3060277-2, And Inspect Associated Parts**							RE (-)			
72 ENG2						Mos	29-Aug-2019				
Eff: 14-Nov-2005 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
72-5181 Rev 1	**Engine - By-Pass Section - Rework/Install Planetary Gearshaft Assembly, Part No. 3060129-3, -4 To Part No. 3060129-7**							RE (-)			
72 ENG1						Mos	11-Nov-2013				
Eff: 03-Jul-2008 Complied With						Hrs					
						Enc					
72-5181 Rev 1	**Engine - By-Pass Section - Rework/Install Planetary Gearshaft Assembly, Part No. 3060129-3, -4 To Part No. 3060129-7**							RE (-)			
72 ENG2						Mos	11-Nov-2013				
Eff: 03-Jul-2008 Complied With	PREVIOUSLY					Hrs	3,011.7				
						Enc	1,768				
727010	**Inspect Bypass Stator Vane Assembly.**							RE		EMM - Requirement, EMM	**≈24-Apr-2025**
72 ENG1	057150					Mos	09-Feb-2024				
						Hrs	5,253.5	1,200	-200/+100	(6,453.5)	1,178.7 Hrs (+100)
						Enc	3,756				
727010	**Inspect Bypass Stator Vane Assembly.**							RE		EMM - Requirement, EMM	**≈24-Apr-2025**
72 ENG2	057150					Mos	09-Feb-2024				
						Hrs	5,253.5	1,200	-200/+100	(6,453.5)	1,178.7 Hrs (+100)
						Enc	3,756				
72-CUS-001	**ADD Special Inspection - Several stator vanes found with resin erosion and should be reinspected every 150 flight hours per TFE731-20BR LMM 72-70-04.**							RE			**≈08-Jun-2024**
72 ENG2						Mos	09-Feb-2024				
						Hrs	5,253.5	150		5,403.5	128.7 Hrs
						Enc	3,756				
831702-SB No. 3	**Engine Condition Trend Monitoring Kit-TFE731-P/N 831702-All; Possible Cable Short With P/N 832787-1/-2/-4**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 22-Jul-2010						Hrs					
						Enc					
831702-SB No. 3	**Engine Condition Trend Monitoring Kit-TFE731-P/N 831702-All; Possible Cable Short With P/N 832787-1/-2/-4**							T (A/R)		Recommended	
72 ENG2						Mos					
Eff: 22-Jul-2010						Hrs					
						Enc					
831708-SB-001	**Napoli A5 Nozzle Adjustment Software P/N 831708**							T (A/R)			
72 ENG1						Mos					
Eff: 30-Jun-2015						Hrs					
						Enc					
831708-SB-001	**Napoli A5 Nozzle Adjustment Software P/N 831708**							T (A/R)			
72 ENG2						Mos					
Eff: 30-Jun-2015						Hrs					
						Enc					
D201012000013 Rev 2	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85 (Krypton 85) above 10,000 Becquerels**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 12-Aug-2021						Hrs					
						Enc					
D201012000013 Rev 2	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85 (Krypton 85) above 10,000 Becquerels**							T (A/R)		Service Information Letter	
72 ENG2						Mos					
Eff: 12-Aug-2021						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
D201612000016	**Maintenance Recommendations for Intermittent Fan Vibration on TFE731-20 and -40 Model Engines**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 09-Jan-2017					Hrs					
					Enc					
D201612000016	**Maintenance Recommendations for Intermittent Fan Vibration on TFE731-20 and -40 Model Engines**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 09-Jan-2017					Hrs					
					Enc					
D201801000060	**Crossover Tube, Oil Cap/Dipstick, Packing Removal/Installation**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 30-Mar-2018					Hrs					
	(NOTE: EFFECTIVITY: This service information letter (SIL) is applicable to all operators of TFE731 series turbofan engines.)				Enc					
D201801000060	**Crossover Tube, Oil Cap/Dipstick, Packing Removal/Installation**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 30-Mar-2018					Hrs					
	(NOTE: EFFECTIVITY: This service information letter (SIL) is applicable to all operators of TFE731 series turbofan engines.)				Enc					
D201808000040	**Prevention of Migration of Super Absorbent Polymer (SAP) Filter Medium Particles into Aircraft Fuel Supplies and Engine Operation with Jet Fuel Contaminated with Diesel Exhaust Fluid (DEF)**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 15-Oct-2018					Hrs					
					Enc					
D201808000040	**Prevention of Migration of Super Absorbent Polymer (SAP) Filter Medium Particles into Aircraft Fuel Supplies and Engine Operation with Jet Fuel Contaminated with Diesel Exhaust Fluid (DEF)**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 15-Oct-2018					Hrs					
					Enc					
D201809000003	**Guidelines for Calibration of the Airflow Rig(s) Used on TFE731 A4 Nozzle Segments**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 30-Oct-2020					Hrs					
					Enc					
D201809000003	**Guidelines for Calibration of the Airflow Rig(s) Used on TFE731 A4 Nozzle Segments**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 30-Oct-2020					Hrs					
					Enc					
D202001000409	**Usage-Based MSP Program**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 22-Jan-2020					Hrs					
					Enc					
D202001000409	**Usage-Based MSP Program**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 22-Jan-2020					Hrs					
					Enc					
Engine 1	**Honeywell - TFE731-20BR**						RE (-)			
72 A/F					Mos					
3060084-2 P-116949C	Time at install:				Hrs					
					Ldg					
Engine 2	**Honeywell - TFE731-20BR**						RE (-)			
72 A/F					Mos					
3060084-2 P-116950C	Time at install:				Hrs					
					Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
SIL No. 74	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**							RE (-)		Service Information Letter	
72 ENG1						Mos					
						Hrs					
						Enc					
SIL No. 74	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**							RE (-)		Service Information Letter	
72 ENG2						Mos					
						Hrs					
						Enc					
SIL No. 74 Rev 1	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 06-Jun-2018						Hrs					
						Enc					
SIL No. 74 Rev 1	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**							T (A/R)		Service Information Letter	
72 ENG2						Mos					
Eff: 06-Jun-2018						Hrs					
						Enc					
TFE731-72-3239 R3								RE (-)			
72 ENG1						Mos	12-Feb-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-3239 R3								RE (-)			
72 ENG2						Mos	15-Feb-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-3239RWK R3	**Rework HP Compressor Radial Impeller**							T (A/R)		Service Bulletin	
72 ENG1						Mos					
Eff: 12-Apr-1999						Hrs					
						Enc					
TFE731-72-3239RWK R3	**Rework HP Compressor Radial Impeller**							T (A/R)		Service Bulletin	
72 ENG2						Mos					
Eff: 12-Apr-1999						Hrs					
						Enc					
TFE731-72-3485RWK	**Engine - Compressor Section - Inspect/Rework HP Compressor Diffuser Mounting Bolt Holes As Required**							T (A/R)		Service Bulletin	
72 ENG1						Mos					
Eff: 24-Jul-1992						Hrs					
						Enc					
TFE731-72-3485RWK	**Engine - Compressor Section - Inspect/Rework HP Compressor Diffuser Mounting Bolt Holes As Required**							T (A/R)		Service Bulletin	
72 ENG2						Mos					
Eff: 24-Jul-1992						Hrs					
						Enc					
TFE731-72-5101	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)		Service Bulletin	
72 ENG1						Mos					
Eff: 03-Jun-1997						Hrs					
						Enc					
TFE731-72-5101	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)		Service Bulletin	
72 ENG2						Mos					
Eff: 03-Jun-1997						Hrs					
						Enc					
TFE731-72-5101 Rev 1	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5101 Rev 1	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5101 Rev 2	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5101 Rev 2	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5101 Rev 3	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5101 Rev 3	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5101 Rev 4	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG1						Mos	12-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5101 Rev 4	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG2						Mos	15-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5101 Rev 5	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5101 Rev 5	**Engine - Service Life - Service Life Limits Of Critical Life Limited Components**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5101 Rev 6	**Engine - Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Service Bulletin	
72 ENG1						Mos	11-Nov-2013				
Eff: 15-May-2007 Complied With						Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5101 Rev 6	**Engine - Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Service Bulletin	
72 ENG2						Mos	11-Nov-2013				
Eff: 15-May-2007 Complied With						Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5110	**Engine - By-Pass Section - Replace Fan Support Shaft No. 1 Bellows Seal And Associated Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 04-Dec-1997						Hrs					
						Enc					
TFE731-72-5110	**Engine - By-Pass Section - Replace Fan Support Shaft No. 1 Bellows Seal And Associated Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 04-Dec-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5110 Rev 1	**Engine - By-Pass Section - Replace Fan Support Shaft No. 1 Bellows Seal And Associated Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					
TFE731-72-5110 Rev 1	**Engine - By-Pass Section - Replace Fan Support Shaft No. 1 Bellows Seal And Associated Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					
TFE731-72-5110 Rev 2	**Engine - By-Pass Section - Replace Fan Support Shaft No. 1 Bellows Seal And Associated Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	11-Nov-2013				
Eff: 12-Feb-2009 Complied With						Hrs					
(NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next compressor zone inspection (CZI) or next access to affected parts, whichever occurs first. The service bulletin(s) listed in Table 3 shall be accomplished prior to or concurrent with this service bulletin: TFE731-72-5203 ENGINE - BY-PASS SECTION - Install Improved Number 1 Segmented Carbon Seal, PN 3060457-1)						Enc					
TFE731-72-5110 Rev 2	**Engine - By-Pass Section - Replace Fan Support Shaft No. 1 Bellows Seal And Associated Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Nov-2013				
Eff: 12-Feb-2009 Complied With						Hrs					
(NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next compressor zone inspection (CZI) or next access to affected parts, whichever occurs first. The service bulletin(s) listed in Table 3 shall be accomplished prior to or concurrent with this service bulletin: TFE731-72-5203 ENGINE - BY-PASS SECTION - Install Improved Number 1 Segmented Carbon Seal, PN 3060457-1)						Enc					
TFE731-72-5111	**Engine - Replace Mainshaft No. 4 And No. 5 Bellows Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 23-Dec-1997						Hrs					
						Enc					
TFE731-72-5111	**Engine - Replace Mainshaft No. 4 And No. 5 Bellows Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 23-Dec-1997						Hrs					
						Enc					
TFE731-72-5111 Rev 1	**Engine - Replace Mainshaft No. 4 And No. 5 Bellows Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5111 Rev 1	**Engine - Replace Mainshaft No. 4 And No. 5 Bellows Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5111 Rev 2	**Engine - Replace Mainshaft No. 4 And No. 5 Bellows Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5111 Rev 2	**Engine - Replace Mainshaft No. 4 And No. 5 Bellows Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5111 Rev 3	**Engine - Replace Mainshaft No. 4 And No. 5 Bellows Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	11-Nov-2013				
Eff: 28-Mar-2007 Complied With						Hrs					
(NOTE: Honeywell recommends that this service bulletin shall be accomplished at the next compressor zone inspection (CZI) or next access to affected parts whichever occurs first.)						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5111 Rev 3	**Engine - Replace Mainshaft No. 4 And No. 5 Bellows Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Nov-2013				
Eff: 28-Mar-2007 Complied With						Hrs					
	(NOTE: Honeywell recommends that this service bulletin shall be accomplished at the next compressor zone inspection (CZI) or next access to affected parts whichever occurs first.)					Enc					
TFE731-72-5115	**Compressor Section - Replace Bolts That Secure The Lp Compressor Case Assembly To The Combustion Chamber (Plenum) Case**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 02-Jul-1997						Hrs					
						Enc					
TFE731-72-5115	**Compressor Section - Replace Bolts That Secure The Lp Compressor Case Assembly To The Combustion Chamber (Plenum) Case**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 02-Jul-1997						Hrs					
						Enc					
TFE731-72-5115 Rev 1	**Compressor Section - Replace Bolts That Secure The Lp Compressor Case Assembly To The Combustion Chamber (Plenum) Case**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	11-Nov-2013				
Eff: 03-Apr-2007 Complied With						Hrs					
						Enc					
TFE731-72-5115 Rev 1	**Compressor Section - Replace Bolts That Secure The Lp Compressor Case Assembly To The Combustion Chamber (Plenum) Case**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Nov-2013				
Eff: 03-Apr-2007 Complied With						Hrs					
						Enc					
TFE731-72-5120 Rev 1	**Engine - Compressor Section - Replace The No. 4 High Pressure Rotor Roller Bearing**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	11-Nov-2013				
Eff: 28-Mar-2007 Complied With						Hrs					
						Enc					
TFE731-72-5120 Rev 1	**Engine - Compressor Section - Replace The No. 4 High Pressure Rotor Roller Bearing**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Nov-2013				
Eff: 28-Mar-2007 Complied With						Hrs					
						Enc					
TFE731-72-5124	**Engine - Accessory Drives - Install/Rework Accessory Drive Gearbox Assembly, Part Number 3060827-3 to Part Number 3060827-2**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 19-Mar-1998						Hrs					
						Enc					
TFE731-72-5124	**Engine - Accessory Drives - Install/Rework Accessory Drive Gearbox Assembly, Part Number 3060827-3 to Part Number 3060827-2**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 19-Mar-1998						Hrs					
						Enc					
TFE731-72-5124 Rev 1	**Engine - Accessory Drives - Install/Rework Accessory Drive Gearbox Assembly, Part Number 3060827-3 to Part Number 3060827-2**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5124 Rev 1	**Engine - Accessory Drives - Install/Rework Accessory Drive Gearbox Assembly, Part Number 3060827-3 to Part Number 3060827-2**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5124 Rev 2	**Engine - Accessory Drives - Install/Rework Accessory Drive Gearbox Assembly, Part Number 3060827-3 to Part Number 3060827-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Jan-2008						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5124 Rev 2	**Engine - Accessory Drives - Install/Rework Accessory Drive Gearbox Assembly, Part Number 3060827-3 to Part Number 3060827-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 22-Jan-2008						Hrs					
						Enc					
TFE731-72-5126	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, Part Number 3072231-2/-3 to Part Number 3072231-5**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 12-Jun-2000						Hrs					
						Enc					
TFE731-72-5126	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, Part Number 3072231-2/-3 to Part Number 3072231-5**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 12-Jun-2000						Hrs					
						Enc					
TFE731-72-5126 Rev 1	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, Part Number 3072231-2/-3 to Part Number 3072231-5**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
TFE731-72-5126 Rev 1	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, Part Number 3072231-2/-3 to Part Number 3072231-5**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
TFE731-72-5126 Rev 2	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, Part Number 3072231-2/-3 to Part Number 3072231-5**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 13-Feb-2008						Hrs					
(NOTE: Compliance: This service bulletin may be accomplished at operator's option, however, this service bulletin may be accomplished at the next Major Periodic Inspection (MPI) or the next time the oil filter cover is removed for other maintenance.)						Enc					
TFE731-72-5126 Rev 2	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, Part Number 3072231-2/-3 to Part Number 3072231-5**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 13-Feb-2008						Hrs					
(NOTE: Compliance: This service bulletin may be accomplished at operator's option, however, this service bulletin may be accomplished at the next Major Periodic Inspection (MPI) or the next time the oil filter cover is removed for other maintenance.)						Enc					
TFE731-72-5131	**Engine - Turbine Section - Replace Specific Identified LP Turbine 2nd Stage Rotating Air Seal, Part Number 3074108-2**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Eff: 30-Sep-1999 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-5131	**Engine - Turbine Section - Replace Specific Identified LP Turbine 2nd Stage Rotating Air Seal, Part Number 3074108-2**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Eff: 30-Sep-1999 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-5131 Rev 1	**Engine - Turbine Section - Replace Specific Identified LP Turbine 2nd Stage Rotating Air Seal, Part Number 3074108-2**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 01-Nov-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5131 Rev 1	**Engine - Turbine Section - Replace Specific Identified LP Turbine 2nd Stage Rotating Air Seal, Part Number 3074108-2**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 01-Nov-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5132	**Engine - Accessory Drives Section - Install (Oil) Filter Element, Part Number 3070945-1 (Sampling Kit, Part Number 831044-1)**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	12-Feb-2008				
Eff: 10-Aug-1999 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5132	**Engine - Accessory Drives Section - Install (Oil) Filter Element, Part Number 3070945-1 (Sampling Kit, Part Number 831044-1)**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	15-Feb-2008				
Eff: 10-Aug-1999 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5132 Rev 1	**Engine - Accessory Drives Section - Install (Oil) Filter Element, Part Number 3070945-1 (Sampling Kit, Part Number 831044-1)**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	15-Feb-2008				
Eff: 12-Feb-2008 Complied With	AT MANUFACTURE					Hrs	0				
						Enc					
TFE731-72-5132 Rev 1	**Engine - Accessory Drives Section - Install (Oil) Filter Element, Part Number 3070945-1 (Sampling Kit, Part Number 831044-1)**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	15-Feb-2008				
Eff: 12-Feb-2008 Complied With	AT MANUFACTURE					Hrs	0				
						Enc					
TFE731-72-5134	**Engine - By-Pass Section - Rework/Replace Fan Rotor Assembly**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	12-Feb-2008				
Eff: 08-Jun-2000						Hrs	0				
						Enc	0				
TFE731-72-5134	**Engine - By-Pass Section - Rework/Replace Fan Rotor Assembly**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	15-Feb-2008				
Eff: 08-Jun-2000						Hrs	0				
						Enc	0				
TFE731-72-5134 Rev 1	**Engine - By-Pass Section - Rework/Replace Fan Rotor Assembly**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	12-Feb-2008				
Eff: 14-Mar-2003 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-5134 Rev 1	**Engine - By-Pass Section - Rework/Replace Fan Rotor Assembly**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	15-Feb-2008				
Eff: 14-Mar-2003 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-5134 Rev 2	**Engine - By-Pass Section - Rework/Replace Fan Rotor Assembly**							T (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 13-Feb-2008						Hrs					
						Enc					
TFE731-72-5134 Rev 2	**Engine - By-Pass Section - Rework/Replace Fan Rotor Assembly**							T (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 13-Feb-2008						Hrs					
						Enc					
TFE731-72-5134 Rev 3	**Engine - By-Pass Section - Rework/Replace Fan Rotor Assembly**							T (A/R)		Cat. 3 - Optional	
72 ENG1						Mos					
Eff: 21-Dec-2020						Hrs					
(NOTE: CONCURRENT REQUIREMENTS: TFE731-72-5158, TFE731-72-5269)						Enc					
TFE731-72-5134 Rev 3	**Engine - By-Pass Section - Rework/Replace Fan Rotor Assembly**							T (A/R)		Cat. 3 - Optional	
72 ENG2						Mos					
Eff: 21-Dec-2020						Hrs					
(NOTE: CONCURRENT REQUIREMENTS: TFE731-72-5158, TFE731-72-5269)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5136	**Engine - By-Pass Section - Install Fan Stator Vane(S), Pn 3060378-1/3060379-1 (As Applicable) And Associated Shroud Grommet(S) Or Replace The Fan Stator Vane Assembly**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	12-Feb-2008				
Eff: 07-Oct-1999 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5136	**Engine - By-Pass Section - Install Fan Stator Vane(S), Pn 3060378-1/3060379-1 (As Applicable) And Associated Shroud Grommet(S) Or Replace The Fan Stator Vane Assembly**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	15-Feb-2008				
Eff: 07-Oct-1999 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5136 Rev 1	**Engine - By-Pass Section - Install Fan Stator Vane(S), Pn 3060378-1/3060379-1 (As Applicable) And Associated Shroud Grommet(S) Or Replace The Fan Stator Vane Assembly**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 08-Feb-2008						Hrs					
						Enc					
TFE731-72-5136 Rev 1	**Engine - By-Pass Section - Install Fan Stator Vane(S), Pn 3060378-1/3060379-1 (As Applicable) And Associated Shroud Grommet(S) Or Replace The Fan Stator Vane Assembly**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 08-Feb-2008						Hrs					
						Enc					
TFE731-72-5137	**Engine - Turbine Section - Install High Pressure HP Turbine Rotor Assembly, Part Number 3060555-4**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 08-Aug-2001						Hrs					
						Enc					
TFE731-72-5137	**Engine - Turbine Section - Install High Pressure HP Turbine Rotor Assembly, Part Number 3060555-4**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 08-Aug-2001						Hrs					
						Enc					
TFE731-72-5137 Rev 1	**Engine - Turbine Section - Install High Pressure HP Turbine Rotor Assembly, Part Number 3060555-4**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	29-Aug-2019				
Eff: 14-Dec-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5137 Rev 1	**Engine - Turbine Section - Install High Pressure HP Turbine Rotor Assembly, Part Number 3060555-4**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	29-Aug-2019				
Eff: 14-Dec-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5138	**Engine - Turbine Section - Installation of Turbine Interstage Transition (ITT) Duct and Engine Clevis**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Jan-2001						Hrs					
						Enc					
TFE731-72-5138	**Engine - Turbine Section - Installation of Turbine Interstage Transition (ITT) Duct and Engine Clevis**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 22-Jan-2001						Hrs					
						Enc					
TFE731-72-5138 Rev 1	**Engine - Turbine Section - Installation of Turbine Interstage Transition (ITT) Duct and Engine Clevis**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 14-Dec-2007						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5138 Rev 1	**Engine - Turbine Section - Installation of Turbine Interstage Transition (ITT) Duct and Engine Clevis**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 14-Dec-2007						Hrs					
						Enc					
TFE731-72-5140	**Engine - Turbine Section - Rework/Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 27-Oct-2000						Hrs					
						Enc					
TFE731-72-5140	**Engine - Turbine Section - Rework/Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 27-Oct-2000						Hrs					
						Enc					
TFE731-72-5140 Rev 1	**Engine - Turbine Section - Rework/Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5140 Rev 1	**Engine - Turbine Section - Rework/Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5140 Rev 2	**Engine - Turbine Section - Rework/Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5140 Rev 2	**Engine - Turbine Section - Rework/Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5140 Rev 3	**Engine - Turbine Section - Rework/Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 11-May-2009						Hrs					
(NOTE: Concurrent Requirements: TFE731-72-5204, TFE731-72-5179)						Enc					
TFE731-72-5140 Rev 3	**Engine - Turbine Section - Rework/Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 11-May-2009						Hrs					
(NOTE: Concurrent Requirements: TFE731-72-5204, TFE731-72-5179)						Enc					
TFE731-72-5141	**Engine - Compressor Section - Inspection/Replacement (As Required) of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) Part Number 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 05-May-2000						Hrs					
						Enc					
TFE731-72-5141	**Engine - Compressor Section - Inspection/Replacement (As Required) of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) Part Number 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 05-May-2000						Hrs					
						Enc					
TFE731-72-5141 Rev 1	**Engine - Compressor Section - Inspection/Replacement (As Required) of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) Part Number 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-5141 Rev 1	**Engine - Compressor Section - Inspection/Replacement (As Required) of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) Part Number 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Nov-2013				
Not Applicable						Hrs	3,011.7				
						Enc	1,768				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5141 Rev 2	**Engine - Compressor Section - Inspection/Replacement (As Required) of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) Part Number 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 11-Jun-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5141 Rev 2	**Engine - Compressor Section - Inspection/Replacement (As Required) of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) Part Number 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 11-Jun-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5142	**Engine - Turbine Section - Installation of HP Turbine Nozzle Segments, Part No. 3060840-1/-2/-3**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 13-Jul-2001						Hrs					
						Enc					
TFE731-72-5142	**Engine - Turbine Section - Installation of HP Turbine Nozzle Segments, Part No. 3060840-1/-2/-3**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 13-Jul-2001						Hrs					
						Enc					
TFE731-72-5142 Rev 1	**Engine - Turbine Section - Installation of HP Turbine Nozzle Segments, Part No. 3060840-1/-2/-3**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	11-Nov-2013				
Eff: 07-Jun-2007 Complied With						Hrs					
						Enc					
TFE731-72-5142 Rev 1	**Engine - Turbine Section - Installation of HP Turbine Nozzle Segments, Part No. 3060840-1/-2/-3**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	11-Nov-2013				
Eff: 07-Jun-2007 Complied With PREVIOUSLY						Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5144	**Engine - Compressor Section - Install Water Wash Tube Assembly, Part Number 3061180-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 10-Jan-2001						Hrs					
						Enc					
TFE731-72-5144	**Engine - Compressor Section - Install Water Wash Tube Assembly, Part Number 3061180-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 10-Jan-2001						Hrs					
						Enc					
TFE731-72-5145	**Engine - Consumables Installation Kits**							RE (-)		Service Bulletin	
72 ENG1						Mos					
Eff: 01-Mar-2001						Hrs					
						Enc					
TFE731-72-5145	**Engine - Consumables Installation Kits**							RE (-)		Service Bulletin	
72 ENG2						Mos					
Eff: 01-Mar-2001						Hrs					
						Enc					
TFE731-72-5145 Rev 1	**Engine - Consumables Installation Kits**							RE (-)		Service Bulletin	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5145 Rev 1	**Engine - Consumables Installation Kits**							RE (-)		Service Bulletin	
72 ENG2						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5145 Rev 2	**Engine - Consumables Installation Kits**						T (-)		Service Bulletin	
72 ENG1					Mos					
Eff: 28-Mar-2007					Hrs					
					Enc					
TFE731-72-5145 Rev 2	**Engine - Consumables Installation Kits**						T (-)		Service Bulletin	
72 ENG2					Mos					
Eff: 28-Mar-2007					Hrs					
					Enc					
TFE731-72-5145 Rev 3	**Engine - Consumables Installation Kits**						T (A/R)		Service Bulletin	
72 ENG1					Mos					
Eff: 16-Dec-2021					Hrs					
					Enc					
TFE731-72-5145 Rev 3	**Engine - Consumables Installation Kits**						T (A/R)		Service Bulletin	
72 ENG2					Mos					
Eff: 16-Dec-2021					Hrs					
					Enc					
TFE731-72-5146	**Engine - Compressor Section - Replace 1st Stage Compressor Wheel (Rotor) Shroud, Part Number 3060359-3, on Specific Identified Engine Serial Numbers**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 25-Jan-2001					Hrs					
					Enc					
TFE731-72-5146	**Engine - Compressor Section - Replace 1st Stage Compressor Wheel (Rotor) Shroud, Part Number 3060359-3, on Specific Identified Engine Serial Numbers**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 25-Jan-2001					Hrs					
					Enc					
TFE731-72-5146 Rev 1	**Engine - Compressor Section - Replace 1st Stage Compressor Wheel (Rotor) Shroud, Part Number 3060359-3, on Specific Identified Engine Serial Numbers**						T (A/R)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 17-Aug-2007					Hrs					
					Enc					
TFE731-72-5146 Rev 1	**Engine - Compressor Section - Replace 1st Stage Compressor Wheel (Rotor) Shroud, Part Number 3060359-3, on Specific Identified Engine Serial Numbers**						T (A/R)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 17-Aug-2007					Hrs					
					Enc					
TFE731-72-5147	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 27-Apr-2001					Hrs					
					Enc					
TFE731-72-5147	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 27-Apr-2001					Hrs					
					Enc					
TFE731-72-5147 Rev 1	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-72-5147 Rev 1	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-72-5147 Rev 2	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
					Hrs					
					Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5147 Rev 2	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5147 Rev 3	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5147 Rev 3	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5147 Rev 4	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Complied With	PREVIOUSLY SEE REV 3 - CW AT MANUFACTURER					Hrs					
						Enc					
TFE731-72-5147 Rev 4	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5147 Rev 5	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	13-Mar-2018				
Eff: 28-Jan-2009 Complied With						Hrs					
						Enc					
TFE731-72-5147 Rev 5	**Engine - Compressor Section - Replace No. 4 and No. 5 Segmented Carbon Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	13-Mar-2018				
Eff: 28-Jan-2009 Complied With						Hrs					
						Enc					
TFE731-72-5148	**Engine - Accessory Drives Section - Provide Authority for Installation of an Alternate Transfer Gearbox Housing Assembly**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 23-Mar-2001						Hrs					
						Enc					
TFE731-72-5148	**Engine - Accessory Drives Section - Provide Authority for Installation of an Alternate Transfer Gearbox Housing Assembly**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 23-Mar-2001						Hrs					
						Enc					
TFE731-72-5148 Rev 1	**Engine - Accessory Drives Section - Provide Authority for Installation of an Alternate Transfer Gearbox Housing Assembly**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 14-Dec-2007						Hrs					
						Enc					
TFE731-72-5148 Rev 1	**Engine - Accessory Drives Section - Provide Authority for Installation of an Alternate Transfer Gearbox Housing Assembly**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 14-Dec-2007						Hrs					
						Enc					
TFE731-72-5150	**Engine - By-Pass Section - Replace the Hoisting Bracket on the Fan Duct Set, Part Number 3072420-13 (Upper Half), on Specific Identified Engines**							RE (-)		Cat.1-Safety	
72 ENG1						Mos					
Eff: 29-Jun-2001						Hrs					
						Enc					
TFE731-72-5150	**Engine - By-Pass Section - Replace the Hoisting Bracket on the Fan Duct Set, Part Number 3072420-13 (Upper Half), on Specific Identified Engines**							RE (-)		Cat.1-Safety	
72 ENG2						Mos					
Eff: 29-Jun-2001						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5150 Rev 1	**Engine - By-Pass Section - Replace the Hoisting Bracket on the Fan Duct Set, Part Number 3072420-13 (Upper Half), on Specific Identified Engines**							RE (-)		Cat.1-Safety	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5150 Rev 1	**Engine - By-Pass Section - Replace the Hoisting Bracket on the Fan Duct Set, Part Number 3072420-13 (Upper Half), on Specific Identified Engines**							RE (-)		Cat.1-Safety	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5150 Rev 2	**Engine - By-Pass Section - Replace the Hoisting Bracket on the Fan Duct Set, Part Number 3072420-13 (Upper Half), on Specific Identified Engines**							RE (-)		Cat.1-Safety	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5150 Rev 2	**Engine - By-Pass Section - Replace the Hoisting Bracket on the Fan Duct Set, Part Number 3072420-13 (Upper Half), on Specific Identified Engines**							RE (-)		Cat.1-Safety	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5150 Rev 3	**Engine - By-Pass Section - Replace the Hoisting Bracket on the Fan Duct Set, Part Number 3072420-13 (Upper Half), on Specific Identified Engines**							RE (-)		Cat.1-Safety	
72 ENG1						Mos	29-Aug-2019				
Eff: 11-Jun-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5150 Rev 3	**Engine - By-Pass Section - Replace the Hoisting Bracket on the Fan Duct Set, Part Number 3072420-13 (Upper Half), on Specific Identified Engines**							RE (-)		Cat.1-Safety	
72 ENG2						Mos	29-Aug-2019				
Eff: 11-Jun-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5151	**Engine - Turbine Section - Replace LP Turbine 2nd Stage (LPT2) Nozzle Retainer**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 09-Nov-2001						Hrs					
						Enc					
TFE731-72-5151	**Engine - Turbine Section - Replace LP Turbine 2nd Stage (LPT2) Nozzle Retainer**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 09-Nov-2001						Hrs					
						Enc					
TFE731-72-5151 Rev 1	**Engine - Turbine Section - Replace LP Turbine 2nd Stage (LPT2) Nozzle Retainer**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 31-Oct-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5151 Rev 1	**Engine - Turbine Section - Replace LP Turbine 2nd Stage (LPT2) Nozzle Retainer**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 31-Oct-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5152	**Engine - Combustion Section - Replace Outer Transition Liner, Part Number 3060573-1, with Part Number 3060573-2 or 3067016-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 08-Feb-2002						Hrs					
						Enc					
TFE731-72-5152	**Engine - Combustion Section - Replace Outer Transition Liner, Part Number 3060573-1, with Part Number 3060573-2 or 3067016-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 08-Feb-2002						Hrs					
						Enc					
TFE731-72-5152 Rev 1	**Engine - Combustion Section - Replace Outer Transition Liner, Part Number 3060573-1, with Part Number 3060573-2 or 3067016-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5152 Rev 1	**Engine - Combustion Section - Replace Outer Transition Liner, Part Number 3060573-1, with Part Number 3060573-2 or 3067016-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5152 Rev 2	**Engine - Combustion Section - Replace Outer Transition Liner, Part Number 3060573-1, with Part Number 3060573-2 or 3067016-1**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 17-Aug-2007						Hrs					
						Enc					
TFE731-72-5152 Rev 2	**Engine - Combustion Section - Replace Outer Transition Liner, Part Number 3060573-1, with Part Number 3060573-2 or 3067016-1**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 17-Aug-2007						Hrs					
						Enc					
TFE731-72-5153	**Engine - By-Pass Section - Install Fan Duct Set, PN 3072420-13 (Matched Set), or Upper By-pass Duct, PN 3061300-3, -5, -7 or PN 70060073-1 (As Applicable), and Lower By-Pass Duct, PN 3061300-4, -6, -8 or PN 70060074-1 (As Applicable), for TFE731-20 and -40 Model Engines**							T (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 23-Jan-2007						Hrs					
						Enc					
TFE731-72-5153	**Engine - By-Pass Section - Install Fan Duct Set, PN 3072420-13 (Matched Set), or Upper By-pass Duct, PN 3061300-3, -5, -7 or PN 70060073-1 (As Applicable), and Lower By-Pass Duct, PN 3061300-4, -6, -8 or PN 70060074-1 (As Applicable), for TFE731-20 and -40 Model Engines**							T (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 23-Jan-2007						Hrs					
						Enc					
TFE731-72-5153 Rev 1	**Engine - By-Pass Section - Install Fan Duct Set, PN 3072420-13 (Matched Set), or Upper By-pass Duct, PN 3061300-3, -5, -7 or PN 70060073-1 (As Applicable), and Lower By-Pass Duct, PN 3061300-4, -6, -8 or PN 70060074-1 (As Applicable), for TFE731-20 and -40 Model Engines**							T (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 28-May-2015						Hrs					
(AVG MAN HRS: 6)						Enc					
TFE731-72-5153 Rev 1	**Engine - By-Pass Section - Install Fan Duct Set, PN 3072420-13 (Matched Set), or Upper By-pass Duct, PN 3061300-3, -5, -7 or PN 70060073-1 (As Applicable), and Lower By-Pass Duct, PN 3061300-4, -6, -8 or PN 70060074-1 (As Applicable), for TFE731-20 and -40 Model Engines**							T (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 28-May-2015						Hrs					
(AVG MAN HRS: 6)						Enc					
TFE731-72-5153 Rev 2	**Engine - By-Pass Section - Install Fan Duct Set, PN 3072420-13 (Matched Set), or Upper By-pass Duct, PN 3061300-3, -5, -7 or PN 70060073-1 (As Applicable), and Lower By-Pass Duct, PN 3061300-4, -6, -8 or PN 70060074-1 (As Applicable), for TFE731-20 and -40 Model Engines**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Apr-2018						Hrs					
(AVG MAN HRS: 6) (NOTE: CONCURRENT REQUIREMENTS:)						Enc					
TFE731-72-5153 Rev 2	**Engine - By-Pass Section - Install Fan Duct Set, PN 3072420-13 (Matched Set), or Upper By-pass Duct, PN 3061300-3, -5, -7 or PN 70060073-1 (As Applicable), and Lower By-Pass Duct, PN 3061300-4, -6, -8 or PN 70060074-1 (As Applicable), for TFE731-20 and -40 Model Engines**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 22-Apr-2018						Hrs					
(AVG MAN HRS: 6) (NOTE: CONCURRENT REQUIREMENTS:)						Enc					
TFE731-72-5154	**Engine - Turbine Section - Inspection of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 27-Jun-2002						Hrs					
						Enc					
TFE731-72-5154	**Engine - Turbine Section - Inspection of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 27-Jun-2002						Hrs					
						Enc					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5154 Rev 1	**Engine - Turbine Section - Inspection of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5154 Rev 1	**Engine - Turbine Section - Inspection of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5154 Rev 2	**Engine - Turbine Section - Inspection of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 01-Nov-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5154 Rev 2	**Engine - Turbine Section - Inspection of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 01-Nov-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5157	**Engine - Compressor Section - Remove Specific Identified LP Compressor Second Stage (LPC2) Discs**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 07-Mar-2003						Hrs					
						Enc					
TFE731-72-5157	**Engine - Compressor Section - Remove Specific Identified LP Compressor Second Stage (LPC2) Discs**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 07-Mar-2003						Hrs					
						Enc					
TFE731-72-5157 Rev 1	**Engine - Compressor Section - Remove Specific Identified LP Compressor Second Stage (LPC2) Discs**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 01-Nov-2007						Hrs					
						Enc					
TFE731-72-5157 Rev 1	**Engine - Compressor Section - Remove Specific Identified LP Compressor Second Stage (LPC2) Discs**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 01-Nov-2007						Hrs					
						Enc					
TFE731-72-5158 Rev 3	**Engine - By-Pass Section - Install an Improved Fan Disc, Fan Shaft, and Fan Roller Bearing to Enhance Fan Balance Retention**							RE (-)		Category 3	
72 ENG1						Mos	11-Nov-2013				
Eff: 11-Mar-2009 Complied With						Hrs					
						Enc					
TFE731-72-5158 Rev 3	**Engine - By-Pass Section - Install an Improved Fan Disc, Fan Shaft, and Fan Roller Bearing to Enhance Fan Balance Retention**							RE (-)		Category 3	
72 ENG2						Mos	11-Nov-2013				
Eff: 11-Mar-2009 Complied With	PREVIOUSLY					Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5159	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 05-Feb-2003						Hrs					
						Enc					
TFE731-72-5159	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 05-Feb-2003						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5159 Rev 1	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5159 Rev 1	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5159 Rev 2	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5159 Rev 2	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5159 Rev 3	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5159 Rev 3	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5159 Rev 4	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	13-Mar-2018				
Eff: 20-Sep-2012 Complied With						Hrs					
						Enc					
TFE731-72-5159 Rev 4	**Engine - Accessory Drives Section - Install the Improved Filter By-Pass Valve Assembly, PN 3060782-2**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 20-Sep-2012						Hrs					
						Enc					
TFE731-72-5160	**Engine - Turbine Section - Rework/Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating LPT3 Blades, Part Number 3060788-1**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	12-Feb-2008				
Eff: 05-Jun-2003 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5160	**Engine - Turbine Section - Rework/Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating LPT3 Blades, Part Number 3060788-1**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	15-Feb-2008				
Eff: 05-Jun-2003 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5160 Rev 1	**Engine - Turbine Section - Rework/Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating LPT3 Blades, Part Number 3060788-1**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 21-Jan-2008						Hrs					
						Enc					
TFE731-72-5160 Rev 1	**Engine - Turbine Section - Rework/Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating LPT3 Blades, Part Number 3060788-1**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 21-Jan-2008						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5163	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots**							RE (-)		Service Bulletin	
72 ENG1						Mos					
Eff: 14-Mar-2003						Hrs					
						Enc					
TFE731-72-5163	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots**							RE (-)		Service Bulletin	
72 ENG2						Mos					
Eff: 14-Mar-2003						Hrs					
						Enc					
TFE731-72-5163 Rev 1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots**							RE (-)		Service Bulletin	
72 ENG1						Mos	12-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5163 Rev 1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots**							RE (-)		Service Bulletin	
72 ENG2						Mos	15-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5163 Rev 2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots**							RE (-)		Service Bulletin	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5163 Rev 2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots**							RE (-)		Service Bulletin	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5163 Rev 3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots**							T (-)		Service Bulletin	
72 ENG1						Mos					
Eff: 03-Jul-2008						Hrs					
						Enc					
TFE731-72-5163 Rev 3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots**							T (-)		Service Bulletin	
72 ENG2						Mos					
Eff: 03-Jul-2008						Hrs					
						Enc					
TFE731-72-5163 Rev 4	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots on TFE731 Model Engines**							T (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 16-Nov-2015						Hrs					
						Enc					
TFE731-72-5163 Rev 4	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots on TFE731 Model Engines**							T (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 16-Nov-2015						Hrs					
						Enc					
TFE731-72-5163 Rev 5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots on TFE731 Model Engines**							T (A/R)		Category 3, Optional	
72 ENG1						Mos					
Eff: 27-Nov-2019						Hrs					
						Enc					
TFE731-72-5163 Rev 5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots on TFE731 Model Engines**							T (A/R)		Category 3, Optional	
72 ENG2						Mos					
Eff: 27-Nov-2019						Hrs					
						Enc					
TFE731-72-5163WA	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
Eff: 14-Mar-2003						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5163WA	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
Eff: 14-Mar-2003						Hrs					
						Enc					
TFE731-72-5163WA Rev 1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5163WA Rev 1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5163WA Rev 2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5163WA Rev 2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5163WA Rev 3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots**							T (A/R)			
72 ENG1						Mos					
Eff: 03-Jul-2008						Hrs					
						Enc					
TFE731-72-5163WA Rev 3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots**							T (A/R)			
72 ENG2						Mos					
Eff: 03-Jul-2008						Hrs					
						Enc					
TFE731-72-5164	**Engine - Turbine Section - Replace the Number 6 Rear Bearing Housing**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	12-Feb-2008				
Eff: 07-May-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5164	**Engine - Turbine Section - Replace the Number 6 Rear Bearing Housing**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	15-Feb-2008				
Eff: 07-May-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5164 Rev 1	**Engine - Turbine Section - Replace the Number 6 Rear Bearing Housing**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 14-Dec-2007						Hrs					
						Enc					
TFE731-72-5164 Rev 1	**Engine - Turbine Section - Replace the Number 6 Rear Bearing Housing**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 14-Dec-2007						Hrs					
						Enc					
TFE731-72-5165	**Engine - Turbine Section - Install an Improved LP Turbine 2nd (LPT2) Stage Nozzle Retainer and LPT2 Stage Shroud Segments**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 10-Sep-2003						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5165	**Engine - Turbine Section - Install an Improved LP Turbine 2nd (LPT2) Stage Nozzle Retainer and LPT2 Stage Shroud Segments**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 10-Sep-2003						Hrs					
						Enc					
TFE731-72-5165 Rev 1	**Engine - Turbine Section - Install an Improved LP Turbine 2nd (LPT2) Stage Nozzle Retainer and LPT2 Stage Shroud Segments**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Eff: 17-Aug-2007 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5165 Rev 1	**Engine - Turbine Section - Install an Improved LP Turbine 2nd (LPT2) Stage Nozzle Retainer and LPT2 Stage Shroud Segments**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Eff: 17-Aug-2007 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5166	**Engine - Turbine Section - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, Part No. 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Eff: 09-Dec-2003 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-5166	**Engine - Turbine Section - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, Part No. 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Eff: 09-Dec-2003 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-72-5166 Rev 1	**Engine - Turbine Section - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, Part No. 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 21-Jul-2004 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5166 Rev 1	**Engine - Turbine Section - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, Part No. 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 21-Jul-2004 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5172	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 21-Nov-2005						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-5172	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 21-Nov-2005						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-5172 Rev 1	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG1						Mos					
						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-5172 Rev 1	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG2						Mos					
						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-5172 Rev 2	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG1						Mos					
						Hrs					
(AVG MAN HRS: 3)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5172 Rev 2	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG2						Mos					
						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-5172 Rev 3	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG1						Mos	11-Nov-2013				
Complied With						Hrs	3,011.7				
(AVG MAN HRS: 3)						Enc	1,768				
TFE731-72-5172 Rev 3	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG2						Mos	11-Nov-2013				
Complied With						Hrs	3,011.7				
(AVG MAN HRS: 3)						Enc	1,768				
TFE731-72-5172 Rev 4	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							T (-)		Category 2	
72 ENG1						Mos					
Eff: 07-Apr-2014						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-5172 Rev 4	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Turbine Blade Life Limits**							T (-)		Category 2	
72 ENG2						Mos					
Eff: 07-Apr-2014						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-5172 Rev 5	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Recommended Blade Replacement Intervals for TFE731-20, -40, -50, -60 Series Engine Models**							RE		Category 2	**≈07-Dec-2024**
72 ENG1						Mos	11-Nov-2013				
Complied With						Hrs	3,011.7	3,000		6,000	725.2 Hrs
(Manual Adjustment: -11.7 Hrs)						Enc					
TFE731-72-5172 Rev 5	**Engine - Turbine Section - HPT and LPT Blade Hour Tracking and Recommended Blade Replacement Intervals for TFE731-20, -40, -50, -60 Series Engine Models**							RE		Category 2	**≈07-Dec-2024**
72 ENG2						Mos	11-Nov-2013				
Complied With						Hrs	3,011.7	3,000		6,000	725.2 Hrs
(Manual Adjustment: -11.7 Hrs)						Enc					
TFE731-72-5173	**Replace Specific Identified Helical Ring Gears, Part No.3060277-2, and Inspect Associated Parts**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 15-Jun-2005						Hrs					
						Enc					
TFE731-72-5173	**Replace Specific Identified Helical Ring Gears, Part No.3060277-2, and Inspect Associated Parts**							RE (-)		Recommended	
72 ENG2						Mos					
Eff: 15-Jun-2005						Hrs					
						Enc					
TFE731-72-5174	**Engine ? Turbine Section ? Remove Specific Identified High Pressure Turbine (Hpt) Rotor Discs**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Eff: 05-Mar-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5174	**Engine ? Turbine Section ? Remove Specific Identified High Pressure Turbine (Hpt) Rotor Discs**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Eff: 05-Mar-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5174 Rev 1	**Engine ? Turbine Section ? Remove Specific Identified High Pressure Turbine (Hpt) Rotor Discs**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 04-Dec-2007						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5174 Rev 1	**Engine ? Turbine Section ? Remove Specific Identified High Pressure Turbine (Hpt) Rotor Discs**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 04-Dec-2007						Hrs					
						Enc					
TFE731-72-5175	**Engine - Turbine Section - Replace Low Pressure (LP) 3rd Stage Turbine (LPT3) Blades, Part No. 3060690-1, on Specific Identified LPT3 Rotor Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 08-Sep-2004 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5175	**Engine - Turbine Section - Replace Low Pressure (LP) 3rd Stage Turbine (LPT3) Blades, Part No. 3060690-1, on Specific Identified LPT3 Rotor Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 08-Sep-2004 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5176	**Install Air-Oil Separator, Part No. 3075781-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Eff: 12-May-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5176	**Install Air-Oil Separator, Part No. 3075781-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Eff: 12-May-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5177	**Engine-Turbine Section- Replace Specific Identified Lp Second Stage Turbine Blades (Lpt2), Part No. 3075424-1/-2 (As Applicable)**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 10-Aug-2004 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5177	**Engine-Turbine Section- Replace Specific Identified Lp Second Stage Turbine Blades (Lpt2), Part No. 3075424-1/-2 (As Applicable)**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 10-Aug-2004 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5178	**Engine - Turbine Section - Install Low Pressure First Stage Turbine (Lpt1) Blades, Pn 3060612-2**							RE (-)			
72 ENG1						Mos					
Eff: 28-Oct-2008						Hrs					
						Enc					
TFE731-72-5178	**Engine - Turbine Section - Install Low Pressure First Stage Turbine (Lpt1) Blades, Pn 3060612-2**							RE (-)			
72 ENG2						Mos					
Eff: 28-Oct-2008						Hrs					
						Enc					
TFE731-72-5178 Rev 1	**Engine - Turbine Section - Install Low Pressure First Stage Turbine (Lpt1) Blades, Pn 3060612-2**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5178 Rev 1	**Engine - Turbine Section - Install Low Pressure First Stage Turbine (Lpt1) Blades, Pn 3060612-2**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5178 Rev 2	**Engine - Turbine Section - Install Low Pressure First Stage Turbine (Lpt1) Blades, Pn 3060612-2**							T (A/R)			
72 ENG1						Mos					
Eff: 04-Aug-2014						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5178 Rev 2	**Engine - Turbine Section - Install Low Pressure First Stage Turbine (Lpt1) Blades, Pn 3060612-2**							T (A/R)			
72 ENG2						Mos					
Eff: 04-Aug-2014						Hrs					
						Enc					
TFE731-72-5179	**Engine - Turbine Section - Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3, on TFE731-20, -40, -50, and -60 Series Engines**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 16-Feb-2009						Hrs					
(AVG MAN HRS: 10)						Enc					
TFE731-72-5179	**Engine - Turbine Section - Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3, on TFE731-20, -40, -50, and -60 Series Engines**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 16-Feb-2009						Hrs					
(AVG MAN HRS: 10)						Enc					
TFE731-72-5179 Rev 1	**Engine - Turbine Section - Install Low Pressure Second Stage Turbine (Lpt2) Blades Pn 3075424-3 On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 3	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5179 Rev 1	**Engine - Turbine Section - Install Low Pressure Second Stage Turbine (Lpt2) Blades Pn 3075424-3 On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 3	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5179 Rev 2	**Engine - Turbine Section - Install Low Pressure Second Stage Turbine (Lpt2) Blades Pn 3075424-3 On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 3	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-5179 Rev 2	**Engine - Turbine Section - Install Low Pressure Second Stage Turbine (Lpt2) Blades Pn 3075424-3 On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 3	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-5179 Rev 3	**Engine - Turbine Section - Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3, on TFE731-20, -40, -50, and -60 Series Engines**							T (A/R)		Category 3	
72 ENG1						Mos					
Eff: 04-Aug-2014						Hrs					
(AVG MAN HRS: 10)						Enc					
TFE731-72-5179 Rev 3	**Engine - Turbine Section - Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3, on TFE731-20, -40, -50, and -60 Series Engines**							T (A/R)		Category 3	
72 ENG2						Mos					
Eff: 04-Aug-2014						Hrs					
(AVG MAN HRS: 10)						Enc					
TFE731-72-5180	**Engine - Convert Engine Model TFE731-20BR to Engine Model TFE731-20AR-1B**							T (A/R)		Category 3	
72 ENG1						Mos					
Eff: 21-Apr-2005						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-72-5180	**Engine - Convert Engine Model TFE731-20BR to Engine Model TFE731-20AR-1B**							T (A/R)		Category 3	
72 ENG2						Mos					
Eff: 21-Apr-2005						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-72-5181	**Engine - By-Pass Section - Rework/Install Planetary Gearshaft Assembly, Part No. 3060129-3, -4 to Part No. 3060129-7**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 17-Jun-2005						Hrs					
						Enc					
TFE731-72-5181	**Engine - By-Pass Section - Rework/Install Planetary Gearshaft Assembly, Part No. 3060129-3, -4 to Part No. 3060129-7**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 17-Jun-2005						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5191	**Engine - Compressor Section - Install Low Pressure Second Stage Compressor (LPC2) Rotor Assembly, Part Number 3072416-15/-16, Incorporating LPC2 Blades, Part Number 3060342-3**							RE (-)		Category 3	
72 ENG1						Mos	12-Feb-2008				
Eff: 28-Mar-2007 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 10)						Enc	0				
TFE731-72-5191	**Engine - Compressor Section - Install Low Pressure Second Stage Compressor (LPC2) Rotor Assembly, Part Number 3072416-15/-16, Incorporating LPC2 Blades, Part Number 3060342-3**							RE (-)		Category 3	
72 ENG2						Mos	15-Feb-2008				
Eff: 28-Mar-2007 Complied With	AT MANUFACTURE					Hrs	0				
(AVG MAN HRS: 10)						Enc	0				
TFE731-72-5191 Rev 1	**Engine - Compressor Section - Install Low Pressure Second Stage Compressor (LPC2) Rotor Assembly, Part Number 3072416-15/-16, Incorporating LPC2 Blades, Part Number 3060342-3**							T (A/R)		Category 3	
72 ENG1						Mos					
Eff: 06-Feb-2008						Hrs					
(AVG MAN HRS: 10)						Enc					
TFE731-72-5191 Rev 1	**Engine - Compressor Section - Install Low Pressure Second Stage Compressor (LPC2) Rotor Assembly, Part Number 3072416-15/-16, Incorporating LPC2 Blades, Part Number 3060342-3**							T (A/R)		Category 3	
72 ENG2						Mos					
Eff: 06-Feb-2008						Hrs					
(AVG MAN HRS: 10)						Enc					
TFE731-72-5195	**Engine - Compressor Section - Install Low Pressure Compressor (LPC) Case Assembly, PN 3074730-5**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	12-Feb-2008				
Eff: 16-Jul-2007 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5195	**Engine - Compressor Section - Install Low Pressure Compressor (LPC) Case Assembly, PN 3074730-5**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Feb-2008				
Eff: 16-Jul-2007 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-72-5195 Rev 1	**Engine - Compressor Section - Install Low Pressure Compressor (Lpc) Case Assembly, Part Number 3074730-5**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 19-Sep-2008						Hrs					
						Enc					
TFE731-72-5195 Rev 1	**Engine - Compressor Section - Install Low Pressure Compressor (Lpc) Case Assembly, Part Number 3074730-5**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 19-Sep-2008						Hrs					
						Enc					
TFE731-72-5196	**Engine - By-Pass Section - Replace/Rework Fan Stator Vane Assembly, PN 3060163-4 to PN 3060163-5 and PN 3060239-4 to PN 3060239-5 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 29-Apr-2008						Hrs					
						Enc					
TFE731-72-5196	**Engine - By-Pass Section - Replace/Rework Fan Stator Vane Assembly, PN 3060163-4 to PN 3060163-5 and PN 3060239-4 to PN 3060239-5 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 29-Apr-2008						Hrs					
						Enc					
TFE731-72-5196 Rev 1	**Engine - By-Pass Section - Replace/Rework Fan Stator Vane Assembly, Part Number 3060163-4 To 3060163-5 And Part Number 3060239-4 To 3060239-5 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 18-Nov-2008						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5196 Rev 1	**Engine - By-Pass Section - Replace/Rework Fan Stator Vane Assembly, Part Number 3060163-4 To 3060163-5 And Part Number 3060239-4 To 3060239-5 (As Applicable)**						T (A/R)		Cat.3-Product Improvement	
72 ENG2					Mos					
Eff: 18-Nov-2008					Hrs					
					Enc					
TFE731-72-5197	**Engine - Compressor Section - Install Deswirl, PN 3060326-4**						RE (-)		Category 2	
72 ENG1					Mos					
Eff: 17-Sep-2007					Hrs					
					Enc					
TFE731-72-5197	**Engine - Compressor Section - Install Deswirl, PN 3060326-4**						RE (-)		Category 2	
72 ENG2					Mos					
Eff: 17-Sep-2007					Hrs					
					Enc					
TFE731-72-5197 Rev 1	**Engine - Compressor Section - Install Deswirl, PN 3060326-4**						T (-)		Category 2	
72 ENG1					Mos					
Eff: 19-Dec-2008					Hrs					
					Enc					
TFE731-72-5197 Rev 1	**Engine - Compressor Section - Install Deswirl, PN 3060326-4**						T (-)		Category 2	
72 ENG2					Mos					
Eff: 19-Dec-2008					Hrs					
					Enc					
TFE731-72-5197 Rev 2	**Engine - Compressor Section - Install Deswirl, PN 3060326-4**						RE (-)		Cat. 2 - Recommended	
72 ENG1					Mos					
Eff: 27-Nov-2019					Hrs					
					Enc					
TFE731-72-5197 Rev 2	**Engine - Compressor Section - Install Deswirl, PN 3060326-4**						RE (-)		Cat. 2 - Recommended	
72 ENG2					Mos					
Eff: 27-Nov-2019					Hrs					
					Enc					
TFE731-72-5198	**Engine - Compressor Section - Inspect Low Pressure Compressor First Stage Rotor Assembly (LPC1) Blades, PN 3060341-1, and Rework LPC2 Rotating Shroud, PN 3072403-4 to PN 3072403-5**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos	12-Feb-2008				
Eff: 07-Sep-2007 Complied With	AT MANUFACTURE				Hrs	0				
					Enc	0				
TFE731-72-5198	**Engine - Compressor Section - Inspect Low Pressure Compressor First Stage Rotor Assembly (LPC1) Blades, PN 3060341-1, and Rework LPC2 Rotating Shroud, PN 3072403-4 to PN 3072403-5**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos	15-Feb-2008				
Eff: 07-Sep-2007 Complied With	AT MANUFACTURE				Hrs	0				
					Enc	0				
TFE731-72-5198 Rev 1	**Engine - Compressor Section - Inspect Low Pressure First Stage Rotor Assembly (Lpc1) Blades, Part Number 3060341-1, And Rework Lpc2 Rotating Shroud, Part Number 3072403-4 To Part Number 3072403-5**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-72-5198 Rev 1	**Engine - Compressor Section - Inspect Low Pressure First Stage Rotor Assembly (Lpc1) Blades, Part Number 3060341-1, And Rework Lpc2 Rotating Shroud, Part Number 3072403-4 To Part Number 3072403-5**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5198 Rev 2	**Engine - Compressor Section - Inspect Low Pressure First Stage Rotor Assembly (Lpc1) Blades, Part Number 3060341-1, And Rework Lpc2 Rotating Shroud, Part Number 3072403-4 To Part Number 3072403-5**						T (A/R)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 19-Sep-2008					Hrs					
					Enc					
TFE731-72-5198 Rev 2	**Engine - Compressor Section - Inspect Low Pressure First Stage Rotor Assembly (Lpc1) Blades, Part Number 3060341-1, And Rework Lpc2 Rotating Shroud, Part Number 3072403-4 To Part Number 3072403-5**						T (A/R)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 19-Sep-2008					Hrs					
					Enc					
TFE731-72-5199	**Engine - Compressor Section - Install Improved-Design First Stage Low Pressure Compressor (LPC1) Rotor Shroud, PN 3071873-6 and LPC1 Rotor Assembly, PN 3070440-24, -26 (As Applicable)**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 18-Jan-2008					Hrs					
					Enc					
TFE731-72-5199	**Engine - Compressor Section - Install Improved-Design First Stage Low Pressure Compressor (LPC1) Rotor Shroud, PN 3071873-6 and LPC1 Rotor Assembly, PN 3070440-24, -26 (As Applicable)**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 18-Jan-2008					Hrs					
					Enc					
TFE731-72-5199 Rev 1	**Engine - Compressor Section - Install Improved-Design First Stage Low Pressure Compressor (LPC1) Rotor Shroud, Pn 3071873-6 And LPC1 Rotor Assembly, Pn 3070440-24, -26 (As Applicable)**						T (A/R)		Category 2	
72 ENG1					Mos					
Eff: 19-Sep-2008					Hrs					
					Enc					
TFE731-72-5199 Rev 1	**Engine - Compressor Section - Install Improved-Design First Stage Low Pressure Compressor (LPC1) Rotor Shroud, Pn 3071873-6 And LPC1 Rotor Assembly, Pn 3070440-24, -26 (As Applicable)**						T (A/R)		Category 2	
72 ENG2					Mos					
Eff: 19-Sep-2008					Hrs					
					Enc					
TFE731-72-5200	**Replace Low Pressure Compressor 2nd Stage (LPC2) Rotor Assembly, Pn 3072416-12, -13, -17 With Pn 3075841-2**						T (A/R)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 22-May-2008					Hrs					
					Enc					
TFE731-72-5200	**Replace Low Pressure Compressor 2nd Stage (LPC2) Rotor Assembly, Pn 3072416-12, -13, -17 With Pn 3075841-2**						T (A/R)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 22-May-2008					Hrs					
					Enc					
TFE731-72-5201	**Engine - Compressor Section - Replace Low Pressure Compressor 4Th Stage (Lpc4) Case And Vane Assembly, Pn 3060361-4 With Pn 3060361-5**						T (A/R)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 10-Dec-2008					Hrs					
					Enc					
TFE731-72-5201	**Engine - Compressor Section - Replace Low Pressure Compressor 4Th Stage (Lpc4) Case And Vane Assembly, Pn 3060361-4 With Pn 3060361-5**						T (A/R)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 10-Dec-2008					Hrs					
					Enc					
TFE731-72-5202	**Engine - Compressor Section - Install Improved No. 4 Segmented Carbon Seal, Pn 3060437-1, And No. 5 Segmented Carbon Seal, Pn 3060436-1**						T (A/R)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 21-Apr-2008					Hrs					
					Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5202	**Engine - Compressor Section - Install Improved No. 4 Segmented Carbon Seal, Pn 3060437-1, And No. 5 Segmented Carbon Seal, Pn 3060436-1**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 21-Apr-2008						Hrs					
						Enc					
TFE731-72-5203	**Engine - By-Pass Section - Install Improved No. 1 Segmented Carbon Seal, Pn 3060457-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	11-Nov-2013				
Eff: 21-Apr-2008 Complied With						Hrs					
						Enc					
TFE731-72-5203	**Engine - By-Pass Section - Install Improved No. 1 Segmented Carbon Seal, Pn 3060457-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Nov-2013				
Eff: 21-Apr-2008 Complied With	PREVIOUSLY					Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5204	**Engine - Turbine Section - Incorporate Improved Design Low Pressure Turbine First Stage (LPT1) Rotor Assembly And LPT2 Rotor Assembly Blade Retainers**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 11-Apr-2008						Hrs					
						Enc					
TFE731-72-5204	**Engine - Turbine Section - Incorporate Improved Design Low Pressure Turbine First Stage (LPT1) Rotor Assembly And LPT2 Rotor Assembly Blade Retainers**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 11-Apr-2008						Hrs					
						Enc					
TFE731-72-5204 Rev 1	**Engine - Turbine Section - Incorporate Improved Design Low Pressure Turbine First Stage (LPT1) Rotor Assembly And LPT2 Rotor Assembly Blade Retainers**							RE (-)			
72 ENG1						Mos	11-Nov-2013				
Eff: 11-May-2009 Complied With						Hrs					
						Enc					
TFE731-72-5204 Rev 1	**Engine - Turbine Section - Incorporate Improved Design Low Pressure Turbine First Stage (LPT1) Rotor Assembly And LPT2 Rotor Assembly Blade Retainers**							RE (-)			
72 ENG2						Mos	11-Nov-2013				
Eff: 11-May-2009 Complied With						Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5207	**Engine - Turbine Section - Replace Non-Captured Hpt And Lpt2 Curvic Seal Rings With Captured Seal Rings**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 12-Dec-2008 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5207	**Engine - Turbine Section - Replace Non-Captured Hpt And Lpt2 Curvic Seal Rings With Captured Seal Rings**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 12-Dec-2008 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5208	**Rework/Install LP Third Stage Turbine (LPT 3) Rotor Assembly Incorporating Improved-Design LPT 3 Blades, Pn 3061823-2**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	11-Nov-2013				
Eff: 23-Oct-2009 Complied With						Hrs					
						Enc					
TFE731-72-5208	**Rework/Install LP Third Stage Turbine (LPT 3) Rotor Assembly Incorporating Improved-Design LPT 3 Blades, Pn 3061823-2**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Nov-2013				
Eff: 23-Oct-2009 Complied With						Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5211	**Re-Sequence High Pressure (HP) Turbine Nozzle Vane Segments On Specific Engines**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	29-Aug-2019				
Eff: 21-Jul-2009 Not Applicable						Hrs	4,516.2				
						Enc	2,733				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5211	**Re-Sequence High Pressure (HP) Turbine Nozzle Vane Segments On Specific Engines**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	29-Aug-2019				
Eff: 21-Jul-2009 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-72-5215	**Install Improved Rear Bearing Housing Support That Provides Additional Clearance To Lpt3 Blades**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 18-Mar-2010						Hrs					
						Enc					
TFE731-72-5215	**Install Improved Rear Bearing Housing Support That Provides Additional Clearance To Lpt3 Blades**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 18-Mar-2010						Hrs					
						Enc					
TFE731-72-5216	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal PN 3020052-26**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 07-Jun-2011						Hrs					
						Enc					
TFE731-72-5216	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal PN 3020052-26**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 07-Jun-2011						Hrs					
						Enc					
TFE731-72-5216 Rev 1	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal Pn 3020052-26**							RE (-)		Category 2	
72 ENG1						Mos	11-Nov-2013				
Eff: 28-Oct-2011 Complied With						Hrs	3,011.7				
(NOTE: Honeywell recommends that this service bulletin be accomplished at the next MPI, or the next access to the affected parts, whichever occurs first. Access is defined as removal of the engine fuel pump or removal of the aircraft hydraulic pump.)						Enc	1,768				
TFE731-72-5216 Rev 1	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal Pn 3020052-26**							RE (-)		Category 2	
72 ENG2						Mos	11-Nov-2013				
Eff: 28-Oct-2011 Complied With						Hrs	3,011.7				
(NOTE: Honeywell recommends that this service bulletin be accomplished at the next MPI, or the next access to the affected parts, whichever occurs first. Access is defined as removal of the engine fuel pump or removal of the aircraft hydraulic pump.)						Enc	1,768				
TFE731-72-5217	**Install Improved Front Frame Assembly, Pn 3060421-3, Pn 3061505-4, Or Pn 3060439-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Oct-2010						Hrs					
						Enc					
TFE731-72-5217	**Install Improved Front Frame Assembly, Pn 3060421-3, Pn 3061505-4, Or Pn 3060439-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 22-Oct-2010						Hrs					
						Enc					
TFE731-72-5218	**Introduction Of New Second Stage Low Pressure Compressor (Lpc2) Blade, Pn 3075840-3**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 08-Nov-2010						Hrs					
						Enc					
TFE731-72-5218	**Introduction Of New Second Stage Low Pressure Compressor (Lpc2) Blade, Pn 3075840-3**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 08-Nov-2010						Hrs					
						Enc					
TFE731-72-5221	**Replace Specific Identified Low Pressure Second Stage Turbine (Lpt2) Rotor Blades, Pn 3075424-2, -3**							RE (-)		Cat.1-Safety	
72 ENG1						Mos	11-Nov-2013				
Eff: 11-Nov-2010 Not Applicable						Hrs	3,011.7				
						Enc	1,768				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5221	**Replace Specific Identified Low Pressure Second Stage Turbine (Lpt2) Rotor Blades, Pn 3075424-2, -3**							RE (-)		Cat.1-Safety	
72 ENG2						Mos	11-Nov-2013				
Eff: 11-Nov-2010 Not Applicable						Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5221 Rev 1	**Replace Specific Identified Low Pressure Second Stage Turbine (LPT2) Rotor Blades, PN 3075424-2, -3**							RE (-)		Cat.1-Safety	
72 ENG1						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 11.5) (NOTE: COMPLIANCE: Honeywell recommends that the engine be disassembled for the removal of any suspect LPT2 rotor blade, PN 3075424-2, -3, at the next scheduled major periodic inspection (MPI) or at next access to the LPT2 rotor assembly, PN 3060608-2, -3, -5, not to exceed 3000 hours TSN on the LPT2 rotor blades, PN 3075424-2, -3, whichever comes first. Next access is defined as when the LPT module is disassembled.)						Enc	2,822				
TFE731-72-5221 Rev 1	**Replace Specific Identified Low Pressure Second Stage Turbine (LPT2) Rotor Blades, PN 3075424-2, -3**							RE (-)		Cat.1-Safety	
72 ENG2						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 11.5) (NOTE: COMPLIANCE: Honeywell recommends that the engine be disassembled for the removal of any suspect LPT2 rotor blade, PN 3075424-2, -3, at the next scheduled major periodic inspection (MPI) or at next access to the LPT2 rotor assembly, PN 3060608-2, -3, -5, not to exceed 3000 hours TSN on the LPT2 rotor blades, PN 3075424-2, -3, whichever comes first. Next access is defined as when the LPT module is disassembled.)						Enc	2,822				
TFE731-72-5221 Rev 1 Para (3)	**Turbine Section - Replace Specific Identified Low Pressure Second Stage Turbine (Lpt2) Rotor Blades, Pn 3075424-2, -3 Review Engine Log Book (Including The Life Limited Part Log Card For The Installed Lpt2 Rotor Assembly, Pn 3060608-2, -3, -5), And This Service Bulletin To Determine If The Engine Is Effected (Category 1)**							RE (-)		Category 1	
72 ENG1						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-72-5221 Rev 1 Para (3)	**Turbine Section - Replace Specific Identified Low Pressure Second Stage Turbine (Lpt2) Rotor Blades, Pn 3075424-2, -3 Review Engine Log Book (Including The Life Limited Part Log Card For The Installed Lpt2 Rotor Assembly, Pn 3060608-2, -3, -5), And This Service Bulletin To Determine If The Engine Is Effected (Category 1)**							RE (-)		Category 1	
72 ENG2						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-72-5221 Rev 1 Para (6)	**Turbine Section - Replace Specific Identified Low Pressure Second Stage Turbine (Lpt2) Rotor Blades, Pn 3075424-2, -3 Remove Suspect Lpt2 Rotor Blade (Category 1)**							RE (-)		Category 1	
72 ENG1						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-72-5221 Rev 1 Para (6)	**Turbine Section - Replace Specific Identified Low Pressure Second Stage Turbine (Lpt2) Rotor Blades, Pn 3075424-2, -3 Remove Suspect Lpt2 Rotor Blade (Category 1)**							RE (-)		Category 1	
72 ENG2						Mos	14-Dec-2020				
Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-72-5222	**Engine - Compressor Section - Install Front Frame Assembly that has Additional Corrosion Protection Features**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 19-Aug-2011						Hrs					
						Enc					
TFE731-72-5222	**Engine - Compressor Section - Install Front Frame Assembly that has Additional Corrosion Protection Features**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 19-Aug-2011						Hrs					
						Enc					
TFE731-72-5222 Rev 1	**Engine - Compressor Section - Install Front Frame Assembly that has Additional Corrosion Protection Features**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 01-May-2012						Hrs					
(NOTE: Honeywell recommends that this service bulletin be accomplished at the next CZI.)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5222 Rev 1	**Engine - Compressor Section - Install Front Frame Assembly that has Additional Corrosion Protection Features**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 01-May-2012						Hrs					
	(NOTE: Honeywell recommends that this service bulletin be accomplished at the next CZI.)					Enc					
TFE731-72-5222 Rev 2	**Engine - Compressor Section - Install Front Frame Assembly that has Additional Corrosion Protection Features**							T		Cat.2-Reliability	**≈07-Dec-2024**
72 ENG1						Mos					
						Hrs		6,000		6,000	725.2 Hrs
	(AVG MAN HRS: 4) (NOTE: CONCURRENT REQUIREMENTS					Enc					
	COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next CZI.)										
TFE731-72-5222 Rev 2	**Engine - Compressor Section - Install Front Frame Assembly that has Additional Corrosion Protection Features**							T		Cat.2-Reliability	**≈07-Dec-2024**
72 ENG2						Mos					
						Hrs		6,000		6,000	725.2 Hrs
	(AVG MAN HRS: 4) (NOTE: CONCURRENT REQUIREMENTS					Enc					
	COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next CZI.)										
TFE731-72-5223	**Engine - Bypass Section - Apply Protective Coating to the Aft Flange of the Composite Bypass Duct on TFE731-20, -40, -50, and -60 Engine Models**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	11-Nov-2013				
Eff: 19-Aug-2011 Complied With						Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5223	**Engine - Bypass Section - Apply Protective Coating to the Aft Flange of the Composite Bypass Duct on TFE731-20, -40, -50, and -60 Engine Models**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Nov-2013				
Eff: 19-Aug-2011 Complied With						Hrs	3,011.7				
						Enc	1,768				
TFE731-72-5223 Rev 1	**Engine - Bypass Section - Apply Protective Coating to the Aft Flange of the Composite Bypass Duct on TFE731-20, -40, -50, and -60 Engine Models**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
	(AVG MAN HRS: 2) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next MPI. If a CZI is					Enc					
	being accomplished, Service Bulletin TFE731-72-5224 should be complied with instead of this service bulletin.)										
TFE731-72-5223 Rev 1	**Engine - Bypass Section - Apply Protective Coating to the Aft Flange of the Composite Bypass Duct on TFE731-20, -40, -50, and -60 Engine Models**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
	(AVG MAN HRS: 2) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next MPI. If a CZI is					Enc					
	being accomplished, Service Bulletin TFE731-72-5224 should be complied with instead of this service bulletin.)										
TFE731-72-5224	**Engine - Bypass Section - Inspect, Rework, or Replace Composite Bypass Ducts on TFE731-20, -40, -50, and -60 Engine Models**							T (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 19-Aug-2011						Hrs					
						Enc					
TFE731-72-5224	**Engine - Bypass Section - Inspect, Rework, or Replace Composite Bypass Ducts on TFE731-20, -40, -50, and -60 Engine Models**							T (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 19-Aug-2011						Hrs					
						Enc					
TFE731-72-5224 R1	**Inspect, Rework, or Replace Composite Bypass Ducts on TFE731-20, -40, -50, and -60 Engine Models**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
	(AVG MAN HRS: 14) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next CZI.)					Enc					
TFE731-72-5224 R1	**Inspect, Rework, or Replace Composite Bypass Ducts on TFE731-20, -40, -50, and -60 Engine Models**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
	(AVG MAN HRS: 14) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next CZI.)					Enc					
TFE731-72-5225	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2)Shroud, PN 3072403-6**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 22-Jul-2011						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5225	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2)Shroud, PN 3072403-6**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 22-Jul-2011						Hrs					
						Enc					
TFE731-72-5225 Rev 1	**Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2)Shroud, PN 3072403-6**							T (A/R)		Category 2	**≈07-Dec-2024**
72 ENG1						Mos					
Eff: 17-Aug-2012						Hrs				[6,000]	725.2 Hrs
						Enc					
TFE731-72-5225 Rev 1	**Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2)Shroud, PN 3072403-6**							T (A/R)		Category 2	**≈07-Dec-2024**
72 ENG2						Mos					
Eff: 17-Aug-2012						Hrs				[6,000]	725.2 Hrs
						Enc					
TFE731-72-5227	**Engine - Accessory Drive Gearbox Assembly Section - Introduction Of Accessory Drive Gearbox Assembly With Hydrodynamic Carbon Face Seals**							T (-)		Category 2	
72 ENG1						Mos					
Eff: 19-Mar-2014						Hrs					
						Enc					
TFE731-72-5227	**Engine - Accessory Drive Gearbox Assembly Section - Introduction Of Accessory Drive Gearbox Assembly With Hydrodynamic Carbon Face Seals**							T (-)		Category 2	
72 ENG2						Mos					
Eff: 19-Mar-2014						Hrs					
						Enc					
TFE731-72-5227 Rev 1	**Engine - Accessory Drive Gearbox Assembly Section - Introduction Of Accessory Drive Gearbox Assembly With Hydrodynamic Carbon Face Seals**							T (A/R)		Cat.2-Reliability	**≈07-Dec-2024**
72 ENG1						Mos					
Eff: 24-Jul-2015						Hrs				[6,000]	725.2 Hrs
(AVG MAN HRS: 1) (NOTE: Honeywell recommends that this service bulletin be accomplished at the next CZI.)						Enc					
TFE731-72-5227 Rev 1	**Engine - Accessory Drive Gearbox Assembly Section - Introduction Of Accessory Drive Gearbox Assembly With Hydrodynamic Carbon Face Seals**							T (A/R)		Cat.2-Reliability	**≈07-Dec-2024**
72 ENG2						Mos					
Eff: 24-Jul-2015						Hrs				[6,000]	725.2 Hrs
(AVG MAN HRS: 1) (NOTE: Honeywell recommends that this service bulletin be accomplished at the next CZI.)						Enc					
TFE731-72-5228RWK	**Provide Eddy Current Corrosion Inspection And Rework Instructions For The Front Frame Assemblies**							T (A/R)			
72 ENG1						Mos					
Eff: 01-May-2012						Hrs					
						Enc					
TFE731-72-5228RWK	**Provide Eddy Current Corrosion Inspection And Rework Instructions For The Front Frame Assemblies**							T (A/R)			
72 ENG2						Mos					
Eff: 01-May-2012						Hrs					
						Enc					
TFE731-72-5236	**Engine - Fan Inlet Housing Installation - Installation Of New Or Reworked Fan Inlet Housing**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 25-Nov-2013						Hrs					
						Enc					
TFE731-72-5236	**Engine - Fan Inlet Housing Installation - Installation Of New Or Reworked Fan Inlet Housing**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 25-Nov-2013						Hrs					
						Enc					
TFE731-72-5236 Rev 1	**Engine - Fan Inlet Housing Installation - Installation Of New Or Reworked Fan Inlet Housing**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 23-Jan-2015						Hrs					
						Enc					
TFE731-72-5236 Rev 1	**Engine - Fan Inlet Housing Installation - Installation Of New Or Reworked Fan Inlet Housing**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 23-Jan-2015						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5247	**Engine - Bypass Section - Replace Fan Stator Vane Assembly, PN 3060163-3, -4, -5 with PN 70060130-1 for TFE731-20, -40 Engine Models**							RE (-)		Category 2	**≈07-Dec-2024**
72 ENG1						Mos					
Eff: 08-Jul-2015						Hrs				[6,000]	725.2 Hrs
						Enc					
TFE731-72-5247	**Engine - Bypass Section - Replace Fan Stator Vane Assembly, PN 3060163-3, -4, -5 with PN 70060130-1 for TFE731-20, -40 Engine Models**							RE (-)		Category 2	**≈07-Dec-2024**
72 ENG2						Mos					
Eff: 08-Jul-2015						Hrs				[6,000]	725.2 Hrs
						Enc					
TFE731-72-5251	**Engine - Turbine Section - Accomplish Eddy Current Inspection of Specific Second Stage Low Pressure Turbine (LPT2) Blades PN 3075424 on TFE731-20 -40 -50 -60 Model Engines**							RE (-)		Category 2	
72 ENG1						Mos	29-Aug-2019				
Eff: 25-Mar-2015 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 12) (NOTE: Honeywell recommends that this service bulletin be accomplished at next access to affected parts but no later than the next MPI. (3) Next access is defined as whenever the LP tie rod is unstretched)						Enc	2,733				
TFE731-72-5251	**Engine - Turbine Section - Accomplish Eddy Current Inspection of Specific Second Stage Low Pressure Turbine (LPT2) Blades PN 3075424 on TFE731-20 -40 -50 -60 Model Engines**							RE (-)		Category 2	
72 ENG2						Mos	29-Aug-2019				
Eff: 25-Mar-2015 Not Applicable						Hrs	4,516.2				
(AVG MAN HRS: 12) (NOTE: Honeywell recommends that this service bulletin be accomplished at next access to affected parts but no later than the next MPI. (3) Next access is defined as whenever the LP tie rod is unstretched)						Enc	2,733				
TFE731-72-5251 Rev 1	**Engine - Turbine Section - Accomplish Eddy Current Inspection of Specific Second Stage Low Pressure Turbine (LPT2) Blades, PN 3075424, on TFE731-20, -40, -50, -60 Model Engines**							T (A/R)		Cat. 2 - Recommended	
72 ENG1						Mos					
Eff: 16-Feb-2021						Hrs					
(AVG MAN HRS: 12) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at next access to affected parts but no later than the next MPI.)						Enc					
TFE731-72-5251 Rev 1	**Engine - Turbine Section - Accomplish Eddy Current Inspection of Specific Second Stage Low Pressure Turbine (LPT2) Blades, PN 3075424, on TFE731-20, -40, -50, -60 Model Engines**							T (A/R)		Cat. 2 - Recommended	
72 ENG2						Mos					
Eff: 16-Feb-2021						Hrs					
(AVG MAN HRS: 12) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at next access to affected parts but no later than the next MPI.)						Enc					
TFE731-72-5253	**ENGINE - COMPRESSOR SECTION - Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5 on TFE731-20, -40, -50, and -60 Engine Models**							T (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 02-Dec-2015						Hrs					
						Enc					
TFE731-72-5253	**ENGINE - COMPRESSOR SECTION - Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5 on TFE731-20, -40, -50, and -60 Engine Models**							T (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 02-Dec-2015						Hrs					
						Enc					
TFE731-72-5253 Rev 1	**ENGINE - COMPRESSOR SECTION - Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5 on TFE731-20, -40, -50, and -60 Engine Models**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 29-Oct-2019						Hrs					
(NOTE: COMPLIANCE: Honeywell recommends this service bulletin be accomplished at next access.)						Enc					
TFE731-72-5253 Rev 1	**ENGINE - COMPRESSOR SECTION - Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5 on TFE731-20, -40, -50, and -60 Engine Models**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 29-Oct-2019						Hrs					
(NOTE: COMPLIANCE: Honeywell recommends this service bulletin be accomplished at next access.)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5256	**Engine - Fan Disc - Identify and Replace Specific Fan Discs, PN 3060287-2, with Suspect Shot Peened Rolled Edges on TFE731-20 and -40 Engine Models**							T (-)		Cat.1-Safety	
72 ENG1						Mos					
Eff: 07-Oct-2016						Hrs					
(AVG MAN HRS: 20) (NOTE: WARNING: FAILURE TO COMPLY WITH THIS SERVICE BULLETIN COULD CAUSE DISTRESS TO THE FAN DISC. IF LEFT UNCORRECTED, THIS DISTRESS COULD CAUSE A FAN DISC RUPTURE - HIGH ENERGY FRAGMENTS COULD BE EJECTED FROM THE ENGINE AND COULD CAUSE SERIOUS INJURY OR DEATH TO PERSONNEL, AND "DAMAGE TO" OR "LOSS OF" THE AIRCRAFT.)						Enc					
TFE731-72-5256	**Engine - Fan Disc - Identify and Replace Specific Fan Discs, PN 3060287-2, with Suspect Shot Peened Rolled Edges on TFE731-20 and -40 Engine Models**							T (-)		Cat.1-Safety	
72 ENG2						Mos					
Eff: 07-Oct-2016						Hrs					
(AVG MAN HRS: 20) (NOTE: WARNING: FAILURE TO COMPLY WITH THIS SERVICE BULLETIN COULD CAUSE DISTRESS TO THE FAN DISC. IF LEFT UNCORRECTED, THIS DISTRESS COULD CAUSE A FAN DISC RUPTURE - HIGH ENERGY FRAGMENTS COULD BE EJECTED FROM THE ENGINE AND COULD CAUSE SERIOUS INJURY OR DEATH TO PERSONNEL, AND "DAMAGE TO" OR "LOSS OF" THE AIRCRAFT.)						Enc					
TFE731-72-5256 Rev 1	**Engine - Bypass Section - Identify and Replace Specific Fan Disks, PN 3060287-2, with Suspect Shot Peened Rolled Edges on TFE731-20 and -40 Engine Models**							RE (-)		Category 1	
72 ENG1						Yrs	24-Jun-2021				
Eff: 07-Oct-2016 Not Applicable						Hrs	4,694.8				
(AVG MAN HRS: 32) (UPDATE NOTE: N/A by Fan S/N. Affected S/N not installed.) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next access to affected parts but not later than the next MPI, 9,000 disk cycles, or 5 years from the original October 7, 2016 publish date of this service bulletin, whichever occurs first.)						Enc	2,882				
TFE731-72-5256 Rev 1	**Engine - Bypass Section - Identify and Replace Specific Fan Disks, PN 3060287-2, with Suspect Shot Peened Rolled Edges on TFE731-20 and -40 Engine Models**							RE (-)		Category 1	
72 ENG2						Yrs	24-Jun-2021				
Eff: 07-Oct-2016 Not Applicable						Hrs	4,694.8				
(AVG MAN HRS: 32) (UPDATE NOTE: N/A by Fan S/N. Affected S/N not installed) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at the next access to affected parts but not later than the next MPI, 9,000 disk cycles, or 5 years from the original October 7, 2016 publish date of this service bulletin, whichever occurs first.)						Enc	2,882				
TFE731-72-5258	**Engine - Bypass Section - Replace No. 2 Bearing Spacer, PN 3060125-1, with PN 3060125-3, on TFE731-20, -40 Engines**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 09-Aug-2019						Hrs					
(AVG MAN HRS: 0.5) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished when/if there is a fan vibration issue or the current part is no longer serviceable.)						Enc					
TFE731-72-5258	**Engine - Bypass Section - Replace No. 2 Bearing Spacer, PN 3060125-1, with PN 3060125-3, on TFE731-20, -40 Engines**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 09-Aug-2019						Hrs					
(AVG MAN HRS: 0.5) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished when/if there is a fan vibration issue or the current part is no longer serviceable.)						Enc					
TFE731-72-5260	**Compressor Section - Identify and Replace Specific Low Pressure Compressor 4Th Stage (LPC4) Case and Vane Assembly, PN 3060361-5, on TFE731-20, -40, -50, -60 Series Engine Models**							T (-)		Category 2, Custom Task	**≈07-Dec-2024**
72 ENG1						Mos					
						Hrs				[6,000]	725.2 Hrs
						Enc					
TFE731-72-5260	**Compressor Section - Identify and Replace Specific Low Pressure Compressor 4Th Stage (LPC4) Case and Vane Assembly, PN 3060361-5, on TFE731-20, -40, -50, -60 Series Engine Models**							T (-)		Category 2, Custom Task	**≈07-Dec-2024**
72 ENG2						Mos					
						Hrs				[6,000]	725.2 Hrs
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-5264	**ENGINE - BYPASS SECTION - Replace Rigid Shaft Coupling PN 3060116-1 with PN 3060116-2**							T (-)			
72 ENG1						Mos					
Eff: 08-Jun-2016						Hrs					
						Enc					
TFE731-72-5264	**ENGINE - BYPASS SECTION - Replace Rigid Shaft Coupling PN 3060116-1 with PN 3060116-2**							T (-)			
72 ENG2						Mos					
Eff: 08-Jun-2016						Hrs					
						Enc					
TFE731-72-5264 Rev 1	**Engine - Bypass Section - Replace Rigid Shaft Coupling, PN 3060116-1 with PN 3060116-2, on TFE731-20, -40 Engines**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 09-Aug-2019						Hrs					
(AVG MAN HRS: 0.5) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished when/if there is a fan vibration issue or the current part is no longer serviceable.)						Enc					
TFE731-72-5264 Rev 1	**Engine - Bypass Section - Replace Rigid Shaft Coupling, PN 3060116-1 with PN 3060116-2, on TFE731-20, -40 Engines**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 09-Aug-2019						Hrs					
(AVG MAN HRS: 0.5) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished when/if there is a fan vibration issue or the current part is no longer serviceable.)						Enc					
TFE731-72-5267	**Engine - Bypass Section - Composite Bypass Duct Optional Replacement Configurations on Specific TFE731-20 -40 Engine Models**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Apr-2018						Hrs					
(NOTE: CONCURRENT REQUIREMENTS:)						Enc					
TFE731-72-5267	**Engine - Bypass Section - Composite Bypass Duct Optional Replacement Configurations on Specific TFE731-20 -40 Engine Models**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 22-Apr-2018						Hrs					
(NOTE: CONCURRENT REQUIREMENTS:)						Enc					
TFE731-72-5268	**Engine - Engine Wire Harness Installation - Apply Retaining Compound to Engine Wiring Harness Attachment Nuts and Install Silicone Self Adhering Tape to Engine ITT Harness Electrical Connector**							T (A/R)		Cat. 2 - Recommended	
72 ENG1						Mos					
Eff: 13-Aug-2019						Hrs					
(AVG MAN HRS: 0.25)						Enc					
TFE731-72-5268	**Engine - Engine Wire Harness Installation - Apply Retaining Compound to Engine Wiring Harness Attachment Nuts and Install Silicone Self Adhering Tape to Engine ITT Harness Electrical Connector**							T (A/R)		Cat. 2 - Recommended	
72 ENG2						Mos					
Eff: 13-Aug-2019						Hrs					
(AVG MAN HRS: 0.25)						Enc					
TFE731-72-A5240	**Engine - Turbine Section - Inspect Or Replace Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades Installed On Tfe731-20 -40 -50 And -60 Series Engines**							T (A/R)		Category 1	
72 ENG1						Mos					
Eff: 25-Jun-2014						Hrs					
(AVG MAN HRS: 12)						Enc					
TFE731-72-A5240	**Engine - Turbine Section - Inspect Or Replace Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades Installed On Tfe731-20 -40 -50 And -60 Series Engines**							T (A/R)		Category 1	
72 ENG2						Mos					
Eff: 25-Jun-2014						Hrs					
(AVG MAN HRS: 12)						Enc					
TFE731-72-A5242	**Engine - Turbine Section - Suspect Second Stage Low Pressure Turbine (Lpt2) Blades On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 1	
72 ENG1						Mos	13-Jun-2014				
Eff: 05-Jun-2014 Complied With	REVIEWED ENGINE LOGBOOK MAINTENANCE RECORDS, NO LPT2 BLADES AFFECTED ON SECTION (E) OF THE AD. NO FURTHER ACTION REQUIRED AT THIS TIME.					Hrs	3,195.4				
						Enc	1,869				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-A5242	**Engine - Turbine Section - Suspect Second Stage Low Pressure Turbine (Lpt2) Blades On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 1	
72 ENG2						Mos	13-Jun-2014				
Eff: 05-Jun-2014 Complied With	REVIEWED ENGINE LOGBOOK MAINTENANCE RECORDS, NO LPT2 BLADES AFFECTED ON SECTION (E) OF THE AD. NO FURTHER ACTION REQUIRED AT THIS TIME.					Hrs	3,195.4				
						Enc	1,869				
TFE731-72-A5242 Rev 1	**Engine - Turbine Section - Suspect Second Stage Low Pressure Turbine (Lpt2) Blades On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 1	
72 ENG1						Mos	14-Jul-2014				
Complied With	IN ACCORDANCE WITH PARAGRAPH 1.E, REVIEWED ENGINE LOGBOOK MAINTENANCE RECORDS NO LPT2 BLADE(S) AFFECTED. NO FURTHER ACTION REQUIRED AT THIS TIME.					Hrs	3,221.4				
						Enc	1,883				
TFE731-72-A5242 Rev 1	**Engine - Turbine Section - Suspect Second Stage Low Pressure Turbine (Lpt2) Blades On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 1	
72 ENG2						Mos	14-Jul-2014				
Complied With	IN ACCORDANCE WITH PARAGRAPH 1.E, REVIEWED ENGINE LOGBOOK MAINTENANCE RECORDS NO LPT2 BLADE(S) AFFECTED. NO FURTHER ACTION REQUIRED AT THIS TIME.					Hrs	3,221.4				
						Enc	1,883				
TFE731-72-A5242 Rev 2	**Engine - Turbine Section - Suspect Second Stage Low Pressure Turbine (Lpt2) Blades On Tfe731-20 -40 -50 And -60 Series Engines**							T (A/R)		Category 1	
72 ENG1						Mos					
Eff: 29-Aug-2014						Hrs					
						Enc					
TFE731-72-A5242 Rev 2	**Engine - Turbine Section - Suspect Second Stage Low Pressure Turbine (Lpt2) Blades On Tfe731-20 -40 -50 And -60 Series Engines**							RE (-)		Category 1	
72 ENG2						Mos	14-Jul-2014				
Eff: 29-Aug-2014 Complied With	PARTIAL COMPLIANCES/B RETROACTIVE ACTION REQUIRED:					Hrs					
						Enc					
TFE731-72-A5246	**Engine - Turbine Section - Eddy Current Inspect Second Stage Low Pressure Turbine Rotor Assemblies with Suspect Blades Installed on Tfe731-20 -40 -50 And -60 Series Engines**							T (-)		Category 1	
72 ENG1						Mos					
Eff: 25-Jun-2014						Hrs					
						Enc					
TFE731-72-A5246	**Engine - Turbine Section - Eddy Current Inspect Second Stage Low Pressure Turbine Rotor Assemblies with Suspect Blades Installed on Tfe731-20 -40 -50 And -60 Series Engines**							T (-)		Category 1	
72 ENG2						Mos					
Eff: 25-Jun-2014						Hrs					
						Enc					
TFE731-72-A5246 Rev 1	**Engine - Turbine Section - Eddy Current Inspect Second Stage Low Pressure Turbine Rotor Assemblies with Suspect Blades Installed on TFE731-20, -40, -50 and -60 Series Engines**							T (A/R)		Alert, Cat.1-Safety	
72 ENG1						Mos					
Eff: 16-Feb-2021						Hrs					
						Enc					
TFE731-72-A5246 Rev 1	**Engine - Turbine Section - Eddy Current Inspect Second Stage Low Pressure Turbine Rotor Assemblies with Suspect Blades Installed on TFE731-20, -40, -50 and -60 Series Engines**							T (A/R)		Alert, Cat.1-Safety	
72 ENG2						Mos					
Eff: 16-Feb-2021						Hrs					
						Enc					
TFE731-A72-5121	**One Time Oil and Filter Resample**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	14-Dec-2020				
Eff: 21-Jan-1998 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-A72-5121	**One Time Oil and Filter Resample**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	14-Dec-2020				
Eff: 21-Jan-1998 Not Applicable						Hrs	4,610.5				
						Enc	2,822				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-5185	**Engine - Turbine Section - Inspect/Replace (If Required) Specific Identified High Pressure (Hp) Turbine Rotor Discs, Part No. 3060841-1**							RE (-)		Cat.1-Safety	
72 ENG1						Mos	14-Dec-2020				
Eff: 05-Jul-2006 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-A72-5185	**Engine - Turbine Section - Inspect/Replace (If Required) Specific Identified High Pressure (Hp) Turbine Rotor Discs, Part No. 3060841-1**							RE (-)		Cat.1-Safety	
72 ENG2						Mos	14-Dec-2020				
Eff: 05-Jul-2006 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
▼ 73 - ENGINE - FUEL AND CONTROL											
	Engine Fuel Flow Transducer							RE (O/C)			
73 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Fuel Flow Transducer							RE (O/C)			
73 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Fuel Pump Assembly							RE (O/C)			
73 ENG1		0				Mos	12-Feb-2008				
3060760-4	New	0				Hrs	0				
2577		0				Enc	0				
	Engine Fuel Pump Assembly							RE (O/C)			
73 ENG2		0				Mos	15-Feb-2008				
3060760-4	New	0				Hrs	0				
2581		0				Enc	0				
	Engine Fuel Temperature Bulb							RE (O/C)			
73 A/F	Left	0				Mos	13-Mar-2008				
MS28034-3	New	0				Hrs	0				
P9091		0				Ldg	0				
	Engine Fuel Temperature Bulb							RE (O/C)			
73 A/F	Right	0				Mos	13-Mar-2008				
MS28034-3	New	0				Hrs	0				
P9084		0				Ldg	0				
	Fuel Control Unit							RE (O/C)			
73 ENG1		0				Mos	12-Feb-2008				
3070800-37	New	0				Hrs	0				
19160		0				Enc	0				
	Fuel Control Unit							RE (O/C)			
73 ENG2						Mos	09-Oct-2017				
3070800-47						Hrs	3,975.9				
19831						Enc	2,348				
	Fuel Flow Divider/Drain Valve							RE (O/C)			
73 ENG1		0				Mos	12-Feb-2008				
394476-2	New	0				Hrs	0				
2746		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fuel Flow Divider/Drain Valve							RE (O/C)			
73 ENG2			0				Mos	15-Feb-2008				
394476-2		New	0				Hrs	0				
2734			0				Enc	0				
		Fuel Pressure Switch							RE (O/C)			
73 A/F		Left					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Fuel Pressure Switch							RE (O/C)			
73 A/F		Right					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Fuel Pump Pressure Differential Indicator							RE (O/C)			
73 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Fuel Pump Pressure Differential Indicator							RE (O/C)			
73 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Motive Flow Fuel Pump Assembly							RE (O/C)			
73 ENG1				1			Mos	08-Nov-2021				
3060759-1		Overhauled		0	4,803.7		Hrs	4,803.7				
1713				0	2,960		Enc	2,960				
(UPDATE NOTE: L/H Engine fuel pump shaft splines found worn. Fuel pump replaced IAW 73-21-02.)												
		Motive Flow Fuel Pump Assembly							RE (O/C)			
73 ENG2				2			Mos	08-Nov-2021				
3060759-1		Overhauled		0	4,803.7		Hrs	4,803.7				
1693				0	2,960		Enc	2,960				
(UPDATE NOTE: R/H Engine fuel pump shaft splines found worn. Fuel pump replaced IAW 73-21-02.)												
		Motive Flow Fuel Pump Shaft							RE (O/C)			
73 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Motive Flow Fuel Pump Shaft							RE (O/C)			
73 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		No. 1 Fuel Manifold Nozzle Assembly							RE (O/C)			
73 ENG1							Mos	11-Nov-2013				
3060540-2							Hrs	3,011.7				
98-01371-568							Enc	1,768				
		No. 1 Fuel Manifold Nozzle Assembly							RE (O/C)			
73 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 10 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	072923402408						Enc	1,768				
		No. 10 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 11 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	08-29234-03227						Enc	1,768				
		No. 11 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 12 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	010137102961						Enc	1,768				
		No. 12 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 2 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	042923401009						Enc	1,768				
		No. 2 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 3 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	042923401242						Enc	1,768				
		No. 3 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 4 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	032923400714						Enc	1,768				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 4 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	990137101820						Enc	1,768				
		No. 5 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 6 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	072923400737						Enc	1,768				
		No. 6 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 7 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	072923400739						Enc	1,768				
		No. 7 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 8 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	990137100116						Enc	1,768				
		No. 8 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 9 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG1						Mos	11-Nov-2013				
	3060540-2						Hrs	3,011.7				
	08-29234-03224						Enc	1,768				
		No. 9 Fuel Manifold Nozzle Assembly							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Pressure Limiter (PCD) Valve							RE (O/C)			
	73 ENG1		0				Mos	12-Feb-2008				
	3070685-11	New	0				Hrs	0				
	17620		0				Enc	0				
		Pressure Limiter (PCD) Valve							RE (O/C)			
	73 ENG2		0				Mos	15-Feb-2008				
	3070685-11	New	0				Hrs	0				
	17709		0				Enc	0				
		Relief Valve							RE (O/C)			
	73 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Relief Valve							RE (O/C)			
	73 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
2002-22-12		**Titeflex Hoses - High-Pressure and Medium-Pressure Hoses - Inspection/ Replacement**							RE (-)		Mandatory (Appliance AD)	
	73 ENG1						Mos	13-Mar-2008				
	Eff: 13-Dec-2002 Complied With	AT MANUFACTURE					Hrs	8.7				
							Enc	8				
2002-22-12		**Titeflex Hoses - High-Pressure and Medium-Pressure Hoses - Inspection/ Replacement**							RE (-)		Mandatory (Appliance AD)	
	73 ENG2						Mos					
	Eff: 13-Dec-2002						Hrs					
							Enc					
45-73-1		**Engine Fuel and Control - Replacement of Dual Fuel Flow Converter**							RE (-)		Recommended	
	73 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-73-1 Rev 1		**Engine Fuel and Control - Replacement of Dual Fuel Flow Converter**							RE (-)		Recommended	
	73 A/F						Mos	14-Dec-2020				
	Eff: 16-Aug-2002 Not Applicable						Hrs	4,610.5				
							Ldg	2,822				
45-73-2		**Engine Fuel and Control - Engine Fuel Flow Transducer Bracket Replacement**							T (-)		Recommended	
	73 A/F						Mos					
	Eff: 03-Oct-2016						Hrs					
	(AVG MAN HRS: 4.5)						Ldg					
45-73-2 Rev 1		**Engine Fuel and Control - Engine Fuel Flow Transducer Bracket Replacement**							RE (-)		Recommended	
	73 A/F						Mos	19-Nov-2022				
	Eff: 09-Jan-2017 Complied With						Hrs	5,136.6				
	(AVG MAN HRS: 4.5) (NOTE: NOTE: This modification must be performed in conjunction with Honeywell Service Bulletin No. 73-5145, to replace the existing 3061157-1 and 3061148-1 Fuel Tube assemblies, and must be performed on both engines.)						Ldg	3,167				
45-73-2 Rev 2		**Engine Fuel and Control - Engine Fuel Flow Transducer Bracket Replacement**							T (A/R)		Recommended	
	73 A/F						Mos					
	Eff: 18-Dec-2023						Hrs					
	(AVG MAN HRS: 4.5) (NOTE: NOTE: This modification must be performed in conjunction with Honeywell Service Bulletin No. 73-5145, to replace the existing 3061157-1 and 3061148-1 Fuel Tube assemblies and must be performed on both engines.)						Ldg					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-73-3	**Engine Fuel and Control - TFE731 Engine Fuel Control Assembly Reliability**							T (-)		Recommended	
73 A/F						Mos					
Eff: 22-Sep-2017						Hrs					
(AVG MAN HRS: 6)						Ldg					
45-73-3 Rev 1	**Engine Fuel and Control - TFE731 Engine Fuel Control Assembly Reliability**							T (A/R)		Recommended	
73 A/F						Mos					
Eff: 13-Aug-2018						Hrs					
(AVG MAN HRS: 6)						Ldg					
730120	**Replace Fuel Filter Element**							RE		EMM - Requirement	**≈24-Oct-2024**
73 ENG1	057130					Mos	09-Feb-2024				
						Hrs	5,253.5	600	-100/+50	(5,853.5)	578.7 Hrs (+50)
						Enc	3,756				
730120	**Replace Fuel Filter Element**							RE		EMM - Requirement	**≈24-Oct-2024**
73 ENG2	057130					Mos	09-Feb-2024				
						Hrs	5,253.5	600	-100/+50	(5,853.5)	578.7 Hrs (+50)
						Enc	3,756				
732120	**Inspect Motive Flow Fuel Pump Drive Spline**							RE		EMM - Requirement, EMM	**≈24-Oct-2024**
73 ENG1	057130					Mos	09-Feb-2024				
						Hrs	5,253.5	600	-100/+50	(5,853.5)	578.7 Hrs (+50)
						Enc	3,756				
732120	**Inspect Motive Flow Fuel Pump Drive Spline**							RE		EMM - Requirement, EMM	**≈24-Oct-2024**
73 ENG2	057130					Mos	09-Feb-2024				
						Hrs	5,253.5	600	-100/+50	(5,853.5)	578.7 Hrs (+50)
						Enc	3,756				
73-3074	**Engine Fuel And Control - Distribution - Rework Fuel Pump Filter Bypass Valve And Replace Mounting Flange Screws**							T (A/R)			
73 ENG1						Mos					
Eff: 22-Oct-1984						Hrs					
						Enc					
73-3074	**Engine Fuel And Control - Distribution - Rework Fuel Pump Filter Bypass Valve And Replace Mounting Flange Screws**							T (A/R)			
73 ENG2						Mos					
Eff: 22-Oct-1984						Hrs					
						Enc					
73-3099RWK	**Engine Fuel And Control - Distribution - Replace Fuel Pump Filter Bypass Valve Assembly**							T (A/R)			
73 ENG1						Mos					
Eff: 23-Feb-1990						Hrs					
						Enc					
73-3099RWK	**Engine Fuel And Control - Distribution - Replace Fuel Pump Filter Bypass Valve Assembly**							T (A/R)			
73 ENG2						Mos					
Eff: 23-Feb-1990						Hrs					
						Enc					
73-5109 Rev 1	**Engine Fuel And Control - Motive Flow Line Installation - Install Motive Flow Tube Mounting Bracket And Clamp (Inactive For Further Accomplishment. Refer To Sb Tfe731-73-5127 Or Sb Tfe731-73-5139)**							RE (-)			
73 ENG1						Mos					
						Hrs					
						Enc					
73-5109 Rev 1	**Engine Fuel And Control - Motive Flow Line Installation - Install Motive Flow Tube Mounting Bracket And Clamp (Inactive For Further Accomplishment. Refer To Sb Tfe731-73-5127 Or Sb Tfe731-73-5139)**							RE (-)			
73 ENG2						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
73-5109 Rev 2	**Engine Fuel And Control - Motive Flow Line Installation - Install Motive Flow Tube Mounting Bracket And Clamp (Inactive For Further Accomplishment. Refer To Sb Tfe731-73-5127 Or Sb Tfe731-73-5139)**						T (A/R)			
73 ENG1					Mos					
Eff: 31-Jul-2014					Hrs					
					Enc					
73-5109 Rev 2	**Engine Fuel And Control - Motive Flow Line Installation - Install Motive Flow Tube Mounting Bracket And Clamp (Inactive For Further Accomplishment. Refer To Sb Tfe731-73-5127 Or Sb Tfe731-73-5139)**						T (A/R)			
73 ENG2					Mos					
Eff: 31-Jul-2014					Hrs					
					Enc					
73-5114	**INSPECT FUEL PUMP TO FUEL HEATER/OIL COOLER TUBE ASSEMBLY**						T (A/R)		Recommended - Alert	
73 ENG1					Mos					
Eff: 30-Jul-1998					Hrs					
					Enc					
73-5114	**INSPECT FUEL PUMP TO FUEL HEATER/OIL COOLER TUBE ASSEMBLY**						T (A/R)		Recommended - Alert	
73 ENG2					Mos					
Eff: 30-Jul-1998					Hrs					
					Enc					
73-5115 Rev 1	**Engine Fuel And Control - Controlling - Rework Fuel Pump Using Differential Pressure Indicator, Pn 5911442-2**						RE (-)			
73 ENG1					Mos					
					Hrs					
					Enc					
73-5115 Rev 1	**Engine Fuel And Control - Controlling - Rework Fuel Pump Using Differential Pressure Indicator, Pn 5911442-2**						RE (-)			
73 ENG2					Mos					
					Hrs					
					Enc					
73-5115 Rev 2	**Engine Fuel And Control - Controlling - Rework Fuel Pump Using Differential Pressure Indicator, Pn 5911442-2**						RE (-)			
73 ENG1					Mos	29-Aug-2019				
Eff: 25-Jan-2008 Not Applicable					Hrs	4,516.2				
					Enc	2,733				
73-5115 Rev 2	**Engine Fuel And Control - Controlling - Rework Fuel Pump Using Differential Pressure Indicator, Pn 5911442-2**						RE (-)			
73 ENG2					Mos	29-Aug-2019				
Eff: 25-Jan-2008 Not Applicable					Hrs	4,516.2				
					Enc	2,733				
73-5124 Rev 1	**Engine Fuel And Control - Distribution - Install Clamps Between Fuel Pump To Fuel Heater/Oil Cooler Tube Assembly And The Fuel Heater/Oil Cooler To Fuel Pump Tube Assembly**						T (A/R)			
73 ENG1					Mos					
Eff: 08-Feb-2008					Hrs					
					Enc					
73-5124 Rev 1	**Engine Fuel And Control - Distribution - Install Clamps Between Fuel Pump To Fuel Heater/Oil Cooler Tube Assembly And The Fuel Heater/Oil Cooler To Fuel Pump Tube Assembly**						T (A/R)			
73 ENG2					Mos					
Eff: 08-Feb-2008					Hrs					
					Enc					
73-5127 Rev 1	**Engine Fuel And Control - Distribution - Replace Fuel Pump To Motive Flow Pump Tube Assembly, Pn 3061192-1/3061201-1 With P/N 3061314-2**						RE (-)			
73 ENG1					Mos	11-Nov-2013				
Eff: 10-Nov-2005 Complied With					Hrs					
					Enc					
73-5127 Rev 1	**Engine Fuel And Control - Distribution - Replace Fuel Pump To Motive Flow Pump Tube Assembly, Pn 3061192-1/3061201-1 With P/N 3061314-2**						RE (-)			
73 ENG2					Mos	11-Nov-2013				
Eff: 10-Nov-2005 Complied With PREVIOUSLY					Hrs	3,011.7				
					Enc	1,768				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
73-5128 Rev 1	**Engine Fuel & Control - Distribution - Install Primary Fuel Tube Assembly, Pn 3061203-1 And Secondary Fuel Tube Assembly, Pn 3061204-1**							RE (-)			
73 ENG1						Mos	11-Nov-2013				
Eff: 12-Dec-2007 Complied With						Hrs					
						Enc					
73-5128 Rev 1	**Engine Fuel & Control - Distribution - Install Primary Fuel Tube Assembly, Pn 3061203-1 And Secondary Fuel Tube Assembly, Pn 3061204-1**							RE (-)			
73 ENG2						Mos	11-Nov-2013				
Eff: 12-Dec-2007 Complied With	PREVIOUSLY					Hrs	3,011.7				
						Enc	1,768				
73-5139	**Engine Fuel And Control - Controlling - Install Improved Fuel Pump To Motive Flow Pump Tube Assembly Pn 70060060-1**							T (A/R)			
73 ENG1						Mos					
Eff: 31-May-2013						Hrs					
						Enc					
73-5139	**Engine Fuel And Control - Controlling - Install Improved Fuel Pump To Motive Flow Pump Tube Assembly Pn 70060060-1**							T (A/R)			
73 ENG2						Mos					
Eff: 31-May-2013						Hrs					
						Enc					
73-5140	**Engine Fuel And Control - Controlling - Install Motive Flow Fuel Pump Pn 70060003-1**							T (A/R)			
73 ENG1						Mos					
Eff: 31-May-2013						Hrs					
						Enc					
73-5140	**Engine Fuel And Control - Controlling - Install Motive Flow Fuel Pump Pn 70060003-1**							T (A/R)			
73 ENG2						Mos					
Eff: 31-May-2013						Hrs					
						Enc					
73-SB05 Rev 1	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**							RE (-)			
73 ENG1						Mos					
						Hrs					
						Enc					
73-SB05 Rev 1	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**							RE (-)			
73 ENG2						Mos					
						Hrs					
						Enc					
73-SB05 Rev 2	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**							T (A/R)			
73 ENG1						Mos					
Eff: 06-Feb-2004						Hrs					
						Enc					
73-SB05 Rev 2	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**							T (A/R)			
73 ENG2						Mos					
Eff: 06-Feb-2004						Hrs					
						Enc					
73-SB08	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG1						Mos					
Eff: 22-Dec-1999						Hrs					
						Enc					
73-SB08	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG2						Mos					
Eff: 22-Dec-1999						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
73-SB08 Rev 1	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG1						Mos					
						Hrs					
						Enc					
73-SB08 Rev 1	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG2						Mos					
						Hrs					
						Enc					
73-SB08 Rev 2	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							T (A/R)			
73 ENG1						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
73-SB08 Rev 2	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							T (A/R)			
73 ENG2						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
73-SB13	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							RE (-)			
73 ENG1						Mos					
Eff: 14-Mar-2012						Hrs					
						Enc					
73-SB13	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							RE (-)			
73 ENG2						Mos					
Eff: 14-Mar-2012						Hrs					
						Enc					
73-SB13 Rev 1	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							T (A/R)			
73 ENG1						Mos					
Eff: 18-Sep-2012						Hrs					
						Enc					
73-SB13 Rev 1	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							RE (-)			
73 ENG2						Mos	09-Oct-2017				
Eff: 18-Sep-2012 Complied With						Hrs	3,975.9				
						Enc	2,348				
75-73-02	**Engine Fuel and Control - TFE731 Engine Fuel Control Assembly Reliability**							RE (-)		Recommended	
73 A/F						Mos					
Eff: 22-Sep-2017						Hrs					
(AVG MAN HRS: 6)						Ldg					
75-73-02 Rev 1	**Engine Fuel and Control - TFE731 Engine Fuel Control Assembly Reliability**							RE (-)		Recommended	
73 A/F						Mos					
Eff: 06-Nov-2017						Hrs					
(AVG MAN HRS: 6)						Ldg					
75-73-02 Rev 2	**Engine Fuel and Control - TFE731 Engine Fuel Control Assembly Reliability**							RE (-)		Recommended	
73 A/F						Mos					
Eff: 13-Aug-2018						Hrs					
(AVG MAN HRS: 6)						Ldg					
98-17-01	**Flex Fuel Tube**							RE (-)		Mandatory	
73 ENG1						Mos					
						Hrs					
						Enc					
98-17-01	**Flex Fuel Tube**							RE (-)		Mandatory	
73 ENG2						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
98-17-01 R1	**Flex Fuel Tube**							T (A/R)		Mandatory	
73 ENG1						Mos					
Eff: 19-May-1999						Hrs					
						Enc					
98-17-01 R1	**Flex Fuel Tube**							T (A/R)		Mandatory	
73 ENG2						Mos					
Eff: 19-May-1999						Hrs					
						Enc					
A73-5133	**Engine Fuel And Control - Controlling - Replace Inlet Filter Screen Assembly, Part No. 765310, On Specific Identified Motive Flow Fuel Pumps**							RE (-)			
73 ENG1						Mos	14-Dec-2020				
Eff: 16-Aug-2004 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
A73-5133	**Engine Fuel And Control - Controlling - Replace Inlet Filter Screen Assembly, Part No. 765310, On Specific Identified Motive Flow Fuel Pumps**							RE (-)			
73 ENG2						Mos	14-Dec-2020				
Eff: 16-Aug-2004 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
AW 73-004	**Honeywell Fuel Pump**							RE (-)		Advisory Wire	
73 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
TFE731-73-5107	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, Pn 3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 29-Jun-1999						Hrs					
						Enc					
TFE731-73-5107	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, Pn 3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 29-Jun-1999						Hrs					
						Enc					
TFE731-73-5107 Rev 1	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, Pn 3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	29-Aug-2019				
Eff: 16-Nov-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5107 Rev 1	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, Pn 3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	29-Aug-2019				
Eff: 16-Nov-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5109	**Engine Fuel and Control - Motive Flow Line Installation - Install Motive Flow Tube Mounting Bracket and Clamp (Inactive for Further Accomplishment. Refer to SB TFE731-73-5127 or SB TFE731-73-5139)**							RE (-)		Category 3	
73 ENG1						Mos					
Eff: 19-Sep-1997						Hrs					
						Enc					
TFE731-73-5109	**Engine Fuel and Control - Motive Flow Line Installation - Install Motive Flow Tube Mounting Bracket and Clamp (Inactive for Further Accomplishment. Refer to SB TFE731-73-5127 or SB TFE731-73-5139)**							RE (-)		Category 3	
73 ENG2						Mos					
Eff: 19-Sep-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-5115	**Engine Fuel and Control - Controlling - Rework Fuel Pump Using Differential Pressure Indicator, Part Number 5911442-2**							RE (-)		Category 3	
73 ENG1						Mos					
Eff: 12-Oct-1998						Hrs					
						Enc					
TFE731-73-5115	**Engine Fuel and Control - Controlling - Rework Fuel Pump Using Differential Pressure Indicator, Part Number 5911442-2**							RE (-)		Category 3	
73 ENG2						Mos					
Eff: 12-Oct-1998						Hrs					
						Enc					
TFE731-73-5118	**Engine Fuel & Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motors**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 12-Nov-1998						Hrs					
						Enc					
TFE731-73-5118	**Engine Fuel & Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motors**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 12-Nov-1998						Hrs					
						Enc					
TFE731-73-5118 Rev 1	**Engine Fuel & Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motors**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
						Hrs					
						Enc					
TFE731-73-5118 Rev 1	**Engine Fuel & Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motors**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
						Hrs					
						Enc					
TFE731-73-5118 Rev 2	**Engine Fuel & Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motors**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
						Hrs					
						Enc					
TFE731-73-5118 Rev 2	**Engine Fuel & Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motors**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
						Hrs					
						Enc					
TFE731-73-5118 Rev 3	**Engine Fuel & Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motors**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	29-Aug-2019				
Eff: 11-Jun-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5118 Rev 3	**Engine Fuel & Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motors**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	29-Aug-2019				
Eff: 11-Jun-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5120	**Engine Fuel And Control - Distribution - Install Fuel Manifold Flexible Hose Assemblies (Primary), Pn 3061294-1**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	12-Feb-2008				
Eff: 11-Feb-2000 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-73-5120	**Engine Fuel And Control - Distribution - Install Fuel Manifold Flexible Hose Assemblies (Primary), Pn 3061294-1**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	15-Feb-2008				
Eff: 11-Feb-2000 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-5121	**Engine Fuel And Control - Distribution - Rework/Replace Fuel Nozzle Assembly, PN 3060540-3, With PN 3060540-2**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	12-Feb-2008				
Eff: 17-Dec-1999 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-73-5121	**Engine Fuel And Control - Distribution - Rework/Replace Fuel Nozzle Assembly, PN 3060540-3, With PN 3060540-2**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	15-Feb-2008				
Eff: 17-Dec-1999 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-73-5121 Rev 1	**Engine Fuel And Control - Distribution - Rework/Replace Fuel Nozzle Assembly, PN 3060540-3, With PN 3060540-2**							T (A/R)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 22-Feb-2008						Hrs					
						Enc					
TFE731-73-5121 Rev 1	**Engine Fuel And Control - Distribution - Rework/Replace Fuel Nozzle Assembly, PN 3060540-3, With PN 3060540-2**							T (A/R)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 22-Feb-2008						Hrs					
						Enc					
TFE731-73-5124	**Engine Fuel and Control - Distribution - Install Clamps Between Fuel Heater Pump to Fuel Heater/Oil Cooler Tube Assembly and the Fuel Heater/Oil Cooler to Fuel Pump Tube Assembly**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 25-May-2001						Hrs					
						Enc					
TFE731-73-5124	**Engine Fuel and Control - Distribution - Install Clamps Between Fuel Heater Pump to Fuel Heater/Oil Cooler Tube Assembly and the Fuel Heater/Oil Cooler to Fuel Pump Tube Assembly**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 25-May-2001						Hrs					
						Enc					
TFE731-73-5125	**Engine Fuel And Control - Controlling - Replacement Of Relief Valve, Pn 5909242, On Specific Identified Fuel Pumps**							RE (-)		Cat.3-Product Improvement	
73 ENG1						Mos	12-Feb-2008				
Eff: 03-Jul-2001 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-73-5125	**Engine Fuel And Control - Controlling - Replacement Of Relief Valve, Pn 5909242, On Specific Identified Fuel Pumps**							RE (-)		Cat.3-Product Improvement	
73 ENG2						Mos	15-Feb-2008				
Eff: 03-Jul-2001 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-73-5125 Rev 1	**Engine Fuel And Control - Controlling - Replacement Of Relief Valve, Pn 5909242, On Specific Identified Fuel Pumps**							T (A/R)		Cat.3-Product Improvement	
73 ENG1						Mos					
Eff: 31-Jan-2008						Hrs					
						Enc					
TFE731-73-5125 Rev 1	**Engine Fuel And Control - Controlling - Replacement Of Relief Valve, Pn 5909242, On Specific Identified Fuel Pumps**							T (A/R)		Cat.3-Product Improvement	
73 ENG2						Mos					
Eff: 31-Jan-2008						Hrs					
						Enc					
TFE731-73-5127	**Engine Fuel and Control - Distribution - Replace Fuel Pump to Motive Flow Pump Tube Assembly, P/N 3061192-1/3061201-1 with P/N 3061314-2**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	12-Feb-2008				
Eff: 06-Feb-2002 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-5127	**Engine Fuel and Control - Distribution - Replace Fuel Pump to Motive Flow Pump Tube Assembly, P/N 3061192-1/3061201-1 with P/N 3061314-2**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	15-Feb-2008				
Eff: 06-Feb-2002 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-73-5128	**Engine Fuel and Control - Distribution - Install Primary Fuel Tube Assembly, Part Number 3061203-1, and Secondary Fuel Tube Assembly, Part Number 3061204-1**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 21-Dec-2001						Hrs					
						Enc					
TFE731-73-5128	**Engine Fuel and Control - Distribution - Install Primary Fuel Tube Assembly, Part Number 3061203-1, and Secondary Fuel Tube Assembly, Part Number 3061204-1**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 21-Dec-2001						Hrs					
						Enc					
TFE731-73-5130	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	11-Nov-2013				
Eff: 07-Oct-2002 Not Applicable						Hrs	3,011.7				
						Enc	1,768				
TFE731-73-5130	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	11-Nov-2013				
Eff: 07-Oct-2002 Not Applicable						Hrs	3,011.7				
						Enc	1,768				
TFE731-73-5130 Rev 1	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5130 Rev 1	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	29-Aug-2019				
Eff: 18-Jun-2007 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5131	**Engine Fuel And Control - Controlling - Install Fuel Pump That Incorporates Differential Pressure Indicator, Part No. 5913809-2**							RE (-)		Cat.3-Product Improvement	
73 ENG1						Mos	12-Feb-2008				
Eff: 28-May-2004 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-73-5131	**Engine Fuel And Control - Controlling - Install Fuel Pump That Incorporates Differential Pressure Indicator, Part No. 5913809-2**							RE (-)		Cat.3-Product Improvement	
73 ENG2						Mos	15-Feb-2008				
Eff: 28-May-2004 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-73-5134	**Engine Fuel and Control - Distribution - Install Pcd Air toFuel Control Unit (P3) Tube Assembly, P/N 3061068-3**							RE (-)		Category 2	
73 ENG1						Mos	12-Feb-2008				
Eff: 26-Apr-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-5134	**Engine Fuel and Control - Distribution - Install Pcd Air toFuel Control Unit (P3) Tube Assembly, P/N 3061068-3**							RE (-)		Category 2	
73 ENG2						Mos	15-Feb-2008				
Eff: 26-Apr-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-73-5135	**Engine Fuel And Control - Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	14-Dec-2020				
Eff: 29-Mar-2005 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-73-5135	**Engine Fuel And Control - Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	14-Dec-2020				
Eff: 29-Mar-2005 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-73-5136	**Engine Fuel And Control - Controlling - Replace Main Turbine Engine Fuel Pump Fuel Filter Element With Fuel Filter Element, Part No. 897830-1**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	11-Nov-2013				
Eff: 12-Sep-2005 Complied With						Hrs					
						Enc					
TFE731-73-5136	**Engine Fuel And Control - Controlling - Replace Main Turbine Engine Fuel Pump Fuel Filter Element With Fuel Filter Element, Part No. 897830-1**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	11-Nov-2013				
Eff: 12-Sep-2005 Complied With	PREVIOUSLY					Hrs	3,011.7				
						Enc	1,768				
TFE731-73-5137	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Pumps (Fuel Pump), Part No. 3060760-4**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	29-Aug-2019				
Eff: 15-Mar-2006 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5137	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Pumps (Fuel Pump), Part No. 3060760-4**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	11-Nov-2013				
Eff: 15-Mar-2006 Not Applicable						Hrs	3,011.7				
						Enc	1,768				
TFE731-73-5138	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	29-Aug-2019				
Eff: 21-Mar-2006 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5138	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	29-Aug-2019				
Eff: 21-Mar-2006 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-73-5141	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly Pn 3070800-47 And -49**							RE (-)		Category 3	
73 ENG1						Mos					
Eff: 28-Mar-2012						Hrs					
						Enc					
TFE731-73-5141	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly Pn 3070800-47 And -49**							RE (-)		Category 3	
73 ENG2						Mos					
Eff: 28-Mar-2012						Hrs					
						Enc					
TFE731-73-5141 Rev 1	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly Pn 3070800-47 And -49**							T (A/R)		Category 3	
73 ENG1						Mos					
Eff: 21-Jun-2012						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-5141 Rev 1	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly Pn 3070800-47 And -49**							T (A/R)		Category 3	
73 ENG2						Mos					
Eff: 21-Jun-2012						Hrs					
						Enc					
TFE731-73-5145	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	05-Oct-2017				
Eff: 05-Oct-2016 Complied With						Hrs	3,975.9				
(AVG MAN HRS: 2)						Enc	2,348				
TFE731-73-5145	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	05-Oct-2017				
Eff: 05-Oct-2016 Complied With						Hrs	3,975.9				
(AVG MAN HRS: 2)						Enc	2,348				
TFE731-73-5145 Paragraph 1.E.(2)	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines - Recurring Inspection**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	05-Oct-2017				
Eff: 05-Oct-2016 Complied With	S/B THEN INSTALLATION OF FUEL LINE {P/N: 70060172-1} HOSE ASSY { P/N: 3061288-1} AND SERVICE KIT {P/N: 4573140001-8013					Hrs	3,975.9				
(AVG MAN HRS: 2)						Enc	2,348				
TFE731-73-5145 Paragraph 1.E.(2)	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines - Recurring Inspection**							RE (-)		Cat.1-Safety	
73 ENG2						Mos					
Eff: 05-Oct-2016						Hrs					
(AVG MAN HRS: 2)						Enc					
TFE731-73-5145 Paragraph 1.E.(3)	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines - Corrective Action**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	05-Oct-2017				
Eff: 05-Oct-2016 Complied With						Hrs	3,975.9				
(AVG MAN HRS: 2)						Enc	2,348				
TFE731-73-5145 Paragraph 1.E.(3)	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines - Corrective Action**							RE (-)		Cat.1-Safety	
73 ENG2						Mos					
Eff: 05-Oct-2016						Hrs					
(AVG MAN HRS: 2)						Enc					
TFE731-73-5145 R1	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	10-Oct-2017				
Eff: 21-Nov-2017 Complied With						Hrs					
(AVG MAN HRS: 2)						Enc					
TFE731-73-5145 R1	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	10-Oct-2017				
Eff: 21-Nov-2017 Complied With						Hrs					
(AVG MAN HRS: 2)						Enc					
TFE731-73-5145 R1 Paragraph 1.E.(2)	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines - Recurring Inspection**							RE (-)		Cat.1-Safety	
73 ENG1						Mos					
Eff: 21-Nov-2017						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-5145 R1 Paragraph 1.E.(2)	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines - Recurring Inspection**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	05-Oct-2017				
Eff: 21-Nov-2017 Complied With						Hrs	3,975.9				
						Enc	2,348				
TFE731-73-5145 R1 Paragraph 1.E.(3)	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines - Corrective Action**							RE (-)		Cat.1-Safety	
73 ENG1						Mos					
Eff: 21-Nov-2017						Hrs					
						Enc					
TFE731-73-5145 R1 Paragraph 1.E.(3)	**Engine Fuel and Controlling - Distribution - Replacement of Fuel Flow Meter Tube Assemblies, PN 3061157-1 and PN 3061148-1, with Improved Fuel Hose Assembly, PN 3061288-1, and Fuel Tube Assembly, PN 70060172-1, on TFE731-20, -40 Model Engines - Corrective Action**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	05-Oct-2017				
Eff: 21-Nov-2017 Complied With						Hrs	3,975.9				
						Enc	2,348				
TFE731-73-5146	**Install Improved Fuel Control Assembly (FCA), PN 3070800-28, -30, -37, -47, -69, and -79, with Improved Solenoid Attachment Screws on TFE731-20, -40, -50, and -60 Engine Models**							T (-)		Cat.2-Reliability	**≈07-Dec-2024**
73 ENG1						Mos					
						Hrs				[6,000]	725.2 Hrs
(AVG MAN HRS: 6) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished when the FCA is replaced for any cause (when FCA is no longer serviceable) or at the next MPI or CZI, whichever occurs first. APPLICABILITY: Applies to Fuel Control Assembly P/N 3070800-28, -30, -37, -39, -47 and -49 with S/N's prior to S/N 20681.)						Enc					
TFE731-73-5146	**Install Improved Fuel Control Assembly (FCA), PN 3070800-28, -30, -37, -47, -69, and -79, with Improved Solenoid Attachment Screws on TFE731-20, -40, -50, and -60 Engine Models**							T (-)		Cat.2-Reliability	**≈07-Dec-2024**
73 ENG2						Mos					
						Hrs				[6,000]	725.2 Hrs
(AVG MAN HRS: 6) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished when the FCA is replaced for any cause (when FCA is no longer serviceable) or at the next MPI or CZI, whichever occurs first. APPLICABILITY: Applies to Fuel Control Assembly P/N 3070800-28, -30, -37, -39, -47 and -49 with S/N's prior to S/N 20681.)						Enc					
TFE731-73-5146 R1	**Install Improved Fuel Control Assembly (FCA), PN 3070800-28, -30, -37, -47, -69, and -79, with Improved Solenoid Attachment Screws on TFE731-20, -40, -50, and -60 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 24-Jan-2018						Hrs					
						Enc					
TFE731-73-5146 R1	**Install Improved Fuel Control Assembly (FCA), PN 3070800-28, -30, -37, -47, -69, and -79, with Improved Solenoid Attachment Screws on TFE731-20, -40, -50, and -60 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 24-Jan-2018						Hrs					
						Enc					
TFE731-73-5151	**Engine Fuel and Control - Distribution - Inspect Primary Fuel Line Manifold and No. 6 Bearing Oil Scavenge Aft Tube Assembly and Add Clamping on Engine Models TFE731-20, -40, -50, -60**							T (A/R)		Cat. 2 - Recommended	
73 ENG1						Mos					
Eff: 18-Apr-2019						Hrs					
(AVG MAN HRS: 3) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at next engine removal.)						Enc					
TFE731-73-5151	**Engine Fuel and Control - Distribution - Inspect Primary Fuel Line Manifold and No. 6 Bearing Oil Scavenge Aft Tube Assembly and Add Clamping on Engine Models TFE731-20, -40, -50, -60**							T (A/R)		Cat. 2 - Recommended	
73 ENG2						Mos					
Eff: 18-Apr-2019						Hrs					
(AVG MAN HRS: 3) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at next engine removal.)						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-5153 Rev 1	**Engine Fuel and Control - Distribution - Install Improved Fuel Pump to Fuel Heater/Oil Cooler Tube Assembly, PN 3061249-2, on Engine Model TFE731-60**							T (A/R)		Cat.3-Product Improvement	
73 ENG1						Mos					
Eff: 23-Mar-2020						Hrs					
	(AVG MAN HRS: 1) (NOTE: COMPLIANCE: For the engines installed in aircraft engine Positions 1 and 3, Honeywell recommends that this service bulletin be accomplished at the next routine periodic inspection. For engines installed in aircraft engine Position 2, Honeywell recommends that this service bulletin be accomplished when the fuel pump to fuel heater/oil cooler tube assembly, PN 3061249-1, is no longer serviceable.)					Enc					
TFE731-73-5153 Rev 1	**Engine Fuel and Control - Distribution - Install Improved Fuel Pump to Fuel Heater/Oil Cooler Tube Assembly, PN 3061249-2, on Engine Model TFE731-60**							T (A/R)		Cat.3-Product Improvement	
73 ENG2						Mos					
Eff: 23-Mar-2020						Hrs					
	(AVG MAN HRS: 1) (NOTE: COMPLIANCE: For the engines installed in aircraft engine Positions 1 and 3, Honeywell recommends that this service bulletin be accomplished at the next routine periodic inspection. For engines installed in aircraft engine Position 2, Honeywell recommends that this service bulletin be accomplished when the fuel pump to fuel heater/oil cooler tube assembly, PN 3061249-1, is no longer serviceable.)					Enc					
TFE731-73-5154	**Engine Fuel and Control - Distribution - Install Primary Fuel Line Manifold, PN 3060928-5 Or -6, as Applicable, on Engine Models TFE731-20, -40, -50, -60**							RE (-)		Cat.3-Product Improvement	
73 ENG1						Mos					
Eff: 18-Apr-2019						Hrs					
(AVG MAN HRS: 4)						Enc					
TFE731-73-5154	**Engine Fuel and Control - Distribution - Install Primary Fuel Line Manifold, PN 3060928-5 Or -6, as Applicable, on Engine Models TFE731-20, -40, -50, -60**							RE (-)		Cat.3-Product Improvement	
73 ENG2						Mos					
Eff: 18-Apr-2019						Hrs					
(AVG MAN HRS: 4)						Enc					
TFE731-A73-5110	**Inspection Of Secondary Fuel Line Manifold For Chaffing/Cutting**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	14-Dec-2020				
Eff: 16-Mar-1998 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
TFE731-A73-5110	**Inspection Of Secondary Fuel Line Manifold For Chaffing/Cutting**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	14-Dec-2020				
Eff: 16-Mar-1998 Not Applicable						Hrs	4,610.5				
						Enc	2,822				
▼ 74 - IGNITION											
	5 O'Clock Igniter (#1 Position) Plug							RE (O/C)			
74 ENG1						Mos	11-Nov-2013				
3074541-4						Hrs	3,011.7				
Unknown						Enc	1,768				
	5 O'Clock Igniter (#1 Position) Plug							RE (O/C)			
74 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	7 O'Clock Igniter (#2 Position) Plug							RE (O/C)			
74 ENG1						Mos	11-Nov-2013				
3074541-4						Hrs	3,011.7				
Unknown						Enc	1,768				
	7 O'Clock Igniter (#2 Position) Plug							RE (O/C)			
74 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Ignition Exciter							RE (O/C)			
	74 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Ignition Exciter							RE (O/C)			
	74 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Ignition Unit							RE (O/C)			
	74 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Ignition Unit							RE (O/C)			
	74 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		K22 Relay							RE (O/C)			
	74 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		K61 Relay							RE (O/C)			
	74 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		No. 1 Ignition Lead							RE (O/C)			
	74 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 1 Ignition Lead							RE (O/C)			
	74 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 2 Ignition Lead							RE (O/C)			
	74 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 2 Ignition Lead							RE (O/C)			
	74 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Tail Cone Relay (P13) Panel							RE (O/C)			
	74 A/F						Mos	28-Dec-2011				
	Unknown						Hrs	2,284.1				
	Unknown						Ldg	1,365				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-74-1	**Ignition - Conversion of AlliedSignal Engine Configuration**							RE (-)		Optional	
74 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-74-1 Rev 1	**Ignition - Conversion of AlliedSignal Engine Configuration**							RE (-)		Optional	
74 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-74-1 Rev 2	**Ignition - Conversion of AlliedSignal Engine Configuration**							RE (-)		Optional	
74 A/F						Mos	29-Aug-2019				
Eff: 16-Feb-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
740140	**Remove And Inspect 5 O'Clock Igniter Plug And Lead**							RE		EMM - Requirement, EMM	**≈05-Feb-2025**
74 ENG1	057160					Mos	20-May-2020				
						Hrs	4,593.2	1,600	-100/+50	(6,193.2)	918.4 Hrs (+50)
						Enc	2,809				
740140	**Remove And Inspect 5 O'Clock Igniter Plug And Lead**							RE		EMM - Requirement, EMM	**≈05-Feb-2025**
74 ENG2	057160					Mos	20-May-2020				
						Hrs	4,593.2	1,600	-100/+50	(6,193.2)	918.4 Hrs (+50)
						Enc	2,809				
740160	**Remove And Inspect 7 O'Clock Igniter Plug And Lead**							RE		EMM - Requirement, EMM	**≈05-Feb-2025**
74 ENG1	057160					Mos	20-May-2020				
						Hrs	4,593.2	1,600	-100/+50	(6,193.2)	918.4 Hrs (+50)
						Enc	2,809				
740160	**Remove And Inspect 7 O'Clock Igniter Plug And Lead**							RE		EMM - Requirement, EMM	**≈05-Feb-2025**
74 ENG2	057160					Mos	20-May-2020				
						Hrs	4,593.2	1,600	-100/+50	(6,193.2)	918.4 Hrs (+50)
						Enc	2,809				
▼ 75 - BLEED AIR											
	P2/T2 Probe							RE (O/C)			
75 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	P2/T2 Probe							RE (O/C)			
75 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
TFE731-75-5101	**Air - Distribution - Install Low Pressure (Lp) Bleed Duct, Pn 3060770-2 Or 3060770-3, And Outer Flange, Pn 3071244-2 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
75 ENG1						Mos	12-Feb-2008				
Eff: 12-Nov-2003 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-75-5101	**Air - Distribution - Install Low Pressure (Lp) Bleed Duct, Pn 3060770-2 Or 3060770-3, And Outer Flange, Pn 3071244-2 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
75 ENG2						Mos	15-Feb-2008				
Eff: 12-Nov-2003 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 76 - ENGINE CONTROLS											
	Aft Throttle Cable							RE (O/C)			
76 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Aft Throttle Cable							RE (O/C)			
76 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine (DEEC) Computer							RE (O/C)			
76 ENG1		0				Mos	12-Feb-2008				
2118882-1008	New	0				Hrs	0				
47-AW0359		0				Enc	0				
Brand F:760110											
	Engine (DEEC) Computer							RE (O/C)			
76 ENG2		0				Mos	15-Feb-2008				
2118882-1008	New	0				Hrs	0				
127-AW0429		0				Enc	0				
Brand F:760110											
	Forward Throttle Cable							RE (O/C)			
76 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Forward Throttle Cable							RE (O/C)			
76 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Solenoid Controller Valve							RE (O/C)			
76 ENG1		0				Mos	12-Feb-2008				
109696-6-1	New	0				Hrs	0				
13020		0				Enc	0				
	Solenoid Controller Valve							RE (O/C)			
76 ENG2		0				Mos	15-Feb-2008				
109696-6-1	New	0				Hrs	0				
13019		0				Enc	0				
	Surge Bleed Valve							RE (O/C)			
76 ENG1		0				Mos	12-Feb-2008				
978812-7-1	New	0				Hrs	0				
13523		0				Enc	0				
	Surge Bleed Valve							RE (O/C)			
76 ENG2		0				Mos	15-Feb-2008				
978812-7-1	New	0				Hrs	0				
13521		0				Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Throttle Control Module							RE (O/C)			
	76 A/F					1	Mos	18-Sep-2017				
	69011-17						Hrs	3,947.9				
	1042182						Ldg	2,334				
45-76-1		**Engine Controls - DEEC Software Upgrade**							RE (-)		Optional	
	76 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-76-1 Rev 1		**Engine Controls - DEEC Software Upgrade**							RE (-)		Optional	
	76 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-76-1 Rev 2		**Engine Controls - DEEC Software Upgrade**							RE (-)		Optional	
	76 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-76-1 Rev 3		**Engine Controls - DEEC Software Upgrade**							RE (-)		Optional	
	76 A/F						Mos	29-Aug-2019				
	Eff: 01-Jul-1999 Not Applicable						Hrs	4,516.2				
							Ldg	2,733				
45-76-2		**Engine Controls - Thrust Reverser Max Thrust Credit**							RE (-)		Optional	
	76 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-76-2 Rev 1		**Engine Controls - Thrust Reverser Max Thrust Credit**							RE (-)		Optional	
	76 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-76-2 Rev 2		**Engine Controls - Thrust Reverser Max Thrust Credit**							RE (-)		Optional	
	76 A/F						Mos	29-Aug-2019				
	Eff: 07-Dec-2001 Not Applicable						Hrs	4,516.2				
							Ldg	2,733				
45-76-3		**Inspection of the Throttle Cable Housing Assemblies for Safety Wire**							RE (-)		Recommended	
	76 A/F						Mos	13-Mar-2008				
	Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
							Ldg	8				
45-76-3 Rev 1		**Inspection of the Throttle Cable Housing Assemblies for Safety Wire**							RE (-)		Recommended	
	76 A/F						Mos	14-Dec-2020				
	Eff: 17-Dec-2007 Not Applicable						Hrs	4,610.5				
							Ldg	2,822				
761330		**Download Engine (DEEC) Computer ECTM**							RE		Custom Task	
	76 ENG1						Days	27-Mar-2024	30		26-Apr-2024	OVD
	2118882-1008						Hrs	5,263.4				
	47-AW0359						Enc	3,766	50		3,816	545 Enc
	(AVG MAN HRS: 0.5)											
761330		**Download Engine (DEEC) Computer ECTM**							RE		Custom Task	
	76 ENG2						Days	27-Mar-2024	30		26-Apr-2024	OVD
	2118882-1008						Hrs	5,263.4				
	127-AW0429						Enc	3,766	50		3,816	545 Enc
	(AVG MAN HRS: 0.5)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
76-5103	**Engine Controls - Power Control - Inatall Digital Electronic Engine Control (Deec), Pn 2118882-1004**							T (A/R)			
76 ENG1						Mos					
Eff: 22-Aug-1997						Hrs					
						Enc					
76-5103	**Engine Controls - Power Control - Inatall Digital Electronic Engine Control (Deec), Pn 2118882-1004**							T (A/R)			
76 ENG2						Mos					
Eff: 22-Aug-1997						Hrs					
						Enc					
76-5114 Rev 1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (Deec), Pn 2118882-1007**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
76-5114 Rev 1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (Deec), Pn 2118882-1007**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
76-5114 Rev 2	**Engine Controls - Power Control - Install Digital Electronic Engine Control (Deec), Pn 2118882-1007**							RE (-)			
76 ENG1						Mos	12-Feb-2008				
Eff: 26-Jul-2002 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
76-5114 Rev 2	**Engine Controls - Power Control - Install Digital Electronic Engine Control (Deec), Pn 2118882-1007**							RE (-)			
76 ENG2						Mos	15-Feb-2008				
Eff: 26-Jul-2002 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
76-5118	**Engine Controls - Power Control - Rework Digital Electronic Engine Control (Deec), Part No 2118882-1006 To Part No 2118882-1005 Matt Williams To Do All Distribution**							T (A/R)			
76 ENG1						Mos	12-Feb-2008				
Eff: 30-May-2002						Hrs	0				
						Enc	0				
76-5118	**Engine Controls - Power Control - Rework Digital Electronic Engine Control (Deec), Part No 2118882-1006 To Part No 2118882-1005 Matt Williams To Do All Distribution**							T (A/R)			
76 ENG2						Mos	15-Feb-2008				
Eff: 30-May-2002						Hrs	0				
						Enc	0				
AW 76-001	**TFE731 Engine Uncommanded Accelerations**							RE (-)		Advisory Wire	
76 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 76-004	**Learjet 40 & 45 Throttle Cable Improvement**							RE (-)		Advisory Wire	
76 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
TFE731-76-1035 Rev 1	**Engine Controls - Solenoid Controller Valve Assembly - Rework Or Replace Solenoid Controller Valve Assembly, Pn 109696-5-1 To/With Pn 109696-6-1**							RE (-)			
76 ENG1						Mos	12-Feb-2008				
Eff: 31-Mar-2000 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-1035 Rev 1	**Engine Controls - Solenoid Controller Valve Assembly - Rework Or Replace Solenoid Controller Valve Assembly, Pn 109696-5-1 To/With Pn 109696-6-1**							RE (-)			
76 ENG2						Mos	15-Feb-2008				
Eff: 31-Mar-2000 Not Applicable	BY SERIAL NUMBER					Hrs	0				
						Enc	0				
TFE731-76-5109	**Engine Controls - Power Control - Install/Rework Solenoid Controller Valve, Pn 109696-5-1 To Pn 109696-6-1**							RE (-)	Cat.3-Product Improvement		
76 ENG1						Mos					
Eff: 12-Aug-1998						Hrs					
						Enc					
TFE731-76-5109	**Engine Controls - Power Control - Install/Rework Solenoid Controller Valve, Pn 109696-5-1 To Pn 109696-6-1**							RE (-)	Cat.3-Product Improvement		
76 ENG2						Mos					
Eff: 12-Aug-1998						Hrs					
						Enc					
TFE731-76-5109 Rev 1	**Engine Controls - Power Control - Install/Rework Solenoid Controller Valve, Pn 109696-5-1 To Pn 109696-6-1**							RE (-)	Cat.3-Product Improvement		
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-5109 Rev 1	**Engine Controls - Power Control - Install/Rework Solenoid Controller Valve, Pn 109696-5-1 To Pn 109696-6-1**							RE (-)	Cat.3-Product Improvement		
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-5109 Rev 2	**Engine Controls - Power Control - Install/Rework Solenoid Controller Valve, Pn 109696-5-1 To Pn 109696-6-1**							T (A/R)	Cat.3-Product Improvement		
76 ENG1						Mos					
Eff: 20-Sep-2004						Hrs					
						Enc					
TFE731-76-5109 Rev 2	**Engine Controls - Power Control - Install/Rework Solenoid Controller Valve, Pn 109696-5-1 To Pn 109696-6-1**							T (A/R)	Cat.3-Product Improvement		
76 ENG2						Mos					
Eff: 20-Sep-2004						Hrs					
						Enc					
TFE731-76-5111	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1005**							RE (-)		Category 3	
76 ENG1						Mos					
Eff: 28-Apr-1999						Hrs					
						Enc					
TFE731-76-5111	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1005**							RE (-)		Category 3	
76 ENG2						Mos					
Eff: 28-Apr-1999						Hrs					
						Enc					
TFE731-76-5111 Rev 1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1005**							T (A/R)		Category 3	
76 ENG1						Mos					
Eff: 25-Oct-1999						Hrs					
						Enc					
TFE731-76-5111 Rev 1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1005**							T (A/R)		Category 3	
76 ENG2						Mos					
Eff: 25-Oct-1999						Hrs					
						Enc					
TFE731-76-5113	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1006**							T (A/R)		Category 3	
76 ENG1						Mos					
Eff: 24-Jul-2000						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-5113	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1006**							T (A/R)		Category 3	
76 ENG2						Mos					
Eff: 24-Jul-2000						Hrs					
						Enc					
TFE731-76-5114	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1007**							RE (-)		Cat.2-Reliability	
76 ENG1						Mos					
Eff: 08-Jun-2001						Hrs					
						Enc					
TFE731-76-5114	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1007**							RE (-)		Cat.2-Reliability	
76 ENG2						Mos					
Eff: 08-Jun-2001						Hrs					
						Enc					
TFE731-76-5116	**Engine Controls - Power Control - Rework/Install Surge Bleed Valve, Pn 978812-7-1**							RE (-)		Cat.3-Product Improvement	
76 ENG1						Mos	12-Feb-2008				
Eff: 28-Oct-2002 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-76-5116	**Engine Controls - Power Control - Rework/Install Surge Bleed Valve, Pn 978812-7-1**							RE (-)		Cat.3-Product Improvement	
76 ENG2						Mos	15-Feb-2008				
Eff: 28-Oct-2002 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-76-5116 Rev 1	**Engine Controls - Power Control - Rework/Install Surge Bleed Valve, Pn 978812-7-1**							T (A/R)		Cat.3-Product Improvement	
76 ENG1						Mos					
Eff: 30-Jan-2008						Hrs					
						Enc					
TFE731-76-5116 Rev 1	**Engine Controls - Power Control - Rework/Install Surge Bleed Valve, Pn 978812-7-1**							T (A/R)		Cat.3-Product Improvement	
76 ENG2						Mos					
Eff: 30-Jan-2008						Hrs					
						Enc					
TFE731-76-5120	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1008**							RE (-)		Cat.2-Reliability	
76 ENG1						Mos	12-Feb-2008				
Eff: 27-May-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-76-5120	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1008**							RE (-)		Cat.2-Reliability	
76 ENG2						Mos	15-Feb-2008				
Eff: 27-May-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-76-5120 Rev 1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1008**							T (A/R)		Cat.2-Reliability	
76 ENG1						Mos					
Eff: 14-Sep-2004 (AVG MAN HRS: 1)						Hrs					
						Enc					
TFE731-76-5120 Rev 1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (DEEC), Part No. 2118882-1008**							T (A/R)		Cat.2-Reliability	
76 ENG2						Mos					
Eff: 14-Sep-2004 (AVG MAN HRS: 1)						Hrs					
						Enc					
TFE731-76-5122	**Engine Controls - Power Control - Replace Specific Identified Digital Electronic Engine Controls (Deec), Pn 2118882-1008 And -2009**							RE (-)		Cat.2-Reliability	
76 ENG1						Mos					
Eff: 02-Jul-2007						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-5122	**Engine Controls - Power Control - Replace Specific Identified Digital Electronic Engine Controls (Deec), Pn 2118882-1008 And -2009**							RE (-)		Cat.2-Reliability	
76 ENG2						Mos					
Eff: 02-Jul-2007						Hrs					
						Enc					
TFE731-76-5122 Rev 1	**Engine Controls - Power Control - Replace Specific Identified Digital Electronic Engine Controls (Deec), Pn 2118882-1008 And -2009**							T (A/R)		Cat.2-Reliability	
76 ENG1						Mos					
Eff: 20-Aug-2010						Hrs					
						Enc					
TFE731-76-5122 Rev 1	**Engine Controls - Power Control - Replace Specific Identified Digital Electronic Engine Controls (Deec), Pn 2118882-1008 And -2009**							T (A/R)		Cat.2-Reliability	
76 ENG2						Mos					
Eff: 20-Aug-2010						Hrs					
						Enc					
TFE731-76-5123	**Engine Controls - Power Control - Replace Specific Identified Digital Electronic Engine Controls (Deec), Part Numbers 2118882-1008, 2118882-2009, 2118882 -5001, And 2118882-6002**							RE (-)		Cat.2-Reliability	
76 ENG1						Mos	29-Aug-2019				
Eff: 23-Apr-2008 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
TFE731-76-5123	**Engine Controls - Power Control - Replace Specific Identified Digital Electronic Engine Controls (Deec), Part Numbers 2118882-1008, 2118882-2009, 2118882 -5001, And 2118882-6002**							RE (-)		Cat.2-Reliability	
76 ENG2						Mos	29-Aug-2019				
Eff: 23-Apr-2008 Not Applicable						Hrs	4,516.2				
						Enc	2,733				
Y7600000	**Engine DEEC Wire Harness Shield Overbraids and Shield Terminations - Perform Visual Inspection.**							RE		TLMC 05-13-03	**≈24-Apr-2025**
76 A/F	05-13-03					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 410/420) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	3,757				
Y7600001	**Thrust Lever Control Module - Perform Functional Test.**							RE		TLMC 05-13-01	**≈24-Apr-2025**
76 A/F	05-13-01					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:76-10-02 (ZONE: 200) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 76-10-02.))						Ldg	3,757				
Y7610007	**Engine Control Cables - Perform Visual Inspection of forward and aft cable connections.**							RE		TLMC 05-13-02	**≈24-Apr-2025**
76 A/F	05-13-02					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
Alias1:5-10-00 (ZONE: 220FL 220FR 310CC 310DC 450CL 460CR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))						Ldg	3,757				
▼ 77 - ENGINE INDICATING											
	Engine Vibration Accelerometer							RE (O/C)			
77 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Vibration Accelerometer							RE (O/C)			
77 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Vibration Monitor Box							RE (O/C)			
77 A/F		0				Mos	13-Mar-2008				
241-241-000-501	New	0				Hrs	0				
AC75898		0				Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		ITT Harness Assembly							RE (O/C)			
	77 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		ITT Harness Assembly							RE (O/C)			
	77 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		N1 Compensator							RE (O/C)			
	77 ENG1		0				Mos	12-Feb-2008				
	3060735-4	New	0				Hrs	0				
	071309701139		0				Enc	0				
		N1 Compensator							RE (O/C)			
	77 ENG2		0				Mos	15-Feb-2008				
	3060735-5	New	0				Hrs	0				
	071309701066		0				Enc	0				
		N1 Lead Monopole							RE (O/C)			
	77 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		N1 Lead Monopole							RE (O/C)			
	77 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		N1 Monopole							RE (O/C)			
	77 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		N1 Monopole							RE (O/C)			
	77 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		N2 Monopole							RE (O/C)			
	77 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		N2 Monopole							RE (O/C)			
	77 ENG2						Mos	16-Aug-2013				
	3070722-8						Hrs	2,912.5				
	12910300158						Enc	1,706				
		P36 Relay Box							RE (O/C)			
	77 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-77-02	**Engine Indicating - Engine Vibration Accelerometer Inspection**							T (A/R)		Recommended	
77 A/F						Mos					
Eff: 13-Mar-2023						Hrs					
(AVG MAN HRS: 2)						Ldg					
45-77-1	**Power Plant - Inspection of the Dual Fuel Flow Converter Wiring**							RE (-)		Recommended	
77 A/F						Mos					
Eff: 09-Nov-2009						Hrs					
(AVG MAN HRS: 7)						Ldg					
45-77-1 Rev 1	**Power Plant - Inspection of the Dual Fuel Flow Converter Wiring**							RE (-)		Recommended	
77 A/F						Mos	14-Dec-2020				
Eff: 15-Mar-2010 Not Applicable						Hrs	4,610.5				
(AVG MAN HRS: 7)						Ldg	2,822				
77-5106 Rev 1	**Engine Indicating - Temperature - Install Improved Thermocouple Harness**							T (A/R)			
77 ENG1						Mos					
Eff: 25-Jan-2008						Hrs					
						Enc					
77-5106 Rev 1	**Engine Indicating - Temperature - Install Improved Thermocouple Harness**							T (A/R)			
77 ENG2						Mos					
Eff: 25-Jan-2008						Hrs					
						Enc					
TFE731-77-5102	**Engine Indicating - Power - Add Bracket, Part Number MS9592-010, on N1 Monopole (Speed Sensor) Lead Assembly**							RE (-)		Category 3	
77 ENG1						Mos					
Eff: 27-Aug-1997						Hrs					
						Enc					
TFE731-77-5102	**Engine Indicating - Power - Add Bracket, Part Number MS9592-010, on N1 Monopole (Speed Sensor) Lead Assembly**							RE (-)		Category 3	
77 ENG2						Mos					
Eff: 27-Aug-1997						Hrs					
						Enc					
TFE731-77-5102 Rev 1	**Engine Indicating - Power - Add Bracket, Part Number Ms9592-010, on N1 Monopole (Speed Sensor) Lead Assembly**							RE (-)		Category 3	
77 ENG1						Mos	12-Feb-2008				
Eff: 07-Jan-2003 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-77-5102 Rev 1	**Engine Indicating - Power - Add Bracket, Part Number Ms9592-010, on N1 Monopole (Speed Sensor) Lead Assembly**							RE (-)		Category 3	
77 ENG2						Mos	15-Feb-2008				
Eff: 07-Jan-2003 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-77-5102 Rev 2	**Engine Indicating - Power - Add Bracket, Part Number Ms9592-010, on N1 Monopole (Speed Sensor) Lead Assembly**							T (A/R)		Category 3	
77 ENG1						Mos					
Eff: 25-Jan-2008						Hrs					
						Enc					
TFE731-77-5102 Rev 2	**Engine Indicating - Power - Add Bracket, Part Number Ms9592-010, on N1 Monopole (Speed Sensor) Lead Assembly**							T (A/R)		Category 3	
77 ENG2						Mos					
Eff: 25-Jan-2008						Hrs					
						Enc					
TFE731-77-5106	**Engine Indicating - Temperature - Install Improved Thermocouple Harness**							RE (-)		Category 3	
77 ENG1						Mos					
Eff: 10-Sep-1998						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-77-5106	**Engine Indicating - Temperature - Install Improved Thermocouple Harness**						RE (-)		Category 3	
77 ENG2					Mos					
Eff: 10-Sep-1998					Hrs					
					Enc					
TFE731-77-5108	**Engine Indicating - Power - Install Shrink Wrap Over The Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security**						RE (-)		Cat.2-Reliability	
77 ENG1					Mos					
Eff: 20-Apr-2005					Hrs					
					Enc					
TFE731-77-5108	**Engine Indicating - Power - Install Shrink Wrap Over The Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security**						RE (-)		Cat.2-Reliability	
77 ENG2					Mos					
Eff: 20-Apr-2005					Hrs					
					Enc					
TFE731-77-5108 Rev 1	**Engine Indicating - Power - Install Shrink Wrap Over The Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security**						RE (-)		Cat.2-Reliability	
77 ENG1					Mos					
					Hrs					
					Enc					
TFE731-77-5108 Rev 1	**Engine Indicating - Power - Install Shrink Wrap Over The Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security**						RE (-)		Cat.2-Reliability	
77 ENG2					Mos					
					Hrs					
					Enc					
TFE731-77-5108 Rev 2	**Engine Indicating - Power - Install Shrink Wrap Over The Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security**						RE (-)		Cat.2-Reliability	
77 ENG1					Mos	12-Feb-2008				
Complied With	AT MANUFACTURE				Hrs	0				
					Enc	0				
TFE731-77-5108 Rev 2	**Engine Indicating - Power - Install Shrink Wrap Over The Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security**						RE (-)		Cat.2-Reliability	
77 ENG2					Mos	15-Feb-2008				
Complied With	AT MANUFACTURE				Hrs	0				
					Enc	0				
TFE731-77-5108 Rev 3	**Engine Indicating - Power - Install Shrink Wrap Over The Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security**						RE (-)		Cat.2-Reliability	
77 ENG1					Mos	13-Mar-2018				
Eff: 11-Aug-2008 Complied With					Hrs					
					Enc					
TFE731-77-5108 Rev 3	**Engine Indicating - Power - Install Shrink Wrap Over The Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security**						RE (-)		Cat.2-Reliability	
77 ENG2					Mos	11-Nov-2013				
Eff: 11-Aug-2008 Complied With					Hrs	3,011.7				
					Enc	1,768				
TFE731-77-5109	**Engine Indicating - Power - Install Improved N1 Lead Assembly, Pn 3060718-4 Or Pn 3060729-4 (As Applicable)**						T (A/R)		Cat.2-Reliability	
77 ENG1					Mos					
Eff: 18-Aug-2008					Hrs					
					Enc					
TFE731-77-5109	**Engine Indicating - Power - Install Improved N1 Lead Assembly, Pn 3060718-4 Or Pn 3060729-4 (As Applicable)**						T (A/R)		Cat.2-Reliability	
77 ENG2					Mos					
Eff: 18-Aug-2008					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Y7741000	**Engine Vibration Monitoring System - Perform Functional Test.**							RE		TLMC 05-14-03	**≈12-Oct-2025**
77 A/F	05-14-03					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
Alias1:77-41-00 (ZONE: 410/420) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 77-41-00.))						Ldg	2,822				
▼ 78 - EXHAUST											
	Engine Throttle Retard Actuator							RE (O/C)			
78 A/F	No.1					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Throttle Retard Actuator							RE (O/C)			
78 A/F	No.2					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Exhaust Nozzle							RE (O/C)			
78 A/F	No.1					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Exhaust Nozzle							RE (O/C)			
78 A/F	No.2					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	GPM Hydraulic Control Valve							RE (O/C)			
78 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	GPM Hydraulic Control Valve							RE (O/C)			
78 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Inboard Latchbox Actuator							RE (O/C)			
78 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Inboard Latchbox Actuator							RE (O/C)			
78 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Outboard Latchbox Actuator							RE (O/C)			
78 A/F	Left					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Outboard Latchbox Actuator							RE (O/C)			
78 A/F	Right					Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Thrust Reverser							RE (O/C)			
	78 A/F	Left	0				Mos	13-Mar-2008				
	LJ7830101-5	New	0				Hrs	0				
	A30040465		0				Ldg	0				
		Thrust Reverser							RE (O/C)			
	78 A/F	Right	0				Mos	13-Mar-2008				
	LJ7830101-6	New	0				Hrs	0				
	A30040465		0				Ldg	0				
		Thrust Reverser Actuator							RE (O/C)			
	78 A/F	Left Inboard					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Actuator							RE (O/C)			
	78 A/F	Left Outboard		0			Mos	03-Jun-2013				
	LJ7833100-3	Overhauled		0			Hrs	2,863.3				
	A30040547			0			Ldg	1,680				
		Thrust Reverser Actuator							RE (O/C)			
	78 A/F	Right Inboard					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Actuator							RE (O/C)			
	78 A/F	Right Outboard					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Control Box							RE (O/C)			
	78 A/F	Left					Mos	28-Dec-2011				
	LJ7836706-3						Hrs	2,284.1				
	00446						Ldg	1,365				
		Thrust Reverser Control Box							RE (O/C)			
	78 A/F	Right	0				Mos	13-Mar-2008				
	LJ7836706-3	New	0				Hrs	0				
	00432		0				Ldg	0				
		Thrust Reverser Control Valve							RE (O/C)			
	78 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Control Valve							RE (O/C)			
	78 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Hydraulic Control Valve							RE (O/C)			
	78 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Thrust Reverser Hydraulic Control Valve							RE (O/C)			
	78 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Hydraulic Isolation Valve							RE (O/C)			
	78 A/F	Left		0			Mos	13-Mar-2008				
	R-9045-9	New		0			Hrs	0				
	1036			0			Ldg	0				
		Thrust Reverser Hydraulic Isolation Valve							RE (O/C)			
	78 A/F	Right		0			Mos	13-Mar-2008				
	R-9045-9	New		0			Hrs	0				
	1038			0			Ldg	0				
		Thrust Reverser Wire Harness							RE (O/C)			
	78 A/F	Left Inboard					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Wire Harness							RE (O/C)			
	78 A/F	Left Outboard					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Wire Harness							RE (O/C)			
	78 A/F	Right Inboard					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Thrust Reverser Wire Harness							RE (O/C)			
	78 A/F	Right Outboard					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Transformer/Rectifier Electronic Control Unit							RE (O/C)			
	78 A/F						Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
2014-13-06		**Engine Exhaust - Thrust Reverser Support Flange**							RE (-)		Mandatory	
	78 ENG1						Mos	30-Nov-2018				
	Eff: 19-Aug-2014 Complied With	TERMINATING ACTION					Hrs	4,336.4				
							Enc	2,549				
2014-13-06		**Engine Exhaust - Thrust Reverser Support Flange**							RE (-)		Mandatory	
	78 ENG2						Mos	30-Nov-2018				
	Eff: 19-Aug-2014 Complied With	TERMINATING ACTION					Hrs	4,336.4				
							Enc	2,549				
2014-13-06 Para (g)(2)		**Do a fluorescent penetrant inspection for corrosion of the metallic components of the Thrust Reverser's attach flange for any corrosion, and all applicable related**							RE (-)		Mandatory	
	78 ENG1						Mos	14-Nov-2013				
	Eff: 19-Aug-2014 Complied With	BULLETIN 45-78-9 DATED FEBRUARY 27, 2012 WAS COMPLIED WITH PRIOR TO AUGUST 19, 2014					Hrs					
							Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2014-13-06 Para (g)(2)	**Do a fluorescent penetrant inspection for corrosion of the metallic components of the Thrust Reverser's attach flange for any corrosion, and all applicable related**							RE (-)		Mandatory	
78 ENG2						Mos	14-Nov-2013				
Eff: 19-Aug-2014 Complied With	BULLETIN 45-78-9 DATED FEBRUARY 27, 2012 WAS COMPLIED WITH PRIOR TO AUGUST 19, 2014					Hrs					
						Enc					
2018-02-04 PARA (G)(1)	**Inspection Of The Muffler**							RE (-)			
78 A/F						Mos					
						Hrs					
						Ldg					
2018-02-04 PARA (G)(2)	**Remove And Replace The Affected Muffler In Lieu Of Doing The Inspection Required In Para (G)(1)**							RE (-)			
78 A/F						Mos					
						Hrs					
						Ldg					
2018-02-04 PARA (H)(1) & (2)	**Replacement Of The Muffler**							RE (-)			
78 A/F						Mos					
						Hrs					
						Ldg					
45-78-1	**Exhaust - Activation of Thrust Reversers**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-1 Rev 1	**Exhaust - Activation of Thrust Reversers**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-1 Rev 2	**Exhaust - Activation of Thrust Reversers**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-1 Rev 3	**Exhaust - Activation of Thrust Reversers**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-1 Rev 4	**Exhaust - Activation of Thrust Reversers**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-1 Rev 5	**Exhaust - Activation of Thrust Reversers**							RE (-)		Optional	
78 A/F						Mos	29-Aug-2019				
Eff: 10-Nov-2000 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-78-10	**Exhaust - AFT Engine Mount Firewall Pan Assembly And Seal Replacement**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					
45-78-10 Rev 1	**Exhaust - AFT Engine Mount Firewall Pan Assembly And Seal Replacement**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-78-10 Rev 2	**Exhaust - AFT Engine Mount Firewall Pan Assembly And Seal Replacement**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					
45-78-10 Rev 3	**Exhaust - AFT Engine Mount Firewall Pan Assembly And Seal Replacement**							T (-)		Optional	
78 A/F						Mos					
Eff: 07-Oct-2013						Hrs					
						Ldg					
45-78-10 Rev 4	**Exhaust - AFT Engine Mount Firewall Pan Assembly And Seal Replacement**							T (A/R)		Optional	
78 A/F						Mos					
Eff: 01-Jun-2015						Hrs					
(AVG MAN HRS: 6.5)						Ldg					
45-78-11	**Exhaust - High Pressure Pylon Duct Seal and Bumper Plate Replacement**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					
45-78-11 Rev 1	**Exhaust - High Pressure Pylon Duct Seal and Bumper Plate Replacement**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					
45-78-11 Rev 2	**Exhaust - High Pressure Pylon Duct Seal and Bumper Plate Replacement**							RE (-)		Optional	
78 A/F						Mos	14-Nov-2013				
Eff: 07-Oct-2013 Complied With						Hrs	3,011.7				
						Ldg	1,768				
45-78-11 Rev 3	**Exhaust - High Pressure Pylon Duct Seal and Bumper Plate Replacement**							RE (-)		Optional	
78 A/F						Mos	07-Jul-2015				
Eff: 01-Jun-2015 Complied With	NO REWORK IF PREVIOS C/W					Hrs	3,528.4				
(AVG MAN HRS: 12.5)						Ldg	2,053				
45-78-12	**Exhaust - Replacement of the Thrust Reverser Control Unit**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					
45-78-12 Rev 1	**Exhaust - Replacement of the Thrust Reverser Control Unit**							RE (-)		Optional	
78 A/F						Mos					
Eff: 19-May-2014						Hrs					
						Ldg					
45-78-12 Rev 2	**Exhaust - Replacement of the Thrust Reverser Control Unit**							RE (-)		Optional	
78 A/F						Mos	29-Aug-2019				
Eff: 19-Jun-2017 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-78-2	**Exhaust - Replacement of Thrust Reverser Hydraulic Control Valve**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-2 Rev 1	**Exhaust - Replacement of Thrust Reverser Hydraulic Control Valve**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-78-2 Rev 2	**Exhaust - Replacement of Thrust Reverser Hydraulic Control Valve**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-2 Rev 3	**Exhaust - Replacement of Thrust Reverser Hydraulic Control Valve**							RE (-)		Optional	
78 A/F						Mos	29-Aug-2019				
Eff: 16-Feb-2001 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-78-3	**Exhaust - Thrust Reverser Wiring Upgrade**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-3 Rev 1	**Exhaust - Thrust Reverser Wiring Upgrade**							RE (-)		Optional	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-3 Rev 2	**Exhaust - Thrust Reverser Wiring Upgrade**							RE (-)		Optional	
78 A/F						Mos	29-Aug-2019				
Eff: 23-Nov-2009 Not Applicable						Hrs	4,516.2				
						Ldg	2,733				
45-78-4	**Exhaust - Installation of Thrust Reverser Idle Limit Lock**							RE (-)		Recommended	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-4 Rev 1	**Exhaust - Installation of Thrust Reverser Idle Limit Lock**							RE (-)		Recommended	
78 A/F						Mos	13-Mar-2008				
Not Applicable	BY SERIAL NUMBER					Hrs	8.7				
						Ldg	8				
45-78-4 Rev 2	**Exhaust - Installation of Thrust Reverser Idle Limit Lock**							RE (-)		Recommended	
78 A/F						Mos	14-Dec-2020				
Eff: 16-Feb-2001 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-78-5	**Exhaust - Improvement of Engine Beam Firewall Seal**							RE (-)		Recommended	
78 A/F						Mos	14-Dec-2020				
Eff: 17-Jan-2003 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-78-6	**Exhaust - Thrust Reverser Wire Harness - Switch Inspection and Replacement**							RE (-)		Recommended	
78 A/F						Mos	14-Dec-2020				
Eff: 20-Oct-2004 Not Applicable						Hrs	4,610.5				
						Ldg	2,822				
45-78-7	**Exhaust - Replacement of the Engine Service Island**							RE (-)		Optional	
78 A/F						Mos	01-Apr-2008				
Not Applicable	NO ACTION REQUIRED SB SUPERCEDED					Hrs					
						Ldg					
45-78-7 Rev 1	**Exhaust - Replacement of the Engine Service Island**							T (A/R)		Optional	
78 A/F						Mos					
Eff: 22-Jan-2007						Hrs					
						Ldg					
45-78-8	**Power Plant - Installation of Thrust Reverser Alternate Pinning Provisions**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
45-78-8 Rev 1	**Power Plant - Installation of Thrust Reverser Alternate Pinning Provisions**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					
45-78-8 Rev 2	**Power Plant - Installation of Thrust Reverser Alternate Pinning Provisions**							RE (-)		Optional	
78 A/F						Mos					
						Hrs					
						Ldg					
45-78-8 Rev 3	**Power Plant - Installation of Thrust Reverser Alternate Pinning Provisions**							T (A/R)		Optional	
78 A/F						Mos					
Eff: 27-Jan-2014						Hrs					
						Ldg					
45-78-9	**Powerplant - Installation of the Thrust Reverser and Service Island Mounting Flange Gaskets**							RE (-)		Recommended	
78 A/F						Mos					
Eff: 27-Feb-2012						Hrs					
(AVG MAN HRS: 21)						Ldg					
45-78-9 Rev 1	**Powerplant - Installation of the Thrust Reverser and Service Island Mounting Flange Gaskets**							RE (-)		Recommended	
78 A/F						Mos	14-Nov-2013				
Eff: 05-Nov-2012 Complied With						Hrs	3,011.7				
(AVG MAN HRS: 21) (NOTE: 1200 hrs or next C check, whichever first)						Ldg	1,768				
45-78-9 Rev 2	**Powerplant - Installation of the Thrust Reverser and Service Island Mounting Flange Gaskets**							RE (-)		Recommended	
78 A/F						Mos	10-Jan-2020				
Eff: 10-Aug-2015 Not Applicable	BY EFFECTIVITY					Hrs	4,590.8				
						Ldg	2,807				
(AVG MAN HRS: 31) (NOTE: A/C with composite fan duct installed. Complete these instructions within the next 1200 flight hours or the next C phase inspection, whichever comes first)											
AW 78-009	**Cracked Thrust Reverser Fairing**							RE (-)		Advisory Wire	
78 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 78-010	**Thrust Reverser Actuator Upgrade**							RE (-)		Advisory Wire	
78 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
AW 78-011	**Thrust Reverser Procedures**							RE (-)		Advisory Wire	
78 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
D7830078	**** Thrust Reverser System Throttle Retard Actuator - Perform Operational Check.**							RE	TLMC 04-10-00, TLMC 05-14-03, Ch.5 Interval		**≈12-Oct-2025**
78 A/F	05-14-03					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
Alias1:78-32-40 (ZONE: 470/480) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 78-32-40.))						Ldg	2,822				
H7830081	**Thrust Reversers - Remove link rod assemblies and perform magnetic particle inspection.**							RE		TLMC 05-14-03	**≈12-Oct-2025**
78 A/F	05-14-03					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
Alias1:78-30-01 (ZONE: 470/480) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 7, 78-30-01.))						Ldg	2,822				
H7830082	**Thrust Reversers - Remove thrust reverser door assemblies and perform eddy current inspection of pivot fitting and door hinges.**							RE		TLMC 05-14-03	**≈12-Oct-2025**
78 A/F	05-14-03					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
Alias1:78-30-03 (ZONE: 470/480) (SOURCE: MM-104, MM-105) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 78-30-02 and 78-30- 03.))						Ldg	2,822				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
R7830007	**Thrust Reverser - Perform conductivity check of RH thrust reverser door skin and cowl adjacent to APU exhaust.**							RE		TLMC 05-19-00	**≈20-Jun-2024**
78 APU1						Mos	07-Apr-2016				
						Hrs	1,188.9	1,200	-/+25	2,388.9	281.9 Hrs (+25)
	Alias1:78-30-01 (ZONE: 460/480) (NOTE: (Refer to NDI Manual [NDI-104], Part 6, 78-30-01.))					APUS					
Y7830000	**Exhaust Nozzle - Perform Visual Inspection.**							RE		TLMC 05-14-03	**≈12-Oct-2025**
78 A/F	05-14-03					Mos	10-Feb-2021	96	-/+14d	(10-Feb-2029)	4.7 Years (+14 Days)
						Hrs	4,610.5	2,400	-/+25	(7,010.5)	1,735.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 470/480) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	2,822				
Y7830001	**Thrust Reverser Inner Fan Duct Assembly - Perform Visual Inspection. Inspect from exhaust end only.**							RE		TLMC 05-13-03	**≈24-Apr-2025**
78 A/F	05-13-03					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 470/480) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7830002	**Thrust Reverser Door and Hinge Fittings - Perform Visual Inspection.**							RE		TLMC 05-13-03	**≈24-Apr-2025**
78 A/F	05-13-03					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 470/480) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7830003	**Thrust Reverser Primary Actuator and Latch Assembly - Perform Visual Inspection.**							RE		TLMC 05-13-03	**≈24-Apr-2025**
78 A/F	05-13-03					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 470CL, 470DL, 480CR, 480DR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7830004	**Thrust Reverser Hydraulic Control Valve (HCV), Throttle Retard Actuator, and Associated Plumbing - Perform Visual Inspection.**							RE		TLMC 05-13-03	**≈24-Apr-2025**
78 A/F	05-13-03					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 470AL, 470BL, 480AR, 480BR) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7830005	**Thrust Reverser Door Seals and Retainers - Perform Visual Inspection.**							RE		TLMC 05-13-03	**≈24-Apr-2025**
78 A/F	05-13-03					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 470/480) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
Y7830006	**Thrust Reverser Wire Harness - Perform Visual Inspection.**							RE		TLMC 05-13-03	**≈24-Apr-2025**
78 A/F	05-13-03					Mos	09-Feb-2024	48	-/+14d	(09-Jan-2028)	3.6 Years (+14 Days)
						Hrs	5,253.5	1,200	-/+25	(6,453.5)	1,178.7 Hrs (+25)
	Alias1:5-10-00 (ZONE: 470/480) (Tol. Adjustment: -30d) (SOURCE: MM-104, MM-105) (NOTE: (Refer to 5-10-00.))					Ldg	3,757				
▼ 79 - OIL											
	Air Breather Valve Assembly							RE (O/C)			
79 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	Air Breather Valve Assembly							RE (O/C)			
79 ENG2						Mos	15-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				
	APU Temperature Oil Bulb							RE (O/C)			
79 A/F						Mos	13-Mar-2008				
Unknown						Hrs	0				
Unknown						Ldg	0				
	Engine Oil Chip Detector							RE (O/C)			
79 ENG1						Mos	12-Feb-2008				
Unknown						Hrs	0				
Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Oil Chip Detector							RE (O/C)			
79 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Fuel Heater / Oil Cooler Assembly							RE (O/C)			
79 ENG1			0				Mos	12-Feb-2008				
3060709-4		New	0				Hrs	0				
2753			0				Enc	0				
		Fuel Heater / Oil Cooler Assembly							RE (O/C)			
79 ENG2			0				Mos	15-Feb-2008				
3060709-4		New	0				Hrs	0				
2796			0				Enc	0				
		Fuel/Oil Valve							RE (O/C)			
79 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Fuel/Oil Valve							RE (O/C)			
79 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Lower Left Oil Cooler Assembly							RE (O/C)			
79 ENG1			0				Mos	12-Feb-2008				
160554-5		New	0				Hrs	0				
2752			0				Enc	0				
		Lower Left Oil Cooler Assembly							RE (O/C)			
79 ENG2			0				Mos	15-Feb-2008				
160554-5		New	0				Hrs	0				
2757			0				Enc	0				
		Lower Right Oil Cooler Assembly							RE (O/C)			
79 ENG1			0				Mos	12-Feb-2008				
160554-6		New	0				Hrs	0				
2695			0				Enc	0				
		Lower Right Oil Cooler Assembly							RE (O/C)			
79 ENG2			0				Mos	15-Feb-2008				
160554-6		New	0				Hrs	0				
2590			0				Enc	0				
		Oil Check Valve Assembly							RE (O/C)			
79 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Oil Check Valve Assembly							RE (O/C)			
79 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Oil Filter Bypass Valve							RE (O/C)			
	79 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Oil Filter Bypass Valve							RE (O/C)			
	79 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Oil Filter By-Pass Valve							RE (O/C)			
	79 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
	LMM:79-30-01 PB 3000/4000											
		Oil Filter By-Pass Valve							RE (O/C)			
	79 ENG2		0				Mos	13-Oct-2010				
	3060782-2	New	0				Hrs	1,599.6				
	08-06451-09974		0				Enc	969				
	LMM:79-30-01 PB 3000/4000											
		Oil Flow Reduction Valve							RE (O/C)			
	79 ENG1		0				Mos	12-Feb-2008				
	3060769-1	New	0				Hrs	0				
	08-06451-08501		0				Enc	0				
		Oil Flow Reduction Valve							RE (O/C)			
	79 ENG2		0				Mos	15-Feb-2008				
	3060769-1	New	0				Hrs	0				
	070645107434		0				Enc	0				
		Oil Pressure Regulator							RE (O/C)			
	79 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Oil Pressure Regulator							RE (O/C)			
	79 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Oil Pressure Switch							RE (O/C)			
	79 A/F	Left					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Oil Pressure Switch							RE (O/C)			
	79 A/F	Right					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
		Oil Pressure Transducer							RE (O/C)			
	79 A/F	No.1					Mos	13-Mar-2008				
	Unknown						Hrs	0				
	Unknown						Ldg	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Oil Pressure Transducer							RE (O/C)			
79 A/F		No.2					Mos	13-Mar-2008				
Unknown							Hrs	0				
Unknown							Ldg	0				
		Oil Pump							RE (O/C)			
79 ENG1				0			Mos	10-Jul-2010				
3060785-2		Overhauled		0			Hrs	1,452.2				
071405701301				0			Enc	883				
		Oil Pump							RE (O/C)			
79 ENG2				0			Mos	17-Apr-2012				
3060785-3		Overhauled		0			Hrs	2,413.2				
081405700333				0			Enc	1,441				
		Oil Tank Assembly							RE (O/C)			
79 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Oil Tank Assembly							RE (O/C)			
79 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Oil Temperature Bulb							RE (O/C)			
79 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Oil Temperature Bulb							RE (O/C)			
79 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Oil Temperature Control Valve							RE (O/C)			
79 ENG1			0				Mos	12-Feb-2008				
158465-6		New	0				Hrs	0				
12980			0				Enc	0				
		Oil Temperature Control Valve							RE (O/C)			
79 ENG2			0				Mos	15-Feb-2008				
158465-6		New	0				Hrs	0				
12964			0				Enc	0				
		Oil Temperature Regulator							RE (O/C)			
79 ENG1							Mos	12-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				
		Oil Temperature Regulator							RE (O/C)			
79 ENG2							Mos	15-Feb-2008				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Pressure Breather Valve							RE (O/C)			
	79 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Pressure Breather Valve							RE (O/C)			
	79 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Temperature Oil Bulb							RE (O/C)			
	79 A/F	Left	0				Mos	13-Mar-2008				
	MS28034-3	New	0				Hrs	0				
	P9095		0				Ldg	0				
		Temperature Oil Bulb							RE (O/C)			
	79 A/F	Right	0				Mos	13-Mar-2008				
	MS28034-3	New	0				Hrs	0				
	P9098		0				Ldg	0				
		Thermo Lockout Valve Switch Assembly							RE (O/C)			
	79 ENG1						Mos	12-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Thermo Lockout Valve Switch Assembly							RE (O/C)			
	79 ENG2						Mos	15-Feb-2008				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Upper Oil Cooler Assembly							RE (O/C)			
	79 ENG1		0				Mos	12-Feb-2008				
	160552-3	New	0				Hrs	0				
	1789		0				Enc	0				
		Upper Oil Cooler Assembly							RE (O/C)			
	79 ENG2		0				Mos	15-Feb-2008				
	160552-3	New	0				Hrs	0				
	1790		0				Enc	0				
790001		**Engine Baseline SOAP Sample**							RE (-)		EMM - Requirement	
	79 ENG1						Mos					
							Hrs					
							Enc					
790001		**Engine Baseline SOAP Sample**							RE (-)		EMM - Requirement	
	79 ENG2						Mos					
							Hrs					
							Enc					
790130		**Analysis Oil And Filter (SOAP)**							RE		EMM - Requirement, EMM	**≈08-Jun-2024**
	79 ENG1	057110					Mos	09-Feb-2024				
							Hrs	5,253.5	150	+100	(5,403.5)	128.7 Hrs (+100)
	(APX COST: 0)						Enc	3,756				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
790130	**Analysis Oil And Filter (SOAP)**							RE		EMM - Requirement, EMM	**≈08-Jun-2024**
79 ENG2	057110					Mos	09-Feb-2024				
						Hrs	5,253.5	150	+100	(5,403.5)	128.7 Hrs (+100)
(APX COST: 0)						Enc	3,756				
790140	**Perform Oil Change**							RE		EMM - Requirement, EMM	**≈24-Apr-2025**
79 ENG1	057150					Mos	09-Feb-2024				
						Hrs	5,253.5	1,200	+100	(6,453.5)	1,178.7 Hrs (+100)
						Enc	3,756				
790140	**Perform Oil Change**							RE		EMM - Requirement, EMM	**≈24-Apr-2025**
79 ENG2	057150					Mos	09-Feb-2024				
						Hrs	5,253.5	1,200	+100	(6,453.5)	1,178.7 Hrs (+100)
						Enc	3,756				
790150	**Inspect Chip Detector For Contamination And Perform Resistance Check**							RE		EMM - Requirement, EMM	**≈24-Oct-2024**
79 ENG1	057130					Mos	09-Feb-2024				
						Hrs	5,253.5	600	-100/+50	(5,853.5)	578.7 Hrs (+50)
						Enc	3,756				
790150	**Inspect Chip Detector For Contamination And Perform Resistance Check**							RE		EMM - Requirement, EMM	**≈24-Oct-2024**
79 ENG2	057130					Mos	09-Feb-2024				
						Hrs	5,253.5	600	-100/+50	(5,853.5)	578.7 Hrs (+50)
						Enc	3,756				
790160	**Inspect Chip Detector For Contamination**							RE		EMM - Requirement, EMM	**≈08-Jun-2024**
79 ENG1	057110					Mos	09-Feb-2024				
						Hrs	5,253.5	150	+100	(5,403.5)	128.7 Hrs (+100)
(SOURCE: LMM (72-03-06))						Enc	3,756				
790160	**Inspect Chip Detector For Contamination**							RE		EMM - Requirement, EMM	**≈08-Jun-2024**
79 ENG2	057110					Mos	09-Feb-2024				
						Hrs	5,253.5	150	+100	(5,403.5)	128.7 Hrs (+100)
(SOURCE: LMM (72-03-06))						Enc	3,756				
793315	**Check Oil Filter Bypass Valve Circuit/Thermal Lockout Switch**							RE		EMM - Requirement, EMM	**≈24-Apr-2025**
79 ENG1	057150					Mos	09-Feb-2024				
						Hrs	5,253.5	1,200	-200/+100	(6,453.5)	1,178.7 Hrs (+100)
						Enc	3,756				
793315	**Check Oil Filter Bypass Valve Circuit/Thermal Lockout Switch**							RE		EMM - Requirement, EMM	**≈24-Apr-2025**
79 ENG2	057150					Mos	09-Feb-2024				
						Hrs	5,253.5	1,200	-200/+100	(6,453.5)	1,178.7 Hrs (+100)
						Enc	3,756				
79-5103 Rev 1	**Install Dipstick Housing And Plug, Part No 361-530-9481**							T (A/R)			
79 ENG1						Mos					
Eff: 12-Mar-2008						Hrs					
						Enc					
79-5103 Rev 1	**Install Dipstick Housing And Plug, Part No 361-530-9481**							T (A/R)			
79 ENG2						Mos					
Eff: 12-Mar-2008						Hrs					
						Enc					
79-5107	**Oil - Storage - Install Loop Clamps On Oil Tubes To Prevent Vibration And Chaffing**							T (A/R)			
79 ENG1						Mos					
Eff: 10-Apr-2007						Hrs					
						Enc					
79-5107	**Oil - Storage - Install Loop Clamps On Oil Tubes To Prevent Vibration And Chaffing**							T (A/R)			
79 ENG2						Mos					
Eff: 10-Apr-2007						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R1	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R1	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R10	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R10	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R11	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R11	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R12	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R12	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R13	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R13	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R14	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34 R14	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R15	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R15	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R16	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R16	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R17	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R17	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R18	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R18	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R19	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R19	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R2	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R2	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34 R20	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (A/R)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R20	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (A/R)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R3	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R3	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R4	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R4	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R5	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R5	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R6	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R6	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R7	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R7	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R8	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34 R8	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R9	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R9	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
TFE731-79-5103	**Oil - Storage - Install Dipstick Housing and Plug, Part Number 361-530-9481**						RE (-)		Category 3	
79 ENG1					Mos					
Eff: 30-Jun-1997					Hrs					
					Enc					
TFE731-79-5103	**Oil - Storage - Install Dipstick Housing and Plug, Part Number 361-530-9481**						RE (-)		Category 3	
79 ENG2					Mos					
Eff: 30-Jun-1997					Hrs					
					Enc					
TFE731-79-5104	**Oil - Distribution - Replace Oil Flow Reduction Valve (Orv)**						RE (-)		Cat.3-Product Improvement	
79 ENG1					Mos					
Eff: 15-Apr-1999					Hrs					
					Enc					
TFE731-79-5104	**Oil - Distribution - Replace Oil Flow Reduction Valve (Orv)**						RE (-)		Cat.3-Product Improvement	
79 ENG2					Mos					
Eff: 15-Apr-1999					Hrs					
					Enc					
TFE731-79-5104 Rev 1	**Oil - Distribution - Replace Oil Flow Reduction Valve (Orv)**						RE (-)		Cat.3-Product Improvement	
79 ENG1					Mos					
					Hrs					
					Enc					
TFE731-79-5104 Rev 1	**Oil - Distribution - Replace Oil Flow Reduction Valve (Orv)**						RE (-)		Cat.3-Product Improvement	
79 ENG2					Mos					
					Hrs					
					Enc					
TFE731-79-5104 Rev 2	**Oil - Distribution - Replace Oil Flow Reduction Valve (Orv)**						T (A/R)		Cat.3-Product Improvement	
79 ENG1					Mos					
Eff: 20-Sep-2004					Hrs					
					Enc					
TFE731-79-5104 Rev 2	**Oil - Distribution - Replace Oil Flow Reduction Valve (Orv)**						T (A/R)		Cat.3-Product Improvement	
79 ENG2					Mos					
Eff: 20-Sep-2004					Hrs					
					Enc					
TFE731-79-5105	**Oil - Distribution - Oil Lube, Pn 3060701-4/-5 To Pn 3060701-6**						RE (-)		Cat.2-Reliability	
79 ENG1					Mos					
Eff: 24-Dec-1998					Hrs					
					Enc					
TFE731-79-5105	**Oil - Distribution - Oil Lube, Pn 3060701-4/-5 To Pn 3060701-6**						RE (-)		Cat.2-Reliability	
79 ENG2					Mos					
Eff: 24-Dec-1998					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-5105 Rev 1	**Oil - Distribution - Oil Lube, Pn 3060701-4/-5 To Pn 3060701-6**						T (A/R)		Cat.2-Reliability	
79 ENG1					Mos					
Eff: 28-Mar-2007					Hrs					
					Enc					
TFE731-79-5105 Rev 1	**Oil - Distribution - Oil Lube, Pn 3060701-4/-5 To Pn 3060701-6**						T (A/R)		Cat.2-Reliability	
79 ENG2					Mos					
Eff: 28-Mar-2007					Hrs					
					Enc					
TFE731-79-5106	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG1					Mos					
Eff: 13-May-1999					Hrs					
					Enc					
TFE731-79-5106	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG2					Mos					
Eff: 13-May-1999					Hrs					
					Enc					
TFE731-79-5106 Rev 1	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG1					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 1	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG2					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 2	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG1					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 2	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG2					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 3	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG1					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 3	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG2					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 4	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG1					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 4	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG2					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 5	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)			
79 ENG1					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-5106 Rev 5	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)			
79 ENG2					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 6	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG1					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 6	**Oil - Distribution - Install An Improved Oil Drainback System**						RE (-)		Category 3	
79 ENG2					Mos					
					Hrs					
					Enc					
TFE731-79-5106 Rev 7	**Oil - Distribution - Install An Improved Oil Drainback System**						T (A/R)		Category 3	
79 ENG1					Mos					
Eff: 06-Feb-2013					Hrs					
					Enc					
TFE731-79-5106 Rev 7	**Oil - Distribution - Install An Improved Oil Drainback System**						T (A/R)		Category 3	
79 ENG2					Mos					
Eff: 06-Feb-2013					Hrs					
					Enc					
TFE731-79-5110	**Oil - Storage - Replace/Rework Oil Tank Filler Plug For Use With Lockwire on TFE731-20, -40, -50, -60 Model Engines**						RE (-)		Cat.3-Product Improvement	
79 ENG1					Mos					
Eff: 28-Feb-2001					Hrs					
					Enc					
TFE731-79-5110	**Oil - Storage - Replace/Rework Oil Tank Filler Plug For Use With Lockwire on TFE731-20, -40, -50, -60 Model Engines**						RE (-)		Cat.3-Product Improvement	
79 ENG2					Mos					
Eff: 28-Feb-2001					Hrs					
					Enc					
TFE731-79-5110 Rev 1	**Oil - Storage - Replace/Rework Oil Tank Filler Plug For Use With Lockwire on TFE731-20, -40, -50, -60 Model Engines**						T (-)		Cat.3-Product Improvement	
79 ENG1					Mos					
Eff: 12-Mar-2008					Hrs					
					Enc					
TFE731-79-5110 Rev 1	**Oil - Storage - Replace/Rework Oil Tank Filler Plug For Use With Lockwire on TFE731-20, -40, -50, -60 Model Engines**						T (-)		Cat.3-Product Improvement	
79 ENG2					Mos					
Eff: 12-Mar-2008					Hrs					
					Enc					
TFE731-79-5110 Rev 2	**Oil - Storage - Replace/Rework Oil Tank Filler Plug For Use With Lockwire on TFE731-20, -40, -50, -60 Model Engines**						T (A/R)		Cat.3-Product Improvement	
79 ENG1					Mos					
Eff: 09-May-2018					Hrs					
(AVG MAN HRS: 1)					Enc					
TFE731-79-5110 Rev 2	**Oil - Storage - Replace/Rework Oil Tank Filler Plug For Use With Lockwire on TFE731-20, -40, -50, -60 Model Engines**						T (A/R)		Cat.3-Product Improvement	
79 ENG2					Mos					
Eff: 09-May-2018					Hrs					
(AVG MAN HRS: 1)					Enc					
TFE731-79-5111	**Oil - Distribution - Install Oil Lube Pump, Pn 3060701-7**						RE (-)		Cat.2-Reliability	
79 ENG1					Mos					
Eff: 01-Oct-2001					Hrs					
					Enc					
TFE731-79-5111	**Oil - Distribution - Install Oil Lube Pump, Pn 3060701-7**						RE (-)		Cat.2-Reliability	
79 ENG2					Mos					
Eff: 01-Oct-2001					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-5111 Rev 1	**Oil - Distribution - Install Oil Lube Pump, Pn 3060701-7**							T (A/R)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					
TFE731-79-5111 Rev 1	**Oil - Distribution - Install Oil Lube Pump, Pn 3060701-7**							T (A/R)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					
TFE731-79-5112	**Oil - Distribution - Install Improved Oil Lube And Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 18-Apr-2002						Hrs					
						Enc					
TFE731-79-5112	**Oil - Distribution - Install Improved Oil Lube And Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 18-Apr-2002						Hrs					
						Enc					
TFE731-79-5112 Rev 1	**Oil - Distribution - Install Improved Oil Lube And Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	12-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5112 Rev 1	**Oil - Distribution - Install Improved Oil Lube And Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos	15-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5112 Rev 2	**Oil - Distribution - Install Improved Oil Lube And Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos					
						Hrs					
						Enc					
TFE731-79-5112 Rev 2	**Oil - Distribution - Install Improved Oil Lube And Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
						Hrs					
						Enc					
TFE731-79-5112 Rev 3	**Oil - Distribution - Install Improved Oil Lube And Scavenge Pump**							T (A/R)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 12-Apr-2012						Hrs					
						Enc					
TFE731-79-5112 Rev 3	**Oil - Distribution - Install Improved Oil Lube And Scavenge Pump**							T (A/R)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 12-Apr-2012						Hrs					
						Enc					
TFE731-79-5113	**Oil-Distibution-Install Oil Supply Tube Assembly, Part No. 3061207-6 Or 3061208-6 (As Applicable)**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	12-Feb-2008				
Eff: 26-Jun-2002 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5113	**Oil-Distibution-Install Oil Supply Tube Assembly, Part No. 3061207-6 Or 3061208-6 (As Applicable)**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos	15-Feb-2008				
Eff: 26-Jun-2002 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-5113 Rev 1	**Oil-Distibution-Install Oil Supply Tube Assembly, Part No. 3061207-6 Or 3061208-6 (As Applicable)**							T (A/R)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					
TFE731-79-5113 Rev 1	**Oil-Distibution-Install Oil Supply Tube Assembly, Part No. 3061207-6 Or 3061208-6 (As Applicable)**							T (A/R)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					
TFE731-79-5114	**Oil - Distribution - Install Fairing Panels, Pn 3061265-1 And 3061289-1**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 12-Nov-2003						Hrs					
						Enc					
TFE731-79-5114	**Oil - Distribution - Install Fairing Panels, Pn 3061265-1 And 3061289-1**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 12-Nov-2003						Hrs					
						Enc					
TFE731-79-5114 Rev 1	**Oil - Distribution - Install Fairing Panels, Pn 3061265-1 And 3061289-1**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos	12-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5114 Rev 1	**Oil - Distribution - Install Fairing Panels, Pn 3061265-1 And 3061289-1**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos	15-Feb-2008				
Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5114 Rev 2	**Oil - Distribution - Install Fairing Panels, Pn 3061265-1 And 3061289-1**							T (A/R)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 12-Mar-2008						Hrs					
						Enc					
TFE731-79-5114 Rev 2	**Oil - Distribution - Install Fairing Panels, Pn 3061265-1 And 3061289-1**							T (A/R)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 12-Mar-2008						Hrs					
						Enc					
TFE731-79-5115	**Install Oil Tank Sight Glass Decal Pn 461-512-9001**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos	12-Feb-2008				
Eff: 12-Mar-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5115	**Install Oil Tank Sight Glass Decal Pn 461-512-9001**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos	15-Feb-2008				
Eff: 12-Mar-2004 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5116	**Oil - Distribution - Replace The Seal On By-Pass Duct Panel, Part No. 3061101-1/-2/-4/-5**							T (A/R)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 05-Jan-2007						Hrs					
						Enc					
TFE731-79-5116	**Oil - Distribution - Replace The Seal On By-Pass Duct Panel, Part No. 3061101-1/-2/-4/-5**							T (A/R)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 05-Jan-2007						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-5117	**Oil - Distribution - Replace the Seal(s) On Bottom Panel, Part No. 3060947-2 Through -11**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos	12-Feb-2008				
Eff: 10-Sep-2007 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5117	**Oil - Distribution - Replace the Seal(s) On Bottom Panel, Part No. 3060947-2 Through -11**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos	15-Feb-2008				
Eff: 10-Sep-2007 Complied With	AT MANUFACTURE					Hrs	0				
						Enc	0				
TFE731-79-5117 Rev 1	**Oil - Distribution - Replace the Seal(s) on Bottom Panel, PN 3060947-2 Thru -12**							T (A/R)		Category 3, Optional	
79 ENG1						Mos					
Eff: 31-Jan-2024						Hrs					
(AVG MAN HRS: 1.5)						Enc					
TFE731-79-5117 Rev 1	**Oil - Distribution - Replace the Seal(s) on Bottom Panel, PN 3060947-2 Thru -12**							T (A/R)		Category 3, Optional	
79 ENG2						Mos					
Eff: 31-Jan-2024						Hrs					
(AVG MAN HRS: 1.5)						Enc					
TFE731-79-5118	**Oil - Distribution - Install Oil Cooler Inlet Tube Assembly, PN 70060057-2**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 18-Jun-2007						Hrs					
						Enc					
TFE731-79-5118	**Oil - Distribution - Install Oil Cooler Inlet Tube Assembly, PN 70060057-2**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 18-Jun-2007						Hrs					
						Enc					
TFE731-79-5118 Rev 1	**Oil - Distribution - Install Oil Cooler Inlet Tube Assembly, PN 70060057-2**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
						Hrs					
						Enc					
TFE731-79-5118 Rev 1	**Oil - Distribution - Install Oil Cooler Inlet Tube Assembly, PN 70060057-2**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
						Hrs					
						Enc					
TFE731-79-5118 Rev 2	**Oil - Distribution - Install Oil Cooler Inlet Tube Assembly, PN 70060057-2**							T (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 06-Feb-2013						Hrs					
(NOTE: Deleted all references to series TFE731-60 engine models. TFE731-60 engines in compliance with previous revisions of this service bulletin should refer to service bulletin TFE731-79-5124 for further recommended action)						Enc					
TFE731-79-5118 Rev 2	**Oil - Distribution - Install Oil Cooler Inlet Tube Assembly, PN 70060057-2**							T (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 06-Feb-2013						Hrs					
(NOTE: Deleted all references to series TFE731-60 engine models. TFE731-60 engines in compliance with previous revisions of this service bulletin should refer to service bulletin TFE731-79-5124 for further recommended action)						Enc					
TFE731-79-5118 Rev 3	**Oil - Distribution - Install Oil Cooler Inlet Tube Assembly, PN 70060057-2**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 24-Feb-2020						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-5118 Rev 3	**Oil - Distribution - Install Oil Cooler Inlet Tube Assembly, PN 70060057-2**							RE (-)	Cat.3-Product Improvement		
79 ENG2						Mos					
Eff: 24-Feb-2020						Hrs					
						Enc					
TFE731-79-5119	**Install Improved Packings In Oil Lube And Scavenge Pump, Pn 3060785-1, -2**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	13-Mar-2018				
Eff: 26-Aug-2009 Complied With						Hrs					
						Enc					
TFE731-79-5119	**Install Improved Packings In Oil Lube And Scavenge Pump, Pn 3060785-1, -2**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos	11-Nov-2013				
Eff: 26-Aug-2009 Complied With						Hrs	3,011.7				
						Enc	1,768				
TFE731-79-5121	**Install Lube With Regulator And Scavenge Pump (Oil Lube Pump) Pn 3060785-3**							T (A/R)		Category 2	
79 ENG1						Mos					
Eff: 29-Feb-2012						Hrs					
						Enc					
TFE731-79-5121	**Install Lube With Regulator And Scavenge Pump (Oil Lube Pump) Pn 3060785-3**							RE (-)		Category 2	
79 ENG2						Mos	11-Nov-2013				
Eff: 29-Feb-2012 Complied With	PREVIOUSLY					Hrs	3,011.7				
						Enc	1,768				
TFE731-79-5125	**Engine - Oil Distribution - Install New Forward No. 6 Bearing Oil Supply Tube Assembly Pn 3060900-2 And Mid No. 6 Bearing Oil Supply Tube Assembly Pn 3060901-6**							T (A/R)		Category 2	
79 ENG1						Mos					
Eff: 25-Jul-2013						Hrs					
						Enc					
TFE731-79-5125	**Engine - Oil Distribution - Install New Forward No. 6 Bearing Oil Supply Tube Assembly Pn 3060900-2 And Mid No. 6 Bearing Oil Supply Tube Assembly Pn 3060901-6**							T (A/R)		Category 2	
79 ENG2						Mos					
Eff: 25-Jul-2013						Hrs					
						Enc					
TFE731-79-5127	**Oil - Distribution - Install Two-Piece Air-Oil Cooler Supply Tube Assembly**							T (A/R)		Category 2	**≈07-Dec-2024**
79 ENG1						Mos					
Eff: 14-Mar-2014						Hrs				[6,000]	725.2 Hrs
						Enc					
TFE731-79-5127	**Oil - Distribution - Install Two-Piece Air-Oil Cooler Supply Tube Assembly**							T (A/R)		Category 2	**≈07-Dec-2024**
79 ENG2						Mos					
Eff: 14-Mar-2014						Hrs				[6,000]	725.2 Hrs
						Enc					
TFE731-79-5129	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-20, -40, -60 Model Engines**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 09-May-2018						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-79-5129	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-20, -40, -60 Model Engines**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 09-May-2018						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-79-5134	**Engine Oil - Distribution - Replace No. 6 Bearing Oil Supply Tube Assembly, PN 3060964-1 or -2, with PN 3060964-7 or -8, and Add a Clamp on Engine Models TFE731-20, -40, -50, -60**							RE (-)	Cat. 2 - Recommended		
79 ENG1						Mos					
						Hrs					
(AVG MAN HRS: 4) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at next cause for removal or MPI, whichever occurs first.)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-5134	**Engine Oil - Distribution - Replace No. 6 Bearing Oil Supply Tube Assembly, PN 3060964-1 or -2, with PN 3060964-7 or -8, and Add a Clamp on Engine Models TFE731-20, -40, -50, -60**							RE (-)		Cat. 2 - Recommended	
79 ENG2						Mos					
						Hrs					
(AVG MAN HRS: 4) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at next cause for removal or MPI, whichever occurs first.)						Enc					
TFE731-79-5134 Rev 1	**Engine Oil - Distribution - Replace No. 6 Bearing Oil Supply Tube Assembly, PN 3060964-1 or -2, with PN 3060964-7 or -8, and Add a Clamp on Engine Models TFE731-20, -40, -50, -60**							T		Cat. 2 - Recommended	**≈11-Dec-2024**
79 ENG1						Mos					
On Hold						Hrs	3,011.7	3,000		[6,011.7]	736.9 Hrs
(AVG MAN HRS: 4) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at next cause for removal or MPI, whichever occurs first.)						Enc					
TFE731-79-5134 Rev 1	**Engine Oil - Distribution - Replace No. 6 Bearing Oil Supply Tube Assembly, PN 3060964-1 or -2, with PN 3060964-7 or -8, and Add a Clamp on Engine Models TFE731-20, -40, -50, -60**							T		Cat. 2 - Recommended	**≈11-Dec-2024**
79 ENG2						Mos	24-Jun-2021				
On Hold						Hrs	3,011.7	3,000		[6,011.7]	736.9 Hrs
(AVG MAN HRS: 4) (NOTE: COMPLIANCE: Honeywell recommends that this service bulletin be accomplished at next cause for removal or MPI, whichever occurs first.)						Enc					
▼ 90 - GENERAL - SUPPLEMENTAL TYPE CERTIFICATE (STC)											
90-STC ST10526SC	**Replacement Thrust Reverser Control Units (Nordam), Supplemental Type Certificate**							RE (-)			
90 A/F						Mos	13-Mar-2008				
Complied With						Hrs					
						Ldg					
▼ 91 - CHARTS											
AW 91-001	**APU Wire Harness And Rudder Control Cable Chaffing**							RE (-)		Advisory Wire	
91 A/F						Mos	13-Mar-2008				
						Hrs					
						Ldg					
▼ 100 - GENERAL											
5837088-SB No. 1	**Removal/Installation Of Low Pressure Tie Rod - Lp Compressor Shaft Stretch Fixture**							T (A/R)			
100 ENG1						Mos					
Eff: 16-Sep-2011						Hrs					
						Enc					
5837088-SB No. 1	**Removal/Installation Of Low Pressure Tie Rod - Lp Compressor Shaft Stretch Fixture**							T (A/R)			
100 ENG2						Mos					
Eff: 16-Sep-2011						Hrs					
						Enc					
D202005000806	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
100 APU1						Mos					
Eff: 06-May-2020						Hrs					
						APUS					