

TEMPORARY CHANGE NO. 107
to the
EASA APPROVED AIRPLANE FLIGHT MANUAL
(Rep. 180-MAN-0010-01100)

Approved under authority of DOA EASA.21J.685

Publication Affected	P.180 Avanti II EASA Approved Airplane Flight Manual (Rep. 180-MAN-0010-01100, Issued October 21, 2005, or later revisions).
Applicability	Airplanes from MSN 1105 and up
Description	RVSM operation allowed if Mod. 80-1234 or S.B. 80-0467 is installed. If none of them is installed, RVSM operation is temporarily allowed up to October 20th, 2021 .
Instructions	This temporary change updates RVSM Limitations section and is related to installation of Piaggio Service Bulletin (S.B.) n. 80-0467 (Piaggio Mod. n. 80-1234). Insert pages 1 and 2 immediately after the Log of Temporary Changes. <u>For airplanes MSN 1105-2999:</u> - introduce page 2-33-bis/2-34-bis after page 2-33 <u>For airplanes MSN 3001+:</u> - introduce page 2-33.C-bis/2-34.C-bis after page 2-33.C

Retain, in the applicable Flight Manual, until superseded.



INTENTIONALLY LEFT BLANK

At page 2-32, para 2.23 (RVSM), add the following NOTE after the title.

2.23 REDUCED VERTICAL SEPARATION MINIMA (RVSM) OPERATIONS

NOTE

After **October 20th, 2021**, NO RVSM OPERATION ALLOWED
IF Mod. DMT 80-1234 is not installed or S.B. 80-0467 is not
installed.



LIMITATIONS

REDUCED VERTICAL SEPARATION MINIMA (RVSM) OPERATIONS

INTENTIONALLY LEFT BLANK

At page 2-32.C, para 2.23 (RVSM), add the following NOTE after the title.

2.23 REDUCED VERTICAL SEPARATION MINIMA (RVSM) OPERATIONS

NOTE

After **October 20th, 2021**, NO RVSM OPERATION ALLOWED
IF Mod. DMT 80-1234 is not installed or S.B. 80-0467 is not
installed.

LIMITATIONS

REDUCED VERTICAL SEPARATION MINIMA (RVSM) OPERATIONS

INTENTIONALLY LEFT BLANK