Company

Owner: Tech Flight Aviation, LLC
Operator:

Major Assemblies

Airframe	Falcon 50	**041**	26-Feb-2025	13,520.9 Hrs	9,133 Ldg	9,133 Flt	5,682.7 Hrs(APU)
Eng 1	TFE731-3D-1C	**P-76304C**	26-Feb-2025	13,527.1 Hrs	7,886 Enc		
Eng 2	TFE731-3D-1C	**P-76302C**	26-Feb-2025	13,246 Hrs	7,993 Enc		
Eng 3	TFE731-3D-1C	**P-76309C**	26-Feb-2025	13,475.8 Hrs	7,974 Enc		
APU 1	GTCP36-100[A]	**P-223**	24-Feb-2025	4,666.8 Hrs	APUS		

Additional Information

Program Type: Standard, General Categories: EMM,FAR 91,FAA Registered A/C

Cost: 1,185+
Man Hrs: 1,860.3+

Analyst: Darryl Dauphin ddauphin@jetsupport.com

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 0 - GENERAL											
010010	**Renew Aircraft Registration**							RE			
0 A/F						Mos	29-Nov-2023	36		29-Nov-2026	1.7 Years
						Hrs	13,287.4				
Brand C::010010						Ldg	8,989				
						Flt	8,989				
Aircraft registration	**aircraft registration renewal**							RE			
0 A/F						Mos	24-Jan-2025	84		[31-Dec-2030]	5.8 Years
						Hrs					
						Ldg					
						Flt					
F50-071 R1	**Operation on unpaved runways**							T (A/R)			
0 A/F						Mos					
Eff: 16-Dec-1987						Hrs					
						Ldg					
Note: M0299						Flt					
F50-161	**General - Maximum take-off weight upgraded to 40,780 LB**							RE (-)			
0 A/F						Mos					
						Hrs					
						Ldg					
Note: M1230B						Flt					
F50-161 R2	**General - Maximum take-off weight upgraded to 40,780 LB**							T (A/R)			
0 A/F						Mos					
Eff: 29-Jul-1998						Hrs					
						Ldg					
Note: M1230B						Flt					
▼ 1 - --											
F50-024	**Airplane No. 4 retrofitting - DC power, AC power generations and fire protection**							RE (-)			
1 A/F						Mos					
						Hrs					
						Ldg					
Note: M0152						Flt					
F50-024 R1	**Airplane No. 4 retrofitting - DC power, AC power generations and fire protection**							RE (-)			
1 A/F						Mos	22-Jan-1981				
Eff: 04-Apr-1980						Hrs					
						Ldg					
Note: M0152						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-071	**Operation on unpaved runways**							RE (-)		Optional	
1 A/F						Mos					
Eff: 22-Feb-1984						Hrs					
						Ldg					
						Flt					
F50-154	**Take-off and landing operational limits - Field elevation limit extended to 14,000FT**							T (A/R)			
1 A/F						Mos					
Eff: 29-Jun-1987						Hrs					
						Ldg					
Note: M1154						Flt					
F50-161 R1	**General - Maximum take-off weight upgraded to 40,780 LB**							RE (-)			
1 A/F						Mos					
						Hrs					
						Ldg					
Note: M1230B						Flt					
F50-163	**Maximum operating altitude extended to 49,000FT**							T (A/R)			
1 A/F						Mos					
Eff: 10-Apr-1986						Hrs					
						Ldg					
Note: M0017, M1265						Flt					
F50-173	**Cable protection in the wing leading edges**							T (A/R)			
1 A/F						Mos					
Eff: 11-Dec-1985						Hrs					
						Ldg					
Note: M0377						Flt					
F50-191	**Forward extended CG envelope - Truncation ending at 20.9 percent for 40,780lb (18,500kg)**							RE (-)			
1 A/F						Mos					
						Hrs					
						Ldg					
Note: M1430, A/C with MTOW = 40,700 lb (18 500kg) and MZFW = 25,570 lb (11 600 kg) (SB F50 to 161)						Flt					
F50-191 R1	**Forward extended CG envelope - Truncation ending at 20.9 percent for 40,780lb (18,500kg)**							RE (-)			
1 A/F						Mos					
						Hrs					
						Ldg					
Note: M1430, A/C with MTOW = 40,700 lb (18 500kg) and MZFW = 25,570 lb (11 600 kg) (SB F50 to 161)						Flt					
F50-191 R2	**Forward extended CG envelope - Truncation ending at 20.9 percent for 40,780lb (18,500kg)**							RE (-)			
1 A/F						Mos	06-Dec-2002				
Eff: 18-Dec-1990 Complied With						Hrs					
						Ldg					
Note: M1430, A/C with MTOW = 40,700 lb (18 500kg) and MZFW = 25,570 lb (11 600 kg) (SB F50 to 161)						Flt					
F50-314	**Replacement of filotex type A0604 or A1604 cable by type -CF or KZ cable**							T (A/R)			
1 A/F						Mos					
Eff: 12-Jan-2000						Hrs					
						Ldg					
Note: M2432, 2 to 252 and SB kits utilizing FILOTEX A1604 or A0604 cable						Flt					
F50-450	**Requirements for application of the SSIP and of the CPCP to maintain airworthiness up through the aircraft Limit Of Validity -LOV-**							RE (-)			
1 A/F						Mos					
						Hrs					
						Ldg					
Note: M2955, AD EASA F-2004-163						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-450 R1	**Requirements for application of the SSIP and of the CPCP to maintain airworthiness up through the aircraft Limit Of Validity -LOV-**							RE (-)			
1 A/F						Mos					
						Hrs					
						Ldg					
Note: M2955, AD EASA F-2004-163						Flt					
F50-460	**General Requirements for Enrollment into the Corrosion Prevention Control Program (C.P.C.P) to Maintain Airframe Airworthiness (Cancelled - Refer to Chapter 5-15) (No longer applicable)**							RE (-)			
1 A/F						Mos					
						Hrs					
						Ldg					
Note: M2955, M3133						Flt					
F50-460 R1	**General Requirements for Enrollment into the Corrosion Prevention Control Program (C.P.C.P) to Maintain Airframe Airworthiness (Cancelled - Refer to Chapter 5-15) (No longer applicable)**							T (A/R)			
1 A/F						Mos					
Eff: 16-Jul-2009						Hrs					
						Ldg					
Note: M2955, M3133						Flt					
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS											
05-10-00-12M	**"12 M" Inspection**							RE			
5 A/F						Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
(SOURCE: MPD 05-10-00)						Hrs	13,386.3				
Note: Removed tolerance adjustment per Steve Betts email, 5/23/2024. DRD						Ldg	9,044				
						Flt	9,043				
05-10-00-1B	**1B Inspection**							RE			**≈23-Aug-2028**
5 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	14,776.7	1,255.8 Hrs (+30)
(SOURCE: MPD 05-10-00)						Ldg	8,977				
						Flt	8,977				
05-10-00-1C	**1C Inspection**							RE			
5 A/F						Yrs	14-Sep-2023	6	+2m	31-Oct-2028	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -317.2d) (SOURCE: MPD 05-10-00)						Ldg	8,977				
Note: The manufacturer authorizes a maximum tolerance of plus 2 months beyond the C inspection calendar due time. The interval between two C Inspections must be reckoned from the end of the C Inspection if the duration of the inspection does not exceed 3 months. If the duration of the C Inspection exceeds 3 months, the interval must be reckoned 3 months after the beginning of the C Inspection. (Adjust the subsequent C inspection task based on when this C inspection was complied with.)						Flt	8,977				
05-10-00-24M	**"24 M" Inspection**							RE			
5 A/F						Mos	14-Sep-2023	24	+1m	14-Sep-2025	6.4 Months (+30 Days)
(Manual Adjustment: 0d) (UPDATE NOTE: Removed -171d tolerance adjustment per Rafael Pena email, 1/14/25. DRD) (SOURCE: MPD 05-10-00)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
05-10-00-2B	**2B Inspection**							RE			**≈25-Dec-2031**
5 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	3,000	+30	15,978.6	2,457.7 Hrs (+30)
(SOURCE: MPD 05-10-00)						Ldg	8,785				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
05-10-00-2C	**2C Inspection**							RE			
5 A/F						Yrs	02-Sep-2016	12	+2m	02-Sep-2028	3.5 Years (+61 Days)
						Hrs	12,978.6				
(SOURCE: MPD 05-10-00)						Ldg	8,785				
Note: The manufacturer authorizes a maximum tolerance of plus 2 months beyond the C inspection calendar due time. The interval between two C Inspections must be reckoned from the end of the C Inspection if the duration of the inspection does not exceed 3 months. If the duration of the C Inspection exceeds 3 months, the interval must be reckoned 3 months after the beginning of the C Inspection. (Adjust the subsequent C inspection task based on when this C inspection was complied with.)						Flt					
05-10-00-36M	**"36 M" Inspection**							RE			
5 A/F						Mos	14-Sep-2023	36	+1m	03-Sep-2025	6 Months (+30 Days)
(Tol. Adjustment: -370d) (SOURCE: MPD 05-10-00)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
05-10-00-3B	**3B Inspection**							RE			**≈21-Feb-2036**
5 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	4,500	+30	17,478.6	3,957.7 Hrs (+30)
(SOURCE: MPD 05-10-00)						Ldg	8,785				
						Flt					
05-10-00-3C	**3C Inspection**							RE (-)			
5 A/F						Yrs	22-Apr-1998		+2m		
						Hrs	8,651.1				
(SOURCE: MPD 05-10-00)						Ldg	6,170				
Note: The manufacturer authorizes a maximum tolerance of plus 2 months beyond the C inspection calendar due time. The interval between two C Inspections must be reckoned from the end of the C Inspection if the duration of the inspection does not exceed 3 months. If the duration of the C Inspection exceeds 3 months, the interval must be reckoned 3 months after the beginning of the C Inspection. (Adjust the subsequent C inspection task based on when this C inspection was complied with.)						Flt					
05-10-00-4B	**4B Inspection**							RE			**≈21-Apr-2040**
5 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	6,000	+30	18,978.6	5,457.7 Hrs (+30)
(SOURCE: MPD 05-10-00)						Ldg	8,785				
						Flt					
05-10-00-4C	**4C Inspection**							RE (-)			
5 A/F						Mos			+2m		
						Hrs					
(SOURCE: MPD 05-10-00)						Ldg					
Note: The manufacturer authorizes a maximum tolerance of plus 2 months beyond the C inspection calendar due time. The interval between two C Inspections must be reckoned from the end of the C Inspection if the duration of the inspection does not exceed 3 months. If the duration of the C Inspection exceeds 3 months, the interval must be reckoned 3 months after the beginning of the C Inspection. (Adjust the subsequent C inspection task based on when this C inspection was complied with.)						Flt					
05-10-00-5C	**5C Inspection**							RE (-)			
5 A/F						Mos			+2m		
						Hrs					
(SOURCE: MPD 05-10-00)						Ldg					
Note: The manufacturer authorizes a maximum tolerance of plus 2 months beyond the C inspection calendar due time. The interval between two C Inspections must be reckoned from the end of the C Inspection if the duration of the inspection does not exceed 3 months. If the duration of the C Inspection exceeds 3 months, the interval must be reckoned 3 months after the beginning of the C Inspection. (Adjust the subsequent C inspection task based on when this C inspection was complied with.)						Flt					
053401	**Far 91.411/91.413 Pitot Static Inspection**							RE			
5 A/F						Mos	14-Sep-2023	24		14-Sep-2025	6.4 Months
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
05-50-00-100-801	**Cleaning After Electrolyte Spillage**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
Ref:24-080					Ldg					
					Flt					
05-50-00-200-801	**Check After a Towing Incident**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
Ref:32-140					Ldg					
					Flt					
05-50-00-200-802	**Check After Hailstorm**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
Ref:51-050					Ldg					
					Flt					
05-50-00-200-803	**Check After a Lightning Strike**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
Ref:51-060					Ldg					
					Flt					
05-50-00-200-804	**Check After a Rejected Take-Off or Emergency Braking**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
Ref:32-160 (SOURCE: Falcon 50/50EX MPD)					Ldg					
Note: To be performed if at least one tire is deflated.					Flt					
05-50-00-200-805	**Check After Flying Under Excessive Load Factor or Through Excessive Turbulence**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
Ref:51-040					Ldg					
					Flt					
05-50-00-200-806	**Check After Aircraft Tilting Backward During Maintenance or Power Back Operations**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
					Ldg					
					Flt					
05-50-00-200-809	**Inspection After Slat Operation In Overspeed Condition**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
(SOURCE: Falcon 50/50EX MPD)					Ldg					
Note: To be performed after slats operation at more than maximum speed for slats operation as defined in the Airplane Flight Manual (AFM).					Flt					
05-50-00-200-810	**Inspection After Flap Operation In Overspeed Condition**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
(SOURCE: Falcon 50/50EX MPD)					Ldg					
Note: To be performed after flaps operation at more than maximum speed for flaps operation as defined in the Airplane Flight Manual (AFM).					Flt					
05-50-00-200-812	**Inspection After Landing Gear Extension In Overspeed Condition**						RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F					Mos					
					Hrs					
					Ldg					
Note: To be performed after landing gear operation at more than maximum speed for operating landing gear (VLO) and after landing gear extension at more than maximum speed for landing gear extended (VLE), (VLO) and (VLE) as defined in the Airplane Flight Manual (AFM).					Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
05-50-00-200-813	**Check After Wheel Impact With an Obstacle at Take off or Landing**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
Ref:32-170						Ldg					
						Flt					
05-50-00-200-817	**Check After Collision With Foreign Object**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
05-50-00-200-822	**Operation To Be Performed After VMO/MMO Exceedance**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
(SOURCE: Falcon 50/50EX MPD)						Ldg					
						Flt					
05-50-00-200-823	**Check of the Slats After Overheating**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
05-50-00-620-801	**Specific Maintenance For A/C Operating In Corrosive Ambient Conditions**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
Note: To be applied on aircraft operating in conditions that can contribute to the development of corrosion.						Flt					
05-50-00-620-803	**Specific Maintenance For A/C Operating In Cold Weather**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
Ref:05-105						Ldg					
Note: If aircraft has been operated and parked under continuously freezing temperatures for more than 15 flights						Flt					
05-50-00-620-804	**Procedure For Aircraft Prolonged Operation at Low Temperatures**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
Ref:51-165						Ldg					
Note: To be performed when A/C is operated or parked under freezing temperature for more than 300 flight hours or 6 months (first limit reached).						Flt					
05-50-00-620-805	**Specific Maintenance to Prevent Fuel Contamination**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
05-50-00-700-803	**Check After Fire Extinguisher Percussion**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
Ref:20-350						Ldg					
						Flt					
05-50-00-700-807	**Check After Landing on a Dry and Dirty Runway**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
Ref:32-180						Ldg					
						Flt					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
05-50-00-700-808	**Check After Hard / Overweight Landing**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
Ref:32-130						Ldg					
Note: To be performed after landing at weight beyond Maximum Landing Weight (MLW) and with a vertical speed at touch down greater than 360 ft/min.						Flt					
05-50-00-700-810	**Check After a Flight Through Sand**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
Note: To be performed after flying through sand.						Flt					
05-50-00-700-818	**Check After an Electrical Fire**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
Note: To be performed after an electrical fire.						Flt					
05-50-00-700-822	**Check After a FlightThrough Volcanic Ashes**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
Note: To be performed after flying through volcanic ash.						Flt					
05-50-00-730-802	**Check of the Braking System at Acceleration/ Stop After Troubleshooting**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
05-50-00-860-801	**Check and Preparation For Flight With One Engine Inoperative**							RE (A/R)		Unsch Maint Chk (5-50)	
5 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
05-50-00-910-801	**Aircraft Check Flight**							RE		Unsch Maint Chk (5-50)	
5 A/F	05-10-00-1C					Mos	14-Sep-2023	72	+2m	(31-Oct-2028)	3.7 Years
						Hrs	13,276.7				
Ref:51-070 (Tol. Adjustment: -372d)						Ldg	8,977				
						Flt	8,977				
05-60-00-200-801-01	**Basic Inspection**							RE		Acft Maint Ops (5-10)	**≈03-Dec-2025**
5 A/F						Mos	03-Feb-2025	12	+1m	03-Feb-2026	11.1 Months (+28 Days)
						Hrs	13,496.2	300	+30	13,796.2	275.3 Hrs (+30)
Note: Removed tolerance adjustment per Steve Betts email, 5/23/2024. DRD						Ldg	9,121				
						Flt	9,121				
05-60-00-200-801-03	**Basic Inspection - Ground Servicing Checks**							RE		Acft Maint Ops (5-10)	**≈13-Aug-2025**
5 A/F						Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
						Hrs	13,386.3	300	+30	13,686.3	165.4 Hrs (+30)
Note: Removed tolerance adjustment per Steve Betts email, 5/23/2024. DRD						Ldg	9,044				
						Flt	9,043				
2013-03-12	**Periodic inspections (Superseded by AD 2017-09-03)**							RE (-)		Mandatory	
5 A/F						Mos	16-Oct-2013				
Eff: 19-Mar-2013						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2013-03-12 Paragraph (g)	**Periodic inspections - Maintenance Program Revision**							T (-)		Mandatory	
5 A/F						Mos					
Eff: 19-Mar-2013						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2013-03-12 Paragraph (i)	**Periodic inspections - Terminating Action for certain ADs**							T (-)		Mandatory	
5 A/F						Mos					
Eff: 19-Mar-2013						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-09-03	**Periodic inspections (Superseded by FAA AD 2023-05-15)**							RE (-)		Mandatory	
5 A/F						Mos	18-Oct-2018				
Eff: 13-Jun-2017						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-09-03 Par. (g)	**Periodic Inspection - Maintenance Program Revision**							T (-)		Mandatory	
5 A/F						Mos					
Eff: 19-Mar-2013						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-09-03 Par. (i)	**Periodic Inspection - New Maintenance or Inspection Program Revision**							RE (-)		Mandatory	
5 A/F						Mos	31-Oct-2018				
Eff: 13-Jun-2017 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-09-03 Par. (k)	**Periodic Inspection - Terminating Action for Certain ADs**							T (-)		Mandatory	
5 A/F						Mos					
Eff: 13-Jun-2017						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
Note: Accomplishing the actions required by paragraph (g) or (i) of this AD terminates all requirements of AD 2010-26-05 and AD 2012-02-18 for the Dassault Aviation Model MYSTERE-FALCON 50 airplanes specified in those ADs						Flt					
2018-20-07	**Time limits/maintenance checks - Revision of Maintenance or Inspection Program (Superseded by FAA AD 2023-05-15)**							RE (-)		Mandatory	
5 A/F						Mos	17-Oct-2018				
Eff: 07-Nov-2018						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2018-20-07 Paragraph (g)	**Time limits/maintenance checks - Revision of Maintenance or Inspection Program, As Applicable**							RE (-)		Mandatory	
5 A/F						Mos	31-Oct-2018				
Eff: 07-Nov-2018 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2018-20-07 Paragraph (i)	**Time limits/maintenance checks - Revision of Maintenance or Inspection Program - Accomplishing the Actions Required by Paragraph (g) of this Ad Terminates All Requirements of Ad 2017-09-03, 2010-26-05, 2012-02-18**							RE (-)		Mandatory	
5 A/F						Mos					
Eff: 07-Nov-2018						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2023-05-15	**Time Limits/Maintenance Checks - New or More Restrictive Airworthiness Limitations (Supersedes FAA AD 2017-09-03 and FAA AD 2018-20-07)**							RE (-)		Mandatory	
5 A/F						Mos	29-Nov-2023				
Eff: 18-May-2023 Complied With	Customer provided Traxall maintenance tracking incorporating MPD 05-40 with Airworthy Limitations, Rev 26 - April 2022, DGT 113872 - PUB 237 or 238.					Hrs	13,287.4				
(ISSUING AUTHORITY: FAA)						Ldg	8,989				
						Flt					

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2023-05-15 Par. (g)	**Time Limits/Maintenance Checks - New or More Restrictive Airworthiness Limitations: Retained Revision of the Existing Maintenance or Inspection Program, With No Changes**							RE (-)		Mandatory	
5 A/F						Mos	29-Nov-2023				
Eff: 07-Nov-2018 Complied With	Customer provided Traxall maintenance tracking incorporating MPD 05-40 with Airworthy Limitations, Rev 26 - April 2022, DGT 113872 - PUB 237 or 238.					Hrs	13,287.4				
(ISSUING AUTHORITY: FAA)						Ldg	8,989				
						Flt	8,989				
2023-05-15 Par. (i)	**Time Limits/Maintenance Checks - New or More Restrictive Airworthiness Limitations: New Revision of the Existing Maintenance or Inspection Program**							RE (-)		Mandatory	
5 A/F						Days	29-Nov-2023				
Eff: 18-May-2023 Complied With	Customer provided Traxall maintenance tracking incorporating MPD 05-40 with Airworthy Limitations, Rev 26 - April 2022, DGT 113872 - PUB 237 or 238.					Hrs	13,287.4				
(ISSUING AUTHORITY: FAA)						Ldg	8,989				
Note: COMPLIANCE: This AD requires revising the existing maintenance or inspection program, as applicable within 90 days after the effective date of this AD.						Flt	8,989				
The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022–0166 is at the applicable "limitations" and "associated thresholds" as incorporated by the requirements of paragraph (3) of EASA AD 2022–0166, or within 90 days after the effective date of this AD, whichever occurs later.											
Accomplishing the actions required by paragraph (g) or (i) of this AD terminates the requirements of AD 2010–26–05 for Dassault Aviation Model MYSTERE–FALCON 50 airplanes only.											
PKG 1000/1500 Hour	**Engine - 1000 to 1500 Hour Inspection**							RE			**≈03-Apr-2027**
5 ENG1						Mos	04-Jan-2023				
						Hrs	13,282.8	1,000	+500	14,282.8	755.7 Hrs (+500)
						Enc	7,730				
PKG 1000/1500 Hour	**Engine - 1000 to 1500 Hour Inspection**							RE			**≈19-Sep-2024**
5 ENG2						Mos	31-Aug-2015				
						Hrs	12,125.7	1,000	+500	13,125.7	0 Hrs (+379.7)
						Enc	7,353				
PKG 1000/1500 Hour	**Engine - 1000 to 1500 Hour Inspection**							RE			**≈12-Nov-2026**
5 ENG3						Mos	26-Feb-2014				
						Hrs	12,890.5	1,200	+300	14,090.5	614.7 Hrs (+300)
						Enc	7,586				
PKG 150/250 Hour	**Engine - 150 to 250 Hour Inspection**							RE			**≈20-May-2025**
5 ENG1						Mos	06-Dec-2024				
						Hrs	13,459.5	150	+100	13,609.5	82.4 Hrs (+100)
(ZONE: .)						Enc	7,844				
PKG 150/250 Hour	**Engine - 150 to 250 Hour Inspection**							RE			**≈20-May-2025**
5 ENG2						Mos	06-Dec-2024				
						Hrs	13,178.4	150	+100	13,328.4	82.4 Hrs (+100)
(ZONE: .)						Enc	7,951				
PKG 150/250 Hour	**Engine - 150 to 250 Hour Inspection**							RE			**≈20-May-2025**
5 ENG3						Mos	06-Dec-2024				
						Hrs	13,408.2	150	+100	13,558.2	82.4 Hrs (+100)
(ZONE: .)						Enc	7,932				
PKG 300/400 Hour	**Engine - 300 to 400 Hour Inspection**							RE			**≈23-Apr-2025**
5 ENG1						Mos	04-Jan-2023				
						Hrs	13,282.8	300	+100	13,582.8	55.7 Hrs (+100)
						Enc	7,730				
PKG 300/400 Hour	**Engine - 300 to 400 Hour Inspection**							RE			**≈17-Feb-2025**
5 ENG2						Mos	20-Oct-2021				
						Hrs	12,938.2	300	+100	13,238.2	0 Hrs (+92.2)
						Enc	7,801				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
PKG 300/400 Hour	**Engine - 300 to 400 Hour Inspection**							RE			**≈17-Feb-2025**
5 ENG3						Mos	20-Oct-2021				
						Hrs	13,168	300	+100	13,468	0 Hrs (+92.2)
						Enc	7,782				
PKG 600/800 Hour	**Engine - 600 to 800 Hour Inspection**							RE			**≈21-Feb-2026**
5 ENG1						Mos	04-Jan-2023				
						Hrs	13,282.8	600	+200	13,882.8	355.7 Hrs (+200)
						Enc	7,730				
PKG 600/800 Hour	**Engine - 600 to 800 Hour Inspection**							RE			**≈24-Sep-2026**
5 ENG2						Mos	20-Oct-2021				
						Hrs	13,213.1	600	+200	13,813.1	567.1 Hrs (+200)
						Enc	8,940				
PKG 600/800 Hour	**Engine - 600 to 800 Hour Inspection**							RE			**≈12-Mar-2025**
5 ENG3						Mos	26-Feb-2014				
						Hrs	12,890.5	600	+200	13,490.5	14.7 Hrs (+200)
						Enc	7,586				
▼ 8 - LEVELING AND WEIGHING.											
080001	**Weight and Balance Aircraft**							RE			
8 A/F						Mos	12-Sep-2023	36		12-Sep-2026	1.5 Years
						Hrs					
						Ldg					
						Flt					
▼ 9 - TOWING AND TAXIING											
09-10-00-910-810	**Debogging the Aircraft**							RE (A/R)		Unsch Maint Chk (5-50)	
9 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
▼ 10 - PARKING, MOORING, STORAGE AND RETURN TO SERVICE											
10-10-00-200-801	**Check After Parking of the Aircraft In High Wind Conditions**							RE (A/R)		Unsch Maint Chk (5-50)	
10 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
10-10-00-550-801	**Storage / Return to Service of the Aircraft**							RE (A/R)		Unsch Maint Chk (5-50)	
10 A/F						Mos	30-Apr-2024				
						Hrs	13,296.7				
Ref:20-355						Ldg	8,994				
Note: If the aircraft stays on ground for a long period of time (more than 4 weeks), refer to task "STORAGE / RETURN TO SERVICE OF THE AIRCRAFT" for aircraft pre-storage and storage conditions (Refer to TASK 10-10-00-550-801 para. "Overview of the job").						Flt	8,994				
10-10-00-550-801-02	**Perform Storage of the Aircraft for a Maximum Duration of 2 Months to 12 Months**							RE (A/R)			
10 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
10-10-00-550-801-03	**Perform Storage of the Aircraft for a Maximum Duration of 12 Months to 18 Months**							RE (A/R)			
10 A/F						Mos					
						Hrs					
						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
10-20-00-910-802	**Mooring the Aircraft In Case of Snowfall**							RE (A/R)		Unsch Maint Chk (5-50)	
10 A/F						Mos					
						Hrs					
Ref:10-030						Ldg					
						Flt					
F50-034	**Flight kit - Addition of a total temperature probe cover**							RE (-)			
10 A/F						Mos					
						Hrs					
						Ldg					
Note: M0178						Flt					
F50-034 R1	**Flight kit - Addition of a total temperature probe cover**							RE (-)			
10 A/F						Mos					
Eff: 20-Feb-1981						Hrs					
						Ldg					
Note: M0178						Flt					
F50-101	**Structural provisions for ventilation outlet shutters**							T (A/R)			
10 A/F						Mos					
Eff: 03-Jul-1984						Hrs					
						Ldg					
Note: M0709A, M0709B						Flt					
▼ 11 - PLACARDS AND MARKINGS											
F50-062	**Required placards - Center engine S-duct inspection door - Placard giving locking instructions**							RE (-)			
11 A/F						Mos	22-Jan-1981				
Eff: 25-Feb-1980						Hrs					
						Ldg					
Note: M0148						Flt					
F50-333	**Pilot instrument panel - Warning placard concerning "ADC" flag on PFD upon static source change**							RE (-)			
11 A/F						Mos					
Eff: 12-Apr-2000						Hrs					
						Ldg					
Note: M2661, 251 to 289 with COLLINS ADC 850F P/N 822-1036-406						Flt					
F50-396	**Composite horizontal stabilizer identification**							RE (-)			
11 A/F						Mos	08-Aug-2001				
Eff: 10-Apr-2002 Complied With						Hrs					
						Ldg					
						Flt					
F50-401	**Crew and Passenger door locking instructions for closing door from inside the aircraft (This SB is superseded by SB F50-548)**							T (-)			
11 A/F						Mos					
Eff: 08-Oct-2002						Hrs					
						Ldg					
Note: M2850						Flt					
F50-445	**Baggage compartment - New placards specifying the maximum authorized weight on the avionics rack floor and fairing**							RE (-)			
11 A/F						Mos					
Eff: 17-Mar-2004						Hrs					
						Ldg					
Note: M2918, M2923, 253 to 352 without M2918 & M2923						Flt					
F50-449	**Safety placard and engine 2 hoist limitations**							T (A/R)			
11 A/F						Mos					
Eff: 11-Jun-2004						Hrs					
						Ldg					
Note: M2943						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-495	**Toilets - Addition of placards for applicable antifreeze products**							T (A/R)			
11 A/F						Mos					
Eff: 16-Mar-2009						Hrs					
						Ldg					
Note: M3103, 1 to 352 with toilet and without M3103						Flt					
F50-548	**Markings and Placards - Crew and Passenger Doors - Replacement of "Locking Instructions for Closing Door from Inside the Aircraft" Label (This SB supersedes SB F50-401)**							T (-)		Optional	
11 A/F						Mos					
Eff: 19-Jun-2017						Hrs					
(AVG MAN HRS: 1)						Ldg					
						Flt					
F50-548 R1	**Markings and Placards - Crew and Passenger Doors - Replacement of "Locking Instructions for Closing Door from Inside the Aircraft" Label (This SB supersedes SB F50-401)**							T (A/R)		Optional	
11 A/F						Mos					
Eff: 30-Oct-2017						Hrs					
(AVG MAN HRS: 1)						Ldg					
						Flt					
F50-549	**Placards and Markings - Passenger Compartment - Addition of No Smoking Pictograms**							T (-)		Optional	
11 A/F						Mos					
Eff: 15-Feb-2017						Hrs					
(AVG MAN HRS: 2)						Ldg					
						Flt					
F50-549-R1	**Placards and Markings - Cockpit and Cabin - Addition of No Smoking Pictograms**							T (A/R)		Optional	
11 A/F						Mos					
Eff: 15-Nov-2021						Hrs					
MOD:R2596, MOD:R3071 (AVG MAN HRS: 2)						Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to MYSTERE-FALCON 50 aircraft with serial numbers 2 thru 352 for which CS 26 compliance is required (European registered aircraft used for commercial operations).						Flt					
▼ 20 - STANDARD PRACTICES – AIRFRAME											
20-30-00-330-801	**Temporary Repair After Minor Damage to a Composite Material Component**							RE (A/R)		Unsch Maint Chk (5-50)	
20 A/F						Mos					
						Hrs					
Ref:51-065						Ldg					
						Flt					
20-31-00-140-801	**Rinsing the Aircraft Exterior**							RE (A/R)		Unsch Maint Chk (5-50)	
20 A/F						Mos					
						Hrs					
Ref:20-318						Ldg					
Note: It is recommended to perform an aircraft rinsing at the first available time: • after flying at low level above sea (airport near the sea), • if flight is performed after de-icing, • after flying in volcanic ash.						Flt					
20-31-00-910-801	**Ground De-Icing and Preventive Anti-Icing**							RE (A/R)		Unsch Maint Chk (5-50)	
20 A/F						Mos					
						Hrs					
Ref:20-625						Ldg					
						Flt					
20-33-00-300-804	**Temporary Repair of a Hydraulic or Water Pipe Using Rynglok Fittings**							RE (A/R)		Unsch Maint Chk (5-50)	
20 A/F						Mos					
						Hrs					
						Ldg					
Note: Temporary repair time limit is 6 months or 200 flight hours whichever comes first.						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
20-60-00-370-813	**Application of the Paint Scheme on Composite Components**							RE (A/R)		Unsch Maint Chk (5-50)	
20 A/F						Mos					
						Hrs					
Ref:20-615						Ldg					
Note: To be performed in case of complete paint renewal.						Flt					
20-60-00-370-816-04	**Restoration Of The Paint Scheme Of The Landing Gears - Rh Mlg Leg (R2Gf)**							RE (A/R)			
20 A/F	Right					Mos	16-Sep-2018				
C23792-1010-/-1012						Hrs					
U68						Ldg					
						Flt					
20-60-00-370-816-09	**Restoration Of The Paint Scheme Of The Landing Gears - Nlg Leg (3Gf)**							RE (A/R)			
20 A/F						Mos	16-Sep-2018				
C23789-1007-/-/-1010						Hrs					
U93						Ldg					
						Flt					
98-06-01	**Wiring Harnesses And Adjacent Equipment**							RE (-)		Mandatory	
20 A/F						Mos	11-Sep-1998				
Eff: 15-Apr-1998						Hrs	8,721				
(ISSUING AUTHORITY: FAA)						Ldg	6,251				
						Flt					
F50-092	**Use of S41-21 and S71-21 teleforce controls authorized**							T (A/R)			
20 A/F						Mos	18-Jun-1987				
Eff: 25-Feb-1982	Partially Complied With					Hrs	4,087.5				
SB:F50-20-001						Ldg	2,821				
						Flt					
F50-100	**Electrical wire routing in the rear compartment**							T (A/R)			
20 A/F						Mos					
Eff: 15-Nov-1982						Hrs					
						Ldg					
Note: M0616, M0644A, M0644B						Flt					
F50-105	**ITT solenoid selector valves replaced for sterer valves**							RE (-)			
20 A/F						Mos					
						Hrs					
						Ldg					
Note: M1007						Flt					
F50-105 R1	**ITT solenoid selector valves replaced for sterer valves**							T (A/R)			
20 A/F						Mos					
Eff: 26-Mar-1987						Hrs					
						Ldg					
Note: M1007						Flt					
F50-147	**Additionnal bonding of engine and APU generators**							RE (-)			
20 A/F						Mos					
						Hrs					
						Ldg					
Note: M1118B, M1118A						Flt					
F50-147 R1	**Additionnal bonding of engine and APU generators**							T (A/R)			
20 A/F						Mos					
Eff: 22-Oct-1991						Hrs					
						Ldg					
Note: M1118B, M1118A						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-256	**Wiring harnesses coming out of RH electrical cabinet - Protection to be provided opposite to equipment supports between frames 9 and 11**							RE (-)			
20 A/F						Mos					
						Hrs					
						Ldg					
Note: M2071, AD EASA 96-094-017 R1 (AD FAA 98-06-01)						Flt					
F50-256 R1	**Wiring harnesses coming out of RH electrical cabinet - Protection to be provided opposite to equipment supports between frames 9 and 11**							RE (-)			
20 A/F						Mos	11-Sep-1998				
Eff: 22-Dec-1996 Complied With						Hrs					
						Ldg					
Note: M2071, AD EASA 96-094-017 R1 (AD FAA 98-06-01)						Flt					
F50-322	**Inspection and improved protection of varius wiring assemblies**							RE (-)			
20 A/F						Mos					
Eff: 16-Jun-1999						Hrs					
						Ldg					
Note: M2484						Flt					
F50-336	**Inspection and protection of wiring assemblies**							RE (-)			
20 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-336 R1	**Inspection and protection of wiring assemblies**							RE (-)			
20 A/F						Mos					
Eff: 10-May-2000						Hrs					
						Ldg					
						Flt					
F50-371	**New retaining system for the standby pump selector lever in "in flight" position**							T (A/R)			
20 A/F						Mos					
Eff: 15-May-2002						Hrs					
						Ldg					
Note: M2769, A/C without M2769						Flt					
F50-486	**Wiring and oxygen line routing at frame 9 - Adding clamps to prevent interference**							RE (-)			
20 A/F						Mos	25-May-2010				
Eff: 11-Jan-2007 Complied With						Hrs	11,245				
						Ldg	7,850				
Note: M3021						Flt					
▼ 21 - AIR CONDITIONING AND PRESSURIZATION											
	Aerator							RE (O/C)			
21 A/F	Copilot					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Aerator							RE (O/C)			
21 A/F	Pilot					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Air Actuator Valve							RE (O/C)			
21 A/F						Mos	09-Aug-2021				
NYLC50440-1						Hrs					
118						Ldg					
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Air Conditioning Control Box							RE (O/C)			
21 A/F	5897651-8 Unknown						Mos	09-Apr-2021				
							Hrs					
							Ldg					
							Flt					
		Air Conditioning Flow Limiter							RE (H/T)			
21 A/F	Unknown Unknown	Cabin					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Air Conditioning Flow Limiter							RE (H/T)			
21 A/F	Unknown Unknown	Cockpit					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Air Conditioning Non Return Valve							RE (O/C)			
21 A/F	Unknown Unknown	Left					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Air Conditioning Non Return Valve							RE (O/C)			
21 A/F	Unknown Unknown	Right					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Air Conditioning Valve							RE (O/C)			
21 A/F	BYLB50423-1 1124	Cabin					Mos	08-Nov-2018				
							Hrs					
							Ldg					
							Flt					
		Air Conditioning Valve							RE (O/C)			
21 A/F	Unknown Unknown	Cockpit					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Air Cooling Unit							RE (H/T)			
21 A/F	3500C01 333	Lower Serviceable					Mos	24-Sep-2024				
							Hrs	13,400.7				
							Ldg	9,055				
							Flt	9,055				
		Air Cooling Unit							RE (H/T)			
21 A/F	Unknown Unknown	Upper					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Airflow Sensor							RE (O/C)			
21 A/F	Unknown Unknown						Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Altimetric Switch							RE (O/C)			
21 A/F						Mos	31-Jul-2014				
4224ZR21						Hrs					
1427						Ldg					
						Flt					
	Baggage Compartment Isolation Valve							RE (O/C)			
21 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Baggage Compartment Positive And Negative Pressure Relief Valve							RE (O/C)			
21 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Baggage Compartment Positive And Negative Pressure Relief Valve							RE (O/C)			
21 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Baggage Compartment Supply Valve							RE (O/C)			
21 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Cabin Pressurization Controller							RE (O/C)			
21 A/F						Mos	23-Apr-2021				
22201D141700						Hrs					
246						Ldg					
						Flt					
	Cold Air Non Return Valve							RE (O/C)			
21 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Cold Air Non Return Valve							RE (O/C)			
21 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Cooling Turbine							RE (H/T)			
21 A/F	Lower					Mos	31-Jul-2014				
3176C01		6,926		52.5		Hrs					
437		4,627		23		Ldg					
						Flt					
	Cooling Turbine							RE (H/T)			
21 A/F	Upper					Mos	31-Jul-2014				
3176C01		6,926		52.5		Hrs					
194		4,627		23		Ldg					
						Flt					

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Dual Temperature Regulation Valve							RE (O/C)			
	21 A/F	Cabin					Mos	23-Apr-2021				
	BYLB-50418-12						Hrs					
	864						Ldg					
							Flt					
		Dual Temperature Regulation Valve							RE (O/C)			
	21 A/F	Cockpit					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Duct Temperature Probe							RE (O/C)			
	21 A/F	Cabin					Mos	23-Apr-2021				
	AYLF50425						Hrs					
	582						Ldg					
							Flt					
		Duct Temperature Probe							RE (O/C)			
	21 A/F	Cockpit					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ECU Thermostat							RE (O/C)			
	21 A/F	Upper					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Electrical Rack Blower							RE (O/C)			
	21 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Electrical Rack Blower							RE (O/C)			
	21 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Electropneumatic And Pneumatic Valves - Overpressure Relief Valve Vacuum Supply Lines							RE (O/C)			
	21 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Front Toilet Blower							RE (O/C)			
	21 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hot Air Non Return Valve							RE (O/C)			
	21 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Hot Air Non Return Valve							RE (O/C)			
	21 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Jet Pump							RE (O/C)			
	21 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Negative Pressure Relief Valve							RE (O/C)			
	21 A/F	Lower					Mos	31-Jul-2014				
	CYLB50416						Hrs					
	987						Ldg					
							Flt					
		Negative Pressure Relief Valve							RE (O/C)			
	21 A/F	Upper					Mos	31-Jul-2014				
	CYLB50416						Hrs					
	985						Ldg					
							Flt					
		Nicotine Filter							RE (O/C)			
	21 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Cone Blower							RE (O/C)			
	21 A/F						Mos	04-Apr-2015				
	EVT205D						Hrs					
	92						Ldg					
							Flt					
		Nose Cone Pressure Regulation Pneumatic Actuator							RE (O/C)			
	21 A/F						Mos	01-Apr-2021				
	7021-000						Hrs					
	175						Ldg					
							Flt					
		Nose Cone Pressure Relief Valve							RE (O/C)			
	21 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Cone Shut Off Valve							RE (O/C)			
	21 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Relay, A/C V Puls (16H1)							RE (O/C)			
	21 A/F	Cabin					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Relay, A/C V Puls (16H2)							RE (O/C)			
	21 A/F	Cockpit					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Stand-By Regulator							RE (O/C)			
	21 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Temperature Amplifier Probe							RE (O/C)			
	21 A/F	Cabin					Mos	03-Apr-2017				
	HYLZ-50514-013						Hrs					
	1740J						Ldg					
							Flt					
		Temperature Amplifier Probe							RE (O/C)			
	21 A/F	Cockpit					Mos	10-Sep-2008				
	HYLZ-50514-11						Hrs					
	490E						Ldg					
							Flt					
		Temperature Controller							RE (O/C)			
	21 A/F						Mos	03-Feb-2017				
	5897-651-8						Hrs					
	273						Ldg					
							Flt					
		Temperature Thermostat							RE (O/C)			
	21 A/F	Cabin					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Temperature Thermostat							RE (O/C)			
	21 A/F	Cockpit					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Triple Altitude/Differential Pressure Indicator							RE (O/C)			
	21 A/F						Mos	23-Apr-2021				
	15900-904						Hrs					
	728						Ldg					
							Flt					
2010-26-05		**Air Conditioning - Regulation Valve Overpressure Tightness Check**							RE (-)		Mandatory	
	21 A/F						Mos					
	Eff: 25-Jan-2011						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
2010-26-05 Paragraph (g) (Emerg)		**Air Conditioning - Emergency Pneumatic Regulation Valve Overpressure Tightness Check**							RE (-)		Mandatory	
	21 A/F						Mos					
	Eff: 25-Jan-2011						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
	Note: MANDATORY						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2010-26-05 Paragraph (g) (Main)	**Air Conditioning - Main Electro-Pneumatic Regulation Valve Overpressure Tightness Check**							RE (-)		Mandatory	
21 A/F						Mos					
Eff: 25-Jan-2011						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
Note: MANDATORY						Flt					
2010-26-05R1	**Air Conditioning - Regulation Valve Overpressure Tightness Check (This AD Terminates All Requirements)**							RE (-)		Mandatory	
21 A/F						Mos					
Eff: 06-Dec-2023						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
210100-0101	**Automatic Regulator Selector**							RE (O/C)			
21 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
210200-0101	**ECU Control Valve**							RE (O/C)			
21 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
21-20-01-350-801-01	**Restoration of the Flow Limiters (Overhaul) - LH Flow Limiter (L518H)**							RE		Comp Maint Ops (5-20)	**≈12-Apr-2028**
21 A/F	Cockpit					Mos	05-Nov-2005				
Unknown						Hrs	10,146.7	4,500	+3%	14,646.7	1,125.8 Hrs (+135)
Unknown						Ldg	7,155				
						Flt					
Note: P/N 2725F030100 (1)											
21-20-01-350-801-02	**Restoration of the Flow Limiters (Overhaul) - RH Flow Limiter (R518H)**							RE		Comp Maint Ops (5-20)	**≈12-Apr-2028**
21 A/F	Cabin					Mos	05-Nov-2005				
Unknown						Hrs	10,146.7	4,500	+3%	14,646.7	1,125.8 Hrs (+135)
Unknown						Ldg	7,155				
						Flt					
Note: P/N 2725F030100 (1)											
21-30-00-790-802-01	**In-Flight Check of Cabin Sealing**							RA		Acft Maint Ops (5-10)	**≈25-Jan-2027**
21 A/F						Mos	03-Jul-2003				
						Hrs	9,649.7				
						Ldg					
Note: Or procedure 21-30-00-790-801 (Ground check of cabin sealing). The second inspection is to be done at 10000 Flt.						Flt	6,820	3,000		9,820	687 Flt
21-30-00-790-802-01 (5-40)	**In-Flight Check of Cabin Sealing**							RA		AWL (5-40), CMR	**≈25-Jan-2027**
21 A/F						Mos	03-Jul-2003				
						Hrs	9,649.7				
Ref:21-080						Ldg					
Note: Or procedure 21-30-00-790-801 (Ground check of cabin sealing). The second inspection is to be done at 10000 Flt.						Flt	6,820	3,000		9,820	687 Flt
21-30-09-720-801-01	**Test Triple Altitude/Differential Pressure Indicator Altitude Alert**							RE (N/A)		Comp Maint Ops (5-20)	
21 A/F						Mos					
15900-904						Hrs					
728						Ldg					
						Flt					
Note: P/N 3311AJ68. except AC S/N 251											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
21-30-17-820-801-01		**Calibration of the Altimetric Switch - Altimetric Switch (150H)**							RE		Comp Maint Ops (5-20)	**≈05-Apr-2035**
21 A/F	4224ZR21 1427	Note: P/N 4224ZR21 (1) No tolerance					Mos	31-Jul-2014				
							Hrs	13,160.9	4,000		17,160.9	3,640 Hrs
							Ldg	8,909				
							Flt					
21-31-09-350-801-01		**Restoration of the Nose Cone Ventilation Fan (Replacement of Bearings) - Nose Cone Fan (83H)**							RE		Comp Maint Ops (5-20)	**≈04-Sep-2031**
21 A/F	EVT205D 92	Note: P/N EVT205D (1)					Mos	16-May-2015				
							Hrs	12,268.6	3,600	+3%	15,868.6	2,347.7 Hrs (+108)
							Ldg	8,399				
							Flt					
21-31-13-720-801-01		**Functional Test of the Nose Cone Pressure Regulation Pneumatic Actuator - Pneumatic Actuator**							RE		Acft Maint Ops (5-10)	
21 A/F	05-10-00-1C	(Tol. Adjustment: -225.9d)					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
							Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
21-31-13-720-801-02		**Functional Test of the Nose Cone Pressure Regulation Pneumatic Actuator - Nose Cone Pressure-Relief Valve**							RE		Acft Maint Ops (5-10)	
21 A/F	05-10-00-1C	(Tol. Adjustment: -225.9d)					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
							Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
21-31-25-220-801-01		**Check / Replacement of the Nose Cone Ventilation Fan Brushes - Nose Cone Fan (83H)**							RE		Comp Maint Ops (5-20)	**≈04-Sep-2031**
21 A/F	4224ZR21 1427						Mos	16-May-2015				
							Hrs	12,268.6	3,600	+3%	15,868.6	2,347.7 Hrs (+108)
							Ldg	8,399				
							Flt					
21-32-00-710-801-01		**Operational Test of the Cabin Pressurization System**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
21 A/F	05-10-00-1B						Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
							Flt	8,977				
21-32-00-710-801-01 (5-40)		**Operational Test of the Cabin Pressurization System**							RE		AWL (5-40), CMR	**≈12-Oct-2028**
21 A/F	Ref:21-100						Mos	14-Sep-2023				
							Hrs	13,276.7	1,550		14,826.7	1,305.8 Hrs
							Ldg	8,977				
							Flt	8,977				
21-32-00-790-801-01		**Leak Check Around the Static Pressure Probes - LH Static Pressure Probe (16F1)**							RE		Acft Maint Ops (5-10)	
21 A/F	05-10-00-24M	(Tol. Adjustment: -171d) Note: Specifc RVSM requirement					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
							Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
21-32-00-790-801-02		**Leak Check Around the Static Pressure Probes - RH Static Pressure Probe (16F2)**							RE		Acft Maint Ops (5-10)	
21 A/F	05-10-00-24M	(Tol. Adjustment: -171d) Note: Specifc RVSM requirement					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
							Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
21-32-06-200-801-01		**Inspection / Check of the Electropneumatic and Pneumatic Valves - Cleaning of Electropneumatic Valve (L74H)**							RE		Comp Maint Ops (5-20)	**≈12-Jan-2029**
21 A/F	2095A010100 104						Mos	14-Sep-2023				
							Hrs	13,276.7	1,640	+3%	14,916.7	1,395.8 Hrs (+49.2)
							Ldg	8,977				
							Flt	8,977				
		Note: P/N 2095A010100 or 2095A010400 or 2095D010100 or 2095D010400 or 2095K010900 or 2095K011000 or 2095L010900 or 2095L011000 More frequently if passengers are heavy smokers										
21-32-06-200-801-02		**Inspection / Check of the Electropneumatic and Pneumatic Valves - Cleaning of Pneumatic Valve (R74H)**							RE		Comp Maint Ops (5-20)	**≈12-Jan-2029**
21 A/F	2096B010500 151						Mos	14-Sep-2023				
							Hrs	13,276.7	1,640	+3%	14,916.7	1,395.8 Hrs (+49.2)
							Ldg	8,977				
							Flt	8,977				
		Note: P/N 2096B010200 or 2096B010500 or 2096E010200 or 2096E010500 or 2096L010900 or 2096L011000 or 2096M010900 or 2096M011000 or 2096T020900 or 2096T021000 or 2096U010200 or 2096U010500 or 2096V010900 or 2096V011000 or 2096Z020200 or 2096Z020500 More frequently if passengers are heavy smokers										
21-32-06-200-801-03		**Inspection / Check of the Electropneumatic and Pneumatic Valves - Check of Overpressure Tightness of Electropneumatic Valve (L74H)**							RE		Comp Maint Ops (5-20)	**≈12-Jan-2029**
21 A/F	2095A010100 104						Mos	14-Sep-2023				
							Hrs	13,276.7	1,640		14,916.7	1,395.8 Hrs
							Ldg	8,977				
							Flt	8,977				
		Note: P/N 2095A010100 or 2095A010400 or 2095D010100 or 2095D010400 or 2095K010900 or 2095K011000 or 2095L010900 or 2095L011000 For valves having already undergone the cleaning operation at the date of Dec. 2006 (TR4 after Reissue 4), the overpressure check operation is due at the next 1640 FH. No tolerance										
21-32-06-200-801-03 (5-40)		**Inspection / Check of the Electropneumatic and Pneumatic Valves - Check of Overpressure Tightness of Electropneumatic Valve (L74H)**							RE		AWL (5-40), CMR	**≈12-Jan-2029**
21 A/F	2095A010100 104						Mos	14-Sep-2023				
							Hrs	13,276.7	1,640		14,916.7	1,395.8 Hrs
							Ldg	8,977				
							Flt	8,977				
		Note: P/N 2095A010100 or 2095A010400 or 2095D010100 or 2095D010400 or 2095K010900 or 2095K011000 or 2095L010900 or 2095L011000 For valves having already undergone the cleaning operation at the date of Dec. 2006 (TR4 after Reissue 4), the overpressure check operation is due at the next 1640 FH. No tolerance										
21-32-06-200-801-04		**Inspection / Check of the Electropneumatic and Pneumatic Valves - Check of Overpressure Tightness of Pneumatic Valve (R74H)**							RE		Comp Maint Ops (5-20)	**≈12-Jan-2029**
21 A/F	2096B010500 151						Mos	14-Sep-2023				
							Hrs	13,276.7	1,640		14,916.7	1,395.8 Hrs
							Ldg	8,977				
							Flt	8,977				
		Note: P/N 2096B010200 or 2096B010500 or 2096E010200 or 2096E010500 or 2096L010900 or 2096L011000 or 2096M010900 or 2096M011000 or 2096T020900 or 2096T021000 or 2096U010200 or 2096U010500 or 2096V010900 or 2096V011000 or 2096Z020200 or 2096Z020500 For valves having already undergone the cleaning operation at the date of Dec. 2006 (TR4 after Reissue 4), the overpressure check operation is due at the next 1640 FH. No tolerance										
21-32-06-200-801-04 (5-40)		**Inspection / Check of the Electropneumatic and Pneumatic Valves - Check of Overpressure Tightness of Pneumatic Valve (R74H)**							RE		AWL (5-40), CMR	**≈12-Jan-2029**
21 A/F	2096B010500 151						Mos	14-Sep-2023				
							Hrs	13,276.7	1,640		14,916.7	1,395.8 Hrs
							Ldg	8,977				
							Flt	8,977				
		Note: P/N 2096B010200 or 2096B010500 or 2096E010200 or 2096E010500 or 2096L010900 or 2096L011000 or 2096M010900 or 2096M011000 or 2096T020900 or 2096T021000 or 2096U010200 or 2096U010500 or 2096V010900 or 2096V011000 or 2096Z020200 or 2096Z020500 For valves having already undergone the cleaning operation at the date of Dec. 2006 (TR4 after Reissue 4), the overpressure check operation is due at the next 1640 FH. No tolerance										

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
21-32-06-200-801-05	**Inspection / Check of the Electropneumatic and Pneumatic Valves - Check of Overpressure Relief Valve Vacuum Supply Lines (975HP) and (976HP)**							RE		Comp Maint Ops (5-20)	**≈16-Mar-2039**
21 A/F						Mos	11-Feb-2009				
						Hrs	11,082.1	7,500		18,582.1	5,061.2 Hrs
						Ldg	7,729				
Note: P/N F50B722401 or F50B722403						Flt					
No tolerance											
21-32-06-200-801-05 (5-40)	**Inspection / Check of the Electropneumatic and Pneumatic Valves - Check of Overpressure Relief Valve Vacuum Supply Lines (975HP) and (976HP)**							RE		AWL (5-40), CMR	**≈16-Mar-2039**
21 A/F						Mos	11-Feb-2009				
						Hrs	11,082.1	7,500		18,582.1	5,061.2 Hrs
Ref:21-160						Ldg	7,729				
Note: P/N F50B722401 or F50B722403						Flt					
No tolerance											
21-32-06-720-801-01	**Functional Test of the Electropneumatic and Pneumatic Valves - Electropneumatic Valve (L74H)**							RE		Comp Maint Ops (5-20)	**≈21-Dec-2036**
21 A/F						Mos	14-Sep-2023				
2095A010100						Hrs	13,276.7	4,500	+3%	17,776.7	4,255.8 Hrs (+135)
104						Ldg	8,977				
						Flt	8,977				
Note: P/N 2095A010100 or 2095A010400 or 2095D010100 or 2095D010400 or 2095K010900 or 2095K011000 or 2095L010900 or 2095L011000											
(1)											
21-32-06-720-801-01 (5-40)	**Functional Test of the Electropneumatic and Pneumatic Valves - Electropneumatic Valve (L74H)**							RE		AWL (5-40), CMR	**≈10-May-2038**
21 A/F						Mos	14-Sep-2023				
2095A010100						Hrs	13,276.7	5,000		18,276.7	4,755.8 Hrs
104						Ldg	8,977				
						Flt	8,977				
Note: P/N 2095A010100 or 2095A010400 or 2095D010100 or 2095D010400 or 2095K010900 or 2095K011000 or 2095L010900 or 2095L011000											
(1)											
21-32-06-720-801-02	**Functional Test of the Electropneumatic and Pneumatic Valves - Pneumatic Valve (R74H)**							RE		Comp Maint Ops (5-20)	**≈21-Dec-2036**
21 A/F						Mos	14-Sep-2023				
2096B010500						Hrs	13,276.7	4,500	+3%	17,776.7	4,255.8 Hrs (+135)
151						Ldg	8,977				
						Flt	8,977				
Note: P/N 2096B010200 or 2096B010500 or 2096E010200 or 2096E010500 or 2096L010900 or 2096L011000 or 2096M010900 or 2096M011000 or 2096T020900 or 2096T021000 or 2096U010200 or 2096U010500 or 2096V010900 or 2096V011000 or 2096Z020200 or 2096Z020500 (1)											
21-32-06-720-801-02 (5-40)	**Functional Test of the Electropneumatic and Pneumatic Valves - Pneumatic Valve (R74H)**							RE		AWL (5-40), CMR	**≈10-May-2038**
21 A/F						Mos	14-Sep-2023				
2096B010500						Hrs	13,276.7	5,000		18,276.7	4,755.8 Hrs
151						Ldg	8,977				
						Flt	8,977				
Note: P/N 2096B010200 or 2096B010500 or 2096E010200 or 2096E010500 or 2096L010900 or 2096L011000 or 2096M010900 or 2096M011000 or 2096T020900 or 2096T021000 or 2096U010200 or 2096U010500 or 2096V010900 or 2096V011000 or 2096Z020200 or 2096Z020500 (1)											
21-32-06-720-802-01	**Functional Test of the Cabin Altitude Limitation - Electropneumatic Valve (L74H)**							RE		Acft Maint Ops (5-10)	
21 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: To be done at the beginning of the C inspection						Flt	8,977				
21-32-06-720-802-02	**Functional Test of the Cabin Altitude Limitation - Pneumatic Valve (R74H)**							RE		Acft Maint Ops (5-10)	
21 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: To be done at the beginning of the C inspection						Flt	8,977				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
21-32-06-900-801-01	**ELECTROPNEUMATIC VALVE (L74H)**							RE (O/C)			
21 A/F						Mos	14-Sep-2023				
2095A010100	Repaired				0	Hrs	13,276.7				
104					0	Ldg	8,977				
					0	Flt	8,977				
21-32-06-900-802-01	**PNEUMATIC VALVE (R74H)**							RE (O/C)			
21 A/F						Mos	14-Sep-2023				
2096B010500	Repaired				0	Hrs	13,276.7				
151					0	Ldg	8,977				
					0	Flt	8,977				
21-32-17-720-801-01	**Functional Test of the Baggage Compartment Pressure Relief Valves - LH Positive and Negative Pressure Relief Valve (L536H)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
21 A/F	05-10-00-2B					Mos	02-Sep-2016				
						Hrs	12,978.6	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					
21-32-17-720-801-01 (5-40)	**Functional Test of the Baggage Compartment Pressure Relief Valves - LH Positive and Negative Pressure Relief Valve (L536H)**							RE		AWL (5-40), CMR	**≈03-Dec-2033**
21 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	3,700		16,678.6	3,157.7 Hrs
						Ldg	8,785				
						Flt					
21-32-17-720-801-02	**Functional Test of the Baggage Compartment Pressure Relief Valves - RH Positive and Negative Pressure Relief Valve (R536H)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
21 A/F	05-10-00-2B					Mos	02-Sep-2016				
						Hrs	12,978.6	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					
21-32-17-720-801-02 (5-40)	**Functional Test of the Baggage Compartment Pressure Relief Valves - RH Positive and Negative Pressure Relief Valve (R536H)**							RE		AWL (5-40), CMR	**≈03-Dec-2033**
21 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	3,700		16,678.6	3,157.7 Hrs
						Ldg	8,785				
						Flt					
21-32-33-710-801-01	**Operational Test of the Baggage Compartment Isolation and Supply Valves - Baggage Compartment Isolation Valve (153H)**							RE		Acft Maint Ops (5-10)	**≈06-Aug-2025**
21 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	600	+30	13,679.2	158.3 Hrs (+30)
						Ldg	8,836				
						Flt					
21-32-33-710-801-01 (5-40)	**Operational Test of the Baggage Compartment Isolation and Supply Valves - Baggage Compartment Isolation Valve (153H)**							RE		AWL (5-40), CMR	**≈26-Sep-2025**
21 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	650		13,729.2	208.3 Hrs
Ref:21-010						Ldg	8,836				
						Flt					
21-32-33-710-801-02	**Operational Test of the Baggage Compartment Isolation and Supply Valves - Baggage Compartment Hot Air Supply Valve (154H)**							RE		Acft Maint Ops (5-10)	**≈06-Aug-2025**
21 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	600	+30	13,679.2	158.3 Hrs (+30)
						Ldg	8,836				
						Flt					
21-32-33-710-801-02 (5-40)	**Operational Test of the Baggage Compartment Isolation and Supply Valves - Baggage Compartment Hot Air Supply Valve (154H)**							RE		AWL (5-40), CMR	**≈26-Sep-2025**
21 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	650		13,729.2	208.3 Hrs
Ref:21-010						Ldg	8,836				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
21-32-38-710-801-01	**Operational Test of the Cabin Negative Pressure Relief Valves - Upper Negative Pressure Relief Valve (977HP)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
21 A/F	Upper05-10-00-2B					Mos	02-Sep-2016				
CYLB50416						Hrs	12,978.6	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
985						Ldg	8,785				
						Flt					
Note: A/C 001-060											
21-32-38-710-801-02	**Operational Test of the Cabin Negative Pressure Relief Valves - Lower Negative Pressure Relief Valve (978HP)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
21 A/F	Lower05-10-00-2B					Mos	02-Sep-2016				
CYLB50416						Hrs	12,978.6	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
987						Ldg	8,785				
						Flt					
Note: A/C 001-060											
21-32-38-820-801-01	**Calibration of the Cabin Negative Pressure Relief Valves - Upper Negative Pressure Relief Valve (977HP)**							RE		Comp Maint Ops (5-20)	**≈11-Jun-2031**
21 A/F	Upper					Mos	31-Jul-2014				
CYLB50416						Hrs	11,785.6	4,000		15,785.6	2,264.7 Hrs
985						Ldg	8,159				
						Flt					
Note: P/N CYLB50416 A/C 001-060 (1) No tolerance											
21-32-38-820-801-02	**Calibration of the Cabin Negative Pressure Relief Valves - Lower Negative Pressure Relief Valve (978HP)**							RE		Comp Maint Ops (5-20)	**≈11-Jun-2031**
21 A/F	Lower					Mos	31-Jul-2014				
CYLB50416						Hrs	11,785.6	4,000	+3%	15,785.6	2,264.7 Hrs (+120)
987						Ldg	8,159				
						Flt					
Note: P/N CYLB50416 A/C 001-060 (1) No tolerance											
21-32-41-200-801-01	**Inspection of the Nicotine Filter Cartridge - Nicotine Filter (534H)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
21 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
Note: more often if necessary						Flt	8,977				
21-51-29-720-801-01	**Functional Test of the Lower Cooling Unit Air Intake Door**							RE		Acft Maint Ops (5-10)	
21 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
21-51-30-640-801-01	**Lubrication of the Lower Cooling Unit Air Intake Door Control Cable**							RE		Acft Maint Ops (5-10)	
21 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
21-52-01-350-801-01	**Restoration of the Cooling Units (Overhaul) - Upper Cooling Unit (R519H)**							RE		Comp Maint Ops (5-20)	**≈11-Jun-2031**
21 A/F	Upper					Mos	31-Jul-2014				
Unknown						Hrs	11,785.6	4,000	+3%	15,785.6	2,264.7 Hrs (+120)
Unknown						Ldg	8,159				
						Flt					
Note: P/N 3500C01 (1) No tolerance More frequently if humid climate, intensive use of APU, dusty runway											

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
21-52-01-350-801-02	**Restoration of the Cooling Units (Overhaul) - Lower Cooling Unit (L519H)**							RE		Comp Maint Ops (5-20)	**≈05-Dec-2035**
21 A/F	Lower					Mos	24-Sep-2024				
3500C01						Hrs	13,400.7	4,000	+3%	17,400.7	3,879.8 Hrs (+120)
333						Ldg	9,055				
						Flt	9,055				
Note: P/N 3500C01											
(1) No tolerance											
More frequently if humid climate, intensive use of APU, dusty runway											
21-52-05-350-801-01	**Restoration of the Turbocooler (Overhaul) - Upper Turbocooler (R544H)**							RE		Comp Maint Ops (5-20)	**≈11-Jun-2031**
21 A/F	Upper					Mos	31-Jul-2014				
3176C01						Hrs	11,785.6	4,000	+3%	15,785.6	2,264.7 Hrs (+120)
194						Ldg	8,159				
						Flt					
Note: P/N 3176C01											
(1)											
21-52-05-350-801-02	**Restoration of the Turbocooler (Overhaul) - Lower Turbocooler (L544H)**							RE		Comp Maint Ops (5-20)	**≈05-Jul-2025**
21 A/F	Lower					Mos	06-Dec-2002				
3176C01						Hrs	9,648.1	4,000	+3%	13,648.1	127.2 Hrs (+120)
437						Ldg					
						Flt					
Note: P/N 3176C01											
(1)											
21-52-05-610-801-01	**Turbocooler Oil Servicing - Lower Turbocooler (L544H)**							RE		Acft Maint Ops (5-10)	**≈06-Aug-2025**
21 A/F	Lower					Mos	16-Sep-2018				
3176C01						Hrs	13,079.2	600	+30	13,679.2	158.3 Hrs (+30)
437						Ldg	8,836				
						Flt					
Note: More frequently if APU is used intensively											
21-52-05-610-801-02	**Turbocooler Oil Servicing - Upper Turbocooler (R544H)**							RE		Acft Maint Ops (5-10)	**≈06-Aug-2025**
21 A/F	Upper					Mos	16-Sep-2018				
3176C01						Hrs	13,079.2	600	+30	13,679.2	158.3 Hrs (+30)
194						Ldg	8,836				
						Flt					
Note: More frequently if APU is used intensively											
21-52-05-700-801-01	**Turbocooler Oil Level Check - Lower Turbocooler (L544H)**							RE		Acft Maint Ops (5-10)	**≈10-Jul-2025**
21 A/F	Lower					Mos	06-Dec-2024				
3176C01						Hrs	13,453.3	200	+10%	13,653.3	132.4 Hrs (+20)
437						Ldg	9,091				
						Flt	9,091				
21-52-05-700-801-02	**Turbocooler Oil Level Check - Upper Turbocooler (R544H)**							RE		Acft Maint Ops (5-10)	**≈10-Jul-2025**
21 A/F	Upper					Mos	06-Dec-2024				
3176C01						Hrs	13,453.3	200	+10%	13,653.3	132.4 Hrs (+20)
194						Ldg	9,091				
						Flt	9,091				
F50-005	**Baggage compartment pressurization and isolation valves added indicating light**							RE (-)			
21 A/F						Mos					
Eff: 14-Jan-1980						Hrs					
						Ldg					
Note: M0027						Flt					
F50-018	**Improved cabin temperature control system**							RE (-)			
21 A/F						Mos					
						Hrs					
						Ldg					
Note: M0072						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-018 R1	**Improved cabin temperature control system**							RE (-)			
21 A/F						Mos					
Eff: 15-May-1981						Hrs					
						Ldg					
Note: M0072						Flt					
F50-022	**Relocation of the cockpit temperature control duct probe and new pilot foot gasper**							RE (-)			
21 A/F						Mos					
Eff: 29-Oct-1979						Hrs					
						Ldg					
Note: M0099, M0080						Flt					
F50-025	**Improved cabin pressure controller**							RE (-)			
21 A/F						Mos					
Eff: 14-Nov-1979						Hrs					
						Ldg					
						Flt					
F50-026	**Addition of a ball valve on the air vent**							RE (-)			
21 A/F						Mos					
Eff: 27-Sep-1979						Hrs					
						Ldg					
						Flt					
F50-043	**Nose cone ventilation - Fan supplied even when the airplane is on jacks**							T (A/R)			
21 A/F						Mos					
Eff: 29-Nov-1979						Hrs					
						Ldg					
Note: M0265						Flt					
F50-045	**Cockpit Air Conditioning - Installation of a thermostat with an increased setting**							RE (-)			
21 A/F						Mos					
Eff: 17-Dec-1979						Hrs					
						Ldg					
Note: M0099B						Flt					
F50-050	**Air conditioning - Pipes made with unsuitable resine replaced**							RE (-)			
21 A/F						Mos					
Eff: 12-Feb-1980						Hrs					
						Ldg					
Note: M0375						Flt					
F50-099	**New installation of cold air ducts at frame 28**							T (A/R)			
21 A/F						Mos					
Eff: 29-Jun-1982						Hrs					
						Ldg					
Note: M0783A, M0783B						Flt					
F50-164	**Pressurization - Outflow valve identification plate**							RE (-)			
21 A/F						Mos					
Eff: 02-Apr-1985						Hrs					
						Ldg					
Note: M1289						Flt					
F50-237	**Improved temperature regulation in the cockpit**							RE (-)			
21 A/F						Mos					
Eff: 09-Nov-1994						Hrs					
						Ldg					
Note: M1823						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-258	**Installation of an emergency pneumatic valve fitted with a closing electric valve**							T (A/R)			
21 A/F						Mos					
Eff: 17-May-2000						Hrs					
						Ldg					
Note: M2039, M2137						Flt					
F50-337	**Forced grounding of the torque motor of the automatic pressurization selector in the "dump" mode**							T (A/R)			
21 A/F						Mos					
Eff: 15-Jan-2003						Hrs					
						Ldg					
Note: M2693, M2615, A/C equipped with a pressurization controller 22201N061000 OR 22201D131700						Flt					
F50-360	**Pressurization - Installation of an improved automatic selector**							T (A/R)			
21 A/F						Mos					
Eff: 30-Oct-2003						Hrs					
						Ldg					
Note: M2693, M2615						Flt					
F50-386	**Air flow regulation in cockpit**							RE (-)			
21 A/F						Mos					
Eff: 10-Apr-2002						Hrs					
						Ldg					
Note: M2656, 283 to 286, 288, 290, 292 to 294, 296, 298, 299 with M2000						Flt					
F50-435	**Interference between a flight control system rod and an air conditioning duct**							T (A/R)			
21 A/F						Mos					
Eff: 11-Jun-2004						Hrs					
						Ldg					
Note: M2895						Flt					
F50-444	**Baggage compartment ventilation and air conditioning - Increased hot air flow and improved insulation**							RE (-)			
21 A/F						Mos					
						Hrs					
						Ldg					
Note: M2754, M2821						Flt					
F50-444 R1	**Baggage compartment ventilation and air conditioning - Increased hot air flow and improved insulation**							RE (-)			
21 A/F						Mos					
Eff: 12-Jul-2006						Hrs					
						Ldg					
Note: M2754, M2821						Flt					
F50-470	**Modifying the clamping of an air conditioning hose to prevent interference with a flight control linkage rod**							RE (-)			
21 A/F						Mos	12-Apr-2010				
Eff: 13-Apr-2006 Not Applicable	by PN					Hrs					
						Ldg					
Note: M2995						Flt					
▼ 22 - AUTOFLIGHT											
	Flight Guidance Computer							RE (O/C)			
22 A/F	No.2					Mos	29-Sep-2023				
622-5224	Serviceable					Hrs	13,277.7				
25183						Ldg	8,978				
						Flt	8,978				
	Aileron Autopilot Servomotor							RE (O/C)			
22 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Aileron Servomotor Capstan							RE (O/C)			
22 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Autopilot Amplifier							RE (O/C)			
22 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Autopilot Computer							RE (O/C)			
22 A/F		Copilot					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Autopilot Computer							RE (O/C)			
22 A/F		Pilot					Mos	18-Jun-2021				
622-4964-001							Hrs					
1209							Ldg					
							Flt					
		Autopilot Control Panel							RE (O/C)			
22 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Autopilot Control Panel							RE (O/C)			
22 A/F		No.2					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Autopilot Mode Selector							RE (O/C)			
22 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Autopilot Pitch Servo Cable							RE (O/C)			
22 A/F		Pilot					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Autopilot Roll Servo Cable							RE (O/C)			
22 A/F		Pilot					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Autopilot Yaw Computer							RE (O/C)			
22 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Autopilot Yaw Servo Cable							RE (O/C)			
	22 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Elevator Autopilot Servomotor							RE (O/C)			
	22 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Elevator Servomotor Capstan							RE (O/C)			
	22 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Guidance Computer							RE (O/C)			
	22 A/F	No.1					Mos	18-Jun-2021				
	622-5224-001						Hrs					
	4217						Ldg					
							Flt					
		Mach Trim Unit							RE (O/C)			
	22 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Print Attenuat Card							RE (O/C)			
	22 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rate of Yaw Gyro							RE (O/C)			
	22 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rudder Autopilot Servomotor							RE (O/C)			
	22 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rudder Servomotor Capstan							RE (O/C)			
	22 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Yaw Damper Actuator							RE (O/C)			
	22 A/F						Mos	12-Dec-2015				
	622-3167-099						Hrs	12,581.8				
	3462						Ldg	8,597				
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2002-22-13	**Rockwell Collins, Inc. - Flight management computers (FMC)**							RE (-)		Mandatory (Appliance AD)	
22 A/F						Mos	14-Sep-2003				
Eff: 20-Dec-2002 Not Applicable	by manufacturer					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
220100-0101	**Autopilot Pitch Servo**							RE (O/C)			
22 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
220200-0101	**Autopilot Roll Servo**							RE (O/C)			
22 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
220300-0101	**Autopilot Yaw Servo**							RE (O/C)			
22 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
22-10-00-700-801-01	**Check of the AP / FD System Disengagement Protections**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
22 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
Note: A/C with APS80 (option 22-10-01, 22-12-01 or 22-14-01)						Flt	8,977				
22-10-00-710-801-01	**Operational Test of the Automatic Flight Control System (AFCS)**							RE		Acft Maint Ops (5-10)	
22 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: also RVSM requirement						Ldg	8,977				
Cat II validation						Flt	8,977				
22-10-05-720-801-01	**FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - AILERON SERVOMOTOR (4CA or 210CA)**							RE		Acft Maint Ops (5-10)	
22 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+2m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
(SOURCE: Falcon 50/50EX MPD)						Ldg	8,785				
Note: A/C with APS 80: (4CA).						Flt					
A/C with APS 85: (4CA).											
A/C with PROLINE 4 avionics (M1924): (210CA).											
22-10-05-720-801-02	**FUNCTIONAL TEST OF THE AUTOPILOT SERVOMOTORS - ELEVATOR SERVOMOTOR (5CA or 211CA)**							RE		Acft Maint Ops (5-10)	
22 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+2m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
(SOURCE: Falcon 50/50EX MPD (DGT 125296) (DGT 125297))						Ldg	8,785				
Note: A/C with APS 80: (5CA).						Flt					
A/C with APS 85: (5CA).											
A/C with PROLINE 4 avionics (M1924): (211CA).											
22-10-07-700-801-01	**Check of the Autopilot Servomotor Cables and Pulleys - Aileron**							RE		Acft Maint Ops (5-10)	
22 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: also RVSM requirement						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
22-10-07-700-801-02	**Check of the Autopilot Servomotor Cables and Pulleys - Elevator**							RE		Acft Maint Ops (5-10)	
22 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
	Note: also RVSM requirement					Ldg	8,977				
						Flt	8,977				
22-10-07-700-801-03	**Check of the Autopilot Servomotor Cables and Pulleys - Rudder**							RE		Acft Maint Ops (5-10)	
22 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
	Note: also RVSM requirement.					Ldg	8,977				
	A/C with APS 80					Flt	8,977				
22-10-13-700-801-01	**Check / Adjustment of the Autopilot Servomotor Capstan Slip Torque - Aileron Servomotor Capstan (502CA)**							RE (N/A)		Comp Maint Ops (5-20)	
22 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
22-10-13-700-801-02	**Check / Adjustment of the Autopilot Servomotor Capstan Slip Torque - Elevator Servomotor Capstan (503CA)**							RE (N/A)		Comp Maint Ops (5-20)	
22 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
22-10-13-720-801-01	**Restoration of the Autopilot Servomotor Capstan (Functional Test) - Aileron Servomotor Capstan (502CA)**							RE		Comp Maint Ops (5-20)	**≈08-Mar-2042**
22 A/F						Mos	26-Sep-2003				
Unknown						Hrs	9,656.1	10,000	+3%	19,656.1	6,135.2 Hrs (+300)
Unknown						Ldg	6,824				
						Flt					
	Note: P/N 792-6784-001										
	(1)										
22-10-13-720-801-02	**Restoration of the Autopilot Servomotor Capstan (Functional Test) - Elevator Servomotor Capstan (503CA)**							RE		Comp Maint Ops (5-20)	**≈08-Mar-2042**
22 A/F						Mos	26-Sep-2003				
Unknown						Hrs	9,656.1	10,000	+3%	19,656.1	6,135.2 Hrs (+300)
Unknown						Ldg	6,824				
						Flt					
	Note: P/N 792-6784-001										
	(1)										
22-10-13-720-801-03	**Restoration of the Autopilot Servomotor Capstan (Functional Test) - Rudder Servomotor Capstan (504CA)**							RE		Comp Maint Ops (5-20)	**≈08-Mar-2042**
22 A/F						Mos	26-Sep-2003				
Unknown						Hrs	9,656.1	10,000	+3%	19,656.1	6,135.2 Hrs (+300)
Unknown						Ldg	6,824				
						Flt					
	Note: P/N 792-6785-001										
	(1)										
22-13-01-350-801-01	**Restoration of the Yaw Damper Actuator (Overhaul) - Yaw Damper Linear Actuator (220CA) or (2CJ)**							RE (N/A)		Comp Maint Ops (5-20)	
22 A/F						Mos					
622-3167-099						Hrs					
3462						Ldg					
						Flt					
22-13-01-350-801-01 (5-40)	**Restoration of the Yaw Damper Actuator (Overhaul) - Yaw Damper Linear Actuator (220CA) or (2CJ)**							RE (N/A)		AWL (5-40), CMR	
22 A/F						Mos					
622-3167-099						Hrs					
3462						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
22-15-00-720-801-01	**Functional Test of Mach Trim**							RE (-)			
22 A/F						Mos	16-Sep-2018				
						Hrs					
						Ldg					
						Flt					
F50-010	**Collins FCS 80 autopilot use in CAT II approaches**							T (A/R)			
22 A/F						Mos					
Eff: 02-Mar-1984						Hrs					
						Ldg					
Note: M0058, A/C with a FCS 80 autopilot CAT 1 approaches						Flt					
F50-052	**Comparator activated after G/S capture - Cross over of ILS 1 and ILS 2 information - Marking of "MASTER" light modified**							RE (-)			
22 A/F						Mos					
						Hrs					
						Ldg					
Note: M0188						Flt					
F50-052 R1	**Comparator activated after G/S capture - Cross over of ILS 1 and ILS 2 information - Marking of "MASTER" light modified**							RE (-)			
22 A/F						Mos					
						Hrs					
						Ldg					
Note: M0188						Flt					
F50-052 R2	**Comparator activated after G/S capture - Cross over of ILS 1 and ILS 2 information - Marking of "MASTER" light modified**							RE (-)			
22 A/F						Mos					
Eff: 06-Jan-1984						Hrs					
						Ldg					
Note: M0188						Flt					
F50-053	**Autopilot controller - Improvement of power supply monitoring**							RE (-)			
22 A/F						Mos					
Eff: 29-Aug-1980						Hrs					
						Ldg					
Note: M0232						Flt					
F50-054	**Flight directors - Improved tracking of the glideslope**							RE (-)			
22 A/F						Mos					
Eff: 29-Aug-1980						Hrs					
						Ldg					
Note: M0270, 3 to 11 with COLLINS FGC 80 FD						Flt					
F50-079	**Possibility of installing a SPERRY Autopilot**							RE (-)			
22 A/F						Mos					
						Hrs					
						Ldg					
Note: M0241, 1 to 17, 19 to 27, 29 to 79 and A/C in which a SPERRY autopilot is to be installed						Flt					
F50-079 R1	**Possibility of installing a SPERRY Autopilot**							T (A/R)			
22 A/F						Mos					
Eff: 07-Nov-1980						Hrs					
						Ldg					
Note: M0241, 1 to 17, 19 to 27, 29 to 79 and A/C in which a SPERRY autopilot is to be installed						Flt					
F50-546	**Auto Flight - Automatic Flight Control System (AFCS) - Replacement of the Auto Pilot Servomotor Cables**							RE (-)		Optional	
22 A/F						Mos					
Eff: 13-Jun-2019						Hrs					
(AVG MAN HRS: 14.5)						Ldg					
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-546-1		**Auto Flight - Automatic Flight Control System (AFCS) - Replacement of the Auto Pilot Servomotor Cables - Removing and Discarding Aileron Servomotor Cables (P/N 59309) Manufactured by SKF, Installing New Aileron Servomotor Cables (P/N 30-1654) Manufactured by JACOTTET**							T (A/R)		Optional	
22 A/F							Mos					
Eff: 13-Jun-2019							Hrs					
(AVG MAN HRS: 5.5)							Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to aircraft equipped with APS 80.							Flt					
F50-546-2		**Auto Flight - Automatic Flight Control System (AFCS) - Replacement of the Auto Pilot Servomotor Cables - Removing and Discarding Yaw Servomotor Cables (P/N 59303) Manufactured by SKF, Installing New Yaw Servomotor Cables (P/N 30-1655) Manufactured by JACOTTET**							T (A/R)		Optional	
22 A/F							Mos					
Eff: 13-Jun-2019							Hrs					
(AVG MAN HRS: 4.5)							Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to aircraft equipped with APS 80.							Flt					
F50-546-3		**Auto Flight - Automatic Flight Control System (AFCS) - Replacement of the Auto Pilot Servomotor Cables - Removing and Discarding Pitch Servomotor Cables (P/N 59304) manufactured by SKF, Installing New Pitch Servomotor Cables (P/N 30-1656) Manufactured by JACOTTET**							T (A/R)		Optional	
22 A/F							Mos					
Eff: 13-Jun-2019							Hrs					
(AVG MAN HRS: 4.5)							Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to aircraft equipped with APS 80.							Flt					
▼ 23 - COMMUNICATIONS												
		Alto Audio Amplifier							RE (O/C)			
23 A/F							Mos	29-Sep-2023				
106500-0250-00010		New	0				Hrs	13,277.7				
260025			0				Ldg	8,978				
			0				Flt	8,978				
		BT Inline Relay							RE (O/C)			
23 A/F							Mos	29-Sep-2023				
107830-1051-00010		New	0				Hrs	13,277.7				
800058			0				Ldg	8,978				
			0				Flt	8,978				
		Gogo Avance L3							RE (O/C)			
23 A/F							Mos	29-Sep-2023				
P34110-003		New	0				Hrs	13,277.7				
34110003297SE			0				Ldg	8,978				
			0				Flt	8,978				
		Aircell Dual Patch Antenna							RE (O/C)			
23 A/F							Mos	14-Sep-2005				
015-11203-001							Hrs					
Unknown							Ldg					
							Flt					
		Audio Control Panel							RE (O/C)			
23 A/F		No.1					Mos	09-May-2015				
M1045-FBAA-HJF7							Hrs					
821268							Ldg					
							Flt					
		Audio Control Panel							RE (O/C)			
23 A/F		No.2					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Communication Management Unit							RE (O/C)			
	23 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Datalink Satcom DL-150							RE (O/C)			
	23 A/F						Mos	29-Sep-2023				
	DL150-00	New		0			Hrs	13,277.7				
	MAN-2802			0			Ldg	8,978				
				0			Flt	8,978				
		Dual HF1/HF2 Rack							RE (O/C)			
	23 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flitefone Antenna							RE (O/C)			
	23 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flitefone Transceiver							RE (O/C)			
	23 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flitefone Transceiver							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		HF Amplifier Coupler							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		HF Amplifier Coupler							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		HF Antenna							RE (O/C)			
	23 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		HF Condenser							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		HF Condenser							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		HF Control							RE (O/C)			
	23 A/F	No.1					Mos	26-Sep-2014				
	622-4093-002						Hrs					
	1021						Ldg					
							Flt					
		HF Control							RE (O/C)			
	23 A/F	No.2					Mos	26-Sep-2014				
	622-4093-002						Hrs					
	646						Ldg					
							Flt					
		HF Transceiver							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		HF Transceiver							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nav Control							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nav Control							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		PA (Baker) Amplifier							RE (O/C)			
	23 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Public Address (Team) Amplifier							RE (O/C)			
	23 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radio Selector Box							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Radio Selector Box							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Selcal Decoder							RE (O/C)			
	23 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Subwoofer Speaker							RE (O/C)			
	23 A/F	No.1					Mos	29-Sep-2023				
	106511-514-4A0001	New	0				Hrs	13,277.7				
	150811		0				Ldg	8,978				
			0				Flt	8,978				
		Subwoofer Speaker							RE (O/C)			
	23 A/F	No.2					Mos	29-Sep-2023				
	106511-514-4A0001	New	0				Hrs	13,277.7				
	150812		0				Ldg	8,978				
			0				Flt	8,978				
		Universal Unilink 801							RE (O/C)			
	23 A/F						Mos	29-Sep-2023				
	10801-01	New	0				Hrs	13,277.7				
	0850		0				Ldg	8,978				
			0				Flt	8,978				
		VHF Antenna							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF Antenna							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF Antenna							RE (O/C)			
	23 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF Control							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF Control							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		VHF Control							RE (O/C)			
	23 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF Transceiver							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF Transceiver							RE (O/C)			
	23 A/F	No.2					Mos	23-Oct-2012				
	822-1112-001						Hrs					
	5253						Ldg					
							Flt					
		VHF Transceiver							RE (O/C)			
	23 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Xmitter HF Rack							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Xmitter HF Rack							RE (O/C)			
	23 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
230028-0101		**Bluetooth Receiver**							RE (O/C)			
	23 A/F						Mos	29-Sep-2023				
	107840-0300-000012	New		0			Hrs	13,277.7				
	600116			0			Ldg	8,978				
				0			Flt	8,978				
232A51		**Airshow 500 Unit**							RE (O/C)			
	23 A/F						Mos	21-May-2024				
	441-1333-100	Tested/Inspected					Hrs	13,302.5				
	500T0622						Ldg	8,998				
	Brand C::231B60						Flt	8,998				
23-60-00-760-801-01		**Visual Inspection and Electrical Bonding Check of the Static Dischargers**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
	23 A/F	05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
							Flt	8,977				
23-81-01-900-801-01		**(RTU) Radio Tuning Unit**							RE (O/C)			
	23 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
23-81-01-900-801-02	**(RTU) Radio Tuning Unit**							RE (O/C)			
23 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
F50-041	**Relocation of the aft cone static discharger**							RE (-)			
23 A/F						Mos					
Eff: 29-Nov-1979						Hrs					
						Ldg					
Note: M0128						Flt					
F50-257 R2	**Satellite Communication - Fin Tip Antenna Installation Capability**							T (A/R)		Optional	
23 A/F						Mos					
Eff: 26-Aug-2016						Hrs					
(AVG MAN HRS: 45)						Ldg					
Note: COVERED MOD: M2083						Flt					
M2703											
M3275											
F50-259	**Satellite communication - Reinforced fairing fasteners**							T (A/R)			
23 A/F						Mos					
Eff: 16-Jul-1997						Hrs					
						Ldg					
Note: M2171, A/C with 2 to part fin tip fairing FGFB823671A2 for satellite communication (M2083A or SB F50-257)						Flt					
F50-288	**VHF - 8.33 KHZ channel spacing**							RE (-)			
23 A/F						Mos					
						Hrs					
						Ldg					
Note: M2349, M2325, M2473, 251, 253 to 352 with V5.1 COLLINS avionics (SB F50-279)						Flt					
F50-288 R1	**VHF - 8.33 KHZ channel spacing**							RE (-)			
23 A/F						Mos					
Eff: 07-Jul-1999						Hrs					
						Ldg					
Note: M2349, M2325, M2473, 251, 253 to 352 with V5.1 COLLINS avionics (SB F50-279)						Flt					
F50-342	**VHF - 8.33 KHZ channel spacing**							RE (-)			
23 A/F						Mos					
						Hrs					
						Ldg					
Note: M2472, 2 to 250, 252 with COLLINS 22A or 22B or 422A or 422B VHF transceiver assemblies						Flt					
F50-342 R1	**VHF - 8.33 KHZ channel spacing**							T (A/R)			
23 A/F						Mos					
Eff: 07-Jul-1999						Hrs					
						Ldg					
Note: M2472, 2 to 250, 252 with COLLINS 22A or 22B or 422A or 422B VHF transceiver assemblies						Flt					
F50-361	**VHF1/VHF2 antenna - Installation of a new antenna**							RE (-)			
23 A/F						Mos					
						Hrs					
						Ldg					
Note: M2703, M2799, A/C with a SATCOM AERO to H system (M2083A or SB F50-257) or SATCOM AERO to I system						Flt					
F50-361 R1	**VHF1/VHF2 antenna - Installation of a new antenna**							T (A/R)			
23 A/F						Mos					
Eff: 05-Dec-2001						Hrs					
						Ldg					
Note: M2703, M2799, A/C with a SATCOM AERO to H system (M2083A or SB F50-257) or SATCOM AERO to I system						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-397	**Satellite communication - Replacement of the vertical tip fairing**							T (A/R)			
23 A/F						Mos					
Eff: 19-Feb-2004						Hrs					
						Ldg					
Note: M2816, A/C with a "SATCOM" satellite communication system including a vertical fin tip antenna						Flt					
F50-405	**New LEM M83 microphones**							T (A/R)			
23 A/F						Mos					
Eff: 06-Nov-2002						Hrs					
						Ldg					
Note: M2830						Flt					
F50-426	**COLLINS HF9000 - Impedance matching of the couplers/antenna connection**							RE (-)			
23 A/F						Mos					
Eff: 17-Mar-2004						Hrs					
						Ldg					
Note: M2887, 251, 253 to 352 with COLLINS HF 9000 system as per M2094 or M2343 and without M2887						Flt					
F50-505	**Replacement of obsolete video source selector**							T (A/R)			
23 A/F						Mos					
Eff: 25-May-2009						Hrs					
						Ldg					
Note: M3107, 1 to 352 equipped with a Video Source Selector P/N VSS-02(-T), VSS-02-04T, VSS-03, VSS-04, VSS-480-08(-T), VSS-480-08 -NT, VSS-480-09(-T), VSS-480-09-NT, VSS-480-10, VSS-480-14-NT, VSS-480-17, VSS-480-17-NT or VSS-480-19.						Flt					
▼ 24 - ELECTRICAL POWER											
	(Emergency) Stand-by Horizon - Battery (5F)							RE (H/T)			
24 A/F						Mos	24-Mar-2021				
NCS734-01-030						Hrs					
3318						Ldg					
						Flt					
	Alternating Current Voltmeter							RE (O/C)			
24 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	APU Generator Control							RE (O/C)			
24 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	APU Starter Generator							RE (H/T)			
24 A/F						Mos	11-Dec-2024				
8060-320-1	Serviceable					Hrs	13,453.3				
187						Ldg	9,091				
						Flt	9,091				
	APU Starter/ Relay							RE (O/C)			
24 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
Brand C::243250						Flt					
	Auxiliary Stand-By Battery (710PE)							RE (H/T)			
24 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Battery (Thermistor) Temperature Probe							RE (O/C)			
	24 A/F	No.1					Mos	09-May-2019				
	P600-14A						Hrs					
	17622						Ldg					
							Flt					
		Battery (Thermistor) Temperature Probe							RE (O/C)			
	24 A/F	No.2					Mos	09-May-2019				
	P600-14A						Hrs					
	13403						Ldg					
							Flt					
		Battery Connector							RE (O/C)			
	24 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Battery Connector							RE (O/C)			
	24 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Battery Fan							RE (O/C)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Battery Reverse Current Relay							RE (O/C)			
	24 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Battery Reverse Current Relay							RE (O/C)			
	24 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Battery Temperature Indicator							RE (O/C)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		DC APU Ammeter							RE (O/C)			
	24 A/F						Mos	04-Apr-2015				
	2396-324-0						Hrs					
	223						Ldg					
							Flt					
		Engine Starter Generator							RE (H/T)			
	24 A/F	No.1					Mos	30-Dec-2016				
	8060-320-1						Hrs					
	1573						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Starter Generator							RE (H/T)			
	24 A/F	No.2					Mos	27-Jan-2016				
	8060-360						Hrs					
	T21453						Ldg					
							Flt					
		Engine Starter Generator							RE (H/T)			
	24 A/F	No.3					Mos	26-Aug-2021				
	8060-320-1						Hrs					
	1311						Ldg					
							Flt					
		Frequency Monitor Printed Card							RE (O/C)			
	24 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Frequency Monitor Printed Card							RE (O/C)			
	24 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Generator Control							RE (O/C)			
	24 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Generator Control							RE (O/C)			
	24 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Generator Control							RE (O/C)			
	24 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Generator Reverse Current Relay							RE (O/C)			
	24 A/F	APU					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Generator Reverse Current Relay							RE (O/C)			
	24 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Generator Reverse Current Relay							RE (O/C)			
	24 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Generator Reverse Current Relay							RE (O/C)			
	24 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Ground Power Receptacle							RE (O/C)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Ground Sys (62K) Relay							RE (O/C)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Ground Sys (63K) Relay							RE (O/C)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inverter							RE (O/C)			
	24 A/F	Cabin					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IRS 1 Stand-By Battery (195NP)							RE (H/T)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IRS 2 Stand-By Battery (295NP)							RE (H/T)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IRS 3 Stand-By Battery (95NP)							RE (H/T)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lead/Acid Stand-By Battery							RE (H/T)			
	24 A/F						Mos	14-Sep-2023				
	PS-835-D	Repaired				0	Hrs	13,276.7				
	2379					0	Ldg	8,977				
						0	Flt	8,977				
		Main Battery							RE (H/T)			
	24 A/F	No.1					Mos	30-Apr-2024				
	018804-000	Overhauled		0			Hrs	13,296.7				
	09052001DAAAS			0			Ldg	8,994				
				0			Flt	8,994				

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Main Battery							RE (H/T)			
	24 A/F	No.2					Mos	30-Apr-2024				
	018804-000	Overhauled		0			Hrs	13,296.7				
	09052001088E1			0			Ldg	8,994				
				0			Flt	8,994				
		Overvolt External Power PCB							RE (O/C)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Power Supply DC Ammeter							RE (O/C)			
	24 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Power Supply DC Ammeter							RE (O/C)			
	24 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Power Supply DC Voltmeter							RE (O/C)			
	24 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Power Supply DC Voltmeter							RE (O/C)			
	24 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Starter/ Relay							RE (O/C)			
	24 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Starter/ Relay							RE (O/C)			
	24 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Starter/ Relay							RE (O/C)			
	24 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Static Inverter							RE (O/C)			
	24 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Static Inverter							RE (O/C)			
	24 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Static Inverter							RE (O/C)			
	24 A/F	StandBy					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Static Inverter "Emergency Supply" Stand-By Battery (23F)							RE (H/T)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF 1 Stand-By Battery (17RC)							RE (H/T)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF 3 Stand-By Battery (85RC)							RE (H/T)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VHF Emergency Power Supply							RE (O/C)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2008-09-21		**Electrical feeder bundle and a bus bar - inspect for damage of the electrical feeder bundle; repair or replace wiring, as applicable**							RE (-)		Mandatory	
	24 A/F						Mos	12-Oct-2010				
	Eff: 12-Jun-2008 Not Applicable	per SN					Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
2015-08-02		**Electrical Power - Installation of Protective Plates Between the Electrical Wiring Under the Glare Shield and the Engine Fire Pull Handles**							RE (-)		Mandatory	
	24 A/F						Mos	24-Mar-2021				
	Eff: 29-Apr-2015						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
240100-0101		**Blower, Battery Ventilation**							RE (O/C)			
	24 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
24-20-00-720-802-01		**Functional Test of the AC Generation System**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
	24 A/F	05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
	Note: A/C without COLLINS PROLINE 4 AVIONICS						Flt	8,977				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
24-30-00-710-801-01	**Operational Test of the Voltage Monitoring Circuits - Engine 1**							RE		Acft Maint Ops (5-10)	**≈22-Feb-2026**
24 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	600	+30	13,876.7	355.8 Hrs (+30)
						Ldg	8,977				
Note: For aircraft with at least one G.C.U. D22-010 before Amdt P						Flt	8,977				
24-30-00-710-801-02	**Operational Test of the Voltage Monitoring Circuits - Engine 2**							RE		Acft Maint Ops (5-10)	**≈22-Feb-2026**
24 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	600	+30	13,876.7	355.8 Hrs (+30)
						Ldg	8,977				
Note: For aircraft with at least one G.C.U. D22-010 before Amdt P						Flt	8,977				
24-30-00-710-801-03	**Operational Test of the Voltage Monitoring Circuits - Engine 3**							RE		Acft Maint Ops (5-10)	**≈22-Feb-2026**
24 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	600	+30	13,876.7	355.8 Hrs (+30)
						Ldg	8,977				
Note: For aircraft with at least one G.C.U. D22-010 before Amdt P						Flt	8,977				
24-30-00-710-801-04	**Operational Test of the Voltage Monitoring Circuits - APU**							RE		Acft Maint Ops (5-10)	**≈22-Feb-2026**
24 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	600	+30	13,876.7	355.8 Hrs (+30)
						Ldg	8,977				
Note: For aircraft with at least one G.C.U. D22-010 before Amdt P						Flt	8,977				
24-31-13-350-801-01	**Restoration of the Starter-Generators (Overhaul) - Engine 1 Starter-Generator (3P1)**							RE		Comp Maint Ops (5-20)	**≈09-Mar-2026**
24 A/F	No.1					Mos	24-Dec-2016				
8060-320-1						Hrs	12,992.8	900	+3%	13,892.8	371.9 Hrs (+27)
1573						Ldg	8,795				
						Flt					
Note: P/N 8060-3 or 8060-3-1 or 8060-300 or 8060-300-1 or 8060-320 or 8060-320-1 Note: (1) and (24)											
24-31-13-350-801-02	**Restoration of the Starter-Generators (Overhaul) - Engine 2 Starter-Generator (3P2)**							RE		Comp Maint Ops (5-20)	**≈08-Apr-2027**
24 A/F	No.2					Mos	17-Oct-2018				
8060-360						Hrs	13,081.5	1,200	+3%	14,281.5	760.6 Hrs (+36)
T21453						Ldg	8,840				
						Flt					
Note: P/N 8060-360 or P/N 8060-370 Note: (1) and (24)											
24-31-13-350-801-03	**Restoration of the Starter-Generators (Overhaul) - Engine 3 Starter-Generator (3P3)**							RE		Comp Maint Ops (5-20)	**≈09-Oct-2026**
24 A/F	No.3					Mos	24-Aug-2021				
8060-320-1						Hrs	13,202.3	900	+3%	14,102.3	581.4 Hrs (+27)
1311						Ldg					
						Flt					
Note: P/N 8060-3 or 8060-3-1 or 8060-300 or 8060-300-1 or 8060-320 or 8060-320-1 Note: (1) and (24)											
24-31-13-350-801-04	**Restoration of the Starter-Generators (Overhaul) - APU Starter-Generator (103P) or (21PA)**							RE		Comp Maint Ops (5-20)	**≈28-Feb-2027**
24 A/F						Mos	11-Dec-2024				
8060-320-1						Hrs	13,453.3				
187						Ldg	9,091				
						Flt	9,091				
Note: P/N 8060-3 or 8060-3-1 or 8060-300 or 8060-300-1 or 8060-320 or 8060-320-1 Note: (1) and (24)					135.5	Hrs (APU)	5,643.1	900	+3%	6,407.6	724.9 Hrs(APU) (+ 27)

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
24-31-17-220-803-01		**Check of the Engine Starter-Generator Brushes - Engine 1 Starter-Generator (3P1)**							RE		Comp Maint Ops (5-20)	**≈23-Sep-2025**
24 A/F	8060-320-1 1573	No.1					Mos	14-Sep-2023				
							Hrs	13,276.7	450	+30	13,726.7	205.8 Hrs (+30)
							Ldg	8,977				
							Flt	8,977				
		Note: P/N 8060-320 or P/N 8060-320-1										
24-31-17-220-803-02		**Check of the Engine Starter-Generator Brushes - Engine 2 Starter-Generator (3P2)**							RE		Comp Maint Ops (5-20)	**≈08-Aug-2025**
24 A/F	8060-360 T21453	No.2					Mos	31-Oct-2018				
							Hrs	13,081.5	600	+60	13,681.5	160.6 Hrs (+60)
							Ldg	8,840				
							Flt					
		Note: P/N 8060-360 Maintenance option 1 (check with removal of the starter-generator) Note: (20)										
24-31-17-220-803-03		**Check of the Engine Starter-Generator Brushes - Engine 3 Starter-Generator (3P3)**							RE		Comp Maint Ops (5-20)	**≈12-Jan-2026**
24 A/F	8060-320-1 1311	No.3					Mos	21-Aug-2024				
							Hrs	13,385.7	450	+30	13,835.7	314.8 Hrs (+30)
							Ldg	9,043				
							Flt	9,042				
		Note: P/N 8060-320 or P/N 8060-320-1										
24-32-00-710-803-01		**Operational Test of the Battery Bus Diodes - Diode (59P1)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
24 A/F		05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
							Flt	8,977				
24-32-00-710-803-02		**Operational Test of the Battery Bus Diodes - Diode (59P2)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
24 A/F		05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
							Flt	8,977				
24-32-01-350-801-01		**Restoration of a Main Nickel-Cadmium Battery (Overhaul) - Battery 1 (2P1)**							RE		Comp Maint Ops (5-20)	
24 A/F	018804-000 09052001DAAAS	No.1					Mos	30-Apr-2024	12	+1m	30-Apr-2025	55 Days (+30)
							Hrs	13,296.7				
							Ldg	8,994				
							Flt	8,994				
		Note: P/N 2376 or 2376-4 (14)										
24-32-01-350-801-02		**Restoration of a Main Nickel-Cadmium Battery (Overhaul) - Battery 2 (2P2)**							RE		Comp Maint Ops (5-20)	
24 A/F	018804-000 09052001088E1	No.2					Mos	30-Apr-2024	12	+1m	30-Apr-2025	55 Days (+30)
							Hrs	13,296.7				
							Ldg	8,994				
							Flt	8,994				
		Note: P/N 2376 or 2376-4 (14)										
24-32-01-700-801-01		**Regular Check of a Nickel-Cadmium Battery - Main Battery 1 (2P1) (This operation is not to be performed if operation 24-32-01-350-801-01 is scheduled at the same time.)**							RE		Comp Maint Ops (5-20)	
24 A/F	018804-000 09052001DAAAS	No.1					Mos	05-Nov-2024	6	+15d	30-Apr-2025	55 Days (+15)
							Hrs	13,427.3	250	+25	13,677.3	156.4 Hrs (+25)
							Ldg	9,074				
		(Tol. Adjustment: -5d) (SOURCE: Falcon 50/50EX MPD)					Flt	9,074				
		Note: NOTE 14: This task can be completed by replacing the battery with the same or other serviced/overhauled battery, providing that an equivalent servicing/overhaul was performed per the vendor's applicable document. It is recommended to replace the Ni-Cad batteries P/N 4076-10 after 12Y.										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
24-32-01-700-801-02		**Regular Check of a Nickel-Cadmium Battery - Main Battery 2 (2P2) (This operation is not to be performed if operation 24-32-01-350-801-01 is scheduled at the same time.)**							RE		Comp Maint Ops (5-20)	
24 A/F		No.2					Mos	05-Nov-2024	6	+15d	30-Apr-2025	55 Days (+15)
018804-000							Hrs	13,427.3	250	+25	13,677.3	156.4 Hrs (+25)
09052001088E1							Ldg	9,074				
		(Tol. Adjustment: -5d) (SOURCE: Falcon 50/50EX MPD)					Flt	9,074				
		Note: NOTE 14: This task can be completed by replacing the battery with the same or other serviced/overhauled battery, providing that an equivalent servicing/overhaul was performed per the vendor's applicable document. It is recommended to replace the Ni-Cad batteries P/N 4076-10 after 12Y.										
24-32-01-700-802-01		**Regular Check of a Lead / Acid Battery - Main Battery 1 (2P1)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F		No.1					Mos	30-Apr-2024				
018804-000							Hrs	13,296.7				
09052001DAAAS							Ldg	8,994				
		Note: Lead/Acid Battery Not Installed					Flt	8,994				
24-32-01-700-802-02		**Regular Check of a Lead / Acid Battery -Main Battery 2 (2P2)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F		No.2					Mos	30-Apr-2024				
018804-000							Hrs	13,296.7				
09052001088E1							Ldg	8,994				
		Note: Lead/Acid Battery Not Installed					Flt	8,994				
24-32-01-960-801-01		**Discard of the Main Lead / Acid Batteries - Battery 1 (2P1)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F		No.1					Mos	30-Apr-2024				
018804-000							Hrs	13,296.7				
09052001DAAAS							Ldg	8,994				
		Note: Lead/Acid Battery Not Installed					Flt	8,994				
24-32-01-960-801-02		**Discard of the Main Lead / Acid Batteries - Battery 2 (2P2)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F		No.2					Mos	30-Apr-2024				
018804-000							Hrs	13,296.7				
09052001088E1							Ldg	8,994				
		Note: Lead/Acid Battery Not Installed					Flt	8,994				
24-32-05-710-801-01		**Operational Test of the Battery Fan - Battery Fan (55P)**							RE (A/R)		Acft Maint Ops (5-10)	
24 A/F							Mos					
Unknown							Hrs					
Unknown							Ldg					
		Note: To be performed during installation of batteries					Flt					
24-32-09-610-801-01		**Servicing of "J.E.T." Nickel-Cadmium Stand-By Batteries - Static Inverter "Emergency Supply" (23F)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F							Mos					
Unknown							Hrs					
Unknown							Ldg					
		Note: J.E.T. Nickel-Cadmium Battery not installed					Flt					
24-32-09-610-801-01		**Servicing of "Saft" Nickel-Cadmium Stand-By Batteries - Stand-By Horizon Battery (5F)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F							Mos					
NCS734-01-030							Hrs					
3318							Ldg					
		Note: "Saft" Nickel-Cadmium Battery not installed					Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
24-32-09-610-801-02	**Servicing of (various models) Stand-By Batteries - IRS 1 Stand-By Battery (195NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: IRS 1 Stand-By Battery not installed										
24-32-09-610-801-03	**Servicing of "Saft" Nickel-Cadmium Stand-By Batteries - IRS 2 Stand-By Battery (295NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: "Saft" Nickel-Cadmium Battery not installed										
24-32-09-610-801-04	**Servicing of "Saft" Nickel-Cadmium Stand-By Batteries - IRS 3 Stand-By Battery (95NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: "Saft" Nickel-Cadmium Battery not installed										
24-32-09-610-801-05	**Servicing of "Saft" Nickel-Cadmium Stand-By Batteries - Auxiliary Battery (710PE)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: "Saft" Nickel-Cadmium Battery not installed										
24-32-09-610-801-06	**Servicing of "Saft" Nickel-Cadmium Stand-By Batteries - VHF 3 Stand-By Battery (85RC)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Saft Nickel-Cadmium not installed										
24-32-09-610-801-07	**Servicing of "Saft" Nickel-Cadmium Stand-By Batteries - VHF 1 Stand-By Battery (17RC)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Saft Nickel-Cadmium not installed										
24-32-09-610-802-01	**Servicing of "J.E.T." Lead / Acid Stand-By Batteries - Voltage Test of the Battery**							RE		Comp Maint Ops (5-20)	
24 A/F						Mos	26-Feb-2025	6		26-Aug-2025	5.8 Months
PS-835-D						Hrs	13,520.9				
2379						Ldg	9,133				
						Flt	9,133				
	Note: P/N 501-1228-02 or 501-1228-04 A/C with Option 24-50-02 or 24-50-03 installed No tolerance										
24-32-09-610-802-02	**Servicing of "J.E.T." Lead / Acid Stand-By Batteries - Capacity Test of the Battery**							RE		Comp Maint Ops (5-20)	
24 A/F						Yrs	30-Aug-2024	1		30-Aug-2025	5.9 Months
PS-835-D						Hrs	13,386.3				
2379						Ldg	9,044				
						Flt	9,043				
	Note: P/N 501-1228-02 or 501-1228-04 A/C with Option 24-50-02 or 24-50-03 installed No tolerance										

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
24-32-09-710-802-01	**Operational Test of "Securaplane" Xl245 Type Stand-By Batteries - Stand-By Horizon Battery (5F)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
NCS734-01-030						Hrs					
3318						Ldg					
						Flt					
	Note: "Securaplane" Xl245 Type Battery not installed										
24-32-09-710-802-02	**Operational Test of "Securaplane" Xl245 Type Stand-By Batteries - IRS 1 Stand-By Battery (195NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Securaplane Xl245 Type not Installed										
24-32-09-710-802-03	**Operational Test of "Securaplane" Xl245 Type Stand-By Batteries - IRS 2 Stand-By Battery (295NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Securaplane Xl245 Type not Installed										
24-32-09-710-802-04	**Operational Test of "Securaplane" Xl245 Type Stand-By Batteries - IRS 3 Stand-By Battery (95NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Securaplane Xl245 Type not Installed										
24-32-09-710-802-05	**Operational Test of "Securaplane" Xl245 Type Stand-By Batteries - Auxiliary Battery (710PE)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Securaplane Xl245 Type not Installed										
24-32-09-960-802-01	**Discard of the "Securaplane" Xl245 Type Stand-By Battery Packs - Stand-By Horizon Battery (5F)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
NCS734-01-030						Hrs					
3318						Ldg					
						Flt					
	Note: "Securaplane" Xl245 Type Battery not installed										
24-32-09-960-802-02	**Discard of the "Securaplane" Xl245 Type Stand-By Battery Packs - IRS 1 Stand-By Battery (195NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Yrs	24-Mar-2021				
Unknown						Hrs					
Unknown						Ldg					
						Flt					
24-32-09-960-802-03	**Discard of the "Securaplane" Xl245 Type Stand-By Battery Packs - IRS 2 Stand-By Battery (295NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Securaplane Xl245 Type not Installed										
24-32-09-960-802-04	**Discard of the "Securaplane" Xl245 Type Stand-By Battery Packs - IRS 3 Stand-By Battery (95NP)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Securaplane Xl245 Type not Installed										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
24-32-09-960-802-05	**Discard of the "Securaplane" Xl245 Type Stand-By Battery Packs - Auxiliary Battery (710PE)**							RE (N/A)		Comp Maint Ops (5-20)	
24 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
	Note: Securaplane Xl245 Type not Installed										
24-33-05-220-803-01	**Check of the APU Starter-Generator Brushes - APU Starter-Generator (103P) or (21PA)**							RE		5-20	**≈30-Nov-2025**
24 A/F						Mos	11-Dec-2024				
8060-320-1						Hrs	13,453.3				
187						Ldg	9,091				
	(SOURCE: Falcon 50/50EX MPD)					Flt	9,091				
	Note: P/N 8060-320 or 8060-320-1				135.5	Hrs (APU)	5,643.1	450	+30	5,957.6	274.9 Hrs(APU) (+ 30)
24-40-00-720-801-01	**Functional Test of the Ground Power Receptacle Overvoltage Protection PCB - GPU Overvoltage Protection PCB (42P)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
24 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
24-41-00-720-801-01	**Functional Test of Battery Charging By GPU - General Test of the Charging Function**							RE (N/A)		Acft Maint Ops (5-10)	
24 A/F						Mos					
						Hrs					
	(SOURCE: Falcon 50/50EX MPD)					Ldg					
						Flt					
24-41-00-720-801-02	**Functional Test of Battery Charging By GPU - Test of the Safety Devices**							RE (N/A)		Acft Maint Ops (5-10)	
24 A/F						Mos					
						Hrs					
						Ldg					
	Note: A/C with (SB F50-362 or SB F50-429)					Flt					
24-63-13-710-801-01	**Operational Test of the Dome Light PCB - Dome Light PCB (415J)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
24 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
246501	**"D" Bus-Tie Relay**							RE (O/C)			
24 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
350-24-004	**Special Check/Rework - DC Power Center (DCPC) System - Replacement of the Left DC Power Center**							RE (-)		Recommended	
24 A/F						Mos	18-Jun-1987				
	Eff: 30-Dec-2023 Complied With					Hrs					
	(AVG MAN HRS: 8)					Ldg					
	Note: COMPLIANCE: Recommended before Dec 31/2023, for all the affected left DCPC units that have accumulated 3500 total flight hours or more since date of manufacture.					Flt					
87-06-09	**MECHANICAL PRODUCTS, INC. Model 4001, 4200, 4310, and 8500 Series Circuit Breakers**							RE (-)		Mandatory (Appliance AD)	
24 A/F						Mos	18-Jun-1987				
	Eff: 27-Apr-1987 Complied With					Hrs					
	(ISSUING AUTHORITY: FAA)					Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
95-01-03	**Electrical Wire Bundles**							RE (-)		Mandatory	
24 A/F						Mos	08-Feb-1995				
Eff: 18-Jan-1995 Complied With						Hrs	8,183				
(ISSUING AUTHORITY: FAA)						Ldg	5,751				
						Flt					
F50-032	**Limitation of the battery charge after a start - Time-delay printed card replaced**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M0138						Flt					
F50-032 R1	**Limitation of the battery charge after a start - Time-delay printed card replaced**							T (A/R)			
24 A/F						Mos					
Eff: 21-Sep-1981						Hrs					
						Ldg					
Note: M0138						Flt					
F50-048	**Bus bar supply cables - Improved cable separation at bottom of frame 28**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M0184						Flt					
F50-048 R1	**Bus bar supply cables - Improved cable separation at bottom of frame 28**							RE (-)			
24 A/F						Mos	22-Jan-1981				
Eff: 04-Apr-1980						Hrs					
						Ldg					
Note: M0184						Flt					
F50-084	**Improved wiring routing in nose cone**							T (A/R)			
24 A/F						Mos					
Eff: 07-Sep-1983						Hrs					
						Ldg					
Note: M0695B, M0695D, M0695C						Flt					
F50-176	**Improved overvoltage protection**							T (A/R)			
24 A/F						Mos					
Eff: 10-Feb-1986						Hrs					
						Ldg					
Note: M1380, M0805						Flt					
F50-200	**External power - Relocation of diode 59P1**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M1309, M3218						Flt					
F50-200 R1	**External power - Relocation of diode 59P1**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M1309, M3218						Flt					
F50-200 R2	**External power - Relocation of diode 59P1**							T (A/R)			
24 A/F						Mos					
Eff: 02-Jul-2014						Hrs					
						Ldg					
Note: M1309, M3218						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-211	**Electrical power - DC generation - Protection of exciter line by improved performance relays**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M1532						Flt					
F50-211 R1	**Electrical power - DC generation - Protection of exciter line by improved performance relays**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M1532						Flt					
F50-211 R2	**Electrical power - DC generation - Protection of exciter line by improved performance relays**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M1532						Flt					
F50-211 R3	**Electrical power - DC generation - Protection of exciter line by improved performance relays**							T (A/R)			
24 A/F						Mos					
Eff: 17-Apr-2008						Hrs					
						Ldg					
Note: M1532						Flt					
F50-214	**Static inverter voltage monitoring**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M1612						Flt					
F50-214 R1	**Static inverter voltage monitoring**							T (A/R)			
24 A/F						Mos					
Eff: 10-May-1990						Hrs					
						Ldg					
Note: M1612						Flt					
F50-219	**Generator control unit - Improved reliability of the overvoltage protection printed circuit board**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M1640B, M1640A						Flt					
F50-219 R1	**Generator control unit - Improved reliability of the overvoltage protection printed circuit board**							T (A/R)			
24 A/F						Mos					
Eff: 27-Feb-1992						Hrs					
						Ldg					
Note: M1640B, M1640A						Flt					
F50-238	**Generator control unit - Optimization of overvoltage monitoring circuit**							T (A/R)			
24 A/F						Mos					
Eff: 15-May-1996						Hrs					
						Ldg					
Note: M1863B, M1863A						Flt					
F50-255	**Replacement of 413J or 113P PCB**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M2042, M2502						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-255 R1	**Replacement of 413J or 113P PCB**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M2042, M2502						Flt					
F50-255 R2	**Replacement of 413J or 113P PCB**							T (A/R)			
24 A/F						Mos					
Eff: 01-Sep-2001						Hrs					
						Ldg					
Note: M2042, M2502						Flt					
F50-265	**A/C power supplied through ground power receptacle - Making the battery bus power supply system more reliable**							RE (-)			
24 A/F						Mos					
Eff: 02-Sep-1998						Hrs					
						Ldg					
Note: M2205						Flt					
F50-291	**Modified connections for generators 1 and 3 excitation connectors**							RE (-)			
24 A/F						Mos					
Eff: 17-Feb-1999						Hrs					
						Ldg					
Note: M2252, M2222						Flt					
F50-295	**Digital battery temperature indicator**							T (A/R)			
24 A/F						Mos					
Eff: 13-Sep-2000						Hrs					
						Ldg					
Note: M2245						Flt					
F50-317	**Automatic coupling of the main bus bars on ground power**							T (A/R)			
24 A/F						Mos					
Eff: 14-Mar-2001						Hrs					
						Ldg					
Note: M2493						Flt					
F50-334	**Improved overvoltage protection on ground power receptacle**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M2800, M2079, A/C without M2800						Flt					
F50-334 R1	**Improved overvoltage protection on ground power receptacle**							T (A/R)			
24 A/F						Mos					
Eff: 17-Jun-2003						Hrs					
						Ldg					
Note: M2800, M2079, A/C without M2800						Flt					
F50-339	**Nickel-Cadmium main batteries - Capacity increased to 36 A.h**							T (A/R)			
24 A/F						Mos					
Eff: 13-Mar-2003						Hrs					
						Ldg					
Note: M2715						Flt					
F50-354	**FMS Collins 6100 - FMS 99 STEP 2 (Minor 3) - CSU modification**							RE (-)			
24 A/F						Mos					
Eff: 16-May-2001						Hrs					
						Ldg					
Note: M2759, 279 to 352 with COLLINS FMS 6100 to FMS 99 STEP 2 (MINOR 3) compliant with M2689 or SB F50-353 and (if installed) M2685						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-356-1	**Securaplane battery installation**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: 253 to 352 with SAFT batteries for IRS, Standby Attitude systems and Auxiliary Batteries						Flt					
F50-356-1 R1	**Securaplane battery installation**							RE (-)			
24 A/F						Mos					
Eff: 10-Apr-2003						Hrs					
						Ldg					
Note: 253 to 352 with SAFT batteries for IRS, Standby Attitude systems and Auxiliary Batteries						Flt					
F50-356-2	**Securaplane battery installation**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: 253 to 352 with SAFT batteries for IRS, Standby Attitude systems and Auxiliary Batteries						Flt					
F50-356-2 R1	**Securaplane battery installation**							RE (-)			
24 A/F						Mos					
Eff: 10-Apr-2003						Hrs					
						Ldg					
Note: 253 to 352 with SAFT batteries for IRS, Standby Attitude systems and Auxiliary Batteries						Flt					
F50-362	**Battery charging using GPU**							RE (-)			
24 A/F						Mos					
Eff: 10-Jul-2003						Hrs					
						Ldg					
Note: M2633						Flt					
F50-366	**Wire harness thermal protection sleeve application**							T (-)			
24 A/F						Mos					
Eff: 17-Dec-2001						Hrs					
						Ldg					
Note: A/C with GARRETT or SOLAR APUs as per STC 1220EA or STC 1242 EA						Flt					
F50-366-R1	**Electrical Power - Wire Harness Thermal Protection Sleeve Application**							T (A/R)		Optional	
24 A/F						Mos					
Eff: 15-Dec-2021						Hrs					
(AVG MAN HRS: 16)						Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to MYSTERE-FALCON 50 aircraft with serial numbers 2 thru 252 equipped with Garrett or Solar Auxiliary Power Units installed under either STC 1220 EA (Garrett) or STC 1242 EA (Solar).						Flt					
F50-385	**Replacement of a PCB (ERCA)**							T (A/R)			
24 A/F						Mos					
Eff: 10-Apr-2002						Hrs					
						Ldg					
Note: M2627						Flt					
F50-393	**Load shed annunciator diode installation**							RE (-)			
24 A/F						Mos					
Eff: 15-May-2002						Hrs					
						Ldg					
Note: STC SA8312SW-D						Flt					
F50-395	**Improvement to routing of AHS standby battery wiring**							RE (-)			
24 A/F						Mos					
Eff: 08-Oct-2002						Hrs					
						Ldg					
Note: M2839						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-418	**Prevention of voltage drop during engine start**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M2867						Flt					
F50-418 R1	**Prevention of voltage drop during engine start**							RE (-)			
24 A/F						Mos					
Eff: 21-Jan-2004						Hrs					
						Ldg					
Note: M2867						Flt					
F50-429	**Battery charging using GPU**							T (A/R)			
24 A/F						Mos					
Eff: 09-Jul-2004						Hrs					
						Ldg					
Note: M2633						Flt					
F50-432	**Prevention of voltage drop during engine start**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M2898, M3218, 2 to 252 except A/C with SB F50-280 (TFE 731-40 engine retrofit)						Flt					
F50-432 R1	**Prevention of voltage drop during engine start**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M2898, M3218, 2 to 252 except A/C with SB F50-280 (TFE 731-40 engine retrofit)						Flt					
F50-432 R2	**Prevention of voltage drop during engine start**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
Note: M2898, M3218, 2 to 252 except A/C with SB F50-280 (TFE 731-40 engine retrofit)						Flt					
F50-432 R3	**Prevention of voltage drop during engine start**							T (A/R)			
24 A/F						Mos					
Eff: 04-Jul-2014						Hrs					
						Ldg					
Note: M2898, M3218, 2 to 252 except A/C with SB F50-280 (TFE 731-40 engine retrofit)						Flt					
F50-461	**Annunciator panel switches lighting - Modifying the power supply logics**							RE (-)			
24 A/F						Mos					
Eff: 11-Jan-2006						Hrs					
						Ldg					
Note: M2986, 251, 253 to 352 without M2986						Flt					
F50-483	**Circuit breaker panel - Improved routing of the wiring assemblies**							RE (-)			
24 A/F						Mos	24-Aug-2007				
Eff: 14-Jun-2007						Hrs	10,670.1				
						Ldg	7,474				
Note: M3093, AD EASA 2007-0175 (AD FAA 2008-09-21)						Flt					
F50-506	**Galley circuit breaker identification**							RE (-)			
24 A/F						Mos					
						Hrs					
						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-506 R1	**Galley circuit breaker identification**							RE (-)			
24 A/F						Mos					
Eff: 16-Mar-2009						Hrs					
						Ldg					
						Flt					
F50-517	**Overhead panel - Replacement of the switches containing tritium**							T (A/R)			
24 A/F						Mos					
Eff: 17-Apr-2013						Hrs					
						Ldg					
Note: M3176						Flt					
F50-528	**Main electrical box - Contactor wires reinforcement**							T (A/R)			
24 A/F						Mos					
Eff: 23-Jan-2014						Hrs					
						Ldg					
Note: M3224						Flt					
F50-530	**Installation of protective plates under the glareshield**							RE (-)			
24 A/F						Mos	07-Feb-2015				
Eff: 19-Dec-2013						Hrs					
						Ldg					
						Flt					
F50-558	**Electrical Power - DC Generation - Check of Feeder Cable Chafing Against Windshield Air Duct at RH Frame 26**							RE (-)		Optional	
24 A/F						Mos					
Eff: 18-Jan-2023						Hrs					
						Ldg					
						Flt					
▼ 25 - EQUIPMENT/FURNISHINGS											
	Divan Passenger Life Vest							RE (O/C)			
25 A/F	Divan - No.1					Mos	28-Aug-2024				
P01074-101	Serviceable					Hrs					
23052190025						Ldg					
						Flt					
	Divan Passenger Life Vest							RE (O/C)			
25 A/F	Divan - No.2					Mos	28-Aug-2024				
P01074-101	Serviceable					Hrs					
16031310718						Ldg					
						Flt					
	Divan Passenger Life Vest							RE (O/C)			
25 A/F	Divan - No.3					Mos	28-Aug-2024				
P01074-101	Serviceable					Hrs					
23052190055						Ldg					
						Flt					
	Cabin Display Computer							RE (O/C)			
25 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Cabin Telecommunications Router (CTR)							RE (O/C)			
25 A/F						Mos	29-Sep-2023				
Not Installed						Hrs	13,277.7				
Not Installed						Ldg	8,978				
						Flt	8,978				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		ELT Battery							RE (H/T)			
	25 A/F						Mos	14-Dec-2021				
	452-0133						Hrs					
	390637-012						Ldg					
							Flt					
		Elt/Nav Interface							RE (O/C)			
	25 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Emergency Locator (ELT) Transmitter							RE (O/C)			
	25 A/F						Mos	02-Dec-2005				
	C406-N						Hrs					
	01094						Ldg					
							Flt					
		Emergency Locator Transmitter (ELT) Antenna							RE (O/C)			
	25 A/F						Mos	02-Dec-2005				
	110-340						Hrs					
	3123509						Ldg					
							Flt					
		First Aid Kit							RE (O/C)			
	25 A/F						Mos	14-Sep-2023				
	FL220-FAKAA	Overhauled		0			Hrs	13,276.7				
	0119-1128			0			Ldg	8,977				
				0			Flt	8,977				
		Flight Deck Controler							RE (O/C)			
	25 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Heating Carpet							RE (O/C)			
	25 A/F	3rd					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Heating Carpet							RE (O/C)			
	25 A/F	Copilot					Mos	14-Sep-2023				
	592045	Tested/Inspected					Hrs	13,276.7				
	408						Ldg	8,977				
							Flt	8,977				
		Heating Carpet							RE (O/C)			
	25 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Jump Seat							RE (O/C)			
	25 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Life Raft							RE (O/C)			
	25 A/F	No.1					Mos	20-Nov-2024				
	RAF1206-305T	Overhauled		0			Hrs	13,446.1				
	1121011158H			0			Ldg	9,086				
				0			Flt	9,086				
		Life Raft							RE (O/C)			
	25 A/F	No.2					Mos	20-Nov-2024				
	RAF1206-305T1						Hrs	13,446.1				
	1120090851H						Ldg	9,086				
							Flt	9,086				
		Life Vest (Crew)							RE (O/C)			
	25 A/F	3rd					Mos	14-Sep-2023				
	P01074-101C	New	0				Hrs	13,276.7				
	23041070186		0				Ldg	8,977				
			0				Flt	8,977				
		Life Vest (Crew)							RE (O/C)			
	25 A/F	Copilot					Mos	14-Sep-2023				
	P01074-101C	New	0				Hrs	13,276.7				
	23041070127		0				Ldg	8,977				
			0				Flt	8,977				
		Life Vest (Crew)							RE (O/C)			
	25 A/F	Pilot					Mos	14-Sep-2023				
	P01074-101C	New	0				Hrs	13,276.7				
	23041070118		0				Ldg	8,977				
			0				Flt	8,977				
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.1					Mos	24-Mar-2021				
	P01074-101						Hrs					
	15111390018						Ldg					
							Flt					
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.10					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.11					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.2					Mos	24-Mar-2021				
	P01074-101						Hrs					
	15111390143						Ldg					
							Flt					
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.3					Mos	30-Aug-2024				
	D21343-175	Serviceable					Hrs	13,386.3				
	D21343-175						Ldg	9,044				
							Flt	9,043				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.4					Mos	30-Aug-2024				
	P01074-101	Serviceable					Hrs	13,386.3				
	15111390134						Ldg	9,044				
							Flt	9,043				
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.5					Mos	30-Aug-2024				
	P01074-101	Serviceable					Hrs	13,386.3				
	1511390069						Ldg	9,044				
							Flt	9,043				
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.6					Mos	30-Aug-2024				
	P01074-101	Serviceable					Hrs	13,386.3				
	23052190311						Ldg	9,044				
							Flt	9,043				
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.7					Mos	28-Aug-2024				
	Not Installed						Hrs	13,386.3				
	Not Installed						Ldg	9,044				
	(UPDATE NOTE: Seats 7,8 and 9 life vests are the divan which are already being tracked separately)						Flt	9,043				
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.8					Mos	28-Aug-2024				
	Not Installed						Hrs	13,386.3				
	Not Installed						Ldg	9,044				
	(UPDATE NOTE: Seats 7,8 and 9 life vests are the divan which are already being tracked separately)						Flt	9,043				
		Life Vest (Passenger)							RE (O/C)			
	25 A/F	No.9					Mos	28-Aug-2024				
	Not Installed						Hrs	13,386.3				
	Not Installed						Ldg	9,044				
	(UPDATE NOTE: Seats 7,8 and 9 life vests are the divan which are already being tracked separately)						Flt	9,043				
		Microwave Oven							RE (O/C)			
	25 A/F						Mos	20-Jan-1981				
	JE69OT						Hrs	0				
	FG929735B						Ldg	0				
							Flt					
		Pilot Seat							RE (O/C)			
	25 A/F	Left					Mos	16-Oct-2013				
	394-11						Hrs					
	44						Ldg					
							Flt					
		Pilot Seat							RE (O/C)			
	25 A/F	Right					Mos	16-Oct-2013				
	394-21						Hrs					
	44						Ldg					
							Flt					
		Portable Emergency Locator Transmitter							RE (O/C)			
	25 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Remote ELT Control							RE (O/C)			
	25 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Satellite Radio Antenna							RE (O/C)			
	25 A/F						Mos	27-Mar-2007				
	C1420-1						Hrs					
	169474						Ldg					
							Flt					
		Seat Belt							RE (O/C)			
	25 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Seat Belt							RE (O/C)			
	25 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Shoulder Harness							RE (O/C)			
	25 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Shoulder Harness							RE (O/C)			
	25 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Survival Kit							RE (O/C)			
	25 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Survival Kit							RE (O/C)			
	25 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Survival Kit							RE (O/C)			
	25 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Survival Kit							RE (O/C)			
	25 A/F	No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2002-21-01	**Electrical terminal contact pins - Britax Sell GmbH & Co. OHG Water Boilers, Coffee Makers, and Beverage Makers**							RE (-)	Mandatory (Appliance AD)		
25 A/F						Yrs	14-Sep-2003				
Eff: 27-Nov-2002 Not Applicable	by manufacturer					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2007-12-12	**Power wire supplying the galley's coffee-maker and the surrounding structure**							RE (-)		Mandatory	
25 A/F						Mos	18-Mar-2008				
Eff: 16-Jul-2007 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2007-12-12 Paragraph (f)(1)	**Power wire supplying the galley's coffee-maker and the surrounding structure - disable the galley's coffee-maker by pulling and locking out the circuit breaker 710HG**							RE (-)		Mandatory	
25 A/F						Mos					
Eff: 16-Jul-2007						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2007-12-12 Paragraph (f)(2)	**Power wire supplying the galley's coffee-maker and the surrounding structure - inspect for damaged wire sleeves, check their proper clearance**							RE (-)		Mandatory	
25 A/F						Mos					
Eff: 16-Jul-2007						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2008-05-08	**Life raft - verify that all life rafts are stowed correctly with deployment straps outboard, and are repacked to specified dimensions.**							RE (-)		Mandatory	
25 A/F						Mos	12-Oct-2010				
Eff: 08-Apr-2008 Not Applicable	per aircraft SN					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2008-05-08 Paragraph (f)(1)	**Life raft - verify that all life rafts are stowed correctly with deployment straps outboard, and are repacked to specified dimensions.**							RE (-)		Mandatory	
25 A/F						Mos	12-Oct-2010				
Eff: 08-Apr-2008 Not Applicable	per aircraft SN					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2008-05-08 Paragraph (f)(2)	**Life raft - verify that all life rafts are stowed correctly with deployment straps outboard, and are repacked to specified dimensions. - Install placards on the sofa**							RE (-)		Mandatory	
25 A/F						Mos	12-Oct-2010				
Eff: 08-Apr-2008 Not Applicable	per aircraft SN					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2015-10-02	**Zodiac Seats France Passenger Seat Assemblies (This AD replaces AD 2014-20-11)**							RE (-)	Mandatory (Appliance AD)		
25 A/F						Mos	08-Jul-2015				
Eff: 12-Jun-2015						Hrs					
Brand A:9990-2015-10-02 (AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2023-12-25	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets**							RE (-)		Mandatory	
25 A/F						Mos					
Eff: 23-Aug-2023						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
Note: APPLICABILITY: This AD applies to Survitec Group Limited (RFD Beaufort Ltd.) life jackets identified in paragraphs (c) (1) and (2) of this AD, having a part number and serial number identified in tables 2 through 13 of Survitec [RFD] Alert Service Bulletin 25-207-A, Version 1, dated November 24, 2021, and a date of manufacture between October 1, 2018, and April 30, 2019, inclusive.						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2023-12-25 Par. (g)	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection**							RE (-)		Mandatory	
25 A/F						Mos	21-Dec-2023				
Eff: 23-Aug-2023 Not Applicable	Life jackets installed is manufactured by BF aerospace company.					Hrs	13,288.4				
(ISSUING AUTHORITY: FAA)						Ldg	8,991				
						Flt	8,991				
2023-12-25 Par. (h)	**Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action**							T (A/R)		Mandatory	
25 A/F						Mos					
Eff: 23-Aug-2023						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
Note: COMPLIANCE: Before further flight after accomplishing the requirements of paragraph (g) of this AD, do the applicable actions required by paragraph (h)(1) and (2) of this AD.						Flt					
25 ELT registration	**NOAA ELT registrationU:rapego92P:Rafaelpena92**							RE (-)			
25 A/F						Mos	24-Jan-2025			[15-Jan-2027]	1.9 Years
						Hrs					
(UPDATE NOTE: U:rapego92 P:Rafaelpena92)						Ldg					
						Flt					
25-00-01-200-801-01	**Inspection Of The Onboard Kit**							RE (-)			
25 A/F						Mos	16-Sep-2018				
						Hrs					
						Ldg					
						Flt					
25-11-05-200-801-01 (5-40)	**Visual Inspection of Buckle Spring of Anjou Aeronautique Safety Belts and Restraint System (Type 343 and 343-1)**							RE (N/A)		AWL (5-40), FDBCK	
25 A/F						Mos					
						Hrs					
						Ldg					
Note: See CN 2002-105 (AB) and CN 2002-104 (AB) Type 343 or 343-1 not fitted						Flt					
25-11-05-220-801-01	**Detailed Inspection of the Pilot Seat Safety Belt Assembly - LH Pilot Seat (L2MG)**							RE		Acft Maint Ops (5-10)	
25 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: For PACIFIC SCIENTIFIC belts, refer to French DGAC Airworthiness Directive No.80-166-IMP (AB) and FAA AD No. 80-01-05 (R1)						Flt	8,977				
25-11-05-220-801-02	**Detailed Inspection of the Pilot Seat Safety Belt Assembly - RH Pilot Seat (R2MG)**							RE		Acft Maint Ops (5-10)	
25 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: For PACIFIC SCIENTIFIC belts, refer to French DGAC Airworthiness Directive No.80-166-IMP (AB) and FAA AD No. 80-01-05 (R1)						Flt	8,977				
25-11-13-640-801-01	**Greasing of the Pilot Seat Actuator Rod End-Fittings - LH Pilot Seat (L2MG)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
25 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
25-11-13-640-801-02	**Greasing of the Pilot Seat Actuator Rod End-Fittings - RH Pilot Seat (R2MG)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
25 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
25-11-19-960-801-01	**Replacement of the Pilot Seat Locking Pin Springs - LH Pilot Seat (L2MG)**							RE		Acft Maint Ops (5-10)	
25 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
25-11-19-960-801-02	**Replacement of the Pilot Seat Locking Pin Springs - RH Pilot Seat (R2MG)**							RE		Acft Maint Ops (5-10)	
25 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
25-40-25-100-801-01	**Cleaning of the Trash Cans**							RE		Acft Maint Ops (5-10)	**≈16-Sep-2026**
25 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	1,000	+30	14,079.2	558.3 Hrs (+30)
						Ldg	8,836				
Note: (FAA AD 74-08-09 Amdt 39-1917 and decree dated 4/05/1989)						Flt					
25-60-00	**Life rafts visual inspection 90 days (privaira)**							RE			
25 A/F						Mos	26-Feb-2025	3		26-May-2025	81 Days
						Hrs	13,520.9				
						Ldg	9,133				
						Flt	9,133				
25-60-00	**Life vest visual inspection 90 days (privaira)**							RE			
25 A/F						Mos	26-Feb-2025	3		26-May-2025	81 Days
						Hrs	13,520.9				
						Ldg	9,133				
						Flt	9,133				
25-60-00-200-801-02	**Inspection of the Safety Equipment - Safety Equipment**							RE		Acft Maint Ops (5-10)	
25 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
25-60-00-200-801-03	**Inspection of the Safety Equipment - First Aid Kit**							RE		Acft Maint Ops (5-10)	
25 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: May be done more often depending on local regulations and/or manufacturer's recommendations						Ldg	8,977				
						Flt	8,977				
25-60-00-200-801-05	**First aid kit seal inspection (privaira)**							RE			
25 A/F						Mos	26-Feb-2025	1		26-Mar-2025	20 Days
FL220-FAKAA						Hrs	13,520.9				
0119-1128						Ldg	9,133				
						Flt	9,133				
256012	**Life Raft - Restoration (Overhaul)**							RE			
25 A/F	No.2					Mos	20-Nov-2024	72		12-Nov-2030	5.7 Years
RAF1206-305T1						Hrs	13,446.1				
1120090851H						Ldg	9,086				
Hydrostatic Tested Date 12-Nov-2024						Flt	9,086				
25-61-00-710-801-01	**Operational Test of the Emergency Locator System - Self-Test**							RE (N/A)		Acft Maint Ops (5-10)	
25 A/F						Mos					
C406-N						Hrs					
01094						Ldg					
						Flt					
Note: A/C with ELT 96/97											

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
25-61-00-710-801-02	**Operational Test of the Emergency Locator System - Check of Cockpit Controls**							RE		Acft Maint Ops (5-10)	
25 A/F	05-10-00-36M					Mos	14-Sep-2023	36	+1m	(03-Sep-2025)	6 Months (+30 Days)
C406-N						Hrs	13,276.7				
01094						Ldg	8,977				
(Tol. Adjustment: -345d)						Flt	8,977				
Note: A/C with ELT 96/97											
25-61-00-710-801-03	**Operational Test of the Emergency Locator System - Operational Test of Elt 90/91**							RE		Acft Maint Ops (5-10)	
25 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
C406-N						Hrs	13,386.3				
01094						Ldg	9,044				
(Tol. Adjustment: -83d)						Flt	9,043				
25-61-00-710-801-04	**Operational Test Of The Emergency Locator System (ELT) - Check Of ELT 96/97 Unit Controls**							RE (A/R)			
25 A/F						Mos	24-Mar-2021				
						Hrs					
						Ldg					
						Flt					
25-61-01-710-801-01	**Operational Test of the Emergency Locator Transmitter (ELT) G-Switch - Elt (32RB)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F						Mos					
						Hrs					
						Ldg					
Note: P/N ELT90A2560XXX or ELT91A2560XXX or ELT96A2560XXX or ELT97A2560XXX						Flt					
(16)											
25-61-13-960-801-01	**Discard of the Elt Battery Packs - Elt (32RB)**							RE (Due)		Comp Maint Ops (5-20)	
25 A/F						Mos	28-Dec-2021			31-Jul-2026	1.4 Years
Expiration Date 31-Jul-2026						Hrs	13,221.7				
						Ldg	8,945				
Note: P/N ELT90A2560XXX or ELT91A2560XXX or ELT96A2560XXX or ELT97A2560XXX or P/N JE2-1978-1 or JE2-1978-1NG						Flt					
After use in an emergency or when the total of all known transmissions exceeds one hour or at expiration date written on unit											
256200	**CVR-30 6 Mos Periodic Inspection**							RE			
25 A/F						Mos	26-Feb-2025	6		26-Aug-2025	5.8 Months
						Hrs	13,520.9				
						Ldg	9,133				
						Flt	9,133				
25-62-01-720-801-01	**Functional Test of the FDR / CVR Underwater Locator Beacons - CVR Underwater Locator Beacon (10FZ1)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F						Mos	29-Sep-2023				
Not Installed						Hrs	13,277.7				
Not Installed						Ldg	8,978				
						Flt	8,978				
25-62-01-720-801-02	**Functional Test of the FDR / CVR Underwater Locator Beacons - FDR Underwater Locator Beacon (130FZ1)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
25-62-05-960-801-01	**Restoration of the FDR / CVR Underwater Locator Beacons (Discard of the FDR / CVR ULB Battery) - CVR ULB Beacon (10FZ1)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F						Mos	29-Sep-2023				
Not Installed						Hrs	13,277.7				
Not Installed						Ldg	8,978				
(SOURCE: Falcon 50/50EX MPD)						Flt	8,978				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
25-62-05-960-801-02	**Restoration of the FDR / CVR Underwater Locator Beacons (Discard of the FDR / CVR ULB Battery) - FDR ULB Beacon (130FZ1)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
(SOURCE: Falcon 50/50EX MPD)						Flt					
25-64-17-200-802-01	**Pilot Life Vest Inspection**							RE			
25 A/F	Pilot					Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
P01074-101C						Hrs	13,386.3				
23041070118						Ldg	9,044				
						Flt	9,043				
25-64-17-200-802-02	**Co-Pilot Life Vest Inspection**							RE			
25 A/F	Copilot					Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
P01074-101C						Hrs	13,386.3				
23041070127						Ldg	9,044				
						Flt	9,043				
25-64-17-200-802-10	**Passenger Life Vest Inspection**							RE			
25 A/F	Divan - No.1					Mos	28-Aug-2024	12		28-Aug-2025	5.8 Months
P01074-101						Hrs					
23052190025						Ldg					
						Flt					
25-64-17-200-802-11	**Passenger Life Vest Inspection**							RE			
25 A/F	Divan - No.2					Mos	28-Aug-2024	12		28-Aug-2025	5.8 Months
P01074-101						Hrs					
16031310718						Ldg					
						Flt					
25-64-17-200-802-12	**Passenger Life Vest Inspection**							RE			
25 A/F	Divan - No.3					Mos	28-Aug-2024	12		28-Aug-2025	5.8 Months
P01074-101						Hrs					
23052190055						Ldg					
						Flt					
25-64-17-200-803-01	**No.1 Passenger Life Vest Inspection**							RE			
25 A/F	No.1					Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
P01074-101						Hrs	13,386.3				
15111390018						Ldg	9,044				
						Flt	9,043				
25-64-17-200-803-02	**No.2 Passenger Life Vest Inspection**							RE			
25 A/F	No.2					Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
P01074-101						Hrs	13,386.3				
15111390143						Ldg	9,044				
						Flt	9,043				
25-64-17-200-803-03	**No.3 Passenger Life Vest Inspection**							RE			
25 A/F	No.3					Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
D21343-175						Hrs	13,386.3				
D21343-175						Ldg	9,044				
						Flt	9,043				
25-64-17-200-803-04	**No.4 Passenger Life Vest Inspection**							RE			
25 A/F	No.4					Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
P01074-101						Hrs	13,386.3				
15111390134						Ldg	9,044				
						Flt	9,043				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
25-64-17-200-803-05	**No.5 Passenger Life Vest Inspection**							RE			
25 A/F	No.5					Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
P01074-101						Hrs	13,386.3				
1511390069						Ldg	9,044				
						Flt	9,043				
25-64-17-200-803-06	**No.6 Passenger Life Vest Inspection**							RE			
25 A/F	No.6					Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
P01074-101						Hrs	13,386.3				
23052190311						Ldg	9,044				
						Flt	9,043				
25-64-17-200-803-07	**No.7 Passenger Life Vest Inspection**							RE (N/A)			
25 A/F	No.7					Mos	28-Aug-2024				
Not Installed						Hrs	13,386.3				
Not Installed						Ldg	9,044				
						Flt	9,043				
25-64-17-200-803-08	**No.8 Passenger Life Vest Inspection**							RE (N/A)			
25 A/F	No.8					Mos	28-Aug-2024				
Not Installed						Hrs	13,386.3				
Not Installed						Ldg	9,044				
						Flt	9,043				
25-64-17-200-803-09	**No.9 Passenger Life Vest Inspection**							RE (N/A)			
25 A/F	No.9					Mos	28-Aug-2024				
Not Installed						Hrs	13,386.3				
Not Installed						Ldg	9,044				
						Flt	9,043				
25-64-17-350-802-01	**Restoration of the Crew Life Vests (Overhaul or Discard) - LH Pilot Life Vest (L10ME)**							RE		Comp Maint Ops (5-20)	
25 A/F	Pilot					Yrs	14-Sep-2023	5		26-Apr-2028	3.1 Years
P01074-101C						Hrs	13,276.7				
23041070118						Ldg	8,977				
Restored Date 26-Apr-2023						Flt	8,977				
	Note: P/N 63600-501 or P/N 63600-505										
25-64-17-350-802-02	**Restoration of the Crew Life Vests (Overhaul or Discard) - RH Pilot Life Vest (R10ME)**							RE		Comp Maint Ops (5-20)	
25 A/F	Copilot					Yrs	14-Sep-2023	5		26-Apr-2028	3.1 Years
P01074-101C						Hrs	13,276.7				
23041070127						Ldg	8,977				
Restored Date 26-Apr-2023						Flt	8,977				
	Note: P/N 63600-501 or P/N 63600-505										
25-64-17-350-802-03	**Restoration of the Crew Life Vests (Overhaul or Discard) - Third Crew Member Life Vest (M10ME)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F	3rd					Mos					
P01074-101C						Hrs					
23041070186						Ldg					
						Flt					
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests**							RE			
25 A/F	Divan - No.1					Mos		60		12-Jan-2026	10.4 Months
P01074-101						Hrs					
23052190025						Ldg					
Restored Date 12-Jan-2021						Flt					

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests**							RE			
25 A/F	Divan - No.2					Mos		60		12-Jan-2026	10.4 Months
P01074-101						Hrs					
16031310718						Ldg					
Restored Date 12-Jan-2021						Flt					
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests**							RE			
25 A/F	Divan - No.3					Mos		60		12-Jan-2026	10.4 Months
P01074-101						Hrs					
23052190055						Ldg					
Restored Date 12-Jan-2021						Flt					
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE		Comp Maint Ops (5-20)	
25 A/F	No.1					Yrs	24-Mar-2021	5		24-Mar-2026	1 Year
P01074-101						Hrs					
15111390018						Ldg					
Restored Date 24-Mar-2021						Flt					
Note: P/N 63600-101 or P/N 63600-105											
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F	No.10					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F	No.11					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE		Comp Maint Ops (5-20)	
25 A/F	No.2					Yrs	24-Mar-2021	5		24-Mar-2026	1 Year
P01074-101						Hrs					
15111390143						Ldg					
Restored Date 24-Mar-2021						Flt					
Note: P/N 63600-101 or P/N 63600-105											
25-64-17-350-803-01	**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE		Comp Maint Ops (5-20)	
25 A/F	No.3					Yrs	30-Aug-2024	5		12-Jan-2026	10.4 Months
D21343-175						Hrs	13,386.3				
D21343-175						Ldg	9,044				
Restored Date 12-Jan-2021						Flt	9,043				
Note: P/N 63600-101 or P/N 63600-105											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
25-64-17-350-803-01		**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE		Comp Maint Ops (5-20)	
25 A/F	P01074-101 15111390134	No.4 Restored Date 12-Jan-2021 Note: P/N 63600-101 or P/N 63600-105					Yrs	30-Aug-2024	5		12-Jan-2026	10.4 Months
							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
25-64-17-350-803-01		**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE		Comp Maint Ops (5-20)	
25 A/F	P01074-101 1511390069	No.5 Restored Date 12-Jan-2021 Note: P/N 63600-101 or P/N 63600-105					Yrs	30-Aug-2024	5		12-Jan-2026	10.4 Months
							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
25-64-17-350-803-01		**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE		Comp Maint Ops (5-20)	
25 A/F	P01074-101 23052190311	No.6 Restored Date 31-May-2023 Note: P/N 63600-101 or P/N 63600-105					Yrs	30-Aug-2024	5		31-May-2028	3.2 Years
							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
25-64-17-350-803-01		**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F	Not Installed Not Installed	No.7					Mos	28-Aug-2024				
							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
25-64-17-350-803-01		**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F	Not Installed Not Installed	No.8					Mos	28-Aug-2024				
							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
25-64-17-350-803-01		**Restoration of the Passenger Life Vests (Overhaul or Discard) - Passenger Life Vests (11ME)**							RE (N/A)		Comp Maint Ops (5-20)	
25 A/F	Not Installed Not Installed	No.9					Mos	28-Aug-2024				
							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
256999		**Inspection Instructions For Continued Airworthiness (Ica) Ica Ref: Artex Document 570-5060 Rev C And Far 91.207D**							RE			
25 A/F							Mos	30-Aug-2024	12		30-Aug-2025	5.9 Months
							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
256D62		**AED Defibrillator**							RE (O/C)			
25 A/F	M5068A A15J-07694						Mos	23-Dec-2015				
							Hrs					
							Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
25C001C	**HYDROSTATIC TEST NO. 1 LIFERAFT CYLINDER**							RE			
25 A/F	No.1					Mos	20-Nov-2024	72		12-Nov-2030	5.7 Years
RAF1206-305T					0	Hrs	13,446.1				
1121011158H					0	Ldg	9,086				
Hydrostatic Tested Date 12-Nov-2024					0	Flt	9,086				
25-CMM-001	**Life Raft - Inspection**							RE			
25 A/F	No.1					Mos	20-Nov-2024	12		20-Nov-2025	8.6 Months
RAF1206-305T						Hrs	13,446.1				
1121011158H						Ldg	9,086				
(SOURCE: Vendor)						Flt	9,086				
25-CMM-001	**Life Raft - Inspection**							RE			
25 A/F	No.2					Mos	20-Nov-2024	12		20-Nov-2025	8.6 Months
RAF1206-305T1						Hrs	13,446.1				
1120090851H						Ldg	9,086				
(SOURCE: Vendor)						Flt	9,086				
25-CMM-002	**Life Raft ELT - Battery replacement**							RE (Due)		Replacement	
25 A/F	No.1					Mos	20-Nov-2024			30-Apr-2029	4.2 Years
RAF1206-305T						Hrs	13,446.1				
1121011158H						Ldg	9,086				
Expiration Date 30-Apr-2029						Flt	9,086				
25-CMM-002	**Life Raft ELT - Battery replacement**							RE (Due)		Replacement	
25 A/F	No.2					Mos	20-Nov-2024			30-Apr-2029	4.2 Years
RAF1206-305T1						Hrs	13,446.1				
1120090851H						Ldg	9,086				
Expiration Date 30-Apr-2029						Flt	9,086				
25-CUS-003	**Recertify Life Raft**							RE			
25 A/F	No.1					Yrs	20-Nov-2024	3		20-Nov-2027	2.7 Years
RAF1206-305T						Hrs	13,446.1				
1121011158H						Ldg	9,086				
						Flt	9,086				
25-CUS-004	**Recertify Life Raft**							RE			
25 A/F	No.2					Yrs	20-Nov-2024	3		20-Nov-2027	2.7 Years
RAF1206-305T1						Hrs	13,446.1				
1120090851H						Ldg	9,086				
						Flt	9,086				
25-CUS-FAK	**First Aid Kit - Inspection**							RE			
25 A/F						Mos	04-Sep-2024	12		04-Sep-2025	6.1 Months
FL220-FAKAA						Hrs	13,386.3				
0119-1128						Ldg	9,044				
Inspected Date 04-Sep-2024						Flt	9,043				
74-08-09 R2	**Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles**							RE (-)		Mandatory	
25 A/F						Mos	03-Jun-2011				
Eff: 06-Aug-1974 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
74-08-09 R2 Paragraph (g)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
(ISSUING AUTHORITY: FAA)					Ldg					
					Flt					
74-08-09 R2 Paragraph (h)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking" sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking" sign, the required procedure must provide that the announcement be made prior to each takeoff.**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
(ISSUING AUTHORITY: FAA)					Ldg					
					Flt					
74-08-09 R2 Paragraph (i)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
(ISSUING AUTHORITY: FAA)					Ldg					
					Flt					
74-08-09 R2 Paragraph (j)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
(ISSUING AUTHORITY: FAA)					Ldg					
					Flt					
74-08-09 R2 Paragraph (k)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974					Hrs					
(ISSUING AUTHORITY: FAA)					Ldg					
					Flt					
74-08-09 R3	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles**						RE (-)		Mandatory	
25 A/F					Mos	03-Feb-2017				
Eff: 28-Mar-2012 Complied With					Hrs					
(ISSUING AUTHORITY: FAA)					Ldg					
					Flt					
74-08-09 R3 Paragraph (g)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - (1) Install a placard on each side of each lavatory door over the door knob, or on each side of each lavatory door, or adjacent to each side of each lavatory door. (2) Install a placard on or near each lavatory paper or linen waste disposal receptacle door, containing the legible words or symbology indicating "No Cigarette Disposal."**						RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974 Complied With					Hrs					
(ISSUING AUTHORITY: FAA)					Ldg					
					Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
74-08-09 R3 Paragraph (h)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - establish a procedure that requires that, no later than a time immediately after the "No Smoking'' sign is extinguished following takeoff, an announcement be made by a crewmember to inform all aircraft occupants that smoking is prohibited in the aircraft lavatories; except that, if the aircraft is not equipped with a "No Smoking'' sign, the required procedure must provide that the announcement be made prior to each takeoff.**							RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
74-08-09 R3 Paragraph (i)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Install a self-contained, removable ashtray on or near the entry side of each lavatory door. One ashtray may serve more than one lavatory door if the ashtray can be seen readily from the cabin side of each lavatory door served.**							RE (-)		Mandatory	
25 A/F					Mos					
Eff: 06-Aug-1974 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
74-08-09 R3 Paragraph (j)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - An airplane with multiple lavatory doors may be operated with up to 50 percent of the lavatory door ashtrays missing or inoperative, provided 50 percent of the missing or inoperative ashtrays are replaced within 3 days and all remaining missing or inoperative ashtrays are replaced within 10 days. An airplane with only 1 lavatory door may be operated for a period of 10 days with the lavatory door ashtray missing or inoperative**							T (A/R)		Mandatory	
25 A/F					Mos					
Eff: 28-Mar-2012 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
74-08-09 R3 Paragraph (k)	**Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.**							RE		Mandatory	**≈15-Jul-2026**
25 A/F					Mos		03-Feb-2017				
Eff: 06-Aug-1974 Complied With						Hrs	13,018.4	1,000		14,018.4	497.5 Hrs
(ISSUING AUTHORITY: FAA)						Ldg	8,809				
						Flt					
83-01-06	**Inflatable Life Preservers and Individual Flotation Devices**							RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos		24-Mar-2021				
Eff: 28-Feb-1983						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
83-11-03	**Attendant Restraint System Rotary Buckle Assemblies**							RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos		24-Mar-2021				
Eff: 18-Jul-1983						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
98-25-10	**Aircraft Belts, Inc - Seat Restraint Systems** **(Superseded by FAA AD 98-25-10 R1)**							RE (-)		Mandatory (Appliance AD)	
25 A/F					Mos		13-Jan-1999				
						Hrs	8,749.8				
(ISSUING AUTHORITY: FAA)						Ldg	6,277				
						Flt					
F50-055	**Pilot and copilot seats - Back-rest hinge reinforcement**							T (A/R)			
25 A/F					Mos						
Eff: 29-Oct-1980						Hrs					
						Ldg					
Note: M0302, A/C with pilot/copilot seats P/N 394-10 and 394-20						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-085	**Cockpit - Front floors made even**							RE (-)			
25 A/F						Mos	09-Apr-1984				
Complied With						Hrs					
						Ldg					
Note: M0687A						Flt					
F50-085 R1	**Cockpit - Front floors made even**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
Note: M0687A						Flt					
F50-085 R2	**Cockpit - Front floors made even**							T (A/R)			
25 A/F						Mos					
Eff: 28-Sep-1981						Hrs					
						Ldg					
Note: M0687A						Flt					
F50-097	**ELT - New location to prevent overheating**							RE (-)			
25 A/F						Mos					
Eff: 29-Dec-1982						Hrs					
						Ldg					
Note: M0605B, 2 to 40 with a JOLLIET JE2 ELT (option 25 -61-02)						Flt					
F50-127	**Cockpit - Additional draining of headliner**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
Note: M0896A, M1478A, 2 to 127 and 128 to 352 with M1478A not recorded "complied with" or "not applicable" in the Inspection Handbook						Flt					
F50-127 R1	**Cockpit - Additional draining of headliner**							T (A/R)			
25 A/F						Mos					
Eff: 24-Jan-1990						Hrs					
						Ldg					
Note: M0896A, M1478A, 2 to 127 and 128 to 352 with M1478A not recorded "complied with" or "not applicable" in the Inspection Handbook						Flt					
F50-142	**Installation of on-board ladder in the aft compartment**							T (A/R)			
25 A/F						Mos					
Eff: 26-Jul-1984						Hrs					
						Ldg					
Note: M1132						Flt					
F50-153	**ELT - Isolation of the tape antenna**							T (A/R)			
25 A/F						Mos					
Eff: 26-Apr-1984						Hrs					
						Ldg					
Note: M0110, A/C with a JOLIET JE2 ELT before Dec. 1983 (Option AMD to BA No 25- 61-02)						Flt					
F50-180	**Cockpit - Draining of overhead panels between frames 7 and 9**							T (A/R)			
25 A/F						Mos					
Eff: 24-Jan-1990						Hrs					
						Ldg					
Note: M1178, M1378, M1478B						Flt					
F50-195	**Toilet drain sealing**							T (A/R)			
25 A/F						Mos					
Eff: 27-Jan-1988						Hrs					
						Ldg					
Note: M1451, A/C with a KOEHLER to DAYTON 250001-11 toilet (options: 25-25-00, 25-25-11, 25-25-12, 25-25-17, 25-25-20, 25-25-29, 25 -25-30)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-282	**Installation of a three-frequency ELT**							T (A/R)			
25 A/F						Mos					
Eff: 31-May-2000						Hrs					
						Ldg					
Note: M2360, M2356, M2361, A/C with SOCATA ELT90 or ELT91 2 to freq. ELT						Flt					
F50-358	**Cockpit - Improved protection of wiring and cables against interference with throttle controls**							T (A/R)			
25 A/F						Mos					
Eff: 10-Apr-2002						Hrs					
						Ldg					
Note: M2796, M2704						Flt					
F50-392	**Equipment/furnishings - Isolation of cabin electrical components (Superseded by SB F50-509) (No longer applicable)**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
Note: M2893						Flt					
F50-392 R1	**Equipment/furnishings - Isolation of cabin electrical components (Superseded by SB F50-509) (No longer applicable)**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
Note: M2893						Flt					
F50-392 R2	**Equipment/furnishings - Isolation of cabin electrical components (Superseded by SB F50-509) (No longer applicable)**							RE (-)			
25 A/F						Mos					
Eff: 09-Mar-2006						Hrs					
						Ldg					
Note: M2893						Flt					
F50-398	**Rear toilet unit - Improved drainage**							RE (-)			
25 A/F						Mos					
Eff: 10-Apr-2003						Hrs					
						Ldg					
Note: M2837						Flt					
F50-406	**Seat belts and harnesses - Replacement of ANJOU AERO type 343 or 343-1 with 349**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
Note: M2822, A/C with ANJOU AERO type 343 or 343-1 seat belts and/or harnesses						Flt					
F50-406 R1	**Seat belts and harnesses - Replacement of ANJOU AERO type 343 or 343-1 with 349**							T (A/R)			
25 A/F						Mos					
Eff: 10-Apr-2003						Hrs					
						Ldg					
Note: M2822, A/C with ANJOU AERO type 343 or 343-1 seat belts and/or harnesses						Flt					
F50-408	**Pilot seats P/N 394-11and 394-21 - New forward stops for increased control column travel**							T (A/R)			
25 A/F						Mos					
Eff: 10-Jul-2003						Hrs					
						Ldg					
Note: M2801, 2 to 139, 141, 143, 145, 146 with SICMA AEROSEAT pilot seats P/N 394-11 and 394-21 without seat cushion cutout						Flt					
F50-417	**New "No smoking/fasten seat belts" and "Return to seat" ordinance signs**							T (A/R)			
25 A/F						Mos					
Eff: 14-Feb-2003						Hrs					
						Ldg					
Note: M2862						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-437	**Replacement of bar galley lighting tube power supply wire**							T (A/R)			
25 A/F						Mos					
Eff: 22-Mar-2005						Hrs					
						Ldg					
Note: M2944, 2 to 251 outfitted by DASSAULT AVIATION and with a bar galley lighting tube power supply wire as illustrated in figure 4 of this SB						Flt					
F50-456	**Galley wiring inspection**							RE (-)			
25 A/F						Mos	31-Mar-2007				
Eff: 27-Oct-2006						Hrs	10,527.5				
						Ldg	7,387				
Note: AD EASA 2006-0329						Flt					
F50-458-1	**Headliner - PSU wire inspection**							RE (-)			
25 A/F						Mos					
Eff: 15-Dec-2004						Hrs					
						Ldg					
Note: STC SA7079SWD						Flt					
F50-467	**Passenger Service Unit (PSU) - Air gasper duct replacement**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
Note: M3020						Flt					
F50-467 R1	**Passenger Service Unit (PSU) - Air gasper duct replacement**							RE (-)			
25 A/F						Mos					
Eff: 14-Jun-2007						Hrs					
						Ldg					
Note: M3020						Flt					
F50-471	**Disabling the coffee maker**							RE (-)			
25 A/F						Mos	31-Mar-2007				
Eff: 27-Oct-2006						Hrs	10,527.5				
						Ldg	7,387				
Note: AD EASA 2006-0329						Flt					
F50-479	**Equipment and Furnishings - Pilot Seats P/N 394-14 and 394-24 - Modifications for Improved Pull-Up Travel of Control Columns**							RE (-)			
25 A/F						Mos					
Eff: 12-Jul-2007						Hrs					
						Ldg					
Note: M3014						Flt					
F50-479-R1	**Equipment and Furnishings - Pilot Seats P/N 394-1XXX and 394-2XXX - Modifications for Improved Pull-Up Travel of Control Columns**							T (-)		Optional	
25 A/F						Mos					
Eff: 22-May-2019						Hrs					
(AVG MAN HRS: 14)						Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to aircraft equipped with LEM M83 pilot microphones by application of Service Bulletin F50-405 or modification MF50 M2830.						Flt					
F50-479-R2	**Equipment and Furnishings - Pilot Seats P/N 394-1XXX and 394-2XXX - Modifications for Improved Pull-Up Travel of Control Columns**							RE (-)		Optional	
25 A/F						Mos					
Eff: 29-Nov-2023						Hrs					
MOD:M3014 (AVG MAN HRS: 14)						Ldg					
						Flt					
F50-480	**Life rafts - Checking installation clearances for easy removal**							RE (-)			
25 A/F						Mos	24-Aug-2007				
Eff: 08-Dec-2006						Hrs	10,670.1				
						Ldg	7,474				
Note: AD 2006-0366 (AD FAA 2008-05-08)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-487	**Sound proofing - Removal and replacement of 4319N neoprene**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
Note: M2978						Flt					
F50-487 R1	**Sound proofing - Removal and replacement of 4319N neoprene**							T (A/R)			
25 A/F						Mos					
Eff: 13-Dec-2006	Customer requested not to be done at this time.					Hrs					
						Ldg					
Note: M2978						Flt					
F50-491	**Alternate current power generation - New KGS inverters installation**							T (A/R)			
25 A/F						Mos					
Eff: 25-May-2007						Hrs					
						Ldg					
Note: M2905, A/C with KGS AC power inverters P/N SB120 &/or SS120						Flt					
F50-492	**Installation of ELTA 406 MHZ ELT**							RE (-)			
25 A/F						Mos					
Eff: 01-Jul-2009						Hrs					
						Ldg					
Note: M2861, 256, 270 to 352 with M2356, M2360 or M2361 or SB F50-282 (3-frequency ELT)						Flt					
F50-509	**Cabin electrical equipment isolation - Installation of plastic inserts (On hold)**							RE (-)			
25 A/F						Mos					
Eff: 18-Feb-2011						Hrs					
						Ldg					
Note: M3121, A/C equipped with DFJ completion.						Flt					
F50-509 R1	**Cabin Electrical Equipment Isolation - Installation of Plastic Inserts**							RE (-)		Optional	
25 A/F						Mos					
Eff: 22-Jul-2016						Hrs					
(AVG MAN HRS: 10)						Ldg					
						Flt					
F50-513	**Cabin varnished veneer items - Sampling and chemical analysis**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-513 R1	**Cabin varnished veneer items - Sampling and chemical analysis**							RE (-)			
25 A/F						Mos					
Eff: 05-Feb-2013						Hrs					
						Ldg					
						Flt					
F50-514	**Cabin varnished veneer items rework**							RE (-)			
25 A/F						Mos					
Eff: 05-Feb-2013						Hrs					
						Ldg					
Note: R1672, AD EASA 2014-0082						Flt					
F50-524	**Pilot and copilot seats - installation improvement**							RE (-)			
25 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C which have already performed their first "C" inspection and with pilot seats P/N 394 series						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-524 R1	**Pilot and copilot seats - installation improvement**							RE (-)			
25 A/F						Mos	16-Oct-2013				
Eff: 27-Jul-2012						Hrs	11,682.33				
						Ldg	8,099				
Note: A/C which have already performed their first "C" inspection and with pilot seats P/N 394 series						Flt					
F50-545	**Equipment/ Furnishings - Coffee Maker - Suppression of Interference Between Rack Guiding Pin and Coffee Maker**							T (A/R)		Recommended	
25 A/F						Mos					
Eff: 12-May-2016						Hrs					
(AVG MAN HRS: 1)						Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to MYSTERE-FALCON 50 aircraft that are equipped with Iacobucci coffee maker P/N HFE96-28xxx.						Flt					
F50-S036	**Equipment - Furnishing - Cockpit - Air Lite Rechargeable Flashlights Installation**							T (A/R)		Optional	
25 A/F						Mos					
Eff: 14-Sep-2021						Hrs					
						Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to F50 aircraft with serial numbers 2 thru 352 equipped with Astronics EF-2C Rechargeable Utility flashlight P/N P2-07-0009-520 in the cockpit afterward bulkhead(s).						Flt					
▼ 26 - FIRE PROTECTION											
	APU Fire Detector							RE (O/C)			
26 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	APU Fire Extinguisher Percussion (28W) Cartridge							RE (H/T)			
26 A/F						Mos	30-Aug-2024				
13083-5	Serviceable					Hrs	13,386.3				
48394						Ldg	9,044				
						Flt	9,043				
	Baggage Compartment Fire Extinguisher Percussion (23W) Cartridge							RE (H/T)			
26 A/F						Mos	30-Aug-2024				
13083-5	Serviceable					Hrs	13,386.3				
4406						Ldg	9,044				
						Flt	9,043				
	Baggage Compartment Smoke Detector							RE (O/C)			
26 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine 1 First-Shoot Fire Extinguisher Percussion (L14W) Cartridge							RE (H/T)			
26 A/F						Mos	14-Sep-2023				
861385	Tested/Inspected					Hrs	13,276.7				
01466						Ldg	8,977				
						Flt	8,977				
	Engine 1 Second-Shoot Fire Extinguisher Percussion (L15W) Cartridge							RE (H/T)			
26 A/F						Mos	14-Sep-2023				
861385	Tested/Inspected					Hrs	13,276.7				
26						Ldg	8,977				
						Flt	8,977				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine 2 First-Shoot Fire Extinguisher Percussion (M14W) Cartridge							RE (H/T)			
26 A/F							Mos	28-Dec-2023				
861375		New	0				Hrs	13,288.4				
Unknown			0				Ldg	8,991				
			0				Flt	8,991				
		Engine 2 Second-Shoot Fire Extinguisher Percussion (M15W) Cartridge							RE (H/T)			
26 A/F							Mos	14-Sep-2023				
861385		New	0				Hrs	13,276.7				
02111			0				Ldg	8,977				
			0				Flt	8,977				
		Engine 3 First-Shoot Fire Extinguisher Percussion (R14W) Cartridge							RE (H/T)			
26 A/F							Mos	16-Feb-2024				
M861375		New	0				Hrs	13,292.4				
1969			0				Ldg	8,992				
			0				Flt	8,992				
		Engine 3 Second-Shoot Fire Extinguisher Percussion (R15W) Cartridge							RE (H/T)			
26 A/F							Mos	16-Feb-2024				
861385		New	0				Hrs	13,292.4				
Unknown			0				Ldg	8,992				
			0				Flt	8,992				
		Engine Dual Check Valve							RE (O/C)			
26 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Dual Check Valve							RE (O/C)			
26 A/F		No.2					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Dual Check Valve							RE (O/C)			
26 A/F		No.3					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Fire Detector							RE (O/C)			
26 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Fire Detector							RE (O/C)			
26 A/F		No.2					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Fire Detector							RE (O/C)			
26 A/F		No.3					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fire Warning Panel							RE (O/C)			
26 A/F	75-0361-1 40	Serviceable					Mos Hrs Ldg Flt	29-Nov-2023 13,287.4 8,989 8,989				
		Main Landing Gear (MLG) Bay Fire Detector							RE (O/C)			
26 A/F	Unknown Unknown	Left					Mos Hrs Ldg Flt	20-Jan-1981 0 0				
		Main Landing Gear (MLG) Bay Fire Detector							RE (O/C)			
26 A/F	Unknown Unknown	Right					Mos Hrs Ldg Flt	20-Jan-1981 0 0				
		Portable Fire Extinguisher							RE (H/T)			
26 A/F	898052 Y-605551	Cockpit					Mos Hrs Ldg Flt	16-Oct-2013 13,160.9 8,909				
		Portable Fire Extinguisher (Cabin)							RE (H/T)			
26 A/F	860640 57702	No.1 Serviceable					Mos Hrs Ldg Flt	24-Mar-2021				
		Rear Compartment Fire Detector							RE (O/C)			
26 A/F	Unknown Unknown						Mos Hrs Ldg Flt	20-Jan-1981 0 0				
		Rear Compartment Fire Extinguisher Percussion (24W) Cartridge							RE (H/T)			
26 A/F	13083-5 4426	Right Serviceable					Mos Hrs Ldg Flt	30-Aug-2024 13,386.3 9,044 9,043				
		Rear Compartment Fire Extinguisher Percussion (25W) Cartridge							RE (H/T)			
26 A/F	13083-5 44880	Left Tested/Inspected					Mos Hrs Ldg Flt	14-Sep-2023 13,276.7 8,977 8,977				
2001-22-14		**Overland Aviation Services - Fire Extinguishing System Bottle Cartridges - Check/ Replace**							RE (-)		Mandatory (Appliance AD)	
26 A/F	Eff: 10-Dec-2001 Not Applicable	by manufacturer (AVG MAN HRS: 8) (ISSUING AUTHORITY: FAA)					Mos Hrs Ldg Flt	14-Sep-2003				
2003-26-14		**Kidde Aerospace - Hand-Held Halon Fire Extinguishers Removal**							RE (-)		Mandatory (Appliance AD)	
26 A/F	Eff: 20-Feb-2004 Not Applicable	due to SN range Brand A:9990-2003-26-14 (AVG MAN HRS: 1) (APX COST: 60) (ISSUING AUTHORITY: FAA)					Mos Hrs Ldg Flt	21-Jan-2005				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2010-04-16	**SICLI Halon 1211 Portable Fire Extinguishers as Installed on Various Airplanes and Rotorcraft**							RE (-)		Mandatory	
26 A/F						Mos	24-Mar-2021				
Eff: 08-Mar-2010 Not Applicable	By manufacture					Hrs					
						Ldg					
Brand A:9990-2010-04-16 (ISSUING AUTHORITY: FAA)						Flt					
Note: Applicability: This AD applies to Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers manufactured by SICLI, having part number (P/N) 1708337B4 and having any serial number listed in Table 1 of this AD.											
2010-24-08 Paragraph (g)	**Landing Gear - two pipes of the emergency brake system 2 located near the nose landing gear bearing - do a general visual inspection for correct installation**							RE (-)		Mandatory	
26 A/F						Mos					
Eff: 09-Dec-2010						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2010-24-08 Paragraph (h)	**Landing Gear - two pipes of the emergency brake system 2 located near the nose landing gear bearing - If the emergency brake system number 2 is found installed incorrectly during the inspection required by paragraph (g) of this AD: Before further flight, install the emergency brake system number 2 correctly**							RE (-)		Mandatory	
26 A/F						Mos					
Eff: 09-Dec-2010						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2011-07-11	**Fire protection - Visually inspect the extinguishing system line and the low pressure bleed line of the number 2 engine at frame 42 in the rear compartment to determine proper installation of the lines**							RE (-)		Mandatory	
26 A/F						Days	20-Apr-2011				
Eff: 18-Apr-2011 Complied With						Hrs	11,347				
(ISSUING AUTHORITY: FAA)						Ldg	7,914				
						Flt					
2019-23-18	**Fire Protection - Total Life Limit of the Fire Extinguisher Percussion Cartridges**							RE (-)		Mandatory	
26 A/F						Mos	24-Mar-2021				
Eff: 17-Jan-2020 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
26-10-00-720-801-01	**Functional Test of the Pneumatic Fire Detectors - Engine 1 Fire Detector (L2W)**							RE		Comp Maint Ops (5-20)	**≈02-Oct-2035**
26 A/F	No.1					Mos	20-May-2014				
Unknown						Hrs	11,737.43	5,600		17,337.43	3,816.53 Hrs
Unknown						Ldg	8,122				
						Flt					
Note: P/N 30016190040013 or 360113290040021 To be performed during an engine removal without exceeding 5600 h											
26-10-00-720-801-01 (5-40)	**Functional Test of the Pneumatic Fire Detectors - Engine 1 Fire Detector (L2W)**							RE		AWL (5-40), CMR	**≈02-Oct-2035**
26 A/F	No.1					Mos	20-May-2014				
Unknown						Hrs	11,737.43	5,600		17,337.43	3,816.53 Hrs
Unknown						Ldg	8,122				
						Flt					
Note: P/N 30016190040013 or 360113290040021 To be performed during an engine removal without exceeding 5600 h											
26-10-00-720-801-02	**Functional Test of the Pneumatic Fire Detectors - Engine 2 Fire Detector (M2W)**							RE		Comp Maint Ops (5-20)	**≈02-Oct-2035**
26 A/F	No.2					Mos	20-May-2014				
Unknown						Hrs	11,737.43	5,600		17,337.43	3,816.53 Hrs
Unknown						Ldg	8,122				
						Flt					
Note: P/N 30016190040013 or 360113290040021 To be performed during an engine removal without exceeding 5600 h											

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-10-00-720-801-02 (5-40)	**Functional Test of the Pneumatic Fire Detectors - Engine 2 Fire Detector (M2W)**							RE		AWL (5-40), CMR	**≈02-Oct-2035**
26 A/F	No.2					Mos	20-May-2014				
Unknown						Hrs	11,737.43	5,600		17,337.43	3,816.53 Hrs
Unknown						Ldg	8,122				
						Flt					
	Note: P/N 30016190040013 or 360113290040021 To be performed during an engine removal without exceeding 5600 h										
26-10-00-720-801-03	**Functional Test of the Pneumatic Fire Detectors - Engine 3 Fire Detector (R2W)**							RE		Comp Maint Ops (5-20)	**≈02-Oct-2035**
26 A/F	No.3					Mos	20-May-2014				
Unknown						Hrs	11,737.43	5,600		17,337.43	3,816.53 Hrs
Unknown						Ldg	8,122				
						Flt					
	Note: P/N 30016190040013 or 360113290040021 To be performed during an engine removal without exceeding 5600 h										
26-10-00-720-801-03 (5-40)	**Functional Test of the Pneumatic Fire Detectors - Engine 3 Fire Detector (R2W)**							RE		AWL (5-40), CMR	**≈02-Oct-2035**
26 A/F	No.3					Mos	20-May-2014				
Unknown						Hrs	11,737.43	5,600		17,337.43	3,816.53 Hrs
Unknown						Ldg	8,122				
						Flt					
	Note: P/N 30016190040013 or 360113290040021 To be performed during an engine removal without exceeding 5600 h										
26-10-00-720-801-04	**Functional Test of the Pneumatic Fire Detectors - APU Fire Detector (72W)**							RE		Comp Maint Ops (5-20)	**≈15-Jun-2030**
26 A/F						Mos	25-May-2003				
Unknown						Hrs	9,829.4	5,600		15,429.4	1,908.5 Hrs
Unknown						Ldg	6,932				
						Flt					
	Note: P/N 30011690040012 To be performed during an APU inspection without exceeding 5600 h										
26-10-00-720-801-04 (5-40)	**Functional Test of the Pneumatic Fire Detectors - APU Fire Detector (72W)**							RE		AWL (5-40), CMR	**≈15-Jun-2030**
26 A/F						Mos	25-May-2003				
Unknown						Hrs	9,829.4	5,600		15,429.4	1,908.5 Hrs
Unknown						Ldg	6,932				
						Flt					
	Note: P/N 30011690040012 To be performed during an APU inspection without exceeding 5600 h										
26-10-00-720-801-05	**Functional Test of the Pneumatic Fire Detectors - Rear Compartment Fire Detector (22W)**							RE		Comp Maint Ops (5-20)	**≈22-Feb-2031**
26 A/F						Mos	20-May-2005				
Unknown						Hrs	10,077.9	5,600		15,677.9	2,157 Hrs
Unknown						Ldg	7,109				
						Flt					
	Note: P/N 300123860027014 or 30015160027012 no tolerance										
26-10-00-720-801-05 (5-40)	**Functional Test of the Pneumatic Fire Detectors - Rear Compartment Fire Detector (22W)**							RE		AWL (5-40), CMR	**≈22-Feb-2031**
26 A/F						Mos	20-May-2005				
Unknown						Hrs	10,077.9	5,600		15,677.9	2,157 Hrs
Unknown						Ldg	7,109				
						Flt					
	Note: P/N 300123860027014 or 30015160027012 no tolerance										
26-10-00-720-801-06	**Functional Test of the Pneumatic Fire Detectors - LH MLG Bay Fire Detector (29W1)**							RE		Comp Maint Ops (5-20)	**≈22-Feb-2031**
26 A/F	Left					Mos	20-May-2005				
Unknown						Hrs	10,077.9	5,600		15,677.9	2,157 Hrs
Unknown						Ldg	7,109				
						Flt					
	Note: P/N 3001198002703 no tolerance										

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-10-00-720-801-06 (5-40)	**Functional Test of the Pneumatic Fire Detectors - LH MLG Bay Fire Detector (29W1)**							RE		AWL (5-40), CMR	**≈22-Feb-2031**
26 A/F	Left					Mos	20-May-2005				
Unknown						Hrs	10,077.9	5,600		15,677.9	2,157 Hrs
Unknown						Ldg	7,109				
						Flt					
	Note: P/N 3001198002703 no tolerance										
26-10-00-720-801-07	**Functional Test of the Pneumatic Fire Detectors - RH MLG Bay Fire Detector (29W2)**							RE		Comp Maint Ops (5-20)	**≈22-Feb-2031**
26 A/F	Right					Mos	20-May-2005				
Unknown						Hrs	10,077.9	5,600		15,677.9	2,157 Hrs
Unknown						Ldg	7,109				
						Flt					
	Note: P/N 3001198002703 no tolerance										
26-10-00-720-801-07 (5-40)	**Functional Test of the Pneumatic Fire Detectors - RH MLG Bay Fire Detector (29W2)**							RE		AWL (5-40), CMR	**≈22-Feb-2031**
26 A/F	Right					Mos	20-May-2005				
Unknown						Hrs	10,077.9	5,600		15,677.9	2,157 Hrs
Unknown						Ldg	7,109				
						Flt					
	Note: P/N 3001198002703 no tolerance										
26-20-01-760-801-01	**Check of the Correct Operation of Fire Extinguisher Control Switches - "Eng 1" Selector Switch (Position "1")**							RE		Acft Maint Ops (5-10)	
26 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
26-20-01-760-801-02	**Check of the Correct Operation of Fire Extinguisher Control Switches - "Eng 1" Selector Switch (Position "2")**							RE		Acft Maint Ops (5-10)	
26 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
26-20-01-760-801-03	**Check of the Correct Operation of Fire Extinguisher Control Switches - "Eng 2" Selector Switch (Position "1")**							RE		Acft Maint Ops (5-10)	
26 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
26-20-01-760-801-04	**Check of the Correct Operation of Fire Extinguisher Control Switches - "Eng 2" Selector Switch (Position "2")**							RE		Acft Maint Ops (5-10)	
26 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
	(Tol. Adjustment: -225.9d)					Ldg	8,977				
						Flt	8,977				
26-20-01-760-801-05	**Check of the Correct Operation of Fire Extinguisher Control Switches - "Eng 3" Selector Switch (Position "1")**							RE		Acft Maint Ops (5-10)	
26 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
	(Tol. Adjustment: -225.9d)					Ldg	8,977				
						Flt	8,977				
26-20-01-760-801-06	**Check of the Correct Operation of Fire Extinguisher Control Switches - "Eng 3" Selector Switch (Position "2")**							RE		Acft Maint Ops (5-10)	
26 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
	(Tol. Adjustment: -225.9d)					Ldg	8,977				
						Flt	8,977				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-01-760-801-07		**Check of the Correct Operation of Fire Extinguisher Control Switches - "Fire APU" Selector Switch**							RE		Acft Maint Ops (5-10)	
26 A/F		05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
							Hrs	13,276.7				
(Tol. Adjustment: -225.9d)							Ldg	8,977				
							Flt	8,977				
26-20-01-760-801-08		**Check of the Correct Operation of Fire Extinguisher Control Switches - "Fire Bag Comp" Selector Switch**							RE		Acft Maint Ops (5-10)	
26 A/F		05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
							Hrs	13,276.7				
(Tol. Adjustment: -225.9d)							Ldg	8,977				
							Flt	8,977				
26-20-01-760-801-09		**Check of the Correct Operation of Fire Extinguisher Control Switches - "Fire Aft Comp" Selector Switch**							RE		Acft Maint Ops (5-10)	
26 A/F		05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
							Hrs	13,276.7				
(Tol. Adjustment: -225.9d)							Ldg	8,977				
							Flt	8,977				
26-20-09-220-801-01		**Weighing of the Fire Extinguishers - Engine 1 First-Shoot, Engine 2 Second-Shoot Fire Extinguisher (14W1)**							RE		Comp Maint Ops (5-20)	
26 A/F							Yrs	30-Aug-2024	1		30-Aug-2025	5.9 Months
860640							Hrs	13,386.3				
359							Ldg	9,044				
Weighed Date 30-Aug-2024							Flt	9,043				
		Note: P/N 860640										
		No tolerance										
26-20-09-220-801-02		**Weighing of the Fire Extinguishers - Engine 2 First-Shoot, Engine 3 Second-Shoot Fire Extinguisher (14W2)**							RE		Comp Maint Ops (5-20)	
26 A/F							Yrs	30-Aug-2024	1		30-Aug-2025	5.9 Months
860640							Hrs	13,386.3				
50448							Ldg	9,044				
Weighed Date 30-Aug-2024							Flt	9,043				
		Note: P/N 860640										
		No tolerance										
26-20-09-220-801-03		**Weighing of the Fire Extinguishers - Engine 3 First-Shoot, Engine 1 Second-Shoot Fire Extinguisher (14W3)**							RE		Comp Maint Ops (5-20)	
26 A/F							Yrs	30-Aug-2024	1		30-Aug-2025	5.9 Months
860640							Hrs	13,386.3				
20587							Ldg	9,044				
Weighed Date 30-Aug-2024							Flt	9,043				
		Note: P/N 860640										
		No tolerance										
26-20-09-220-801-04		**Weighing of the Fire Extinguishers - APU Fire Extinguisher (73W)**							RE		Comp Maint Ops (5-20)	
26 A/F							Yrs	30-Aug-2024	1		30-Aug-2025	5.9 Months
30111102							Hrs	13,386.3				
08102A1							Ldg	9,044				
Weighed Date 30-Aug-2024							Flt	9,043				
		Note: P/N 30111102										
		No tolerance										
26-20-09-220-801-05		**Weighing of the Fire Extinguishers - Rear Compartment Fire Extinguisher (23W1)**							RE		Comp Maint Ops (5-20)	
26 A/F		Left					Yrs	30-Aug-2024	1		30-Aug-2025	5.9 Months
30702102							Hrs	13,386.3				
03954D2							Ldg	9,044				
Weighed Date 30-Aug-2024							Flt	9,043				
		Note: P/N 30702102 or 30702102-1										
		No tolerance										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-09-220-801-06	**Weighing of the Fire Extinguishers - Rear/Baggage Compartment Fire Extinguisher (23W2)**							RE		Comp Maint Ops (5-20)	
26 A/F	Right					Yrs	30-Aug-2024	1		30-Aug-2025	5.9 Months
30702102						Hrs	13,386.3				
09429D2						Ldg	9,044				
Weighed Date 30-Aug-2024						Flt	9,043				
Note: P/N 30702102 or 30702102-1											
No tolerance											
26-20-09-350-801-01	**Restoration of the Fire Extinguishers (Hydrostatic Test and Pressure Gage Calibration) - Engine 1 First-Shoot, Engine 2 Second-Shoot Fire Extinguisher (14W1)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	24-Mar-2021	5		24-Mar-2026	1 Year
860640						Hrs					
359						Ldg					
Restored Date 24-Mar-2021						Flt					
Note: P/N 860640											
(1) No tolerance											
26-20-09-350-801-02	**Restoration of the Fire Extinguishers (Hydrostatic Test and Pressure Gage Calibration) - Engine 2 First-Shoot, Engine 3 Second-Shoot Fire Extinguisher (14W2)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	14-Sep-2023	5		02-May-2028	3.2 Years
860640					0	Hrs	13,276.7				
50448					0	Ldg	8,977				
Restored Date 02-May-2023					0	Flt	8,977				
Note: P/N 860640											
(1) No tolerance											
26-20-09-350-801-03	**Restoration of the Fire Extinguishers (Hydrostatic Test and Pressure Gage Calibration) - Engine 3 First-Shoot, Engine 1 Second-Shoot Fire Extinguisher (14W3)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	14-Sep-2023	5		02-May-2028	3.2 Years
860640					0	Hrs	13,276.7				
20587					0	Ldg	8,977				
Restored Date 02-May-2023					0	Flt	8,977				
Note: P/N 860640											
(1) No tolerance											
26-20-09-350-801-04	**Restoration of the Fire Extinguishers (Hydrostatic Test and Pressure Gage Calibration) - APU Fire Extinguisher (73W)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	14-Sep-2023	5		19-Apr-2028	3.1 Years
30111102					0	Hrs	13,276.7				
08102A1					0	Ldg	8,977				
Restored Date 19-Apr-2023					0	Flt	8,977				
Note: P/N 30111102											
(1) No tolerance											
26-20-09-350-801-05	**Restoration of the Fire Extinguishers (Hydrostatic Test and Pressure Gage Calibration) - Rear Compartment Fire Extinguisher (23W1)**							RE		Comp Maint Ops (5-20)	
26 A/F	Left					Yrs	14-Sep-2023	5		14-Apr-2028	3.1 Years
30702102					0	Hrs	13,276.7				
03954D2					0	Ldg	8,977				
Restored Date 14-Apr-2023					0	Flt	8,977				
Note: P/N 30702102 or 30702102-1											
(1) No tolerance											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-09-350-801-06		**Restoration of the Fire Extinguishers (Hydrostatic Test and Pressure Gage Calibration) - Rear/Baggage Compartment Fire Extinguisher (23W2)**							RE		Comp Maint Ops (5-20)	
26 A/F	30702102	Right				0	Yrs	14-Sep-2023	5		20-Apr-2028	3.1 Years
	09429D2					0	Hrs	13,276.7				
		Restored Date 20-Apr-2023				0	Ldg	8,977				
							Flt	8,977				
		Note: P/N 30702102 or 30702102-1 (1) No tolerance										
26-20-09-900-801-01		**Engine 1 First- Shoot, Engine 2 Second-Shoot Fire (14W1) Extinguisher**							RE (O/C)			
26 A/F	860640	Overhauled					Mos	09-Jan-2018				
	359						Hrs					
							Ldg					
							Flt					
26-20-09-900-801-02		**Engine 2 First- Shoot, Engine 3 Second-Shoot Fire (14W2) Extinguisher**							RE (O/C)			
26 A/F	860640	Overhauled		0			Mos	14-Sep-2023				
	50448			0			Hrs	13,276.7				
				0			Ldg	8,977				
							Flt	8,977				
26-20-09-900-801-03		**Engine 3 First- Shoot, Engine 1 Second-Shoot Fire (14W3) Extinguisher**							RE (O/C)			
26 A/F	860640	Overhauled		0			Mos	14-Sep-2023				
	20587			0			Hrs	13,276.7				
				0			Ldg	8,977				
							Flt	8,977				
26-20-09-900-802-01		**APU Fire Extinguisher (73W)**							RE (O/C)			
26 A/F	30111102	Overhauled		0			Mos	14-Sep-2023				
	08102A1			0			Hrs	13,276.7				
				0			Ldg	8,977				
							Flt	8,977				
26-20-09-900-803-01		**Rear/Baggage Compartment Fire Extinguisher (23W2)**							RE (O/C)			
26 A/F	30702102	Right					Mos	14-Sep-2023				
	09429D2	Overhauled		0			Hrs	13,276.7				
				0			Ldg	8,977				
				0			Flt	8,977				
26-20-09-900-804-01		**Rear Compartment Fire Extinguisher (23W1)**							RE (O/C)			
26 A/F	30702102	Left					Mos	14-Sep-2023				
	03954D2	Overhauled		0			Hrs	13,276.7				
				0			Ldg	8,977				
				0			Flt	8,977				
26-20-11-700-801-01		**Checking Extinguishing Lines For Clogging - APU Fire Extinguisher (73W)**							RE		Acft Maint Ops (5-10)	
26 A/F	30111102	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
	08102A1						Hrs	13,276.7				
		(Tol. Adjustment: -225.9d)					Ldg	8,977				
							Flt	8,977				
26-20-11-700-801-02		**Checking Extinguishing Lines For Clogging - Engine 1 First-Shoot, Engine 2 Second-Shoot Fire Extinguisher (14W1)**							RE		Acft Maint Ops (5-10)	
26 A/F	860640	05-10-00-1C					Yrs	02-Sep-2016	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
	359						Hrs	12,978.6				
							Ldg	8,785				
							Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-11-700-801-03	**Checking Extinguishing Lines For Clogging - Engine 2 First-Shoot, Engine 3 Second-Shoot Fire Extinguisher (14W2)**							RE		Acft Maint Ops (5-10)	
26 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
860640						Hrs	13,276.7				
Unknown						Ldg	8,977				
(Tol. Adjustment: -225.9d)						Flt	8,977				
26-20-11-700-801-04	**Checking Extinguishing Lines For Clogging - Engine 3 First-Shoot, Engine 1 Second-Shoot Fire Extinguisher (14W3)**							RE		Acft Maint Ops (5-10)	
26 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
860640						Hrs	13,276.7				
Unknown						Ldg	8,977				
(Tol. Adjustment: -225.9d)						Flt	8,977				
26-20-11-700-801-05	**Checking Extinguishing Lines For Clogging - Rear/Baggage Compartment Fire Extinguisher (23W2)**							RE		Acft Maint Ops (5-10)	
26 A/F	Right05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
30702102						Hrs	13,276.7				
09429D2						Ldg	8,977				
(Tol. Adjustment: -225.9d)						Flt	8,977				
26-20-11-700-801-06	**Checking Extinguishing Lines For Clogging - Rear Compartment Fire Extinguisher (23W1)**							RE		Acft Maint Ops (5-10)	
26 A/F	Left05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
30702102						Hrs	13,276.7				
03954D2						Ldg	8,977				
(Tol. Adjustment: -225.9d)						Flt	8,977				
26-20-13-760-801-01	**Insulation Test Engine 1 First- Shoot, Engine 2 Second-Shoot Fire (14W1) Extinguisher Engine 1 First-Shoot, Engine 2 Second-Shoot Percussion Cartridge System**							RE (A/R)			
26 A/F						Mos	30-Sep-2019				
860640						Hrs					
359						Ldg					
						Flt					
26-20-13-760-802-01	**Insulation Test Engine 2 First- Shoot, Engine 3 Second-Shoot Fire (14W2) Extinguisher Engine 2 First-Shoot, Engine 3 Second-Shoot Percussion Cartridge System**							RE (A/R)			
26 A/F						Mos	14-Sep-2023				
860640						Hrs	13,276.7				
50448						Ldg	8,977				
						Flt	8,977				
26-20-13-760-803-01	**Insulation Test Engine 3 First- Shoot, Engine 1 Second-Shoot Fire (14W3) Extinguisher Engine 3 First-Shoot, Engine 1 Second-Shoot Percussion Cartridge System**							RE (A/R)			
26 A/F						Mos	14-Sep-2023				
860640						Hrs	13,276.7				
20587						Ldg	8,977				
						Flt	8,977				
26-20-13-760-804-01	**Insulation Test Apu (73W) Fire Extinguisher Percussion Cartridge System**							RE (A/R)			
26 A/F						Mos	14-Sep-2023				
30111102						Hrs	13,276.7				
08102A1						Ldg	8,977				
						Flt	8,977				
26-20-13-760-805-01	**Insulation Test Rear/Baggage Compartment (23W2) Fire Extinguisher Percussion Cartridge System**							RE (A/R)			
26 A/F	Right					Mos	14-Sep-2023				
30702102						Hrs	13,276.7				
09429D2						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-13-760-806-01	**Insulation Test Rear Compartment (23W1) Fire Extinguisher Percussion Cartridge System**							RE (A/R)			
26 A/F	Left					Mos	14-Sep-2023				
30702102						Hrs	13,276.7				
03954D2						Ldg	8,977				
						Flt	8,977				
26-20-13-960-801-01	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 1 First-Shoot Percussion Cartridge (L14W) (Service Life)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	10-Nov-2021	5		10-Nov-2026	1.7 Years
861385						Hrs					
01466						Ldg					
						Flt					
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-01 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 1 First-Shoot Percussion Cartridge (L14W)**							RE		Comp Maint Ops (5-20), Life Limit	
26 A/F						Yrs	20-Oct-2021	7		20-Oct-2028	3.6 Years
861385						Hrs					
01466						Ldg					
	Manufactured Date 20-Oct-2021					Flt					
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-02	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 2 First-Shoot Percussion Cartridge (M14W) (Service Life)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	28-Dec-2023	5		28-Dec-2028	3.8 Years
861375						Hrs	13,288.4				
Unknown						Ldg	8,991				
						Flt	8,991				
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-02 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 2 First-Shoot Percussion Cartridge (M14W)**							RE		Comp Maint Ops (5-20), Life Limit	
26 A/F						Yrs	28-Dec-2023	7		30-Jun-2030	5.3 Years
861375						Hrs	13,288.4				
Unknown						Ldg	8,991				
	Manufactured Date 30-Jun-2023					Flt	8,991				
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-03	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 3 First-Shoot Percussion Cartridge (R14W) (Service Life)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	16-Feb-2024	5		16-Feb-2029	4 Years
M861375						Hrs	13,292.4				
1969						Ldg	8,992				
	(RII ITEM)					Flt	8,992				
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-03 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 3 First-Shoot Percussion Cartridge (R14W)**							RE		Comp Maint Ops (5-20), Life Limit	
26 A/F						Yrs	16-Feb-2024	7		01-Sep-2029	4.5 Years
M861375						Hrs	13,292.4				
1969						Ldg	8,992				
	Manufactured Date 01-Sep-2022					Flt	8,992				
	(RII ITEM)										
	Note: P/N 861375 or 861385										
	(6)										

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-13-960-801-04	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 1 Second-Shoot Percussion Cartridge (L15W) (Service Life)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	12-May-2022	5		12-May-2027	2.2 Years
861385						Hrs					
26						Ldg					
						Flt					
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-04 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 1 Second-Shoot Percussion Cartridge (L15W)**							RE		Comp Maint Ops (5-20), Life Limit	
26 A/F						Yrs	29-Apr-2022	7		29-Apr-2029	4.2 Years
861385						Hrs					
26						Ldg					
	Manufactured Date 29-Apr-2022					Flt					
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-05	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 2 Second-Shoot Percussion Cartridge (M15W) (Service Life)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	14-Sep-2023	5		14-Sep-2028	3.5 Years
						Hrs	13,276.7				
						Ldg	8,977				
	Note: P/N 861375 or 861385					Flt	8,977				
	(6)										
26-20-13-960-801-05 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 2 Second-Shoot Percussion Cartridge (M15W)**							RE		Comp Maint Ops (5-20), Life Limit	
26 A/F						Yrs	14-Sep-2023	7		30-Apr-2030	5.2 Years
	Manufactured Date 30-Apr-2023					Hrs	13,276.7				
						Ldg	8,977				
	Note: P/N 861375 or 861385					Flt	8,977				
	(6)										
26-20-13-960-801-06	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 3 Second-Shoot Percussion Cartridge (R15W) (Service Life)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	16-Feb-2024	5		16-Feb-2029	4 Years
861385						Hrs	13,292.4				
	Unknown					Ldg	8,992				
	(RII ITEM)					Flt	8,992				
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-06 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - Engine 3 Second-Shoot Percussion Cartridge (R15W)**							RE		Comp Maint Ops (5-20), Life Limit	
26 A/F						Yrs	16-Feb-2024	7		[24-Jan-2028]	2.9 Years
861385						Hrs	13,292.4				
	Unknown					Ldg	8,992				
	Manufactured Date 01-Mar-2021					Flt	8,992				
	(RII ITEM)										
	Note: P/N 861375 or 861385										
	(6)										
26-20-13-960-801-07	**Discard of the Fire Extinguisher Percussion Cartridges - Baggage Compartment Percussion Cartridge (23W) (Service Life)**							RE		Comp Maint Ops (5-20)	
26 A/F						Yrs	30-Aug-2024	6		30-Aug-2030	5.5 Years
13083-5						Hrs	13,386.3				
4406						Ldg	9,044				
						Flt	9,043				
	Note: P/N 13083-5										
	(103)										

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-13-960-801-07 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - Baggage Compartment Percussion Cartridge (23W)**							RE	Comp Maint Ops (5-20), Life Limit		
26 A/F						Yrs	30-Aug-2024	9		30-Apr-2030	5.2 Years
13083-5						Hrs	13,386.3				
4406						Ldg	9,044				
Manufactured Date 30-Apr-2021						Flt	9,043				
Note: P/N 13083-5 (103)											
26-20-13-960-801-08	**Discard of the Fire Extinguisher Percussion Cartridges - RH Rear Compartment Percussion Cartridge (24W) (Service Life)**							RE	Comp Maint Ops (5-20)		
26 A/F	Right					Yrs	30-Aug-2024	6		30-Aug-2030	5.5 Years
13083-5						Hrs	13,386.3				
4426						Ldg	9,044				
Note: P/N 13083-5 (103)						Flt	9,043				
26-20-13-960-801-08 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - RH Rear Compartment Percussion Cartridge (24W)**							RE	Comp Maint Ops (5-20), Life Limit		
26 A/F	Right					Yrs	30-Aug-2024	9		30-Apr-2030	5.2 Years
13083-5						Hrs	13,386.3				
4426						Ldg	9,044				
Manufactured Date 30-Apr-2021						Flt	9,043				
Note: P/N 13083-5 (103)											
26-20-13-960-801-09	**Discard of the Fire Extinguisher Percussion Cartridges - LH Rear Compartment Percussion Cartridge (25W) (Service Life)**							RE	Comp Maint Ops (5-20)		
26 A/F	Left					Yrs	24-Mar-2021	6		24-Mar-2027	2 Years
13083-5						Hrs	13,161.4				
44880						Ldg	8,910				
Note: P/N 13083-5 (103)						Flt					
26-20-13-960-801-09 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - LH Rear Compartment Percussion Cartridge (25W)**							RE	Comp Maint Ops (5-20), Life Limit		
26 A/F	Left					Yrs	24-Mar-2021	9		24-Mar-2030	5.1 Years
13083-5						Hrs	13,161.4				
44880						Ldg	8,910				
Manufactured Date 24-Mar-2021						Flt					
Note: P/N 13083-5 (103)											
26-20-13-960-801-10	**Discard of the Fire Extinguisher Percussion Cartridges - APU Percussion Cartridge (28W) (Service Life)**							RE	Comp Maint Ops (5-20)		
26 A/F						Yrs	30-Aug-2024	6		30-Aug-2030	5.5 Years
13083-5						Hrs	13,386.3				
48394						Ldg	9,044				
Note: P/N 13083-5 (103)						Flt	9,043				
26-20-13-960-801-10 (Max)	**Discard of the Fire Extinguisher Percussion Cartridges - APU Percussion Cartridge (28W)**							RE	Comp Maint Ops (5-20), Life Limit		
26 A/F						Yrs	30-Aug-2024	9		30-Sep-2031	6.6 Years
13083-5						Hrs	13,386.3				
48394						Ldg	9,044				
Manufactured Date 30-Sep-2022						Flt	9,043				
Note: P/N 13083-5 (103)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-15-210-801-01		**General Visual Inspection Cockpit Portable Fire Extinguisher**							RE			
26 A/F		Cockpit					Mos	26-Feb-2025	1		26-Mar-2025	20 Days
898052							Hrs	13,520.9				
Y-605551							Ldg	9,133				
							Flt	9,133				
		Note: -										
26-20-15-210-801-01		**General Visual Inspection No. 1 Cabin Portable Fire Extinguisher**							RE			
26 A/F		No.1					Mos	26-Feb-2025	1		26-Mar-2025	20 Days
860640							Hrs	13,520.9				
57702							Ldg	9,133				
							Flt	9,133				
		Note: -										
26-20-15-350-802-02		**Restoration of the Portable Extinguishers (Overhaul) - Cabin Portable Fire Extinguisher (501WB)**							RE (N/A)		Comp Maint Ops (5-20)	
26 A/F		No.1					Mos					
860640							Hrs					
57702							Ldg					
							Flt					
26-20-15-350-802-03		**Restoration of the Portable Extinguishers (Overhaul) - Second Cabin Portable Fire Extinguisher (502WB)**							RE (N/A)		Comp Maint Ops (5-20)	
26 A/F		No.2					Mos					
860640							Hrs					
50448							Ldg					
							Flt					
26-20-15-720-801-01		**Weighing of the Portable Fire Extinguishers - Cockpit Portable Fire Extinguisher (500WB)**							RE		Comp Maint Ops (5-20)	
26 A/F		Cockpit					Mos	26-Feb-2025	24	+3%m	26-Feb-2027	2 Years (+21 Days)
898052							Hrs	13,520.9				
Y-605551							Ldg	9,133				
		Weighed Date 26-Feb-2025					Flt	9,133				
		Note: P/N 898052 NOTE 101: Location and quantity of components vary with aircraft interior configuration. Refer to supplemental maintenance documentation for exact configuration of your aircraft.										
26-20-15-720-801-02		**Weighing of the Portable Fire Extinguishers - Cabin Portable Fire Extinguisher (501WB)**							RE		Comp Maint Ops (5-20)	
26 A/F		No.1					Mos	26-Feb-2025	18		26-Aug-2026	1.5 Years
860640							Hrs	13,520.9				
57702							Ldg	9,133				
		Weighed Date 26-Feb-2025					Flt	9,133				
		Note: P/N 890275 or 892480 NOTE 101: Location and quantity of components vary with aircraft interior configuration. Refer to supplemental maintenance documentation for exact configuration of your aircraft. No tolerance										
26-20-15-720-801-03		**Weighing of the Portable Fire Extinguishers - Second Cabin Portable Fire Extinguisher (502WB)**							RE (N/A)		Comp Maint Ops (5-20)	
26 A/F		No.2					Mos					
860640							Hrs					
50448							Ldg					
							Flt					
		Note: Not Installed										

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
26-20-15-790-801-01	**Hydrostatic Test of the Portable Fire Extinguishers - Cockpit Portable Fire Extinguisher (500WB)**							RE		Comp Maint Ops (5-20)	
26 A/F	Cockpit					Yrs	16-Oct-2013	12	+3%m	16-Oct-2025	7.5 Months (+131 Days)
898052						Hrs	13,160.9				
Y-605551						Ldg	8,909				
Hydrostatic Tested Date 16-Oct-2013						Flt					
	Note: P/N 898052. NOTE 101: Location and quantity of components vary with aircraft interior configuration. Refer to supplemental maintenance documentation for exact configuration of your aircraft. NOTE 1: Return to approved repair agent for maintenance action. Specify on your Work Order to the repair agent the type and minimum contents of the maintenance action that are listed in the AMM maintenance procedure. As an alternative, you can install a new unit, overhauled unit, or an exchange unit that has been maintained in accordance with this task requirement.										
26-20-15-790-801-02	**Hydrostatic Test of the Portable Fire Extinguishers - Cabin Portable Fire Extinguisher (501WB)**							RE		Comp Maint Ops (5-20)	
26 A/F	No.1					Yrs	29-Nov-2023	12	+3%m	29-Nov-2035	10.7 Years (+131 Days)
860640						Hrs	13,287.4				
57702						Ldg	8,989				
Hydrostatic Tested Date 29-Nov-2023						Flt	8,989				
	Note: P/N 898052. NOTE 101: Location and quantity of components vary with aircraft interior configuration. Refer to supplemental maintenance documentation for exact configuration of your aircraft. NOTE 1: Return to approved repair agent for maintenance action. Specify on your Work Order to the repair agent the type and minimum contents of the maintenance action that are listed in the AMM maintenance procedure. As an alternative, you can install a new unit, overhauled unit, or an exchange unit that has been maintained in accordance with this task requirement.										
26-20-15-790-801-03	**Hydrostatic Test of the Portable Fire Extinguishers - Second Cabin Portable Fire Extinguisher (502WB)**							RE (N/A)		Comp Maint Ops (5-20)	
26 A/F	No.2					Mos					
860640						Hrs					
50448						Ldg					
						Flt					
	Note: Not Installed										
26-20-15-900-801-03	**SECOND CABIN PORTABLE FIRE EXTINGUISHER (502WB)**							RE (H/T)			
26 A/F	No.2					Mos	24-Mar-2021				
860640						Hrs					
50448						Ldg					
						Flt					
97-04-15	**Pacific Scientific Company, HTL/Kin-Tech Division, Fire Extinguisher Bottle Cartridges**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	11-Sep-2003				
Eff: 07-Mar-1997 Not Applicable	By PN					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
99-04-10	**Prevent Fire in the Passenger Compartment Resulting from Failure of the Fluorescent Light Ballast of the Cabin Sidewall**							RE (-)		Mandatory (Appliance AD)	
26 A/F						Mos	14-Sep-2003				
Eff: 18-Mar-1999 Not Applicable	By light installed manufacturer					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
F50-209	**Fire protection - Increased luminosity of fuel shut-off pull-handle indicator lights**							T (A/R)			
26 A/F						Mos					
Eff: 05-Oct-1989						Hrs					
						Ldg					
	Note: M1615					Flt					
F50-239	**Halon portable fire extinguishers - Capability for installation of new supports P/N 896698R**							T (A/R)			
26 A/F						Mos					
Eff: 07-Dec-1994						Hrs					
						Ldg					
	Note: M1851					Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-359	**Baggage compartment fire extinguishing line - Clamping improvement**							T (A/R)			
26 A/F						Mos					
Eff: 13-Jun-2001						Hrs					
						Ldg					
Note: M2710						Flt					
F50-369	**Fire protection - LH, RH and center fire wire system improvement**							RE (-)			
26 A/F						Mos					
Eff: 10-Oct-2001						Hrs					
						Ldg					
Note: M2751, 251, 253 to 313 and A/C with TFE 731-40-1C engines (SB F50-280)						Flt					
F50-443	**Smoke detection in baggage compartment - Improved test**							RE (-)			
26 A/F						Mos					
						Hrs					
						Ldg					
Note: M2932						Flt					
F50-443 R1	**Smoke detection in baggage compartment - Improved test**							T (A/R)			
26 A/F						Mos					
Eff: 05-Nov-2004						Hrs					
						Ldg					
Note: M2932						Flt					
F50-519-Alert	**Check for possible swapping of extinguishing and LP bleed lines at frame 42**							RE (-)			
26 A/F						Mos	08-Apr-2011				
Eff: 18-Feb-2011						Hrs					
						Ldg					
Note: AD EASA 2011-0025-E (AD FAA 2011-07-11)						Flt					
F50-520	**Engine 2 LP bleed/extinguishing lines - Foolproofing the unions**							T (A/R)			
26 A/F						Mos					
Eff: 15-Oct-2012						Hrs					
						Ldg					
Note: M3203						Flt					
F50-523	**Replacement of engine 3 fire extinguishing system pipe P/N F50B791303**							T (A/R)			
26 A/F						Mos					
Eff: 10-Mar-2014						Hrs					
						Ldg					
Note: M3219						Flt					
▼ 27 - FLIGHT CONTROLS											
	(Normal) Aileron Trim Actuator							RE (O/C)			
27 A/F						Mos	18-Aug-2016				
021057-26						Hrs					
Unknown						Ldg					
						Flt					
	Aileron Artificial Feel Unit							RE (O/C)			
27 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Aileron Control Pressure Seal Box							RE (O/C)			
27 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Aileron Emergency Actuator							RE (O/C)			
	27 A/F						Mos	25-Aug-2016				
	021127						Hrs					
	Unknown						Ldg					
							Flt					
		Aileron Neutral Return Unit							RE (O/C)			
	27 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Aileron Neutral Return Unit							RE (O/C)			
	27 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Aileron Servo-Actuator							RE (O/C)			
	27 A/F	Left					Mos	12-Nov-1982				
	103117-01						Hrs	770.5				
	128						Ldg	552				
							Flt					
		Aileron Servo-Actuator							RE (O/C)			
	27 A/F	Right					Mos	12-Nov-1982				
	103117-02						Hrs	770.5				
	23						Ldg	552				
							Flt					
		Aileron-Rudder-Elevator Trim Triple Indicator							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Actuator							RE (O/C)			
	27 A/F	Left Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Actuator							RE (O/C)			
	27 A/F	Left Middle					Mos	22-Mar-2019				
	106091-02						Hrs					
	236						Ldg					
							Flt					
		Airbrake Actuator							RE (O/C)			
	27 A/F	Left Outboard					Mos	14-Sep-2023				
	106091-01	Serviceable					Hrs	13,276.7				
	1596						Ldg	8,977				
							Flt	8,977				
		Airbrake Actuator							RE (O/C)			
	27 A/F	Right Inboard					Mos	05-Nov-2024				
	106091-03	Serviceable					Hrs	13,427.3				
	1267						Ldg	9,074				
							Flt	9,074				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Airbrake Actuator							RE (O/C)			
	27 A/F	Right Middle					Mos	05-Nov-2024				
	106091-02	Serviceable					Hrs	13,427.3				
	1674						Ldg	9,074				
							Flt	9,074				
		Airbrake Actuator							RE (O/C)			
	27 A/F	Right Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Actuator Supply Check Valve							RE (O/C)			
	27 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Check Valve							RE (O/C)			
	27 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Check Valve							RE (O/C)			
	27 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Restrictor							RE (O/C)			
	27 A/F	Left Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Restrictor							RE (O/C)			
	27 A/F	Left Middle					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Restrictor							RE (O/C)			
	27 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Restrictor							RE (O/C)			
	27 A/F	Right Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Restrictor							RE (O/C)			
	27 A/F	Right Middle					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Airbrake Restrictor							RE (O/C)			
	27 A/F	Right Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Angle of Attack Indicator							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Angle of Attack Interface Unit							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Angle of Attack Probe							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Arthur Q-Unit							RE (O/C)			
	27 A/F	Aileron					Mos	01-Apr-2021				
	106043-20						Hrs					
	1639						Ldg					
							Flt					
		Arthur Q-Unit							RE (O/C)			
	27 A/F	Elevator					Mos	14-Sep-2023				
	106043-19	Serviceable					Hrs	13,276.7				
	1431						Ldg	8,977				
							Flt	8,977				
		Control Column							RE (O/C)			
	27 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Control Column							RE (O/C)			
	27 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Double Angle Gearbox							RE (O/C)			
	27 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Double Angle Gearbox							RE (O/C)			
	27 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Elevator Neutral Return Unit							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Elevator Servo-Actuator							RE (O/C)			
	27 A/F						Mos	24-Mar-2021				
	103062-36						Hrs					
	2266						Ldg					
							Flt					
		Elevator/Aileron Arthur Q-Unit Monitoring-Printed Circuit							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flap Center Screw Jack							RE (O/C)			
	27 A/F	Left Inboard					Mos					
	021137-16						Hrs					
	Unknown						Ldg					
							Flt					
		Flap Center Screw Jack							RE (O/C)			
	27 A/F	Right Inboard					Mos					
	021137-16						Hrs					
	Unknown						Ldg					
							Flt					
		Flap Flap Position Indicator							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flap Lateral Screw Jack							RE (O/C)			
	27 A/F	Right Inboard					Mos	15-Nov-1985				
	021137-16						Hrs	3,081				
	Unknown						Ldg	2,154				
							Flt					
		Flap Lateral Screw Jack (L501C)							RE (O/C)			
	27 A/F	Left Inboard					Mos	15-Nov-1985				
	021137-16						Hrs	3,081				
	Unknown						Ldg	2,154				
							Flt					
		Flap Position Transmitter							RE (O/C)			
	27 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flap Position Transmitter							RE (O/C)			
	27 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Flap Power Drive Unit							RE (O/C)			
27 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Flap Screw Jack							RE (O/C)			
27 A/F	Right Outboard					Mos	15-Nov-1985				
021137-18						Hrs	3,081				
Unknown						Ldg	2,154				
						Flt					
	Flap Screw Jack (L502C)							RE (O/C)			
27 A/F	Left Outboard					Mos	15-Nov-1985				
021137-17						Hrs	3,081				
Unknown						Ldg	2,154				
						Flt					
	Flap Single Gearbox							RE (O/C)			
27 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Flap Single Gearbox							RE (O/C)			
27 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Flap/Slat Control Box							RE (O/C)			
27 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Horizontal Stabilizer Actuator Emergency Electric Motor							RE (O/C)			
27 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Horizontal Stabilizer Actuator Normal Electric Motor							RE (O/C)			
27 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Horizontal Stabilizer Airbrakes-Trim Control Box							RE (O/C)			
27 A/F						Mos	30-Dec-2016				
013015-14						Hrs					
924						Ldg					
						Flt					
	Horizontal Stabilizer Electric Actuator							RE (O/C)			
27 A/F						Mos	29-Nov-2023				
021121-11	Repaired				0	Hrs	13,287.4				
23					0	Ldg	8,989				
					0	Flt	8,989				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Horizontal Stabilizer Position Pick-Off Transmitter							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inboard/Outboard Airbrake Actuator Circuit Nonreturn Valve							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inboard/Outboard Airbrake Circuit Pressure Relief Valve							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inboard/Outboard Airbrake Electro- Distributor							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Intermediate Bearing							RE (O/C)			
	27 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Intermediate Bearing							RE (O/C)			
	27 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Leading Edge Selector Valve Control Cable							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Middle Airbrake Circuit Pressure Relief Valve							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Middle Airbrake Electro- Distributor							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Normal Slat Circuit Adjustable Restrictor							RE (O/C)			
	27 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Normal Slat Circuit Adjustable Restrictor							RE (O/C)			
	27 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pitch Gust Valve							RE (O/C)			
	27 A/F						Mos	19-Feb-2014				
	104086-13						Hrs					
	3285						Ldg					
							Flt					
		Pitch Main Artificial (Afu) Feel Unit							RE (O/C)			
	27 A/F						Mos	16-Sep-2018				
	105034-07						Hrs					
	614						Ldg					
							Flt					
		Pitch/Trim Switch							RE (O/C)			
	27 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pitch/Trim Switch							RE (O/C)			
	27 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rudder Artificial Feel Unit							RE (O/C)			
	27 A/F						Mos	16-Sep-2018				
	105043-07						Hrs					
	758						Ldg					
							Flt					
		Rudder Auxiliary Artificial Feel Unit							RE (O/C)			
	27 A/F						Mos	16-Sep-2018				
	105070-04						Hrs					
	Unknown						Ldg					
							Flt					
		Rudder Servo-Actuator							RE (O/C)			
	27 A/F						Mos	10-Mar-2006				
	103103-13						Hrs					
	893						Ldg					
							Flt					
		Rudder Trim Actuator							RE (O/C)			
	27 A/F						Mos	16-Sep-2018				
	021057-28						Hrs					
	5575						Ldg					
							Flt					
		Rudder/Elevator Control Pressure Seal Box							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Slat Actuator							RE (O/C)			
	27 A/F	Left Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Actuator							RE (O/C)			
	27 A/F	Right Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Airspeed Switch							RE (O/C)			
	27 A/F						Mos	02-Dec-2015				
	4219F010301	Overhauled			0		Hrs					
	1107				0		Ldg					
							Flt					
		Slat Control Distributor							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Emergency Actuator							RE (O/C)			
	27 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Emergency Actuator							RE (O/C)			
	27 A/F	Right Outboard					Mos	15-Nov-2012				
	106132-07						Hrs					
	3913						Ldg					
							Flt					
		Slat Inboard Actuator							RE (O/C)			
	27 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Inboard Actuator							RE (O/C)			
	27 A/F	Right Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Outboard Actuator							RE (O/C)			
	27 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Outboard Actuator							RE (O/C)			
	27 A/F	Right Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Slat Retraction Flow Restrictor							RE (O/C)			
	27 A/F	Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Retraction Restrictor							RE (O/C)			
	27 A/F	Left Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Retraction Restrictor							RE (O/C)			
	27 A/F	Right Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Stand-By Distributor							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Supply Circuit Check Valve							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slat Supply Distributor							RE (O/C)			
	27 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slats Emergency Circuit Adjustable Diaphragm							RE (O/C)			
	27 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slats Emergency Circuit Adjustable Diaphragm							RE (O/C)			
	27 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Variable Ratio (Amedee) Bellcrank							RE (O/C)			
	27 A/F						Mos	11-Aug-2016				
	028008-28						Hrs					
	Unknown						Ldg					
							Flt					
2000-11-03		**Pitch Feel System - Airplane Flight Manual (AFM) Revision**							RE (-)		Mandatory	
	27 A/F						Mos	08-Jul-2000				
	Eff: 16-Jun-2000 Complied With						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2007-25-10	**Trailing Edge Flap Control Linkage Rotating Rod**							RE (-)		Mandatory	
27 A/F	Eff: 14-Jan-2008 (ISSUING AUTHORITY: FAA)					Mos	14-Aug-2008				
						Hrs	10,983.8				
						Ldg	7,666				
						Flt					
27-00-00-640-803-01	**Pressure Greasing / Lubrication of Flight Control Bearings and Hinge Pins In Pressurized Area - Roll**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-00-00-640-803-02	**Pressure Greasing / Lubrication of Flight Control Bearings and Hinge Pins In Pressurized Area - Yaw**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-00-00-640-803-03	**Pressure Greasing / Lubrication of Flight Control Bearings and Hinge Pins In Pressurized Area - Pitch**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-00-00-640-804-01	**Pressure Greasing / Lubrication of Flight Control Bearings and Hinge Pins Outside Pressurized Area - Roll**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-00-00-640-804-02	**Pressure Greasing / Lubrication of Flight Control Bearings and Hinge Pins Outside Pressurized Area - Yaw**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-00-00-640-804-03	**Pressure Greasing / Lubrication of Flight Control Bearings and Hinge Pins Outside Pressurized Area - Pitch**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-00-00-640-806-01	**Visual Inspection and Greasing of Yaw and Pitch Control Sealed Boxes**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-00-00-710-801-01	**Operational Test of the Flight Controls - Hydraulic System 1**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-00-00-710-801-02	**Operational Test of the Flight Controls - Hydraulic System 2**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-00-00-710-802-01	**Operational Test of the Trim Systems - Roll**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-00-00-710-802-02	**Operational Test of the Trim Systems - Yaw**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-00-00-720-803-01	**Functional Test of Roll and Pitch Auxiliary AFU (AAFU Connection and Visual Inspection) - LH Roll AAFU (L960CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-00-00-720-803-02	**Functional Test of Roll and Pitch Auxiliary AFU (AAFU Connection and Visual Inspection) - RH Roll AAFU (R960CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-00-00-720-803-03	**Functional Test of Roll and Pitch Auxiliary AFU (AAFU Connection and Visual Inspection) - Pitch AAFU (924CW)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
270100-0101	**Motor, Flap Gear**							RE (O/C)			
27 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
27-12-01-640-801-01	**Pressure Greasing of the Aileron Servo-Actuator Bearings - LH Aileron Servo-Actuator (L950CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-12-01-640-801-02	**Pressure Greasing of the Aileron Servo-Actuator Bearings - RH Aileron Servo-Actuator (R950CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-12-01-790-802-01	**Check For Internal Leaks on the Aileron Servo-Actuators - LH Aileron Servo-Actuator (L950CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-12-01-790-802-02	**Check For Internal Leaks on the Aileron Servo-Actuators - RH Aileron Servo-Actuator (R950CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-13-01-640-806-01	**Lubrication of the Roll Control Linkage Hinge Pins Outside Pressurized Area**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-13-01-640-808-01	**Greasing of the Roll Control Linkage Ball-Bushings Outside Pressurized Area**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
27-13-05-640-801-01	**Visual Inspection and Greasing of Roll Control Sealed Boxes**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-13-07-350-801-01	**Restoration of "Amedee" Variable Bellcrank (Functional Test and Servicing) - Variable Bellcrank (Amedee) (930CC)**							RE		Comp Maint Ops (5-20)	
27 A/F 028008-28 Unknown						Yrs	02-Sep-2016	12	+5m	02-Sep-2028	3.5 Years (+153 Days)
						Hrs	12,978.6				
						Ldg	8,785				
Note: P/N 028008-28 (1)						Flt					
27-14-01-350-801-01	**Restoration of the Roll Trim Actuator (Functional Test) - Roll Trim Actuator (112C)**							RE		Comp Maint Ops (5-20)	
27 A/F 021057-26 Unknown						Yrs	18-Aug-2016	12	+5m	18-Aug-2028	3.5 Years (+153 Days)
						Hrs					
						Ldg					
Note: P/N 021057-26 or P/N 021057-38 or P/N 021057-46 Note: (1)						Flt					
27-14-03-350-801-01	**Restoration of the Roll Emergency Trim Actuator (Functional Test) - Roll Emergency Trim Actuator (103C)**							RE		Comp Maint Ops (5-20)	
27 A/F 021127 Unknown						Yrs	02-Sep-2016	12	+5m	02-Sep-2028	3.5 Years (+153 Days)
						Hrs	12,978.6				
(SOURCE: Falcon 50/50EX MPD)						Ldg	8,785				
Note: NOTE 1: Return to approved repair agent for maintenance action. Specify on your Work Order to the repair agent the type and minimum contents of the maintenance action that are listed in the AMM maintenance procedure. As an alternative, you can install a new unit, overhauled unit, or an exchange unit that has been maintained in accordance with this task requirement.						Flt					
27-14-03-720-802-01	**Functional Test of the Roll Emergency Trim Actuator - Roll Emergency Trim Actuator (103C)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-14-05-720-801-01	**Functional Test of the Roll Trim Control Safety Relays - Roll Trim Unit (119C)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-15-00-720-801-01	**Functional Test of the Roll Arthur Variable Bellcrank Monitoring System**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
27 A/F	05-10-00-2B					Mos	02-Sep-2016				
						Hrs	12,978.6	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-15-01-640-801-01	**Pressure Greasing of the Roll Arthur Variable Bellcrank Bearings - Roll Arthur Variable Bellcrank (43C)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-15-01-720-801-01	**Functional Test of the Roll Arthur Variable Bellcrank - Roll Arthur Variable Bellcrank (43C)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-15-05-350-801-01	**Restoration of the Roll Main AFU (Inspection, Servicing and Functional Test) - Roll Main AFU (940CC)**							RE		Comp Maint Ops (5-20)	
27 A/F						Yrs	16-Sep-2018	12	+5m	16-Sep-2030	5.5 Years (+153 Days)
Unknown						Hrs	13,079.2				
Unknown						Ldg	8,836				
Note: P/N 105044-07 (1)						Flt					
27-15-07-640-801-01	**Pressure Greasing of the Roll Auxiliary AFU Bearing - LH Roll AAFU (L960CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-15-07-640-801-02	**Pressure Greasing of the Roll Auxiliary AFU Bearing - RH Roll AAFU (R960CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-22-01-350-801-01	**Restoration of the Rudder Servo-Actuator (Functional Test of Valves and Check of Damper) - Rudder Servo-Actuator (571CC)**							RE (N/A)		Comp Maint Ops (5-20)	
27 A/F						Mos					
103103-13						Hrs					
893						Ldg					
(SOURCE: Falcon 50/50EX MPD)						Flt					
27-22-01-350-802-01	**Restoration of the Rudder Servo-Actuator (Functional Test) - Rudder Servo-Actuator (571CC)**							RE		Comp Maint Ops (5-20)	**≈14-Oct-2043**
27 A/F						Mos	10-Mar-2006				
103103-13						Hrs	10,231.8	10,000	+3%	20,231.8	6,710.9 Hrs (+300)
893						Ldg	7,207				
Note: P/N 103103-13 (1) No tolerance.						Flt					
27-22-01-350-802-01 (5-40)	**Restoration of the Rudder Servo-Actuator (Functional Test) - Rudder Servo-Actuator (571CC)**							RE		AWL (5-40), CMR	**≈14-Oct-2043**
27 A/F						Mos	10-Mar-2006				
103103-13						Hrs	10,231.8	10,000		20,231.8	6,710.9 Hrs
893						Ldg	7,207				
Note: P/N 103103-13 (1) No tolerance.						Flt					
27-22-01-640-801-01	**Pressure Greasing of the Rudder Servo-Actuator Bearings - Rudder Servo-Actuator (571CC)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
103103-13						Hrs	12,978.6				
893						Ldg	8,785				
						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-22-01-790-802-01	**Check For Internal Leaks on the Rudder Servo-Actuator - Rudder Servo-Actuator (571CC)**							RE		Acft Maint Ops (5-10)	
27 A/F 103103-13 893	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
						Ldg	8,977				
(Tol. Adjustment: -225.9d)						Flt	8,977				
27-23-01-640-806-01	**Lubrication of the Yaw Control Linkage Hinge Pins Outside Pressurized Area**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-23-01-640-807-01	**Greasing of the Yaw Control Linkage Ball-Bushings In Pressurized Area**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-23-01-640-808-01	**Greasing of the Yaw Control Linkage Ball-Bushings Outside Pressurized Area**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
27-24-01-350-801-01	**Restoration of the Yaw Trim Actuator (Functional Test) - Yaw Trim Actuator (92C)**							RE		Comp Maint Ops (5-20)	
27 A/F 021057-28 5575						Yrs	16-Sep-2018	12	+5m	16-Sep-2030	5.5 Years (+153 Days)
						Hrs					
						Ldg					
Note: P/N 021057-28 or 021057-36 or 021057-48 (1)						Flt					
27-24-05-720-802-01	**Functional Test of the Yaw Trim Control Safety Relays - Yaw Trim Safety Relay (93C)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Dec-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-24-05-720-802-02	**Functional Test of the Yaw Trim Control Safety Relays - Yaw Trim Safety Relay (94C)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Dec-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-25-05-350-801-01	**Restoration of the Yaw Main AFU (Inspection, Servicing and Functional Test) - Yaw Main AFU (573CC)**							RE		Comp Maint Ops (5-20)	
27 A/F 105043-07 758						Yrs	16-Sep-2018	12	+5m	16-Sep-2030	5.5 Years (+153 Days)
						Hrs					
						Ldg					
Note: P/N 105043-07 (1)						Flt					
27-25-07-350-801-01	**Restoration of the Yaw Auxiliary AFU (Inspection, Servicing and Functional Test) - Yaw AAFU (572CC)**							RE		Comp Maint Ops (5-20)	
27 A/F 105070-04 Unknown						Yrs	16-Sep-2018	12	+5m	16-Sep-2030	5.5 Years (+153 Days)
						Hrs					
						Ldg					
Note: P/N 105070-04 (1)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-31-01-640-801-01	**Greasing of the Control Columns - Pilot Control Column/Wheel (L8Tb)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Dec-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-31-01-640-801-02	**Greasing of the Control Columns - Copilot Control Column/Wheel (R8Tb)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Dec-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-32-01-350-801-01	**Restoration of the Elevator Servo-Actuator (Functional Test) - Elevator Servo-Actuator (925CW)**							RE		Comp Maint Ops (5-20)	**≈01-Dec-2051**
27 A/F						Mos	24-Mar-2021				
103062-36						Hrs	13,161.4	10,000		23,161.4	9,640.5 Hrs
2266						Ldg					
						Flt					
Note: P/N 103062-36 or 103062-40											
(1)											
No tolerance											
27-32-01-350-801-01 (5-40)	**Restoration of the Elevator Servo-Actuator (Functional Test) - Elevator Servo-Actuator (925CW)**							RE		AWL (5-40), CMR	**≈01-Dec-2051**
27 A/F						Mos	24-Mar-2021				
103062-36						Hrs	13,161.4	10,000		23,161.4	9,640.5 Hrs
2266						Ldg					
						Flt					
Note: P/N 103062-36 or 103062-40											
(1)											
No tolerance											
27-32-01-640-801-01	**Pressure Greasing of the Elevator Servo-Actuator Bearings - Elevator Servo-Actuator (925CW)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
103062-36						Hrs	12,978.6				
2266						Ldg	8,785				
						Flt					
27-32-01-790-802-01	**Check For Internal Leaks on the Elevator Servo-Actuator - Elevator Servo-Actuator (925CW)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
103062-36						Hrs	13,276.7				
2266						Ldg	8,977				
(Tol. Adjustment: -225.9d)						Flt	8,977				
27-32-03-350-801-01	**Restoration of the Gust Damping Valve (Functional Test) - Gust Damping Valve (31F)**							RE		Comp Maint Ops (5-20)	**≈05-Dec-2047**
27 A/F						Mos	19-Feb-2014				
104086-13						Hrs	11,724.2	10,000		21,724.2	8,203.3 Hrs
3285						Ldg					
						Flt					
Note: P/N 104086-13											
(1)											
No tolerance.											
27-32-03-350-801-01 (5-40)	**Restoration of the Gust Damping Valve (Functional Test) - Gust Damping Valve (31F)**							RE		AWL (5-40), CMR	**≈05-Dec-2047**
27 A/F						Mos	19-Feb-2014				
104086-13						Hrs	11,724.2	10,000		21,724.2	8,203.3 Hrs
3285						Ldg					
						Flt					
Note: P/N 104086-13											
(1)											
No tolerance.											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-33-01-640-806-01	**Lubrication of the Pitch Control Linkage Hinge Pins Outside Pressurized Area**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-33-01-640-807-01	**Greasing of the Pitch Control Linkage Ball-Bushings In Pressurized Area**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-35-00-720-801-01	**Functional Test of the Pitch Arthur Control System**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
27 A/F	05-10-00-2B					Mos	02-Sep-2016				
						Hrs	12,978.6	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					
27-35-01-640-801-01	**Pressure Greasing of the Pitch Arthur Variable Bellcrank Bearings - Pitch Arthur Variable Bellcrank (42C)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-35-01-720-801-01	**Functional Test of the Pitch Arthur Variable Bellcrank - Pitch Arthur Variable Bellcrank (42C)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-35-05-350-801-01	**Restoration of the Pitch Main AFU (Inspection, Servicing and Functional Test) - Pitch Main AFU (524C)**							RE		Comp Maint Ops (5-20)	
27 A/F						Yrs	16-Sep-2018	12	+5m	16-Sep-2030	5.5 Years (+153 Days)
105034-07						Hrs					
614						Ldg					
Note: P/N 105034-07 (1)						Flt					
27-35-07-640-801-01	**Pressure Greasing of the Pitch Auxiliary AFU Bearings - Pitch AAFU (924CW)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
27-40-00-720-801-01	**Functional Test of the Horizontal Stabilizer Control and Indicating System**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-40-01-210-802-01	**Visual Inspection of the Horizontal Stabilizer Actuator - Horizontal Stabilizer Electric Actuator (54C)**							RE		Comp Maint Ops (5-20)	
27 A/F						Yrs	29-Nov-2023	6	+3%d	31-Aug-2028	3.5 Years (+65 Days)
021121-11						Hrs	13,287.4				
23						Ldg	8,989				
(Tol. Adjustment: -454d)						Flt	8,989	3,750	+3%	12,739	3,606 Flt (+112.5)
Note: P/N 021121-01 or 021121-05 or 021121-06 or 021121-07 or 021121-08 or 021121-09 or 021121-11 or 021121-12											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-40-01-350-801-01		**Restoration of the Horizontal Stabilizer Actuator (Full Disassembly, Inspection/Check and Ndt) - Horizontal Stabilizer Electric Actuator (54C)**							RE		Comp Maint Ops (5-20)	
27 A/F	021121-11						Yrs	29-Nov-2023	12	+3%d	29-Nov-2035	10.7 Years (+131 Days)
23							Hrs	13,287.4				
(Tol. Adjustment: -1489 Flt)							Ldg	8,989				
Note: P/N 021121-01 or 021121-05 or 021121-06 or 021121-07 or 021121-08 or 021121-09 or 021121-11 or 021121-12 (1)							Flt	8,989	7,500	+3%	15,000	5,867 Flt (+225)
27-40-01-640-802-01		**Greasing of the Horizontal Stabilizer Actuator Hinges and Jack Screw - Horizontal Stabilizer Electric Actuator (54C)**							RE		Acft Maint Ops (5-10)	
27 A/F	021121-11	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
23							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
27-40-01-720-801-01		**Measurement of the Horizontal Stabilizer Actuator Slip - Normal Electric Motor (954CA)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F		05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
							Flt	8,977				
27-40-01-720-801-02		**Measurement of the Horizontal Stabilizer Actuator Slip - Emergency Electric Motor (954CB)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F		05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
							Flt	8,977				
27-40-03-100-801-01		**Check / Cleaning of the Electromagnetic Brake of the Horizontal Stabilizer Actuator Motors - Normal Electric Motor (954CA)**							RE (N/A)		Acft Maint Ops (5-10)	
27 A/F							Mos					
							Hrs					
							Ldg					
Note: Before SB F50-267							Flt					
27-40-03-760-801-01		**Measurement of the Drop-Out Current of the Electromagnetic Brake of Hs Actuator Normal Motor - Normal Electric Motor (954CA)**							RE (N/A)		Acft Maint Ops (5-10)	
27 A/F							Mos					
							Hrs					
							Ldg					
Note: Before SB F50-247 or Before SB F50-267							Flt					
27-40-15-710-801-01		**Operational Test of the Hs Emergency Trim Control Relay**							RE		Acft Maint Ops (5-10)	
27 A/F		05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
							Hrs	12,978.6				
							Ldg	8,785				
							Flt					
27-40-17-720-801-01		**Functional Test of the Horizontal Stabilizer Relay Box - Hs Relay Box (80C)**							RE		Acft Maint Ops (5-10)	**≈21-Feb-2036**
27 A/F		05-10-00-3B					Mos	02-Sep-2016				
							Hrs	12,978.6	4,500	+30	(17,478.6)	3,957.7 Hrs (+30)
							Ldg	8,785				
							Flt					
27-40-17-720-801-01 (5-40)		**Functional Test of the Horizontal Stabilizer Relay Box - Hs Relay Box (80C)**							RE		AWL (5-40), CMR	**≈12-Jul-2037**
27 A/F							Mos	02-Sep-2016				
							Hrs	12,978.6	5,000		17,978.6	4,457.7 Hrs
Ref:27-896							Ldg	8,785				
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-50-00-640-801-01	**Greasing / Lubrication of Flap Mechanisms**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
27-50-00-720-801-01	**Functional Test of the Flap Control and Indicating System**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-50-00-720-802-01	**Functional Test of the Flap Asymmetry Detection System**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-50-00-720-804-01	**Measurement of Overall Linkage Play of Flap Linkage - LH Wing**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-50-00-720-804-02	**Measurement of Overall Linkage Play of Flap Linkage - RH Wing**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-52-13-200-801-01	**Check / Greasing of Flap Control Rod Splines - LH Wing**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
27-52-13-200-801-02	**Check / Greasing of Flap Control Rod Splines - RH Wing**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
27-53-01-220-801-01	**Cleaning / Check of the Flap Screw Jack Actuating Screw - LH Outboard Flap Screw Jack (L502C)**							RE		Acft Maint Ops (5-10)	
27 A/F 021137-17 Unknown	Left Outboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
(Tol. Adjustment: -83d)						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
27-53-01-220-801-02	**Cleaning / Check of the Flap Screw Jack Actuating Screw - LH Inboard Flap Lateral Screw Jack (L501C)**							RE		Acft Maint Ops (5-10)	
27 A/F 021137-16 Unknown	Left Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
(Tol. Adjustment: -83d)						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-53-01-220-801-03	**Cleaning / Check of the Flap Screw Jack Actuating Screw - LH Inboard Flap Center Screw Jack (L500C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Left Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-16						Hrs	13,386.3				
Unknown						Ldg	9,044				
(Tol. Adjustment: -83d)						Flt	9,043				
27-53-01-220-801-04	**Cleaning / Check of the Flap Screw Jack Actuating Screw - RH Inboard Flap Center Screw Jack (R500C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Right Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-16						Hrs	13,386.3				
Unknown						Ldg	9,044				
(Tol. Adjustment: -83d)						Flt	9,043				
27-53-01-220-801-05	**Cleaning / Check of the Flap Screw Jack Actuating Screw - RH Inboard Flap Lateral Screw Jack (R501C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Right Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-16						Hrs	13,386.3				
Unknown						Ldg	9,044				
(Tol. Adjustment: -83d)						Flt	9,043				
27-53-01-220-801-06	**Cleaning / Check of the Flap Screw Jack Actuating Screw - RH Outboard Flap Screw Jack (R502C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Right Outboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-18						Hrs	13,386.3				
Unknown						Ldg	9,044				
(Tol. Adjustment: -83d)						Flt	9,043				
27-53-01-350-801-01	**Restoration of the Flap Screw Jacks (Overhaul) - LH Outboard Flap Screw Jack (L502C)**							RE (N/A)		Comp Maint Ops (5-20)	
27 A/F	Left Outboard					Mos	15-Nov-1985				
021137-17						Hrs	3,081				
Unknown						Ldg	2,154				
						Flt					
27-53-01-350-801-02	**Restoration of the Flap Screw Jacks (Overhaul) - LH Inboard Flap Lateral Screw Jack (L501C)**							RE (N/A)		Comp Maint Ops (5-20)	
27 A/F	Left Inboard					Mos	15-Nov-1985				
021137-16						Hrs	3,081				
Unknown						Ldg	2,154				
						Flt					
27-53-01-350-801-03	**Restoration of the Flap Screw Jacks (Overhaul) - LH Inboard Flap Center Screw Jack (L500C)**							RE (N/A)		Comp Maint Ops (5-20)	
27 A/F	Left Inboard					Mos					
021137-16						Hrs					
Unknown						Ldg					
						Flt					
27-53-01-350-801-04	**Restoration of the Flap Screw Jacks (Overhaul) - RH Inboard Flap Center Screw Jack (R500C)**							RE (N/A)		Comp Maint Ops (5-20)	
27 A/F	Right Inboard					Mos					
021137-16						Hrs					
Unknown						Ldg					
						Flt					
27-53-01-350-801-05	**Restoration of the Flap Screw Jacks (Overhaul) - RH Inboard Flap Lateral Screw Jack (R501C)**							RE (N/A)		Comp Maint Ops (5-20)	
27 A/F	Right Inboard					Mos	15-Nov-1985				
021137-16						Hrs	3,081				
Unknown						Ldg	2,154				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-53-01-350-801-06	**Restoration of the Flap Screw Jacks (Overhaul) - RH Outboard Flap Screw Jack (R502C)**							RE (N/A)		Comp Maint Ops (5-20)	
27 A/F	Right Outboard					Mos	15-Nov-1985				
021137-18						Hrs	3,081				
Unknown						Ldg	2,154				
						Flt					
27-53-01-640-802-01	**Greasing of Flap Screw Jacks - LH Outboard Flap Screw Jack (L502C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Left Outboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-17											
Unknown						Hrs	13,386.3				
(Tol. Adjustment: -83d)						Ldg	9,044				
						Flt	9,043				
27-53-01-640-802-02	**Greasing of Flap Screw Jacks - LH Inboard Flap Lateral Screw Jack (L501C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Left Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-16											
Unknown						Hrs	13,386.3				
(Tol. Adjustment: -83d)						Ldg	9,044				
						Flt	9,043				
27-53-01-640-802-03	**Greasing of Flap Screw Jacks - LH Inboard Flap Center Screw Jack (L500C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Left Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-16											
Unknown						Hrs	13,386.3				
(Tol. Adjustment: -83d)						Ldg	9,044				
						Flt	9,043				
27-53-01-640-802-04	**Greasing of Flap Screw Jacks - RH Inboard Flap Center Screw Jack (R500C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Right Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-16											
Unknown						Hrs	13,386.3				
(Tol. Adjustment: -83d)						Ldg	9,044				
						Flt	9,043				
27-53-01-640-802-05	**Greasing of Flap Screw Jacks - RH Inboard Flap Lateral Screw Jack (R501C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Right Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-16											
Unknown						Hrs	13,386.3				
(Tol. Adjustment: -83d)						Ldg	9,044				
						Flt	9,043				
27-53-01-640-802-06	**Greasing of Flap Screw Jacks - RH Outboard Flap Screw Jack (R502C)**							RE		Acft Maint Ops (5-10)	
27 A/F	Right Outboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
021137-18											
Unknown						Hrs	13,386.3				
(Tol. Adjustment: -83d)						Ldg	9,044				
						Flt	9,043				
27-53-01-720-804-01	**Check of Screw / Nut Play on Flap Screw Jacks - LH Outboard Flap Screw Jack (L502C)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	Left Outboard05-10-00-1B					Mos	14-Sep-2023				
021137-17						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
Unknown						Ldg	8,977				
						Flt	8,977				
27-53-01-720-804-02	**Check of Screw / Nut Play on Flap Screw Jacks - LH Inboard Flap Lateral Screw Jack (L501C)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	Left Inboard05-10-00-1B					Mos	14-Sep-2023				
021137-16						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
Unknown						Ldg	8,977				
						Flt	8,977				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-53-01-720-804-03	**Check of Screw / Nut Play on Flap Screw Jacks - LH Inboard Flap Center Screw Jack (L500C)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	Left Inboard05-10-00-1B					Mos	14-Sep-2023				
021137-16						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
Unknown						Ldg	8,977				
						Flt	8,977				
27-53-01-720-804-04	**Check of Screw / Nut Play on Flap Screw Jacks - RH Inboard Flap Center Screw Jack (R500C)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	Right Inboard05-10-00-1B					Mos	14-Sep-2023				
021137-16						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
Unknown						Ldg	8,977				
						Flt	8,977				
27-53-01-720-804-05	**Check of Screw / Nut Play on Flap Screw Jacks - RH Inboard Flap Lateral Screw Jack (R501C)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	Right Inboard05-10-00-1B					Mos	14-Sep-2023				
021137-16						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
Unknown						Ldg	8,977				
						Flt	8,977				
27-53-01-720-804-06	**Check of Screw / Nut Play on Flap Screw Jacks - RH Outboard Flap Screw Jack (R502C)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	Right Outboard05-10-00-1B					Mos	14-Sep-2023				
021137-18						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
Unknown						Ldg	8,977				
						Flt	8,977				
27-60-00-720-802-01	**Functional Test of the Airbrake System**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-60-00-720-802-01 (5-40)	**Functional Test of the Airbrake System**							RE		AWL (5-40), CMR	**≈26-Mar-2052**
27 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	10,000		23,276.7	9,755.8 Hrs
Ref:27-720						Ldg	8,977				
Note: Control panel microswitch test						Flt	8,977				
27-61-01-720-801-01	**Functional Test of the Airbrake Position Microswitches - LH Outboard Airbrake Position Microswitch (25C1)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-61-01-720-801-02	**Functional Test of the Airbrake Position Microswitches - LH Center Airbrake Position Microswitch (24C1)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-61-01-720-801-03	**Functional Test of the Airbrake Position Microswitches - LH Inboard Airbrake Position Microswitch (23C1)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-61-01-720-801-04	**Functional Test of the Airbrake Position Microswitches - RH Inboard Airbrake Position Microswitch (23C2)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-61-01-720-801-05	**Functional Test of the Airbrake Position Microswitches - RH Center Airbrake Position Microswitch (24C2)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-61-01-720-801-06	**Functional Test of the Airbrake Position Microswitches - RH Outboard Airbrake Position Microswitch (25C2)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-62-01-640-801-01	**Greasing of the Airbrake Actuators - LH Outboard Airbrake Actuator (L30C)**							RE		Acft Maint Ops (5-10)	
27 A/F 106091-01 1596 (Tol. Adjustment: -83d)	Left Outboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
27-62-01-640-801-02	**Greasing of the Airbrake Actuators - LH Middle Airbrake Actuator (L29C)**							RE		Acft Maint Ops (5-10)	
27 A/F 106091-02 236 (Tol. Adjustment: -83d)	Left Middle05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
27-62-01-640-801-03	**Greasing of the Airbrake Actuators - LH Inboard Airbrake Actuator (L28C)**							RE		Acft Maint Ops (5-10)	
27 A/F Unknown Unknown (Tol. Adjustment: -83d)	Left Inboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
27-62-01-640-801-04	**Greasing of the Airbrake Actuators - RH Inboard Airbrake Actuator (R28C)**							RE		Acft Maint Ops (5-10)	
27 A/F 106091-03 1267	Right Inboard05-10-00-12M					Mos	05-Nov-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
						Hrs	13,427.3				
						Ldg	9,074				
						Flt	9,074				
27-62-01-640-801-05	**Greasing of the Airbrake Actuators - RH Middle Airbrake Actuator (R29C)**							RE		Acft Maint Ops (5-10)	
27 A/F 106091-02 1674	Right Middle05-10-00-12M					Mos	05-Nov-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
						Hrs	13,427.3				
						Ldg	9,074				
						Flt	9,074				
27-62-01-640-801-06	**Greasing of the Airbrake Actuators - RH Outboard Airbrake Actuator (R30C)**							RE		Acft Maint Ops (5-10)	
27 A/F Unknown Unknown (Tol. Adjustment: -83d)	Right Outboard05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
27-80-00-710-806-01	**Operational Test of the Ground / Flight Relays and Angle-Of-Attack Sensor Contacts**							RE		Acft Maint Ops (5-10)	**≈16-Sep-2026**
27 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	1,000	+30	14,079.2	558.3 Hrs (+30)
						Ldg	8,836				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-80-00-720-801-01	**Functional Test of the Slats - Normal Mode**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-80-00-720-801-02	**Functional Test of the Slats - Automatic Mode**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-80-00-720-801-03	**Functional Test of the Slats - Emergency Mode**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
27 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
27-80-01-350-802-01	**Restoration of the Slat Supply Distributor (Functional Test) - Slat Supply Distributor (508D)**							RE		Comp Maint Ops (5-20)	
27 A/F Unknown Unknown						Yrs	31-Oct-2018	12	+5m	31-Oct-2030	5.7 Years (+151 Days)
						Hrs	13,081.5				
						Ldg	8,840				
Note: P/N 108103-02 or 108103-05 (1)						Flt					
27-80-17-720-801-01	**Functional Test of the Slat Position Microswitches - LH Inboard Slat Retracted Microswitch (53D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-80-17-720-801-02	**Functional Test of the Slat Position Microswitches - RH Inboard Slat Retracted Microswitch (54D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-80-17-720-801-03	**Functional Test of the Slat Position Microswitches - LH Outboard Slat Retracted Microswitch (55D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-80-17-720-801-04	**Functional Test of the Slat Position Microswitches - RH Outboard Slat Retracted Microswitch (56D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-80-17-720-801-05	**Functional Test of the Slat Position Microswitches - LH Inboard Slat Extended Microswitch (57D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-80-17-720-801-06	**Functional Test of the Slat Position Microswitches - RH Inboard Slat Extended Microswitch (58D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
27-80-17-720-801-07	**Functional Test of the Slat Position Microswitches - LH Outboard Slat Extended Microswitch (59D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-80-17-720-801-08	**Functional Test of the Slat Position Microswitches - RH Outboard Slat Extended Microswitch (60D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
27-80-31-640-801-01	**Servicing of the Slat Control Cable - Slat Control Cable (509D)**							RE		Acft Maint Ops (5-10)	
27 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
85-22-10	**COLLINS AVIONICS DIVISION/ROCKWELL INTERNATIONAL - Flight Director Indicators and Horizontal Situation Indicators**							RE (-)		Mandatory (Appliance AD)	
27 A/F						Mos					
Eff: 31-Dec-1985 Not Applicable	per equipment installed					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
99-25-09	**Hinge Pin Assemblies of Horizontal Stabilizer**							RE (-)		Mandatory	
27 A/F						Mos	14-Sep-2023				
Eff: 12-Jan-2000 Complied With						Hrs	13,276.7				
(ISSUING AUTHORITY: FAA)						Ldg	8,977				
						Flt	8,977				
99-25-09 Paragraph (a)	**Hinge Pin Assemblies of Horizontal Stabilizer - Dassault Airplane Flight Manual (AFM) Revision**							RE (-)		Mandatory	
27 A/F						Mos					
Eff: 12-Jan-2000 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
99-25-09 Paragraph (b),(c)	**Hinge Pin Assemblies of Horizontal Stabilizer - Initial and Repetitive Inspections**							RE		Mandatory	
27 A/F						Mos	14-Sep-2023	72		14-Sep-2029	4.5 Years
Complied With						Hrs	13,276.7				
(ISSUING AUTHORITY: FAA)						Ldg	8,977	3,750		12,727	3,594 Ldg
						Flt	8,977				
99-25-09 Paragraph (e)	**Hinge Pin Assemblies of Horizontal Stabilizer - Hinge Pin Replacement**							RE (-)		Mandatory	
27 A/F						Mos					
Eff: 12-Jan-2000 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
F50-007	**Leading edge slats - Separate test of the microswitches**							RE (-)			
27 A/F						Mos					
Eff: 08-Feb-1980						Hrs					
						Ldg					
Note: M0030						Flt					
F50-046	**Increased gap between box door and servocontrol**							RE (-)			
27 A/F						Mos					
Eff: 07-Mar-1980						Hrs					
						Ldg					
Note: M0263						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-082	**Airbrakes - Elimination of the asymmetries at low temperatures**							T (A/R)			
27 A/F						Mos					
Eff: 28-Jan-1981						Hrs					
						Ldg					
Note: M0382						Flt					
F50-165	**Airbrakes - Pressure holding valves**							T (A/R)			
27 A/F						Mos					
Eff: 26-Mar-1987						Hrs					
						Ldg					
Note: M0987, M0739A						Flt					
F50-166	**Outboard slats - Monitoring of the flight/ground switches**							T (A/R)			
27 A/F						Mos					
Eff: 17-Nov-1986						Hrs					
						Ldg					
Note: M1142						Flt					
F50-170	**Elevators and aileron servo-actuators - Installation of protection boxes**							RE (-)			
27 A/F						Mos					
						Hrs					
						Ldg					
Note: M0911						Flt					
F50-170 R1	**Elevators and aileron servo-actuators - Installation of protection boxes**							T (A/R)			
27 A/F						Mos					
Eff: 29-Nov-1993						Hrs					
						Ldg					
Note: M0911						Flt					
F50-181	**Slat actuators - New swivel connector design**							T (A/R)			
27 A/F						Mos					
Eff: 20-Nov-1986						Hrs					
						Ldg					
Note: M1326						Flt					
F50-187	**Horizontal stabilizer actuator - Hinge pin installation safety device**							RE (-)			
27 A/F						Mos	18-Jun-1987				
Eff: 24-Feb-1988 Complied With						Hrs	4,087.5				
SB:F50-27-010						Ldg	2,821				
						Flt					
F50-193	**Normal slat actuators - New scraper ring bearing**							T (A/R)			
27 A/F						Mos					
Eff: 20-Nov-1986						Hrs					
						Ldg					
Note: M1434						Flt					
F50-201	**Outboard slat emergency actuators - New scraper ring bearing**							T (A/R)			
27 A/F						Mos					
Eff: 15-Jun-1988						Hrs					
						Ldg					
Note: M1440B						Flt					
F50-233	**Leading edge slats - Improved protection of the slat emergency extension switch**							RE (-)			
27 A/F						Mos					
						Hrs					
						Ldg					
Note: M1733						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-233 R1	**Leading edge slats - Improved protection of the slat emergency extension switch**							T (A/R)			
27 A/F						Mos					
Eff: 05-Nov-2004						Hrs					
						Ldg					
Note: M1733						Flt					
F50-245	**Inboard flaps - Addition of a second spring on the control lever of the flaps retracted microswitch**							T (A/R)			
27 A/F						Mos					
Eff: 28-Jun-1995						Hrs					
						Ldg					
Note: M1919						Flt					
F50-247	**Horizontal stabilizer actuator - Normal motor replacement**							T (A/R)			
27 A/F						Mos					
Eff: 07-Feb-1996						Hrs					
						Ldg					
Note: M1898, 2 to 240, 242 to 245, 247 to 251 with HS actuator P/N 021121-01						Flt					
F50-267	**Horizontal stabilizer actuator - Reduced maintenance for normal motor**							T (A/R)			
27 A/F						Mos					
Eff: 04-Mar-1998						Hrs					
						Ldg					
Note: M2140, M2181, 2 to 264 with HS actuator P/N 021121-01 or 021121-05 or 021121-06						Flt					
F50-298	**Aileron auxiliary AFU - Check of the attaching screws**							T (A/R)			
27 A/F						Mos					
Eff: 14-Mar-2001						Hrs					
						Ldg					
						Flt					
F50-343-Alert	**Horizontal stabilizer - Emergency control - Check of wiring assembly integrity**							RE (-)			
27 A/F						Mos					
Eff: 10-Jun-1999						Hrs					
						Ldg					
						Flt					
F50-345	**Non-destructive testing of carbon ailerons for aircraft S/N 5, 15, 33, 71, 92, 154, 164**							RE (-)			
27 A/F						Mos					
Eff: 11-Jul-2001						Hrs					
						Ldg					
						Flt					
F50-455-Alert	**Flaps - Inspecting proper control rod installation**							T (A/R)			
27 A/F						Mos					
Eff: 06-Jun-2005						Hrs					
						Ldg					
						Flt					
F50-468	**Flaps - Checking and labelling the rotating rod's orientation in the wing root area**							RE (-)			
27 A/F						Mos	29-Aug-2006				
Eff: 12-May-2006						Hrs	10,346.8				
						Ldg	7,284				
Note: M2996, AD EASA 2006-0115 (AD FAA 2007-25-10)						Flt					
▼ 28 - FUEL											
	APU Fuel Supply Hose							RE (H/T)			
28 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Booster Pump							RE (O/C)			
	28 A/F	No.1					Mos	03-Jun-2022				
	2061H02						Hrs					
	1083						Ldg					
							Flt					
		Booster Pump							RE (O/C)			
	28 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Booster Pump							RE (O/C)			
	28 A/F	No.3					Mos	28-Jul-2023				
	2061H	Overhauled		0			Hrs	13,276.7				
	595			0			Ldg	8,977				
				0			Flt	8,977				
		BP Manifold Transfer Valve Actuator							RE (O/C)			
	28 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		BP Manifold Transfer Valve Actuator							RE (O/C)			
	28 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Center Feeder Tank Drain Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Center Section Air Vent Draining Ball Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Center Section Air Vent Draining Ball Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Center Section Fuelling Float Switch							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Center Section Fuelling Float Switch							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Center Section Overfull Float Switch							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Center Section Overfull Float Switch							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Center Tank Loading Printed Card							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Center Transfer Pump Priming Check Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Door Feeder Tank Drain Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Door Feeder Tank Drain Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Supply Hose							RE (H/T)			
	28 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Supply Hose							RE (H/T)			
	28 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Supply Hose							RE (H/T)			
	28 A/F	No.3					Mos	08-Mar-2004				
	665106EE2001						Hrs					
	DF1-2004						Ldg					
							Flt					
		Engine Pressurization Air Filter							RE (O/C)			
	28 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Pressurization Air Filter							RE (O/C)			
	28 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Feeder Tank Air Vent Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Feeder Tank Ck Valve/Hi-Level Valve Return Hose							RE (H/T)			
	28 A/F	Center					Mos	14-Sep-2023				
	71030-676A						Hrs	13,276.7				
	82885						Ldg	8,977				
							Flt	8,977				
		Feeder Tank Ck Valve/Hi-Level Valve Return Hose							RE (H/T)			
	28 A/F	Left					Mos	14-Sep-2023				
	71030-496A	New	0				Hrs	13,276.7				
	82736		0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank Ck Valve/Hi-Level Valve Return Hose							RE (H/T)			
	28 A/F	Right					Mos	14-Sep-2023				
	71030-496A	New	0				Hrs	13,276.7				
	82735		0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank Drain Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Feeder Tank Drain Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Feeder Tank Forward Pressure Reducer Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Feeder Tank High Level/Valve Supply Hose							RE (H/T)			
	28 A/F	Center					Mos	14-Sep-2023				
	71028-2460A	New	0				Hrs	13,276.7				
	82824		0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank High Level/Valve Supply Hose							RE (H/T)			
	28 A/F	Left					Mos	14-Sep-2023				
	71028-1290A	New	0				Hrs	13,276.7				
	92929		0				Ldg	8,977				
			0				Flt	8,977				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Feeder Tank High Level/Valve Supply Hose							RE (H/T)			
28 A/F		Right					Mos	14-Sep-2023				
71028-1290A		New	0				Hrs	13,276.7				
82928			0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank Manifold							RE (O/C)			
28 A/F		Center					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Feeder Tank Manifold							RE (O/C)			
28 A/F		Left					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Feeder Tank Manifold							RE (O/C)			
28 A/F		Right					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Feeder Tank Overfull Float Switch							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Feeder Tank Pressure Relief Valve							RE (O/C)			
28 A/F		Left					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Feeder Tank Pressurerelief Valve							RE (O/C)			
28 A/F		Right					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Feeder Tank Pressurization Forward Non Return Valve							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Feeder Tank Quantity Gauge							RE (O/C)			
28 A/F		Center					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Feeder Tank Quantity Gauge							RE (O/C)			
28 A/F		Left					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Feeder Tank Quantity Gauge							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Feeder Tank Regulation Valve Supply Hose							RE (H/T)			
	28 A/F	Center					Mos	14-Sep-2023				
	71029-450A	New	0				Hrs	13,276.7				
	83021		0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank Regulation Valve Supply Hose							RE (H/T)			
	28 A/F	Left					Mos	14-Sep-2023				
	71029-1020A	New	0				Hrs	13,276.7				
	82966		0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank Regulation Valve Supply Hose							RE (H/T)			
	28 A/F	Right					Mos	14-Sep-2023				
	71029-1020A	New	0				Hrs	13,276.7				
	82967		0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank Regulation/Transfer Valve Sply Hose							RE (H/T)			
	28 A/F	Center					Mos	14-Sep-2023				
	71029-560A	New	0				Hrs	13,276.7				
	82986		0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank Solenoid/Transfer Valve Hose							RE (H/T)			
	28 A/F	Center					Mos	14-Sep-2023				
	71029-420A	New	0				Hrs	13,276.7				
	83037		0				Ldg	8,977				
			0				Flt	8,977				
		Feeder Tank Solenoid/Transfer Valve Hose							RE (H/T)			
	28 A/F	Left					Mos	27-Feb-2024				
	71029-3808	New	0				Hrs	13,292.4				
	83423		0				Ldg	8,992				
			0				Flt	8,992				
		Feeder Tank Solenoid/Transfer Valve Hose							RE (H/T)			
	28 A/F	Right					Mos	27-Feb-2024				
	71029-3808	New	0				Hrs	13,292.4				
	83424		0				Ldg	8,992				
			0				Flt	8,992				
		Feeder Tank Transfer Jet-Pump							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Feeder Tank Transfer Jet-Pump							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Feeder Tank Transfer Valve							RE (H/T)			
	28 A/F	Center					Mos	20-Jan-1981				
	2504-3						Hrs	0				
	1712						Ldg	0				
							Flt					
		Feeder Tank Transfer Valve							RE (H/T)			
	28 A/F	Left					Mos	20-Oct-2021				
	2504-3						Hrs					
	721						Ldg					
							Flt					
		Feeder Tank Transfer Valve							RE (H/T)			
	28 A/F	Right					Mos	20-Jan-1981				
	2504-3						Hrs	0				
	1656						Ldg	0				
							Flt					
		Feeder Tank Vacuum Pressure Relief Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Feeder Tank Vacuum Pressure Relief Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Filler Block							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Filler Plug							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Filler Plug							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Filler Valve							RE (O/C)			
	28 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Filler Valve							RE (O/C)			
	28 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Filler Valve							RE (O/C)			
	28 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Filling Circuit Transfer Check Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Fire Shut-Off Handle							RE (O/C)			
	28 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Fire Shut-Off Handle							RE (O/C)			
	28 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Fire Shut-Off Handle							RE (O/C)			
	28 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Forward Center Wing Drain Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Fuel Fire Shut-Off Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Fuel Fire Shut-Off Valve							RE (O/C)			
	28 A/F	Middle					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Fuel Fire Shut-Off Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Fuel Quantity Indicator							RE (O/C)			
	28 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fuel Quantity Indicator							RE (O/C)			
28 A/F		Left					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Fuel Quantity Indicator							RE (O/C)			
28 A/F		Right					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Fuel Tank Low Level Printed Circuit Card							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Fuel Temperature Indicator							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Fuel Test Valve							RE (O/C)			
28 A/F							Mos	14-Sep-2023				
AV24A1156		Serviceable					Hrs	13,276.7				
RL84006							Ldg	8,977				
							Flt	8,977				
		Fuel Test Valve Proximity Sensor							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Fuel Xfer Pump Switch							RE (O/C)			
28 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Fuel Xfer Pump Switch							RE (O/C)			
28 A/F		No.2					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Fuel Xfer Pump Switch							RE (O/C)			
28 A/F		No.3					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Isolating Valve							RE (O/C)			
28 A/F		Left					Mos	24-Mar-2021				
AV24A1157							Hrs					
L20651							Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Isolating Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Jet Pump Booster System Check Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Jet Pump Booster System Check Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lateral Tank Loading Printed Card							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Low Pressure Pump Bell Housing							RE (O/C)			
	28 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Low Pressure Pump Bell Housing							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Low Pressure Pump Bell Housing							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Low Pressure Switch							RE (O/C)			
	28 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Low Pressure Switch							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Low Pressure Switch							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Low Transfer Pressure Switch							RE (O/C)			
28 A/F		Center					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Low Transfer Pressure Switch							RE (O/C)			
28 A/F		Left					Mos	07-Jul-2015				
1G344-1							Hrs					
1748							Ldg					
							Flt					
		Low Transfer Pressure Switch							RE (O/C)			
28 A/F		Right					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Microswitch, Fuel Door Clsg(42Q)							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Middle Center Wing Drain Valve							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Middle Isolating Valve							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Middle Tank Level Solenoid Valve							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Pressure Refueling Unit							RE (O/C)			
28 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Quantity Indicator System Amplifier							RE (O/C)			
28 A/F		Center					Mos	24-Oct-1984				
706-720-1							Hrs	2,295.25				
275							Ldg	1,597				
							Flt					
		Quantity Indicator System Amplifier							RE (O/C)			
28 A/F		Left					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Quantity Indicator System Amplifier							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rear Center Wing Drain Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Shut-Off Valve Flexible Control Cable							RE (O/C)			
	28 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Shut-Off Valve Flexible Control Cable							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Shut-Off Valve Flexible Control Cable							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Strainer							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Strainer							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		System Center Feeder Tank Test Check Valve							RE (O/C)			
	28 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		System Center Feeder Tank Test Check Valve							RE (O/C)			
	28 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tank High Level Float Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Tank High Level Float Valve							RE (O/C)			
	28 A/F	Middle					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tank High Level Float Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tank Level Solenoid Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tank Level Solenoid Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tank Low Level Float Valve							RE (O/C)			
	28 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tank Low Level Float Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tank Low Level Float Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tank Pressurization Automatic Drain							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Test System Check Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Transfer Interconnection Valve Actuator							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Transfer Interconnection Valve Actuator							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Transfer Jet Pump Filter							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Transfer Jet Pump Filter							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Transfer Manifold Refueling Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Transfer Pump							RE (O/C)			
	28 A/F	Center					Mos	10-Aug-2024				
	2060A-01	Overhauled		0			Hrs	13,363.9				
	2618			0			Ldg	9,034				
				0			Flt	9,033				
		Transfer Pump							RE (O/C)			
	28 A/F	Left					Mos	24-Mar-2021				
	2060A-01						Hrs					
	E46406						Ldg					
							Flt					
		Transfer Pump							RE (O/C)			
	28 A/F	Right					Mos	30-Sep-2019				
	2060A-01						Hrs					
	A01986						Ldg					
							Flt					
		Transfer Pump Check Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Transfer Pump Check Valve							RE (O/C)			
	28 A/F	Middle					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Transfer Pump Check Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Transfer Unit							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Valve Box							RE (H/T)			
	28 A/F	Left					Mos	09-Aug-2021				
	2415-1010						Hrs					
	1246						Ldg					
							Flt					
		Valve Box							RE (H/T)			
	28 A/F	Right					Mos	09-Aug-2021				
	2415-1010						Hrs					
	1727						Ldg					
							Flt					
		Wing Air Vent Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Air Vent Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Center Quantity Gauge							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Center Quantity Gauge							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Drain Valve							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Drain Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Forward Quantity Gauge							RE (O/C)			
	28 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Wing Fuelling Float Switch							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Fuelling Float Switch							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Inboard Quantity Gauge							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Inboard Quantity Gauge							RE (O/C)			
	28 A/F	Right					Mos	26-Aug-2021				
	792-366-1A						Hrs					
	373						Ldg					
							Flt					
		Wing Outboard Quantity Gauge							RE (O/C)			
	28 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Outboard Quantity Gauge							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Rear Quantity Gauge							RE (O/C)			
	28 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Tank Negative Pressure Relief Valve							RE (O/C)			
	28 A/F	Left					Mos	07-Feb-2017				
	B06GA1050						Hrs					
	2695						Ldg					
							Flt					
		Wing Tank Negative Pressure Relief Valve							RE (O/C)			
	28 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Tank Pressurization Automatic Drain							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Wing Tank Pressurization Rear Non Return Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Tank Rear Pressure Reducer Valve							RE (O/C)			
	28 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2002-06-12		**Feeder Tanks - To prevent fuel leaks from the feeder tanks**							RE (-)		Mandatory	
	28 A/F						Mos	10-Dec-2002				
	Eff: 07-May-2002 Not Applicable	By Aircraft SN					Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
2002-06-12 Paragraph (a)		**Feeder Tanks - To prevent fuel leaks from the feeder tanks - Leak Testing**							RE (-)		Mandatory	
	28 A/F						Mos	10-Dec-2002				
	Eff: 07-May-2002 Not Applicable	By Aircraft SN					Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
2002-06-12 Paragraph (b)		**Feeder Tanks - To prevent fuel leaks from the feeder tanks - Corrective Action**							RE (-)		Mandatory	
	28 A/F						Mos	10-Dec-2002				
	Eff: 07-May-2002 Not Applicable	By Aircraft SN					Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
2002-06-12 Paragraph (c)		**Feeder Tanks - To prevent fuel leaks from the feeder tanks - Modification**							RE (-)		Mandatory	
	28 A/F						Mos	10-Dec-2002				
	Eff: 07-May-2002 Not Applicable	By Aircraft SN					Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
2004-04-11		**Left-hand and right-hand feeder tanks - Installation**							RE (-)		Mandatory	
	28 A/F						Mos	12-Oct-2010				
	Eff: 05-Apr-2004 Complied With						Hrs	11,295				
	(ISSUING AUTHORITY: FAA)						Ldg	7,881				
							Flt					
28-00-00-280-801-01		**Fuel Contamination Detection Test**							RE		Acft Maint Ops (5-10)	
	28 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
	(Tol. Adjustment: -83d)						Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
28-00-00-910-804		**Measures to Be Taken After Maintenance Operations In the Fuel Tanks**							T (A/R)		Unsch Maint Chk (5-50)	
	28 A/F						Mos					
							Hrs			+50		
	(SOURCE: Falcon 50/50EX MPD)						Ldg					
	Note: To be performed after any operation in the fuel tanks requiring the use of sealant, and to be performed again after 25-75 flight hours from the initial operation.						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-00-00-960-802-01		**Discard of Feeder Tank Fuel Hoses - LH Feeder Tank Sol./Transf. Valve Hose (L903Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	71029-3808	Left					Mos	27-Feb-2024	144	-/+20%m	[31-Dec-2032]	7.8 Years (+874 Days)
	83423						Hrs	13,292.4				
		Manufactured Date 31-Dec-2022					Ldg	8,992				
							Flt	8,992				
		Note: P/N 70837-380 or 71029-380A (104)										
28-00-00-960-802-02		**Discard of Feeder Tank Fuel Hoses - Center Feeder Tank Sol./Transf. Valve Hose (M903Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	71029-420A	Center					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
	83037						Hrs	13,276.7				
		Manufactured Date 30-Jun-2023					Ldg	8,977				
							Flt	8,977				
		Note: P/N 70837-420 or 71029-420A (104)										
28-00-00-960-802-03		**Discard of Feeder Tank Fuel Hoses - RH Feeder Tank Sol./Transf. Valve Hose (R903Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	71029-3808	Right					Mos	27-Feb-2024	144	-/+20%m	[31-Dec-2032]	7.8 Years (+874 Days)
	83424						Hrs	13,292.4				
		Manufactured Date 31-Dec-2022					Ldg	8,992				
							Flt	8,992				
		Note: P/N 70837-380 or71029-380A (104)										
28-00-00-960-802-04		**Discard of Feeder Tank Fuel Hoses - LH Feeder Tank Reg. Valve Supply Hose (L904Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	71029-1020A	Left					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
	82966						Hrs	13,276.7				
		Manufactured Date 30-Jun-2023					Ldg	8,977				
							Flt	8,977				
		Note: P/N 70837-1020 or 71029-1020A (104)										
28-00-00-960-802-05		**Discard of Feeder Tank Fuel Hoses - Center Feeder Tank Reg. Valve Supply Hose (M904Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	71029-450A	Center					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
	83021						Hrs	13,276.7				
		Manufactured Date 30-Jun-2023					Ldg	8,977				
							Flt	8,977				
		Note: P/N 70837-450 or 71029-450A (104)										
28-00-00-960-802-06		**Discard of Feeder Tank Fuel Hoses - RH Feeder Tank Reg. Valve Supply Hose (R904Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	71029-1020A	Right					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
	82967						Hrs	13,276.7				
		Manufactured Date 30-Jun-2023					Ldg	8,977				
							Flt	8,977				
		Note: P/N 70837-1020 or 71029-1020A (104)										
28-00-00-960-802-07		**Discard of Feeder Tank Fuel Hoses - Center Feeder Tank Reg./Transf. Valve Supply Hose (M905Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	71029-560A	Center					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
	82986						Hrs	13,276.7				
		Manufactured Date 30-Jun-2023					Ldg	8,977				
							Flt	8,977				
		Note: P/N 70837-560 or 71029-560A (104)										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-00-00-960-802-08	**Discard of Feeder Tank Fuel Hoses - LH Feeder Tank High Level/Sol. Valve Hose (L906QD)**							RE		Comp Maint Ops (5-20)	
28 A/F	Left					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
71028-610A						Hrs	13,276.7				
83094						Ldg	8,977				
Manufactured Date 30-Jun-2023						Flt	8,977				
(SOURCE: Falcon 50/50EX MPD)											
Note: P/N 70836-610 or P/N 71028-610 or P/N 71028-610A.											
NOTE 104: The utilization limit, depending on the storage time of hoses elastomer (neoprene) air data, fuel and hydraulic system, before their installation on aircraft, is defined in the table given in fig. 1.											
28-00-00-960-802-09	**Discard of Feeder Tank Fuel Hoses - RH Feeder Tank High Level/Sol. Valve Hose (R906QD)**							RE		Comp Maint Ops (5-20)	
28 A/F	Right					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
71028-610A						Hrs	13,276.7				
83095						Ldg	8,977				
Manufactured Date 30-Jun-2023						Flt	8,977				
(SOURCE: Falcon 50/50EX MPD)											
Note: P/N 70836-610 or P/N 71028-610 or P/N 71028-610A.											
NOTE 104: The utilization limit, depending on the storage time of hoses elastomer (neoprene) air data, fuel and hydraulic system, before their installation on aircraft, is defined in the table given in fig. 1.											
28-00-00-960-802-10	**Discard of Feeder Tank Fuel Hoses - LH Feeder Tank High Level/Valve Supply Hose (L907Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	Left					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
71028-1290A						Hrs	13,276.7				
92929						Ldg	8,977				
Manufactured Date 30-Jun-2023						Flt	8,977				
Note: P/N 70836-1290 or 71028-1290A (104)											
28-00-00-960-802-11	**Discard of Feeder Tank Fuel Hoses - Center Feeder Tank High Level/Valve Supply Hose (M907Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	Center					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
71028-2460A						Hrs	13,276.7				
82824						Ldg	8,977				
Manufactured Date 30-Jun-2023						Flt	8,977				
Note: P/N 70836-2460 or 71028-2460A (104)											
28-00-00-960-802-12	**Discard of Feeder Tank Fuel Hoses - RH Feeder Tank High Level/Valve Supply Hose (R907Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	Right					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
71028-1290A						Hrs	13,276.7				
82928						Ldg	8,977				
Manufactured Date 30-Jun-2023						Flt	8,977				
Note: P/N 70836-1290 or 71028-1290A (104)											
28-00-00-960-802-13	**Discard of Feeder Tank Fuel Hoses - LH Feeder Tank Ck Valve/High Level Valve Return Hose (L908Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	Left					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
71030-496A						Hrs	13,276.7				
82736						Ldg	8,977				
Manufactured Date 30-Jun-2023						Flt	8,977				
Note: P/N 70838-496 or 71030-496A (104)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-00-00-960-802-14	**Discard of Feeder Tank Fuel Hoses - Center Feeder Tank Ck Valve/High Level Valve Return Hose (M908Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	Center					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
71030-676A						Hrs	13,276.7				
82885						Ldg	8,977				
Manufactured Date 30-Jun-2023						Flt	8,977				
Note: P/N 70838-676 or 71030-676A (104)											
28-00-00-960-802-15	**Discard of Feeder Tank Fuel Hoses - RH Feeder Tank Ck Valve/High Level Valve Return Hose (R908Qd)**							RE		Comp Maint Ops (5-20)	
28 A/F	Right					Mos	14-Sep-2023	144	-/+20%m	30-Jun-2035	10.3 Years (+877 Days)
71030-496A						Hrs	13,276.7				
82735						Ldg	8,977				
Manufactured Date 30-Jun-2023						Flt	8,977				
Note: P/N 70838-496 or 71030-496A (104)											
28-20-00-710-802-01	**Operational Test of the Transfer Valves and Isolation Valves - Transfer Manifold Transfer Valves (17Q1) and (17Q2)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
28 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
Note: during engine run-up						Flt	8,977				
28-20-00-710-802-02	**Operational Test of the Transfer Valves and Isolation Valves - Transfer Valve (13Q1) and (13Q2)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
28 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
Note: during engine run-up						Flt	8,977				
28-20-00-710-802-03	**Operational Test of the Transfer Valves and Isolation Valves - Isolation Valves (L17Qd) , (M17Qd) and (R17Qd)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
28 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
Note: during engine run-up						Flt	8,977				
28-20-00-900-801-08	**Feeder Tank High Level/Solenoid Valve Hose**							RE (H/T)			
28 A/F	Left					Mos	14-Sep-2023				
71028-610A	New	0				Hrs	13,276.7				
83094		0				Ldg	8,977				
		0				Flt	8,977				
28-20-00-900-801-09	**Feeder Tank High Level/Solenoid Valve Hose**							RE (H/T)			
28 A/F	Right					Mos	14-Sep-2023				
71028-610A	New	0				Hrs	13,276.7				
83095		0				Ldg	8,977				
		0				Flt	8,977				
28-21-01-350-801-01	**Restoration of the Booster Pumps (Replacement of Motor Brushes) - Booster Pump 1 (3Q1)**							RE		Comp Maint Ops (5-20)	**≈01-Aug-2027**
28 A/F	No.1					Mos	11-Aug-2021				
2061H02						Hrs	13,195	1,200	+3%	14,395	874.1 Hrs (+36)
1083						Ldg	8,930				
Note: P/N 2061H or 2061H02 (1)						Flt					
28-21-01-350-801-02	**Restoration of the Booster Pumps (Replacement of Motor Brushes) - Booster Pump 2 (3Q2)**							RE (N/A)		Comp Maint Ops (5-20)	
28 A/F	No.2					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-21-01-350-801-03		**Restoration of the Booster Pumps (Replacement of Motor Brushes) - Booster Pump 3 (3Q3)**							RE		Comp Maint Ops (5-20)	**≈10-Oct-2027**
	28 A/F	No.3					Mos	28-Jul-2023				
	2061H						Hrs	13,276.7	1,200	+3%	14,462.9	942 Hrs (+36)
	595						Ldg	8,977				
		(Tol. Adjustment: -13.8 Hrs)					Flt	8,977				
		Note: P/N 2061H or 2061H02										
		(1)										
28-21-01-350-802-01		**Restoration of the Booster Pumps (Replacement of Bearings) - Booster Pump 1 (3Q1)**							RE		Comp Maint Ops (5-20)	**≈19-Jul-2027**
	28 A/F	No.1					Mos	15-Jan-2015				
	2061H02						Hrs	11,982.4	2,400	+3%	14,382.4	861.5 Hrs (+72)
	1083						Ldg	8,262				
							Flt					
		Note: P/N 2061H or 2061H02										
		(1)										
		P/N 2061H : This periodicity must be reduced to 1200 hours when JP4 is used										
		P/N 2061H02 : only one bearing										
28-21-01-350-802-02		**Restoration of the Booster Pumps (Replacement of Bearings) - Booster Pump 2 (3Q2)**							RE (N/A)		Comp Maint Ops (5-20)	
	28 A/F	No.2					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		Note: P/N 2061H or 2061H02										
		(1)										
		P/N 2061H : This periodicity must be reduced to 1200 hours when JP4 is used										
		P/N 2061H02 : only one bearing										
28-21-01-350-802-03		**Restoration of the Booster Pumps (Replacement of Bearings) - Booster Pump 3 (3Q3)**							RE		Comp Maint Ops (5-20)	**≈21-Feb-2031**
	28 A/F	No.3					Mos	28-Jul-2023				
	2061H						Hrs	13,276.7	2,400	+3%	15,676.7	2,155.8 Hrs (+72)
	595						Ldg	8,977				
							Flt	8,977				
		Note: P/N 2061H or 2061H02										
		(1)										
		P/N 2061H : This periodicity must be reduced to 1200 hours when JP4 is used										
		P/N 2061H02 : only one bearing										
28-21-05-200-802-01		**Check of Low Pressure Crossfeed Draining and Shut-Off Valve Seals of the BP Manifold - BP 1 Manifold (L14Qd)**							RE		Comp Maint Ops (5-20)	**≈04-Feb-2043**
	28 A/F	Left					Mos	15-Dec-1988				
	Unknown						Hrs	9,982	10,000	+3%	19,982	6,461.1 Hrs (+300)
	Unknown						Ldg	6,861				
							Flt					
		Note: P/N L88A19-202 or L88A19-203 or L88A19-205 or L88A19-207 or L88A19-208 or L88A19-209										
		(1)										
28-21-05-200-802-02		**Check of Low Pressure Crossfeed Draining and Shut-Off Valve Seals of the BP Manifold - BP 3 Manifold (R14Qd)**							RE		Comp Maint Ops (5-20)	**≈25-Feb-2043**
	28 A/F	Right					Mos	21-Dec-2004				
	Unknown						Hrs	10,004.7	10,000	+3%	20,004.7	6,483.8 Hrs (+300)
	Unknown						Ldg	7,048				
							Flt					
		Note: P/N L88A19-202 or L88A19-203 or L88A19-205 or L88A19-207 or L88A19-208 or L88A19-209										
		(1)										
28-21-07-100-801-01		**Cleaning of the Jet Pump Filters - LH Jet Pump Filter (L40QD)**							RE		Acft Maint Ops (5-10)	
	28 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
							Hrs	13,276.7				
		(SOURCE: Falcon 50/50EX MPD)					Ldg	8,977				
		Note: Also at 25-75 hours following C inspection. More often if necessary					Flt	8,977				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-21-07-100-801-01	**Cleaning of the Jet Pump Filters - LH Jet Pump Filter (L40Qd) (Also at 25-75 hours following C inspection. More often if necessary.)**							RE (A/R)		Acft Maint Ops (5-10)	
28 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7		+50		
(SOURCE: Falcon 50/50EX MPD)						Ldg	8,977				
Note: After completing this task at 25-75 hours following C inspection, reset task interval to T: A/R.						Flt	8,977				
28-21-07-100-801-02	**Cleaning of the Jet Pump Filters - RH Jet Pump Filter (R40QD)**							RE		Acft Maint Ops (5-10)	
28 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(SOURCE: Falcon 50/50EX MPD)						Ldg	8,977				
Note: Also at 25-75 hours following C inspection. More often if necessary						Flt	8,977				
28-21-07-100-801-02	**Cleaning of the Jet Pump Filters - RH Jet Pump Filter (R40Qd) (Also at 25-75 hours following C inspection. More often if necessary.)**							RE (A/R)		Acft Maint Ops (5-10)	
28 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7		+50		
(SOURCE: Falcon 50/50EX MPD)						Ldg	8,977				
Note: After completing this task at 25-75 hours following C inspection, reset task interval to T: A/R.						Flt	8,977				
28-21-13-790-801-01	**Leak Test of the Fuel Shut-Off Valves - Engine 1 Shut-Off Valve integrated in BP 1 manifold (L14QD)**							RE		Acft Maint Ops (5-10)	**≈05-Mar-2028**
28 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	1,530		14,609.2	1,088.3 Hrs
						Ldg	8,836				
Note: At each engine removal without exceeding 1530 Hrs						Flt					
28-21-13-790-801-01 (5-40)	**Leak Test of the Fuel Shut-Off Valves - Engine 1 Shut-Off Valve integrated in BP 1 manifold (L14QD)**							RE		AWL (5-40), CMR	**≈05-Mar-2028**
28 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	1,530		14,609.2	1,088.3 Hrs
						Ldg	8,836				
						Flt					
28-21-13-790-801-02	**Leak Test of the Fuel Shut-Off Valves - Engine 2 Shut-Off Valve integrated in BP 2 manifold (M14QD)**							RE		Acft Maint Ops (5-10)	**≈05-Mar-2028**
28 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	1,530		14,609.2	1,088.3 Hrs
						Ldg	8,836				
Note: At each engine removal without exceeding 1530 Hrs						Flt					
28-21-13-790-801-02 (5-40)	**Leak Test of the Fuel Shut-Off Valves - Engine 2 Shut-Off Valve integrated in BP 2 manifold (M14QD)**							RE		AWL (5-40), CMR	**≈05-Mar-2028**
28 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	1,530		14,609.2	1,088.3 Hrs
						Ldg	8,836				
Note: At each engine removal without exceeding 1530 Hrs						Flt					
28-21-13-790-801-03	**Leak Test of the Fuel Shut-Off Valves - Engine 3 Shut-Off Valve integrated in BP 3 manifold (R14QD)**							RE		Acft Maint Ops (5-10)	**≈05-Mar-2028**
28 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	1,530		14,609.2	1,088.3 Hrs
						Ldg	8,836				
Note: At each engine removal without exceeding 1530 Hrs						Flt					
28-21-13-790-801-03 (5-40)	**Leak Test of the Fuel Shut-Off Valves - Engine 3 Shut-Off Valve integrated in BP 3 manifold (R14QD)**							RE		AWL (5-40), CMR	**≈05-Mar-2028**
28 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	1,530		14,609.2	1,088.3 Hrs
						Ldg	8,836				
Note: At each engine removal without exceeding 1530 Hrs						Flt					
28-21-14-720-801-01	**Functional Test of the BP Manifold thermal Expansion Systems - BP 1 Manifold (L14Qd)**							RE		Comp Maint Ops (5-20)	**≈02-Dec-2041**
28 A/F	Left					Mos	17-May-1988				
Unknown						Hrs	9,560	10,000	+3%	19,560	6,039.1 Hrs (+300)
Unknown						Ldg	6,540				
						Flt					
Note: P/N L88A19-202 or L88A19-203 or L88A19-205 or L88A19-207 or L88A19-208 or L88A19-209 (1)											

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-21-14-720-801-02	**Functional Test of the BP Manifold thermal Expansion Systems - BP 3 Manifold (R14Qd)**							RE		Comp Maint Ops (5-20)	**≈25-Feb-2043**
28 A/F	Right					Mos	21-Dec-2004				
Unknown						Hrs	10,004.7	10,000	+3%	20,004.7	6,483.8 Hrs (+300)
Unknown						Ldg	7,048				
						Flt					
Note: P/N L88A19-202 or L88A19-203 or L88A19-205 or L88A19-207 or L88A19-208 or L88A19-209											
(1)											
28-21-16-610-801-01	**Servicing of the Fuel Shut-Off Valves Control Cables - Servicing of the Control Cables and Checking of the Shut-Off Valves Opening/Closing**							RE		Acft Maint Ops (5-10)	
28 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
						Hrs	13,386.3	1,000	+30		
						Ldg	9,044				
						Flt	9,043				
28-21-16-610-801-01 (5-40)	**Servicing of the Fuel Shut-Off Valves Control Cables - Servicing of the Control Cables and Checking of the Shut-Off Valves Opening/Closing**							RE		AWL (5-40), CMR	
28 A/F						Mos	30-Aug-2024	13		30-Sep-2025	6.9 Months
						Hrs	13,386.3	1,000		14,386.3	865.4 Hrs
Ref:28-180						Ldg	9,044				
						Flt	9,043				
28-21-16-610-801-02	**Servicing of the Fuel Shut-Off Valves Control Cables - Measurement of Control Cable Sliding Forces**							RE		Acft Maint Ops (5-10)	
28 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
(Tol. Adjustment: -108d)						Hrs	13,386.3				
Note: A/C with TELEFORCE controls (type S41-21) After SB F50-092						Ldg	9,044				
						Flt	9,043				
28-21-33-960-801-01	**Discard of the Fuel Supply Hoses - APU Fuel Supply Hose (902Qd)**							RE (N/A)		Comp Maint Ops (5-20)	
28 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
28-21-33-960-801-02	**Discard of the Fuel Supply Hoses - Engine 1 Fuel Supply Hose (L901Qd)**							RE (N/A)		Comp Maint Ops (5-20)	
28 A/F	No.1					Mos	21-Dec-2023				
Unknown						Hrs	13,288.4				
Unknown						Ldg	8,991				
30-Sep-2003						Flt	8,991				
28-21-33-960-801-03	**Discard of the Fuel Supply Hoses - Engine 2 Fuel Supply Hose (M901Qd)**							RE (N/A)		Comp Maint Ops (5-20)	
28 A/F	No.2					Mos	21-Dec-2023				
Unknown						Hrs	13,288.4				
Unknown						Ldg	8,991				
30-Jun-2008						Flt	8,991				
28-21-33-960-801-04	**Discard of the Fuel Supply Hoses - Engine 3 Fuel Supply Hose (R901Qd)**							RE (N/A)		Comp Maint Ops (5-20)	
28 A/F	No.3					Mos	21-Dec-2023				
665106EE2001						Hrs	13,288.4				
DF1-2004						Ldg	8,991				
30-Apr-2007						Flt	8,991				
28-22-05-350-801-01	**Restoration of the Transfer Pump (Replacement of Motor Brushes) - LH Transfer Pump (23Q1)**							RE		Comp Maint Ops (5-20)	**≈17-Sep-2029**
28 A/F	Left					Mos	22-Jun-2016				
2060A-01						Hrs	13,161.4	2,000	+3%	15,161.4	1,640.5 Hrs (+60)
E46406						Ldg					
						Flt					
Note: P/N 2060A01 or 2060A12											
(1)											

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-22-05-350-801-02		**Restoration of the Transfer Pump (Replacement of Motor Brushes) - Center Transfer Pump (23Q2)**							RE		Comp Maint Ops (5-20)	**≈09-Apr-2030**
	28 A/F	Center					Mos	10-Aug-2024				
	2060A-01						Hrs	13,363.9	2,000	+3%	15,363.9	1,843 Hrs (+60)
	2618						Ldg	9,034				
							Flt	9,033				
		Note: P/N 2060A01 or 2060A12										
		(1)										
28-22-05-350-801-03		**Restoration of the Transfer Pump (Replacement of Motor Brushes) - RH Transfer Pump (23Q3)**							RE		Comp Maint Ops (5-20)	**≈14-Mar-2029**
	28 A/F	Right					Mos	30-Sep-2019				
	2060A-01						Hrs	12,978.6	2,000	+3%	14,978.6	1,457.7 Hrs (+60)
	A01986						Ldg	8,785				
							Flt					
		Note: P/N 2060A01 or 2060A12										
		(1)										
28-22-05-350-802-01		**Restoration of the Transfer Pump (Replacement of Bearings) - LH Transfer Pump (23Q1)**							RE		Comp Maint Ops (5-20)	**≈17-Sep-2029**
	28 A/F	Left					Mos	22-Jun-2016				
	2060A-01						Hrs	13,161.4	2,000	+3%	15,161.4	1,640.5 Hrs (+60)
	E46406						Ldg					
							Flt					
		Note: P/N 2060A01 or 2060A12										
		(1)										
		P/N 2060A01 : This periodicity must be reduced to 1200 hours when JP4 is used										
		P/N 2060A12 : only one bearing										
28-22-05-350-802-02		**Restoration of the Transfer Pump (Replacement of Bearings) - Center Transfer Pump (23Q2)**							RE		Comp Maint Ops (5-20)	**≈09-Apr-2030**
	28 A/F	Center					Mos	10-Aug-2024				
	2060A-01						Hrs	13,363.9	2,000	+3%	15,363.9	1,843 Hrs (+60)
	2618						Ldg	9,034				
							Flt	9,033				
		Note: P/N 2060A01 or 2060A12										
		(1)										
		P/N 2060A01 : This periodicity must be reduced to 1200 hours when JP4 is used										
		P/N 2060A12 : only one bearing										
28-22-05-350-802-03		**Restoration of the Transfer Pump (Replacement of Bearings) - RH Transfer Pump (23Q3)**							RE		Comp Maint Ops (5-20)	**≈14-Mar-2029**
	28 A/F	Right					Mos	30-Sep-2019				
	2060A-01						Hrs	12,978.6	2,000	+3%	14,978.6	1,457.7 Hrs (+60)
	A01986						Ldg	8,785				
							Flt					
		Note: P/N 2060A01 or 2060A12										
		(1)										
		P/N 2060A01 : This periodicity must be reduced to 1200 hours when JP4 is used										
		P/N 2060A12 : only one bearing										
28-22-13-220-801-01		**Inspection For Corrosion of the Transfer Valve Bases and Lines Fitted With Drainage Sleeves**							RE		Acft Maint Ops (5-10)	
	28 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
							Hrs	13,276.7				
		(Tol. Adjustment: -225.9d)					Ldg	8,977				
		Note: A/C with SB F50-150					Flt	8,977				
28-22-15-350-801-01		**Restoration of the Transfer Valves (Overhaul) - LH Transfer Valve (L615Qs)**							RE		Comp Maint Ops (5-20)	
	28 A/F	Left					Yrs	20-Oct-2021	9	+3%d	20-Oct-2030	5.6 Years (+98 Days)
	2504-3						Hrs	13,213.1	4,800	+3%	18,013.1	4,492.2 Hrs (+144)
	721						Ldg	8,940				
							Flt					
		Note: P/N 2504-3										
		(1)										

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-22-15-350-801-02		**Restoration of the Transfer Valves (Overhaul) - Center Transfer Valve (M615Qs)**							RE		Comp Maint Ops (5-20)	
28 A/F	2504-3 1712	Center					Yrs	09-Aug-2021	9	+3%d	09-Aug-2030	5.4 Years (+98 Days)
							Hrs	13,195.6	4,800	+3%	17,995.6	4,474.7 Hrs (+144)
							Ldg	8,930				
							Flt					
		Note: P/N 2504-3 (1)										
28-22-15-350-801-03		**Restoration of the Transfer Valves (Overhaul) - RH Transfer Valve (R615Qs)**							RE		Comp Maint Ops (5-20)	
28 A/F	2504-3 1656	Right					Yrs	09-Aug-2021	9	+3%d	09-Aug-2030	5.4 Years (+98 Days)
							Hrs	13,195.6	4,800	+3%	17,995.6	4,474.7 Hrs (+144)
							Ldg	8,930				
							Flt					
		Note: P/N 2504-3 (1)										
28-30-00-680-802-05		**Draining of the Fuel Tanks / Fuel Sampling - Leak Check of the Dry Bay**							RE		Acft Maint Ops (5-10)	
28 A/F							Mos	03-Feb-2025	2	-/+5d	03-Apr-2025	28 Days (+5)
							Hrs	13,496.2				
							Ldg	9,121				
		Note: A/C with SB F50-496					Flt	9,121				
28-30-00-680-804-01		**Draining water from the fuel tanks**							RE		Acft Maint Ops (5-10)	
28 A/F							Mos	03-Feb-2025	2	-/+5d	03-Apr-2025	28 Days (+5)
							Hrs	13,496.2				
							Ldg	9,121				
		Note: More often if necessary					Flt	9,121				
28-30-11-960-802-01		**Discard of the Fuel Drain Caps**							RE (N/A)		Acft Maint Ops (5-10)	
28 A/F							Mos					
							Hrs					
							Ldg					
							Flt					
28-41-00-720-802-01		**Functional Test of the Feeder Tank Low Level Indicating System**							RE		Acft Maint Ops (5-10)	
28 A/F		05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
		(Tol. Adjustment: -83d)					Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
28-43-01-720-801-01		**Functional Test of the Fuel Temperature Sensor - Fuel Temperature Probe (51E)**							RE (N/A)		Acft Maint Ops (5-10)	
28 A/F							Mos					
							Hrs					
							Ldg					
							Flt					
28-50-00-700-801-02		**Integrity and Leak Check of Refueling Connector Sealing Valve and Leak Check of Isolation Check Valves - Tightness Check of Refueling System/Transfer System Isolation Check Valves**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
28 A/F		05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
		Note: A/C without SB F50-144					Flt	8,977				
28-70-00-720-801-01		**Functional Test of the Pressurization System**							RE		Acft Maint Ops (5-10)	**≈21-Apr-2040**
28 A/F		05-10-00-4B					Mos	02-Sep-2016				
							Hrs	12,978.6	6,000	+30	(18,978.6)	5,457.7 Hrs (+30)
							Ldg	8,785				
		Note: during engine run-up					Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
28-70-09-350-801-01	**Restoration of the Valve Boxes (Overhaul) - LH Valve Box (L200Qp)**							RE		Comp Maint Ops (5-20)	
28 A/F	Left					Yrs	09-Aug-2021	6	+3%d	09-Aug-2027	2.4 Years (+65 Days)
2415-1010						Hrs	13,195.6	1,600	+3%	14,795.6	1,274.7 Hrs (+48)
1246						Ldg	8,930				
						Flt					
Note: P/N 2415-1010 (1)											
28-70-09-350-801-02	**Restoration of the Valve Boxes (Overhaul) - RH Valve Box (R200Qp)**							RE		Comp Maint Ops (5-20)	
28 A/F	Right					Yrs	09-Aug-2021	6	+3%d	09-Aug-2027	2.4 Years (+65 Days)
2415-1010						Hrs	13,195.6	1,600	+3%	14,795.6	1,274.7 Hrs (+48)
1727						Ldg	8,930				
						Flt					
Note: P/N 2415-1010 (1)											
28-70-13-720-802-01	**Functional Test of the Wing Tank Negative Pressure Relief Valves - LH Wing Tank Negative Pressure Relief Valve (L100Qp)**							RE		Comp Maint Ops (5-20)	**≈01-May-2026**
28 A/F	Left					Mos	06-Feb-2017				
B06GA1050						Hrs	8,944.2	5,000	+3%	13,944.2	423.3 Hrs (+150)
2695						Ldg					
						Flt					
Note: P/N B06GA1050 or B06GA1051 or B06GA1051-1 or B06GA1052 or B06GA1052-1 (18)											
28-70-13-720-802-02	**Functional Test of the Wing Tank Negative Pressure Relief Valves - RH Wing Tank Negative Pressure Relief Valve (R100Qp)**							RE		Comp Maint Ops (5-20)	**≈21-Apr-2028**
28 A/F	Right					Mos	26-Sep-2003				
Unknown						Hrs	9,656.1	5,000	+3%	14,656.1	1,135.2 Hrs (+150)
Unknown						Ldg					
						Flt					
Note: P/N B06GA1050 or B06GA1051 or B06GA1051-1 or B06GA1052 or B06GA1052-1 (18)											
28-70-17-130-801-01	**Cleaning of Fuel Tank Pressurization Air Filters - Engine 1 Pressurization Air Filter (L206Qp)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
28 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
28-70-17-130-801-02	**Cleaning of Fuel Tank Pressurization Air Filters - Engine 2 Pressurization Air Filter (R206Qp)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
28 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
28-70-41-710-801-01	**Operational Test of the Feeder Tank Pressure Relief Valves - LH Feeder Tank Pressure Relief Valve (L300Qp)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
28 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
28-70-41-710-801-02	**Operational Test of the Feeder Tank Pressure Relief Valves - RH Feeder Tank Pressure Relief Valve (R300Qp)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
28 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
86-14-03	**Refueling Connector-Guide Rod**							RE (-)		Mandatory	
28 A/F						Mos	24-Mar-2021				
Eff: 04-Aug-1986						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
86-14-03 Para. (a)	**Refueling Connector-Guide Rod - perform an inspection of the guide rod in the refueling connector for damage**							RE (-)		Mandatory	
28 A/F						Mos					
						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
86-14-03 Para. (b)	**Refueling Connector-Guide Rod - modify the refueling connector by installing a steel guide rod**							RE (-)		Mandatory	
28 A/F						Mos					
Eff: 04-Aug-1986						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
86-15-02	**Actuators-Crossfeed Valves**							RE (-)		Mandatory	
28 A/F						Mos	24-Mar-2021				
Eff: 28-Jul-1986						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
D200906000007 Rev 2	**Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
28 ENG1						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D200906000007 Rev 2	**Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
28 ENG2						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D200906000007 Rev 2	**Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
28 ENG3						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D201907000030	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG1						Mos					
Eff: 13-Aug-2019						Hrs					
						Enc					
D201907000030	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG2						Mos					
Eff: 13-Aug-2019						Hrs					
						Enc					
D201907000030	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG3						Mos					
Eff: 13-Aug-2019						Hrs					
						Enc					
D201907000030 Rev 1	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG1						Mos					
Eff: 07-May-2020						Hrs					
						Enc					
D201907000030 Rev 1	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG2						Mos					
Eff: 07-May-2020						Hrs					
						Enc					
D201907000030 Rev 1	**Biocide Treatment Process**							T (-)		Service Information Letter	
28 ENG3						Mos					
Eff: 07-May-2020						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D201907000030 Rev 2	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
28 ENG1						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D201907000030 Rev 2	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
28 ENG2						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
D201907000030 Rev 2	**Biocide Treatment Process**							T (A/R)		Service Information Letter	
28 ENG3						Mos					
Eff: 02-Aug-2021						Hrs					
						Enc					
F50-006	**Tank pressurization system - Pick off for pressure and sealing checks**							RE (-)			
28 A/F						Mos					
Eff: 12-Jun-1980						Hrs					
						Ldg					
Note: M0028						Flt					
F50-035	**Fuel gage wirings - Cut-off connectors mounted on the center feeder tank ceiling**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
Note: M0240						Flt					
F50-035 R1	**Fuel gage wirings - Cut-off connectors mounted on the center feeder tank ceiling**							RE (-)			
28 A/F						Mos	22-Jan-1981				
Eff: 04-Apr-1980						Hrs					
						Ldg					
Note: M0240						Flt					
F50-036	**Side engine distributor valves - Reinforced fuel shut-off valve - Control levers**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
Note: M0221						Flt					
F50-036 R1	**Side engine distributor valves - Reinforced fuel shut-off valve - Control levers**							RE (-)			
28 A/F						Mos	22-Jan-1981				
Eff: 04-Apr-1980						Hrs					
						Ldg					
Note: M0221						Flt					
F50-040	**Side engine manifold assembly - Separated supply for the low pressure cross-feed valves**							RE (-)			
28 A/F						Mos	18-Jun-1987				
Eff: 04-Feb-1980 Complied With	by visual inspection					Hrs	4,087.5				
SB:F50-28-004						Ldg	2,821				
						Flt					
F50-058	**Zenith transfer unit - Improved safetying of the control shaft**							RE (-)			
28 A/F						Mos					
Eff: 29-May-1980						Hrs					
						Ldg					
Note: M0309						Flt					
F50-073	**Improved fuel gaging system**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
Note: M0236						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-073 R1	**Improved fuel gaging system**							RE (-)			
28 A/F						Mos					
Eff: 25-Apr-1983						Hrs					
						Ldg					
Note: M0236						Flt					
F50-119	**Fuel - New tee-shaped union on the transfert valve**							RE (-)			
28 A/F						Mos	18-Jun-1987				
Complied With	by visual inspection					Hrs	4,087.5				
SB:F50-28-007						Ldg	2,821				
						Flt					
F50-119 R1	**Fuel - New tee-shaped union on the transfert valve**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
Note: M0821						Flt					
F50-119 R2	**Fuel - New tee-shaped union on the transfert valve**							T (A/R)			
28 A/F						Mos					
Eff: 24-Jan-1986						Hrs					
						Ldg					
Note: M0821						Flt					
F50-120	**Fuel - Transfer system - New float valves in the feeder tanks (Part 120-1 Superseded by SB SB-F50-143) (No longer applicable)**							RE (-)			
28 A/F						Mos	18-Jun-1987				
Eff: 10-Mar-1982 Complied With	by visual inspection					Hrs	4,087.5				
SB:F50-28-008						Ldg	2,821				
						Flt					
F50-128	**Centerwing and feeder tanks - Removable sump drain seals (without tank defueling)**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
Note: M0782, M1116						Flt					
F50-128 R1	**Centerwing and feeder tanks - Removable sump drain seals (without tank defueling)**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
Note: M0782, M1116						Flt					
F50-128 R2	**Centerwing and feeder tanks - Removable sump drain seals (without tank defueling)**							T (A/R)			
28 A/F						Mos					
Eff: 12-Dec-1984						Hrs					
						Ldg					
Note: M0782, M1116						Flt					
F50-136	**Installation of fuel temperature indication system**							T (A/R)			
28 A/F						Mos					
Eff: 05-Jul-1984						Hrs					
						Ldg					
Note: M0941						Flt					
F50-137	**Pressure fueling connector - Stainless steel valve guide stem**							RE (-)			
28 A/F						Mos	09-May-1983				
Complied With						Hrs					
						Ldg					
Note: M1108, AD EASA 83-10-3 (AD FAA 86-14-03)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-137 R1	**Pressure fueling connector - Stainless steel valve guide stem**							RE (-)			
28 A/F						Mos	09-May-1983				
Eff: 09-Feb-1983						Hrs					
						Ldg					
Note: M1108, AD EASA 83-10-3 (AD FAA 86-14-03)						Flt					
F50-143	**Fuel - Improved float valve operation**							RE (-)			
28 A/F						Mos	18-Jun-1987				
Eff: 21-May-1984 Complied With	by visual inspection					Hrs	4,087.5				
SB:F50-28-012						Ldg	2,821				
						Flt					
F50-144	**Pressure fueling connector - Installation of a plug**							T (A/R)			
28 A/F						Mos					
Eff: 14-Feb-1984						Hrs					
						Ldg					
Note: M0314						Flt					
F50-146	**Improved feeder tanks drainage**							T (A/R)			
28 A/F						Mos					
Eff: 24-Apr-1985						Hrs					
						Ldg					
Note: M1117, M1357, M1115						Flt					
F50-150	**Fuel system - Protection of parts in contact with superflexit drain sleeves**							RE (-)			
28 A/F						Mos	18-Jun-1987				
Eff: 26-Jul-1984 Complied With						Hrs	4,087.5				
SB:F50-28-015						Ldg	2,821				
						Flt					
F50-175	**Wing-to-side feeder transfer - Emergency control**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
Note: M1300C						Flt					
F50-175 R1	**Wing-to-side feeder transfer - Emergency control**							T (A/R)			
28 A/F						Mos					
Eff: 30-Oct-1986						Hrs					
						Ldg					
Note: M1300C						Flt					
F50-182	**Booster pump crossfeed valves - Installation of sealed actuators**							RE (-)			
28 A/F						Mos	23-Apr-1986				
Eff: 04-Apr-1986 Complied With						Hrs					
						Ldg					
Note: M1360, AD EASA 86-55-4 (AD FAA 86-15-02)						Flt					
F50-183	**Electrostatic connections - Aircraft / ground fueling equipment**							RE (-)			
28 A/F						Mos					
Eff: 17-Dec-1987						Hrs					
						Ldg					
Note: M1332A, M1332B						Flt					
F50-186	**Fuel - Transfer intercommunication valves - Installation of sealed actuators**							T (A/R)			
28 A/F						Mos					
Eff: 07-May-1987						Hrs					
						Ldg					
Note: M1460						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-190	**Installation of placards defining the refueling instructions if load in baggage compartment exceed 400kg**							T (A/R)			
28 A/F						Mos					
Eff: 16-Apr-1987						Hrs					
						Ldg					
Note: M1372						Flt					
F50-203	**Detection of fuel vapors at frames 29 and 31**							T (A/R)			
28 A/F						Mos					
Eff: 15-Mar-1990						Hrs					
						Ldg					
						Flt					
F50-222	**Tank draining - Introduction of a draining tool with collecting bottle**							T (A/R)			
28 A/F						Mos					
Eff: 13-Sep-1995						Hrs					
						Ldg					
Note: M1383						Flt					
F50-390	**Checking the wing center section tank for leaks**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-390 R1	**Checking the wing center section tank for leaks**							RE (-)			
28 A/F						Mos					
Eff: 30-Oct-2003						Hrs					
						Ldg					
						Flt					
F50-411	**Fuel tank sump drain valves - Elimination of the protective screens**							RE (-)			
28 A/F						Mos					
Eff: 15-Jan-2003						Hrs					
						Ldg					
Note: M2854, 191 to 352 with sump drain valves P/N 142D12-11 or 142G12-43 (M1535)						Flt					
F50-415	**Fuselage lateral feeder tanks - Improved protection against lightning strike**							RE (-)			
28 A/F						Mos	12-Oct-2010				
						Hrs					
						Ldg					
						Flt					
F50-415 R1	**Fuselage lateral feeder tanks - Improved protection against lightning strike**							T (A/R)			
28 A/F						Mos					
Eff: 10-May-2006						Hrs					
						Ldg					
Note: M2492, M2916, AD EASA 2002-595 (AD FAA 2004-04-11), 2 to 322, except A/C incorporating M0673						Flt					
F50-428	**Fuselage lateral feeder tanks - Inspection of lightning strike protection patches**							RE (-)			
28 A/F						Mos					
Eff: 10-Jul-2003						Hrs					
						Ldg					
						Flt					
F50-447	**Fuel - Transfer pump - Installing the new brush less motor pumps**							T (A/R)			
28 A/F						Mos					
Eff: 12-Jul-2005						Hrs					
						Ldg					
Note: M2463, M2956						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-452	**Protecting the EIEDs/gauging amplifiers links against interference**							RE (-)			
28 A/F						Mos					
						Hrs					
						Ldg					
Note: M2613						Flt					
F50-452 R1	**Protecting the EIEDs/gauging amplifiers links against interference**							RE (-)			
28 A/F						Mos					
Eff: 13-Oct-2005						Hrs					
						Ldg					
Note: M2613						Flt					
F50-498	**Installation of low pressure booster pump P/N 226075-51**							RE (-)			
28 A/F						Mos	17-Apr-2011				
Eff: 12-Oct-2009						Hrs					
						Ldg					
Note: M1903						Flt					
F50-547	**Fuel - Draining and Defueling - Capability for New Sump Drain Valves**							RE (-)		Optional	
28 A/F						Mos					
Eff: 28-Aug-2019						Hrs					
(AVG MAN HRS: 3.5)						Ldg					
						Flt					
F50-547-1	**Fuel - Draining and Defueling - Capability for New Sump Drain Valves - Drain Tube Replacement (For Sump LH Feeder Tank Sump Drain Valve (L30QV))**							T (A/R)		Optional	
28 A/F						Mos					
						Hrs					
(AVG MAN HRS: 1)						Ldg					
Note: COMPLIANCE: If you choose to comply with this Service Bulletin, accomplishment is to be performed during the replacement of LH feeder tank sump drain valve (L30QV), and/or, Center feeder tank sump drain valve (M30QV), and/or, RH feeder tank sump drain valve (R30QV), and/or, LH feeder tank door sump drain valve (L20QV), and/or, RH feeder tank door sump drain valve (R20QV).						Flt					
F50-547-2	**Fuel - Draining and Defueling - Capability for New Sump Drain Valves - Drain Tube Replacement (For RH Feeder Tank Sump Drain Valve (R30QV))**							T (A/R)		Optional	
28 A/F						Mos					
						Hrs					
(AVG MAN HRS: 1)						Ldg					
Note: COMPLIANCE: If you choose to comply with this Service Bulletin, accomplishment is to be performed during the replacement of LH feeder tank sump drain valve (L30QV), and/or, Center feeder tank sump drain valve (M30QV), and/or, RH feeder tank sump drain valve (R30QV), and/or, LH feeder tank door sump drain valve (L20QV), and/or, RH feeder tank door sump drain valve (R20QV).						Flt					
F50-547-3	**Fuel - Draining and Defueling - Capability for New Sump Drain Valves - Drain Tube Replacement (For Center Feeder Tank Sump Drain Valve (M30QV))**							T (A/R)		Optional	
28 A/F						Mos					
						Hrs					
(AVG MAN HRS: 0.5)						Ldg					
Note: COMPLIANCE: If you choose to comply with this Service Bulletin, accomplishment is to be performed during the replacement of LH feeder tank sump drain valve (L30QV), and/or, Center feeder tank sump drain valve (M30QV), and/or, RH feeder tank sump drain valve (R30QV), and/or, LH feeder tank door sump drain valve (L20QV), and/or, RH feeder tank door sump drain valve (R20QV).						Flt					
F50-547-4	**Fuel - Draining and Defueling - Capability for New Sump Drain Valves - Drain Tube Replacement (For LH Feeder Tank Door Sump Drain Valve (L20QV))**							RE (-)		Optional	
28 A/F						Mos					
Eff: 28-Aug-2019						Hrs					
(AVG MAN HRS: 0.5)						Ldg					
						Flt					
F50-547-5	**Fuel - Draining and Defueling - Capability for New Sump Drain Valves - Drain Tube Replacement (For RH Feeder Tank Door Sump Drain Valve (R20QV))**							RE (-)		Optional	
28 A/F						Mos					
Eff: 28-Aug-2019						Hrs					
(AVG MAN HRS: 0.5)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-553	**Fuel - Draining and Defueling - Sump Drain Valve Improvement**							T (A/R)		Optional	
28 A/F	Eff: 28-Aug-2019 (AVG MAN HRS: 22) Note: EFFECTIVITY: This Service Bulletin is applicable to aircraft that are equipped with ZODIAC fuel sump drain valves P/N: 142D12-X, 142D12-XX, 142G12-XX.					Mos					
						Hrs					
						Ldg					
						Flt					
▼ 29 - HYDRAULIC POWER											
	Auxiliary Hydraulic System Filter							RE (O/C)			
29 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Auxiliary Maintenance Hydraulic Selector							RE (O/C)			
29 A/F						Mos	24-Mar-2021				
AV23C1101						Hrs					
X72532						Ldg					
						Flt					
	Circuit Dual Indicator Pressure Level							RE (O/C)			
29 A/F	No.1					Mos	23-Jun-2015				
5502-367-80-10						Hrs					
218						Ldg					
						Flt					
	Circuit Dual Indicator Pressure Level							RE (O/C)			
29 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Circuit Pressure Transmitter							RE (O/C)			
29 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Circuit Pressure Transmitter							RE (O/C)			
29 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	HP Hydraulic Filter							RE (O/C)			
29 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	HP Hydraulic Filter							RE (O/C)			
29 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	HP Hydraulic Filter							RE (O/C)			
29 A/F	No.3					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Hyd Tank Pressure Valve							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hyd Tank Pressure Valve							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Electro-Pump -Motor							RE (O/C)			
	29 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Pressurization Check Valve							RE (O/C)			
	29 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Pump							RE (H/T)			
	29 A/F	No.1					Mos	26-Oct-1990				
	PVB-022-2/314470						Hrs					
	MX344266EG						Ldg					
							Flt					
		Hydraulic Pump							RE (H/T)			
	29 A/F	No.2					Mos	12-Oct-2010				
	PV022-2						Hrs					
	MX398624H						Ldg					
							Flt					
		Hydraulic Pump							RE (H/T)			
	29 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Pump Pressure Switch							RE (O/C)			
	29 A/F	No.1					Mos	23-Mar-2012				
	90G229						Hrs					
	2449						Ldg					
							Flt					
		Hydraulic Pump Pressure Switch							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Pump Pressure Switch							RE (O/C)			
	29 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Hydraulic Quantity Transmitter (4D1)							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Quantity Transmitter (4D2)							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Reservoir Air Pressure Reducing Valve							RE (O/C)			
	29 A/F						Mos	24-Mar-2021				
	2407ZR4EQ10						Hrs					
	2434						Ldg					
							Flt					
		Hydraulic Reservoir Pressure Reducer							RE (O/C)			
	29 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Reservoir Pressurization Low Pressure Switch							RE (O/C)			
	29 A/F	No.1					Mos	26-Jan-1981				
	8A1206						Hrs					
	082						Ldg					
							Flt					
		Hydraulic Reservoir Pressurization Low Pressure Switch							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Reservoir System							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Reservoir System							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic System Accumulator							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic System Accumulator							RE (O/C)			
	29 A/F	No.2					Mos	26-Jun-2014				
	60833-1						Hrs					
	223						Ldg					
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Hydraulic System Accumulator Filler Valve							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic System Accumulator Filler Valve							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic System Left Ground Pressure Connection							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic System Left Ground Pressure Connection							RE (O/C)			
	29 A/F	No.2					Mos	26-Apr-2017				
	TB3005S4-8D						Hrs					
	N/A						Ldg					
							Flt					
		Hydraulic System Left Ground Return Connection							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic System Right Ground Return Connection							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic System Standby Pump Pressure Switch							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic System Standby Pump Pressure Switch							RE (O/C)			
	29 A/F	No.2					Mos	27-Jul-2016				
	15H0092PH						Hrs					
	Unknown						Ldg					
							Flt					
		No. 1 Circuit Return Regulation Filter							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		No. 1 Circuit Return Regulation Filter							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 2 Circuit Return Regulation Filter							RE (O/C)			
	29 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Accumulator Filler Valve							RE (O/C)			
	29 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pressure Indicator							RE (O/C)			
	29 A/F	No.1					Mos	04-Apr-2015				
	5502-367-80-10						Hrs					
	243						Ldg					
							Flt					
		Pressure Indicator							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Discharge Quick Disconnect Valve							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Discharge Quick Disconnect Valve							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Discharge Quick Disconnect Valve							RE (O/C)			
	29 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Electro Hydraulic Motor							RE (O/C)			
	29 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Return Check Valve							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Return Check Valve							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Pump Return Check Valve							RE (O/C)			
	29 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Check Valve							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Check Valve							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Check Valve							RE (O/C)			
	29 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Coupler Quick Disconnect Coupling							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Coupler Quick Disconnect Coupling							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Coupler Quick Disconnect Coupling							RE (O/C)			
	29 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Fixed-Half Quick Disconnect Coupling							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Fixed-Half Quick Disconnect Coupling							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pump Suction Fixed-Half Quick Disconnect Coupling							RE (O/C)			
	29 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Standby Electric Pump							RE (O/C)			
	29 A/F						Mos	27-Dec-2007				
	1153-1						Hrs					
	Unknown						Ldg					
							Flt					
		System Electro Pump Distributor Check Valve							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		System Electro Pump Distributor Check Valve							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		System No.1 Pressure Relief Valve							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		System No.2 Pressure Relief Valve							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		System Pressure Relief Valve							RE (O/C)			
	29 A/F	No.2					Mos	19-Apr-2001				
	A2451800-1						Hrs					
	FM971						Ldg					
							Flt					
		System Suction Check Valve Ground Connection							RE (O/C)			
	29 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		System Suction Check Valve Ground Connection							RE (O/C)			
	29 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reverser Accumulator Filler Valve							RE (O/C)			
	29 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
29-00-00-610-802		**Replacement of theHydraulic Fluid After Failure of a Hydraulic Power System Component**							RE (A/R)		Unsch Maint Chk (5-50)	
	29 A/F						Mos					
							Hrs					
	Ref:29-150						Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
29-10-00-720-801-01	**Functional Test of the Main Hydraulic Systems - System 1**							RE		Acft Maint Ops (5-10)	**≈21-Apr-2040**
29 A/F	05-10-00-4B					Mos	02-Sep-2016				
						Hrs	12,978.6	6,000	+30	(18,978.6)	5,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-10-00-720-801-02	**Functional Test of the Main Hydraulic Systems - System 2**							RE		Acft Maint Ops (5-10)	**≈21-Apr-2040**
29 A/F	05-10-00-4B					Mos	02-Sep-2016				
						Hrs	12,978.6	6,000	+30	(18,978.6)	5,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-11-01-350-801-01	**Restoration of the Hydraulic Pumps (Overhaul) - Hydraulic Pump 1 (L500MI)**							RE		Comp Maint Ops (5-20)	**≈28-Jan-2030**
29 A/F	No.1					Mos	07-Feb-2015				
PVB-022-2/314470						Hrs	11,292.2	4,000	+3%	15,292.2	1,771.3 Hrs (+120)
MX344266EG						Ldg					
						Flt					
Note: P/N PV3-022-2 or PVB022-2. NOTE (1)											
29-11-01-350-801-02	**Restoration of the Hydraulic Pumps (Overhaul) - Hydraulic Pump 2 (M500MI)**							RE		Comp Maint Ops (5-20)	**≈31-Jan-2030**
29 A/F	No.2					Mos	12-Oct-2010				
PV022-2						Hrs	11,295	4,000	+3%	15,295	1,774.1 Hrs (+120)
MX398624H						Ldg	7,881				
						Flt					
Note: P/N PV3-022-2 or PVB022-2. NOTE (1)											
29-11-01-350-801-03	**Restoration of the Hydraulic Pumps (Overhaul) - Hydraulic Pump 3 (R500MI)**							RE		Comp Maint Ops (5-20)	**≈03-Mar-2029**
29 A/F	No.3					Mos	24-Jul-2008				
Unknown						Hrs	10,967.2	4,000	+3%	14,967.2	1,446.3 Hrs (+120)
Unknown						Ldg	7,657				
						Flt					
Note: P/N PV3-022-2 or PVB022-2. NOTE (1)											
29-11-21-230-801-01	**Special Detailed Inspection of the Internal Part of the Body of the Pressure Relief Valves - Hydraulic Pump 1 Pressure Relief Valve (L100MI)**							RE (N/A)		Comp Maint Ops (5-20)	
29 A/F	No.1					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
29-11-21-230-801-02	**Special Detailed Inspection of the Internal Part of the Body of the Pressure Relief Valves - Hydraulic Pump 2 Pressure Relief Valve (M100MI)**							RE (N/A)		Comp Maint Ops (5-20)	
29 A/F	No.1					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
29-11-21-230-801-03	**Special Detailed Inspection of the Internal Part of the Body of the Pressure Relief Valves - Hydraulic Pump 3 Pressure Relief Valve (R100MI)**							RE (N/A)		Comp Maint Ops (5-20)	
29 A/F	No.2					Mos					
A2451800-1						Hrs					
FM971						Ldg					
						Flt					
29-11-25-960-801-01	**Discard of the Hydraulic Pump Pressure Switches - Hydraulic Pump 1 Pressure Switch (11D1)**							RE (N/A)		Comp Maint Ops (5-20)	
29 A/F	No.1					Mos					
90G229						Hrs					
2449						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
29-11-25-960-801-02	**Discard of the Hydraulic Pump Pressure Switches - Hydraulic Pump 2 Pressure Switch (11D2)**							RE (N/A)		Comp Maint Ops (5-20)	
29 A/F	No.2					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
29-11-25-960-801-03	**Discard of the Hydraulic Pump Pressure Switches - Hydraulic Pump 3 Pressure Switch (11D3)**							RE (N/A)		Comp Maint Ops (5-20)	
29 A/F	No.3					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
29-13-09-100-801-01	**Replacement of the Hydraulic Pump Filtering Elements - Hydraulic Pump 1 Return Filter (L200MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200		14,178.6	657.7 Hrs
						Ldg	8,785				
						Flt					
29-13-09-100-801-02	**Replacement of the Hydraulic Pump Filtering Elements - Hydraulic Pump 2 Return Filter (M200MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200	+30	14,178.6	657.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-13-09-100-801-03	**Replacement of the Hydraulic Pump Filtering Elements - Hydraulic Pump 3 Return Filter (R200MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200	+30	14,178.6	657.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-13-09-100-801-04	**Replacement of the Hydraulic Pump Filtering Elements - Hydraulic Pump 1 Delivery Filter (L350MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200	+30	14,178.6	657.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-13-09-100-801-05	**Replacement of the Hydraulic Pump Filtering Elements - Hydraulic Pump 2 Delivery Filter (M350MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200	+30	14,178.6	657.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-13-09-100-801-06	**Replacement of the Hydraulic Pump Filtering Elements - Hydraulic Pump 3 Delivery Filter (R350MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200	+30	14,178.6	657.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-13-09-100-801-07	**Replacement of the Hydraulic Pump Filtering Elements - Standby Pump Filter (14MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200	+30	14,178.6	657.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-14-33-960-801-01	**Replacement of the Hydraulic Reservoir Filtering Elements - System 1 Hydraulic Reservoir (L501MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200	+30	14,178.6	657.7 Hrs (+30)
						Ldg	8,785				
						Flt					

Task No / SEQ PN/SN / MOC Note or Component Condition	Description	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
29-14-33-960-801-02	**Replacement of the Hydraulic Reservoir Filtering Elements - System 2 Hydraulic Reservoir (R501MI)**							RE		Acft Maint Ops (5-10)	**≈26-Dec-2026**
29 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200	+30	14,178.6	657.7 Hrs (+30)
						Ldg	8,785				
						Flt					
29-14-33-960-802-01	**Replacement of the Chlorine Retaining Element - System 1 Hydraulic Reservoir (L501ML)**							RE (N/A)		Acft Maint Ops (5-10)	
29 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
29-14-33-960-802-02	**Replacement of the Chlorine Retaining Element - System 2 Hydraulic Reservoir (R501ML)**							RE (N/A)		Acft Maint Ops (5-10)	
29 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
29-15-00-720-801-01	**Functional Test of the Hydraulic Reservoir Pressurization System - Hydraulic System 1**							RE		Acft Maint Ops (5-10)	**≈15-Apr-2034**
29 A/F	05-10-00-4B					Mos	27-Dec-2007				
						Hrs	10,810.7	6,000	+30	16,810.7	3,289.8 Hrs (+30)
						Ldg	7,544				
						Flt					
29-15-00-720-801-02	**Functional Test of the Hydraulic Reservoir Pressurization System - Hydraulic System 2**							RE		Acft Maint Ops (5-10)	**≈15-Apr-2034**
29 A/F	05-10-00-4B					Mos	27-Dec-2007				
						Hrs	10,810.7	6,000	+30	16,810.7	3,289.8 Hrs (+30)
						Ldg	7,544				
						Flt					
29-15-05-100-801-01	**Cleaning of the Hydraulic Reservoir Pressure Reducer Filters - Hydraulic Reservoir Pressure Reducer (10MI)**							RE		Comp Maint Ops (5-20)	
29 A/F						Yrs	27-Apr-2023	4		30-Oct-2026	1.7 Years
2407ZR4EQ10						Hrs					
2434						Ldg					
(Tol. Adjustment: -179d)						Flt					
Note: P/N 2407ZR4EQ10											
No tolerance											
29-15-05-350-801-01	**Restoration of the Hydraulic Reservoir Pressure Reducer (Functional Test and Diaphragm Replacement) - Hydraulic Reservoir Pressure Reducer (10MI)**							RE		Comp Maint Ops (5-20)	
29 A/F						Yrs	24-Mar-2021	6		24-Mar-2027	2 Years
2407ZR4EQ10						Hrs					
2434						Ldg					
						Flt					
Note: P/N 2407ZR4EQ10											
(1) No tolerance											
29-20-00-720-801-01	**Functional Test of the Auxiliary Hydraulic System - Test on Hydraulic System 2**							RE		Acft Maint Ops (5-10)	**≈03-Oct-2027**
29 A/F						Mos	26-Sep-2003				
						Hrs	9,656.1	4,800	+30	14,456.1	935.2 Hrs (+30)
						Ldg	6,824				
						Flt					
29-20-03-220-801-01	**Check of the Standby Electric Pump Motor Brushes - Standby Electric Pump (15M)**							RE		Comp Maint Ops (5-20)	**≈16-Dec-2030**
29 A/F						Mos	27-Dec-2007				
1153-1						Hrs	10,810.1	4,800	+3%	15,610.1	2,089.2 Hrs (+144)
Unknown						Ldg	7,544				
						Flt					
Note: P/N EP1600-10 or EP1600-11 or EP1600-12 or GEP110											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
29-20-07-960-801-01	**Discard of the Standby Pump Pressure Switches - System 1 Standby Pump Pressure Switch (16M1)**							RE (N/A)		Comp Maint Ops (5-20)	
29 A/F	No.1					Mos	29-Aug-2006				
Unknown						Hrs					
Unknown						Ldg					
						Flt					
29-20-07-960-801-02	**Discard of the Standby Pump Pressure Switches - System 2 Standby Pump Pressure Switch (16M2)**							RE (N/A)		Comp Maint Ops (5-20)	
29 A/F	No.2					Mos	27-Jul-2016				
15H0092PH						Hrs					
Unknown						Ldg					
						Flt					
F50-008	**Parking brake accumulator pressure gage - Inspection window added**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M0041						Flt					
F50-008 R1	**Parking brake accumulator pressure gage - Inspection window added**							RE (-)			
29 A/F						Mos					
Eff: 13-Feb-1981						Hrs					
						Ldg					
Note: M0041						Flt					
F50-106	**Hydraulic - Tubing-retaining clamps added in the engine pylons**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M0828						Flt					
F50-106 R1	**Hydraulic - Tubing-retaining clamps added in the engine pylons**							T (A/R)			
29 A/F						Mos					
Eff: 25-Apr-1983						Hrs					
						Ldg					
Note: M0828						Flt					
F50-109	**Hydraulic - Thermal relief valves of new design**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M0840, M0870						Flt					
F50-109 R1	**Hydraulic - Thermal relief valves of new design**							T (A/R)			
29 A/F						Mos					
Eff: 26-Mar-1987						Hrs					
						Ldg					
Note: M0840, M0870						Flt					
F50-114	**Hydraulic - Acid fixing elements in the reservoirs**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M0830						Flt					
F50-114 R1	**Hydraulic - Acid fixing elements in the reservoirs**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M0830						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-114 R2	**Hydraulic - Acid fixing elements in the reservoirs**							T (A/R)			
29 A/F						Mos					
Eff: 13-Dec-1990						Hrs					
						Ldg					
Note: M0830						Flt					
F50-125	**Main hydraulic power - Engine-driven pump 1, 2, 3 pressure switch supply tubings replaced**							RE (-)			
29 A/F						Mos	13-Mar-1986				
Eff: 29-Apr-1983 Complied With						Hrs					
						Ldg					
Note: M0953A						Flt					
F50-129	**Hydraulic - Collecting and draining out fluid spilled while filling the reservoirs**							T (A/R)			
29 A/F						Mos					
Eff: 26-Sep-1984						Hrs					
						Ldg					
Note: M0629						Flt					
F50-151	**Pressure relief valves - Improved spring service life and foolproof feature added**							T (A/R)			
29 A/F						Mos					
Eff: 15-Feb-1984						Hrs					
						Ldg					
Note: M0869						Flt					
F50-215	**New pressure measurement system with piezo-electric transducers**							T (A/R)			
29 A/F						Mos					
Eff: 29-May-1991						Hrs					
						Ldg					
Note: M1320						Flt					
F50-216	**Hydraulic - Engine 2 driven pump pressure switch - Installation of a flexible supply line**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M2779, M1855						Flt					
F50-216 R1	**Hydraulic - Engine 2 driven pump pressure switch - Installation of a flexible supply line**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M2779, M1855						Flt					
F50-216 R2	**Hydraulic - Engine 2 driven pump pressure switch - Installation of a flexible supply line**							T (A/R)			
29 A/F						Mos					
Eff: 01-Oct-2001						Hrs					
						Ldg					
Note: M2779, M1855						Flt					
F50-250	**Hydraulic power - Main hydraulic power No 1 and No 3 engine driven pump pressure switches - Installation of flexible supply lines**							T (A/R)			
29 A/F						Mos					
Eff: 29-Mar-1996						Hrs					
						Ldg					
Note: M1886						Flt					
F50-311	**Delaying of hydr#1 pump 1, hydr#1 pump 2 warnings and reduction of landing gear extension time**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M2401						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-311 R1	**Delaying of hydr#1 pump 1, hydr#1 pump 2 warnings and reduction of landing gear extension time**							RE (-)			
29 A/F						Mos					
						Hrs					
						Ldg					
Note: M2401						Flt					
F50-311 R2	**Delaying of hydr#1 pump 1, hydr#1 pump 2 warnings and reduction of landing gear extension time**							T (A/R)			
29 A/F						Mos					
Eff: 13-Feb-2002						Hrs					
						Ldg					
Note: M2401						Flt					
F50-355-Alert	**Inspection of hydraulic lines**							RE (-)			
29 A/F						Mos	26-Aug-2005				
Eff: 21-Apr-2000						Hrs	10,112.3				
						Ldg	7,133				
Note: AD EASA 2000-191-031						Flt					
F50-370 R1-Alert	**Piping in engine pylons - linspection and clamping**							RE (-)			
29 A/F						Mos	03-Jul-2003				
Eff: 27-May-2003 Complied With						Hrs					
						Ldg					
Note: AD EASA 2003-190 (AD FAA 2003-10-04)						Flt					
F50-370-Alert	**Piping in engine pylons - linspection and clamping**							RE (-)			
29 A/F						Mos	03-Jul-2003				
						Hrs					
						Ldg					
Note: AD EASA 2003-190 (AD FAA 2003-10-04)						Flt					
F50-436	**Improvement of access to throttle control**							T (A/R)			
29 A/F						Mos					
Eff: 19-Feb-2004						Hrs					
						Ldg					
Note: M2906						Flt					
F50-440	**Airbrakes, nose wheel steering system and braking system - Check of solenoid selector valves**							T (A/R)			
29 A/F						Mos					
Eff: 17-Mar-2004						Hrs					
						Ldg					
						Flt					
F50-472-Alert	**Hydraulic hose/air tube interference**							RE (-)			
29 A/F						Mos					
Eff: 26-Aug-2005						Hrs					
						Ldg					
Note: 2 to 252 with SB F50-216 and 253 to 342						Flt					
F50-473	**Clamping a hydraulic hose in the servicing compartment to prevent interference witht the APU air tube**							RE (-)			
29 A/F						Mos	17-Apr-2011				
Eff: 14-Dec-2005 Complied With						Hrs					
						Ldg					
Note: M3006, 2 to 252 with SB F50-216 R2 (M1617 or M1885) and with a GARRETT APU (SB F50-002 or M0378) and 253 to 342						Flt					
F50-493	**Replacing Hydraulic Pressure Relief Valve P/N A24518001**							T (A/R)			
29 A/F						Mos					
Eff: 11-Oct-2007						Hrs					
						Ldg					
Note: A/C with pressure relief valves P/N A24518001 with listed in the SB						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 30 - ICE AND RAIN PROTECTION											
	Airframe Emergency Anti-Icing Valve							RE (O/C)			
30 A/F						Mos	20-Feb-2004				
1263-00-12						Hrs					
Unknown						Ldg					
						Flt					
	Airframe Normal Anti-Icing Valve							RE (O/C)			
30 A/F						Mos	20-Feb-2004				
1263-00-12						Hrs					
Unknown						Ldg					
						Flt					
	De-Mist Circuit Resistor							RE (O/C)			
30 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	De-Mist Circuit Speed Selector							RE (O/C)			
30 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	De-Mist Circuit Thermal Fuse							RE (O/C)			
30 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	De-Mist Circuit Thermostat							RE (O/C)			
30 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Dessicant Bottle							RE (O/C)			
30 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Dessicant Bottle							RE (O/C)			
30 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine "S" Duct Anti-Icing Valve							RE (O/C)			
30 A/F	No.2					Mos	22-Jan-1981				
3137-100						Hrs					
29						Ldg					
						Flt					
	Engine Air Intake Anti-Icing Pressure Switch							RE (O/C)			
30 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Air Intake Anti-Icing Pressure Switch							RE (O/C)			
	30 A/F	No.2					Mos	05-Nov-2024				
	8G1199-1	Serviceable					Hrs	13,427.3				
	956						Ldg	9,074				
							Flt	9,074				
		Engine Air Intake Anti-Icing Pressure Switch							RE (O/C)			
	30 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Air Intake Anti-Icing Valve							RE (O/C)			
	30 A/F	No.1					Mos	12-Oct-2010				
	1159-00-9						Hrs					
	Unknown						Ldg					
							Flt					
		Engine Air Intake Anti-Icing Valve							RE (O/C)			
	30 A/F	No.2					Mos	31-Jul-2014				
	1780-00-1						Hrs					
	Unknown						Ldg					
							Flt					
		Engine Air Intake Anti-Icing Valve							RE (O/C)			
	30 A/F	No.3					Mos	10-Mar-2006				
	1780-00-1						Hrs	10,231.8				
	Unknown						Ldg	7,027				
							Flt					
		Front Windshield Heater Regulator							RE (O/C)			
	30 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Front Windshield Heater Regulator							RE (O/C)			
	30 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Outside Air Temperature Probe							RE (O/C)			
	30 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pitot Heat Indicator Printed Circuit Board							RE (O/C)			
	30 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pitot Heat Indicator Printed Circuit Board							RE (O/C)			
	30 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		S-Duct Anti-Icing Pressure Switch							RE (O/C)			
30 A/F	8G1199-1 545	Serviceable					Mos	05-Nov-2024				
							Hrs	13,427.3				
							Ldg	9,074				
							Flt	9,074				
		Side Windshield Heater Regulator							RE (O/C)			
30 A/F	Unknown Unknown	Copilot					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Side Windshield Heater Regulator							RE (O/C)			
30 A/F	Unknown Unknown	Pilot					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Slat Telescopic Duct							RE (O/C)			
30 A/F	5041-200 339	Left Inboard					Mos	04-Apr-2015				
							Hrs					
							Ldg					
							Flt					
		Slat Telescopic Duct							RE (O/C)			
30 A/F	5040-200 430	Left Outboard					Mos	04-Apr-2015				
							Hrs					
							Ldg					
							Flt					
		Slat Telescopic Duct							RE (O/C)			
30 A/F	5041-300 024	Right Inboard					Mos	04-Apr-2015				
							Hrs					
							Ldg					
							Flt					
		Slat Telescopic Duct							RE (O/C)			
30 A/F	5040-100 520	Right Outboard					Mos	14-Sep-2023				
		Serviceable					Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
		Windshield De-Mist Blower							RE (O/C)			
30 A/F	Unknown Unknown						Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Windshield Flexible Drive							RE (O/C)			
30 A/F	Unknown Unknown	Copilot					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Windshield Flexible Drive							RE (O/C)			
30 A/F	Unknown Unknown	Pilot					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Windshield Wiper Arm							RE (O/C)			
	30 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Windshield Wiper Arm							RE (O/C)			
	30 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Windshield Wiper Converter							RE (O/C)			
	30 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Windshield Wiper Converter							RE (O/C)			
	30 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Windshield Wiper Motor (3M1)							RE (O/C)			
	30 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Windshield Wiper Motor (3M2)							RE (O/C)			
	30 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Anti Icing System -Probe Temperature							RE (O/C)			
	30 A/F	No.1					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		Wing Anti Icing System -Probe Temperature							RE (O/C)			
	30 A/F	No.3					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		Wing Anti-Icing Pressure Switch							RE (O/C)			
	30 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Anti-Icing Pressure Switch							RE (O/C)			
	30 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Wiper Parking Position Resistor							RE (O/C)			
30 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
30-11-00-350-801-01	**Restoration of the Slat Telescopic Ducts (Overhaul) - LH Inboard Slat Telescopic Duct (L537H1)**							RE (N/A)		Comp Maint Ops (5-20)	
30 A/F	Left Inboard					Mos					
5041-200						Hrs					
339						Ldg					
						Flt					
30-11-00-350-801-02	**Restoration of the Slat Telescopic Ducts (Overhaul) - RH Inboard Slat Telescopic Duct (R537H1)**							RE (N/A)		Comp Maint Ops (5-20)	
30 A/F	Right Inboard					Mos					
5041-300						Hrs					
024						Ldg					
						Flt					
30-11-00-350-801-03	**Restoration of the Slat Telescopic Ducts (Overhaul) - LH Outboard Slat Telescopic Duct (L537H2)**							RE (N/A)		Comp Maint Ops (5-20)	
30 A/F	Left Outboard					Mos					
5040-200						Hrs					
430						Ldg					
						Flt					
30-11-00-350-801-04	**Restoration of the Slat Telescopic Ducts (Overhaul) - RH Outboard Slat Telescopic Duct (R537H2)**							RE (N/A)		Comp Maint Ops (5-20)	
30 A/F	Right Outboard					Mos					
5040-100						Hrs					
520						Ldg					
						Flt					
30-11-00-720-801-01	**Functional Test of the Slat Telescopic Ducts - LH Inboard Slat Telescopic Duct (L537H1)**							RE		Comp Maint Ops (5-20)	**≈01-Jul-2027**
30 A/F	Left Inboard					Mos	14-Sep-2023				
5041-200						Hrs	13,276.7	1,250	+3%	14,526.7	1,005.8 Hrs (+37.5)
339						Ldg	8,977				
						Flt	8,977	1,000	+3%	9,977	844 Flt (+30)
Note: P/N 5041-000 or 5041-200 (8)											
30-11-00-720-801-02	**Functional Test of the Slat Telescopic Ducts - RH Inboard Slat Telescopic Duct (R537H1)**							RE		Comp Maint Ops (5-20)	**≈01-Jul-2027**
30 A/F	Right Inboard					Mos	14-Sep-2023				
5041-300						Hrs	13,276.7	1,250	+3%	14,526.7	1,005.8 Hrs (+37.5)
024						Ldg	8,977				
						Flt	8,977	1,000	+3%	9,977	844 Flt (+30)
Note: P/N 5041-100 or 5041-300 (8)											
30-11-00-720-801-03	**Functional Test of the Slat Telescopic Ducts - LH Outboard Slat Telescopic Duct (L537H2)**							RE		Comp Maint Ops (5-20)	**≈01-Jul-2027**
30 A/F	Left Outboard					Mos	14-Sep-2023				
5040-200						Hrs	13,276.7	1,250	+3%	14,526.7	1,005.8 Hrs (+37.5)
430						Ldg	8,977				
						Flt	8,977	1,000	+3%	9,977	844 Flt (+30)
Note: P/N 5040-000 or 5040-200 (8)											
30-11-00-720-801-04	**Functional Test of the Slat Telescopic Ducts - RH Outboard Slat Telescopic Duct (R537H2)**							RE		Comp Maint Ops (5-20)	**≈01-Jul-2027**
30 A/F	Right Outboard					Mos	14-Sep-2023				
5040-100						Hrs	13,276.7	1,250	+3%	14,526.7	1,005.8 Hrs (+37.5)
520						Ldg	8,977				
						Flt	8,977	1,000	+3%	9,977	844 Flt (+30)
Note: P/N 5017-100 or 5017-700											

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
30-12-01-720-801-01	**Functional Test of the Wing Anti-Icing Valves - Wing Anti-Icing Valve (113H)**							RE		Comp Maint Ops (5-20)	**≈04-Dec-2025**
30 A/F						Mos	20-Feb-2004				
1263-00-12						Hrs	9,797.4	4,000		13,797.4	276.5 Hrs
Unknown						Ldg	6,910				
						Flt					
	Note: P/N 1263-00-1 or 1263-00-12										
	(1)										
	No tolerance										
	A/C without SB F50-225										
30-12-01-720-801-02	**Functional Test of the Wing Anti-Icing Valves - Wing Stand-By Anti-Icing Valve (97H)**							RE		Comp Maint Ops (5-20)	**≈04-Dec-2025**
30 A/F						Mos	20-Feb-2004				
1263-00-12						Hrs	9,797.4	4,000		13,797.4	276.5 Hrs
Unknown						Ldg	6,910				
						Flt					
	Note: P/N 1263-00-1 or 1263-00-12										
	(1)										
	No tolerance										
	A/C without SB F50-225										
30-20-01-700-801-01	**Functional Test of the Engine Air Intake Anti-Icing Valves - Engine 1 Air Intake Anti-Icing Valve (L103H)**							RE		Comp Maint Ops (5-20)	**≈31-Jan-2030**
30 A/F	No.1					Mos	12-Oct-2010				
1159-00-9						Hrs	11,295	4,000		15,295	1,774.1 Hrs
Unknown						Ldg	7,881				
						Flt					
	Note: P/N 1159-00-9C or 1780-00-1										
	(1)										
	No tolerance										
30-20-01-700-801-02	**Functional Test of the Engine Air Intake Anti-Icing Valves - Engine 2 Air Intake Anti-Icing Valve (M103H)**							RE		Comp Maint Ops (5-20)	**≈11-Jun-2031**
30 A/F	No.2					Mos	31-Jul-2014				
1780-00-1						Hrs	11,785.6	4,000		15,785.6	2,264.7 Hrs
Unknown						Ldg	8,159				
						Flt					
	Note: P/N 1159-00-9C or 1780-00-1										
	(1)										
	No tolerance										
30-20-01-700-801-03	**Functional Test of the Engine Air Intake Anti-Icing Valves - Engine 3 Air Intake Anti-Icing Valve (R103H)**							RE		Comp Maint Ops (5-20)	**≈17-Feb-2027**
30 A/F	No.3					Mos	10-Mar-2006				
1780-00-1						Hrs	10,231.8	4,000		14,231.8	710.9 Hrs
Unknown						Ldg	7,027				
						Flt					
	Note: P/N 1159-00-9C or 1780-00-1										
	(1)										
	No tolerance										
30-30-00-710-801-01	**Operational Test of the Air Data Probe Anti-Icing System**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
30 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
30-41-00-710-801-01	**Operational Test of the Windshield De-Icing System**							RE		Acft Maint Ops (5-10)	**≈21-Apr-2040**
30 A/F	05-10-00-4B					Mos	02-Sep-2016				
						Hrs	12,978.6	6,000	+30	(18,978.6)	5,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
30-42-00-200-801-01	**Inspection of the Desiccant of Cockpit Aft Side Window Demisting - LH Rear Window (146H1)**							RE (N/A)		Acft Maint Ops (5-10)	
30 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
30-42-00-200-801-02	**Inspection of the Desiccant of Cockpit Aft Side Window Demisting - RH Rear Window (146H2)**							RE (N/A)		Acft Maint Ops (5-10)	
30 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
30-43-09-220-801-01	**Check of the Windshield Wiper Motor Brushes - LH Windshield Wiper Motor (3M1)**							RE		Comp Maint Ops (5-20)	**≈27-Aug-2060**
30 A/F	Pilot					Mos	28-Dec-2010				
Unknown						Hrs	11,309.5	15,000		26,309.5	12,788.6 Hrs
Unknown						Ldg	7,893				
(SOURCE: Falcon 50/50EX MPD)						Flt					
30-43-09-220-801-02	**Check of the Windshield Wiper Motor Brushes - RH Windshield Wiper Motor (3M2)**							RE		Comp Maint Ops (5-20)	**≈27-Aug-2060**
30 A/F	Copilot					Mos	28-Dec-2010				
Unknown						Hrs	11,309.5	15,000		26,309.5	12,788.6 Hrs
Unknown						Ldg	7,893				
(SOURCE: Falcon 50/50EX MPD)						Flt					
30-60-01-720-801-01	**Functional Test of the S-Duct Anti-Icing Valve - S-Duct Anti-Icing Valve (104H)**							RE		Comp Maint Ops (5-20)	**≈11-Jun-2031**
30 A/F	No.2					Mos	31-Jul-2014				
3137-100						Hrs	11,785.6	4,000		15,785.6	2,264.7 Hrs
29						Ldg	8,159				
						Flt					
Note: P/N 27441520 or 3137-100											
(1)											
No tolerance											
97-21-16	**AFM - Icing Conditions**							RE (-)		Mandatory	
30 A/F						Mos	24-Mar-2021				
Eff: 18-Nov-1997						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
F50-001	**Electrically desmited pilot's rear window**							RE (-)			
30 A/F						Mos					
						Hrs					
						Ldg					
Note: M0025						Flt					
F50-001 R1	**Electrically desmited pilot's rear window**							T (A/R)			
30 A/F						Mos					
Eff: 08-Sep-1982						Hrs					
						Ldg					
Note: M0025						Flt					
F50-004	**Engine 2 S-Duct air intake anti-ice - Cut off connector for ground tests**							RE (-)			
30 A/F						Mos					
Eff: 08-Feb-1980						Hrs					
						Ldg					
Note: M0020						Flt					
F50-063	**new wing anti-icing solenoid valves**							RE (-)			
30 A/F						Mos	22-Jan-1981				
Eff: 07-Mar-1980						Hrs					
						Ldg					
Note: M0389, A/C equipped with anti-icing solenoid valves (DUKES P/N 1263-00-1, 1 - 76 without amendment letter A)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-069	**Engine S-duct anti-icing "Sundstrand" valve replaced by "Le bozec et gautier" valve**							RE (-)			
30 A/F						Mos					
Eff: 29-Oct-1980						Hrs					
						Ldg					
Note: M0051						Flt					
F50-074	**New ALCO controls windshield wipers**							RE (-)			
30 A/F						Mos					
Eff: 25-Feb-1983						Hrs					
						Ldg					
Note: M0081						Flt					
F50-088	**Outboard slat anti-icing - Strengthened telescopic tube upper shutter ramp**							RE (-)			
30 A/F						Mos					
						Hrs					
						Ldg					
Note: M0641						Flt					
F50-088 R1	**Outboard slat anti-icing - Strengthened telescopic tube upper shutter ramp**							T (A/R)			
30 A/F						Mos					
Eff: 28-Aug-1981						Hrs					
						Ldg					
Note: M0641						Flt					
F50-093	**Wing anti-icing - General connectors union added**							T (A/R)			
30 A/F						Mos					
Eff: 30-Mar-1983						Hrs					
						Ldg					
Note: M0336						Flt					
F50-121	**New location for the windshield ice detection light**							T (A/R)			
30 A/F						Mos					
Eff: 28-Sep-1983						Hrs					
						Ldg					
Note: M0198						Flt					
F50-138	**Wing anti-icing solenoid valves - Improved opening response time**							T (A/R)			
30 A/F						Mos					
Eff: 25-Apr-1983						Hrs					
						Ldg					
Note: M1056						Flt					
F50-155	**Improved drainage of fin stub and of S-duct ventilation louvers (On hold)**							T (A/R)			
30 A/F						Mos					
Eff: 31-Oct-1984						Hrs					
						Ldg					
Note: M1164, M1174						Flt					
F50-156	**Nose wheel well - Installation of deflectors on the nose cone ventilation ports**							T (A/R)			
30 A/F						Mos					
Eff: 06-Feb-1985						Hrs					
						Ldg					
Note: M1181						Flt					
F50-204	**Sealing between the oblique frame and S-duct**							T (A/R)			
30 A/F						Mos					
Eff: 04-Oct-1989						Hrs					
						Ldg					
Note: M1564						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-225	**Modified wing anti-icing system for ground operation detection**							T (A/R)			
30 A/F						Mos					
Eff: 18-Jan-1995						Hrs					
						Ldg					
Note: M1844						Flt					
F50-251	**Aft compartment - Improvement of water leak draining**							RE (-)			
30 A/F						Mos					
						Hrs					
						Ldg					
Note: M2008A, M2008B						Flt					
F50-251 R1	**Aft compartment - Improvement of water leak draining**							T (A/R)			
30 A/F						Mos					
Eff: 18-Dec-1998						Hrs					
						Ldg					
Note: M2008A, M2008B						Flt					
F50-266	**Protection on GCU and main electrical box area - Installation of an "umbrella" shield**							RE (-)			
30 A/F						Mos					
						Hrs					
						Ldg					
Note: M2413						Flt					
F50-266 R1	**Protection on GCU and main electrical box area - Installation of an "umbrella" shield**							T (A/R)			
30 A/F						Mos					
Eff: 06-Nov-2002						Hrs					
						Ldg					
Note: M2413						Flt					
F50-284	**Ice and rain protection - Improved drainage for N° 2 engine S-duct ventilation louvers and fin stub**							RE (-)			
30 A/F						Mos					
						Hrs					
						Ldg					
Note: M1174, M2248						Flt					
F50-284 R1	**Ice and rain protection - Improved drainage for N° 2 engine S-duct ventilation louvers and fin stub**							RE (-)			
30 A/F						Mos					
						Hrs					
						Ldg					
Note: M1174, M2248						Flt					
F50-284 R2	**Ice and rain protection - Improved drainage for N° 2 engine S-duct ventilation louvers and fin stub**							T (A/R)			
30 A/F						Mos					
Eff: 13-Apr-2006						Hrs					
						Ldg					
Note: M1174, M2248						Flt					
F50-412	**Cockpit rear window glass panel demist - Simplifying maintenance operations**							RE (-)			
30 A/F						Mos	26-Sep-2014				
Eff: 13-Mar-2003 Complied With						Hrs					
						Ldg					
						Flt					
F50-446	**Wing anti-icing system modified to detect on-ground operation**							RE (-)			
30 A/F						Mos					
						Hrs					
						Ldg					
Note: M2922, 251, 253 to 315 and A/C with SB F50-280. Note: some A/C have modified their ground operation detection system as per F50-225						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-446 R1	**Wing anti-icing system modified to detect on-ground operation**							RE (-)			
30 A/F						Mos					
Eff: 19-Jan-2010						Hrs					
						Ldg					
Note: M2922, 251, 253 to 315 and A/C with SB F50-280. Note: some A/C have modified their ground operation detection system as per F50-225						Flt					
F50-504	**Wing anti-icing - Pressure transmitter (510H) relocation**							RE (-)			
30 A/F						Mos					
Eff: 15-Mar-2010						Hrs					
						Ldg					
Note: M3137, 251, 253 to 352 and A/C with SB F50-280						Flt					
F50-555	**Ice and Rain Protection - Windshield De-Icing System - Windshield Power Control Improvement**							RE (-)		Service Bulletin	
30 A/F						Mos					
Eff: 15-Nov-2023						Hrs					
						Ldg					
						Flt					
F50-555-R1	**Ice and Rain Protection - Windshield De-Icing System - Windshield Power Control Improvement**							T (A/R)		Service Bulletin	
30 A/F						Mos					
Eff: 30-May-2024						Hrs					
MOD:M3342						Ldg					
						Flt					
▼ 31 - INDICATING / RECORDING SYSTEM											
	Cockpit Voice Recorder (CVR)							RE (O/C)			
31 A/F						Mos	29-Sep-2023				
1606-00-00	New	0				Hrs	13,277.7				
3208		0				Ldg	8,978				
		0				Flt	8,978				
	Davtron Clock							RE (O/C)			
31 A/F	Copilot					Mos	29-Sep-2023				
6420093-5	New	0				Hrs	13,277.7				
C23-12910		0				Ldg	8,978				
		0				Flt	8,978				
	Davtron Clock							RE (O/C)			
31 A/F	Pilot					Mos	29-Sep-2023				
6420093-5	New	0				Hrs	13,277.7				
C23-12909		0				Ldg	8,978				
		0				Flt	8,978				
	Audio Warning Unit							RE (O/C)			
31 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Clock							RE (O/C)			
31 A/F	Copilot					Mos	29-Sep-2023				
Not Installed						Hrs	13,277.7				
Not Installed						Ldg	8,978				
						Flt	8,978				
	Clock							RE (O/C)			
31 A/F	Pilot					Mos	29-Sep-2023				
Not Installed						Hrs	13,277.7				
Not Installed						Ldg	8,978				
						Flt	8,978				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Clock Battery							RE (H/T)			
	31 A/F	Copilot					Mos	29-Sep-2023				
	Not Installed						Hrs	13,277.7				
	Not Installed						Ldg	8,978				
							Flt	8,978				
		Clock Battery							RE (H/T)			
	31 A/F	Pilot					Mos	29-Sep-2023				
	Not Installed						Hrs	13,277.7				
	Not Installed						Ldg	8,978				
							Flt	8,978				
		Cockpit Voice Recorder (CVR)							RE (O/C)			
	31 A/F						Mos	29-Sep-2023				
	Not Installed						Hrs	13,277.7				
	Not Installed						Ldg	8,978				
							Flt	8,978				
		Cockpit Voice Recorder (CVR) Underwater Locator Beacon							RE (O/C)			
	31 A/F						Mos	29-Sep-2023				
	Not Installed						Hrs	13,277.7				
	Not Installed						Ldg	8,978				
							Flt	8,978				
		Cockpit Voice Recorder Acceleration Contact							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Cockpit Voice Recorder Control							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		CVR Microphone							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		EGPWS Computer							RE (O/C)			
	31 A/F						Mos	18-Apr-2005				
	965-1199-005						Hrs					
	24758						Ldg					
							Flt					
		Flight Data Recorder (FDR)							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Data Recorder (FDR) Underwater Locator Beacon							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Flight Data Recorder Acceleration Contact							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Data Recorder Accelerometer							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Data Recorder Control							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Data Recorder Sensor Box							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		GPWS Air Data Computer							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		GPWS Computer							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Ground Proximity Warning System Computer							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Quick Access (QAR) Recorder							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Take Off Warning Printed Card							RE (O/C)			
	31 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2002-20-09		**Rockwell Collins - AFD-3010 Adaptive Flight Display Units**							T (A/R)		Mandatory (Appliance AD)	
	31 A/F						Mos	11-Sep-2003				
	Eff: 12-Nov-2002 Not Applicable						Hrs					
	Brand A:9990-2002-20-09 (ISSUING AUTHORITY: FAA)						Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
31-21-05-960-801-01	**Replacement of the Pilot Clock Batteries - LH Pilot Clock (93D) Battery**							RE (N/A)		Comp Maint Ops (5-20)	
31 A/F	Pilot					Mos	29-Sep-2023				
Not Installed						Hrs	13,277.7				
Not Installed						Ldg	8,978				
						Flt	8,978				
31-21-05-960-801-02	**Replacement of the Pilot Clock Batteries - RH Pilot Clock (103D) Battery**							RE (N/A)		Comp Maint Ops (5-20)	
31 A/F	Copilot					Mos	29-Sep-2023				
Not Installed						Hrs	13,277.7				
Not Installed						Ldg	8,978				
						Flt	8,978				
31-31-00-710-802-01	**Operational Test of the Flight Data Recorder (FDR) System**							RE (N/A)		Acft Maint Ops (5-10)	
31 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C not equipped						Flt					
31-31-00-720-803-01	**Functional Test of the 32-Parameter FDR - FDR (2FZ)**							RE (N/A)		Acft Maint Ops (5-10)	
31 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C not equipped						Flt					
31-31-00-970-801-01	**Download of the Flight Data Recorder (FDR) - FDR (2FZ) / FDR (130FZ)**							RE (N/A)		Acft Maint Ops (5-10)	
31 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C not equipped						Flt					
31-31-09-710-801-01	**Operational Test of the FDR/CVR Acceleration Contacts - Acceleration Contact (4RK)**							RE		Comp Maint Ops (5-20)	
31 A/F						Yrs	12-May-2010	20	+3%d	12-May-2030	5.2 Years (+219 Days)
Unknown						Hrs	11,245				
Unknown						Ldg	7,850				
Note: P/N 400-10B or 400-10W						Flt					
31-31-50-710-801-01	**Operational Test of the Cockpit Voice Recorder (CVR) System - CVR (2RK)**							RE		Acft Maint Ops (5-10)	
31 A/F	05-10-00-36M					Mos	14-Sep-2023	36	+1m	(03-Sep-2025)	6 Months (+30 Days)
(Tol. Adjustment: -345d)						Hrs	13,276.7				
Note: if A/C equipped						Ldg	8,977				
Refer to country of registration						Flt	8,977				
31-31-50-970-801-01	**Download of the Cockpit Voice Recorder (CVR) - CVR (10FZ)**							RE (A/R)		Acft Maint Ops (5-10)	
31 A/F						Mos					
						Hrs					
						Ldg					
Note: If A/C equipped. No Longer Scheduled.						Flt					
31-52-00-710-801-01	**Operational Test Of The Warning Panel Dual Power Supply - Warning Panel (32W)**							RE		Acft Maint Ops (5-10)	**≈07-Aug-2030**
31 A/F						Mos	31-Oct-2018				
						Hrs	13,081.5	2,400	+30	15,481.5	1,960.6 Hrs (+30)
						Ldg	8,840				
						Flt					
31-54-00-720-802-01	**Functional Test of the Take-Off Safeties: Logic Test - Alarm Test**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
31 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
31-54-00-720-802-02	**Functional Test of the Take-Off Safeties: Logic Test - Test of Indication Logic**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
31 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
31-55-00-720-801-01	**Functional Test of the Landing Safeties**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
31 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
31-60-00-710-801-01	**Operational Test of the Engine Indicator Electronic Display (EIED)**							RE (N/A)		Acft Maint Ops (5-10)	
31 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C with TFE 731-40 ENGINES						Flt					
31-60-00-710-801-01 (5-40)	**Operational Test of the Engine Indicator Electronic Display (EIED)**							RE (N/A)		AWL (5-40), CMR	
31 A/F						Mos					
						Hrs					
Ref:31-070						Ldg					
						Flt					
F50-096	**Recording of TR position, radio-altimeter height, three marker beacons, A.P engaged during approach, and ILS deviation**							RE (-)			
31 A/F						Mos					
						Hrs					
						Ldg					
Note: M0398, M0915B, M0771, A/C with a magnetic flight recorder (option No. 31-30-01)						Flt					
F50-096 R1	**Recording of TR position, radio-altimeter height, three marker beacons, A.P engaged during approach, and ILS deviation**							T (A/R)			
31 A/F						Mos					
Eff: 07-Feb-1996						Hrs					
						Ldg					
Note: M0398, M0915B, M0771, A/C with a magnetic flight recorder (option No. 31-30-01)						Flt					
F50-240	**Instruments - Warning panel - Evolution of T/O configuration light definition**							RE (-)			
31 A/F						Mos					
						Hrs					
						Ldg					
Note: M1850, AD EASA 98-300-022 (AD FAA 2001-01-05)						Flt					
F50-240 R1	**Instruments - Warning panel - Evolution of T/O configuration light definition**							RE (-)			
31 A/F						Mos	05-Dec-1998				
Eff: 07-Oct-1998						Hrs					
						Ldg					
Note: M1850, AD EASA 98-300-022 (AD FAA 2001-01-05)						Flt					
F50-297	**Installation of an EGPWS (Enhanced Ground Proximity Warning System)(P/N 965-0976-040-212 MOD 2-212)**							RE (-)			
31 A/F						Mos					
						Hrs					
						Ldg					
Note: M2580, M2054, M2581, M2, 251 to 269, 271 to 272 with COLLINS V5.X avionics (M1965A or M1965B)						Flt					
F50-297 R1	**Installation of an EGPWS (Enhanced Ground Proximity Warning System)(P/N 965-0976-040-212 MOD 2-212)**							RE (-)			
31 A/F						Mos					
Eff: 09-Jul-2004						Hrs					
						Ldg					
Note: M2580, M2054, M2581, M2, 251 to 269, 271 to 272 with COLLINS V5.X avionics (M1965A or M1965B)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-323	**New EGPWS computer (P/N 965-0976-040-208-208) for version 5.1 or version 6.0 Collins Avionics Equipment**							T (A/R)			
31 A/F						Mos					
Eff: 09-Dec-1999						Hrs					
						Ldg					
Note: M2611, M2580, A/C with an ALLIED SIGNAL EGPWS P/N 965-0976-040-105-105 (M2390 and M2391) or P/N 965-0976-040-202-202 (M2393)						Flt					
F50-340	**"T/O CONFIG" warning light - Improvement of brake configuration warning**							RE (-)			
31 A/F						Mos					
						Hrs					
						Ldg					
Note: M2669						Flt					
F50-340 R1	**"T/O CONFIG" warning light - Improvement of brake configuration warning**							T (A/R)			
31 A/F						Mos					
Eff: 17-Jun-2003						Hrs					
						Ldg					
Note: M2669						Flt					
F50-351	**New EGPWS computer (P/N 965-0976-040-212-212) for Collins Avionics version 5.X or 6.X**							RE (-)			
31 A/F						Mos					
						Hrs					
						Ldg					
Note: M2581, M2586, M2585, A/C with Avionics V6.X + EGPWS P/N 965-0976-040-202-202 or -208 -208 and A/C with Avionics V5.X + EGPWS P/N 965-0976-040-105-105 or -208-208						Flt					
F50-351 R1	**New EGPWS computer (P/N 965-0976-040-212-212) for Collins Avionics version 5.X or 6.X**							T (A/R)			
31 A/F						Mos					
Eff: 09-Jul-2004						Hrs					
						Ldg					
Note: M2581, M2586, M2585, A/C with Avionics V6.X + EGPWS P/N 965-0976-040-202-202 or -208 -208 and A/C with Avionics V5.X + EGPWS P/N 965-0976-040-105-105 or -208-208						Flt					
F50-459	**EGPWS - Steep Approach**							RE (-)			
31 A/F						Mos					
Eff: 16-Jun-2005						Hrs					
						Ldg					
Note: M2054, 251, 253 to 352 with EGPWS and COLLINS Avionics V5 P/N 965-0976-040-105-105 or -208-208 or -212-212 or V6 P/N 965-0976-040-202-202 or -208-208 or -212-212						Flt					
F50-484	**Improved EGPWS failure indication**							T (A/R)			
31 A/F						Mos					
Eff: 10-Aug-2007						Hrs					
						Ldg					
Note: M3067, F50 with COLLINS avionics V4.0 or V5.X with an EGPWS						Flt					
F50-497	**Installation of a CTS Quick Access Recorder (QAR) P/N 200-010-1010**							RE (-)			
31 A/F						Mos					
Eff: 17-Apr-2008						Hrs					
						Ldg					
Note: M3042, 251, 253 to 352 with an optional DFDR						Flt					
F50-S035	**Indicating - Recording Systems - Honeywell Enhanced Ground Proximity Warning System (EGPWS) - Upgrade with Optional Runway Safety Package**							T (-)		Optional	
31 A/F						Mos					
Eff: 16-Apr-2021						Hrs					
						Ldg					
Note: EFFECTIVITY: F50 and F50EX aircraft with serial numbers that have previously installed Enhanced Ground Proximity Warning System (EGPWS) computer P/N 965-0976-0XX-212-212 or later.						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-S035-R1	**Indicating - Recording Systems - Honeywell Enhanced Ground Proximity Warning System (EGPWS) Upgrade with Optional Runway Safety Package**							T (A/R)		Optional	
31 A/F						Mos					
Eff: 30-Sep-2021						Hrs					
						Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to F50 and F50EX aircraft with serial numbers that have previously installed Enhanced Ground Proximity Warning System (EGPWS) computer P/N 965-0976-0XX-212-212 or later (aircraft with modification M2581 or M2586 or other certification).						Flt					
▼ 32 - LANDING GEAR											
	Anti Skid Amplifier							RE (O/C)			
32 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Anti-Skid Pressure Switch							RE (O/C)			
32 A/F	Left					Mos	01-Aug-2024				
7G612-1						Hrs	13,356.3				
347						Ldg	9,027				
						Flt	9,026				
	Anti-Skid Pressure Switch							RE (O/C)			
32 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Brake Circuit Filter							RE (O/C)			
32 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Brake Circuit Filter							RE (O/C)			
32 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Brake Circuit Shuttle Valve							RE (O/C)			
32 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Brake Circuit Shuttle Valve							RE (O/C)			
32 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Brake Circuit Swivel Connector							RE (O/C)			
32 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Brake Circuit Swivel Connector							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Brake Servo Valve Return Circuit Check Valve							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Brake Servo Valve Return Circuit Check Valve							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Brake Servo Valve Supply Circuit Check Valve							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Brake Servo Valve Supply Circuit Check Valve							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Driving Cap							RE (O/C)			
	32 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Driving Cap							RE (O/C)			
	32 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Driving Cap							RE (O/C)			
	32 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Driving Cap							RE (O/C)			
	32 A/F	No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Emergency Brake Distributor Check Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Emergency Brakes Distributor Solenoid Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Gear Door Electro Distributor Circuit Restrictor Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		L/G Control Printed Circuit Board							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		L/G Hydraulic Emergency Extension Control Cable							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Landing Gear Circuit Shuttle Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Landing Gear Doors Circuit Shuttle Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Landing Gear Doors Solenoid Directional Valve							RE (O/C)			
	32 A/F						Mos	05-Nov-2024				
	A24520-2	Serviceable					Hrs	13,427.3				
	FM229						Ldg	9,074				
							Flt	9,074				
		Landing Gear Normal/Emergency Selector Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Landing Gear Selector Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Landing Gear Solenoid Directional Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Landing Gear Up IAS Indicator Switch							RE (O/C)			
	32 A/F						Mos	19-Dec-2019				
	4219G010201						Hrs					
	1107						Ldg					
							Flt					
		Lmg Down/Lock Prox Switch							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) (Actuator Side) Shaft							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) (Actuator Side) Shaft							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) (Structure Side) Shaft							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) (Structure Side) Shaft							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Actuator Strut Dash-Pot Sleeve							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Actuator Strut Dash-Pot Sleeve							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Barrel							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Barrel							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Main Landing Gear (MLG) Brace Strut Actuator							RE (H/T)			
	32 A/F	Left					Mos	28-Apr-1989				
	C23925-1103A						Hrs					
	U26						Ldg					
							Flt					
		Main Landing Gear (MLG) Brace Strut Actuator							RE (H/T)			
	32 A/F	Right					Mos	28-Apr-1989				
	C23925-1103A						Hrs					
	47						Ldg					
							Flt					
		Main Landing Gear (MLG) Brake							RE (O/C)			
	32 A/F	Left Inboard					Mos	14-Sep-2023				
	5003280-5	Tested/Inspected					Hrs	13,276.7				
	JUL89-1220						Ldg	8,977				
							Flt	8,977				
		Main Landing Gear (MLG) Brake							RE (O/C)			
	32 A/F	Left Outboard					Mos	14-Sep-2023				
	5003280-5	Tested/Inspected					Hrs	13,276.7				
	JUL79-9						Ldg	8,977				
							Flt	8,977				
		Main Landing Gear (MLG) Brake							RE (O/C)			
	32 A/F	Right Inboard					Mos	24-Mar-2021				
	5003280-5						Hrs					
	DEC91-1396						Ldg					
							Flt					
		Main Landing Gear (MLG) Brake							RE (O/C)			
	32 A/F	Right Outboard					Mos	24-Mar-2021				
	5003280-5						Hrs					
	FEB97-1562						Ldg					
							Flt					
		Main Landing Gear (MLG) Brake Restrictor Valve							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Brake Restrictor Valve							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Brake Servovalve							RE (H/T)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Brake Servovalve							RE (H/T)			
	32 A/F	Right					Mos	29-May-2012				
	9542732-2						Hrs					
	MAY66-124D						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Main Landing Gear (MLG) Door Actuator Proximity Switch							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Door Actuator Proximity Switch							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Door Manual Unlocking Control Pin							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Door Manual Unlocking Control Pin							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Door Restrictor Valve							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Door Restrictor Valve							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Door Uplock							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Door Uplock							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Down Restrictor Valve							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Down Restrictor Valve							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Main Landing Gear (MLG) Drag Brace Proximity Switch							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Drag Brace Proximity Switch							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Front Ball-Joint Bearing							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Front Ball-Joint Bearing							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Leg							RE (H/T)			
	32 A/F	Left					Mos	14-Sep-2023				
	C23791-1009	Overhauled		0			Hrs	13,276.7				
	U78			0			Ldg	8,977				
				0			Flt	8,977				
		Main Landing Gear (MLG) Leg							RE (H/T)			
	32 A/F	Right					Mos	16-Sep-2018				
	C23792-1010-/-1012			0			Hrs					
	U68			0			Ldg					
							Flt					
		Main Landing Gear (MLG) Leg Dual Proximity Switch							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Leg Dual Proximity Switch							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Main Door Actuator							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Main Door Actuator							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Main Landing Gear (MLG) Main Door Uplock Box Proximity Switch							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Main Door Uplock Box Proximity Switch							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Mechanical Emergency Extension Control Cable							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Mechanical Emergency Extension Control Cable							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Mechanical Emergency Extension Flexible Control							RE (O/C)			
	32 A/F						Mos	14-Sep-2023				
	F50B796001110A4	New	0				Hrs	13,276.7				
	3112		0				Ldg	8,977				
			0				Flt	8,977				
		Main Landing Gear (MLG) Proximity Switch							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Proximity Switch							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Rear Ball-Joint Bearing							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Rear Ball-Joint Bearing							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Shock Absorber							RE (H/T)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Main Landing Gear (MLG) Shock Absorber							RE (H/T)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Shock Absorber End-Fitting							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Shock Absorber End-Fitting							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Tire							RE (O/C)			
	32 A/F	Left Inboard					Mos	03-Feb-2025				
	M08401IND03	New	0				Hrs	13,496.2				
	3112T201		0				Ldg	9,121				
			0				Flt	9,121				
		Main Landing Gear (MLG) Tire							RE (O/C)			
	32 A/F	Left Outboard					Mos	03-Feb-2025				
	M08401IND03	New	0				Hrs	13,496.2				
	3113T178		0				Ldg	9,121				
			0				Flt	9,121				
		Main Landing Gear (MLG) Tire							RE (O/C)			
	32 A/F	Right Inboard					Mos	21-Aug-2024				
	M15101-01	New	0				Hrs	13,385.7				
	4085K111		0				Ldg	9,043				
			0				Flt	9,042				
		Main Landing Gear (MLG) Tire							RE (O/C)			
	32 A/F	Right Outboard					Mos	21-Aug-2024				
	M15101-01	New	0				Hrs	13,385.7				
	4083K118		0				Ldg	9,043				
			0				Flt	9,042				
		Main Landing Gear (MLG) Up Restrictor Valve							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Up Restrictor Valve							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Uplock							RE (O/C)			
	32 A/F	Left					Mos	02-Sep-2016				
	C24244-0-1						Hrs					
	U13						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Main Landing Gear (MLG) Uplock							RE (O/C)			
	32 A/F	Right					Mos	02-Sep-2016				
	C24245-0-1						Hrs					
	M014						Ldg					
							Flt					
		Main Landing Gear (MLG) Uplock Proximity Switch							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Uplock Proximity Switch							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Wheel							RE (O/C)			
	32 A/F	Left Inboard					Mos	03-Feb-2025				
	5003279-3	Repaired				0	Hrs	13,496.2				
	Jan98-1915					0	Ldg	9,121				
						0	Flt	9,121				
		Main Landing Gear (MLG) Wheel							RE (O/C)			
	32 A/F	Left Outboard					Mos	03-Feb-2025				
	5003279-3	Repaired				0	Hrs	13,496.2				
	MAY82-298					0	Ldg	9,121				
						0	Flt	9,121				
		Main Landing Gear (MLG) Wheel							RE (O/C)			
	32 A/F	Right Inboard					Mos	21-Aug-2024				
	5003279-3	Tested/Inspected					Hrs	13,385.7				
	FEB88-1315						Ldg	9,043				
							Flt	9,042				
		Main Landing Gear (MLG) Wheel							RE (O/C)			
	32 A/F	Right Outboard					Mos	21-Aug-2024				
	5003279-3	Tested/Inspected					Hrs	13,385.7				
	Oct82-507						Ldg	9,043				
							Flt	9,042				
		Main Landing Gear (MLG) Wheel Tachometer Generator							RE (O/C)			
	32 A/F	Left Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Wheel Tachometer Generator							RE (O/C)			
	32 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear (MLG) Wheel Tachometer Generator							RE (O/C)			
	32 A/F	Right Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Main Landing Gear (MLG) Wheel Tachometer Generator							RE (O/C)			
	32 A/F	Right Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear Lower Brake Swival Fitting							RE (O/C)			
	32 A/F	Left Inboard No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear Lower Brake Swival Fitting							RE (O/C)			
	32 A/F	Left Outboard No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear Return Check Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Main Landing Gear Supply Check Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Na-Blank Printed Circuit							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Na-Blank Printed Circuit							RE (O/C)			
	32 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		NLG Drag Brace Ball-Joint Bearing							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		NLG Drag Brace Ball-Joint Bearing							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		NLG Leg Ball-Joint Bearing							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		NLG Leg Ball-Joint Bearing							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Normal Braking Distributor Return Circuit Check Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Normal/Brake Distributor Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Normal/Emergency Brake Distributor							RE (O/C)			
	32 A/F						Mos	03-Feb-2025				
	57530-2	Serviceable					Hrs	13,496.2				
	131A						Ldg	9,121				
							Flt	9,121				
		Normal/Emergency Brake Selector Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Gear Leg Dual Proximity Switch							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landign Gear (NLG) Uplock Box Switch							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear "Up" Restrictor Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear (NLG) Actuator							RE (O/C)			
	32 A/F						Mos	05-Mar-2017				
	C23810-10-1						Hrs					
	031						Ldg					
							Flt					
		Nose Landing Gear (NLG) Drag Brace							RE (H/T)			
	32 A/F			187			Mos	16-Sep-2018				
	C23811-11			3,431.1			Hrs					
	U54			2,017			Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Nose Landing Gear (NLG) Drag Brace Proximity Switch							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear (NLG) Leg							RE (H/T)			
	32 A/F						Mos	16-Sep-2018				
	C23789-1007-/-/-1010		13,551				Hrs					
	U93		8,298				Ldg					
							Flt					
		Nose Landing Gear (NLG) Proximity Switch							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear (NLG) Shock Absorber							RE (O/C)			
	32 A/F						Mos	16-Sep-2018				
	C23789-1007			0			Hrs					
	U93			0			Ldg					
							Flt					
		Nose Landing Gear (NLG) Tire							RE (O/C)			
	32 A/F	Left					Mos	26-Feb-2025				
	145K13-1	Serviceable					Hrs	13,520.9				
	51682883						Ldg	9,133				
							Flt	9,133				
		Nose Landing Gear (NLG) Tire							RE (O/C)			
	32 A/F	Right					Mos	26-Feb-2025				
	145K13-1	Serviceable					Hrs	13,520.9				
	33303067						Ldg	9,133				
							Flt	9,133				
		Nose Landing Gear (NLG) Uplock							RE (O/C)			
	32 A/F						Mos	24-Feb-2014				
	C24245-4-2						Hrs					
	U738						Ldg					
							Flt					
		Nose Landing Gear (NLG) Wheel							RE (O/C)			
	32 A/F	Left					Mos	26-Feb-2025				
	9543426	Serviceable					Hrs	13,520.9				
	JAN89-3008						Ldg	9,133				
							Flt	9,133				
		Nose Landing Gear (NLG) Wheel							RE (O/C)			
	32 A/F	Right					Mos	26-Feb-2025				
	9543426	Serviceable					Hrs	13,520.9				
	NOV80-1897						Ldg	9,133				
							Flt	9,133				
		Nose Landing Gear Barrel							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Nose Landing Gear Harness							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear Restrictor Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear Retraction Strut (Structure Side) Shaft							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear Retraction Strut Right Ball-Joint Bearing							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear Swivel Coupling							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear Telescopic Bar							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Landing Gear Telescopic Strut Yoke Assembly							RE (H/T)			
	32 A/F						Mos	16-Sep-2018				
	GA58346			0			Hrs					
	63			0			Ldg					
							Flt					
		Nose Landing Gear/Door Manual/Emergency Control Cable							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Overheat Warning Indicator Relay							RE (O/C)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Accumulator							RE (O/C)			
	32 A/F						Mos	14-Oct-2024				
	60833-2	Serviceable					Hrs	13,408.1				
	463						Ldg	9,062				
							Flt	9,062				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Parking Brake Accumulator Filler Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Accumulator Gauge							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Accumulator Supply Check Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Blinker Pressure Switch							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Circuit Overpressure Valve							RE (O/C)			
	32 A/F	Center					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Control Cable							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Control Handle							RE (O/C)			
	32 A/F						Mos	17-Jan-2017				
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		Parking Brake Pressure Switch							RE (O/C)			
	32 A/F	Left					Mos	18-Jun-2014				
	76663-1						Hrs					
	264						Ldg					
							Flt					
		Parking Brake Pressure Switch							RE (O/C)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Parking Brake Selector Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Rear Main Landing Gear (MLG) Pintle Pin							RE (H/T)			
	32 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rear Main Landing Gear (MLG) Pintle Pin							RE (H/T)			
	32 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Steering Amplifier							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Steering Control Unit							RE (O/C)			
	32 A/F						Mos	22-Feb-2019				
	287837-1						Hrs					
	063						Ldg					
							Flt					
		Steering Directional Valve							RE (O/C)			
	32 A/F						Mos	12-Mar-2017				
	C24166-1						Hrs	13,065.2				
	U78						Ldg	8,828				
							Flt					
		Steering Filter							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Steering Hydraulic Unit							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Steering Repeater Box							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Steering Servo Valve							RE (O/C)			
	32 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2001-01-05		**Parking Brake**							RE (-)		Mandatory	
	32 A/F						Mos	08-Mar-2001				
	Eff: 22-Feb-2001						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2001-18-05	**Flight Eagle Tires**							RE (-)	Mandatory (Appliance AD)		
32 A/F						Mos	14-Sep-2003				
Eff: 24-Sep-2001 Not Applicable	by tire size					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2010-24-08	**Landing Gear - two pipes of the emergency brake system 2 located near the nose landing gear bearing**							RE (-)		Mandatory	
32 A/F						Mos	24-Nov-2010				
Eff: 09-Dec-2010						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2011-10-14	**Landing Gear - two pipes of the emergency brake system 2 located near the nose landing gear bearing**							RE (-)		Mandatory	
32 A/F						Mos	20-Apr-2011				
Eff: 17-Jun-2011 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2011-10-14 Paragraph (g)	**Landing Gear - two pipes of the emergency brake system 2 located near the nose landing gear bearing - do a general visual inspection for correct installation**							RE (-)		Mandatory	
32 A/F						Mos					
Eff: 09-Dec-2010 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2011-10-14 Paragraph (h)	**Landing Gear - two pipes of the emergency brake system 2 located near the nose landing gear bearing - If the emergency brake system number 2 is found installed incorrectly during the inspection required by paragraph (g) of this AD: Before further flight, install the emergency brake system number 2 correctly**							RE (-)		Mandatory	
32 A/F						Mos					
Eff: 17-Jun-2011 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2011-10-14 Paragraph (i)	**Landing Gear - two pipes of the emergency brake system 2 located near the nose landing gear bearing - paint the pipe ends of the emergency brake system 2 and related unions**							RE (-)		Mandatory	
32 A/F						Mos					
Eff: 17-Jun-2011 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-16-09	**Landing Gear - Detect and Correct Unprotected Brake Hoses**							RE (-)		Mandatory	
32 A/F						Mos					
Eff: 25-Sep-2017						Hrs					
(AVG MAN HRS: 4) (ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-16-09 Par. 2(g)	**Landing Gear - Detect and Correct Unprotected Brake Hoses - Inspection**							RE (-)		Mandatory	
32 A/F						Mos	31-Oct-2018				
Eff: 25-Sep-2017 Complied With						Hrs					
(AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-16-09 Par. 2(h)	**Landing Gear - Detect and Correct Unprotected Brake Hoses - Installation**							RE (-)		Mandatory	
32 A/F						Mos					
Eff: 25-Sep-2017						Hrs					
(AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)						Ldg					
						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2017-16-09 Par. 2(i)	**Landing Gear - Detect and Correct Unprotected Brake Hoses - Replacement**							T		Mandatory	
32 A/F						Mos		149		25-Feb-2030	5 Years
Eff: 25-Sep-2017						Hrs					
(AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)						Ldg		6,000		≈14,836	5,703 Ldg
						Flt					
32-00-00-700-801-01	**Check of the MLG and NLG Uplock Boxes - NLG Uplock Box (13G)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
C24245-4-2						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
U738						Ldg	8,977				
						Flt	8,977				
Note: A/C with NLG uplock box P/N C24245-4-1											
32-00-00-700-801-02	**Check of the MLG and NLG Uplock Boxes - LH MLG Uplock Box (7G1)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	Left05-10-00-1B					Mos	14-Sep-2023				
C24244-0-1						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
U13						Ldg	8,977				
						Flt	8,977				
Note: A/C with LH MLG uplock box P/N C24244-0-1											
32-00-00-700-801-03	**Check of the MLG and NLG Uplock Boxes - RH MLG Uplock Box (7G2)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	Right05-10-00-1B					Mos	14-Sep-2023				
C24245-0-1						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
M014						Ldg	8,977				
						Flt	8,977				
Note: A/C with RH MLG uplock box P/N C24245-0-1											
32-10-00-640-801-01	**Lubrication of the Main Landing Gears (MLG) and MLG Doors - LH MLG and MLG Doors**							RE		Acft Maint Ops (5-10)	
32 A/F						Mos	26-Feb-2025	6	+5d	26-Aug-2025	5.8 Months (+5 Days)
						Hrs	13,520.9				
						Ldg	9,133	400		9,533	400 Ldg
						Flt	9,133				
32-10-00-640-801-02	**Lubrication of the Main Landing Gears (MLG) and MLG Doors - RH MLG and MLG Doors**							RE		Acft Maint Ops (5-10)	
32 A/F						Mos	26-Feb-2025	6	+5d	26-Aug-2025	5.8 Months (+5 Days)
						Hrs	13,520.9				
						Ldg	9,133	400		9,533	400 Ldg
						Flt	9,133				
32-11-00-220-801-01	**Detailed Inspection of the MLG Legs - LH MLG Leg (L2GF)**							RE		Comp Maint Ops (5-20)	
32 A/F	Left					Mos	14-Sep-2023	72	+8m	14-Sep-2029	4.5 Years (+242 Days)
C23791-1009						Hrs	13,276.7				
U78						Ldg	8,977				
(SOURCE: Falcon 50/50EX MPD)						Flt	8,977				
32-11-00-220-801-01 (5-15)	**Detailed Inspection of the MLG Legs - LH MLG Leg (L2GF)**							RE		CPCP (5-15)	
32 A/F	Left					Mos	14-Sep-2023	80		14-May-2030	5.2 Years
C23791-1009						Hrs	13,276.7				
U78						Ldg	8,977				
						Flt	8,977				
32-11-00-220-801-02	**Detailed Inspection of the MLG Legs - RH MLG Leg (R2GF)**							RE		Comp Maint Ops (5-20)	
32 A/F	Right					Mos	14-Sep-2023	72	+8m	14-Sep-2029	4.5 Years (+242 Days)
C23792-1010-/-1012						Hrs	13,276.7				
U68						Ldg	8,977				
						Flt	8,977				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-11-00-220-801-02 (5-15)	**Detailed Inspection of the MLG Legs - RH MLG Leg (R2GF)**							RE		CPCP (5-15)	
32 A/F	Right					Mos	14-Sep-2023	80		14-May-2030	5.2 Years
C23792-1010-/-1012						Hrs	13,276.7				
U68						Ldg	8,977				
						Flt	8,977				
32-11-00-350-801-01	**Restoration of the MLG Legs (Overhaul) - LH MLG Leg (L2GF)**							RE		Comp Maint Ops (5-20)	
32 A/F	Left					Yrs	14-Sep-2023	12	+5m	14-Sep-2035	10.5 Years (+153 Days)
C23791-1009											
U78					0	Hrs	13,276.7				
					0	Ldg	8,977	6,000		14,977	5,844 Ldg
	Note: P/N C23791-10-1 or P/N C23791-1002 or P/N C23791-1003 or P/N C23791-1004 or P/N C23791-1005 or P/N C23791-1006 or P/N C23791-1007 or P/N C23791-1008 or P/N C23791-1009 or P/N C23791-1010 or P/N C23791-1011 or P/N C23791-1012. (1) - (10) - (105)				0	Flt	8,977				
32-11-00-350-801-02	**Restoration of the MLG Legs (Overhaul) - RH MLG Leg (R2GF)**							RE		Comp Maint Ops (5-20)	
32 A/F	Right					Yrs	16-Sep-2018	12	+5m	16-Sep-2030	5.5 Years (+153 Days)
C23792-1010-/-1012											
U68						Hrs					
						Ldg	8,836	6,000		14,836	5,703 Ldg
	Note: P/N C23792-10-1 or P/N C23792-1002 or P/N C23792-1003 or P/N C23792-1004 or P/N C23792-1005 or P/N C23792-1006 or P/N C23792-1007 or P/N C23792-1008 or P/N C23792-1009 or P/N C23792-1010 or P/N C23792-1011 or P/N C23792-1012. (1) - (10) - (105)					Flt					
32-11-00-960-801-01	**Replacement of the MLG Legs (Discard of Life Limited Parts) - LH MLG Leg (L2GF)**							RE		Comp Maint Ops (5-20)	**≈27-Apr-2055**
32 A/F	Left					Mos					
C23791-1009						Hrs					
U78						Ldg		20,000		20,000	10,867 Ldg
	Note: P/N C23791-10-1 or P/N C23791-1002 or P/N C23791-1003 or P/N C23791-1004 or P/N C23791-1005 or P/N C23791-1006 or P/N C23791-1007 or P/N C23791-1008 or P/N C23791-1009 or P/N C23791-1010 or P/N C23791-1011 or P/N C23791-1012. (1)					Flt					
32-11-00-960-801-01 (5-40)	**Replacement of the MLG Legs (Discard of Life Limited Parts) - LH MLG Leg (L2GF)**							RE		AWL (5-40), Life Limit	**≈27-Apr-2055**
32 A/F	Left					Mos					
C23791-1009						Hrs					
U78						Ldg		20,000		20,000	10,867 Ldg
	Note: P/N C23791-10-1 or C23791-1002 or C23791-1003 or C23791-1004 or C23791-1005 or C23791-1006 or C23791-1007 or C23791-1008 or C23791-1009 or C23791-1010 or C23791-1011 (1)					Flt					
32-11-00-960-801-02	**Replacement of the MLG Legs (Discard of Life Limited Parts) - RH MLG Leg (R2GF)**							RE		Comp Maint Ops (5-20)	**≈10-Nov-2079**
32 A/F	Right					Mos	31-Oct-2018				
C23792-1010-/-1012						Hrs	13,081.5				
U68						Ldg	8,840	20,000		28,840	19,707 Ldg
	Note: P/N C23792-10-1 or P/N C23792-1002 or P/N C23792-1003 or P/N C23792-1004 or P/N C23792-1005 or P/N C23792-1006 or P/N C23792-1007 or P/N C23792-1008 or P/N C23792-1009 or P/N C23792-1010 or P/N C23792-1011 or P/N C23792-1012. (1)					Flt					
32-11-00-960-801-02 (5-40)	**Replacement of the MLG Legs (Discard of Life Limited Parts) - RH MLG Leg (R2GF)**							RE		AWL (5-40), Life Limit	**≈10-Nov-2079**
32 A/F	Right					Mos	31-Oct-2018				
C23792-1010-/-1012						Hrs	13,081.5				
U68						Ldg	8,840	20,000		28,840	19,707 Ldg
	Note: P/N C23792-10-1 or C23792-1002 or C23792-1003 or C23792-1004 or C23792-1005 or C23792-1006 or C23792-1007 or C23792-1008 or C23792-1009 or C23792-1010 or C23792-1011 (1)					Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-11-03-960-801-01	**Discard of the MLG Pintle Pin - LH MLG Pintle Pin (L2Gf7)**							RE		Comp Maint Ops (5-20)	**≈25-Feb-2065**
32 A/F	Left					Mos	13-Jun-1991				
Unknown						Hrs	7,107				
Unknown						Ldg	4,873	18,670		23,543	14,410 Ldg
						Flt					
	Note: P/N D48611 or D52554-1 or D52554-2 for A/C with SB F50-161 only (MTOW : 18.5T)										
32-11-03-960-801-01 (5-40)	**Discard of the MLG Pintle Pin - LH MLG Pintle Pin (L2Gf7)**							RE		AWL (5-40), Life Limit	**≈25-Feb-2065**
32 A/F	Left					Mos	13-Jun-1991				
Unknown						Hrs	7,107				
Unknown						Ldg	4,873	18,670		23,543	14,410 Ldg
						Flt					
	Note: P/N D48611 or D52554-1 or D52554-2 for A/C with SB F50-161 only (MTOW : 18.5T)										
32-11-03-960-801-02	**Discard of the MLG Pintle Pin - RH MLG Pintle Pin (R2Gf7)**							RE		Comp Maint Ops (5-20)	**≈25-Feb-2065**
32 A/F	Right					Mos	13-Jun-1991				
Unknown						Hrs	7,107				
Unknown						Ldg	4,873	18,670		23,543	14,410 Ldg
						Flt					
	Note: P/N D48611 or D52554-1 or D52554-2 for A/C with SB F50-161 only (MTOW : 18.5T)										
32-11-03-960-801-02 (5-40)	**Discard of the MLG Pintle Pin - RH MLG Pintle Pin (R2Gf7)**							RE		AWL (5-40), Life Limit	**≈25-Feb-2065**
32 A/F	Right					Mos	13-Jun-1991				
Unknown						Hrs	7,107				
Unknown						Ldg	4,873	18,670		23,543	14,410 Ldg
						Flt					
	Note: P/N D48611 or D52554-1 or D52554-2 for A/C with SB F50-161 only (MTOW : 18.5T)										
32-11-05-350-801-01	**Restoration of the MLG Shock Absorber (Discard of End-Fitting) - LH MLG Shock Absorber (L2Gf5)**							RE		Comp Maint Ops (5-20)	**≈22-Feb-2063**
32 A/F	Left					Mos	06-Dec-2002				
Unknown						Hrs	9,648.1				
Unknown						Ldg	6,819	16,000		22,819	13,686 Ldg
						Flt					
	Note: P/N C23795-10 or C23795-1001 (1) A/C 1, 3 to 39 before SB F50-0123										
32-11-05-350-801-01 (5-40)	**Restoration of the MLG Shock Absorber (Discard of End-Fitting) - LH MLG Shock Absorber (L2Gf5)**							RE		AWL (5-40)	**≈22-Feb-2063**
32 A/F	Left					Mos	06-Dec-2002				
Unknown						Hrs	9,648.1				
Unknown						Ldg	6,819	16,000		22,819	13,686 Ldg
						Flt					
	Note: P/N C23795-10 or C23795-1001 (1) A/C 1, 3 to 39 before SB F50-0123										
32-11-05-350-801-02	**Restoration of the MLG Shock Absorber (Discard of End-Fitting) - RH MLG Shock Absorber (R2Gf5)**							RE		Comp Maint Ops (5-20)	**≈22-Feb-2063**
32 A/F	Right					Mos	06-Dec-2002				
Unknown						Hrs	9,648.1				
Unknown						Ldg	6,819	16,000		22,819	13,686 Ldg
						Flt					
	Note: P/N C23796-10 or C23796-1001 (1) A/C 1, 3 to 39 before SB F50-0123										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-11-05-350-801-02 (5-40)	**Restoration of the MLG Shock Absorber (Discard of End-Fitting) - RH MLG Shock Absorber (R2Gf5)**							RE		AWL (5-40)	**≈22-Feb-2063**
32 A/F	Right					Mos	06-Dec-2002				
Unknown						Hrs	9,648.1				
Unknown						Ldg	6,819	16,000		22,819	13,686 Ldg
						Flt					
Note: P/N C23796-10 or C23796-1001 (1) A/C 1, 3 to 39 before SB F50-0123											
32-11-05-780-801-01	**Check of the Charging Pressure of the MLG Shock Absorbers - LH MLG Shock Absorber (L2Gf5)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-11-05-780-801-02	**Check of the Charging Pressure of the MLG Shock Absorbers - RH MLG Shock Absorber (R2Gf5)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-11-21-350-801-01	**Restoration of the MLG Brace Actuator (Discard of Dash-Pot Fitting) - LH MLG Brace Strut Actuator (12G1)**							RE (N/A)		Comp Maint Ops (5-20)	
32 A/F	Left					Mos					
C23925-1103A						Hrs					
U26						Ldg					
						Flt					
32-11-21-350-801-01 (5-40)	**Restoration of the MLG Brace Actuator (Discard of Dash-Pot Fitting) - LH MLG Brace Strut Actuator (12G1)**							RE (N/A)		AWL (5-40)	
32 A/F	Left					Mos					
C23925-1103A						Hrs					
U26						Ldg					
						Flt					
32-11-21-350-801-02	**Restoration of the MLG Brace Actuator (Discard of Dash-Pot Fitting) - RH MLG Brace Strut Actuator (12G2)**							RE (N/A)		Comp Maint Ops (5-20)	
32 A/F	Right					Mos					
C23925-1103A						Hrs					
47						Ldg					
						Flt					
32-11-21-350-801-02 (5-40)	**Restoration of the MLG Brace Actuator (Discard of Dash-Pot Fitting) - RH MLG Brace Strut Actuator (12G2)**							RE (N/A)		AWL (5-40)	
32 A/F	Right					Mos					
C23925-1103A						Hrs					
47						Ldg					
						Flt					
32-11-25-220-801-01	**Detailed Inspection of MLG Ball-joint Bearings and Bearing Bores - LH MLG Front Ball-joint Bearing (L90GA)**							RE		Acft Maint Ops (5-10)	
32 A/F						Yrs	29-Nov-2023	6	+8m	29-Nov-2029	4.7 Years (+242 Days)
(SOURCE: Falcon 50/50EX MPD)						Hrs	13,287.4				
Note: A tolerance of 8 Months is applicable.						Ldg	8,989				
If this tolerance is used, the next occurrence is to be calculated from the date of last performed. Recommended to be performed in synchronization with LH MLG DETAILED INSPECTION or OVERHAUL.						Flt	8,989				
32-11-25-220-801-02	**Detailed Inspection of MLG Ball-joint Bearings and Bearing Bores - LH MLG Rear Ball-joint Bearing (L100GA)**							RE		Acft Maint Ops (5-10)	
32 A/F						Yrs	29-Nov-2023	6	+8m	29-Nov-2029	4.7 Years (+242 Days)
(SOURCE: Falcon 50/50EX MPD)						Hrs	13,287.4				
Note: A tolerance of 8 Months is applicable.						Ldg	8,989				
If this tolerance is used, the next occurrence is to be calculated from the date of last performed. Recommended to be performed in synchronization with LH MLG DETAILED INSPECTION or OVERHAUL.						Flt	8,989				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-11-25-220-801-03	**Detailed Inspection of MLG Ball-joint Bearings and Bearing Bores - RH MLG Front Ball-joint Bearing (R90GA)**							RE		Acft Maint Ops (5-10)	
32 A/F						Yrs	29-Nov-2023	6	+8m	29-Nov-2029	4.7 Years (+242 Days)
(SOURCE: Falcon 50/50EX MPD)						Hrs	13,287.4				
Note: A tolerance of 8 Months is applicable.						Ldg	8,989				
If this tolerance is used, the next occurrence is to be calculated from the date of last performed. Recommended to be performed in synchronization with RH MLG DETAILED INSPECTION or OVERHAUL.						Flt	8,989				
32-11-25-220-801-04	**Detailed Inspection of MLG Ball-joint Bearings and Bearing Bores - RH MLG Rear Ball-joint Bearing (R100GA)**							RE		Acft Maint Ops (5-10)	
32 A/F						Yrs	29-Nov-2023	6	+8m	29-Nov-2029	4.7 Years (+242 Days)
(SOURCE: Falcon 50/50EX MPD)						Hrs	13,287.4				
Note: A tolerance of 8 Months is applicable.						Ldg	8,989				
If this tolerance is used, the next occurrence is to be calculated from the date of last performed. Recommended to be performed in synchronization with RH MLG DETAILED INSPECTION or OVERHAUL.						Flt	8,989				
32-20-00-640-801-01	**Lubrication of the Nose Landing Gear (NLG) and NLG Doors - NLG and NLG Doors**							RE		Acft Maint Ops (5-10)	
32 A/F						Mos	26-Feb-2025	6	+5d	26-Aug-2025	5.8 Months (+5 Days)
						Hrs	13,520.9				
						Ldg	9,133	400		9,533	400 Ldg
						Flt	9,133				
32-20-00-640-801-02	**Lubrication of the Nose Landing Gear (NLG) and NLG Doors - NLG Sliding Rod Lower Bearing**							RE (N/A)		Comp Maint Ops (5-20)	
32 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
32-21-00-220-801-01	**Detailed Inspection of the NLG Leg - NLG Leg (3GF)**							RE		Comp Maint Ops (5-20)	
32 A/F C23789-1007-/-/-1010 U93						Mos	14-Sep-2023	72	+8m	14-Sep-2029	4.5 Years (+242 Days)
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
32-21-00-220-801-01 (5-15)	**Detailed Inspection of the NLG Leg - NLG Leg (3GF)**							RE		CPCP (5-15)	
32 A/F C23789-1007-/-/-1010 U93						Mos	14-Sep-2023	80		14-May-2030	5.2 Years
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
32-21-00-350-801-01	**Restoration of the NLG Leg (Overhaul) - NLG Leg (3GF)**							RE		Comp Maint Ops (5-20)	
32 A/F C23789-1007-/-/-1010 U93						Yrs	16-Sep-2018	12	+5m	16-Sep-2030	5.5 Years (+153 Days)
						Hrs					
						Ldg	8,949	6,000		14,949	5,816 Ldg
Note: P/N C23787-10-1 or C23787-10-2 or C23787-10-3 or C23787-1004 or C23787-1005 or C23787-1006 or C23787-1007 or C23787-1008 or C23787-1009 or C23787-1010 (1)-(10)-(105)						Flt					
32-21-00-960-801-01	**Replacement of the NLG Leg (Discard of Life Limited Parts) - NLG Leg (3GF)**							RE		Comp Maint Ops (5-20)	**≈27-Apr-2055**
32 A/F C23789-1007-/-/-1010 U93						Mos					
						Hrs					
						Ldg		20,000		20,000	10,867 Ldg
Note: P/N C23787-10-1 or C23787-10-2 or C23787-10-3 or C23787-1004 or C23787-1005 or C23787-1006 or C23787-1007 or C23787-1008 or C23787-1009 or C23787-1010 (1)-(106)						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-21-00-960-801-01 (5-40)	**Replacement of the NLG Leg (Discard of Life Limited Parts) - NLG Leg (3GF)**							RE		AWL (5-40), Life Limit	**≈06-Nov-2079**
32 A/F						Mos	16-Sep-2018				
C23789-1007-/-/-1010						Hrs	13,079.2				
U93						Ldg	8,836	20,000		28,836	19,703 Ldg
						Flt					
	Note: P/N C23787-10-1 or C23787-10-2 or C23787-10-3 or C23787-1004 or C23787-1005 or C23787-1006 or C23787-1007 or C23787-1008 or C23787-1009 or C23787-1010 (1)-(106)										
32-21-01-610-801-01	**Servicing Nose Landing Gear (NLG) Shock Absorber**							RE (A/R)			
32 A/F						Mos	16-Sep-2018				
C23789-1007						Hrs					
U93						Ldg					
						Flt					
32-21-01-610-802-01	**Charging Nose Landing Gear (NLG) Shock Absorber**							RE (A/R)			
32 A/F						Mos	16-Sep-2018				
C23789-1007						Hrs					
U93						Ldg					
						Flt					
32-21-01-780-801-01	**Check of the Charging Pressure of the NLG Shock Absorber - NLG Shock Absorber (3Gf5)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-21-09-220-801-01	**Detailed Inspection of the NLG Leg and NLG Drag Brace Ball-joint Bearings and Bearing Bores - LH NLG Drag Brace Ball-joint Bearing**							RE		Acft Maint Ops (5-10)	
32 A/F						Yrs	29-Nov-2023	6	+8m	29-Nov-2029	4.7 Years (+242 Days)
	(SOURCE: Falcon 50/50EX MPD)					Hrs	13,287.4				
	Note: A tolerance of 8 Months is applicable.					Ldg	8,989				
	If this tolerance is used, the next occurrence is to be calculated from the date of last performed. Recommended to be performed in synchronization with NLG DETAILED INSPECTION or OVERHAUL.					Flt	8,989				
32-21-09-220-801-02	**Detailed Inspection of the NLG Leg and NLG Drag Brace Ball-joint Bearings and Bearing Bores - RH NLG Drag Brace Ball-joint Bearing**							RE		Acft Maint Ops (5-10)	
32 A/F						Yrs	29-Nov-2023	6	+8m	29-Nov-2029	4.7 Years (+242 Days)
	(SOURCE: Falcon 50/50EX MPD)					Hrs	13,287.4				
	Note: A tolerance of 8 Months is applicable.					Ldg	8,989				
	If this tolerance is used, the next occurrence is to be calculated from the date of last performed. Recommended to be performed in synchronization with NLG DETAILED INSPECTION or OVERHAUL.					Flt	8,989				
32-21-09-220-801-03	**Detailed Inspection of the NLG Leg and NLG Drag Brace Ball-joint Bearings and Bearing Bores - LH NLG Leg Ball-joint Bearing**							RE		Acft Maint Ops (5-10)	
32 A/F						Yrs	29-Nov-2023	6	+8m	29-Nov-2029	4.7 Years (+242 Days)
	(SOURCE: Falcon 50/50EX MPD)					Hrs	13,287.4				
	Note: A tolerance of 8 Months is applicable.					Ldg	8,989				
	If this tolerance is used, the next occurrence is to be calculated from the date of last performed. Recommended to be performed in synchronization with NLG DETAILED INSPECTION or OVERHAUL.					Flt	8,989				
32-21-09-220-801-04	**Detailed Inspection of the NLG Leg and NLG Drag Brace Ball-joint Bearings and Bearing Bores - RH NLG Leg Ball-joint Bearing**							RE		Acft Maint Ops (5-10)	
32 A/F						Yrs	29-Nov-2023	6	+8m	29-Nov-2029	4.7 Years (+242 Days)
	(SOURCE: Falcon 50/50EX MPD)					Hrs	13,287.4				
	Note: A tolerance of 8 Months is applicable.					Ldg	8,989				
	If this tolerance is used, the next occurrence is to be calculated from the date of last performed. Recommended to be performed in synchronization with NLG DETAILED INSPECTION or OVERHAUL.					Flt	8,989				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-22-01-350-801-01	**Restoration of the NLG Drag Brace Yoke Assy (Overhaul) - NLG Drag Brace (11G)**							RE		Comp Maint Ops (5-20)	
32 A/F						Yrs	16-Sep-2018	12	+5m	16-Sep-2030	5.5 Years (+153 Days)
GA58346											
63						Hrs	13,079.2				
						Ldg	8,836	6,000		14,836	5,703 Ldg
	Note: P/N C23811-11 or C23811-1113 or C23811-12 or C23811-13 or C23811-14 or C23811-15 (1)-(10)-(105)					Flt					
32-30-00-720-801-01	**Functional Test of Extension and Retraction of Landing Gears and Doors - Normal Operation**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-30-00-720-801-02	**Functional Test of Extension and Retraction of Landing Gears and Doors - Hydraulic Emergency Operation**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-30-00-720-801-03	**Functional Test of Extension and Retraction of Landing Gears and Doors - Mechanical Emergency Operation**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-31-00-700-801-01	**Check of the Landing Gear Retraction Inhibition on the Ground**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-31-13-790-801-01	**Internal Leak Check of the Landing Gear Solenoid Selector Valve - L/G Solenoid Selector Valve (9G)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-32-00-640-801-01	**Servicing of the Landing Gear Mechanical Emergency Release Control - Lubrication of the NLG Control**							RE		Acft Maint Ops (5-10)	
32 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
32-32-00-640-801-02	**Servicing of the Landing Gear Mechanical Emergency Release Control - Check of the NLG Control Actuation Force**							RE		Acft Maint Ops (5-10)	
32 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
32-32-00-640-801-03	**Servicing of the Landing Gear Mechanical Emergency Release Control - Lubrication of the MLG Controls**							RE		Acft Maint Ops (5-10)	
32 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
	Note: A/C with TELEFORCE controls (type S41-21) After SB F50-092					Ldg	8,977				
						Flt	8,977				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-32-00-640-801-04	**Servicing of the Landing Gear Mechanical Emergency Release Control - Check of the MLG Control Actuation Force**							RE		Acft Maint Ops (5-10)	
32 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
	Note: A/C with TELEFORCE controls (type S41-21) After SB F50-092					Ldg	8,977				
						Flt	8,977				
32-32-00-700-801	**Check After Landing Gear Emergency Extension**							RE (A/R)		Unsch Maint Chk (5-50)	
32 A/F						Mos					
						Hrs					
	Ref:32-120					Ldg					
						Flt					
32-32-17-640-801-01	**Servicing of the Landing Gear Hydraulic Emergency Extension Control - Lubrication of the L/G Hydraulic Emergency Extention Control**							RE		Acft Maint Ops (5-10)	
32 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
	Note: A/C with TELEFORCE controls (type S41-21) After SB F50-092					Ldg	8,977				
						Flt	8,977				
32-32-17-640-801-02	**Servicing of the Landing Gear Hydraulic Emergency Extension Control - Check of Control Actuation Loads**							RE		Acft Maint Ops (5-10)	
32 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
	Note: A/C with TELEFORCE controls (type S41-21) After SB F50-092					Ldg	8,977				
						Flt	8,977				
32-40-00-780-801-01	**Check of Braking Pressures - Normal Braking System**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
32 A/F	05-10-00-2B					Mos	02-Sep-2016				
						Hrs	12,978.6	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					
32-40-00-780-801-02	**Check of Braking Pressures - Emergency Braking System**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
32 A/F	05-10-00-2B					Mos	02-Sep-2016				
						Hrs	12,978.6	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					
32-40-00-780-801-03	**CHECK OF PARKING BRAKING PRESSURE**							RE			**≈25-Dec-2031**
32 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	3,000	-/+30	15,978.6	2,457.7 Hrs (+30)
						Ldg	8,785				
						Flt					
32-41-00-720-802-01	**Functional Test of the Anti-Skid System**							RE		Acft Maint Ops (5-10)	**≈21-Feb-2036**
32 A/F	05-10-00-3B					Mos	02-Sep-2016				
						Hrs	12,978.6	4,500	+30	(17,478.6)	3,957.7 Hrs (+30)
						Ldg	8,785				
						Flt					
32-41-37-960-801-01	**Replacement of the Filter Elements of Braking System Filters - LH MLG Brake Filter (L580Gc)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-41-37-960-801-02	**Replacement of the Filter Elements of Braking System Filters - RH MLG Brake Filter (R580Gc)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
32-41-57-350-801-01	**Restoration of the Brake Servovalves (Overhaul) - LH MLG Brake Servovalve (57G1)**							RE		Comp Maint Ops (5-20)	
32 A/F	Left					Yrs	28-Apr-2012	25	+3%d	28-Apr-2037	12.2 Years (+273 Days)
Unknown						Hrs					
Unknown						Ldg					
Restored Date 28-Apr-2012						Flt					
Note: P/N 9542732-2 (1) For equipment older than 25 years at the date of Mar. 2006 (TR38 after reissue 3 revision 5), OVH to be performed at the next equipment removal, no later than 2B inspection											
32-41-57-350-801-02	**Restoration of the Brake Servovalves (Overhaul) - RH MLG Brake Servovalve (57G2)**							RE		Comp Maint Ops (5-20)	
32 A/F	Right					Yrs	29-May-2012	25	+3%d	29-May-2037	12.2 Years (+273 Days)
9542732-2						Hrs					
MAY66-124D						Ldg					
Restored Date 29-May-2012						Flt					
Note: P/N 9542732-2 (1) For equipment older than 25 years at the date of Mar. 2006 (TR38 after reissue 3 revision 5), OVH to be performed at the next equipment removal, no later than 2B inspection											
32-41-57-960-801-01	**Replacement of the Filter and Seal of the Brake Servovalves - LH MLG Brake Servovalve (57G1)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	Left05-10-00-1B					Mos	14-Sep-2023				
Unknown						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
Unknown						Ldg	8,977				
						Flt	8,977				
32-41-57-960-801-02	**Replacement of the Filter and Seal of the Brake Servovalves - RH MLG Brake Servovalve (57G2)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	Right05-10-00-1B					Mos	14-Sep-2023				
9542732-2						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
MAY66-124D						Ldg	8,977				
						Flt	8,977				
32-42-00-720-801-01	**Functional Test of the Park Brake System - Park Brake System**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
32 A/F	05-10-00-2B					Mos	30-Sep-2019				
						Hrs	13,127.7	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
(SOURCE: Falcon 50/50EX MPD)						Ldg	8,877				
						Flt					
32-42-05-720-801-01	**Functional Test Of The Park Brake Accumulator Capacity**							RE			
32 A/F						Mos	31-Aug-2023	36	+1m	29-Sep-2025	6.9 Months (+30 Days)
(Tol. Adjustment: -331d)						Hrs					
						Ldg					
						Flt					
32-42-05-780-801-01	**Check of the Park Brake System Accumulator Pressure**							RE			**≈08-Aug-2025**
32 A/F						Mos	31-Oct-2018				
						Hrs	13,081.5	600	-/+30	13,681.5	160.6 Hrs (+30)
						Ldg	8,840				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-42-05-780-801-02	**Check of the Park Brake System Accumulator Pressure - Park Brake Accumulator (520GC)**							RE		Acft Maint Ops (5-10)	
32 A/F						Mos	14-Sep-2023	24	+1m	14-Sep-2025	6.4 Months (+30 Days)
(SOURCE: Falcon 50/50EX MPD)						Hrs	13,276.7	2,000		15,276.7	1,755.8 Hrs
Note: Not to exceed 2000FH						Ldg	8,977				
						Flt	8,977				
32-44-00-220-801-01	**Detailed Inspection of the MLG and NLG Wheel Tires**							RE			
32 A/F						Mos	03-Feb-2025	2	+5d	03-Apr-2025	28 Days (+5)
						Hrs	13,496.2				
Brand C::32-44-00-220-801-01						Ldg	9,121				
						Flt	9,121				
32-44-00-780-801-01	**Pressure Check of the MLG and NLG Wheel Tires**							RE		Acft Maint Ops (5-10)	
32 A/F						Mos	26-Feb-2025	2	-/+5d	26-Apr-2025	51 Days (+5)
						Hrs	13,520.9				
						Ldg	9,133				
						Flt	9,133				
32-44-01-280-801-01	**Special Detailed Inspection of the NLG Wheels - LH NLG Wheel (L565Gc)**							RE		Comp Maint Ops (5-20)	**≈18-Jul-2026**
32 A/F	Left					Mos	26-Feb-2025				
9543426						Hrs	13,520.9				
JAN89-3008						Ldg	9,133	500	+3%	9,633	500 Ldg (+15)
						Flt	9,133				
Note: P/N 9543426											
32-44-01-280-801-02	**Special Detailed Inspection of the NLG Wheels - RH NLG Wheel (R565Gc)**							RE		Comp Maint Ops (5-20)	**≈18-Jul-2026**
32 A/F	Right					Mos	26-Feb-2025				
9543426						Hrs	13,520.9				
NOV80-1897						Ldg	9,133	500	+3%	9,633	500 Ldg (+15)
						Flt	9,133				
Note: P/N 9543426											
32-44-09-280-801-01	**Special Detailed Inspection of the MLG Wheels - LH MLG Outboard Wheel (L540Gc)**							RE		Comp Maint Ops (5-20)	**≈26-Mar-2026**
32 A/F	Left Outboard					Mos	03-Feb-2025				
5003279-3						Hrs	13,496.2				
MAY82-298						Ldg	9,121	400	+3%	9,521	388 Ldg (+12)
						Flt	9,121				
Note: P/N 5003279-3											
Can be done at the occasion of the next tire change											
32-44-09-280-801-02	**Special Detailed Inspection of the MLG Wheels - LH MLG Inboard Wheel (L535Gc)**							RE		Comp Maint Ops (5-20)	**≈26-Mar-2026**
32 A/F	Left Inboard					Mos	03-Feb-2025				
5003279-3						Hrs	13,496.2				
Jan98-1915						Ldg	9,121	400	+3%	9,521	388 Ldg (+12)
						Flt	9,121				
Note: P/N 5003279-3											
Can be done at the occasion of the next tire change											
32-44-09-280-801-03	**Special Detailed Inspection of the MLG Wheels - RH MLG Inboard Wheel (R535Gc)**							RE		Comp Maint Ops (5-20)	**≈08-Jan-2026**
32 A/F	Right Inboard					Mos	21-Aug-2024				
5003279-3						Hrs	13,385.7				
FEB88-1315						Ldg	9,043	400	+3%	9,443	310 Ldg (+12)
						Flt	9,042				
Note: P/N 5003279-3											
Can be done at the occasion of the next tire change											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
32-44-09-280-801-04	**Special Detailed Inspection of the MLG Wheels - RH MLG Outboard Wheel (R540Gc)**							RE		Comp Maint Ops (5-20)	**≈08-Jan-2026**
32 A/F	Right Outboard					Mos	21-Aug-2024				
5003279-3						Hrs	13,385.7				
Oct82-507						Ldg	9,043	400	+3%	9,443	310 Ldg (+12)
						Flt	9,042				
Note: P/N 5003279-3											
Can be done at the occasion of the next tire change											
32-50-17-960-801-01	**Replacement of the Steering System Filtering Element - Steering System Filter (511Gh)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
32 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
89-06-05	**Main Landing Gear Unlocking Pin**							RE (-)		Mandatory	
32 A/F						Mos	11-Sep-2003				
Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
89-06-05 R1	**Main Landing Gear Unlocking Pin**							RE (-)		Mandatory	
32 A/F						Mos	24-Mar-2021				
Eff: 12-Jan-1990						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
90-03-05	**MLG Emergency Release System**							RE (-)		Mandatory	
32 A/F						Mos	24-Mar-2021				
Eff: 23-Feb-1990						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
F50-019	**LG - Nose door stops - Augmented gap between control fork and proximity switches when the door is open**							RE (-)			
32 A/F						Mos					
Eff: 29-Nov-1979						Hrs					
						Ldg					
Note: M0075						Flt					
F50-020	**Antiskid control amplifier - Ground and flight test duration reduced**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: M0071						Flt					
F50-020 R1	**Antiskid control amplifier - Ground and flight test duration reduced**							RE (-)			
32 A/F						Mos					
Eff: 30-Dec-1980						Hrs					
						Ldg					
Note: M0071						Flt					
F50-061	**MLG side doors - Maneuver actuators replaced**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: M0136						Flt					
F50-061 R1	**MLG side doors - Maneuver actuators replaced**							RE (-)			
32 A/F						Mos	22-Jan-1981				
Eff: 29-May-1980						Hrs					
						Ldg					
Note: M0136						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-066	**Parking brake handle replaced and attached otherwise to facilitate glareshield removal**							RE (-)			
32 A/F						Mos					
Eff: 29-Oct-1980						Hrs					
						Ldg					
Note: M0047, M0606						Flt					
F50-067	**Landing gear - Improved sealing of the ground/flight switches**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: M0358A						Flt					
F50-067 R1	**Landing gear - Improved sealing of the ground/flight switches**							RE (-)			
32 A/F						Mos					
Eff: 14-Nov-1980						Hrs					
						Ldg					
Note: M0358A						Flt					
F50-095	**Provisions for Goodyear 5003279-1A, 5003279-2, 5003279-2A or 5003279-3 wheels**							RE (-)			
32 A/F						Mos	28-Oct-1981				
Complied With						Hrs					
						Ldg					
Note: M0385A						Flt					
F50-095 R1	**Provisions for Goodyear 5003279-1A, 5003279-2, 5003279-2A or 5003279-3 wheels**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: M0385A						Flt					
F50-095 R2	**Provisions for Goodyear 5003279-1A, 5003279-2, 5003279-2A or 5003279-3 wheels**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: M0385A						Flt					
F50-095 R3	**Provisions for Goodyear 5003279-1A, 5003279-2, 5003279-2A or 5003279-3 wheels**							T (A/R)			
32 A/F						Mos					
Eff: 28-Jun-1984						Hrs					
						Ldg					
Note: M0385A						Flt					
F50-118	**NLG - Emergency mechanical extension control handle check**							T (A/R)			
32 A/F						Mos					
Eff: 08-Nov-1982						Hrs					
						Ldg					
Note: M0972A, M0972B						Flt					
F50-123	**MLG - Reinforced shock absorber end-fittings**							T (A/R)			
32 A/F						Mos					
Eff: 29-Oct-1985						Hrs					
						Ldg					
Note: M0266, A/C with MLG shock absorbers P/N C23795-1001 or C23796-1001						Flt					
F50-124	**ML gear and doors - Replacement of truss actuating cylinder**							RE (-)			
32 A/F						Mos	28-Apr-1989				
Eff: 05-Jan-1984 Complied With						Hrs					
						Ldg					
Note: M0933, A/C with truss actuating cylinder assemblies P/N C23925-11-1 Admt A or C23926-11-1 Admt A						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-134	**Landing gear - Improved protection of proximity switch units**							T (A/R)			
32 A/F						Mos					
Eff: 08-Mar-1984						Hrs					
						Ldg					
Note: M0358B						Flt					
F50-135	**Closing of main landing gear doors - Raising of electrical control threshold**							T (A/R)			
32 A/F						Mos					
Eff: 04-Jan-1984						Hrs					
						Ldg					
Note: M0994						Flt					
F50-159	**Emergency L/G extension control - Latching of the emergency gear pull control in the rest position**							T (A/R)			
32 A/F						Mos					
Eff: 25-Mar-1985						Hrs					
						Ldg					
Note: M1095						Flt					
F50-172	**Normal and emergency LG braking systems - Protectors for the hydraulic lines**							T (A/R)			
32 A/F						Mos					
Eff: 10-Dec-1985						Hrs					
						Ldg					
Note: M0376						Flt					
F50-184	**MLG front bearings - Installation of deeper sealed casings**							RE (-)			
32 A/F						Mos	18-Jun-1991				
Eff: 04-Dec-1986 Complied With						Hrs					
						Ldg					
Note: M1373						Flt					
F50-208	**MLG door uplock units - Manual emergency release system without limited service life**							RE (-)			
32 A/F						Mos	11-Sep-2003				
Complied With						Hrs					
						Ldg					
Note: M1596B, M1596A, AD EASA 89-041-007 R1 (AD FAA 90-03-05)						Flt					
F50-208 R1	**MLG door uplock units - Manual emergency release system without limited service life**							RE (-)			
32 A/F						Mos	23-Feb-1990				
Eff: 25-Jul-1989						Hrs					
						Ldg					
Note: M1596B, M1596A, AD EASA 89-041-007 R1 (AD FAA 90-03-05)						Flt					
F50-212	**MLG door manual emergency release system - Adjustable control bell crank installation**							RE (-)			
32 A/F						Mos	12-Oct-2010				
Eff: 18-Dec-1990 Complied With	Previously CW					Hrs	11,295				
						Ldg	7,881				
Note: M1618						Flt					
F50-226	**Break control valve - New captive ring**							T (A/R)			
32 A/F						Mos					
Eff: 11-Dec-1991						Hrs					
						Ldg					
Note: M1726						Flt					
F50-261	**Installation of restrictor valves with reduced cross-sectional area and modification of L/G indicating wiring harness**							RE (-)			
32 A/F						Mos					
Eff: 29-Jul-1998						Hrs					
						Ldg					
Note: M2216						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-296	**MLG doors - New locking of the adjustment screws for the proximity detector of the uplock boxes**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: M2641						Flt					
F50-296 R1	**MLG doors - New locking of the adjustment screws for the proximity detector of the uplock boxes**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: M2641						Flt					
F50-296 R2	**MLG doors - New locking of the adjustment screws for the proximity detector of the uplock boxes**							T (A/R)			
32 A/F						Mos					
Eff: 10-Oct-2001						Hrs					
						Ldg					
Note: M2641						Flt					
F50-305-Alert	**Checking the restrictor valves of main and nose LG and doors system and the main gear door actuators**							T (A/R)			
32 A/F						Mos					
Eff: 10-Nov-1998						Hrs					
						Ldg					
						Flt					
F50-312	**NLG wheel steering system - Displacement of handwheel**							T (A/R)			
32 A/F						Mos					
Eff: 13-Sep-2000						Hrs					
						Ldg					
Note: M2455, 2 to 250 with PROLINE IV avionics and 251 to 293						Flt					
F50-499	**Installation of LG instruction plates for shock absorber height measurement**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: M3131, A/C without M3131						Flt					
F50-499 R1	**Installation of LG instruction plates for shock absorber height measurement**							T (A/R)			
32 A/F						Mos					
Eff: 15-Mar-2010						Hrs					
						Ldg					
Note: M3131, A/C without M3131						Flt					
F50-510	**MLG - Installation of protective wraps on braking system flexible hoses**							RE (-)			
32 A/F						Mos	12-Apr-2010				
Complied With						Hrs					
						Ldg					
Note: M3152, AD EASA 2013-0255, A/C without MLG leg P/N C23791-1009 Amdt F or P/N C23792-1009 Amdt F						Flt					
F50-510 R1	**MLG - Installation of protective wraps on braking system flexible hoses**							RE (-)			
32 A/F						Mos	25-May-2010				
						Hrs					
						Ldg					
						Flt					
F50-510 R2	**MLG - Installation of protective wraps on braking system flexible hoses**							T (A/R)			
32 A/F						Mos					
Eff: 25-Sep-2013						Hrs					
						Ldg					
Note: M3152, AD EASA 2013-0255, A/C without MLG leg P/N C23791-1009 Amdt F or P/N C23792-1009 Amdt F						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-515 R1-Alert	**Emergency brake system installation check**							RE (-)			
32 A/F						Mos	28-Oct-2010				
Eff: 07-Jun-2011 Complied With						Hrs	11,295.8				
						Ldg	7,884				
Note: M3118, AD EASA 2010-0208-E (AD FAA 2011-10-14)						Flt					
F50-515-Alert	**Emergency brake system installation check**							RE (-)			
32 A/F						Mos	24-Nov-2010				
						Hrs					
						Ldg					
Note: M3118, AD EASA 2010-0208-E (AD FAA 2011-10-14)						Flt					
F50-515-Alert Part 1	**Landing Gear - Brake System - Emergency Brake System Installation Check [Check For Swapped Pipes], Alert Service Bulletin**							RE (-)		Mandatory	
32 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-515-Alert Part 2	**Landing Gear - Brake System - Emergency Brake System Installation Check [Paint Pipe/Union Ends], Alert Service Bulletin**							RE (-)		Mandatory	
32 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-515-R1-Alert Part 1	**Check Landing Gear - Brake System - Emergency Brake System Installation Check, Alert Service Bulletin For Swapped Pipes**							RE (-)		Mandatory	
32 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-515-R1-Alert Part 2	**Paint Landing Gear - Brake System - Emergency Brake System Installation Check, Alert Service Bulletin The Ends Of The Pipes And Unions**							RE (-)		Mandatory	
32 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-518	**MLG - Improvement of braking hoses and corresponding assemblies**							T (-)			
32 A/F						Mos					
Eff: 07-Jun-2011						Hrs					
						Ldg					
Note: M3152, A/C without MLG leg P/N C23791-1009 Amdt F or P/N C23792-1009 Amdt F Note: incorporation of this SB makes SB F50-510 R1 not applicable.						Flt					
F50-518 R1	**MLG - Improvement of Braking Hoses and Corresponding Assemblies**							T (A/R)		Optional	
32 A/F						Mos					
Eff: 28-Sep-2016						Hrs					
(AVG MAN HRS: 2)						Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to MYSTERE-FALCON 50 aircraft which are not equipped with: • LH main landing gear P/N C23791-xxxx Amdt F, • RH main landing gear P/N C23792-xxxx Amdt F. NOTE: Incorporation of this Service Bulletin makes Service Bulletin F50-510 not applicable.						Flt					
F50-521	**LG - Addition of anti-corrosion treatment**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: R1766, A/C 2 to 352 without MLG leg P/N C23791-1010 or P/N C23792-1010 and NLG leg P/N C23787-1010 or C23787-2007 or subsequent.						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-521 R1	**LG - Addition of anti-corrosion treatment**							RE (-)			
32 A/F						Mos					
						Hrs					
						Ldg					
Note: R1766, A/C 2 to 352 without MLG leg P/N C23791-1010 or P/N C23792-1010 and NLG leg P/N C23787-1010 or C23787-2007 or subsequent.						Flt					
F50-521 R2	**LG - Addition of anti-corrosion treatment**							T (A/R)			
32 A/F						Mos					
Eff: 19-Sep-2014						Hrs					
						Ldg					
Note: R1766, A/C 2 to 352 without MLG leg P/N C23791-1010 or P/N C23792-1010 and NLG leg P/N C23787-1010 or C23787-2007 or subsequent.						Flt					
▼ 33 - LIGHTS											
	Cockpit Dimmer Box							RE (O/C)			
33 A/F						Mos	01-Aug-2024				
24-012						Hrs	13,356.3				
42						Ldg	9,027				
						Flt	9,026				
	Anti-Collision Light							RE (O/C)			
33 A/F	Lower					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Anti-Collision Light							RE (O/C)			
33 A/F	Upper					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Anti-Collision Lights Unit Power Supply							RE (O/C)			
33 A/F	Lower					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Anti-Collision Lights Unit Power Supply							RE (O/C)			
33 A/F	Upper					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Console Unit Power Supply							RE (O/C)			
33 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Console Unit Power Supply							RE (O/C)			
33 A/F	Right					Mos	22-Nov-2014				
24-50-1						Hrs					
5009						Ldg					
						Flt					
	Emergency Exit Light							RE (O/C)			
33 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Emergency Exit Light							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Evacuation Light							RE (O/C)			
	33 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Evacuation Light							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Compartment Reading Light							RE (O/C)			
	33 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Compartment Reading Light							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Glare Shield Lighting Power Supply							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Landing Light							RE (O/C)			
	33 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Landing Light							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Landing Light Switch							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Light Assembly							RE (O/C)			
	33 A/F	Lower					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Light Assembly							RE (O/C)			
	33 A/F	Upper					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lighting Unit Power Supply							RE (O/C)			
	33 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lighting Unit Power Supply							RE (O/C)			
	33 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nav Light Fairing							RE (O/C)			
	33 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nav Light Fairing							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Overhead Panel Power Supply							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pilots Master Warning Button							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pilots Master Warning Switch							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Power Supply, Cabin Indrct Light							RE (O/C)			
	33 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Power Supply, Cabin Indrct Light							RE (O/C)			
	33 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Power Supply, Cabin Indrct Light							RE (O/C)			
	33 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Power Supply, Cabin Indrct Light							RE (O/C)			
	33 A/F	No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Power Supply, Cabin Indrct Light							RE (O/C)			
	33 A/F	No.5					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Proximity Taxi Light Circuit Proximity Sensor Proximity Switch							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Segments Unit Power Supply							RE (O/C)			
	33 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Segments Unit Power Supply							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Spot Light							RE (O/C)			
	33 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Spot Light							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Strobe Light, Tail							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Tail Light Power Supply							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Tail Navigation Light							RE (O/C)			
	33 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Taxi Light							RE (O/C)			
	33 A/F						Mos	22-Jan-2025				
	4626	Serviceable					Hrs	13,483.9				
	Unknown						Ldg	9,112				
							Flt	9,112				
		Wing Navigation Light Lens							RE (O/C)			
	33 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Navigation Light Lens							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Strobe Light							RE (O/C)			
	33 A/F	Left					Mos	24-Mar-2021				
	30-1191-3						Hrs					
	321						Ldg					
							Flt					
		Wing Strobe Light							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Strobe Unit Power Supply							RE (O/C)			
	33 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Wing Strobe Unit Power Supply							RE (O/C)			
	33 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2004-09-27		**Optical lighting in the cabin**							RE (-)		Mandatory	
	33 A/F						Mos	12-Oct-2010				
	Eff: 16-Jun-2004 Complied With						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
2004-09-27 Paragraph (a)		**Optical lighting in the cabin - Inspection**							RE (-)		Mandatory	
	33 A/F						Mos					
	Eff: 06-Jun-2004						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2004-09-27 Paragraph (b)	**Optical lighting in the cabin - Corrective Action**							RE (-)		Mandatory	
33 A/F						Mos					
Eff: 16-Jun-2004						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2016-19-13	**Lights - Anti-collision Light Bonding**							RE (-)		Mandatory	
33 A/F						Mos	31-Oct-2018				
Eff: 22-Nov-2016 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
33-20-00-200-802-01	**Passenger Cabin Lighting - Check of the Connection of "SELA" Lighting Tubes**							RE		Acft Maint Ops (5-10)	**≈29-Oct-2025**
33 A/F						Mos	24-Mar-2021				
						Hrs	13,161.4	600	+30	13,761.4	240.5 Hrs (+30)
						Ldg	8,910				
Note: A/C with P/N 18-944, 18-941-1 or 18-934-132 (SELA converters Before SB F50-335)						Flt					
33-50-00-710-804-01	**Emergency Lighting - Operational Test Of The Emergency Lighting System**							RE		Acft Maint Ops (5-10)	**≈21-Feb-2036**
33 A/F	05-10-00-3B					Mos	24-Mar-2021				
						Hrs	13,161.4	4,500	+30	(17,478.6)	3,957.7 Hrs (+30)
						Ldg	8,910				
						Flt					
33-50-00-720-801-01	**Functional Test No. 1 (113L) Emergency (Eps 1) Power Supply**							RE (A/R)			
33 A/F						Mos	30-Sep-2019				
						Hrs					
						Ldg					
						Flt					
33-50-00-720-801-02	**Functional Test No. 2 (114L1) Emergency (Eps 2) Power Supply**							RE (A/R)			
33 A/F						Mos	30-Sep-2019				
						Hrs					
						Ldg					
						Flt					
33-50-00-720-801-03	**Functional Test No. 3 (114L2) Emergency (Eps 3) Power Supply**							RE (A/R)			
33 A/F						Mos	30-Sep-2019				
						Hrs					
						Ldg					
						Flt					
33-50-33-610-801-01	**Servicing of the Emergency Power Supplies - EPS 1 (113L)**							RE (N/A)		Comp Maint Ops (5-20)	
33 A/F	No.1					Mos	12-May-2022				
NCS734-01-030						Hrs	13,232.2				
3638						Ldg	8,949				
(SOURCE: Falcon 50/50EX MPD)						Flt					
33-50-33-610-801-02	**Servicing of the Emergency Power Supplies - EPS 2 (114L1)**							RE		Comp Maint Ops (5-20)	
33 A/F	No.2					Mos	21-May-2024	12	+3%m	12-May-2025	67 Days (+10)
60-2502-1						Hrs	13,302.5				
92						Ldg	8,998				
(Tol. Adjustment: -9d) (SOURCE: Falcon 50/50EX MPD)						Flt	8,998				
Note: NOTE 101: Location and quantity of components vary with aircraft interior configuration. Refer to supplemental maintenance documentation for exact configuration of your aircraft.											
33-50-33-610-801-03	**Servicing of the Emergency Power Supplies - EPS 3 (114L2)**							RE (N/A)		Comp Maint Ops (5-20)	
33 A/F	No.3					Mos	29-Nov-2023				
D734-02-001						Hrs	13,287.4				
464						Ldg	8,989				
(SOURCE: Falcon 50/50EX MPD)						Flt	8,989				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
33-50-33-900-801-01	**Emergency Power Supply (EPS 1) (113L)**							RE (O/C)			
33 A/F	No.1					Mos	09-Aug-2021				
NCS734-01-030						Hrs					
3638						Ldg					
						Flt					
33-50-33-900-801-02	**Emergency Power Supply (EPS 2) (114L1)**							RE (O/C)			
33 A/F	No.2				14	Mos	30-Sep-2019				
60-2502-1					48.5	Hrs					
92					41	Ldg					
						Flt					
33-50-33-900-801-03	**Emergency Power Supply (EPS 3) (114L2)**							RE (O/C)			
33 A/F	No.3					Mos	29-Nov-2023				
D734-02-001	Overhauled		0			Hrs	13,287.4				
464			0			Ldg	8,989				
			0			Flt	8,989				
33-50-37-960-802-01	**Discard of the EPS Battery Packs - EPS 1 (113L) Battery Pack**							RE (N/A)		Comp Maint Ops (5-20)	
33 A/F	No.1					Mos					
NCS734-01-030						Hrs					
3638						Ldg					
(SOURCE: Falcon 50/50EX MPD)						Flt					
33-50-37-960-802-02	**Discard of the EPS Battery Packs - EPS 2 (114L1) Battery Pack**							RE (N/A)		Comp Maint Ops (5-20)	
33 A/F	No.2					Mos					
60-2502-1						Hrs					
92						Ldg					
(SOURCE: Falcon 50/50EX MPD)						Flt					
33-50-37-960-802-03	**Discard of the EPS Battery Packs - EPS 3 (114L2) Battery Pack**							RE		Comp Maint Ops (5-20)	
33 A/F	No.3					Yrs	29-Nov-2023	2		29-Nov-2025	8.9 Months
D734-02-001						Hrs	13,287.4				
464						Ldg	8,989				
(SOURCE: Falcon 50/50EX MPD)						Flt	8,989				
Note: No servicing required. The date of origin is the installation date on the aircraft.											
NOTE 101: Location and quantity of components vary with aircraft interior configuration. Refer to supplemental maintenance documentation for exact configuration of your aircraft.											
90-07-08 R1	**S.E.L.A. LABORATOIRE ABADIE (SELA) Fluorescent Lighting Lamp Connectors, Part Number (P/N) 3185-1A, and Remote Power Units (RPU), P/Ns TR 992, TR 992A, TR 992-1, TR 992-3, TR 992-4, and TR 992-5, manufactured by SELA**							RE (-)		Mandatory (Appliance AD)	
33 A/F						Mos	24-Mar-2021				
Eff: 02-Jul-1990 Not Applicable	per equipment installed					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
95-22-01	**Aerospace Lighting Corporation Power Units and Power Supplies - Fluorescent Lighting System**							RE (-)		Mandatory (Appliance AD)	
33 A/F						Mos	14-Dec-1995				
Eff: 04-Dec-1995 Not Applicable						Hrs	8,345				
(ISSUING AUTHORITY: FAA)						Ldg	5,905				
						Flt					
F50-009	**Installation of wing leading-edge ice detection lights**							RE (-)			
33 A/F						Mos					
						Hrs					
Note: M0026						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-009 R1	**Installation of wing leading-edge ice detection lights**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M0026						Flt					
F50-009 R2	**Installation of wing leading-edge ice detection lights**							T (A/R)			
33 A/F						Mos					
Eff: 19-Dec-1984						Hrs					
						Ldg					
Note: M0026						Flt					
F50-078	**Overhead panel lighting - More progressive control**							RE (-)			
33 A/F						Mos					
Eff: 12-Nov-1980						Hrs					
						Ldg					
Note: M0267						Flt					
F50-133	**New location of LH emergency battery**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M0185						Flt					
F50-133 R1	**New location of LH emergency battery**							T (A/R)			
33 A/F						Mos					
Eff: 12-Dec-1985						Hrs					
						Ldg					
Note: M0185						Flt					
F50-179	**Lighting - Cockpit lighting - New instrument lighting systems**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M0907, M0729, M0966, A/C without EFIS 86 (option 24-12-01 / M1000)						Flt					
F50-179 R1	**Lighting - Cockpit lighting - New instrument lighting systems**							T (A/R)			
33 A/F						Mos					
Eff: 28-Oct-2010						Hrs					
						Ldg					
Note: M0907, M0729, M0966, A/C without EFIS 86 (option 24-12-01 / M1000)						Flt					
F50-241	**Replacement of fin anti-collision light**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M2498, M1853						Flt					
F50-241 R1	**Replacement of fin anti-collision light**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M2498, M1853						Flt					
F50-241 R2	**Replacement of fin anti-collision light**							T (A/R)			
33 A/F						Mos					
Eff: 09-Feb-2000						Hrs					
						Ldg					
Note: M2498, M1853						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-301	**Lights-Alc Light Tube Replacement**							RE (-)		Recommended	
33 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-301-2	**ALC light tube replacement**							RE (-)			
33 A/F						Mos					
Eff: 10-Jun-1999						Hrs					
						Ldg					
Note: M2494						Flt					
F50-318	**Battery direct lighting system - Basic/optional cabin lighting routing and power supply**							RE (-)			
33 A/F						Mos	12-Oct-2010				
						Hrs					
						Ldg					
Note: M2501, AD EASA 2002-086-036 R1						Flt					
F50-318 R1	**Battery direct lighting system - Basic/optional cabin lighting routing and power supply**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M2501, AD EASA 2002-086-036 R1						Flt					
F50-318 R2	**Battery direct lighting system - Basic/optional cabin lighting routing and power supply**							T (A/R)			
33 A/F						Mos					
Eff: 14-Feb-2003						Hrs					
						Ldg					
Note: M2501, AD EASA 2002-086-036 R1						Flt					
F50-335	**Cabin and lavatory lighting - Replacement of lighting converters**							T (A/R)			
33 A/F						Mos					
Eff: 07-Nov-2001						Hrs					
						Ldg					
Note: M2674, M2065, A/C with interioir furnishings installed by DASSAULT AVIATION						Flt					
F50-338	**Wing navigation lights - Installation of dual lights**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M2327						Flt					
F50-338 R1	**Wing navigation lights - Installation of dual lights**							T (A/R)			
33 A/F						Mos					
Eff: 10-Jul-2003						Hrs					
						Ldg					
Note: M2327						Flt					
F50-365	**Cockpit lighting - Modification of the glareshield lighting dimmer**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M2679						Flt					
F50-365 R1	**Cockpit lighting - Modification of the glareshield lighting dimmer**							T (A/R)			
33 A/F						Mos					
Eff: 10-Oct-2001						Hrs					
						Ldg					
Note: M2679						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-372	**Overhead panel - Improved lighting of the air conditioning valve position indicators**							RE (-)			
33 A/F						Mos					
Eff: 16-Jan-2002						Hrs					
						Ldg					
Note: M2770						Flt					
F50-373-1	**Pylon light replacement bulb installation**							RE (-)			
33 A/F						Mos					
Eff: 06-Dec-2004						Hrs					
						Ldg					
Note: 253 to 305 with pylon lights						Flt					
F50-373-2	**Service area lighting - New light bulbs and improved wiring for the pylon lights**							RE (-)			
33 A/F						Mos					
Eff: 06-Dec-2004						Hrs					
						Ldg					
Note: M2773, 253 to 323 with M1983 and/or M2496						Flt					
F50-382	**MED lighting control switch panel assembly upgrade**							RE (-)			
33 A/F						Mos					
Eff: 12-Dec-2001						Hrs					
						Ldg					
						Flt					
F50-391	**assenger cabin lighting - Installation of improved inverters**							RE (-)			
33 A/F						Mos					
Eff: 15-May-2003						Hrs					
						Ldg					
Note: M2764						Flt					
F50-407-1	**Pylon light replacement bulb installation**							T (A/R)			
33 A/F						Mos					
Eff: 20-Nov-2003						Hrs					
						Ldg					
Note: STC SA7307SW-D, 2 to 253 with pylon lights						Flt					
F50-407-2	**RH Pylon light replacement bulb installation**							T (A/R)			
33 A/F						Mos					
Eff: 20-Nov-2003						Hrs					
						Ldg					
Note: M2904, 2 to 252 with RH pylon light as per M1827						Flt					
F50-476	**New pulse light controller of landing lights**							RE (-)			
33 A/F						Mos					
						Hrs					
						Ldg					
Note: M3010, M3200, A/C with pulse light controller PRECISE FLIGHT P/N 2400-25-4-4						Flt					
F50-476 R1	**New pulse light controller of landing lights**							T (A/R)			
33 A/F						Mos					
Eff: 20-Nov-2012						Hrs					
						Ldg					
Note: M3010, M3200, A/C with pulse light controller PRECISE FLIGHT P/N 2400-25-4-4						Flt					
F50-481	**Electrical bonding of "WHELEN" fin tip anti-collision light**							RE (-)			
33 A/F						Mos	17-Oct-2018				
						Hrs					
						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-481 R1	**Electrical bonding of "WHELEN" fin tip anti-collision light**							RE (-)			
33 A/F						Mos	31-Oct-2018				
Eff: 22-Nov-2016 Not Applicable						Hrs					
						Ldg					
Note: M3094, AD EASA 2015-0006, A/C with a "WHELEN" fin tip anti-collosion light per SB F50-241 or M1583, without Satcom fairing. FAA AD 2016-19-13						Flt					
F50-485	**New flashlight/charger assembly**							T (A/R)			
33 A/F						Mos					
Eff: 15-Jun-2006						Hrs					
						Ldg					
Note: M3023, A/C with one DME Corporation Flashlight/Charger assemblies P/N P2-07-0009-120						Flt					
F50-494	**Installing LED wing lights**							T (A/R)			
33 A/F						Mos					
Eff: 10-Aug-2007						Hrs					
						Ldg					
Note: M2795						Flt					
F50-500	**Cockpit lighting - Replacement of potentiometers P/N 319-05-1, 319-50-2, 319-100-1**							T (A/R)			
33 A/F						Mos					
Eff: 06-Aug-2012						Hrs					
						Ldg					
Note: M3204, M3216, 2 to 104 without M729 or SB F50-179						Flt					
F50-503	**Improved electrical bonding of the rear navigation and anticollision light**							RE (-)			
33 A/F						Mos					
Eff: 10-Nov-2009						Hrs					
						Ldg					
Note: M3077, 193 to 352 without M3077						Flt					
F50-538	**Lighting - Exterior Lighting - Installation of Wing LED Anti-Collision Light**							RE (-)		Optional	
33 A/F						Mos					
Eff: 02-Mar-2016						Hrs					
(AVG MAN HRS: 8)						Ldg					
						Flt					
F50-538-1	**Lighting - Exterior Lighting - Installation of LH Wing LED Anti-Collision Light**							T (-)		Optional	
33 A/F						Mos					
Eff: 02-Mar-2016						Hrs					
(AVG MAN HRS: 4)						Ldg					
						Flt					
F50-538-2	**Lighting - Exterior Lighting - Installation of RH Wing LED Anti-Collision Light**							T (-)		Optional	
33 A/F						Mos					
Eff: 02-Mar-2016						Hrs					
(AVG MAN HRS: 4)						Ldg					
						Flt					
F50-538-R1	**Lighting - Exterior Lighting - Installation of Wing LED Anti-Collision Light**							RE (-)		Optional	
33 A/F						Mos					
Eff: 26-Jan-2022						Hrs					
MOD:M2170, MOD:M2344, MOD:M2853, MOD:M3007, MOD:M3247 (AVG MAN HRS: 4)						Ldg					
						Flt					
F50-538-R1-1	**Lighting - Exterior Lighting - Installation of LH Wing LED Anti-Collision Light**							RE (-)		Optional	
33 A/F						Mos					
Eff: 26-Jan-2022						Hrs					
MOD:M2170, MOD:M2344, MOD:M2853, MOD:M3007, MOD:M3247 (AVG MAN HRS: 4)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-538-R1-2	**Lighting - Exterior Lighting - Installation of RH Wing LED Anti-Collision Light**							RE (-)		Optional	
33 A/F						Mos					
Eff: 26-Jan-2022						Hrs					
MOD:M2170, MOD:M2344, MOD:M2853, MOD:M3007, MOD:M3247 (AVG MAN HRS: 4)						Ldg					
						Flt					
F50-538-R2	**Lighting - Exterior Lighting - Installation of Wing Led Anti-Collision Light**							RE (-)		Optional	
33 A/F						Mos					
Eff: 13-Dec-2022						Hrs					
MOD:M2170, MOD:M2344, MOD:M1313, MOD:M2853, MOD:M3007, MOD:M3247 (AVG MAN HRS: 10)						Ldg					
						Flt					
F50-538-R2-1	**Lighting - Exterior Lighting - Installation of Wing Led Anti-Collision Light: Installation of LH Wing Led Anti-Collision Light**							RE (-)		Optional	
33 A/F						Mos					
Eff: 13-Dec-2022						Hrs					
(AVG MAN HRS: 4)						Ldg					
						Flt					
F50-538-R2-2	**Lighting - Exterior Lighting - Installation of Wing Led Anti-Collision Light: Installation of RH Wing Led Anti-Collision Light**							RE (-)		Optional	
33 A/F						Mos					
Eff: 13-Dec-2022						Hrs					
(AVG MAN HRS: 4)						Ldg					
						Flt					
F50-538-R2-3	**Lighting - Exterior Lighting - Installation of Wing Led Anti-Collision Light: Installation of LH Wing Led Anti-Collision Light**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 13-Dec-2022						Hrs					
(AVG MAN HRS: 6)						Ldg					
						Flt					
F50-538-R2-4	**Lighting - Exterior Lighting - Installation of Wing Led Anti-Collision Light: Installation of RH Wing Led Anti-Collision Light**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 13-Dec-2022						Hrs					
(AVG MAN HRS: 6)						Ldg					
						Flt					
F50-543	**Lighting - Exterior Lighting - Installation of LED Dome Lights**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 14-Oct-2019						Hrs					
(AVG MAN HRS: 8.5)						Ldg					
						Flt					
F50-556	**Lighting - Emergency Lighting - Installation of LED Emergency Signs (Replacement One by One)**							RE (-)		Optional	
33 A/F						Mos					
Eff: 31-Mar-2022						Hrs					
MOD:M3328						Ldg					
						Flt					
F50-556-1	**Lighting - Emergency Lighting - Installation of LED Emergency Signs (Replacement One by One) - Replacing the "Exit" Sign (118L)**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 31-Mar-2022						Hrs					
MOD:M3328 (AVG MAN HRS: 3)						Ldg					
						Flt					
F50-556-2	**Lighting - Emergency Lighting - Installation of LED Emergency Signs (Replacement One by One) - Replacing the Passenger Door Sign (116L)**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 31-Mar-2022						Hrs					
MOD:M3328 (AVG MAN HRS: 3)						Ldg					
						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-556-3	**Lighting - Emergency Lighting - Installation of LED Emergency Signs (Replacement One by One) - Replacing the "Exit" Sign (119L1)**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 31-Mar-2022						Hrs					
MOD:M3328 (AVG MAN HRS: 3)						Ldg					
						Flt					
F50-556-4	**Lighting - Emergency Lighting - Installation of LED Emergency Signs (Replacement One by One) - Replacing the "Exit" Sign (119L2)**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 31-Mar-2022						Hrs					
MOD:M3328 (AVG MAN HRS: 3)						Ldg					
						Flt					
F50-S009	**Lights - Exterior Lighting - LED Landing Lights**							T (A/R)		Optional	
33 A/F						Mos					
Eff: 14-Jun-2023						Hrs					
						Ldg					
Note: EFFECTIVITY: This Service Bulletin is applicable to F50 and F50EX aircraft with serial numbers, that are equipped with incandescent light assemblies P/N 4160818 or P/N 4240531, and not equipped with pulse box P/N 2400-25-4-4.						Flt					
▼ 34 - NAVIGATION											
	GI 275 Standby Indicator							RE (O/C)			
34 A/F						Mos	29-Sep-2023				
010-02326-31	New	0				Hrs	13,277.7				
5MZ115217		0				Ldg	8,978				
		0				Flt	8,978				
	TTD Controller							RE (O/C)			
34 A/F						Mos	29-Sep-2023				
911010-2	New	0				Hrs	13,277.7				
2084		0				Ldg	8,978				
		0				Flt	8,978				
	Accelerometer							RE (O/C)			
34 A/F	Copilot					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Accelerometer							RE (O/C)			
34 A/F	Pilot					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	ADF Antenna							RE (O/C)			
34 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	ADF Antenna							RE (O/C)			
34 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	ADF Control Unit							RE (O/C)			
34 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		ADF Control Unit							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ADF Inverter							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ADF Inverter							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ADF Receiver							RE (O/C)			
	34 A/F	No.1					Mos	24-Mar-2021				
	622-2362-001						Hrs					
	12946						Ldg					
							Flt					
		ADF Receiver							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ADF1/ADF2 Control Unit							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Aeronetics RMI							RE (O/C)			
	34 A/F	No.1					Mos	09-May-2006				
	520-3137-307						Hrs					
	8575						Ldg					
							Flt					
		Aeronetics RMI							RE (O/C)			
	34 A/F	No.2					Mos	09-May-2006				
	3137L-B-2-1-C						Hrs					
	5608						Ldg					
							Flt					
		AFIS Data Management Unit (DMU)							RE (O/C)			
	34 A/F						Mos	29-Sep-2023				
	Not Installed						Hrs	13,277.7				
	Not Installed						Ldg	8,978				
							Flt	8,978				
		AHRS, External Compensator							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		AHRS, External Compensator							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Aileron Arthur Pitot Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Aileron Arthur Static Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Air Data (ADC) Computer							RE (O/C)			
	34 A/F	Copilot					Mos	25-Aug-2009				
	822-1036-423						Hrs	12,851.1				
	17LY						Ldg					
							Flt					
		Air Data (ADC) Computer							RE (O/C)			
	34 A/F	Pilot					Mos	29-Sep-2023				
	622-5465-414	Repaired			0		Hrs	13,277.7				
	1091				0		Ldg	8,978				
					0		Flt	8,978				
		Air Data Computer Pitot Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Air Data Computer Pitot Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Air Data Computer Static Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Air Data Computer Static Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Air Data Module							RE (O/C)			
	34 A/F						Mos	24-Mar-2021				
	04077						Hrs					
	05074-104						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		AIR-NAV Computer Unit							RE (O/C)			
34 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Airshow Interface Unit							RE (O/C)			
34 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Airspeed Machmeter Indicator Hose							RE (O/C)			
34 A/F		Copilot - Left					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Airspeed Machmeter Indicator Hose							RE (O/C)			
34 A/F		Copilot - Right					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Airspeed Machmeter Indicator Hose							RE (O/C)			
34 A/F		Pilot - Left					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Airspeed Machmeter Indicator Hose							RE (O/C)			
34 A/F		Pilot - Right					Mos	29-Sep-2023				
19645L0425		New	0				Hrs	13,277.7				
N/A			0				Ldg	8,978				
			0				Flt	8,978				
		Airspeed/Mach Indicator							RE (O/C)			
34 A/F		Copilot					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Airspeed/Mach Indicator							RE (O/C)			
34 A/F		Pilot					Mos	01-Apr-2021				
33075-541							Hrs					
160							Ldg					
							Flt					
		Airspeed/Mach Indicator							RE (O/C)			
34 A/F		StandBy					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Altimeter							RE (O/C)			
34 A/F		Copilot					Mos	22-Sep-2021				
622-3975-005							Hrs					
1752							Ldg					
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Altimeter							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Altitude Alerter							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Altitude Computer							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Analog Interface Unit (Teledyne)							RE (O/C)			
	34 A/F						Mos	14-Sep-2005				
	724986-802						Hrs					
	Unknown						Ldg					
							Flt					
		Angle-Of-Attack (AOA) Sensor							RE (O/C)			
	34 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Angle-Of-Attack (AOA) Sensor							RE (O/C)			
	34 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Argus 5000 Display							RE (O/C)			
	34 A/F	No.1					Mos	09-May-2006				
	500-20-15						Hrs					
	004025						Ldg					
							Flt					
		Argus 5000 Display							RE (O/C)			
	34 A/F	No.2					Mos	09-May-2006				
	500-20-15						Hrs					
	004026						Ldg					
							Flt					
		Argus 5000 Processor							RE (O/C)			
	34 A/F	No.1					Mos	09-May-2006				
	RAA-5007-02						Hrs					
	008014						Ldg					
							Flt					
		Arguus 5000 Processor							RE (O/C)			
	34 A/F	No.2					Mos	09-May-2006				
	RAA-5007-02						Hrs					
	008013						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		ATC Antenna							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ATC Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ATC Transponder							RE (O/C)			
	34 A/F	No.1					Mos	24-Mar-2021				
	010-00736-00						Hrs					
	20S012259						Ldg					
							Flt					
		ATC Transponder							RE (O/C)			
	34 A/F	No.2					Mos	24-Mar-2021				
	010-00736-00						Hrs					
	20S012333						Ldg					
							Flt					
		ATC Transponder Control							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ATC1/ATC2 Control Panel							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		ATC1/ATC2 Inverter							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Attitude/Heading Computer							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Attitude/Heading Computer							RE (O/C)			
	34 A/F	No.2					Mos	26-Feb-2025				
	822-1378-001						Hrs	13,520.9				
	2B43F						Ldg	9,133				
							Flt	9,133				
		Attitude/Heading Computer							RE (O/C)			
	34 A/F	No.3					Mos	26-Feb-2025				
	822-1378-001						Hrs	13,520.9				
	2B43G						Ldg	9,133				
							Flt	9,133				

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Cabin Display Control							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Cabin Display Converter							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Cabin Fwd Display							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Cabin Temperature Indicator							RE (O/C)			
	34 A/F						Mos	09-Aug-2021				
	HYLZ-50514-012						Hrs					
	1249J						Ldg					
							Flt					
		Cabin Triple Indicator Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Compass Coupler							RE (O/C)			
	34 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Compass Coupler							RE (O/C)			
	34 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Compass Heading Control Box							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Compass Heading Control Box							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Computer-AHRS							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Computer-AHRS							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Configuration Module							RE (O/C)			
	34 A/F	No.1					Mos	29-Sep-2023				
	30171	New	0				Hrs	13,277.7				
	3656		0				Ldg	8,978				
			0				Flt	8,978				
		Configuration Module							RE (O/C)			
	34 A/F	No.2					Mos	29-Sep-2023				
	30171	New	0				Hrs	13,277.7				
	3663		0				Ldg	8,978				
			0				Flt	8,978				
		CONT UNS-1C Display							RE (O/C)			
	34 A/F	No.1					Mos	29-Sep-2023				
	3017-41-211	New	0				Hrs	13,277.7				
	3632		0				Ldg	8,978				
			0				Flt	8,978				
		CONT UNS-1C Display							RE (O/C)			
	34 A/F	No.2					Mos	29-Nov-2023				
	10172-41-211	Repaired				0	Hrs	13,287.4				
	3633					0	Ldg	8,989				
						0	Flt	8,989				
		Control Display (Cdu) Unit							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Copilot Display Control Panel							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Course Heading Panel							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Course Heading Panel							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Course Selector							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Course Selector							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Data Fms Transfer Unit							RE (O/C)			
	34 A/F						Mos	21-Sep-2011				
	1408-00-1						Hrs					
	Unknown						Ldg					
							Flt					
		Directional Gyro							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Directional Gyro							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Display Processor Unit (DPU)							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Display Processor Unit (DPU)							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Display Processor Unit (DPU) Blower							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Display Processor Unit (DPU) Blower							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		DME Antenna							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		DME Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		DME Transceiver							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		DME Transceiver							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Down Converter, GPS-GNSX							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Dual Cut-Off Valve							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		EFIS (AFD) Display Control Panel							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		EFIS (AFD) Display Control Panel							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		EFIS (AFD) Flight Display							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		EFIS (AFD) Flight Display							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		EFIS (AFD) Flight Display							RE (O/C)			
	34 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		EFIS (AFD) Flight Display							RE (O/C)			
	34 A/F	No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Elevator Arthur Pitot Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Elevator Arthur Static Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Emergency Altimeter Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Computer Pt2 Hose							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Computer Pt2 Hose							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Computer Pt2 Hose							RE (O/C)			
	34 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		F/D INDIC./Situation INDIC. (EADI/EHSI) Blower							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		F/D INDIC./Situation INDIC. (EADI/EHSI) Blower							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Director Computer							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Director Computer							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Flight Director Indicator							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Director Indicator							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flight Director Mode Selector							RE (O/C)			
	34 A/F	Copilot					Mos	03-Feb-2017				
	622-5224-001						Hrs					
	4250						Ldg					
							Flt					
		Flight Director Mode Selector							RE (O/C)			
	34 A/F	Pilot					Mos	03-Feb-2017				
	622-2313-068						Hrs					
	1576						Ldg					
							Flt					
		Flight Stream 110							RE (O/C)			
	34 A/F						Mos	29-Sep-2023				
	010-01194-01	New	0				Hrs	13,277.7				
	3G0001565		0				Ldg	8,978				
			0				Flt	8,978				
		FMS CDU 601.3 Software							RE (O/C)			
	34 A/F	No.1					Mos	18-Oct-1997				
	1017-41-001						Hrs	8,615.9				
	340						Ldg	6,153				
							Flt					
		FMS CDU 601.3 Software							RE (O/C)			
	34 A/F	No.2					Mos	18-Oct-1997				
	1017-41-001						Hrs	8,615.9				
	324						Ldg	6,153				
							Flt					
		FMS Computer							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		FMS Computer							RE (O/C)			
	34 A/F	No.2					Mos	19-Dec-2016				
	10172-41-111						Hrs					
	794						Ldg					
							Flt					
		FMS Computer							RE (O/C)			
	34 A/F	No.3					Mos	19-Dec-2016				
	2116-42-1116						Hrs					
	952						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		FMS Control Display Unit							RE (O/C)			
	34 A/F	No.1					Mos	05-Apr-2021				
	10172-41-111						Hrs					
	794						Ldg					
							Flt					
		FMS Control Display Unit							RE (O/C)			
	34 A/F	No.2					Mos	03-Jun-2022				
	10172-41-111	Repaired				0	Hrs	13,252.3				
	1217					0	Ldg	8,958				
							Flt					
		FMS Coupler Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Glideslope Antenna							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		GNS-XLS CDU							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		GNS-XLS CDU							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		GPS 4000A Receiver GPS Receiver							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		GPS 4000A Receiver GPS Receiver							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		GPS Antenna							RE (O/C)			
	34 A/F	No.1					Mos	24-Mar-2021				
	013-00244-00						Hrs					
	22405						Ldg					
							Flt					
		GPS Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Heading Reference System (HDG 1) Flux Valve							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Heading Reference System (HDG 2) Flux Valve							RE (O/C)			
	34 A/F	No.2					Mos	19-Sep-2018				
	622-8154-001						Hrs					
	700056						Ldg					
							Flt					
		Horizontal Situation (HSI) Indicator							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Horizontal Situation (HSI) Indicator							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Database Unit							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Environmental Control - IEC Module							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Environmental Control - IEC Module							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Flight Control Computer							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Flight Control Computer							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Flight Management Control Module							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		IAPS Flight Management Control Module							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS IOC Module							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS IOC Module							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS IOC Module							RE (O/C)			
	34 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS IOC Module							RE (O/C)			
	34 A/F	No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Maintenance Diagnostic Computer							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Optional Control Module							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Optional Control Module							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Power Supply							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Power Supply							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		IAPS Power Supply							RE (O/C)			
	34 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Power Supply							RE (O/C)			
	34 A/F	No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Strapping Unit							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IAPS Strapping Unit							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inertial Navigation Unit							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inertial Navigation Unit							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inertial Reference (IRU 1) Unit							RE (O/C)			
	34 A/F	No.1					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		Inertial Reference (IRU 2) Unit							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inertial Reference (IRU 3) Unit							RE (O/C)			
	34 A/F	No.3					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		INS Blower							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		INS Card Reader							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		INS GRND Speed Indicator							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		INS Static Inverter							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inverter-Stdby Horizon							RE (O/C)			
	34 A/F						Mos	14-Sep-2023				
	501-1240-01	Serviceable					Hrs	13,276.7				
	1249						Ldg	8,977				
							Flt	8,977				
		IRS Blower							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IRS Blower							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IRS Blower							RE (O/C)			
	34 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IRS Selector Unit							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IRS Selector Unit							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		IVA-81A Speed Indicator							RE (O/C)			
	34 A/F						Mos	03-Dec-2012				
	066-500001-1804						Hrs					
	X4011						Ldg					
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		L/G IAS Switch Pitot Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		L/G Ias Switch Static Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lightning/High Intensity Radiated Field Protector							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lightning/High Intensity Radiated Field Protector							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Longitudinal Accelerometer							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lower Display							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lower Display							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lower Static Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lower Static Hose							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Lower Tcas Antenna							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Manifold Block/Cop. S/V Hose							RE (O/C)			
	34 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Marker Antenna							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Mfd-Weather Radar							RE (O/C)			
	34 A/F						Mos	31-Aug-2015				
	6402-11011-01						Hrs					
	5719						Ldg					
							Flt					
		Mode Selector (Msu) Unit							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Multifunction Cathode Ray Tube Display (MFB) Blower							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Multifunction Display (MFD)							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Multifunction Display (MFD)							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Multifunction Display Processor Unit (MPU) Blower							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Multifunction Processor Unit (MPU)							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nav Data Interface							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Nav Data Memory Module							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		NDB2 Memory Module							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Nose Cone Actuator Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Omega Control And Display Unit							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Omega Control And Display Unit							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Omega Optional Equipment Unit							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Omega Optional Equipment Unit							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Outside Temperature Probe							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pilot Display Control Panel							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Pitot Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Pitot Hose							RE (O/C)			
34 A/F		Pilot					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Pitot Probe							RE (O/C)			
34 A/F		Left					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Pitot Probe							RE (O/C)			
34 A/F		Right					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Pressure Transmitter Hose							RE (O/C)			
34 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Proline 21 Main Relay							RE (O/C)			
34 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Pulselite Control							RE (O/C)			
34 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Pwr - 4000 Supply							RE (O/C)			
34 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Radar Indicator							RE (O/C)			
34 A/F							Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Radar Transceiver							RE (O/C)			
34 A/F							Mos	09-Aug-2021				
7021450-801							Hrs					
07117945							Ldg					
							Flt					
		Radio Altimeter Antenna							RE (O/C)			
34 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Radio Altimeter Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radio Altimeter Indicator							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radio Altimeter Indicator							RE (O/C)			
	34 A/F	No.2					Mos	30-Dec-2016				
	622-2855-001						Hrs					
	11269						Ldg					
							Flt					
		Radio Altimeter Receiver Antenna							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radio Altimeter Receiver Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radio Altimeter Receiver/Transmitter							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radio Altimeter Receiver/Transmitter							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radio Altimeter System- Analogic/Digital Converter							RE (O/C)			
	34 A/F	No.1					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		Radio Altimeter System- Analogic/Digital Converter							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radio Altimeter Transmitter Antenna							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Radio Altimeter Transmitter Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Radome Assembly							RE (O/C)			
	34 A/F						Mos	23-Sep-2015				
	F50B207						Hrs					
	166						Ldg					
							Flt					
		Rate of Climb Indicator							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rate of Climb Indicator							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rate of Climb Indicator Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rate of Climb Indicator Hose							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rate of Turn Gyro							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Reference ADC Panel							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Reference ADC Panel							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Resistance Box							RE (O/C)			
	34 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Resistance Box							RE (O/C)			
	34 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Reversion Switch Panel (RSP)							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Reversion Switch Panel (RSP)							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		RMI Indicator							RE (O/C)			
	34 A/F	Copilot					Mos	29-Sep-2023				
	3137-LB21C	Repaired				0	Hrs	13,277.7				
	5608					0	Ldg	8,978				
						0	Flt	8,978				
		RMI Indicator							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slats IAS Switch Pitot Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Slats IAS Switch Static Hose							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Solenoid Valve Center Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Solenoid Valve Center Hose							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Solenoid Valve Front Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Solenoid Valve Lower Hose							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Solenoid Valve Rear Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Solenoid Valve Upper Hose							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Stand By Altimeter							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Stand-By Compass							RE (O/C)			
	34 A/F						Mos	22-Jan-2025				
	KCA105W	Serviceable					Hrs	13,483.9				
	Unknown						Ldg	9,112				
							Flt	9,112				
		Stand-By Horizon							RE (O/C)			
	34 A/F						Mos	29-Sep-2023				
	Not Installed						Hrs	13,277.7				
	Not Installed						Ldg	8,978				
							Flt	8,978				
		Standby Horizon Battery Pack							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Static Manifold							RE (O/C)			
	34 A/F						Mos	24-Mar-2021				
	F50B781004001						Hrs					
	071109094						Ldg					
							Flt					
		Static Pressure Probe							RE (O/C)			
	34 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Static Pressure Probe							RE (O/C)			
	34 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Static Pressure Selector Valve							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Stormscope Display							RE (O/C)			
	34 A/F						Mos	09-May-2006				
	78-8060-5900-8						Hrs					
	FSDO3200241						Ldg					
							Flt					
		Stormscope Processor							RE (O/C)			
	34 A/F						Mos	09-May-2006				
	78-8060-5941-2						Hrs					
	Unknown						Ldg					
							Flt					
		TCAS Antenna							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		TCAS Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		TCAS Audio Amplifier							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		TCAS Control							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		TCAS Indicator							RE (O/C)			
	34 A/F	No.1					Mos	29-Sep-2023				
	066-50001-1804	Repaired				0	Hrs	13,277.7				
	4824					0	Ldg	8,978				
						0	Flt	8,978				
		TCAS Indicator							RE (O/C)			
	34 A/F	No.2					Mos	16-Feb-2024				
	066-01171-1804	Repaired				0	Hrs	13,292.4				
	27594					0	Ldg	8,992				
						0	Flt	8,992				
		TCAS Inverter							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		TCAS L-Band Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		TCAS Processor Unit							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		TCAS Transceiver							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Total Temperature Indicator							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Upper Display							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Upper Display							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Upper Static Hose							RE (O/C)			
	34 A/F	Copilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Upper Static Hose							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Upper Tcas Antenna							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vertical Gyro							RE (O/C)			
	34 A/F	Copilot					Mos	09-Oct-1985				
	2587335-13						Hrs					
	82033488						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Vertical Gyro							RE (O/C)			
	34 A/F	Pilot					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vlf/Om Ant Coupler							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vlf/Om Ant Coupler							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vlf/Omega Antenna							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vlf/Omega Antenna							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VLF/Omega Battery							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		VLF/Omega Battery							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vlf/Omega Receiver/ Computer							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vlf/Omega Receiver/ Computer							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vor/Ils/Mkr Receiver							RE (O/C)			
	34 A/F	No.1					Mos	18-Feb-2022				
	622-6137-201						Hrs	13,232.2				
	18398						Ldg	8,949				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Vor/Ils/Mkr Receiver							RE (O/C)			
	34 A/F	No.2					Mos	18-Feb-2022				
	622-6137-201						Hrs	13,232.2				
	18726						Ldg	8,949				
							Flt					
		Vor/Ils/Mkr Receiver							RE (O/C)			
	34 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vor/Ils/Mkr1/Dme1/Vhf1 Control							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vor/Ils/Mkr2/Dme2/Atc1/Atc2 Control							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vor/Loc Antenna							RE (O/C)			
	34 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Vor/Loc Antenna							RE (O/C)			
	34 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Weather Radar Antenna							RE (O/C)			
	34 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Weather Radar Control Panel (WXP)							RE (O/C)			
	34 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Weather Radar Control Panel (WXP)							RE (O/C)			
	34 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2001-14-51		**UPS Aviation Technologies, Inc., Model Apollo SL30 VHF NAV/COMM Radio**							RE (-)	Mandatory (Appliance AD)		
	34 A/F						Mos	14-Sep-2003				
	Eff: 30-Jul-2001 Not Applicable	by manufacturer					Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2001-15-17	**Rockwell Collins. CTL-92 - Transponder Control Panels**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	06-Dec-2002				
Eff: 20-Aug-2001 Not Applicable	PN not installed					Hrs					
						Ldg					
Brand A:9990-2001-15-17 (ISSUING AUTHORITY: FAA)						Flt					
2001-23-17	**Garmin GNS 430 units**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	14-Sep-2003				
Eff: 28-Dec-2001 Not Applicable	by manufacturer					Hrs					
						Ldg					
Brand A:9990-2001-23-17 (ISSUING AUTHORITY: FAA)						Flt					
2001-24-03	**AFM Limitations Section - Reduced Vertical Separation Minimum (RVSM)**							RE (-)		Mandatory	
34 A/F						Mos	21-Mar-2002				
Eff: 11-Dec-2001						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2002-06-05	**Mode C 621A-3 Air Traffic Control (ATC) Transponders**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	14-Sep-2003				
Eff: 26-Apr-2002 Not Applicable	By manufacturer					Hrs					
						Ldg					
(ISSUING AUTHORITY: FAA)						Flt					
2002-06-06	**Rockwell Collins TDR-94 and TDR-94D Mode S transponders**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos					
Eff: 03-May-2002 Not Applicable	PN not installed					Hrs					
						Ldg					
Brand A:9990-2002-06-06 (ISSUING AUTHORITY: FAA)						Flt					
2002-13-07	**Honeywell - Inertial Reference Units (IRU)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	06-Dec-2002				
Eff: 09-Aug-2002 Not Applicable	No IRU installed					Hrs					
						Ldg					
(ISSUING AUTHORITY: FAA)						Flt					
2002-14-19	**Rockwell Collins, Inc. ADC-85, ADC-85A, ADC-850D, and ADC-850F Air Data Computers**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	24-Mar-2021				
Eff: 23-Aug-2002 Not Applicable	By model installed					Hrs					
						Ldg					
Brand A:9990-2002-14-19 (AVG MAN HRS: 6) (APX COST: 1,040) (ISSUING AUTHORITY: FAA)						Flt					
2003-04-06	**Inspect Primus Integrated Nav Unit/Revise AFM (SUPERSEDED BY AD 2006- 22-05)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	11-Sep-2003				
Eff: 11-Mar-2003 Not Applicable	By equipment installed					Hrs					
						Ldg					
Brand A:9990-2003-04-06 (ISSUING AUTHORITY: FAA)						Flt					
2004-07-24	**Stormscope Antenna Plug Connector**							RE (-)		Mandatory	
34 A/F						Mos	24-Aug-2007				
Eff: 11-May-2004						Hrs	10,670.1				
(ISSUING AUTHORITY: FAA)						Ldg	7,474				
						Flt					
2005-11-14	**Global Positioning System (GPS)**							RE (-)		Mandatory	
34 A/F						Mos	26-Aug-2005				
Eff: 13-Jul-2005						Hrs	10,112.3				
(ISSUING AUTHORITY: FAA)						Ldg	7,133				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2005-11-14 Par. (b)	**Global Positioning System (GPS) - Airplane Flight Manual Revisions**							RE (-)		Mandatory	
34 A/F						Mos					
Eff: 13-Jul-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
Note: Applicability: Model Mystere-Falcon 50 and Model Falcon 2000 series airplanes equipped with Global Positioning/Inertial Reference System (GP/IRS) part number (P/N) HG2001-GC02, P/N HG2001- GC03, or P/N HG2001-GD03; Model Mystere-Falcon 900 and Model Falcon 900EX series airplanes equipped with GP/IRS P/N HG2001-GC03 or P/N HG2001-GD03; except those airplanes on which one of the following has been incorporated during production: Dassault Modification M2004, M3386, or M2873; certificated in any category.						Flt					
2005-11-14 Par. (c)	**Global Positioning System (GPS) - Installation of Deactivation Locking Collars**							RE (-)		Mandatory	
34 A/F						Mos					
Eff: 12-Jul-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
Note: For airplanes on which the GPS is deactivated in accordance with the applicable TC specified in paragraph (b) of this AD: Prior to further flight after deactivating the GPS, install a deactivation locking collar on each GPS 1 and GPS 2 circuit breaker. Note: This installation constitutes terminating action for the requirements of this AD for Model Falcon 2000 series airplanes that are not equipped with HUD, and for Model Mystere-Falcon 50 series airplanes.						Flt					
2005-11-14 Par. (d)	**Global Positioning System (GPS) - Wiring Modification**							RE (-)		Mandatory	
34 A/F						Mos					
Eff: 13-Jul-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
Note: For Model Falcon 2000 series airplanes equipped with HUD; for Model Falcon 900EX series airplanes; and for Model Mystere-Falcon 900 series airplanes: Within 25 months after the effective date of this AD, modify the GP/IRS wiring. After this modification has been completed, the applicable TC required by paragraph (b) of this AD may be removed from the AFM.						Flt					
2006-16-18	**Sandel Avionics Incorporated - Installing a warning placard on the TAWS/RMI**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	24-Mar-2021				
Eff: 25-Sep-2006						Hrs					
Brand A:9990-2006-16-18 (ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2006-16-18 R1	**Sandel Avionics Incorporated - Installing a warning placard on the TAWS/RMI**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	24-Mar-2021				
Eff: 18-Jul-2008						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2006-22-05	**Honeywell Primus II RNZ-850/-851 Integrated Navigation Unit (INU) - CANCELLED(SUPERCEDED BY AD 2010-07-02)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	27-Dec-2006				
Eff: 01-Dec-2006						Hrs	10,444.1				
(ISSUING AUTHORITY: FAA)						Ldg	7,331				
						Flt					
2010-07-02	**Integrated Navigation Units (INUs) - Honeywell Primus II RNZ-850( )/-851( ) (This AD supersedes AD 2006-22-05)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos					
Eff: 03-May-2010 Not Applicable	per equipment installed					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2014-18-01	**Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	23-Sep-2014				
Eff: 14-Oct-2014						Hrs	11,817.6				
Brand A:9990-2014-18-01 (AVG MAN HRS: 4) (APX COST: 85) (ISSUING AUTHORITY: FAA)						Ldg	8,178				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2015-10-51	**Avidyne Integrated Flight Display (IFD) - Navigation - Incorporate Operational Limitations into Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation.**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	08-Jul-2015				
						Hrs	12,304.1				
Brand A:9990-2015-10-51 (ISSUING AUTHORITY: FAA)						Ldg	8,439				
						Flt					
3400000	**Navigation Database Updates**							RE			
34 A/F						Days	26-Feb-2025	28		26-Mar-2025	20 Days
						Hrs	13,520.9				
Brand C:340010						Ldg	9,133				
						Flt	9,133				
34-01-00-720-801-01	**Functional Test of the EFIS System**							RE		Acft Maint Ops (5-10)	
34 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: A/C with COLLINS PROLINE 4 AVIONICS or with EFIS 86						Ldg	8,977				
						Flt	8,977				
34-01-25-710-801-07	**Operational Test of the EFIS Fans - EFIS Fans**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
34 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	14,776.7	1,255.8 Hrs (+30)
Note: A/C with COLLINS PROLINE 4 AVIONICS or with EFIS 86						Ldg	8,977				
						Flt	8,977				
34-10-00-720-801-01	**Functional Test of the Air Data System**							RE		Acft Maint Ops (5-10)	
34 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: also RVSM requirement						Ldg	8,977				
						Flt	8,977				
34-10-00-720-802-01	**Functional Test of the Air Data System Equipment - ADC 1**							RE		Comp Maint Ops (5-20)	
34 A/F 622-5465-414 1091	Pilot					Mos	29-Sep-2023	24	+3%m	29-Sep-2025	6.9 Months (+21 Days)
						Hrs	13,277.7				
						Ldg	8,978				
Note: (P/N 622-4371-012 or 622-4371-412 or 622-4371-641 or 622-5206-017 or 622-5206-413 or 622-5206-642 or 622-5465-217 or 622-5465-317 or 622-5465-414 or 622-5465-416 or 622-5465-417 or 622-5465-419 or 622-5465-643 or 622-5465-644 or 622-5465-645 or 622-8329-001 or 622-8329-017 or 622-8329-030 or 622-8329-031 or 622-8329-646 or 622-8329-647) and aircraft without SB F50-246 (RVSM capability) A/C WITHOUT COLLINS PROLINE 4 AVIONICS						Flt	8,978				
34-10-00-720-802-02	**Functional Test of the Air Data System Equipment - ADC 2**							RE		Comp Maint Ops (5-20)	
34 A/F 822-1036-423 17LY	Copilot					Mos	21-May-2024	12	+3%m	12-May-2025	67 Days (+10)
						Hrs	13,302.5				
						Ldg	8,998				
(Tol. Adjustment: -9d) Note: (P/N 622-4371-012 or 622-4371-412 or 622-4371-641 or 622-5206-017 or 622-5206-413 or 622-5206-642 or 622-5465-217 or 622-5465-317 or 622-5465-414 or 622-5465-416 or 622-5465-417 or 622-5465-419 or 622-5465-643 or 622-5465-644 or 622-5465-645 or 622-8329-001 or 622-8329-017 or 622-8329-030 or 622-8329-031 or 622-8329-646 or 622-8329-647) and aircraft with SB F50-246 (RVSM Capability) also RVSM requirement. (16) A/C WITHOUT COLLINS PROLINE 4 AVIONICS						Flt	8,998				
34-10-00-720-802-03	**Functional Test of the Air Data System Equipment - Stand-By Altimeter**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F Unknown Unknown						Mos	10-Nov-2021				
						Hrs	13,213.1				
						Ldg	8,940				
						Flt					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
34-10-00-720-802-04	**Functional Test of the Air Data System Equipment - Standby Mach Airspeed Indicator**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	StandBy					Mos	10-Nov-2021				
Unknown						Hrs	13,213.1				
Unknown						Ldg	8,940				
						Flt					
	Note: P/N 64032-29-1 A/C WITH COLLINS PROLINE 4 AVIONICS										
34-10-11-720-801-01	**Check of the Electrical Zero Setting of Angle-Of-Attack Sensors - LH AOA Sensor (52F1)**							RE (N/A)		Acft Maint Ops (5-10)	
34 A/F						Mos					
						Hrs					
	(SOURCE: Falcon 50/50EX MPD)					Ldg					
						Flt					
34-10-11-720-801-02	**Check of the Electrical Zero Setting of Angle-Of-Attack Sensors - RH AOA Sensor (52F2)**							RE (N/A)		Acft Maint Ops (5-10)	
34 A/F						Mos					
						Hrs					
	(SOURCE: Falcon 50/50EX MPD)					Ldg					
						Flt					
34-11-00-680-801-01	**Draining of the Total / Static Pressure System**							RE		Acft Maint Ops (5-10)	
34 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)					Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
34-11-00-790-801-02	**Leak Test Pilot Total Air Pressure System**							RE (A/R)			
34 A/F						Mos	16-Sep-2018				
						Hrs					
						Ldg					
						Flt					
34-11-00-790-801-03	**Leak Test Copilot Static Air Pressure System**							RE (A/R)			
34 A/F						Mos	16-Feb-2024				
						Hrs	13,292.4				
						Ldg	8,992				
						Flt	8,992				
34-11-00-790-801-04	**Leak Test Copilot Total Air Pressure System**							RE (A/R)			
34 A/F						Mos	16-Feb-2024				
						Hrs	13,292.4				
						Ldg	8,992				
						Flt	8,992				
34-11-00-790-801-05	**Leak Test Stand-By Static Air Pressure System**							RE (A/R)			
34 A/F						Mos	16-Sep-2018				
						Hrs					
						Ldg					
						Flt					
34-11-01-200-801-01	**Check of the Total Pressure Probe Drain Holes For Clogging - LH Total Pressure Probe (14F1)**							RE		Acft Maint Ops (5-10)	**≈13-Aug-2025**
34 A/F						Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
						Hrs	13,386.3	300	+30	13,686.3	165.4 Hrs (+30)
	Note: Removed tolerance adjustment per Steve Betts email, 5/23/2024. DRD					Ldg	9,044				
						Flt	9,043				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
34-11-01-200-801-02	**Check of the Total Pressure Probe Drain Holes For Clogging - RH Total Pressure Probe (14F2)**							RE		Acft Maint Ops (5-10)	**≈13-Aug-2025**
34 A/F						Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
						Hrs	13,386.3	300	+30	13,686.3	165.4 Hrs (+30)
Note: Removed tolerance adjustment per Steve Betts email, 5/23/2024. DRD						Ldg	9,044				
						Flt	9,043				
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Aileron Arthur Pitot Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Aileron Arthur Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Air Data Computer Pitot Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Air Data Computer Pitot Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Copilot					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Air Data Computer Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F						Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Air Data Computer Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Copilot					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Airspeed Machmeter Indicator Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Copilot - Left					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Airspeed Machmeter Indicator Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Copilot - Right					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
34-11-07-960-801-01	**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Airspeed Machmeter Indicator Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Pilot - Left					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Airspeed Machmeter Indicator Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	19645L0425	Pilot - Right					Mos					
	N/A						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Cabin Triple Indicator Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown						Mos					
	Unknown						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Elevator Arthur Pitot Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown						Mos					
	Unknown						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Elevator Arthur Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown						Mos					
	Unknown						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Emergency Altimeter Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown						Mos					
	Unknown						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Engine Fuel Computer Pt2 Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown	No.1					Mos					
	Unknown						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Engine Fuel Computer Pt2 Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown	No.2					Mos					
	Unknown						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Engine Fuel Computer Pt2 Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown	No.3					Mos					
	Unknown						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (L/G IAS Switch Pitot Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown						Mos					
	Unknown						Hrs					
							Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (L/G Ias Switch Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	Unknown						Mos					
	Unknown						Hrs					
							Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Lower Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Copilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Lower Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Pilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Manifold Block/Cop. S/V Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Right					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Nose Cone Actuator Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F						Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Pitot Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Copilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Pitot Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Pilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Pressure Transmitter Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F						Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Rate of Climb Indicator Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Copilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Rate of Climb Indicator Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Pilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Slats IAS Switch Pitot Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F						Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Slats IAS Switch Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F						Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Solenoid Valve Center Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Copilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Solenoid Valve Center Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Pilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Solenoid Valve Front Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Copilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Solenoid Valve Lower Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Pilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Solenoid Valve Rear Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Copilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Solenoid Valve Upper Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Pilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Upper Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Copilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
34-11-07-960-801-01		**Discard of the Elastomer Hoses Installed on Total and Static Pressure Lines (Upper Static Hose)**							RE (N/A)		Comp Maint Ops (5-20)	
	34 A/F	Pilot					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
342077		**Annunciator**							RE (O/C)			
	34 A/F	Pilot					Mos	15-Apr-2005				
	MD41-1308						Hrs					
	K04-11222						Ldg					
							Flt					

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
34-21-13-100-801-01	**Cleaning / Replacement of the IRU Fan Filters - IRU 1 Fan Filter**							RE (N/A)		Acft Maint Ops (5-10)	
34 A/F						Mos					
						Hrs					
						Ldg					
Note: IRS not installed						Flt					
34-21-13-100-801-02	**Cleaning / Replacement of the IRU Fan Filters - IRU 2 Fan Filter**							RE (N/A)		Acft Maint Ops (5-10)	
34 A/F						Mos					
						Hrs					
						Ldg					
Note: IRS not installed						Flt					
34-21-13-100-801-03	**Cleaning / Replacement of the IRU Fan Filters - IRU 3 Fan Filter**							RE (N/A)		Acft Maint Ops (5-10)	
34 A/F						Mos					
						Hrs					
						Ldg					
Note: IRS not installed						Flt					
34-22-00-710-801-01	**Operational Test of the Attitude and Heading Reference System (AHRS)**							RE (N/A)		Acft Maint Ops (5-10)	
34 A/F						Mos					
						Hrs					
						Ldg					
Note: AHRS (option) and COLLINS PROLINE 4 AVIONICS not installed						Flt					
342237	**Rate Of Turn Gyro**							RE (O/C)			
34 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
342850	**ICA for Collins AHS-3000A GVI**							RE		ICA	**≈26-Dec-2026**
34 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6	1,200		14,178.6	657.7 Hrs
						Ldg	8,785				
						Flt					
34-42-00-710-801-01	**Operational Test of the Radio Altimeter System - Radio Altimeter 1 System**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	No.1					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
Note: Not CAT II operations											
34-42-00-710-801-02	**Operational Test of the Radio Altimeter System - Radio Altimeter 2 System**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F	No.2					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
Note: Not CAT II operations											
344211	**GPS Sensor**							RE (O/C)			
34 A/F						Mos	24-Aug-2005				
453-0505						Hrs					
0190707						Ldg					
						Flt					
345001	**ICA Garmin GX3000 Equipment GVI**							RE		ICA	
34 A/F						Mos	30-Aug-2024	12	-/+2m	13-Sep-2025	6.4 Months (+61 Days)
(Tol. Adjustment: 14d)						Hrs	13,386.3				
Note: Removed tolerance adjustment per Steve Betts email, 5/23/2024. DRD						Ldg	9,044				
						Flt	9,043				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
345002		**ICA Garmin GX3000 Electrical Bonding**							RE		ICA	**≈17-Sep-2029**
34 A/F							Yrs	24-Mar-2021	10		24-Mar-2031	6.1 Years
							Hrs	13,161.4	2,000		15,161.4	1,640.5 Hrs
							Ldg	8,910				
							Flt					
3450071		**Nav Receiver**							RE (O/C)			
34 A/F		No.1					Mos	24-Aug-2005				
453-1055-00							Hrs					
140532							Ldg					
							Flt					
3450072		**Nav Receiver**							RE (O/C)			
34 A/F		No.2					Mos	05-Sep-2018				
622-6137-201							Hrs					
4792							Ldg					
							Flt					
34-51-01-820-801-01		**Calibration of the Vor / Ils / Marker Receivers - Vor/Ils/Marker 1 Receiver (L210NR) / (12RS)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F		No.1					Mos					
622-6137-201							Hrs					
18398							Ldg					
							Flt					
Note: Not CAT II operations												
34-51-01-820-801-02		**Calibration of the Vor / Ils / Marker Receivers - Vor/Ils/Marker 2 Receiver (R210NR) / (22RS)**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F		No.2					Mos					
622-6137-201							Hrs					
18726							Ldg					
							Flt					
Note: Not CAT II operations												
34-54-00-720-802-01		**Functional Test of the Air Traffic Control (ATC) System - ATC 1 System Periodic Tests**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F		No.1					Mos					
010-00736-00							Hrs					
20S012259							Ldg					
							Flt					
34-54-00-720-802-02		**Functional Test of the Air Traffic Control (ATC) System - ATC 2 System Periodic Tests**							RE (N/A)		Comp Maint Ops (5-20)	
34 A/F		No.2					Mos					
010-00736-00							Hrs					
20S012333							Ldg					
							Flt					
346819		**FMS Interface Unit**							RE (O/C)			
34 A/F		No.2					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
347872		**Tcas L-Band Antenna**							RE (O/C)			
34 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
347893		**ICA Allied Signal TCAS Upper L-Band Antenna(s) Inspect**							RE		ICA	**≈10-Feb-2077**
34 A/F							Mos	12-May-2010				
							Hrs	11,245				
							Ldg	7,850	20,000		27,850	18,717 Ldg
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
347894	**ICA Allied Signal TCAS Upper Directional Antenna Inspect**							RE		ICA	**≈07-Jul-2053**
34 A/F						Mos	12-May-2010				
						Hrs	11,245				
						Ldg	7,850	11,500		19,350	10,217 Ldg
						Flt					
347895	**ICA Allied Signal TCAS Lower Antenna(s)**							RE		ICA	**≈30-Dec-2046**
34 A/F						Mos					
						Hrs					
						Ldg		17,000		17,000	7,867 Ldg
						Flt					
530810	**ICA AHRS Structural/Wiring**							RE		ICA	
34 A/F						Mos	14-Sep-2023	72		14-Sep-2029	4.5 Years
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
86-22-10	**Distance Measuring Equipment**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos	24-Mar-2021				
Eff: 17-Nov-1986 Not Applicable	per equipment installed					Hrs					
						Ldg					
(ISSUING AUTHORITY: FAA)						Flt					
86-25-01	**Navigation Receivers**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos					
Eff: 06-Jan-1987 Not Applicable	Per PN installed					Hrs					
						Ldg					
(ISSUING AUTHORITY: FAA)						Flt					
87-16-07	**(HONEYWELL, INC., SPERRY COMMERCIAL FLIGHT SYSTEMS DIVISION (formerly Sperry Corporation, Aerospace and Marine Group) - Electronic Flight Instrument Systems**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos	11-Sep-2003				
Eff: 20-Aug-1987 Not Applicable	Not installed					Hrs					
						Ldg					
(ISSUING AUTHORITY: FAA)						Flt					
89-02-10 R1	**Flight Management System Navigation Computers**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos	24-Mar-2021				
Eff: 14-Oct-1989 Not Applicable	per equipment installed					Hrs					
						Ldg					
(ISSUING AUTHORITY: FAA)						Flt					
89-20-06	**Flight Management Systems**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos	24-Mar-2021				
Eff: 10-Oct-1989 Not Applicable	By manufacture					Hrs					
						Ldg					
(ISSUING AUTHORITY: FAA)						Flt					
93-04-02	**ROCKWELL INTERNATIONAL/COLLINS AVIATION DIVISION TDR-94D Mode S Transponders, P/N CPN 622-9210-002**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos	11-Apr-1993				
						Hrs	7,891				
(ISSUING AUTHORITY: FAA)						Ldg	5,457				
						Flt					
94-01-04	**Honeywell - Traffic Alert And Collision Avoidance System (TCAS) II**							RE (-)	Mandatory (Appliance AD)		
34 A/F						Mos	24-Mar-2021				
Eff: 04-Feb-1994						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
94-01-06	**Rockwell Collins - Traffic Alert and Collision Avoidance System II Processors**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Days	24-Mar-2021				
Eff: 04-Feb-1994 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
97-05-03	**AlliedSignal Avionics, Inc. Models GNS-XLS and GNS-XL Flight Management Systems (SUPERSEDED BY FAA AD 97-05-03 R1)**							RE (-)		Mandatory (Appliance AD)	
34 A/F						Mos	23-Mar-1999				
Eff: 14-Mar-1997 Complied With						Hrs	8,767.8				
(ISSUING AUTHORITY: FAA)						Ldg	6,294				
						Flt					
97-05-03 R1	**AlliedSignal Avionics, Inc. Models GNS-XLS and GNS-XL Flight Management Systems**							T (A/R)		Mandatory (Appliance AD)	
34 A/F						Mos	11-Sep-2003				
Eff: 20-Apr-1999 Not Applicable	No GSN-XLS and GSN-XL installed in aircraft					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
99-23-22 R2	**Mode C Transponder(s) with Single Gillham Code Altitude Input**							T (A/R)		Mandatory (Appliance AD)	
34 A/F						Mos	01-Dec-1999				
Eff: 20-Apr-2000 Not Applicable	as transponder PN 066-01143-0601 installed in both #1 and #2 position.					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
F50-011	**RH air data system - VMO/MMO warning detection added**							T (A/R)			
34 A/F						Mos					
Eff: 28-Dec-1982						Hrs					
						Ldg					
Note: M0380						Flt					
F50-039	**New coaxial cable routings in the vicinity of engine 2 S-duct**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M0162						Flt					
F50-039 R1	**New coaxial cable routings in the vicinity of engine 2 S-duct**							RE (-)			
34 A/F						Mos					
Eff: 30-Oct-1980						Hrs					
						Ldg					
Note: M0162						Flt					
F50-083	**ADC - Structure ground deleted in the IAS computation channel**							RE (-)			
34 A/F						Mos					
Eff: 12-Nov-1980						Hrs					
						Ldg					
Note: M0647						Flt					
F50-157	**Copilot pitot/static system - New routing of pitot lines**							T (A/R)			
34 A/F						Mos					
Eff: 18-Oct-1984						Hrs					
						Ldg					
Note: M1176B, M1176A						Flt					
F50-167	**Stand-by horizon - Back-up power supply test**							T (A/R)			
34 A/F						Mos					
Eff: 28-Aug-1986						Hrs					
						Ldg					
Note: M0196						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-197 R1-Alert	**Total pressure probes with increased anti-icing**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M1500						Flt					
F50-197 R2-Alert	**Total pressure probes with increased anti-icing**							T (A/R)			
34 A/F						Mos					
Eff: 25-Jan-1989						Hrs					
						Ldg					
Note: M1500						Flt					
F50-197-Alert	**Total pressure probes with increased anti-icing**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M1500						Flt					
F50-246	**Navigation - Reduced vertical separation minimum (RVSM) capability**							RE (-)			
34 A/F						Mos	09-Sep-2015				
Complied With						Hrs					
						Ldg					
Note: M2210						Flt					
F50-246 R1	**Navigation - Reduced vertical separation minimum (RVSM) capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2210						Flt					
F50-246 R2	**Navigation - Reduced vertical separation minimum (RVSM) capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2210						Flt					
F50-246 R3	**Navigation - Reduced vertical separation minimum (RVSM) capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2210						Flt					
F50-246 R4	**Navigation - Reduced vertical separation minimum (RVSM) capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2210						Flt					
F50-246 R5	**Navigation - Reduced vertical separation minimum (RVSM) capability**							T (-)			
34 A/F						Mos					
Eff: 15-Oct-2012						Hrs					
						Ldg					
Note: M2210						Flt					
F50-246-R6	**Navigation - Reduced Vertical Separation Minimum (RVSM) Capability**							T (-)		Optional	
34 A/F						Mos					
Eff: 23-Nov-2015						Hrs					
						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-254	**GNSX - Removal of power supply from standby batteries**							T (A/R)			
34 A/F						Mos					
Eff: 07-May-1997						Hrs					
						Ldg					
Note: M1895, with FMS GNSX						Flt					
F50-262	**ADC - New static source error correction (SSEC) module for RVSM capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M1829, M2159, A/C with ADC COLLINS type ADC80G or ADC80J (M0104) or ADC80K (M0716 or M0788) or ADC82C (M0788 or M1496) or ROCKWELL type ADC850F (M1890 or M1924)						Flt					
F50-262 R1	**ADC - New static source error correction (SSEC) module for RVSM capability**							T (A/R)			
34 A/F						Mos					
Eff: 24-Jun-1998						Hrs					
						Ldg					
Note: M1829, M2159, A/C with ADC COLLINS type ADC80G or ADC80J (M0104) or ADC80K (M0716 or M0788) or ADC82C (M0788 or M1496) or ROCKWELL type ADC850F (M1890 or M1924)						Flt					
F50-279	**EFD, IOC, DCP, MDC and FCC - Version 5.1 COLLINS avionics**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2151, M2236, M2301, with COLLINS V4 avionics (M1890 or M1924)						Flt					
F50-279 R1	**EFD, IOC, DCP, MDC and FCC - Version 5.1 COLLINS avionics**							RE (-)			
34 A/F						Mos					
Eff: 25-Mar-1998						Hrs					
						Ldg					
Note: M2151, M2236, M2301, with COLLINS V4 avionics (M1890 or M1924)						Flt					
F50-300	**HONEYWELL HG2001GC03 IRS with new software**							RE (-)			
34 A/F						Mos					
Eff: 01-Jul-1999						Hrs					
						Ldg					
Note: M2410, 251 to 276 with HONEYWELL HG2001GC02 IRS						Flt					
F50-304	**Antenna corrosion inspection**							T (A/R)			
34 A/F						Mos					
Eff: 14-Nov-2001						Hrs					
						Ldg					
						Flt					
F50-306	**IAPS - Interchange of "MDC" and "FAN" circuit breakers**							RE (-)			
34 A/F						Mos					
Eff: 15-Oct-1999						Hrs					
						Ldg					
Note: M2452, 251, 253 to 278 with avionics version < V6 and with M2392						Flt					
F50-307	**New software NZ 4.5 C for the Honeywell flight management system (FMZ 2000)**							RE (-)			
34 A/F						Mos					
Eff: 30-Sep-1998						Hrs					
						Ldg					
Note: M2371, 251, 253 to 352 with avionics V5.1 and 2 FMS FMZ 2000 (M2155) software NZ 4.5						Flt					
F50-308	**New GNS X/ES global FMS computers 17450-0307-0606 with new SM01 software**							RE (-)			
34 A/F						Mos					
Eff: 06-Dec-1999						Hrs					
						Ldg					
Note: M2280, M1973, 251, 253 to 352 with GNS X/ES GLOBAL FMS computers (with built to in GPS) through M1973						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-309	**Software version 602.4 for the universal UNS1C FMS**							RE (-)			
34 A/F						Mos					
Eff: 28-Oct-1998						Hrs					
						Ldg					
Note: M2370, 251, 253 to 352 with avionics V5.1 and with 2 UNIVERSAL UNS1C FMS with built to in 12 - channel GPS (M2244) software 601.2						Flt					
F50-329	**Honeywell FMS (FMZ 2000) - NZ 5.1 software**							RE (-)			
34 A/F						Mos					
Eff: 02-Oct-2006						Hrs					
						Ldg					
Note: M2549, 251, 253 to 352 with avionics V5.1 and with 2 HONEYWELL FMS FMZ 2000 P/N 7018879-02010						Flt					
F50-350	**ADC - Collins 850F version V6.2 ADC**							T (A/R)			
34 A/F						Mos					
Eff: 13-Jun-2001						Hrs					
						Ldg					
Note: M2637, A/C with COLLINS 850 ADC P/N 822-1036-406						Flt					
F50-353	**FMS Collins 6100 - FMS 99 STEP 2 (Minor 3)**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2689, M2759, M2812, 279 to 352 with M2503, M2540, M2505, M2506						Flt					
F50-353 R1	**FMS Collins 6100 - FMS 99 STEP 2 (Minor 3)**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2689, M2759, M2812, 279 to 352 with M2503, M2540, M2505, M2506						Flt					
F50-353 R2	**FMS Collins 6100 - FMS 99 STEP 2 (Minor 3)**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2689, M2759, M2812, 279 to 352 with M2503, M2540, M2505, M2506						Flt					
F50-353 R3	**FMS Collins 6100 - FMS 99 STEP 2 (Minor 3)**							RE (-)			
34 A/F						Mos					
Eff: 10-Jul-2002						Hrs					
						Ldg					
Note: M2689, M2759, M2812, 279 to 352 with M2503, M2540, M2505, M2506						Flt					
F50-364	**IRS blowers - Protection of power supply lines by fuses**							T (A/R)			
34 A/F						Mos					
Eff: 05-Dec-2001						Hrs					
						Ldg					
Note: M2706, A/C with IRS with computers cooled by Honeywell blowers P/N 10089782-103 (M1080 or M1342 or M1442) or 10089782-105 (M1080 or M1342 or M1442 or M1067) or 26006089-102 (M1800)						Flt					
F50-368	**FMS COLLINS-6000 - FMS 00 MINOR 1**							T (A/R)			
34 A/F						Mos					
Eff: 05-Nov-2003						Hrs					
						Ldg					
Note: M2802, M2719, A/C with dual COLLINS FMS (M2503, M2540, M2689, M2685, M2812) and A/C with 3rd COLLINS FMS (M2685, M2812)						Flt					
F50-387	**Static probes - New installation procedure**							RE (-)			
34 A/F						Mos					
Eff: 10-Apr-2002						Hrs					
						Ldg					
Note: M2817						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-388	**AHS Reversion**							T (A/R)			
34 A/F						Mos					
Eff: 15-May-2002						Hrs					
						Ldg					
Note: M2813, A/C with COLLINS Proline 4 and 2 AHS but without a third AHS source						Flt					
F50-389	**Installation of MEGGITT MK I P/N 33509-10-05**							RE (-)			
34 A/F						Mos					
Eff: 15-May-2002						Hrs					
						Ldg					
Note: M2814, 285, 292 to 313 with M2431						Flt					
F50-394	**Collins ADC-850F with Collins Proline 4 avionics version 5 - Improvement of calibration and RVSM performance**							T (A/R)			
34 A/F						Mos					
Eff: 12-Jun-2002						Hrs					
						Ldg					
Note: M2818, A/C with COLLINS Proline 4 V5 (251 to 278) and 2 ADCs P/N 822-1036-141 (M2159 or SB F50-262)						Flt					
F50-400	**ADC - New SSEC module "Y36" for RVSM capability**							T (A/R)			
34 A/F						Mos					
Eff: 10-Dec-2003						Hrs					
						Ldg					
Note: M2840, 2 to 328 with the ADCs COLLINS Type ADC80G or ADC80J or ADC80K or ADC82C or ADC850F or HONEYWELL type AZ-800						Flt					
F50-400 R1	**ADC - New SSEC module "Y36" for RVSM capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2840, 2 to 328 with the ADCs COLLINS Type ADC80G or ADC80J or ADC80K or ADC82C or ADC850F or HONEYWELL type AZ-800						Flt					
F50-400 R2	**ADC - New SSEC module "Y36" for RVSM capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2840, 2 to 328 with the ADCs COLLINS Type ADC80G or ADC80J or ADC80K or ADC82C or ADC850F or HONEYWELL type AZ-800						Flt					
F50-400 R3	**ADC - New SSEC module "Y36" for RVSM capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2840, 2 to 328 with the ADCs COLLINS Type ADC80G or ADC80J or ADC80K or ADC82C or ADC850F or HONEYWELL type AZ-800						Flt					
F50-400 R4	**ADC - New SSEC module "Y36" for RVSM capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2840, 2 to 328 with the ADCs COLLINS Type ADC80G or ADC80J or ADC80K or ADC82C or ADC850F or HONEYWELL type AZ-800						Flt					
F50-400 R5	**ADC - New SSEC module "Y36" for RVSM capability**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2840, 2 to 328 with the ADCs COLLINS Type ADC80G or ADC80J or ADC80K or ADC82C or ADC850F or HONEYWELL type AZ-800						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-400 R6	**ADC - New SSEC module "Y36" for RVSM capability**							T (A/R)			
34 A/F						Mos					
Eff: 10-Dec-2003						Hrs					
						Ldg					
Note: M2840, 2 to 328 with the ADCs COLLINS Type ADC80G or ADC80J or ADC80K or ADC82C or ADC850F or HONEYWELL type AZ-800						Flt					
F50-403	**Collins ADC-850F with Collins Proline 4 avionics version 6 - Improvement of RVSM performance**							T (A/R)			
34 A/F						Mos					
Eff: 12-Jun-2002						Hrs					
						Ldg					
Note: M2750, A/C with COLLINS PROLINE 4 V6 and 2 ADCs P/N 822-1036-423 + SB62						Flt					
F50-410	**Installation of MKII mod 1 and mod 2 MEGGITT SFD**							T (A/R)			
34 A/F						Mos					
Eff: 10-Apr-2003						Hrs					
						Ldg					
Note: M2848, A/C with MEGGITT MK II MOD 1 SFD (M2778)						Flt					
F50-416	**IRS - GPS/IRS hybrid data inhibit**							T (A/R)			
34 A/F						Mos					
Eff: 04-Nov-2003						Hrs					
						Ldg					
Note: M2873, 2 to 330 with COLLINS Avionics Proline 4 V5 or V6.						Flt					
F50-424	**GPS deactivation**							T (A/R)			
34 A/F						Mos					
Eff: 04-Nov-2003						Hrs					
						Ldg					
Note: AD EASA 2003-409 (AD FAA 2005-11-14), 2 to 330 with COLLINS Proline 4 V5 or V6 until compliance with SBF50-416 on applicable A/C						Flt					
F50-431	**ATC with Flight ID**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2879, M2953, A/C with COLLINS Avionics V5.1 & subsequent (SB F50-279 or M2151, M2236, M2301) and V6.X (M2387)						Flt					
F50-431 R1	**ATC with Flight ID**							T (A/R)			
34 A/F						Mos					
Eff: 14-Sep-2004						Hrs					
						Ldg					
Note: M2879, M2953, A/C with COLLINS Avionics V5.1 & subsequent (SB F50-279 or M2151, M2236, M2301) and V6.X (M2387)						Flt					
F50-433	**FMS COLLINS-6000 - FMS 2.2.0.1**							T (A/R)			
34 A/F						Mos					
Eff: 10-Feb-2005						Hrs					
						Ldg					
Note: M2900, M2914, A/C with COLLINS Dual FMS (M2503, M2540, 2719) or 3rd FMS (M2802)						Flt					
F50-457	**ATC with Enhanced surveillance**							RE (-)			
34 A/F						Mos					
						Hrs					
						Ldg					
Note: M2970, M2968, M2966, AD EASA 2010-0003R2 (AD FAA 2014-18-01), 251, 253 to 352 with COLLINS Proline 4 V5.X or V6.X and ATCs TDR to 94D P/N 622-9210-007, RTUs 4220 P/N 822-0730-334, IOC 4000 P/N 622-9814-605 (V5) & IOC 4000 P/N 622-9814-632 (V6)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-457 R1	**ATC with Enhanced surveillance**							RE (-)			
34 A/F						Mos					
Eff: 22-Dec-2006						Hrs					
						Ldg					
Note: M2970, M2968, M2966, AD EASA 2010-0003R2 (AD FAA 2014-18-01), 251, 253 to 352 with COLLINS Proline 4 V5.X or V6.X and ATCs TDR to 94D P/N 622-9210-007, RTUs 4220 P/N 822-0730-334, IOC 4000 P/N 622-9814-605 (V5) & IOC 4000 P/N 622-9814-632 (V6)						Flt					
F50-465	**FMS COLLINS-6000 - FMS 2.2.2**							T (A/R)			
34 A/F						Mos					
Eff: 09-Mar-2006						Hrs					
						Ldg					
Note: M2950, M2951, A/C with COLLINS Dual FMS (M2503, M2540, 2900) or 3rd FMS (M2914)						Flt					
F50-469	**ATC reply inhibit on ground**							RE (-)			
34 A/F						Mos					
Eff: 10-May-2006						Hrs					
						Ldg					
Note: M2998, AD EASA 2010-0067, 251, 253 to 352 without M2998 & with COLLINS avionics V5.X or V6.X and TDR to 94D ATCs P/N 622-9210-004 (M2147) or P/N 622-9210-007 (SB F50-431 or M2879).						Flt					
F50-477	**ATC - Extended Squitter function inhibit**							RE (-)			
34 A/F						Mos					
Eff: 10-May-2006						Hrs					
						Ldg					
Note: M3011						Flt					
F50-489	**Secondary Flight Display - MEGGITT MK II installation**							RE (-)			
34 A/F						Mos					
Eff: 07-Feb-2007						Hrs					
						Ldg					
Note: M2667, M2848, M3013, 285 to 313 equipped with stand to by instruments systems MEGGITT Mark I						Flt					
F50-490	**ATC - Altitude reversion correction**							RE (-)			
34 A/F						Mos					
Eff: 08-Mar-2007						Hrs					
						Ldg					
Note: M3076, 251, 253 to 352 with RTU-4020						Flt					
F50-532	**EFIS cooling system - Obsolescence of COMAIR ROTRON fan P/N 031048**							RE (-)			
34 A/F						Mos					
Eff: 02-Apr-2014						Hrs					
						Ldg					
Note: M3217,5, 7, 27, 30, 34, 36, 78, 132, 251 to 352 and A/C with SB F50-280						Flt					
F50-S004	**ADS-B out (DO 260A) Installation**							T (A/R)			
34 A/F						Mos					
Eff: 23-Mar-2015						Hrs					
						Ldg					
Note: STC ST02963NY-D, A/C with Collins Pro Line 4 or Pro Line 21 equipped with transponders TDR-94 P/N 622-9210-008						Flt					
F50-S007	**Navigation - ADS-B Out (DO 260B) Installation**							T (-)			
34 A/F						Mos					
Eff: 05-Feb-2018						Hrs					
(AVG MAN HRS: 300)						Ldg					
Note: EFFECTIVITY: Aircraft with Rockwell Collins Transponders TDR-94D (P/N 622-9210-409 or 622-9210-008).						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-S007-R1	**Navigation - ADS-B OUT (DO 260B) Installation**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 11-Mar-2019						Hrs					
(AVG MAN HRS: 300)						Ldg					
Note: EFFECTIVITY: Aircraft equipped with Rockwell Collins (Pro Line 4 or Pro Line 21) and with Rockwell Collins Transponders TDR-94D (P/N 622-9210-409 or 622-9210-008). Implementation of Rockwell Collins GPS 4000S and Sensor System Antennas per the Rockwell Collins' STC ST01433WI-D or ST01833WI is a pre-requisite.						Flt					
F50-S024	**Navigation - Honeywell Laseref Upgrade**							T (A/R)		Optional	
34 A/F						Mos					
Eff: 09-Oct-2020						Hrs					
						Ldg					
						Flt					
F50-S032	**Navigation - Collins Pro Line 21 LCD Displays Replacement**							RE (-)		Optional	
34 A/F						Mos					
Eff: 31-Jan-2021						Hrs					
						Ldg					
						Flt					
F50-S032-R1	**Navigation - Collins Pro Line 21 LCD Displays Replacement**							RE (-)		Optional	
34 A/F						Mos					
Eff: 18-Feb-2022						Hrs					
						Ldg					
						Flt					
F50-S032-R2	**Navigation - Collins Pro Line 21 LCD Displays Replacement**							RE (-)		Optional	
34 A/F						Mos					
Eff: 07-Nov-2022						Hrs					
						Ldg					
						Flt					
FAR 91.411	**Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43**							RE		FAR91, FAR 91	
34 A/F	Copilot					Mos	14-Sep-2023	24		30-Sep-2025	6.9 Months
822-1036-423						Hrs	13,276.7				
17LY						Ldg	8,977				
Inspected Date 14-Sep-2023						Flt	8,977				
(ISSUING AUTHORITY: FAA)											
FAR 91.411	**Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43**							RE		FAR91, FAR 91	
34 A/F	Pilot					Mos	29-Sep-2023	24		30-Sep-2025	6.9 Months
622-5465-414						Hrs	13,277.7				
1091						Ldg	8,978				
Inspected Date 29-Sep-2023						Flt	8,978				
(ISSUING AUTHORITY: FAA)											
FAR 91.411	**Altimeter Standby Indicator tests and inspections per FAR 91.411**							RE		FAR91, FAR 91	
34 A/F						Mos	14-Sep-2023	24		30-Sep-2025	6.9 Months
Unknown						Hrs	13,276.7				
Unknown						Ldg	8,977				
(ISSUING AUTHORITY: FAA)						Flt	8,977				
FAR 91.411	**Altimeter test and inspect per FAR 91.411 Appendix E part 43**							RE		FAR91, FAR 91	
34 A/F	Copilot					Mos	14-Sep-2023	24		30-Sep-2025	6.9 Months
622-3975-005						Hrs	13,276.7				
1752						Ldg	8,977				
Inspected Date 14-Sep-2023						Flt	8,977				
(ISSUING AUTHORITY: FAA)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
FAR 91.411	**Altimeter test and inspect per FAR 91.411 Appendix E part 43**							RE		FAR91, FAR 91	
34 A/F	Pilot					Mos	14-Sep-2023	24		30-Sep-2025	6.9 Months
Unknown						Hrs	13,276.7				
Unknown						Ldg	8,977				
Inspected Date 14-Sep-2023						Flt	8,977				
(ISSUING AUTHORITY: FAA)											
FAR 91.411	**Standby Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43**							RE (N/A)		FAR91	
34 A/F						Mos	24-Mar-2021				
24-Mar-2021						Hrs	13,161.4				
						Ldg	8,910				
						Flt					
FAR 91.413	**ATC Transponder test and inspections per FAR 91.413 Appendix F of Part 43**							RE		FAR91, FAR 91	
34 A/F	No.2					Mos	14-Sep-2023	24		30-Sep-2025	6.9 Months
010-00736-00						Hrs	13,276.7				
20S012333						Ldg	8,977				
Inspected Date 14-Sep-2023						Flt	8,977				
Brand A:345044, Brand C:345044 (ISSUING AUTHORITY: FAA)											
FAR 91.413	**ATC Transponder test and inspections per FAR 91.413 Appendix F of Part 43.**							RE		FAR91, FAR 91	
34 A/F	No.1					Mos	14-Sep-2023	24		30-Sep-2025	6.9 Months
010-00736-00						Hrs	13,276.7				
20S012259						Ldg	8,977				
Inspected Date 14-Sep-2023						Flt	8,977				
(ISSUING AUTHORITY: FAA)											
ST583CH	**Installation of AlliedSignal CAS-67A Traffic Alert and Collision Avoidance System (TCAS II)**							RE (-)			
34 A/F						Mos	27-Nov-1996				
Complied With						Hrs					
						Ldg					
						Flt					
▼ 35 - OXYGEN											
	Filler Valve							RE (O/C)			
35 A/F						Mos	14-Sep-2023				
DKR130	New	0				Hrs	13,276.7				
NSN		0				Ldg	8,977				
		0				Flt	8,977				
	First Aid Oxygen Cylinder							RE (O/C)			
35 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Oxygen Bottle HP Indicator							RE (O/C)			
35 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Oxygen Connector							RE (O/C)			
35 A/F	Copilot					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Oxygen Connector							RE (O/C)			
35 A/F		Pilot					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Oxygen Cylinder							RE (H/T)			
35 A/F							Mos	14-Sep-2023				
6350A33-UUU-C		Overhauled		0			Hrs	13,276.7				
806741				0			Ldg	8,977				
				0			Flt	8,977				
		Oxygen HP Indicator							RE (O/C)			
35 A/F		Copilot					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Oxygen Mask							RE (H/T)			
35 A/F		3rd					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Oxygen Mask							RE (H/T)			
35 A/F		Copilot					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Oxygen Mask							RE (H/T)			
35 A/F		Pilot					Mos	14-Sep-2023				
MA10-12-00		Overhauled		0			Hrs	13,276.7				
78380				0			Ldg	8,977				
				0			Flt	8,977				
		Oxygen Pressure Reducing Valve							RE (H/T)			
35 A/F							Mos	30-Mar-2012				
RDN1000							Hrs					
188							Ldg					
							Flt					
		Passenger Oxygen Controller							RE (H/T)			
35 A/F							Mos	08-Jul-2024				
RCA70		Serviceable					Hrs	13,318.9				
1005							Ldg	9,008				
							Flt	9,007				
		Passenger Oxygen Mask							RE (O/C)			
35 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
35 A/F		No.10					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.11					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.12					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.2					Mos	24-Mar-2021				
	289-601-18						Hrs					
	Unknown						Ldg					
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.5					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.6					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.7					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.8					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Oxygen Mask							RE (O/C)			
	35 A/F	No.9					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Portable Oxygen Bottle							RE (H/T)			
35 A/F	176965-08	3658X					Mos	04-Sep-2024				
							Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
		Smoke Hood							RE (H/T)			
35 A/F	Unknown	No.2 Unknown					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Smoke Hood (508WH)							RE (H/T)		Comp Maint Ops (5-20)	
35 A/F	802300-14	No.1 E15040280					Mos	03-Feb-2017				
							Hrs					
							Ldg					
							Flt					
		Therapeutic Oxygen Mask							RE (O/C)			
35 A/F	Unknown	No.1 Unknown					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Toilet Oxygen Mask							RE (O/C)			
35 A/F	Unknown	Unknown					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
2000-05-20		**Passenger Oxygen Masks**							RE (-)		Mandatory	
35 A/F		Eff: 18-Apr-2000 Complied With (ISSUING AUTHORITY: FAA)					Mos	31-May-2000				
							Hrs					
							Ldg					
							Flt					
2007-26-11		**Intertechnique Zodiac Aircraft Systems - F5341 High-pressure oxygen cylinder**							T (A/R)		Mandatory (Appliance AD)	
35 A/F		Eff: 28-Jan-2008 Brand A:9990-2007-26-11 (ISSUING AUTHORITY: FAA)					Mos	25-Jan-2008				
							Hrs	10,858.2				
							Ldg	7,569				
							Flt					
2015-08-07		**Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators**							RE (-)		Mandatory (Appliance AD)	
35 A/F		Eff: 16-Jun-2015 (ISSUING AUTHORITY: FAA)					Mos	24-Mar-2021				
							Hrs					
							Ldg					
							Flt					
2018-21-14		**MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Inspection/ Replacement**							RE (-)		Mandatory (Appliance AD)	
35 A/F		Eff: 27-Mar-2019 (ISSUING AUTHORITY: FAA)					Mos	24-Mar-2021				
							Hrs					
							Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2023-13-11		**Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09)**							RE (-)		Mandatory (Appliance AD)	
	35 A/F						Days	29-Nov-2023				
	Eff: 05-Sep-2023 Not Applicable	Zodiac P/N: 6350A33-UUU-C, S/N: 806741 Oxygen Cylinder installed in aircraft.					Hrs	13,287.4				
							Ldg	8,989				
	(ISSUING AUTHORITY: FAA)						Flt	8,989				
		Note: APPLICABILITY: This AD applies to AVOX Systems Inc. (formerly Scott Aviation) oxygen cylinder and valve assemblies having part number (P/N) 89794077, 89794015, 891511-14, 806835-01, 807982-01, 808433-01, or 891311-14; and oxygen valve assemblies (body and gage assemblies) having P/N 807206–01. These assemblies might be installed on, but not limited to, the aircraft identified in paragraphs (c)(1) through (12) of this AD, certificated in any category. COMPLIANCE: Within 60 days after the effective date of this AD, inspect the oxygen valve assemblies, and oxygen cylinder and valve assemblies, to determine if the serial numbers of the valve, cylinder, and entire assembly, are listed in Appendix 1 or Appendix 2, "Affected Shipments," of the applicable service information identified in paragraphs (h)(1) through (3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial numbers can be conclusively determined from that review.										
35-10-05-350-801-01		**Restoration of the Crew Oxygen Masks (Overhaul) - LH Pilot Oxygen Mask (L502Wh)**							RE		Comp Maint Ops (5-20)	
	35 A/F	Pilot					Yrs	14-Sep-2023	6	+3%d	14-Sep-2029	4.5 Years (+65 Days)
	MA10-12-00						Hrs	13,276.7				
	AT113378						Ldg	8,977				
	Restored Date 14-Sep-2023						Flt	8,977				
		Note: P/N MA10-12-00 or MC10-12-100 or MC10-12-151 or MC10-12-152 or MF20-506 (107)-(1)										
35-10-05-350-801-02		**Restoration of the Crew Oxygen Masks (Overhaul) - RH Pilot Oxygen Mask (R502Wh)**							RE		Comp Maint Ops (5-20)	
	35 A/F	Copilot					Yrs	24-Mar-2021	6	+3%d	24-Mar-2027	2 Years (+65 Days)
	Unknown						Hrs					
	Unknown						Ldg					
	Restored Date 24-Mar-2021						Flt					
		Note: P/N MA10-12-00 or MC10-12-100 or MC10-12-151 or MC10-12-152 or MF20-506 (107)-(1)										
35-10-05-350-801-03		**Restoration of the Crew Oxygen Masks (Overhaul) - Third Crew Member Oxygen Mask (524Wh)**							RE (N/A)		Comp Maint Ops (5-20)	
	35 A/F	3rd					Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		Note: P/N MA10-12-00 or MC10-12-100 or MC10-12-151 or MC10-12-152 or MF20-506 If installed (Option) (107)-(1)										
35-10-05-710-801-01		**Operational Test of the Crew Oxygen Masks - LH Pilot Oxygen Mask (L502Wh)**							RE		Acft Maint Ops (5-10)	
	35 A/F	Pilot05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
	MA10-12-00						Hrs	13,386.3				
	78380						Ldg	9,044				
	(Tol. Adjustment: -83d)						Flt	9,043				
35-10-05-710-801-02		**Operational Test of the Crew Oxygen Masks - RH Pilot Oxygen Mask (R502Wh)**							RE		Acft Maint Ops (5-10)	
	35 A/F	Copilot05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
	Unknown						Hrs	13,386.3				
	Unknown						Ldg	9,044				
	(Tol. Adjustment: -83d)						Flt	9,043				
35-10-05-710-801-03		**Operational Test of the Crew Oxygen Masks - Third Crew Member Oxygen Mask (524Wh)**							RE (N/A)		Acft Maint Ops (5-10)	
	35 A/F	3rd					Mos	07-Jun-2022				
	Unknown						Hrs	13,232.2				
	Unknown						Ldg	8,949				
							Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
351105	**Oxygen Mask Box**							RE (O/C)			
35 A/F	Pilot					Mos	14-Sep-2023				
MXP134	Overhauled		0			Hrs	13,276.7				
2228			0			Ldg	8,977				
			0			Flt	8,977				
351130	**Oxygen Mask Box**							RE (O/C)			
35 A/F	Copilot					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
35-20-00-210-801-01	**General Visual Inspection of the Passenger Oxygen Masks - Passenger Oxygen Mask (9510Wj)**							RE		Acft Maint Ops (5-10)	
35 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
35-20-00-720-801-01	**Functional Test of the Passenger Oxygen System**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
35 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
35-20-01-350-801-01	**Restoration of the Passenger Oxygen Controller (Overhaul) - Passenger Oxygen Controller (1Wh)**							RE		Comp Maint Ops (5-20)	
35 A/F						Yrs	08-Jul-2024	6	+3%d	16-Oct-2027	2.6 Years (+65 Days)
RCA70						Hrs	13,318.9				
1005						Ldg	9,008				
Restored Date 18-Nov-2021						Flt	9,007				
(Tol. Adjustment: -33d)											
Note: P/N RCA70 (107)-(1)											
35-30-01-960-801-01	**DISCARD OF THE SMOKE HOOD - SMOKE HOOD (508WH)**							RE (N/A)		Comp Maint Ops (5-20)	
35 A/F	No.1					Mos					
802300-14						Hrs					
E15040280						Ldg					
(SOURCE: Falcon 50/50EX MPD)						Flt					
35-30-01-960-801-02	**Discard of the Smoke Hood**							RE (N/A)			
35 A/F	No.2					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt					
35-30-05-210-801-01	**General Visual Inspection of the Portable Oxygen Bottle - Portable Oxygen Bottle and Masks (537Wh)**							RE		Comp Maint Ops (5-20)	
35 A/F						Yrs	04-Sep-2024	1	+3%d	04-Sep-2025	6.1 Months (+10 Days)
176965-08						Hrs	13,386.3				
3658X						Ldg	9,044				
						Flt	9,043				
35-30-05-350-801-01	**Restoration of the Portable Oxygen Bottle (Overhaul) - Portable Oxygen Bottle and Masks (537Wh)**							RE		Comp Maint Ops (5-20)	
35 A/F						Yrs	04-Sep-2024	5		15-Apr-2026	1.1 Years
176965-08						Hrs	13,386.3				
3658X						Ldg	9,044				
Restored Date 15-Apr-2021						Flt	9,043				
Note: P/N 894-20330 or GEF312 or GLF312 Note:(107) (1)											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
35-30-05-960-801-01	**Discard of the Portable Oxygen Bottle - Portable Oxygen Bottle and Masks (537Wh)**							RE (N/A)		Comp Maint Ops (5-20)	
35 A/F						Mos					
176965-08						Hrs					
3658X						Ldg					
						Flt					
Note: P/N GLF312											
35-30-09-100-801-01	**Cleaning of the Portable Oxygen Masks - Portable Oxygen Bottle and Masks (537Wh)**							RE		Comp Maint Ops (5-20)	
35 A/F						Yrs	04-Sep-2024	1	+3%d	04-Sep-2025	6.1 Months (+10 Days)
176965-08											
3658X						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
35-40-01-790-801-01	**Hydrostatic Test of the Oxygen Cylinder - Oxygen Cylinder (500Wh)**							RE		Comp Maint Ops (5-20)	
35 A/F						Yrs	14-Sep-2023	3		01-May-2026	1.2 Years
6350A33-UUU-C					0	Hrs	13,276.7				
806741					0	Ldg	8,977				
Hydrostatic Tested Date 01-May-2023					0	Flt	8,977				
Note: P/N 404-712-13 or GST2151 (107)-(1) No tolerance											
35-40-01-960-801-01	**Discard of the Oxygen Cylinder - Oxygen Cylinder (500Wh)**							RE		Comp Maint Ops (5-20)	
35 A/F						Yrs	14-Sep-2023	15		01-Sep-2028	3.5 Years
6350A33-UUU-C						Hrs	13,276.7				
806741						Ldg	8,977				
Manufactured Date 01-Sep-2013						Flt	8,977				
Note: P/N 89723015											
35-40-05-350-801-01	**Restoration of the Oxygen Cylinder Pressure Reducing Valve (Overhaul) - Oxygen Cylinder Pressure Reducing Valve (50Wy)**							RE		Comp Maint Ops (5-20)	
35 A/F						Yrs	24-Mar-2021	6	+3%d	24-Mar-2027	2 Years (+65 Days)
RDN1000						Hrs	13,161.4				
188						Ldg	8,910				
Restored Date 24-Mar-2021						Flt					
Note: P/N RDN1000 (107)-(1)											
84-02-08	**Scott - Oxygen Cylinders**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	19-Mar-1984				
Eff: 09-Feb-1984						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
85-14-01	**Oxygen Mask Presentation Box**							RE (-)		Mandatory	
35 A/F						Mos	24-Mar-2021				
Eff: 15-Aug-1985						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
85-26-03	**SCOTT AVIATION Oxygen Connectors, Part Numbers 289-56 and 289-56-1**							RE (-)		Mandatory (Appliance AD)	
35 A/F						Mos	24-Mar-2021				
Eff: 30-Dec-1985 Not Applicable	Per equipment installed					Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
91-10-05	**O2 CORPORATION (FRANK MCGOWAN CO.) - Oxygen Mask Presentation Units**							T (A/R)		Mandatory (Appliance AD)	
35 A/F	Eff: 03-Jun-1991 (ISSUING AUTHORITY: FAA)					Mos	18-Jun-1991				
						Hrs					
						Ldg					
						Flt					
99-08-21	**Puritan-Bennett Aero Systems Company C351-2000 Series Passenger Oxygen Masks and Portable Oxygen Masks - Passenger Oxygen Masks**							T (A/R)		Mandatory (Appliance AD)	
35 A/F	Eff: 02-Jun-1999 Brand A:9990-1999-08-21 (ISSUING AUTHORITY: FAA)					Mos	04-Nov-1999				
						Hrs					
						Ldg					
						Flt					
▼ 36 - PNEUMATIC											
	Air Bleed Indicator Printed Circuit							RE (O/C)			
36 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Air Bleed Indicator Printed Circuit							RE (O/C)			
36 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Air Conditioning Thermostat							RE (O/C)			
36 A/F	Cabin					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Air Conditioning Thermostat							RE (O/C)			
36 A/F	Cockpit					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Air Pressure Transducer							RE (O/C)			
36 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Air Pressure Transducer							RE (O/C)			
36 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	APU Bleed Air Check Valve							RE (O/C)			
36 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	APU Bleed Venturi Check Valve							RE (O/C)			
36 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Bleed Air Computer (BASC)							RE (O/C)			
	36 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Bleed Air Shutoff Valve							RE (O/C)			
	36 A/F						Mos	09-Aug-2021				
	BYLB50423-1						Hrs					
	299						Ldg					
							Flt					
		Bleed Air Temperature Probe							RE (O/C)			
	36 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Bleed Air Temperature Probe							RE (O/C)			
	36 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Bleed Air Temperature Probe							RE (O/C)			
	36 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine 2 HP Pressure Regulating Valve							RE (O/C)			
	36 A/F						Mos	09-Apr-2021				
	3213902-2						Hrs					
	P-303						Ldg					
							Flt					
		Engine Bleed Air Thermostat							RE (O/C)			
	36 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Bleed Air Thermostat							RE (O/C)			
	36 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Bleed Air Thermostat							RE (O/C)			
	36 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Bleed Venturi Check Valve							RE (O/C)			
	36 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Bleed Venturi Check Valve							RE (O/C)			
	36 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Expansion Pipe							RE (O/C)			
	36 A/F	No.1					Mos	07-Mar-1991				
	B45CB1042						Hrs					
	T613						Ldg					
							Flt					
		Engine Expansion Pipe							RE (O/C)			
	36 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Expansion Pipe							RE (O/C)			
	36 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine HP Bleed Air Check Valve							RE (O/C)			
	36 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine HP Bleed Air Check Valve							RE (O/C)			
	36 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine HP Bleed Air Check Valve							RE (O/C)			
	36 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine HP Bleed Air Shutoff Valve							RE (O/C)			
	36 A/F	No.1					Mos	24-Mar-2021				
	1780-00-1						Hrs					
	1446						Ldg					
							Flt					
		Engine HP Bleed Air Shutoff Valve							RE (O/C)			
	36 A/F	No.2					Mos	27-Dec-2007				
	1780-00-1						Hrs					
	Unknown						Ldg					
							Flt					
		Engine HP Bleed Air Shutoff Valve							RE (O/C)			
	36 A/F	No.3					Mos	31-Jul-2014				
	1159-00-9						Hrs					
	Unknown						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine LP Bleed Air Check Valve							RE (O/C)			
	36 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine LP Bleed Air Check Valve							RE (O/C)			
	36 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine LP Bleed Air Check Valve							RE (O/C)			
	36 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		HP Bleed Air Check Valve							RE (O/C)			
	36 A/F	Cabin					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		HP Bleed Air Check Valve							RE (O/C)			
	36 A/F	Cockpit					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		LP Bleed Air Check Valve							RE (O/C)			
	36 A/F	Cabin					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		LP Bleed Air Check Valve							RE (O/C)			
	36 A/F	Cockpit					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		PT2 Pipe - Engine Sensor							RE (O/C)			
	36 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
36-10-00-790-801-01		**Leak Check of the Bleed Air System - Check For Leaks at APU**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
	36 A/F	05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
	Note: during engine and APU run-up						Ldg	8,977				
							Flt	8,977				
36-10-00-790-801-02		**Leak Check of the Bleed Air System - Check For Leaks at Engine 1**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
	36 A/F	05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
	Note: during engine and APU run-up						Ldg	8,977				
							Flt	8,977				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
36-10-00-790-801-03		**Leak Check of the Bleed Air System - Check For Leaks at Engine 2**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
36 A/F		05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
		Note: during engine and APU run-up					Flt	8,977				
36-10-00-790-801-04		**Leak Check of the Bleed Air System - Check For Leaks at Engine 3**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
36 A/F		05-10-00-1B					Mos	14-Sep-2023				
							Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
							Ldg	8,977				
		Note: during engine and APU run-up					Flt	8,977				
36-10-02-720-801-01		**Functional Test of the Engine HP Bleed Air Valves - Engine 1 HP Bleed Air Valve (23H1)**							RE		Comp Maint Ops (5-20)	**≈06-Apr-2035**
36 A/F		No.1					Mos	24-Mar-2021				
1780-00-1							Hrs	13,161.4	4,000		17,161.4	3,640.5 Hrs
1446							Ldg	8,910				
							Flt					
		Note: P/N 1159-00-9C or 1780-00-1 (1) No tolerance A/C WITH TFE 731-3 ENGINES										
36-10-02-720-801-02		**Functional Test of the Engine HP Bleed Air Valves - Engine 2 HP Bleed Air Valve (23H2)**							RE		Comp Maint Ops (5-20)	**≈25-Sep-2028**
36 A/F		No.2					Mos	27-Dec-2007				
1780-00-1							Hrs	10,810.1	4,000		14,810.1	1,289.2 Hrs
Unknown							Ldg	7,544				
							Flt					
		Note: P/N 1159-00-9C or 1780-00-1 (1) No tolerance A/C WITH TFE 731-3 ENGINES										
36-10-02-720-801-03		**Functional Test of the Engine HP Bleed Air Valves - Engine 3 HP Bleed Air Valve (23H3)**							RE		Comp Maint Ops (5-20)	**≈11-Jun-2031**
36 A/F		No.3					Mos	31-Jul-2014				
1159-00-9							Hrs	11,785.6	4,000		15,785.6	2,264.7 Hrs
Unknown							Ldg	8,159				
							Flt					
		Note: P/N 1159-00-9C or 1780-00-1 (1) No tolerance A/C WITH TFE 731-3 ENGINES										
36-10-03-720-801-01		**Functional Test of the Engine 2 HP Pressure Regulating Valve - Engine 2 HP Pressure Regulating Valve (29H)**							RE		Comp Maint Ops (5-20)	**≈18-Apr-2035**
36 A/F							Mos	05-Apr-2021				
3213902-2							Hrs	13,174.1	4,000		17,174.1	3,653.2 Hrs
P-303							Ldg	8,917				
							Flt					
		Note: P/N 3213902-1 or 3213902-2 (1) No tolerance A/C WITH TFE 731-3 ENGINES										
36-10-05-200-801-01		**Inspection of the Bleed Air Check Valves - Engine 1 LP Bleed Air Check Valve (L515H)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
36 A/F		05-10-00-2B					Mos	24-Mar-2021				
							Hrs	13,161.4	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
							Ldg	8,910				
		Note: For Engine LP/HP circuit : before SB F50-012 or SB F50-103-1.					Flt					
36-10-05-200-801-02		**Inspection of the Bleed Air Check Valves - Engine 2 LP Bleed Air Check Valve (M515H)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
36 A/F		05-10-00-2B					Mos	24-Mar-2021				
							Hrs	13,161.4	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
							Ldg	8,910				
		Note: For Engine LP/HP circuit : before SB F50-012 or SB F50-103-1.					Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
36-10-05-200-801-03	**Inspection of the Bleed Air Check Valves - Engine 3 LP Bleed Air Check Valve (R515H)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
36 A/F	05-10-00-2B					Mos	24-Mar-2021				
						Hrs	13,161.4	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,910				
	Note: For Engine LP/HP circuit : before SB F50-012 or SB F50-103-1.					Flt					
36-10-05-200-801-04	**Inspection of the Bleed Air Check Valves - Engine 1 HP/LP Bleed Air Check Valve (L516H)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
36 A/F	05-10-00-2B					Mos	24-Mar-2021				
						Hrs	13,161.4	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,910				
	Note: For Engine LP/HP circuit : before SB F50-012 or SB F50-103-1.					Flt					
36-10-05-200-801-05	**Inspection of the Bleed Air Check Valves - Engine 2 HP/LP Bleed Air Check Valve (M516H)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
36 A/F	05-10-00-2B					Mos	24-Mar-2021				
						Hrs	13,161.4	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,910				
	Note: For Engine LP/HP circuit : before SB F50-012 or SB F50-103-1.					Flt					
36-10-05-200-801-06	**Inspection of the Bleed Air Check Valves - Engine 3 HP/LP Bleed Air Check Valve (R516H)**							RE		Acft Maint Ops (5-10)	**≈25-Dec-2031**
36 A/F	05-10-00-2B					Mos	24-Mar-2021				
						Hrs	13,161.4	3,000	+30	(15,978.6)	2,457.7 Hrs (+30)
						Ldg	8,910				
	Note: For Engine LP/HP circuit : before SB F50-012 or SB F50-103-1.					Flt					
36-10-05-200-801-07	**Inspection of the Bleed Air Check Valves - APU Bleed Air Check Valve (599H)**							RE		Acft Maint Ops (5-10)	**≈02-Nov-2032**
36 A/F	05-10-00-2B					Mos	29-Nov-2023				
						Hrs	13,287.4	3,000	+30	16,287.4	2,766.5 Hrs (+30)
						Ldg	8,989				
	Note: For APU circuit : After SB F50-002 and before SB F50-075 or SB F50-103-2					Flt	8,989				
36-10-21-710-801-01	**Operational Test of the Bleed Air Isolation Valve - Bleed Air Isolation Valve (43H)**							RE		Acft Maint Ops (5-10)	**≈21-Feb-2036**
36 A/F	05-10-00-3B					Mos	02-Sep-2016				
						Hrs	12,978.6	4,500	+30	(17,478.6)	3,957.7 Hrs (+30)
						Ldg	8,785				
	Note: A/C with TFE 731-3 ENGINES					Flt					
36-10-33-350-801-01	**Restoration of the Bleed Air Articulated Pipes (Leak Test and Discard of Piston Ring) - Engine 1 Articulated Pipe (L510HU)**							RE		Comp Maint Ops (5-20)	**≈13-Jul-2025**
36 A/F	No.1					Mos	26-Sep-2003				
B45CB1042						Hrs	9,656.1	4,000		13,656.1	135.2 Hrs
T613						Ldg					
						Flt					
	Note: P/N B45CB1041 or B45CB1042 or B45CB1062 (1) No tolerance A/C WITH TFE 731-3 ENGINES										
36-10-33-350-801-02	**Restoration of the Bleed Air Articulated Pipes (Leak Test and Discard of Piston Ring) - Engine 2 Articulated Pipe (M510HU)**							RE		Comp Maint Ops (5-20)	**≈13-Jul-2025**
36 A/F	No.2					Mos	26-Sep-2003				
Unknown						Hrs	9,656.1	4,000		13,656.1	135.2 Hrs
Unknown						Ldg					
						Flt					
	Note: P/N B45CB1071 or B45CB1072 (1) No tolerance A/C WITH TFE 731-3 ENGINES										
36-10-33-350-801-03	**Restoration of the Bleed Air Articulated Pipes (Leak Test and Discard of Piston Ring) - Engine 3 Articulated Pipe (R510HU)**							RE		Comp Maint Ops (5-20)	**≈13-Jul-2025**
36 A/F	No.3					Mos	26-Sep-2003				
Unknown						Hrs	9,656.1	4,000		13,656.1	135.2 Hrs
Unknown						Ldg					
						Flt					
	Note: P/N B45CB1041 or B45CB1042 or B45CB1062 (1) No tolerance A/C WITH TFE 731-3 ENGINES										

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-012	**Installation of barber colman check valves with fail safe closing feature**							RE (-)			
36 A/F						Mos					
						Hrs					
						Ldg					
Note: M0022						Flt					
F50-012 R1	**Installation of barber colman check valves with fail safe closing feature**							RE (-)			
36 A/F						Mos					
						Hrs					
						Ldg					
Note: M0022						Flt					
F50-012 R2	**Installation of barber colman check valves with fail safe closing feature**							T (A/R)			
36 A/F						Mos					
Eff: 27-Nov-1981						Hrs					
						Ldg					
Note: M0022						Flt					
F50-075	**APU - Installation of Barber Colman check valve with fail safe closing feature**							RE (-)			
36 A/F						Mos					
						Hrs					
						Ldg					
Note: M0197A, M0766B, M0197B, 2 to 14, 16 to 26, 28, 30, 33 to 250 delivered by the manufacturer without APU						Flt					
F50-075 R1	**APU - Installation of Barber Colman check valve with fail safe closing feature**							T (A/R)			
36 A/F						Mos					
Eff: 27-Nov-1981						Hrs					
						Ldg					
Note: M0197A, M0766B, M0197B, 2 to 14, 16 to 26, 28, 30, 33 to 250 delivered by the manufacturer without APU						Flt					
F50-103	**Barber colman check valves with fail-safe closing feature - Spring replaced**							T (A/R)			
36 A/F						Mos					
Eff: 27-Nov-1981						Hrs					
						Ldg					
Note: M0766A, A/C with BARBER COLMAN CYLB50419-1 check valves (basic or APU system)						Flt					
F50-104	**Environmental cooling unit air supply - Addition of a general connectors union**							T (A/R)			
36 A/F						Mos					
Eff: 18-Jan-1984						Hrs					
						Ldg					
Note: M0807						Flt					
F50-107	**Adjustable brackets for the bleed air and air conditioning ducts**							RE (-)			
36 A/F						Mos					
Eff: 28-Feb-1983						Hrs					
						Ldg					
Note: M0617						Flt					
F50-271	**BASC - Complete electrical provision**							RE (-)			
36 A/F						Mos					
Eff: 27-Jan-1999						Hrs					
						Ldg					
Note: M2203						Flt					
F50-272	**BASC - Simplified electrical provision**							RE (-)			
36 A/F						Mos					
Eff: 18-Dec-1998						Hrs					
						Ldg					
Note: M2204, 251, 253, 255 to 263, 265 to 272 without SB F50-271						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-281	**BASC - Delayed operation of "MINELCO" magnetic indicators**							RE (-)			
36 A/F						Mos					
Eff: 12-Aug-1998						Hrs					
						Ldg					
Note: M2166						Flt					
F50-283	**BASC - Improvement of aircraft faillure management**							RE (-)			
36 A/F						Mos					
Eff: 18-Dec-1998						Hrs					
						Ldg					
Note: M2165						Flt					
F50-463	**Centre engine H.P bleed duct P/N SBJ33057-401 and -402 cracking**							RE (-)			
36 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-463 R1	**Centre engine H.P bleed duct P/N SBJ33057-401 and -402 cracking**							RE (-)			
36 A/F						Mos					
Eff: 09-Mar-2006						Hrs					
						Ldg					
						Flt					
F50-525	**HP2 bleed air pipe installation improvement**							T (A/R)			
36 A/F						Mos					
Eff: 22-Jul-2013						Hrs					
						Ldg					
Note: M3164, M3192, 2 to 95 without SB F50-280						Flt					
▼ 38 - WATER/WASTE											
38-00-00-610-801-01	**Servicing of the Water System**							RE		Acft Maint Ops (5-10)	
38 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
38-10-00-670-801-01	**Sterilization of the Potable Water System-Standard Sterilization**							RE		Acft Maint Ops (5-10)	
38 A/F						Mos	26-Feb-2025	6	+1m	26-Aug-2025	5.8 Months (+31 Days)
						Hrs	13,520.9				
Note: More often if necessary						Ldg	9,133				
						Flt	9,133				
93-23-01	**Nordskog Water Heaters and Coffee Makers - Inspection/Replacement**							RE (-)		Mandatory (Appliance AD)	
38 A/F						Days	24-Mar-2021				
Eff: 07-Dec-1993						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
94-14-03	**Nordskog Water Heaters and Coffee Makers - Inspection/Replacement**							RE (-)		Mandatory (Appliance AD)	
38 A/F						Mos	24-Mar-2021				
Eff: 01-Aug-1994 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-202	**Waste drainage system anti-icing - Addition of a fuse**							RE (-)			
38 A/F						Mos					
Eff: 16-Mar-1989						Hrs					
						Ldg					
Note: M1499						Flt					
F50-260	**Water heater control relay - Replacement of control relay and addition of a test and monitoring circuit**							T (A/R)			
38 A/F						Mos					
Eff: 29-Oct-1997						Hrs					
						Ldg					
Note: M2062, A/C with interior accomodations installed by DASSAULT AVIATION and equipped with a L'HOTELLIER gage P/N 5250, 5251, 5250-1 or 5251-1						Flt					
F50-319	**Aft toilet - Improved sealing of drain chute**							RE (-)			
38 A/F						Mos					
						Hrs					
						Ldg					
Note: M3143, M2618, A/C with "MONOGRAM" aft toilet unit						Flt					
F50-319 R1	**Aft toilet - Improved sealing of drain chute**							RE (-)			
38 A/F						Mos					
						Hrs					
						Ldg					
Note: M3143, M2618, A/C with "MONOGRAM" aft toilet unit						Flt					
F50-319 R2	**Aft toilet - Improved sealing of drain chute**							T (A/R)			
38 A/F						Mos					
Eff: 09-Oct-2013						Hrs					
						Ldg					
Note: M3143, M2618, A/C with "MONOGRAM" aft toilet unit						Flt					
F50-325	**Rear lavatory compartment - Internal improvement of overheat safety system**							T (A/R)			
38 A/F						Mos					
Eff: 15-Oct-1999						Hrs					
						Ldg					
Note: M2184, 2 to 255, 257, 260 to 267, 269, 270, 272 with GOODRICH water heaters P/N 8921082G2 also as identified P/N 7700244-501						Flt					
F50-414	**Aft toilet - Improved installation of the "MONOGRAM" toilet unit**							T (A/R)			
38 A/F						Mos					
Eff: 13-Oct-2004						Hrs					
						Ldg					
Note: M2849, A/C with a MONOGRAM toilet unit and without M2849						Flt					
F50-414 R1	**Aft toilet - Improved installation of the "MONOGRAM" toilet unit**							T (A/R)			
38 A/F						Mos					
Eff: 13-Oct-2004						Hrs					
						Ldg					
Note: M2849, A/C with a MONOGRAM toilet unit and without M2849						Flt					
F50-451	**New drinking water filter**							T (A/R)			
38 A/F						Mos					
Eff: 14-Sep-2004						Hrs					
						Ldg					
Note: M2959, M2930, A/C with old filter P/N PC to MVP						Flt					
F50-540	**Water distribution system - Replacement of Touch-Flo HC-2 faucet**							T (A/R)			
38 A/F						Mos					
Eff: 15-Oct-2014						Hrs					
						Ldg					
Note: R2282, A/C that have a galley equipped with the Touch-Flo faucet P/N HC-2						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 39 - ELECTRICAL - ELECTRONIC PANELS AND MULTIPURPOSE COMPONENTS												
		Electronic Panel							RE (O/C)			
	39 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Hydraulic Panel							RE (O/C)			
	39 A/F						Mos	15-Jun-2014				
	694TS03Y01						Hrs					
	305						Ldg					
							Flt					
		Master Caution Panel							RE (O/C)			
	39 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Printed Circuit Board							RE (O/C)			
	39 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Printed Circuit Board							RE (O/C)			
	39 A/F	No.2					Mos	10-Dec-2016				
	CI853B						Hrs					
	NSN						Ldg					
							Flt					
		Printed Circuit Board							RE (O/C)			
	39 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Printed Circuit Board							RE (O/C)			
	39 A/F	No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Printed Circuit Board							RE (O/C)			
	39 A/F	No.5					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Printed Circuit Board							RE (O/C)			
	39 A/F	No.6					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Printed Circuit Board							RE (O/C)			
	39 A/F	No.7					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Printed Circuit Board							RE (O/C)			
	39 A/F	No.8					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Warning Panel							RE (O/C)			
	39 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
F50-243 R1-Alert		**LH electrical cabinet - Check of clearances between wire bundles and passenger door actuator**							RE (-)			
	39 A/F						Mos	08-Feb-1995				
	Eff: 10-Nov-1994						Hrs					
							Ldg					
	Note: AD EASA 94-238-015 R1 (AD FAA 95-01-03)						Flt					
F50-243-Alert		**LH electrical cabinet - Check of clearances between wire bundles and passenger door actuator**							RE (-)			
	39 A/F						Mos					
							Hrs					
							Ldg					
	Note: AD EASA 94-238-015 R1 (AD FAA 95-01-03)						Flt					
F50-244		**LH electrical cabinet - Installation of a protective wiring housing**							RE (-)			
	39 A/F						Mos	11-Oct-1995				
							Hrs					
							Ldg					
	Note: M1899, AD EASA 94-238-015 R1 (AD FAA 95-01-03)						Flt					
F50-244 R1		**LH electrical cabinet - Installation of a protective wiring housing**							T (A/R)			
	39 A/F						Mos					
	Eff: 11-Oct-1995						Hrs					
							Ldg					
	Note: M1899, AD EASA 94-238-015 R1 (AD FAA 95-01-03)						Flt					
F50-289		**Circuit breaker / load-shed circuits - Addition of orange circuit breaker caps**							RE (-)			
	39 A/F						Mos					
	Eff: 06-May-1998						Hrs					
							Ldg					
	Note: M2320						Flt					
F50-320		**Modification of instrument panel for improving removability of pilot and copilot windshields**							RE (-)			
	39 A/F						Mos					
	Eff: 14-Jun-2000						Hrs					
							Ldg					
	Note: M2284						Flt					
▼ 45 - DIAGNOSTIC AND MAINTENANCE SYSTEM												
		Maintenance Diagnostic Computer (MDC) Module							RE (O/C)			
	45 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
F50-292		**Aircraft/PC computer interface - Installation of an RS232 output airborne interface in rear compartment**							RE (-)			
	45 A/F						Mos					
	Eff: 15-Mar-2000						Hrs					
							Ldg					
	Note: M2117						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-316	**Aircraft computer/PC interface - RS232 output in LH electrical cabinet**							RE (-)			
45 A/F	Eff: 17-Jan-2001					Mos					
						Hrs					
						Ldg					
	Note: M2238, M2544, M2117, 51, 253 to 315 and A/C with SB F50-280					Flt					
▼ 49 - AIRBORNE AUXILIARY POWER											
	Air Intake Door Actuator							RE (O/C)			
49 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Air Load Control Valve							RE (O/C)			
49 APU1						Mos					
Unknown						Hrs					
Unknown						APUS					
	APU - Combustor Drain/Orifice Fitting Valve							RE (O/C)			
49 APU1						Mos					
Unknown						Hrs					
Unknown						APUS					
	APU - Fuel Control							RE (O/C)			
49 APU1						Mos	15-May-1992				
3882600-2-1						Hrs	1,501				
a724						APUS					
	APU - Fuel Nozzle							RE (O/C)			
49 APU1						Mos	08-Oct-2007				
3830061-5						Hrs	3,600.5				
4133						APUS					
	APU - Igniter Plug							RE (O/C)			
49 APU1						Mos					
Unknown						Hrs					
Unknown						APUS					
	APU - Ignition Unit							RE (O/C)			
49 APU1						Mos	03-Feb-2025				
10-516000-1	Serviceable					Hrs					
970218000291						APUS					
	APU - Motion Pick Up Transducer							RE (O/C)			
49 APU1						Mos					
Unknown						Hrs					
Unknown						APUS					
	APU Cap Combustion Chamber							RE (O/C)			
49 A/F						Mos	27-Apr-2002				
3615086-2						Hrs					
77721						Ldg					
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		APU Control Panel							RE (O/C)			
	49 A/F						Mos	26-Oct-2015				
	683TS04Y01SE						Hrs					
	124						Ldg					
							Flt					
		APU Controller							RE (O/C)			
	49 APU1						Mos					
	Unknown						Hrs					
	Unknown						APUS					
		APU Fuel Shut-Off Solenoid Valve							RE (O/C)			
	49 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		APU Hourmeter							RE (O/C)			
	49 APU1						Mos					
	Unknown						Hrs					
	Unknown						APUS					
		APU Surge (Shutoff) Valve							RE (O/C)			
	49 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		APU Control Panel							RE (O/C)			
	49 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Combustion Unit							RE (O/C)			
	49 APU1						Mos					
	Unknown						Hrs					
	Unknown						APUS					
		Compressor Rotor							RE			**≈15-Jan-2191**
	49 APU1						Mos	15-May-1992				
	3615880-1		4,627.2				Hrs	1,501	100,000		96,873.8	92,207 Hrs
	1-16436-8043						APUS					
	APU MM:49-20-00, SIL: APU-56											
		Fuel Shutoff Valve							RE (O/C)			
	49 APU1						Mos					
	Unknown						Hrs					
	Unknown						APUS					
		Ignitor Plug Lead							RE (O/C)			
	49 APU1						Mos					
	Unknown						Hrs					
	Unknown						APUS					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Low Pressure Switch							RE (O/C)			
49 APU1						Mos					
Unknown						Hrs					
Unknown						APUS					
	Thermocouple							RE (O/C)			
49 APU1						Mos					
Unknown						Hrs					
Unknown						APUS					
	Turbine Rotor							RE			**≈11-Apr-2031**
49 APU1						Mos	15-May-1992				
3615880-1		4,627.2				Hrs	1,501	10,000		6,873.8	2,207 Hrs
1y-2487						APUS					
APU MM:49-20-00, SIL:APU-56											
3615880-49-8149	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 12-Jun-2015						Hrs					
						APUS					
3615880-49-8149 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs**							T (-)		Recommended	
49 APU1						Mos					
						Hrs					
						APUS					
3615880-49-8149 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos					
						Hrs					
						APUS					
3615880-49-8149 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Turbine Rotors, PN 3615880-1, PN 3615880-002, PN 3615880-3, and PN 3615880-4, on Multiple APUs**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 15-Dec-2017						Hrs					
(AVG MAN HRS: 1.5)						APUS					
3822101-49-8148	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 10-Jul-2015						Hrs					
						APUS					
3822101-49-8148 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							T (-)		Recommended	
49 APU1						Mos					
Eff: 20-Oct-2015						Hrs					
						APUS					
3822101-49-8148 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 10-Jan-2017						Hrs					
						APUS					
3822101-49-8148 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 27-Nov-2017						Hrs					
(AVG MAN HRS: 1)						APUS					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
3842064-49-8193	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Balance Repair of the Turbine Rotors PN 3842064-1 and PN 3842064-5 on Multiple Auxiliary Power Units (APUs)**							RE (-)	Recommended, Service Bulletin		
49 APU1						Mos					
Eff: 23-Feb-2017						Hrs					
						APUS					
3842064-49-8193 Rev 1	**AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Balance Repair of the Turbine Rotors PN 3842064-1 and PN 3842064-5 on Multiple Auxiliary Power Units (APUs)**							T (A/R)	Recommended, Service Bulletin		
49 APU1						Mos					
Eff: 14-Sep-2017						Hrs					
						APUS					
	Note: Honeywell recommends this service bulletin be done for the balance repair of turbine rotors, PN 3842064-1 and PN 3842064-5.										
3882600-49-7973	**Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1 On the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next APU Shop Visit**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
3882600-49-7973 Rev 1	**Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1 On the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next APU Shop Visit**							T (-)		Recommended	
49 APU1						Mos					
Eff: 10-Apr-2009						Hrs					
						APUS					
3882600-49-7973 Rev 2	**Main Fuel Control Unit (FCU) - Check Nameplate for Latest Change Number. Install Fuel Flow Deflector, PN 70720001-1 On the Fuel Control Differential Pressure (Delta P) Sleeve as Required at Next APU Shop Visit**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 11-May-2019						Hrs					
(AVG MAN HRS: 1)						APUS					
49-00-00-009	**APU - Clean Fuel Nozzle**							RE			**≈16-Nov-2025**
49 APU1						Mos	22-Jul-2024				
3830061-5						Hrs	4,627.2	300	+10%	4,927.2	260.4 Hrs (+30)
4133						APUS					
4900004	**APU Engine Oil Filter Element - Remove, Inspect, Replace**							RE			
49 APU1						Mos	22-Jul-2024	12	+10%m	22-Jul-2025	4.6 Months (+37 Days)
						Hrs	4,627.2	300	+10%	4,927.2	260.4 Hrs (+30)
						APUS					
4900009	**APU Engine - Perform oil change**							RE			
49 APU1						Mos	22-Jul-2024	12	+10%m	22-Jul-2025	4.6 Months (+37 Days)
						Hrs	4,627.2	300	+10%	4,927.2	260.4 Hrs (+30)
						APUS					
490100-0101	**APU Filter Element,Fuel**							RE (O/C)			
49 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
490113	**Door Motor**							RE (O/C)			
49 A/F	APU					Mos	28-Apr-2016				
4175115						Hrs					
12894						Ldg					
						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-10-00-208	**APU - Cleaning/Inspection of Combustor Drain/Orifice Fitting Valve**							RE			**≈25-Oct-2025**
49 APU1						Mos	28-Jun-2023				
Unknown						Hrs	4,606	300		4,906	239.2 Hrs
Unknown						APUS					
491030	**APU Hot Section Inspection**							RE			**≈09-Jan-2028**
49 APU1						Mos	15-Oct-2007				
						Hrs	3,600.5	2,100		5,700.5	1,033.7 Hrs
						APUS					
49-20-00-002	**APU - Igniter Plug, Cleaning and Inspection**							RE		Maintenance Manual	**≈25-Oct-2025**
49 APU1						Mos	28-Jun-2023				
Unknown						Hrs	4,606	300		4,906	239.2 Hrs
Unknown						APUS					
MM:49-20-00, Ref:49-40-33(CX)											
49-20-00-008	**APU - Compressor Rotor Visual Inspection**							RE			**≈09-Jan-2028**
49 APU1						Mos	15-Oct-2007				
3615880-1						Hrs	3,600.5	2,100	+45	5,700.5	1,033.7 Hrs (+45)
1-16436-8043						APUS					
49-20-00-202	**APU Power Unit - Detailed Inspection of Combustor Unit**							RE			**≈16-Nov-2025**
49 APU1						Mos	22-Jul-2024				
Unknown						Hrs	4,627.2	300	+10%	4,927.2	260.4 Hrs (+30)
Unknown						APUS					
49-20-00-207	**APU - Operational Test**							RE (A/R)		Maintenance Manual	
49 APU1						Mos					
						Hrs					
Ref:MM49-20-00						APUS					
493020	**Remove and Replace APU Fuel Filter Element**							RE			**≈25-Oct-2025**
49 APU1						Mos	28-Jun-2023				
						Hrs	4,606	300		4,906	239.2 Hrs
						APUS					
49-3323	**Replacement of Preformed Packings (O-Rings)**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-3323 Rev 1	**Replacement of Preformed Packings (O-Rings)**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-3323 Rev 2	**Replacement of Preformed Packings (O-Rings)**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-3323 Rev 3	**Replacement of Preformed Packings (O-Rings)**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-3323 Rev 4	**Replacement of Preformed Packings (O-Rings)**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-3323 Rev 5	**Replacement of Preformed Packings (O-Rings)**							T (A/R)			
49 APU1						Mos					
Eff: 10-Sep-1976						Hrs					
						APUS					
49-5155	**Incorporate High Press Fuel Sys Modification**							RE (-)			
49 APU1						Mos					
Eff: 07-Mar-1980						Hrs					
(AVG MAN HRS: 6.5)						APUS					
49-5155 Rev 1	**Incorporate High Press Fuel Sys Modification**							T (A/R)			
49 APU1						Mos					
Eff: 28-Feb-1983						Hrs					
(AVG MAN HRS: 6.5)						APUS					
49-5214	**Incorporate Electronic Control Unit with Improved Droop Control**							RE (-)			
49 APU1						Mos					
Eff: 11-Nov-1980						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5214 Rev 1	**Incorporate Electronic Control Unit with Improved Droop Control**							RE (-)			
49 APU1						Mos					
Eff: 29-May-1981						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5214 Rev 2	**Incorporate Electronic Control Unit with Improved Droop Control**							T (A/R)			
49 APU1						Mos					
Eff: 18-May-1982						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5220	**Improved Fuel Control**							T (A/R)			
49 APU1						Mos					
Eff: 10-Nov-1980						Hrs					
						APUS					
49-5245	**Incorporate Improved Combustion Liner, Part No. 3830077-3**							RE (-)			
49 APU1						Mos					
Eff: 12-Jun-1981						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5245 Rev 1	**Incorporate Improved Combustion Liner, Part No. 3830077-3**							RE (-)			
49 APU1						Mos					
Eff: 04-Feb-1982						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5245 Rev 2	**Incorporate Improved Combustion Liner, Part No. 3830077-3**							T (A/R)			
49 APU1						Mos					
Eff: 24-May-1982						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5267	**Rmv Heat Shield From Turb Wheel Deflect Assy**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-5267 Rev 1	**Rmv Heat Shield From Turb Wheel Deflect Assy**							T (A/R)			
49 APU1						Mos					
Eff: 17-Feb-1984						Hrs					
						APUS					
49-5285	**Incorporate Improved Oil Seal**							T (A/R)			
49 APU1						Mos					
Eff: 21-Oct-1981						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-5327	**Incorporate Improved Fuel Control Unit**							T (A/R)			
49 APU1						Mos					
Eff: 29-Apr-1982						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5335	**Installation Of Controller PN 2117406-3 in place of PN 2117406-2**							T (A/R)			
49 APU1						Mos					
Eff: 27-Jul-1982						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5344	**Incorporate Electronic Control Unit with Redundant Overspeed Protection and Icreased Reliability, Replace ECU PN 2117406-1/-2 with PN 2117406-4**							RE (-)			
49 APU1						Mos					
Eff: 23-Nov-1983						Hrs					
(AVG MAN HRS: 0.5)						APUS					
49-5344 Rev 1	**Incorporate Electronic Control Unit with Redundant Overspeed Protection and Icreased Reliability, Replace ECU PN 2117406-1/-2 with PN 2117406-4**							RE (-)			
49 APU1						Mos					
Eff: 23-Jan-1984						Hrs					
(AVG MAN HRS: 0.5)						APUS					
49-5344 Rev 2	**Incorporate Electronic Control Unit with Redundant Overspeed Protection and Icreased Reliability, Replace ECU PN 2117406-1/-2 with PN 2117406-4**							RE (-)			
49 APU1						Mos					
Eff: 17-Apr-1985						Hrs					
(AVG MAN HRS: 0.5)						APUS					
49-5344 Rev 3	**Incorporate Electronic Control Unit with Redundant Overspeed Protection and Icreased Reliability, Replace ECU PN 2117406-1/-2 with PN 2117406-4**							T (A/R)			
49 APU1						Mos					
Eff: 14-Mar-1986						Hrs					
(AVG MAN HRS: 0.5)						APUS					
49-5400	**Incorporate Electronic Control Unit with Redundant Overspeed Protection and Icreased Reliability, Replace ECU PN 2117406-3 with PN 2117406-5**							RE (-)			
49 APU1						Mos					
Eff: 23-Nov-1983						Hrs					
(AVG MAN HRS: 0.5)						APUS					
49-5400 Rev 1	**Incorporate Electronic Control Unit with Redundant Overspeed Protection and Icreased Reliability, Replace ECU PN 2117406-3 with PN 2117406-5**							RE (-)			
49 APU1						Mos					
Eff: 23-Jan-1984						Hrs					
(AVG MAN HRS: 0.5)						APUS					
49-5400 Rev 2	**Incorporate Electronic Control Unit with Redundant Overspeed Protection and Icreased Reliability, Replace ECU PN 2117406-3 with PN 2117406-5**							RE (-)			
49 APU1						Mos					
Eff: 17-Apr-1985						Hrs					
(AVG MAN HRS: 0.5)						APUS					
49-5400 Rev 3	**Incorporate Electronic Control Unit with Redundant Overspeed Protection and Icreased Reliability, Replace ECU PN 2117406-3 with PN 2117406-5**							T (A/R)			
49 APU1						Mos					
Eff: 17-Mar-1986						Hrs					
(AVG MAN HRS: 0.5)						APUS					
49-5458	**Replace Fuel Control Unit**							T (A/R)			
49 APU1						Mos					
Eff: 20-Sep-1983						Hrs					
						APUS					
49-5465	**Repl Ball Bearing 3822004-1 W/3822129-1**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-5465 Rev 1	**Repl Ball Bearing 3822004-1 W/3822129-1**							T (A/R)			
49 APU1						Mos					
Eff: 13-Jan-1986						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-5557	**Incorporate of Improved Combustion Chamber CAP to prevent Hot Spots on Combustor and Tutbine Plenum**							T (A/R)			
49 APU1						Mos					
Eff: 14-Dec-1984						Hrs					
(AVG MAN HRS: 1)						APUS					
49-5622	**Inspection Of Igniter Plug**							T (A/R)			
49 APU1						Mos					
Eff: 13-Jan-1986						Hrs					
						APUS					
49-5663	**Convert 109776-1-1 To -3-1 Or 2-1 To -4-1**							T (A/R)			
49 APU1						Mos					
Eff: 12-Jun-1986						Hrs					
						APUS					
49-5963	**Add Washer To Air Filter Installation**							T (A/R)			
49 APU1						Mos					
Eff: 12-Dec-1990						Hrs					
						APUS					
49-60-00-710-801-01	**Operational Test of the APU Fuel Shut-Off Electric Valve and Fire Detection Circuit - APU Shut-Off Valve (189H)**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
49 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
49-6001	**Inc Improved Turb Nozzle 3846001-5 Or -6/-7/-8**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-6001 Rev 1	**Inc Improved Turb Nozzle 3846001-5 Or -6/-7/-8**							T (A/R)			
49 APU1						Mos					
Eff: 23-Apr-1987						Hrs					
						APUS					
49-6009	**Incorporate Starter Motor & Starter Clutch Assy**							RE (-)			
49 APU1						Mos					
Eff: 14-May-1986						Hrs					
(AVG MAN HRS: 20)						APUS					
49-6009 Rev 1	**Incorporate Starter Motor & Starter Clutch Assy**							RE (-)			
49 APU1						Mos					
Eff: 08-Aug-1986						Hrs					
(AVG MAN HRS: 20)						APUS					
49-6009 Rev 2	**Incorporate Starter Motor & Starter Clutch Assy**							T (A/R)			
49 APU1						Mos					
Eff: 25-May-1990						Hrs					
(AVG MAN HRS: 20)						APUS					
49-6013	**Inc Improved Compressor Seal Assy 3826016-5**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-6013 Rev 1	**Inc Improved Compressor Seal Assy 3826016-5**							T (A/R)			
49 APU1						Mos					
Eff: 14-Nov-1986						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-6014	**Inc Improved Compressor Inlet Hsg 3810036-3**							T (A/R)			
49 APU1						Mos					
Eff: 06-Aug-1986						Hrs					
						APUS					
49-6040	**Incorporate Improved Load Control Valve PN 109776-3-1**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 29-Jun-1987						Hrs					
(AVG MAN HRS: 1)						APUS					
49-6043	**Inc Improved Compressor Inlet Hsg 3810322-1**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-6043 Rev 1	**Inc Improved Compressor Inlet Hsg 3810322-1**							T (A/R)			
49 APU1						Mos					
Eff: 09-Jun-1988						Hrs					
						APUS					
49-6047	**Inspection Of Surge Cont Valve Hose Clamping**							T (A/R)			
49 APU1						Mos					
Eff: 06-Jul-1987						Hrs					
						APUS					
49-6052	**Improve Hot Sect Life, Inc Improved Turb Rtr**							T (A/R)			
49 APU1						Mos					
Eff: 26-Apr-1988						Hrs					
						APUS					
49-6057	**Improve Hot Sect Life, Inc Improved Turb Noz**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-6057 Rev 1	**Improve Hot Sect Life, Inc Improved Turb Noz**							T (A/R)			
49 APU1						Mos					
Eff: 25-May-1990						Hrs					
						APUS					
49-6068	**Rewk Combustion Chamber, Incorporate Igniter Shield**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-6068 Rev 1	**Rewk Combustion Chamber, Incorporate Igniter Shield**							T (A/R)			
49 APU1						Mos					
Eff: 22-Dec-1989						Hrs					
						APUS					
49-6069	**Incorporate Longer Life Igniter Plug 3888096-2**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-6069 Rev 1	**Incorporate Longer Life Igniter Plug 3888096-2**							T (A/R)			
49 APU1						Mos					
Eff: 22-Dec-1989						Hrs					
						APUS					
49-6074	**Incorporate Turbine Rotor 3842088-1**							T (A/R)			
49 APU1						Mos					
Eff: 02-Mar-1990						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
49-6075	**Incorporate Improved Oil Seal PN 3609761-4**						RE (-)		Recommended	
49 APU1						Mos				
Eff: 22-Jun-1990						Hrs				
						APUS				
49-6075 Rev 1	**Incorporate Improved Oil Seal PN 3609761-4**						T (A/R)		Recommended	
49 APU1						Mos				
Eff: 17-Jan-1992						Hrs				
						APUS				
49-6081	**Repl Planetary Bearings 3860004-1 W/3614129-1**						T (A/R)			
49 APU1						Mos				
Eff: 13-May-1991						Hrs				
						APUS				
49-6091	**One Time Inspection Of Gearbox Bolt, Washer & Seal Washer to determine Presence and Serviceability fo these items**						T (A/R)		Recommended	
49 APU1						Mos				
Eff: 26-Apr-1991						Hrs				
(AVG MAN HRS: 0.3)						APUS				
49-6092	**Inc Thermal Barrier Coated Comb Chamber**						RE (-)			
49 APU1						Mos				
						Hrs				
						APUS				
49-6092 Rev 1	**Inc Thermal Barrier Coated Comb Chamber**						RE (-)			
49 APU1						Mos				
						Hrs				
						APUS				
49-6092 Rev 2	**Inc Thermal Barrier Coated Comb Chamber**						T (A/R)			
49 APU1						Mos				
Eff: 19-Feb-1993						Hrs				
						APUS				
49-6097	**Replace Existing Combustr Drain Valve With an Orifice Fitting**						RE (-)		Optional	
49 APU1						Mos				
Eff: 31-May-1991						Hrs				
						APUS				
49-6097 Rev 1	**Replace Existing Combustr Drain Valve With an Orifice Fitting**						T (A/R)		Optional	
49 APU1						Mos				
Eff: 07-Feb-1992						Hrs				
						APUS				
49-6099	**Incorporate Improved Load Control Valve PN 109776-3-2**						T (A/R)		Recommended	
49 APU1						Mos				
Eff: 26-Jul-1991						Hrs				
						APUS				
49-6105	**Inc Improved Cprsr Inlet Seal Assy & Seal Rtr**						T (A/R)			
49 APU1						Mos				
Eff: 20-Sep-1991						Hrs				
						APUS				
49-6106	**Inc Turbine Rotor 3615880-1**						T (A/R)			
49 APU1						Mos				
Eff: 20-Sep-1991						Hrs				
						APUS				
49-6107	**Dimensional Discrepancy May Exist On Turb Rtr**						T (A/R)			
49 APU1						Mos				
Eff: 15-Nov-1991						Hrs				
						APUS				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
49-6108	**Inc Igniter Plug 3888096-3/-4**						T (A/R)			
49 APU1						Mos				
Eff: 20-Sep-1991						Hrs				
						APUS				
49-6113	**Inc Improved Igniter Plug Lead 3888207-1**						T (A/R)		Optional	
49 APU1						Mos				
Eff: 13-Dec-1991						Hrs				
						APUS				
49-6119	**Improperly Manufactured Oil Seal PN 3609761-4**						T (A/R)		Recommended	
49 APU1						Mos				
Eff: 17-Jan-1992						Hrs				
(AVG MAN HRS: 1)						APUS				
49-6121	**Inc Improved Oil Pump Idler Gear Brg**						T (A/R)			
49 APU1						Mos				
Eff: 05-Jun-1992						Hrs				
						APUS				
49-6122	**Inc Improved Turb Housing Scroll 3846004-9**						T (A/R)			
49 APU1						Mos				
Eff: 19-Mar-1993						Hrs				
						APUS				
49-6125	**Incorporate Improved Combustion Chamber CAP, PN 3615086-2**						T (A/R)		Recommended	
49 APU1						Mos				
Eff: 19-Mar-1993						Hrs				
						APUS				
49-6137	**Rewk Or Reident Oil Level & Filler Cap Assy**						RE (-)			
49 APU1						Mos				
						Hrs				
						APUS				
49-6137 Rev 1	**Rewk Or Reident Oil Level & Filler Cap Assy**						T (A/R)			
49 APU1						Mos				
Eff: 12-Dec-1995						Hrs				
						APUS				
49-6140	**Incorporate Improved Igniter Plug Lead PN 3888302-3**						T (A/R)		Optional	
49 APU1						Mos				
Eff: 20-May-1994						Hrs				
						APUS				
49-6149	**Inc Improved Cprsr Seal Assy, Inlet Hsg**						RE (-)			
49 APU1						Mos				
						Hrs				
						APUS				
49-6149 Rev 1	**Inc Improved Cprsr Seal Assy, Inlet Hsg**						RE (-)			
49 APU1						Mos				
						Hrs				
						APUS				
49-6149 Rev 2	**Inc Improved Cprsr Seal Assy, Inlet Hsg**						T (A/R)			
49 APU1						Mos				
Eff: 13-Mar-2013						Hrs				
						APUS				
49-6153	**Inc Igniter Plug 3888366-1**						T (A/R)			
49 APU1						Mos				
Eff: 18-Oct-1994						Hrs				
						APUS				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-6155	**Repl Cprsr Inlet Hsg & Planetary Gr Bolts**							T (A/R)			
49 APU1						Mos					
Eff: 02-Dec-1994						Hrs					
						APUS					
49-6163	**Authorization To Replace Fuel Control Unit**							T (A/R)			
49 APU1						Mos					
Eff: 11-Aug-1995						Hrs					
						APUS					
49-6522	**Repl Thr Wshr, Btfl Pl & Rewk Actr Hsg**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-6522 Rev 1	**Repl Thr Wshr, Btfl Pl & Rewk Actr Hsg**							T (A/R)			
49 APU1						Mos					
Eff: 27-Jan-1995						Hrs					
						APUS					
49-7148	**Change Fuel Control Assy 3882600-5 To -8**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-7148 Rev 1	**Change Fuel Control Assy 3882600-5 To -8**							T (A/R)			
49 APU1						Mos					
Eff: 03-Jul-1996						Hrs					
						APUS					
49-7271	**Invalid - Life Limited Components**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-7271 Rev 1	**Invalid - Life Limited Components**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-7271 Rev 2	**Invalid - Life Limited Components**							T (A/R)			
49 APU1						Mos					
Eff: 13-Mar-1997						Hrs					
						APUS					
49-7286	**Repl Atomizer Gasket 3612610-1 W/3830475-1**							T (A/R)			
49 APU1						Mos					
Eff: 30-Oct-1996						Hrs					
						APUS					
49-7308	**Exchange Of Specific Roller Bearings, Part No. 3842004-1 Manufactured By Fag Canada**							T (A/R)			
49 APU1						Mos					
Eff: 23-Oct-1996						Hrs					
						APUS					
49-7394	**Airborne Auxiliary Power - Gas Turbine Engine - Return Of New Oil Filters, Part No 365303-1 Pti From The Field And Inspection Of Effected APUs If Experiencing Lop Shutdowns**							T (A/R)			
49 APU1						Mos					
Eff: 22-Dec-1997						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
49-7416	**Replace Spring Tension Washers, P/N 3606837-1 With P/N 3606837-2**						RE (-)			
49 APU1					Mos					
					Hrs					
					APUS					
49-7416 Rev 1	**Replace Spring Tension Washers, P/N 3606837-1 With P/N 3606837-2**						RE (-)			
49 APU1					Mos					
					Hrs					
					APUS					
49-7416 Rev 2	**Replace Spring Tension Washers, P/N 3606837-1 With P/N 3606837-2**						T (A/R)			
49 APU1					Mos					
Eff: 22-Dec-2003					Hrs					
					APUS					
49-7540	**Invalid - 1X Inspct/Rplc Coupling P/N234-511-9059**						RE (-)			
49 APU1					Mos					
					Hrs					
					APUS					
49-7540 Rev 1	**Invalid - 1X Inspct/Rplc Coupling P/N234-511-9059**						RE (-)			
49 APU1					Mos					
					Hrs					
					APUS					
49-7540 Rev 2	**Invalid - 1X Inspct/Rplc Coupling P/N234-511-9059**						T (A/R)			
49 APU1					Mos					
Eff: 05-Nov-2002					Hrs					
					APUS					
49-7717	**Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement Of The Coupling Clamp, P/N 234-511-9059, T-Bolt (Fuel Control To Lube Pump Flanges)**						RE (-)			
49 APU1					Mos					
					Hrs					
					APUS					
49-7717 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement Of The Coupling Clamp, P/N 234-511-9059, T-Bolt (Fuel Control To Lube Pump Flanges)**						RE (-)			
49 APU1					Mos					
					Hrs					
					APUS					
49-7717 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement Of The Coupling Clamp, P/N 234-511-9059, T-Bolt (Fuel Control To Lube Pump Flanges)**						T (A/R)			
49 APU1					Mos					
Eff: 17-Apr-2003					Hrs					
					APUS					
49-7933	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**						RE (-)			
49 APU1					Mos					
Eff: 24-Apr-2007					Hrs					
					APUS					
49-7933 Rev 1	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**						RE (-)		Service Bulletin	
49 APU1					Mos					
Eff: 04-Jun-2007					Hrs					
					APUS					
49-7933 Rev 10	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**						T (A/R)		Service Bulletin	
49 APU1					Mos					
Eff: 18-Jan-2022					Hrs					
					APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-7933 Rev 2	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 09-Apr-2010						Hrs					
						APUS					
49-7933 Rev 3	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 31-Oct-2011						Hrs					
						APUS					
49-7933 Rev 4	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 12-Aug-2014						Hrs					
						APUS					
49-7933 Rev 5	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 23-Oct-2014						Hrs					
						APUS					
49-7933 Rev 6	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							RE (-)		Service Bulletin	
49 APU1						Mos					
						Hrs					
						APUS					
49-7933 Rev 7	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 09-Feb-2017						Hrs					
						APUS					
49-7933 Rev 8	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 27-Jul-2017						Hrs					
						APUS					
49-7933 Rev 9	**Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 03-Apr-2020						Hrs					
						APUS					
49-7997	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines.**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 16-Sep-2009						Hrs					
(ZONE: .)						APUS					
49-7997 Rev 1	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 11-Feb-2010						Hrs					
						APUS					
49-7997 Rev 2	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 22-Dec-2010						Hrs					
						APUS					
49-7997 Rev 3	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							RE (-)		Service Bulletin	
49 APU1						Mos					
Eff: 16-Jan-2014						Hrs					
						APUS					
49-7997 Rev 4	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 12-Jan-2015						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
49-7997 Rev 5	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							T (-)		Service Bulletin	
49 APU1						Mos					
Eff: 03-Feb-2017						Hrs					
						APUS					
49-7997 Rev 6	**Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines**							T (A/R)		Service Bulletin	
49 APU1						Mos					
Eff: 05-Nov-2020						Hrs					
						APUS					
49-8252	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (-)			
49 APU1						Mos					
Eff: 31-Aug-2018						Hrs					
						APUS					
49-8252 Rev 1	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (-)			
49 APU1						Mos					
Eff: 07-Mar-2019						Hrs					
						APUS					
49-8252 Rev 2	**Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs**							T (A/R)		Service Bulletin	
49 APU1						Mos					
Eff: 13-Oct-2020						Hrs					
						APUS					
499110	**APU - Soap Check Oil**							RE			**≈16-Nov-2025**
49 APU1						Mos	22-Jul-2024				
						Hrs	4,627.2	300		4,927.2	260.4 Hrs
						APUS					
49-A5476	**Chk P/N Of Ftg Instl At Out P Of Fuel Solv**							RE (-)			
49 APU1						Mos					
						Hrs					
						APUS					
49-A5476 Rev 1	**Chk P/N Of Ftg Instl At Out P Of Fuel Solv**							T (A/R)			
49 APU1						Mos					
Eff: 09-Jan-1984						Hrs					
						APUS					
70721597-49-8166	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 02-Jul-2015						Hrs					
						APUS					
70721597-49-8166 Rev 1	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 31-Aug-2015						Hrs					
						APUS					
70721597-49-8166 Rev 2	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**							RE (-)		Recommended	
49 APU1						Mos					
Eff: 25-Oct-2016						Hrs					
						APUS					
70721597-49-8166 Rev 3	**Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs**							T (A/R)		Recommended	
49 APU1						Mos					
Eff: 13-Oct-2017						Hrs					
(AVG MAN HRS: 1)						APUS					
Note: COMPLIANCE: Honeywell recommends this service bulletin be done for the balance repair of the compressor rotor, PN 70721597-1.											

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
APU 1	**Honeywell - GTCP36-100[A]**							RE (-)			
49 A/F						Mos	11-Dec-2024				
3800016-3-1	Time at install: 4627.2 Hrs					Hrs	13,453.3				
P-223						Ldg	9,091				
						Flt	9,091				
APU-146	**Special On-wing Troubleshooting Check Sheet for Oil “Smell-In-Cabin” (SIC) Complaints**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 18-Aug-2007						Hrs					
						APUS					
APU-151	**Honeywell Commercial Auxiliary Power Unit (APU) Oil Approvals.**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 25-Oct-2007						Hrs					
						APUS					
APU-41	**PRECAUTIONARY MEASURES TO PREVENT EXCESSIVE AXIAL LOADING OF APUGENERATOR OUTPUT SHAFT SEALS AND BEARINGS**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 05-May-1989						Hrs					
						APUS					
APU-41 Rev 1	**PRECAUTIONARY MEASURES TO PREVENT EXCESSIVE AXIAL LOADING OF APUGENERATOR OUTPUT SHAFT SEALS AND BEARINGS**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 05-May-1989						Hrs					
						APUS					
APU-42	**IMPROPER SERVICING PROCEDURES - UNAUTHORIZED USE OF SILICONE BASEDLUBRICANTS ON OIL-WETTED COMPONENTS WITHIN THE APU'SLUBRICATION SYSTEM**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 17-Feb-1989						Hrs					
						APUS					
APU-46	**RECOMMENDED ONE-TIME INSPECTION OF NAMEPLATE RIVETS FOR PROPERINSTALLATION**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 25-Feb-1991						Hrs					
						APUS					
APU-7	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 03-Mar-1988						Hrs					
						APUS					
APU-7 Rev 1	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 03-Mar-1988						Hrs					
						APUS					
APU-7 Rev 2	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 02-Mar-2015						Hrs					
						APUS					
APU-78	**Auxiliary Power Unit (APU) Operational Instructions**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 05-Aug-2003						Hrs					
						APUS					
APU-78 Rev 1	**Auxiliary Power Unit (APU) Operational Instructions**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 30-Sep-2004						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
APU-78 Rev 2	**Auxiliary Power Unit (APU) Operational Instructions**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 30-Sep-2004						Hrs					
						APUS					
APU-83	**SPOTLIGHT TROUBLESHOOTING SYSTEM**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 24-Dec-2003						Hrs					
						APUS					
APU-83 Rev 1	**SPOTLIGHT TROUBLESHOOTING SYSTEM**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 31-Jan-2007						Hrs					
						APUS					
APU-83 Rev 2	**SPOTLIGHT TROUBLESHOOTING SYSTEM**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 31-Jan-2007						Hrs					
						APUS					
D200904000013	**To advise the field of the release of Service Bulletin GTCP36-49-7969.**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 13-Apr-2009						Hrs					
						APUS					
D201010000068	**Operations in Volcanically Active Areas**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 03-Mar-2011						Hrs					
						APUS					
D201012000013	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85(Krypton 85) Above 10,000 Becquerels**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 08-Mar-2011						Hrs					
						APUS					
D201012000013 Rev 1	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85(Krypton 85) Above 10,000 Becquerels**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 15-Jan-2015						Hrs					
						APUS					
D201107000024	**Approved Use of Hydroprocessed Esters and Fatty Acids (HEFA) Biofuel Blends for all Honeywell Commercial Auxiliary Power Units (APU)**							T (-)		Service Information Letter	
49 APU1						Mos					
Eff: 07-Sep-2011						Hrs					
						APUS					
D201107000024 Rev 1	**Approved Use of Biofuel Blends for All Honeywell Commercial and Military Auxiliary Power Units (APU)**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 03-Jun-2020						Hrs					
						APUS					
D201107000065	**Auxiliary Power Unit Operations in Volcanically Active Areas**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 19-Aug-2011						Hrs					
						APUS					
D201112000050	**Acceptance Criteria for On-Wing Borescope Inspections**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 13-Jan-2012						Hrs					
						APUS					
D201112000050 Rev 1	**Acceptance Criteria for On-Wing Borescope Inspections**							T (-)		Service Information Letter	
49 APU1						Mos					
Eff: 14-Aug-2012						Hrs					
						APUS					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D201112000050 Rev 2	**Acceptance Criteria for On-Wing Borescope Inspections**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 26-Nov-2024						Hrs					
						APUS					
F50-002	**Installation of a Garrett GTCP 36-100A APU**							T (A/R)			
49 A/F						Mos					
Eff: 07-Mar-1980						Hrs					
						Ldg					
Note: M0378						Flt					
F50-029	**APU- Bleed air valve indication - Wiring inserted in the computer wiring**							RE (-)			
49 A/F						Mos					
Eff: 14-Nov-1979						Hrs					
						Ldg					
						Flt					
F50-051	**APU - Installation of a high pressure fuel control unit**							RE (-)			
49 A/F						Mos					
						Hrs					
						Ldg					
Note: M0103, M0792, A/C with GTCP36 -100A Garrett APU P/N 3800016-2						Flt					
F50-051 R1	**APU - Installation of a high pressure fuel control unit**							T (A/R)			
49 A/F						Mos					
Eff: 20-Oct-1981						Hrs					
						Ldg					
Note: M0103, M0792, A/C with GTCP36 -100A Garrett APU P/N 3800016-2						Flt					
F50-065	**Diode added between the APU control and fire detection circuits (Superseded by SB-F50-080) (No longer applicable)**							T (A/R)			
49 A/F						Mos					
Eff: 16-Jul-1980						Hrs					
						Ldg					
Note: M0393						Flt					
F50-077	**APU Exhaust gas grille reinforced and possibility of removal**							T (A/R)			
49 A/F						Mos					
Eff: 09-Feb-1981						Hrs					
						Ldg					
Note: M0600, A/C with APU						Flt					
F50-080	**APU - Separate power supply for the indication and control systems**							T (A/R)			
49 A/F						Mos					
Eff: 28-Nov-1980						Hrs					
						Ldg					
Note: M0619						Flt					
F50-086	**Additional sealing between the APU casing and the rear compartment floor**							RE (-)			
49 A/F						Mos					
						Hrs					
						Ldg					
Note: M0693, 2, 3, 5, 7, 9, 12, 15 to 17, 21, 23, 25, 29, 34, 37 and A/C with an APU (SB F50-0002)						Flt					
F50-086 R1	**Additional sealing between the APU casing and the rear compartment floor**							RE (-)			
49 A/F						Mos					
Eff: 25-Apr-1983						Hrs					
						Ldg					
Note: M0693, 2, 3, 5, 7, 9, 12, 15 to 17, 21, 23, 25, 29, 34, 37 and A/C with an APU (SB F50-0002)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-111	**APU box draining improved**							T (A/R)			
49 A/F						Mos					
Eff: 15-Nov-1982						Hrs					
						Ldg					
Note: M0881A, 1 to 65, 67 to 77 and A/C with an APU (SB F50-002)						Flt					
F50-375	**Installation of a new A.P.U power monitoring system**							RE (-)			
49 A/F						Mos					
						Hrs					
						Ldg					
Note: M2988, M2726						Flt					
F50-375 R1	**Installation of a new A.P.U power monitoring system**							RE (-)			
49 A/F						Mos					
Eff: 11-Jan-2006						Hrs					
						Ldg					
Note: M2988, M2726						Flt					
F50-384	**Installation of a new APU power monitoring system**							RE (-)			
49 A/F						Mos					
						Hrs					
						Ldg					
Note: M2988, M2784, 2 to 252 with M0378						Flt					
F50-384 R1	**Installation of a new APU power monitoring system**							RE (-)			
49 A/F						Mos					
						Hrs					
						Ldg					
Note: M2988, M2784, 2 to 252 with M0378						Flt					
F50-384 R2	**Installation of a new APU power monitoring system**							T (A/R)			
49 A/F						Mos					
Eff: 11-Jan-2006						Hrs					
						Ldg					
Note: M2988, M2784, 2 to 252 with M0378						Flt					
F50-462	**Checking for possible interference between wiring/piping and the feeder cables/APU generator**							RE (-)			
49 A/F						Mos					
						Hrs					
						Ldg					
Note: 2 to 252 with APU (SB F50-002 or M0378) and 253 to 343						Flt					
F50-462 R1	**Checking for possible interference between wiring/piping and the feeder cables/APU generator**							RE (-)			
49 A/F						Mos					
Eff: 13-Oct-2005						Hrs					
						Ldg					
Note: 2 to 252 with APU (SB F50-002 or M0378) and 253 to 343						Flt					
F50-536	**Prevention of possible chafing of APU fuel pipe**							RE (-)			
49 A/F						Mos					
						Hrs					
						Ldg					
Note: M3242, A/C with an APU as per SB F50-002 (M378)						Flt					
F50-536 R1	**Prevention of possible chafing of APU fuel pipe**							T (A/R)			
49 A/F						Mos					
Eff: 04-Feb-2015						Hrs					
						Ldg					
Note: M3242, A/C with an APU as per SB F50-002 (M378)						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
SIL 78	**36-150 EMB APU Lift Fixture, Retrofit of sub-component PN 31060 shoulder bolt**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 11-Sep-2011						Hrs					
						APUS					
SIL APU-152	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 18-Jul-2008						Hrs					
						APUS					
SIL APU-152 Rev 1	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 24-Jul-2009						Hrs					
						APUS					
SIL APU-152 Rev 2	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 30-Nov-2010						Hrs					
						APUS					
SIL APU-152 Rev 3	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 19-Feb-2015						Hrs					
						APUS					
SIL APU-152 Rev 4	**Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 08-Feb-2018						Hrs					
						APUS					
SIL APU-7	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
						Hrs					
						APUS					
SIL APU-7 Rev 1	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 03-Mar-1988						Hrs					
						APUS					
SIL APU-7 Rev 2	**Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 02-Mar-2015						Hrs					
						APUS					
SIL D201701000026	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs**							RE (-)		Service Information Letter	
49 APU1						Mos					
Eff: 30-Jan-2017						Hrs					
						APUS					
SIL D201701000026 Rev 1	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs**							T (-)		Service Information Letter	
49 APU1						Mos					
Eff: 23-Jan-2018						Hrs					
						APUS					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
SIL D201701000026 Rev 2	**Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine worksheet for 36-100, 36-150, RE100, and RE220 APUs**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 21-Mar-2018						Hrs					
						APUS					
SIL No. APU-49 Rev 10	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
						Hrs					
						APUS					
	Note: COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).										
SIL No. APU-49 Rev 11	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units(APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
						Hrs					
						APUS					
	Note: Analyst/operator will need to manually set the calendar start. COMPLIANCE: Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).										
SIL No. APU-49 Rev 12	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**							RE (-)		Service Information Letter	
49 APU1						Mos					
						Hrs					
						APUS					
	Note: COMPLIANCE: First and subsequent oil and filter sample. Every Aircraft 'A' check or every 500 APU hours or per AMM or MM criteria (customer option).										
SIL No. APU-49 Rev 13	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**							T (-)		Service Information Letter	
49 APU1						Mos					
Eff: 23-Nov-2023						Hrs					
						APUS					
SIL No. APU-49 Rev 14	**Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)**							T (A/R)		Service Information Letter	
49 APU1						Mos					
Eff: 12-Feb-2025						Hrs					
						APUS					
▼ 51 - STANDARD PRACTICES AND STRUCTURES - GENERAL											
51-00-00-210-801-01	**General Visual Inspection Of The Control Surfaces And Exposed Areas Of The Aircraft Skin**							RE (-)			
51 A/F						Mos	16-Sep-2018				
						Hrs					
						Ldg					
						Flt					
▼ 52 - DOORS											
	Baggage Compartment Counterbalance Cable							RE (O/C)			
52 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Baggage Compartment Counterbalance Cable							RE (O/C)			
52 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Baggage Compartment Door							RE (O/C)			
52 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Baggage Compartment Door Counterbalance Pulley							RE (O/C)			
	52 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Door Baggage Compt Seal							RE (O/C)			
	52 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Emergency Exit							RE (H/T)			
	52 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Emergency Exit							RE (H/T)			
	52 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Door							RE (O/C)			
	52 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Door Pneumatic Actuator							RE (O/C)			
	52 A/F						Mos	09-Feb-2015				
	107-15-0						Hrs					
	1013						Ldg					
							Flt					
		Passenger Door Seal							RE (O/C)			
	52 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Rear Compartment Door							RE (O/C)			
	52 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2000-12-15		**Overwing Emergency Exit - Inspect Overwing Emergency Exits (Superseded by FAA AD 2008-04-14)**							RE (-)		Mandatory	
	52 A/F						Mos	08-Jul-2000				
	Complied With						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					
2008-04-14		**Overwing Emergency Exit - Operational Test and Inspection**							RE		Mandatory	
	52 A/F						Mos	14-Sep-2023	24		14-Sep-2025	6.4 Months
	Eff: 20-Jul-2000 Complied With						Hrs	13,276.7				
	(ISSUING AUTHORITY: FAA)						Ldg	8,977				
							Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2008-04-14 L EXIT	**Operational Test And Inspect Left Overwing Emergency Exit**							RE (-)			
52 A/F						Mos	16-Sep-2018				
						Hrs					
						Ldg					
						Flt					
2008-04-14 RT EXIT	**Operational Test And Inspect Right Overwing Emergency Exit**							RE (-)			
52 A/F						Mos	16-Sep-2018				
						Hrs					
						Ldg					
						Flt					
2017-01-07	**Doors (This AD has been superseded by AD 2018-11-10)**							RE (-)		Mandatory	
52 A/F						Mos					
Eff: 10-Feb-2017						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-01-07 Par. (g)	**Doors - Main Entry/Passenger/Crew Door Check or Functional Test**							RE (-)		Mandatory	
52 A/F						Mos	03-Apr-2017				
Eff: 10-Feb-2017						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2017-01-07 Par. (h)	**Doors - Main Entry/Passenger/Crew Door Closing Inspections, Adjustments, and Operational Tests and Corrective Actions**							T (-)		Mandatory	
52 A/F						Mos					
Eff: 10-Feb-2017						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2018-11-10	**Doors - Main Entry/Passenger/Crew Door Closing Inspections, Adjustments, and Operational Tests and Corrective Actions (This AD replaces AD 2017-01-07)**							RE (-)		Mandatory	
52 A/F						Mos	09-Jul-2018				
Eff: 09-Jul-2018						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2018-11-10 Par. (g)	**Doors - Retained Main Entry/Passenger/Crew Door Closing Inspections, Adjustments, and Operational Tests and Corrective Actions, With No Changes**							RE (-)		Mandatory	
52 A/F						Mos					
Eff: 10-Feb-2017						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2018-11-10 Par. (h)	**Doors - New Requirement of This AD: Repetitive Main Entry/Passenger/Crew Door Closing Inspections, Adjustments, and Operational Tests and Corrective Actions**							RE		Mandatory	
52 A/F						Mos	19-Jun-2024	72		19-Jun-2030	5.3 Years
Complied With	NO DEFECTS NOTED AT THIS TIME					Hrs	13,310.4				
(ISSUING AUTHORITY: FAA)						Ldg	9,006				
Note: COMPLIANCE: Within 72 months after accomplishing the actions required by paragraph (g) of this AD, and thereafter at intervals not to exceed 72 months.						Flt	9,006				
340-52-009	**Cargo Door - Replacement of Cargo Door Cables**							RE (-)		Optional	
52 A/F						Mos	18-Jun-1987				
Eff: 25-Nov-1986 Complied With						Hrs					
Mod:1454						Ldg					
						Flt					
52-00-00-640-802-01	**Lubrication of the Visible Door Hinges**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
(Tol. Adjustment: -83d)						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
52-10-00-200-803-01	**Inspection Check and Servicing of the Passenger Door - Passenger Door (900Ma)**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-01	**Servicing of the Passenger Door - Check of Structure and Latches**							RE		Acft Maint Ops (5-10)	
52 A/F						Mos	14-Sep-2023	24		23-Mar-2025	17 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
(Tol. Adjustment: -171d) (SOURCE: Falcon 50/50EX MPD)						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-01 (5-40)	**Servicing of the Passenger Door - Check of Structure and Latches**							RE		ALI, AWL (5-40)	
52 A/F						Mos	14-Sep-2023	24		23-Mar-2025	17 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
(Tol. Adjustment: -171d) (SOURCE: Falcon 50/50EX MM 5-40 (DGT 113872))						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-02	**Servicing of the Passenger Door - Check of Opening and Closing Mechanism**							RE		Acft Maint Ops (5-10)	
52 A/F						Mos	14-Sep-2023	24		23-Mar-2025	17 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
(Tol. Adjustment: -171d) (SOURCE: Falcon 50/50EX MPD)						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-02 (5-40)	**Servicing of the Passenger Door - Check of Opening and Closing Mechanism**							RE		ALI, AWL (5-40)	
52 A/F						Mos	14-Sep-2023	24		23-Mar-2025	17 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
(Tol. Adjustment: -171d) (SOURCE: Falcon 50/50EX MM 5-40 (DGT 113872))						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-03	**Servicing of the Passenger Door - Greasing / Lubrication**							RE		Acft Maint Ops (5-10)	
52 A/F						Mos	14-Sep-2023	24		23-Mar-2025	17 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
(Tol. Adjustment: -171d) (SOURCE: Falcon 50/50EX MPD)						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-03 (5-40)	**Servicing of the Passenger Door - Greasing / Lubrication**							RE		ALI, AWL (5-40)	
52 A/F						Mos	14-Sep-2023	24		23-Mar-2025	17 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
(Tol. Adjustment: -171d) (SOURCE: Falcon 50/50EX MM 5-40 (DGT 113872))						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-04	**Servicing of the Passenger Door - Check of the Door Counterbalancing System**							RE		Acft Maint Ops (5-10)	
52 A/F						Mos	14-Sep-2023	24		23-Mar-2025	17 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
(Tol. Adjustment: -171d) (SOURCE: Falcon 50/50EX MPD)						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-04 (5-40)	**Servicing of the Passenger Door - Check of the Door Counterbalancing System**							RE		ALI, AWL (5-40)	
52 A/F						Mos	14-Sep-2023	24		23-Mar-2025	17 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
(Tol. Adjustment: -171d) (SOURCE: Falcon 50/50EX MM 5-40 (DGT 113872))						Ldg	8,977				
						Flt	8,977				
52-10-00-610-801-05	**Servicing of the Passenger Door - Check of Door Locked Indication**							RE		Acft Maint Ops (5-10)	
52 A/F						Mos	05-Nov-2024	6		05-May-2025	60 Days
						Hrs	13,427.3	800		14,227.3	706.4 Hrs
(SOURCE: Falcon 50/50EX MPD)						Ldg	9,074				
Note: -						Flt	9,074				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
52-10-00-610-801-05 (5-40)	**Servicing of the Passenger Door - Check of Door Locked Indication**							RE		ALI, AWL (5-40)	
52 A/F						Mos	05-Nov-2024	24		05-Nov-2026	1.7 Years
						Hrs	13,427.3	800		14,227.3	706.4 Hrs
(SOURCE: Falcon 50/50EX MM 5-40 (DGT 113872))						Ldg	9,074				
Note: -						Flt	9,074				
52-10-07-220-801-01	**Detailed Inspection of the Passenger Door Locking Hooks**							RE		Acft Maint Ops (5-10)	**≈14-Nov-2029**
52 A/F						Mos	23-Mar-2005				
						Hrs	10,050.4				
						Ldg					
Note: A/C with M141 (lock P/N F50B295004870A2 or F50B295004880A2)						Flt	7,081	3,750		10,831	1,698 Flt
52-10-07-220-801-01 (5-40)	**Detailed Inspection of the Passenger Door Locking Hooks**							RE		AWL (5-40), CMR	**≈14-Nov-2029**
52 A/F						Mos	23-Mar-2005				
						Hrs	10,050.4				
						Ldg					
Note: A/C with M141 (lock P/N F50B295004870A2 or F50B295004880A2)						Flt	7,081	3,750		10,831	1,698 Flt
52-20-00-610-801-01	**Servicing of the Emergency Exit Door - LH Emergency Exit**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
52-20-00-610-801-02	**Servicing of the Emergency Exit Door - RH Emergency Exit**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
52-20-00-610-801-03	**Servicing of the Emergency Exit Door - Unlocking Test From Inside of LH Emergency Exit Door**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-24M					Mos	14-Sep-2023	24		14-Sep-2025	6.4 Months
						Hrs	13,276.7				
						Ldg	8,977				
Note: No tolerance						Flt	8,977				
52-20-00-610-801-03 (5-40)	**Servicing of the Emergency Exit Door - Unlocking Test From Inside of the LH Emergency Exit Door**							RE		ALI, AWL (5-40)	
52 A/F						Mos	14-Sep-2023	24		14-Sep-2025	6.4 Months
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
52-20-00-610-801-04	**Operational Test of the Emergency Exit Door Unlocking - Unlocking Test From Inside of RH Exit**							RE		Acft Maint Ops (5-10)	
52 A/F						Mos	14-Sep-2023	24		14-Sep-2025	6.4 Months
						Hrs	13,276.7				
						Ldg	8,977				
Note: No tolerance						Flt	8,977				
52-20-00-610-801-04 (5-40)	**Servicing of the Emergency Exit Door - Unlocking Test From Inside of the RH Emergency Exit Door**							RE		ALI, AWL (5-40)	
52 A/F						Mos	14-Sep-2023	24		14-Sep-2025	6.4 Months
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
52-20-00-710-801-03	**Operational Test of the Emergency Exit Door Unlocking - Unlocking Test From Outside of LH Exit**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
52 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
52-20-00-710-801-04	**Operational Test of the Emergency Exit Door Unlocking - Unlocking Test From Outside of RH Exit**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
52 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
						Flt	8,977				
52-20-01-960-801-01	**Discard of the Emergency Exit Doors - LH Emergency Exit Door (900Mb1)**							RE		Comp Maint Ops (5-20)	**≈20-Dec-2073**
52 A/F	Left					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt		26,718		26,718	17,585 Flt
Note: P/N F50B296001XX											
52-20-01-960-801-01 (5-40)	**Discard of the Emergency Exit Doors - LH Emergency Exit Door (900Mb1)**							RE		AWL (5-40), Life Limit	**≈20-Dec-2073**
52 A/F	Left					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt		26,718		26,718	17,585 Flt
Note: P/N F50B296001XX											
52-20-01-960-801-02	**Discard of the Emergency Exit Doors - RH Emergency Exit Door (900Mb2)**							RE		Comp Maint Ops (5-20)	**≈20-Dec-2073**
52 A/F	Right					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt		26,718		26,718	17,585 Flt
Note: P/N F50B296001XX											
52-20-01-960-801-02 (5-40)	**Discard of the Emergency Exit Doors - RH Emergency Exit Door (900Mb2)**							RE		AWL (5-40), Life Limit	**≈20-Dec-2073**
52 A/F	Right					Mos					
Unknown						Hrs					
Unknown						Ldg					
						Flt		26,718		26,718	17,585 Flt
Note: P/N F50B296001XX											
52-30-00-200-801-01 (5-40)	**Visual Inspection of the Baggage Compartment Door**							T		AWL (5-40), SSIP	**≈21-Oct-2072**
52 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C with M142 (SB F50-177)						Flt		26,299		26,299	17,166 Flt
52-30-00-200-802-01	**Inspection of the Baggage Compartment Door Forward Side Fold**							RE (N/A)		Acft Maint Ops (5-10)	
52 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C 002, 003, 004, 006, 008, 010, 011, 013 (without M142 or SB F50-177)						Flt					
52-30-00-200-802-01 (5-40)	**Inspection of the Baggage Compartment Door Forward Side Fold**							RE (N/A)		AWL (5-40), CMR	
52 A/F						Mos					
						Hrs					
Ref:52-240						Ldg					
Note: A/C 002, 003, 004, 006, 008, 010, 011, 013 (without M142 or SB F50-177)						Flt					
52-30-00-610-801-01	**Servicing of the Baggage Compartment Door**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
52-40-00-210-801-01	**General Visual Inspection of the Service Doors**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
52-50-00-710-801-01	**Inspection / Test of the Blowout Doors / Panels**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -195.9d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
52-60-09-610-801-01	**Servicing Of The Rear Compartment Door - Greasing/Lubrication**							RE (A/R)			
52 A/F						Mos	30-Sep-2019				
						Hrs					
						Ldg					
						Flt					
52-60-09-610-801-02	**Servicing Of The Rear Compartment Door - Inspection/Check**							RE (A/R)			
52 A/F						Mos	30-Sep-2019				
						Hrs					
						Ldg					
						Flt					
52-60-09-610-801-03	**Servicing of the Rear Compartment Door**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-36M					Mos	14-Sep-2023	36	+1m	(03-Sep-2025)	6 Months (+30 Days)
(Tol. Adjustment: -345d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
52-70-11-710-801-01	**Operational Test of the S-Duct Door Position Indicating Microswitch**							RE		Acft Maint Ops (5-10)	
52 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
52-70-11-710-801-01 (5-40)	**Operational Test of the S-Duct Door Position Indicating Microswitch**							RE		AWL (5-40), CMR	**≈26-Mar-2052**
52 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	10,000		23,276.7	9,755.8 Hrs
						Ldg	8,977				
						Flt	8,977				
F50-042	**Baggage compartment door - Reinforced fixation of the compensation cable on its pulley**							RE (-)			
52 A/F						Mos					
Eff: 27-Nov-1979						Hrs					
						Ldg					
Note: M0279						Flt					
F50-047	**MED - Improved locking control**							T (A/R)			
52 A/F						Mos					
Eff: 04-Feb-1980						Hrs					
						Ldg					
Note: M0193						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-056	**MED - Rod-to-actuating lever link - Washer added under the pin head**							RE (-)			
52 A/F						Mos					
Eff: 04-Feb-1980						Hrs					
						Ldg					
Note: M0304						Flt					
F50-057	**MED - Improved drainage**							T (A/R)			
52 A/F						Mos					
Eff: 28-Apr-1982						Hrs					
						Ldg					
Note: M0321						Flt					
F50-068	**Rear compartment door - Control lever secured in locked position**							RE (-)			
52 A/F						Mos					
						Hrs					
						Ldg					
Note: M0326						Flt					
F50-068 R1	**Rear compartment door - Control lever secured in locked position**							RE (-)			
52 A/F						Mos					
						Hrs					
						Ldg					
Note: M0326						Flt					
F50-068 R2	**Rear compartment door - Control lever secured in locked position**							RE (-)			
52 A/F						Mos					
						Hrs					
						Ldg					
Note: M0326						Flt					
F50-068 R3	**Rear compartment door - Control lever secured in locked position**							T (A/R)			
52 A/F						Mos					
Eff: 19-Oct-1984						Hrs					
						Ldg					
Note: M0326						Flt					
F50-070	**MED - Locking mechanism improvement**							RE (-)			
52 A/F						Mos					
						Hrs					
						Ldg					
Note: M0193, M0338, M0602-A,						Flt					
F50-070 R1	**MED - Locking mechanism improvement**							T (A/R)			
52 A/F						Mos					
Eff: 15-Nov-1982						Hrs					
						Ldg					
Note: M0193, M0338, M0602-A,						Flt					
F50-115	**Cabin access door - Telescopic ramp attach point reinforced**							RE (-)			
52 A/F						Mos					
						Hrs					
						Ldg					
Note: M0845, 1 to 64, 66, 67, 69 to 72, 74 to 77, 79, 80, 82 to 85, 87 with a telescopic ramp						Flt					
F50-115 R1	**Cabin access door - Telescopic ramp attach point reinforced**							RE (-)			
52 A/F						Mos	18-Jun-1987				
Eff: 21-Jun-1984 Not Applicable	type ramp fitted to aircraft					Hrs	4,087.5				
SB:F50-52-008						Ldg	2,821				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-148	**Emergency exit doors - Improved mechanical strength of the exterior unlocking pushbutton**							RE (-)			
52 A/F						Mos					
						Hrs					
						Ldg					
Note: M1141						Flt					
F50-148 R1	**Emergency exit doors - Improved mechanical strength of the exterior unlocking pushbutton**							T (A/R)			
52 A/F						Mos					
Eff: 11-Dec-1984						Hrs					
						Ldg					
Note: M1141						Flt					
F50-152	**Emergency exit - Security lock**							T (A/R)			
52 A/F						Mos					
Eff: 15-Sep-1985						Hrs					
						Ldg					
Note: M1127						Flt					
F50-168	**Emergency exits - Structural provision for SNC 211-01B1 connectors**							T (A/R)			
52 A/F						Mos					
Eff: 26-Jun-1986						Hrs					
						Ldg					
Note: M1339						Flt					
F50-177	**Baggage compartment door - Local reinforcement of forward side**							RE (-)			
52 A/F						Mos					
Eff: 18-Dec-1987						Hrs					
						Ldg					
Note: M0142						Flt					
F50-188	**MED - Installation of a centering system**							T (A/R)			
52 A/F						Mos					
Eff: 21-Jan-1987						Hrs					
						Ldg					
Note: M0808						Flt					
F50-189	**MED - Installation of an improved technology handrail**							T (A/R)			
52 A/F						Mos					
Eff: 16-Jun-1988						Hrs					
						Ldg					
Note: M1371						Flt					
F50-249	**Baggage compartment door - Improved door counterbalance system reliability**							T (A/R)			
52 A/F						Mos					
Eff: 07-May-1997						Hrs					
						Ldg					
Note: M1925						Flt					
F50-357	**MED - Inside control handle - Improved holding in unlocked position**							T (A/R)			
52 A/F						Mos					
Eff: 11-Apr-2001						Hrs					
						Ldg					
Note: M2567						Flt					
F50-399	**MED - New connection wiring**							T (A/R)			
52 A/F						Mos					
Eff: 15-May-2003						Hrs					
						Ldg					
Note: M2419						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-422	**Refueling door - Installation of a door with an improved latching system**							RE (-)			
52 A/F						Mos					
						Hrs					
						Ldg					
Note: M2006						Flt					
F50-422 R1	**Refueling door - Installation of a door with an improved latching system**							T (A/R)			
52 A/F						Mos					
Eff: 16-Jun-2005						Hrs					
						Ldg					
Note: M2006						Flt					
F50-430	**Rear lavatory servicing door - Installation of a door with an improved latching system**							RE (-)			
52 A/F						Mos					
						Hrs					
						Ldg					
Note: M2015, 2 to 262 with a rear lavatory servicing door P/N F50B281043200						Flt					
F50-430 R1	**Rear lavatory servicing door - Installation of a door with an improved latching system**							T (A/R)			
52 A/F						Mos					
Eff: 19-Apr-2005						Hrs					
						Ldg					
Note: M2015, 2 to 262 with a rear lavatory servicing door P/N F50B281043200						Flt					
F50-454	**TCAS lower antenna door (170A) - Improved protection against corrosion**							RE (-)			
52 A/F						Mos					
Eff: 15-Dec-2004						Hrs					
						Ldg					
Note: M2948						Flt					
F50-531	**MED closing inspection**							RE (-)			
52 A/F						Mos	03-Apr-2017				
Eff: 16-Dec-2014						Hrs	13,067.6				
						Ldg	8,830				
Note: AD EASA 2015-0007						Flt					
▼ 53 - FUSELAGE											
	Flight Compartment Removable Window Fairing							RE (O/C)			
53 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Nose Cone Assembly							RE (O/C)			
53 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Wing To Fuselage Connecting at Frame 29 Rod							RE (O/C)			
53 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Wing To Fuselage Connecting at Frame 29 Rod							RE (O/C)			
53 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2004-07-03	**Fuselage attachments**							RE (-)		Mandatory	
53 A/F						Mos	12-May-2010				
Eff: 04-May-2004						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2004-07-03 Paragraph (a)	**Fuselage attachments - Inspections**							RE (-)		Mandatory	
53 A/F						Mos					
Eff: 04-May-2004						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2004-07-03 Paragraph (b)	**Fuselage attachments - Corrective Actions**							RE (-)		Mandatory	
53 A/F						Mos					
Eff: 04-May-2004						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
53-00-00-200-801-01	**Inspection of the Fuselage Exterior - General Visual Inspection**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-00-00-200-801-01 (5-15)	**Inspection of the Fuselage Exterior - General Visual Inspection**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
						Hrs	13,276.7				
(Tol. Adjustment: -141d)						Ldg	8,977				
						Flt	8,977				
53-00-00-200-802-01 (5-40)	**Visual Inspection of the Skin Panels - Frame 7 to Frame 31**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-00-00-220-801-01	**Detailed Inspection of the Fuselage Frames In Pressurized Area**							RE (N/A)		Acft Maint Ops (5-10)	
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
53-00-00-250-801-01	**Eddy-Current Inspection For Corrosion at Interfaces Between Spot-Welded Skin Panels and Stringers Between Frames 0 and 19**							RE (N/A)		Acft Maint Ops (5-10)	
53 A/F						Mos					
						Hrs					
Note: A/C 002						Ldg					
						Flt					
53-00-00-250-801-01 (5-15)	**Eddy-Current Inspection For Corrosion at Interfaces Between Spot-Welded Skin Panels and Stringers Between Frames 0 and 19**							RE (N/A)		CPCP (5-15)	
53 A/F						Mos					
						Hrs					
Note: A/C 002						Ldg					
						Flt					
53-00-00-250-802-01 (5-40)	**Eddy-Current Inspection of the Fuselage Framework Around the Windows In T2 and T3 Sections**							T		AWL (5-40), SSIP	**≈19-Jul-2086**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		31,250		31,250	22,117 Flt

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
530106	**ICA GPS Antenna and Feed-Thru Inspection**							RE		ICA	
53 A/F						Mos	14-Sep-2023	72		14-Sep-2029	4.5 Years
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-04-01-220-801-01 (5-40)	**Detailed Inspection of the Floor Panel Omegas at Frames 18-19**							T		AWL (5-40), SSIP	**≈20-Feb-2076**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		27,500		27,500	18,367 Flt
53-04-05-250-801-01 (5-40)	**Eddy-Current Inspection of Floor Panel Stiffeners Between Frames 31 and 35**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
530806	**Inspect No.1 and No.2 GPS, XM and ARNAV Antenna**							RE		ICA	
53 A/F						Mos	14-Sep-2023	72		14-Sep-2029	4.5 Years
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-10-00-200-808-01	**Inspection of the NLG Bay**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
53-10-00-200-808-01 (5-15)	**Inspection of the NLG Bay**							RE		CPCP (5-15)	
53 A/F						Mos	30-Aug-2024	13		30-Sep-2025	6.9 Months
						Hrs	13,386.3				
(SOURCE: Falcon 50/50EX MPD)						Ldg	9,044				
						Flt	9,043				
53-10-00-210-802-01	**General Visual Inspection of the Flight Compartment**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-10-00-220-801-01	**Detailed Inspection of the Static Pressure Probe and of the Fuselage Skin In Probe Area**							RE		Acft Maint Ops (5-10), Unsch Maint Chk (5-50)	
53 A/F						Mos	14-Sep-2023	24	+1m	23-Mar-2025	17 Days (+31)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: For RVSM requirements. To be performed in case of painting or damage in RVSM area, except in case of flaked paint on rivet heads or locally around the edge of the static probe base.						Ldg	8,977				
						Flt	8,977				
53-10-00-220-802-01	**Detailed Inspection of the Flight Compartment**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-10-00-220-802-01 (5-15)	**Detailed Inspection of the Flight Compartment**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
53-10-00-220-803-01	**Detailed Inspection of the NLG Bay**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-10-00-220-803-01 (5-15)	**Detailed Inspection of the NLG Bay**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
						Hrs	13,276.7				
(Tol. Adjustment: -141d)						Ldg	8,977				
						Flt	8,977				
53-10-03-250-802-01 (5-40)	**Eddy-Current Inspection of the Passenger Door Frame Corners**							T		AWL (5-40), SSIP	**≈19-Jul-2086**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		31,250		31,250	22,117 Flt
53-10-05-250-801-01 (5-40)	**Eddy-Current Inspection of Frame 12 Around Pax Door Telescopic Rod Fitting**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-10-31-220-801-01 (5-40)	**Detailed Inspection of Cockpit Upper Skin Junction With Windshield and Window Frames**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-10-39-220-801-01	**Detailed Inspection of the Lower Section of the Cockpit Windshield / Window Frames**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
53-10-39-220-801-01 (5-15)	**Detailed Inspection of the Lower Section of the Cockpit Windshield / Window Frames**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
Note: A/C with SB F50-178						Flt	8,977				
53-10-39-220-801-01 (5-40)	**Detailed Inspection of the Lower Section of the Cockpit Windshield / Window Frames**							RE		AWL (5-40), SSIP	**≈18-Feb-2035**
53 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7				
						Ldg	8,977				
Note: A/C with SB F50-178						Flt	8,977	3,750		12,727	3,594 Flt
53-10-39-220-802-01 (5-15)	**Detailed Inspection of the Cockpit Windshield / Window Frames**							RE (N/A)		CPCP (5-15)	
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-10-39-220-803-01	**Detailed Inspection of the Screws Attaching the Windshield Frames to Frame 0**							RE		Acft Maint Ops (5-10)	**≈14-Nov-2029**
53 A/F						Mos	23-Mar-2005				
						Hrs	10,050.4				
						Ldg					
Note: A/C 030-352 (A/C with M281)						Flt	7,081	3,750		10,831	1,698 Flt
53-10-39-220-803-01 (5-40)	**Detailed Inspection of the Screws Attaching the Windshield Frames to Frame 0**							RE		AWL (5-40), CMR	**≈14-Nov-2029**
53 A/F						Mos	23-Mar-2005				
						Hrs	10,050.4				
Ref:53-120						Ldg					
Note: A/C 030-352 (A/C with M281)						Flt	7,081	3,750		10,831	1,698 Flt
53-10-39-220-804-01	**Detailed Inspection of the Frame of the LH and RH Rear Cockpit Windows - LH Side Rear Window**							T		Acft Maint Ops (5-10)	**≈01-Oct-2044**
53 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C ((001-030 and 032-041) and without SB F50-198)						Flt		16,192		16,192	7,059 Flt
53-10-39-220-804-01 (5-40)	**Detailed Inspection of the Frame of the LH and RH Rear Cockpit Windows - LH Side Rear Window**							T		AWL (5-40), CMR	**≈01-Oct-2044**
53 A/F						Mos					
						Hrs					
Ref:53-070						Ldg					
Note: A/C ((001-030 and 032-041) and without SB F50-198)						Flt		16,192		16,192	7,059 Flt
53-10-39-220-804-02	**Detailed Inspection of the Frame of the LH and RH Rear Cockpit Windows - RH Side Rear Window**							T		Acft Maint Ops (5-10)	**≈01-Oct-2044**
53 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C ((001-030 and 032-041) and without SB F50-198)						Flt		16,192		16,192	7,059 Flt
53-10-39-220-804-02 (5-40)	**Detailed Inspection of the Frame of the LH and RH Rear Cockpit Windows - RH Side Rear Window**							T		AWL (5-40), CMR	**≈01-Oct-2044**
53 A/F						Mos					
						Hrs					
Ref:53-070						Ldg					
Note: A/C ((001-030 and 032-041) and without SB F50-198)						Flt		16,192		16,192	7,059 Flt
53-10-39-220-805-01	**Detailed Inspection of the Frame of the RH Cockpit Lateral Window**							RE (N/A)		Acft Maint Ops (5-10)	
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
53-10-39-220-805-01 (5-40)	**Detailed Inspection of the Frame of the RH Cockpit Lateral Window**							RE (N/A)		AWL (5-40), CMR	
53 A/F						Mos					
						Hrs					
Ref:53-040						Ldg					
						Flt					
53-10-39-250-801-01	**Eddy Current Inspection of the Lower Recesses of the Cockpit Windshield / Window Frames**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
53-10-39-250-801-01 (5-15)	**Eddy Current Inspection of the Lower Recesses of the Cockpit Windshield / Window Frames**							RE		CPCP (5-15)	
53 A/F						Mos	02-Sep-2016	148		02-Jan-2029	3.8 Years
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-10-39-250-802-01 (5-40)	**Eddy-Current Inspection of the Cockpit Windshield / Window Frames**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-10-39-270-801-01	**Ultrasonic Check of the Lower Part of the Frames of the Cockpit Windshields and Windows**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
53-10-39-270-801-01 (5-15)	**Ultrasonic Check of the Lower Part of the Frames of the Cockpit Windshields and Windows**							RE		CPCP (5-15)	
53 A/F						Mos	02-Sep-2016	148		02-Jan-2029	3.8 Years
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
53-10-39-270-802-01	**Ultrasonic Check of the Vertical Posts of the Cockpit Windshields and Windows**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+2m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -317.2d) (SOURCE: Falcon 50/50EX MPD) Note: The repeat inspection interval for permissible cracks is 12 months.						Ldg	8,977				
						Flt	8,977				
53-10-39-270-802-01 (5-15)	**Ultrasonic Check of the Vertical Posts of the Cockpit Windshields and Windows**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
53-10-39-270-802-01 (5-40)	**Ultrasonic Check of the Vertical Posts of the Cockpit Windshields and Windows**							RE		AWL (5-40), SSIP	**≈18-Feb-2035**
53 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977	3,750		12,727	3,594 Flt
53-10-41-220-801-01	**Detailed Inspection of the Attachment Fitting of the NLG Actuator**							T		Acft Maint Ops (5-10)	**≈25-Jul-2027**
53 A/F						Mos					
						Hrs					
						Ldg		10,000		10,000	867 Ldg
						Flt					
53-10-41-220-801-01 (5-40)	**Detailed Inspection of the Attachment Fitting of the NLG Actuator**							T		AWL (5-40), CMR	**≈25-Jul-2027**
53 A/F						Mos					
						Hrs					
Ref:53-400						Ldg		10,000		10,000	867 Ldg
						Flt					
53-10-45-250-801-01 (5-40)	**Eddy Current Inspection of the NLG Bay Skin Panel and Door Frame at Frame 7**							T		AWL (5-40), SSIP	**≈19-Jul-2086**
53 A/F						Mos					
						Hrs					
						Ldg		31,250		31,250	22,117 Ldg
						Flt					
53-11-00-210-801-02	**General Visual Inspection of the Nose Cone Area**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-11-00-210-801-02 (5-15)	**General Visual Inspection of the Nose Cone Area**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
						Hrs	13,276.7				
(Tol. Adjustment: -141d)						Ldg	8,977				
						Flt	8,977				
53-11-00-220-801-01	**Detailed Inspection of the Nose Cone Area**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
53-11-00-220-801-01 (5-15)	**Detailed Inspection of the Nose Cone Area**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
53-11-00-760-801-01	**Check of the Nose Cone Electrical Bonding**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: A/C (001-262 and without randome equipped with DAYTON-GRANGER lighting strips P/N16-180)						Ldg	8,977				
						Flt	8,977				
53-30-00-210-802-01	**General Visual Inspection of the Passenger Cabin**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: This check may include additional elements according to various furnishing						Ldg	8,977				
						Flt	8,977				
53-30-00-220-801-01	**Detailed Inspection of the Passenger Cabin**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: This check may include additional elements according to various furnishing.						Flt	8,977				
53-30-00-220-801-01 (5-15)	**Detailed Inspection of the Passenger Cabin**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
Note: This check may include additional elements according to various furnishing.						Flt	8,977				
53-30-00-220-802-01	**Inspection of the Center Floor Angle Piece, RH Side Between Frame 19 and Frame 26**							T		Acft Maint Ops (5-10)	**≈01-Oct-2044**
53 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C 001-069 (A/C without M313)						Flt		16,192		16,192	7,059 Flt
53-30-00-220-802-01 (5-40)	**Inspection of the Center Floor Angle Piece, RH Side Between Frame 19 and Frame 26**							T		AWL (5-40), CMR	**≈01-Oct-2044**
53 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C without M313						Flt		16,192		16,192	7,059 Flt
53-30-00-220-803-01	**Detailed Inspection of the Floor Pick-Up Angle at Frame 27 and of the Floor Panel Between Frame 26 and Frame 29**							T		Acft Maint Ops (5-10)	**≈25-Jul-2027**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		10,000		10,000	867 Flt

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-30-00-220-803-01 (5-40)	**Detailed Inspection of the Floor Pick-Up Angle at Frame 27 and of the Floor Panel Between Frame 26 and Frame 29**							T		AWL (5-40), CMR	**≈25-Jul-2027**
53 A/F						Mos					
						Hrs					
Ref:53-500						Ldg					
						Flt		10,000		10,000	867 Flt
53-30-00-220-805-01 (5-40)	**Detailed Inspection of Fuselage Skin in Splice Area at Stringer 13 Between Frame 13 and 18**							T		AWL (5-40), SSIP	**≈30-Jan-2083**
53 A/F						Mos					
						Hrs					
						Ldg		30,000		30,000	20,867 Ldg
						Flt					
53-30-00-250-801-01 (5-40)	**Eddy-Current Inspection of the Emergency Exit Door Frame Rounded Angles**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-30-00-250-803-01 (5-40)	**Eddy-Current Inspection of the Finger Plate of Circumferential Splice at Frames 19 and 26**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-30-01-220-801-01	**Detailed Inspection of the Feeder Tanks**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
53-30-01-220-801-01 (5-15)	**Detailed Inspection of the Feeder Tanks**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
53-30-01-220-801-01 (5-40)	**Detailed Inspection of the Feeder Tanks**							RE		AWL (5-40), CMR	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
53-30-01-790-801-01	**Leak Test of the Feeder Tank**							RE		Acft Maint Ops (5-10)	**≈23-Aug-2028**
53 A/F	05-10-00-1B					Mos	14-Sep-2023				
						Hrs	13,276.7	1,500	+30	(14,776.7)	1,255.8 Hrs (+30)
						Ldg	8,977				
Note: A/C 001-221						Flt	8,977				
53-30-01-790-801-01 (5-40)	**Leak Test of the Feeder Tank**							RE (N/A)		AWL (5-40)	
53 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7				
Ref:53-360						Ldg	8,977				
						Flt	8,977				
53-40-00-200-804-01	**Inspection of the MLG Bays - LH MLG Bay**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-40-00-200-804-01 (5-15)	**Inspection of the MLG Bays - LH MLG Bay**							RE		CPCP (5-15)	
53 A/F						Mos	30-Aug-2024	13		30-Sep-2025	6.9 Months
						Hrs	13,386.3				
(SOURCE: Falcon 50/50EX MPD)						Ldg	9,044				
						Flt	9,043				
53-40-00-200-804-02	**Inspection of the MLG Bays - RH MLG Bay**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
53-40-00-200-804-02 (5-15)	**Inspection of the MLG Bays - RH MLG Bay**							RE		CPCP (5-15)	
53 A/F						Mos	30-Aug-2024	13		30-Sep-2025	6.9 Months
						Hrs	13,386.3				
(SOURCE: Falcon 50/50EX MPD)						Ldg	9,044				
						Flt	9,043				
53-40-00-210-803-02	**General Visual Inspection of the Fuselage Lower Section Areas and of the Compartments Above the Feeder Tanks**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-40-00-210-803-02 (5-15)	**General Visual Inspection of the Fuselage Lower Section Areas and of the Compartments Above the Feeder Tanks**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	25		14-Oct-2025	7.4 Months
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-40-00-220-802-01	**Detailed Inspection of the Fuselage Structural Fuel Tanks**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
53-40-00-220-802-01 (5-15)	**Detailed Inspection of the Fuselage Structural Fuel Tanks**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
53-40-00-220-802-01 (5-40)	**Detailed Inspection of the Fuselage Structural Fuel Tanks**							RE		AWL (5-40), CMR	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
53-40-00-220-803-01	**Detailed Inspection of the Fuselage Lower Section Areas and of the Compartments Above the Feeder Tanks**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
53-40-00-220-803-01 (5-15)	**Detailed Inspection of the Fuselage Lower Section Areas and of the Compartments Above the Feeder Tanks**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-40-00-220-804-01	**Detailed Inspection of the MLG Bays - LH MLG Bay**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-40-00-220-804-01 (5-15)	**Detailed Inspection of the MLG Bays - LH MLG Bay**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
(Tol. Adjustment: -141d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-40-00-220-804-02	**Detailed Inspection of the MLG Bays - RH MLG Bay**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-40-00-220-804-02 (5-15)	**Detailed Inspection of the MLG Bays - RH MLG Bay**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
(Tol. Adjustment: -141d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-40-07-220-801-01	**Detailed Inspection of the Centerwing Tank Lower Panels**							RE (N/A)		Acft Maint Ops (5-10)	
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
53-40-07-220-801-01 (5-40)	**Detailed Inspection of the Centerwing Tank Lower Panels**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
Ref:53-380						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-40-07-220-801-01 (5-40)	**Detailed Inspection of the Centerwing Tank Lower Panels**							RE (N/A)		ALI, AWL (5-40)	
53 A/F						Mos					
Ref:53-380						Hrs					
Note: A/C 107 Only						Ldg					
						Flt					
53-40-07-250-801-01 (5-40)	**Eddy-Current Inspection of Centerwing Tank Lower Panel Splice**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-40-07-280-801 (5-40)	**Special Detailed Inspection (Ultrasonic) of Centerwing Tank Lower Panels and Mapping of Reworked Areas**							RE		AWL (5-40), SSIP	**≈04-Jan-2045**
53 A/F						Mos	02-Sep-2016				
Ref:53-700						Hrs	12,978.6				
						Ldg					
						Flt	8,785	7,500		16,285	7,152 Flt
53-40-07-280-801-01	**Special Detailed Inspection (Ultrasonic) of Centerwing Tank Lower Panels and Mapping of Reworked Areas**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
Note: Only for A/C with reworked area						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-40-07-280-801-01 (5-15)	**Special Detailed Inspection (Ultrasonic) of Centerwing Tank Lower Panels and Mapping of Reworked Areas**							RE		CPCP (5-15)	
53 A/F						Mos	02-Sep-2016	151		02-Apr-2029	4.1 Years
						Hrs	12,978.6				
						Ldg	8,785				
						Flt					
53-40-07-280-801-01 (5-40)	**Special Detailed Inspection (Ultrasonic) of Centerwing Tank Lower Panels and Mapping of Reworked Areas**							RE		AWL (5-40), SSIP	**≈04-Jan-2045**
53 A/F						Mos	02-Sep-2016				
						Hrs	12,978.6				
Ref:53-700						Ldg					
						Flt	8,785	7,500		16,285	7,152 Flt
53-40-07-960-801-01 (5-40)	**Discard of the Centerwing Tank Lower Panels**							RE (N/A)		AWL (5-40), Life Limit	
53 A/F						Mos					
						Hrs					
						Ldg					
Note: A/C 107 Only P/N F50B237B5						Flt					
53-41-00-220-801-01	**Detailed Inspection of the Upper Wing Root Bolt Recesses - LH Wing**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: A/C with SB F50-331						Ldg	8,977				
						Flt	8,977				
53-41-00-220-801-01 (5-15)	**Detailed Inspection of the Upper Wing Root Bolt Recesses - LH Wing**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
						Hrs	13,276.7				
(Tol. Adjustment: -141d)						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				
53-41-00-220-801-02	**Detailed Inspection of the Upper Wing Root Bolt Recesses - RH Wing**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
Note: A/C with SB F50-331						Ldg	8,977				
						Flt	8,977				
53-41-00-220-801-02 (5-15)	**Detailed Inspection of the Upper Wing Root Bolt Recesses - RH Wing**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
						Hrs	13,276.7				
(Tol. Adjustment: -141d)						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				
53-41-00-620-802-01	**Renewal of the Temporary Protection of the Wing Root Bolt Recesses - LH Wing Upper Bolt Recesses**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				
53-41-00-620-802-01 (5-15)	**Renewal of the Temporary Protection of the Wing Root Bolt Recesses - LH Wing Upper Bolt Recesses**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				
53-41-00-620-802-02	**Renewal of the Temporary Protection of the Wing Root Bolt Recesses - RH Wing Upper Bolt Recesses**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-41-00-620-802-02 (5-15)	**Renewal of the Temporary Protection of the Wing Root Bolt Recesses - RH Wing Upper Bolt Recesses**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				
53-41-00-620-802-03	**Renewal of the Temporary Protection of the Wing Root Bolt Recesses - LH Wing Lower Bolt Recesses**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				
53-41-00-620-802-03 (5-15)	**Renewal of the Temporary Protection of the Wing Root Bolt Recesses - LH Wing Lower Bolt Recesses**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		14-Nov-2029	4.7 Years
						Hrs	13,276.7				
Note: A/C with SB F50-331						Ldg	8,977				
						Flt	8,977				
53-41-00-620-802-04	**Renewal of the Temporary Protection of the Wing Root Bolt Recesses - RH Wing Lower Bolt Recesses**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				
53-41-00-620-802-04 (5-15)	**Renewal of the Temporary Protection of the Wing Root Bolt Recesses - RH Wing Lower Bolt Recesses**							RE		CPCP (5-15)	
53 A/F						Mos	14-Sep-2023	74		14-Nov-2029	4.7 Years
						Hrs	13,276.7				
						Ldg	8,977				
Note: A/C with SB F50-331						Flt	8,977				
53-41-01-640-801-01	**Lubrication of the Wing to Fuselage Connecting Rod - LH Link Rod**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
53-41-01-640-801-02	**Lubrication of the Wing to Fuselage Connecting Rod - RH Link Rod**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
53-50-00-210-804-02	**General Visual Inspection of the Rear Compartment**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
53-50-00-210-804-02 (5-15)	**General Visual Inspection of the Rear Compartment**							RE		CPCP (5-15)	
53 A/F						Mos	30-Aug-2024	13		30-Sep-2025	6.9 Months
						Hrs	13,386.3				
(SOURCE: Falcon 50/50EX MPD)						Ldg	9,044				
						Flt	9,043				
53-50-00-210-806-02	**General Visual Inspection of the Baggage Compartment**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ	Description / PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-50-00-210-806-02 (5-15)	**General Visual Inspection of the Baggage Compartment**								RE		CPCP (5-15)	
53 A/F							Mos	14-Sep-2023	25		23-May-2025	78 Days
							Hrs	13,276.7				
	(Tol. Adjustment: -141d)						Ldg	8,977				
							Flt	8,977				
53-50-00-210-807-02	**General Visual Inspection of the APU Area**								RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-12M						Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
	(Tol. Adjustment: -83d)						Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
53-50-00-220-803-02	**Detailed Inspection of the Baggage Compartment**								RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C						Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
	(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
53-50-00-220-803-02 (5-15)	**Detailed Inspection of the Baggage Compartment**								RE		CPCP (5-15)	
53 A/F							Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
							Hrs	13,276.7				
	(Tol. Adjustment: -312d)						Ldg	8,977				
							Flt	8,977				
53-50-00-220-805-01	**Detailed Inspection of the Rear Compartment**								RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M						Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
53-50-00-220-805-01 (5-15)	**Detailed Inspection of the Rear Compartment**								RE		CPCP (5-15)	
53 A/F							Mos	14-Sep-2023	25		23-May-2025	78 Days
							Hrs	13,276.7				
	(Tol. Adjustment: -141d)						Ldg	8,977				
							Flt	8,977				
53-50-00-220-806-01	**Detailed Inspection Of Apu Exhaust Pipe And Outer Duct**								RE (-)			
53 A/F							Mos	16-Sep-2018				
							Hrs					
							Ldg					
							Flt					
53-50-34-220-801-01 (5-40)	**Detailed Inspection of the Frame 34 Upper and Lower Sections**								T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F							Mos					
							Hrs					
							Ldg					
							Flt		20,000		20,000	10,867 Flt
53-50-35-220-801-01	**Detailed Inspection of the Frame 35 Lower Section**								T		Acft Maint Ops (5-10)	**≈01-Sep-2038**
53 A/F							Mos					
							Hrs					
	Note: A/C ((001-049 and without SB F50-122) and without SB F50-163)						Ldg					
	SB F50-122 mandatory compliance [French DGAC AD 86-74-5[B]] at scheduled inspection						Flt		14,000		14,000	4,867 Flt
53-50-35-220-802-01 (5-40)	**Detailed Inspection of the Frame 35 Upper and Lower sections**								T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F							Mos					
							Hrs					
							Ldg		20,000		20,000	10,867 Ldg
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
53-50-35-250-801-01 (5-40)	**Eddy-Current Inspection of the Frame 35 Vertical Beams**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-50-40-220-802-01	**Detailed Inspection of the Stub-Fuselage Assembly Screws at Frames 41 and 42**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: A/C 001-189						Flt	8,977				
53-50-44-220-801-01 (5-40)	**Detailed Inspection of the Fin Stub Front Spar**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
53 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
53-80-00-200-801-01	**Check of the Condensation and Stream Water Drains**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
53-80-09-710-801-01	**Operational Test of the "Circle Seal" Automatic Drains**							RE		Acft Maint Ops (5-10)	
53 A/F	05-10-00-1C					Mos	14-Sep-2023	72	+2m	(31-Oct-2028)	3.7 Years
						Hrs	13,276.7				
(Tol. Adjustment: -372d)						Ldg	8,977				
						Flt	8,977				
98-15-07	**Junction Reinforcement Fitting Of Baggage Floor**							RE (-)		Mandatory	
53 A/F						Mos	12-Jan-1999				
Eff: 20-Aug-1998						Hrs	8,748				
(ISSUING AUTHORITY: FAA)						Ldg	6,276				
						Flt					
F50-037	**Center aisle floor - Addition of three attach posts**							RE (-)			
53 A/F						Mos					
Eff: 29-Oct-1979						Hrs					
						Ldg					
Note: M0211						Flt					
F50-122	**Section T5 - Strengthening of frame 35 at baggage compartment floor level**							RE (-)			
53 A/F						Mos	18-Jun-1987				
Eff: 25-Jun-1986 Complied With						Hrs	4,087.5				
SB:F50-53-002						Ldg	2,821				
						Flt					
F50-140	**Heated floors in passenger cabin - Lower shrouds re-inforced**							T (A/R)			
53 A/F						Mos					
Eff: 05-Jul-1983						Hrs					
						Ldg					
Note: M1110						Flt					
F50-158	**Improved access to centerwing fuel drains**							T (A/R)			
53 A/F						Mos					
Eff: 12-Sep-1985						Hrs					
						Ldg					
Note: M0940						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-169	**Fuselage-to-center engine cowl junction - Improved sealing**							RE (-)			
53 A/F						Mos	18-Jun-1987				
Eff: 14-Jan-1986 Complied With						Hrs	4,087.5				
SB:F50-53-006						Ldg	2,821				
						Flt					
F50-171	**Reinforced protection shield against center engine rotor burst**							T (A/R)			
53 A/F						Mos					
Eff: 10-Dec-1985						Hrs					
						Ldg					
Note: M0316						Flt					
F50-178	**Windshields and windows - Installation of a removable fairing**							RE (-)			
53 A/F						Mos	03-Jul-2003				
Complied With						Hrs					
						Ldg					
Note: M1310, AD EASA 2009-0209						Flt					
F50-178 R1	**Windshields and windows - Installation of a removable fairing**							RE (-)			
53 A/F						Mos					
						Hrs					
						Ldg					
Note: M1310, AD EASA 2009-0209						Flt					
F50-178 R2	**Windshields and windows - Installation of a removable fairing**							RE (-)			
53 A/F						Mos	03-Jul-2003				
Eff: 27-Aug-2009						Hrs					
						Ldg					
Note: M1310, AD EASA 2009-0209						Flt					
F50-185	**Nose cone - Installation of a guiding system**							T (A/R)			
53 A/F						Mos					
Eff: 16-Feb-1988						Hrs					
						Ldg					
Note: M1366						Flt					
F50-205	**Rework of sealing of double wall at frame 28**							RE (-)			
53 A/F						Mos	13-Aug-1992				
Eff: 09-Nov-1988						Hrs					
						Ldg					
Note: M1576A						Flt					
F50-213	**Cabin window frames - Inspection of riveting opposite frame 14**							T (A/R)			
53 A/F						Mos					
Eff: 20-Feb-1991						Hrs					
						Ldg					
						Flt					
F50-218	**Baggage compartment door - Compensation system pulley - Distribution of loads on frame 34**							T (A/R)			
53 A/F						Mos					
Eff: 21-May-1990						Hrs					
						Ldg					
Note: M1506						Flt					
F50-227	**Rear compartment - Modification of wiring runs in APU exhaust duct area**							RE (-)			
53 A/F						Mos					
Eff: 31-Jul-1991						Hrs					
						Ldg					
Note: M1766, 145 to 223 with a GARRETT GTCP 36-100A APU (M0378 or SB F50-002)						Flt					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-231	**Baggage compartment door frame at FR 35 - Installation of klegecell plug with PR compound (On hold)**							T (A/R)			
53 A/F						Mos					
Eff: 19-Apr-1993						Hrs					
						Ldg					
Note: M1786						Flt					
F50-328	**Double skins of the feeder tanks at frames 28 and 31 - Reworking of seal in the lower section**							RE (-)			
53 A/F						Mos	10-May-2008				
						Hrs					
						Ldg					
Note: M2692, AD EASA 2001-604-038 R1 (AD FAA 2002-06-12)						Flt					
F50-328 R1	**Double skins of the feeder tanks at frames 28 and 31 - Reworking of seal in the lower section**							RE (-)			
53 A/F						Mos					
						Hrs					
						Ldg					
Note: M2692, AD EASA 2001-604-038 R1 (AD FAA 2002-06-12)						Flt					
F50-328 R2	**Double skins of the feeder tanks at frames 28 and 31 - Reworking of seal in the lower section**							RE (-)			
53 A/F						Mos					
Eff: 12-Jun-2002						Hrs					
						Ldg					
Note: M2692, AD EASA 2001-604-038 R1 (AD FAA 2002-06-12)						Flt					
F50-332	**Inspection of various attachments to restore structure, as required, to original design specifications**							RE (-)			
53 A/F						Mos	24-Aug-2007				
Eff: 01-Apr-2004						Hrs					
						Ldg					
						Flt					
F50-377	**Recommended inspection of various attachments to ensure compliance with original specifications and modification as required**							RE (-)			
53 A/F						Mos					
Eff: 13-Mar-2002						Hrs					
						Ldg					
						Flt					
F50-378	**Nose L/G well drainage - Protection against corrosion**							RE (-)			
53 A/F						Mos					
						Hrs					
						Ldg					
Note: M2783						Flt					
F50-378 R1	**Nose L/G well drainage - Protection against corrosion**							RE (-)			
53 A/F						Mos					
						Hrs					
						Ldg					
Note: M2783						Flt					
F50-378 R2	**Nose L/G well drainage - Protection against corrosion**							T (A/R)			
53 A/F						Mos					
Eff: 11-Jun-2004						Hrs					
						Ldg					
Note: M2783						Flt					
F50-404	**Rear tank structure protection**							RE (-)			
53 A/F						Mos	24-Aug-2007				
Eff: 21-Nov-2002						Hrs	10,670.1				
						Ldg	7,474				
Note: M2838, AD EASA 2002-569 (AD FAA 2004-07-24), 283, 289, 291, 292, 294, 297, 301, 312, 315, 316, 320 with B.F. GOODRICH stormscope antenna as per M2208 and A/C with DFJ drawing F50-12712 rev. B or C						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-420	**Eliminating mechanical interference between the karman fairing attachments at stringer 14 and frames 26 and 30A**							T (A/R)			
53 A/F						Mos					
Eff: 15-Sep-2003						Hrs					
						Ldg					
Note: P0327, M2851						Flt					
F50-438	**Avionics rack support base-plate - Relocating the EGPWS rack attachments**							RE (-)			
53 A/F						Mos					
Eff: 06-May-2004						Hrs					
						Ldg					
Note: M2911, 251, 253 to 327 with an EGPWS in nose cone						Flt					
F50-439	**Skin junction at stringer 5 - Reinforcement between frames 7 and 12**							RE (-)			
53 A/F						Mos	24-Aug-2007				
Eff: 06-May-2004						Hrs	10,670.7				
						Ldg	7,474				
						Flt					
F50-442	**Eliminating the klegecell filler blocks in structurally enclosed drainage areas**							RE (-)			
53 A/F						Mos	03-May-2010				
Eff: 09-Mar-2006 Complied With						Hrs	11,245				
						Ldg	7,850				
Note: M2921, A/C without M2921						Flt					
F50-464	**Windshields and windows - imrpoved removal/installation of the removable fairings**							RE (-)			
53 A/F						Mos					
Eff: 14-Jun-2007						Hrs					
						Ldg					
Note: M3072, 177 to 352 with M1310						Flt					
F50-482	**Lavatory partition wall at frame 27 - Modifying a clamp to prevent damage to wiring between the partition wall and the double-skin of the feeder tanks,**							RE (-)			
53 A/F						Mos	30-Apr-2010				
Not Applicable by SN						Hrs					
						Ldg					
						Flt					
F50-482 R1	**Lavatory partition wall at frame 27 - Modifying a clamp to prevent damage to wiring between the partition wall and the double-skin of the feeder tanks,**							RE (-)			
53 A/F						Mos	30-Apr-2010				
Eff: 14-Jun-2007 Not Applicable by SN						Hrs					
						Ldg					
						Flt					
F50-502	**Pilot and copilot windshield frames - Installation of removable access door**							T (A/R)			
53 A/F						Mos					
Eff: 12-Apr-2010						Hrs					
						Ldg					
Note: M3118, 2 to 176 without SB F50-178						Flt					
F50-507	**Engine 2 S-duct protection improvement**							RE (-)			
53 A/F						Mos	25-May-2010				
Eff: 03-Apr-2009 Complied With						Hrs	11,245				
						Ldg	7,850				
Note: M3150						Flt					
▼ 54 - NACELLES/PYLONS											
	Cowling Assy							RE (O/C)			
54 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Cowling Assy							RE (O/C)			
	54 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Main Attach Fitting							RE (O/C)			
	54 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Main Attach Fitting							RE (O/C)			
	54 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Rear Attach Fitting							RE (O/C)			
	54 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Rear Attach Fitting							RE (O/C)			
	54 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Rear Attach Fitting							RE (O/C)			
	54 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Rear Attach Link							RE (O/C)			
	54 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Rear Attachment Auxiliary Fitting Bolt							RE (O/C)			
	54 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Rear Attachment Auxiliary Fitting Bolt							RE (O/C)			
	54 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2003-10-04		**Engine pylons - To prevent chafing and consequent leakage of the hydraulic lines located within the No. 1 and No. 3 engine pylons**							RE (-)		Mandatory	
	54 A/F						Mos	03-Jul-2003				
	Eff: 04-Jun-2003 Complied With						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2003-10-04 Paragraph (b)	**Engine pylons - To prevent chafing and consequent leakage of the hydraulic lines located within the No. 1 and No. 3 engine pylons - Inspection**							RE (-)		Mandatory	
54 A/F						Mos					
Eff: 04-Jun-2003						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2003-10-04 Paragraph (c)	**Engine pylons - To prevent chafing and consequent leakage of the hydraulic lines located within the No. 1 and No. 3 engine pylons - Proper Clearance**							RE (-)		Mandatory	
54 A/F						Mos					
Eff: 04-Jun-2003						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2003-10-04 Paragraph (d)	**Engine pylons - To prevent chafing and consequent leakage of the hydraulic lines located within the No. 1 and No. 3 engine pylons - Incorrect Clearance**							RE (-)		Mandatory	
54 A/F						Mos					
Eff: 04-Jun-2003						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2003-10-04 Paragraph (e)	**Engine pylons - To prevent chafing and consequent leakage of the hydraulic lines located within the No. 1 and No. 3 engine pylons - Fastening Lines, Ensuring Proper Clearance, and Marking Location of Clamps**							RE (-)		Mandatory	
54 A/F						Mos					
Eff: 04-Jun-2003						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2003-10-04 Paragraph (f)	**Engine pylons - To prevent chafing and consequent leakage of the hydraulic lines located within the No. 1 and No. 3 engine pylons - Revision to Maintenance Manual**							RE (-)		Mandatory	
54 A/F						Mos					
Eff: 04-Jun-2003						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
54-00-00-210-810-03	**General Visual Inspection of the Engine 1 and 3 Nacelles and Pylons - Engine 1**							RE		Acft Maint Ops (5-10)	
54 A/F						Mos	21-May-2024	19	+1m	21-Dec-2025	9.7 Months (+31 Days)
						Hrs	13,302.5	800	+30	14,102.5	581.6 Hrs (+30)
Note: A/C with TFE 731-3 ENGINES not to exceed 19 M						Ldg	8,998				
						Flt	8,998				
54-00-00-210-810-03 (5-15)	**General Visual Inspection of the Engine 1 and 3 Nacelles and Pylons - Engine 1**							RE		CPCP (5-15)	
54 A/F						Mos	21-May-2024	19		21-Dec-2025	9.7 Months
						Hrs	13,302.5	800		14,102.5	581.6 Hrs
Note: A/C with TFE 731-3 or TFE 731-40 ENGINES not to exceed 19 M						Ldg	8,998				
						Flt	8,998				
54-00-00-210-810-04	**General Visual Inspection of the Engine 1 and 3 Nacelles and Pylons - Engine 3**							RE		Acft Maint Ops (5-10)	
54 A/F						Mos	21-May-2024	19	+1m	21-Dec-2025	9.7 Months (+31 Days)
						Hrs	13,302.5	800	+30	14,102.5	581.6 Hrs (+30)
Note: A/C with TFE 731-3 or TFE 731-40 ENGINES not to exceed 19 M						Ldg	8,998				
						Flt	8,998				
54-00-00-210-810-04 (5-15)	**General Visual Inspection of the Engine 1 and 3 Nacelles and Pylons - Engine 3**							RE		CPCP (5-15)	
54 A/F						Mos	21-May-2024	19		21-Dec-2025	9.7 Months
						Hrs	13,302.5	800		14,102.5	581.6 Hrs
Note: A/C with TFE 731-3 or TFE 731-40 ENGINES not to exceed 19 M						Ldg	8,998				
						Flt	8,998				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
54-00-00-210-811-02	**General Visual Inspection of the Engine 2 Nacelle**							RE		Acft Maint Ops (5-10)	
54 A/F						Mos	21-May-2024	19	+1m	21-Dec-2025	9.7 Months (+31 Days)
						Hrs	13,302.5	800	+30	14,102.5	581.6 Hrs (+30)
Note: A/C with TFE 731-3 and TFE 731-40 ENGINES not to exceed 19 M						Ldg	8,998				
						Flt	8,998				
54-00-00-210-811-02 (5-15)	**General Visual Inspection of the Engine 2 Nacelle**							RE		CPCP (5-15)	
54 A/F						Mos	21-May-2024	19		21-Dec-2025	9.7 Months
						Hrs	13,302.5	800		14,102.5	581.6 Hrs
Note: A/C with TFE 731-3 or TFE 731-40 ENGINES not to exceed 19 M						Ldg	8,998				
						Flt	8,998				
54-00-00-220-801-01C	**Detailed Inspection Of The Engine 1 Nacelle/Pylon/Forward Mounts (Cpcp)**							RE		CPCP	
54 A/F						Mos	14-Sep-2023	19		14-Apr-2025	39 Days
						Hrs	13,276.7	800		14,076.7	555.8 Hrs
						Ldg	8,977				
						Flt	8,977				
54-00-00-220-802-01	**Detailed Inspection of the Engine 2 Nacelle**							RE		Acft Maint Ops (5-10)	
54 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+2m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
Note: To be performed at an engine removal, close to or at the 2C Inspection						Ldg	8,785				
						Flt					
54-00-00-220-802-01 (5-15)	**Detailed Inspection of the Engine 2 Nacelle**							RE		CPCP (5-15)	
54 A/F						Mos	02-Sep-2016	148		02-Jan-2029	3.8 Years
						Hrs	12,978.6				
Note: may be performed during an engine removal prior to 148M						Ldg	8,785				
						Flt					
54-11-00-610-801-01	**Servicing of the Engine Cowlings - Engine 1 Cowlings**							RE		Acft Maint Ops (5-10)	
54 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
54-11-00-610-801-02	**Servicing of the Engine Cowlings - Engine 2 Cowlings**							RE		Acft Maint Ops (5-10)	
54 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
54-11-00-610-801-03	**Servicing of the Engine Cowlings - Engine 3 Cowlings**							RE		Acft Maint Ops (5-10)	
54 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
54-14-00-210-801-01	**General Visual Inspection of the Engine Core Cowl Assemblies - Engine 1**							RE		Acft Maint Ops (5-10)	**≈23-Apr-2025**
54 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	300		13,576.7	55.8 Hrs
Note: To be performed at an engine removal, close to or at 300 FH						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
54-14-00-210-801-02	**General Visual Inspection of the Engine Core Cowl Assemblies - Engine 2**							RE		Acft Maint Ops (5-10)	**≈23-Apr-2025**
54 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	300		13,576.7	55.8 Hrs
						Ldg	8,977				
Note: To be performed at an engine removal, close to or at 300 FH						Flt	8,977				
54-14-00-210-801-03	**General Visual Inspection of the Engine Core Cowl Assemblies - Engine 3**							RE		Acft Maint Ops (5-10)	**≈17-Jul-2025**
54 A/F						Mos	07-Aug-2024				
						Hrs	13,360.3	300		13,660.3	139.4 Hrs
						Ldg	9,031				
Note: To be performed at an engine removal, close to or at 300 FH						Flt	9,030				
54-42-17-200-801-01	**Check For Non-Loosening of Screws of S-Duct Sections 2 and 3 Coupling Flanges**							RE		Acft Maint Ops (5-10)	**≈06-Aug-2025**
54 A/F						Mos	16-Sep-2018				
						Hrs	13,079.2	600	+30	13,679.2	158.3 Hrs (+30)
						Ldg	8,836				
						Flt					
54-50-00-220-802-01 (5-40)	**Detailed Inspection of Pylon Upper Flange Ribs at Frame 32**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
54 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
F50-023	**Nacelles - Relocation of the LH engine oil level inspection door**							RE (-)			
54 A/F						Mos					
Eff: 07-Mar-1980						Hrs					
						Ldg					
Note: M0122						Flt					
F50-027	**Pylons - Drainage of running water in the air ducts**							RE (-)			
54 A/F						Mos					
						Hrs					
						Ldg					
Note: M0074B, M0074A						Flt					
F50-027 R1	**Pylons - Drainage of running water in the air ducts**							RE (-)			
54 A/F						Mos					
Eff: 04-Apr-1980						Hrs					
						Ldg					
Note: M0074B, M0074A						Flt					
F50-060	**Left engine lower cowl - Instructions for maneuvering the cowl**							RE (-)			
54 A/F						Mos					
						Hrs					
						Ldg					
Note: M0350						Flt					
F50-060 R1	**Left engine lower cowl - Instructions for maneuvering the cowl**							RE (-)			
54 A/F						Mos	22-Jan-1981				
Eff: 20-Mar-1980						Hrs					
						Ldg					
Note: M0350						Flt					
F50-081	**New shape of the side engine generator air intakes**							RE (-)			
54 A/F						Mos					
						Hrs					
						Ldg					
Note: M0633						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-081 R1	**New shape of the side engine generator air intakes**							RE (-)			
54 A/F						Mos					
Eff: 15-May-1981						Hrs					
						Ldg					
Note: M0633						Flt					
F50-089	**Side engine HP bleed air - Fairing accepting new hinged line profile**							RE (-)			
54 A/F						Mos					
Eff: 26-May-1981						Hrs					
						Ldg					
Note: M0681						Flt					
F50-091	**Installation of engines incorporating improved N1 transducer lead**							T (A/R)			
54 A/F						Mos					
Eff: 28-Apr-1982						Hrs					
						Ldg					
Note: M0391, A/C with TFE731-3-1C not including N1 flexible lead (SB GARRETT TFE731-77-3005)						Flt					
F50-110	**LH nacelle air intake - One support assy replaced**							T (A/R)			
54 A/F						Mos					
Eff: 15-Dec-1981						Hrs					
						Ldg					
Note: M0768-2						Flt					
F50-112	**Center engine aft mounts - Stubs of new design**							RE (-)			
54 A/F						Mos	16-Dec-1988				
Eff: 12-Jan-1984						Hrs					
						Ldg					
Note: M0779						Flt					
F50-131	**Engine 2 S-duct inspection door - Device prohibiting incorrect installation of door (Superseded by SB-F50-236) (No longer applicable)**							RE (-)			
54 A/F						Mos					
						Hrs					
						Ldg					
Note: M0999A, M0146A, M0999B						Flt					
F50-131 R1	**Engine 2 S-duct inspection door - Device prohibiting incorrect installation of door (Superseded by SB-F50-236) (No longer applicable)**							RE (-)			
54 A/F						Mos	18-Jun-1987				
Eff: 17-Jul-1985 Complied With						Hrs	4,087.5				
SB:F50-54-010						Ldg	2,821				
						Flt					
F50-192	**Elimination of interference between side engine cowls and engine mounts**							RE (-)			
54 A/F						Mos	16-Dec-1988				
Eff: 08-Jun-1988						Hrs					
						Ldg					
Note: M1317B, M1476-4						Flt					
F50-220	**S-duct - Installation of a doubler inside section 3**							T (A/R)			
54 A/F						Mos					
Eff: 20-Jun-1991						Hrs					
						Ldg					
Note: M1666						Flt					
F50-229	**Nacelles / Pylons - Engine exhaust ducts - Replacement of attachment clamps**							RE (-)			
54 A/F						Mos	12-Dec-2000				
Complied With						Hrs					
						Ldg					
Note: M1613, AD EASA 93-113-013 (AD FAA 94-14-15)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-229 R1	**Nacelles / Pylons - Engine exhaust ducts - Replacement of attachment clamps**							T (A/R)			
54 A/F						Mos					
Eff: 02-Apr-2008						Hrs					
						Ldg					
Note: M1613, AD EASA 93-113-013 (AD FAA 94-14-15)						Flt					
F50-234	**Nacelles / Pylons - Fan aft cowling - Eliminated washer**							T (A/R)			
54 A/F						Mos					
Eff: 08-Sep-1993						Hrs					
						Ldg					
Note: M1845						Flt					
F50-236	**Center engine S-duct - Replacement of hooks for improved positioning of inspection door**							T (A/R)			
54 A/F						Mos					
Eff: 09-Nov-1994						Hrs					
						Ldg					
Note: M1830						Flt					
F50-248	**Pylon trailing edge reinforced skins**							T (A/R)			
54 A/F						Mos					
Eff: 29-Mar-1996						Hrs					
						Ldg					
Note: M1913						Flt					
F50-252	**No 3 engine nacelle upper cowling - Suppression of a interference and addition of a stop**							T (A/R)			
54 A/F						Mos					
Eff: 15-Jan-1997						Hrs					
						Ldg					
Note: M2003, 2 to 250, 252 with GARRETT TFE 731-3-1C						Flt					
F50-264	**Nacelles/Pylons - Rear cowlings - Addition of a washer on an engine mount**							T (A/R)			
54 A/F						Mos					
Eff: 17-Dec-1997						Hrs					
						Ldg					
Note: M2180, 2 to 250, 252 with TFE731-3-1C engines modified by SB to 234 and Allied Signal Aerospace SB TFE731-73-3107						Flt					
F50-285	**Lateral engine cowl doors locking improvement**							RE (-)			
54 A/F						Mos					
Eff: 29-Jul-1998						Hrs					
						Ldg					
Note: M2354						Flt					
F50-290	**Modification to lower cowl assemblies to eliminate interference with engine bottom panel**							RE (-)			
54 A/F						Mos					
Eff: 12-Apr-2000						Hrs					
						Ldg					
Note: M2242						Flt					
F50-326	**Modify upper and lower cowl assemblies to allow easier assemblies**							RE (-)			
54 A/F						Mos					
Eff: 17-May-2000						Hrs					
						Ldg					
Note: M2552						Flt					
F50-346	**Lateral engines - Improved mounting for quick-disconnect connectors**							RE (-)			
54 A/F						Mos					
Eff: 12-Apr-2000						Hrs					
						Ldg					
Note: M2621						Flt					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-379	**Hold-open rod push-pin - Replacement part**							RE (-)			
54 A/F						Mos					
Eff: 08-Oct-2002						Hrs					
						Ldg					
Note: M2785, 251, 253 to 315 and A/C with SB F50-280						Flt					
F50-381	**Engine cowlings - C-clamp on Hartwell latches P/N H245-7**							RE (-)			
54 A/F						Mos					
Eff: 10-Apr-2002						Hrs					
						Ldg					
Note: M2864, 251, 253 to 323 and A/C with SB F50-280						Flt					
F50-409	**Lower fan cowl door - Repair/Replacement of pylon zed longeron at No 1 and No 3 latch cut-outs**							RE (-)			
54 A/F						Mos					
Eff: 13-Mar-2003						Hrs					
						Ldg					
Note: M2845, 251, 253 to 334 and A/C with SB F50-280						Flt					
F50-423	**Nacelles/pylon - Left-hand upper fan cowl door - Tie rod inspection**							RE (-)			
54 A/F						Mos					
Eff: 18-Dec-2002						Hrs					
						Ldg					
						Flt					
F50-448	**Nacelles - Layout clearance improvement**							RE (-)			
54 A/F						Mos					
Eff: 13-Jan-2009						Hrs					
						Ldg					
Note: M2987, M2924, M3053, 251, 253 to 315 and A/C with SB F50 to 280						Flt					
F50-534	**Nacelles and Pylons – Engines – Core Cowl Assembly Corrosion Protection**							T (A/R)		Optional	
54 A/F						Mos					
Eff: 22-Sep-2016						Hrs					
(AVG MAN HRS: 80)						Ldg					
						Flt					
▼ 55 - STABILIZERS											
	Edge Elevator							RE (O/C)			
55 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Elevator							RE (O/C)			
55 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Elevator							RE (O/C)			
55 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Hortizontal Stab Pin							RE (O/C)			
55 A/F	Aft - Left					Mos	14-Sep-2023				
FGFB331075	New	0				Hrs	13,276.7				
2376		0				Ldg	8,977				
		0				Flt	8,977				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Hortizontal Stab Pin							RE (O/C)			
	55 A/F	Aft - Right					Mos	14-Sep-2023				
	FGFB331075	New		0			Hrs	13,276.7				
	2375			0			Ldg	8,977				
				0			Flt	8,977				
		Rudder							RE (O/C)			
	55 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
55-00-00-210-801-01		**General Visual Inspection of the Horizontal and Vertical Stabilizers and of Engine 2 Air Intake and S-Duct**							RE		Acft Maint Ops (5-10)	
	55 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
55-00-00-210-801-01 (5-15)		**General Visual Inspection of the Horizontal and Vertical Stabilizers and of Engine 2 Air Intake and S-Duct**							RE		CPCP (5-15)	
	55 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
	(Tol. Adjustment: -141d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
55-00-00-220-801-01		**Detailed Inspection of the Horizontal and Vertical Stabilizers and of Engine 2 Air Intake and S-Duct**							RE		Acft Maint Ops (5-10)	
	55 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
	(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
55-00-00-220-801-01 (5-15)		**Detailed Inspection of the Horizontal and Vertical Stabilizers and of Engine 2 Air Intake and S-Duct**							RE		CPCP (5-15)	
	55 A/F						Mos	14-Sep-2023	74		01-Feb-2029	3.9 Years
	(Tol. Adjustment: -282d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
55-00-00-270-801-01		**Ultrasonic Inspection For Stress Corrosion In Stabilizer Hinges**							RE		Acft Maint Ops (5-10)	
	55 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
	(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
55-00-00-270-801-01 (5-15)		**Ultrasonic Inspection For Stress Corrosion In Stabilizer Hinges**							RE		CPCP (5-15)	
	55 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
	(Tol. Adjustment: -312d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
55-00-00-270-801-01 (5-40)		**Ultrasonic Inspection For Stress Corrosion In Stabilizer Hinges**							RE		AWL (5-40), SSIP	**≈18-Feb-2035**
	55 A/F						Mos	14-Sep-2023				
	Ref:55-160						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977	3,750		12,727	3,594 Flt
55-00-00-760-801-01		**Check of the Stabilizer Movable Surface Electrical Bonding - Rudder**							RE		Acft Maint Ops (5-10)	
	55 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
	(Tol. Adjustment: -171d)						Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
55-00-00-760-801-02	**Check of the Stabilizer Movable Surface Electrical Bonding - LH Elevator**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
55-00-00-760-801-03	**Check of the Stabilizer Movable Surface Electrical Bonding - RH Elevator**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
55-10-00-220-801-01	**Detailed Inspection of the Horizontal Stabilizer Internal Box Structure - Detailed Inspection of the Hs Internal Box Structure**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
Note: A/C with non-composite HS						Flt					
55-10-00-220-801-01 (5-15)	**Detailed Inspection of the Horizontal Stabilizer Internal Box Structure - Detailed Inspection of the Hs Internal Box Structure**							RE		CPCP (5-15)	
55 A/F						Mos	02-Sep-2016	148		02-Jan-2029	3.8 Years
						Hrs	12,978.6				
						Ldg	8,785				
Note: A/C with non-composite HS						Flt					
55-10-00-220-802-01	**Detailed Inspection of the Horizontal Stabilizer Front and Rear Spars**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-2C					Yrs	02-Sep-2016	12	+5m	(02-Sep-2028)	3.5 Years (+61 Days)
						Hrs	12,978.6				
						Ldg	8,785				
Note: A/C with non-composite HS						Flt					
55-10-00-220-802-01 (5-15)	**Detailed Inspection of the Horizontal Stabilizer Front and Rear Spars**							RE		CPCP (5-15)	
55 A/F						Mos	02-Sep-2016	148		02-Jan-2029	3.8 Years
						Hrs	12,978.6				
						Ldg	8,785				
Note: A/C with non-composite HS						Flt					
55-10-00-220-803-01 (5-40)	**Detailed Inspection of Horizontal Stabilizer Upper Panels Between Root and Rib 2**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
55 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
55-10-00-640-803-01	**Greasing of the Horizontal Stabilizer Front Torque Link, Actuator Upper Hinge, and Elevator U-Joints - Linkage U-Joints and Elevator Bearings**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
55-10-00-640-803-02	**Greasing of the Horizontal Stabilizer Front Torque Link, Actuator Upper Hinge, and Elevator U-Joints - Horizontal Stabilizer Front Hinge Points**							RE		Acft Maint Ops (5-10)	
55 A/F						Mos	26-Feb-2025	6	+1m	26-Aug-2025	5.8 Months (+31 Days)
						Hrs	13,520.9				
Note: A/C without SB F50-206						Ldg	9,133				
						Flt	9,133				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
55-10-03-640-801-01	**Lubrication of the Spring-Loaded Fairing Mechanism**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
55-10-31-220-801-01	**Dimensional Check of Horizontal Stabilizer Rear Hinge Bushings**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	31-Jan-2029	3.9 Years (+150 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
Note: Without exceeding 3750 FC						Ldg	8,977				
						Flt	8,977	3,750		12,727	3,594 Flt
55-10-31-220-801-01 (5-40)	**Dimensional Check of Horizontal Stabilizer Rear Hinge Bushings**							RE		ALI, AWL (5-40)	**≈18-Feb-2035**
55 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7				
Ref:55-150						Ldg	8,977				
Note: Without exceeding 3750 FC						Flt	8,977	3,750		12,727	3,594 Flt
55-10-33-640-801-01	**Lubrication of the Horizontal Stabilizer Rear Hinge Pins**							RE		Acft Maint Ops (5-10)	
55 A/F						Mos	30-Aug-2024	12	+1m	30-Aug-2025	5.9 Months (+31 Days)
						Hrs	13,386.3	600	+30	13,986.3	465.4 Hrs (+30)
Note: Removed tolerance adjustment per Steve Betts email, 5/23/2024. DRD						Ldg	9,044				
						Flt	9,043				
55-10-39-220-801-01 (5-40)	**Detailed Inspection of Horizontal Stabilizer Actuator Attachment Fittings and Pins**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
55 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
55-20-00-220-801-01 (5-40)	**Detailed Inspection of the Elevators Skin and Hinge Fittings**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
55 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
55-20-03-640-801-01	**Lubrication of the Elevator Bearings - LH Elevator**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
Note: A/C without M1382 or not equipped with sealed stainless steel bearings						Ldg	8,977				
						Flt	8,977				
55-20-03-640-801-02	**Lubrication of the Elevator Bearings - RH Elevator**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
Note: A/C without M1382 or not equipped with sealed stainless steel bearings						Ldg	8,977				
						Flt	8,977				
55-20-03-640-802-01	**Lubrication of the Elevator Control Surface Hinges**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
(Tol. Adjustment: -83d)						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
55-40-00-220-801-01 (5-40)	**Detailed Inspection of the Rudder Skin and Hinge Fittings**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
55 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
55-40-05-640-801-01	**Lubrication of the Rudder Bearings**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: A/C without M1382 or not equipped with sealed stainless steel bearings						Flt	8,977				
55-40-05-640-802-01	**Lubrication of the Rudder Control Surface Hinges**							RE		Acft Maint Ops (5-10)	
55 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
(Tol. Adjustment: -83d)						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
F50-031	**Horizontal Stabilizer - Drainage Of The Fairings**							RE (-)			
55 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
F50-031 R1	**Horizontal Stabilizer - Drainage of the fairings**							RE (-)			
55 A/F						Mos	22-Jan-1981				
Eff: 04-Apr-1980						Hrs					
						Ldg					
Note: M0148G						Flt					
F50-206	**Horizontal stabilizer - New scissor-fitting pins**							T (A/R)			
55 A/F						Mos					
Eff: 24-May-1989						Hrs					
						Ldg					
Note: M1485						Flt					
F50-223	**Vertical stabilizer-to-fuselage attachment - Fasteners with reduced tightness**							T (A/R)			
55 A/F						Mos					
Eff: 21-Jan-1993						Hrs					
						Ldg					
Note: M1571A						Flt					
F50-257	**Satellite communication - Fin tip antenna installation capability**							RE (-)			
55 A/F						Mos					
						Hrs					
						Ldg					
Note: M2703, M2083A						Flt					
F50-257 R1	**Satellite communication - Fin tip antenna installation capability**							T (-)			
55 A/F						Mos					
Eff: 11-Jul-2001						Hrs					
						Ldg					
Note: M2703, M2083A						Flt					
F50-274	**Horizontal stabilizer - Rear attachment fittings - Replacement of hinge pins**							RE (-)			
55 A/F						Mos	02-Sep-2016				
Eff: 17-Dec-1997						Hrs					
						Ldg					
Note: M2217, AD EASA 97-370-020 R2 (AD FAA 99-25-09)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-533	**Improvement of horizontal stabilizer trialing edge draining**							RE (-)			
55 A/F	Eff: 23-Apr-2015					Mos					
						Hrs					
						Ldg					
	Note: M3234					Flt					
▼ 56 - WINDOWS											
	Defogging Valve							RE (O/C)			
56 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Defogging Valve							RE (O/C)			
56 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Front Windshield							RE (O/C)			
56 A/F						Mos	17-Jan-2017				
MY20261-10-9						Hrs					
1923						Ldg					
						Flt					
	Lateral Window							RE (O/C)			
56 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Opening Window							RE (O/C)			
56 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Passenger Cabin Window							RE (O/C)			
56 A/F	Left No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Passenger Cabin Window							RE (O/C)			
56 A/F	Left No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Passenger Cabin Window							RE (O/C)			
56 A/F	Left No.3					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Passenger Cabin Window							RE (O/C)			
56 A/F	Left No.4					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Left No.5					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Left No.6					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Left No.7					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Right No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Right No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Right No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Right No.4					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Right No.5					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Right No.6					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Passenger Cabin Window							RE (O/C)			
	56 A/F	Right No.7					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Rear Window							RE (O/C)			
56 A/F	SPS F50.6.4.2 1253	Left					Mos	24-Mar-2021				
							Hrs					
							Ldg					
							Flt					
		Rear Window							RE (O/C)			
56 A/F	Unknown Unknown	Right					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					
		Windshield							RE (O/C)			
56 A/F	MY20268-10-9 3778	Copilot					Mos	24-Mar-2021				
							Hrs					
							Ldg					
							Flt					
		Windshield							RE (O/C)			
56 A/F	F50265001001 125	Pilot					Mos	12-Nov-1982				
							Hrs	770.55				
							Ldg	552				
							Flt					
56-10-09-640-801-01		**Lubrication of the Opening Window Mechanism - LH Sliding Window (145H1)**							RE		Acft Maint Ops (5-10)	
56 A/F	(Tol. Adjustment: -171d)	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
							Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
F50-198		**Cockpit rear windows - Installation of glass windows**							RE (-)			
56 A/F	Note: M1479, M1480B, M1590						Mos					
							Hrs					
							Ldg					
							Flt					
F50-198 R1		**Cockpit rear windows - Installation of glass windows**							T (A/R)			
56 A/F	Eff: 25-Jan-1990 Note: M1479, M1480B, M1590						Mos					
							Hrs					
							Ldg					
							Flt					
F50-441		**Cockpit opening window - Checking the heating network connectors**							T (A/R)			
56 A/F	Eff: 17-Mar-2004						Mos					
							Hrs					
							Ldg					
							Flt					
F50-527		**Structural capability for installation of cockpit windshields P/N 161602-5 and P/N 161602-6**							T (A/R)			
56 A/F	Eff: 06-Aug-2012 Note: R0352						Mos					
							Hrs					
							Ldg					
							Flt					
▼ 57 - WINGS												
		Aileron							RE (O/C)			
57 A/F	Unknown Unknown	Left					Mos	20-Jan-1981				
							Hrs	0				
							Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Aileron							RE (O/C)			
	57 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake							RE (O/C)			
	57 A/F	Left Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake							RE (O/C)			
	57 A/F	Left Middle					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake							RE (O/C)			
	57 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake							RE (O/C)			
	57 A/F	Right Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake							RE (O/C)			
	57 A/F	Right Middle					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake							RE (O/C)			
	57 A/F	Right Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Central Hinge							RE (H/T)			
	57 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Airbrake Central Hinge							RE (H/T)			
	57 A/F	Right Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Central Wing Section							RE (O/C)			
	57 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Flap							RE (O/C)			
	57 A/F	Left Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flap							RE (O/C)			
	57 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flap							RE (O/C)			
	57 A/F	Right Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flap							RE (O/C)			
	57 A/F	Right Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Inboard / Outboard Flap Junction Fairing							RE (O/C)			
	57 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Linking Fairing-Inboard Flap-Left Outboard Flap Assembly							RE (O/C)			
	57 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Movable Slat							RE (O/C)			
	57 A/F	Left Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Movable Slat							RE (O/C)			
	57 A/F	Left Outboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Movable Slat							RE (O/C)			
	57 A/F	Right Inboard					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Movable Slat							RE (O/C)			
	57 A/F	Right Outboard					Mos	11-Jul-2014				
	F50B144B2						Hrs					
	256RA						Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2007-01-12	**Identification Plates of the Outboard Slats**							RE (-)		Mandatory	
57 A/F						Mos	10-Oct-2007				
Eff: 06-Mar-2007						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2007-01-12 Paragraph (g)(1)	**Identification Of Outboard Slats - Inspection and Corrective Actions for Model Mystere-Falcon 50 Airplanes**							RE (-)		Mandatory	
57 A/F						Mos					
						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2007-01-12 Paragraph (g)(2)	**Identification Of Outboard Slats - Inspection and Corrective Actions for Model Mystere-Falcon 50 Airplanes**							RE (-)		Mandatory	
57 A/F						Mos					
						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2008-25-04	**Valve boxes - Analyzed in-service events revealed that corrosion of pressure relief valves in wing fuel tanks was likely to occur well before reaching their Time Between Overhaul (TBO) and could make the valves stick in the closed position - do the ultrasonic inspection**							T		Mandatory	**≈01-Oct-2060**
57 A/F						Mos	01-May-2024				
Eff: 15-Jan-2009 Deferred						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg		14,200		[21,956]	12,823 Ldg
						Flt					
2012-02-18	**Wings - revise the maintenance program to include ''Non-Destructive Check of Flap Tracks 2 and 5,'' Maintenance Procedure 57-607, of Chapter 5-40, ''Airworthiness Limitations,'' (This AD has been removed by AD 2019-05-14)**							T (-)		Mandatory	
57 A/F						Mos					
						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2013-09-03	**Wing Fuel Tank Modification**							T		Mandatory	
57 A/F						Mos	01-May-2024	150		[14-Feb-2026]	11.5 Months
Eff: 14-Aug-2013 Deferred						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2018-24-02	**LH and RH Ailerons of Airplanes Equipped with Blended Winglets - Reinforcing Straps (Doublers) - Inspection/ Replacement**							RE (-)		Mandatory	
57 A/F						Mos	16-Dec-2018				
Eff: 02-Jan-2019 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2018-24-02 Par. (g)	**LH and RH Ailerons of Airplanes Equipped with Blended Winglets - Reinforcing Straps (Doublers) - Repetitive Inspections and Corrective Action**							RE (-)		Mandatory	
57 A/F						Mos	22-Feb-2019				
Eff: 02-Jan-2019 Not Applicable						Hrs					
(AVG MAN HRS: 1) (ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2018-24-02 Par. (h)	**LH and RH Ailerons of Airplanes Equipped with Blended Winglets - Reinforcing Straps (Doublers) - Replacement (Terminating Action)**							RE (-)		Mandatory	
57 A/F						Mos					
Eff: 02-Jan-2019						Hrs					
(AVG MAN HRS: 32) (ISSUING AUTHORITY: FAA)						Ldg					
Note: NOTE: Refer to Aviation Partners, Inc., Falcon Service Bulletin SBF9-17-002, Revision A, dated December 20, 2017.						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
57-00-00-210-801-03	**General Visual Inspection of the Wings - LH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-210-801-03 (5-15)	**General Visual Inspection of the Wings - LH Wing**							RE		CPCP (5-15)	
57 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
(Tol. Adjustment: -141d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-210-801-04	**General Visual Inspection of the Wings - RH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-210-801-04 (5-15)	**General Visual Inspection of the Wings - RH Wing**							RE		CPCP (5-15)	
57 A/F						Mos	14-Sep-2023	25		23-May-2025	78 Days
(Tol. Adjustment: -141d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-220-802-01	**Detailed Inspection of the Wings - LH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-220-802-01 (5-15)	**Detailed Inspection of the Wings - LH Wing**							RE		CPCP (5-15)	
57 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
(Tol. Adjustment: -312d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-220-802-02	**Detailed Inspection of the Wings - RH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-220-802-02 (5-15)	**Detailed Inspection of the Wings - RH Wing**							RE		CPCP (5-15)	
57 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
(Tol. Adjustment: -312d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-760-801-01	**Electrical Bonding Check of the Wing Movable Surfaces - LH Aileron**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
57-00-00-760-801-02	**Electrical Bonding Check of the Wing Movable Surfaces - RH Aileron**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-760-801-03	**Electrical Bonding Check of the Wing Movable Surfaces - LH Flaps**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-760-801-04	**Electrical Bonding Check of the Wing Movable Surfaces - RH Flaps**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-760-801-05	**Electrical Bonding Check of the Wing Movable Surfaces - LH Slats**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-760-801-06	**Electrical Bonding Check of the Wing Movable Surfaces - RH Slats**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-760-801-07	**Electrical Bonding Check of the Wing Movable Surfaces - LH Airbrakes**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-00-00-760-801-08	**Electrical Bonding Check of the Wing Movable Surfaces - RH Airbrakes**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-10-00-220-801-01	**Detailed Inspection of the MLG Wheel Well Gap Sealing Brushes - LH MLG Bay**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
(Tol. Adjustment: -83d)						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				
57-10-00-220-801-02	**Detailed Inspection of the MLG Wheel Well Gap Sealing Brushes - RH MLG Bay**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
(Tol. Adjustment: -83d)						Hrs	13,386.3				
						Ldg	9,044				
						Flt	9,043				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
57-10-00-290-801-01	**Borescope Inspection of the Wing Tanks**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
57-10-00-290-801-01 (5-15)	**Borescope Inspection of the Wing Tanks**							RE		CPCP (5-15)	
57 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
57-10-00-290-801-01 (5-40)	**Borescope Inspection of the Wing Tanks**							RE		AWL (5-40), CMR	
57 A/F						Mos	14-Sep-2023	74		01-Jan-2029	3.8 Years
						Hrs	13,276.7				
(Tol. Adjustment: -312d)						Ldg	8,977				
						Flt	8,977				
57-10-01-220-801-01 (5-40)	**Detailed Inspection of Lower Wing Panels**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
57-10-01-270-801-01	**Ultrasonic Inspection of the Wing Lower Surface Panel Stiffeners Between Ribs 13 and 17**							T		Acft Maint Ops (5-10)	**≈22-Mar-2039**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		14,200		14,200	5,067 Flt
57-10-01-270-801-01 (5-40)	**Ultrasonic Inspection of the Wing Lower Surface Panel Stiffeners Between Ribs 13 and 17**							T		AWL (5-40), CMR	**≈22-Mar-2039**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		14,200		14,200	5,067 Flt
57-10-01-280-801-01	**Special Detailed Inspection (Ultrasonic) of Lower Wing Panels and Mapping of Reworked Areas (Only for A/C with reworked area)**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-2C					Yrs	14-Sep-2023	12	+2m	08-Jul-2034	9.3 Years (+62 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -432.2d) (SOURCE: Falcon 50/50EX MPD)						Ldg	8,977				
						Flt	8,977				
57-10-01-280-801-01 (5-15)	**Special Detailed Inspection (Ultrasonic) of Lower Wing Panels and Mapping of Reworked Areas**							RE		CPCP (5-15)	
57 A/F						Mos	14-Sep-2023	151		12-Jul-2035	10.4 Years
						Hrs	13,276.7				
(Tol. Adjustment: -272d)						Ldg	8,977				
						Flt	8,977				
57-10-01-280-801-01 (5-40)	**Special Detailed Inspection (Ultrasonic) of Lower Wing Panels and Mapping of Reworked Areas**							RE		AWL (5-40), SSIP	**≈16-Jul-2045**
57 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977	7,500		16,477	7,344 Flt
57-10-14-200-801-01 (5-40)	**Inspection of Wing Front Spar From Root to Rib 8 and From Rib 9 to Rib 17**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
57-10-14-200-802-01 (5-40)	**Inspection of Wing Front Spar From Rib 8 to Rib 9**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
57-10-14-250-802-01 (5-40)	**SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR SPLICE AREA AT RIB7 - LH WING**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
(SOURCE: Falcon 50/50EX MM 5-40 (DGT 113872))						Ldg					
Note: A/C that have overpassed 20000FC at the effective date of the revision 26, must apply the R3245-CDS. Contact Dassault-Aviation to get this R3245-CDS.						Flt		20,000		20,000	10,867 Flt
57-10-14-250-802-02 (5-40)	**SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR SPLICE AREA AT RIB7 - RH WING**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
(SOURCE: Falcon 50/50EX MM 5-40 (DGT 113872))						Ldg					
Note: A/C that have overpassed 20000FC at the effective date of the revision 26, must apply the R3245-CDS. Contact Dassault-Aviation to get this R3245-CDS.						Flt		20,000		20,000	10,867 Flt
57-10-15-200-801-01 (5-40)	**Inspection of Wing Rear Spar 1 From Root to Rib 3**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
57-10-15-200-802-01 (5-40)	**Inspection of Wing Rear Spar 2 From Rib 3 to Rib 17**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
57-10-15-250-801-01 (5-40)	**Eddy-Current Inspection of Wing Rear Spar Rib 8 Splice**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
57-41-13-640-801-01	**Greasing / Lubrication of the Slat Mechanisms (Lubrication Of The Slat Rollers)**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-24M					Mos	14-Sep-2023	24	+1m	(14-Sep-2025)	6.4 Months (+30 Days)
(Tol. Adjustment: -171d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-45-25-250-801-01 (5-40)	**Eddy Current Inspection of Slat Tracks**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
57-55-00-700-801-01	**Check of the Flap Lateral Clearance - LH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				
57-55-00-700-801-02	**Check of the Flap Lateral Clearance - RH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
(Tol. Adjustment: -225.9d)						Hrs	13,276.7				
						Ldg	8,977				
						Flt	8,977				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
57-55-07-220-801-01	**Detailed Inspection of the Protection on Inboard / Outboard Flap Junction Fairing Friction Areas - LH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
57-55-07-220-801-02	**Detailed Inspection of the Protection on Inboard / Outboard Flap Junction Fairing Friction Areas - RH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
57-55-11-210-801-01	**General Visual Inspection of the Fore Flap Brackets - LH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
Note: A/C with SB F50-174						Flt	8,977				
57-55-11-210-801-02	**General Visual Inspection of the Fore Flap Brackets - RH Wing**							RE		Acft Maint Ops (5-10)	**≈03-Aug-2025**
57 A/F						Mos	14-Sep-2023				
						Hrs	13,276.7	400	+30	13,676.7	155.8 Hrs (+30)
Note: A/C without SB F50-174						Ldg	8,977				
						Flt	8,977				
57-55-13-640-801-01	**Greasing / Lubrication of Flap Rollers and Tracks - LH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F						Mos	14-Sep-2023	24	+1m	23-Mar-2025	17 Days (+31)
						Hrs	13,276.7	800	+30	14,076.7	555.8 Hrs (+30)
(Tol. Adjustment: -171d)						Ldg	8,977				
						Flt	8,977				
57-55-13-640-801-02	**Greasing / Lubrication of Flap Rollers and Tracks - RH Wing**							RE		Acft Maint Ops (5-10)	
57 A/F						Mos	14-Sep-2023	24	+1m	23-Mar-2025	17 Days (+31)
						Hrs	13,276.7	800	+30	14,076.7	555.8 Hrs (+30)
(Tol. Adjustment: -171d)						Ldg	8,977				
						Flt	8,977				
57-55-21-250-801-01	**Eddy-Current Inspection of the Flap Tracks 2 and 5**							RE		Acft Maint Ops (5-10)	**≈20-Jun-2040**
57 A/F						Mos	12-May-2010				
						Hrs	11,245				
						Ldg					
						Flt	7,850	6,800		14,650	5,517 Flt
57-55-21-250-801-01 (5-40)	**Eddy-Current Inspection of the Flap Tracks 2 and 5**							RE		AWL (5-40), CMR	**≈20-Jun-2040**
57 A/F						Mos	12-May-2010				
						Hrs	11,245				
Ref:57-607						Ldg					
						Flt	7,850	6,800		14,650	5,517 Flt
57-60-00-220-801-01 (5-40)	**Detailed Inspection of the Aileron Skin and Hinge Fittings**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
57 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
57-60-05-640-801-01	**Pressure Lubrication of the Aileron Bearings - LH Aileron Bearings**							RE		Acft Maint Ops (5-10)	
57 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
Note: A/C without M1382 or A/C not equipped with sealed stainless steel bearings						Ldg	8,977				
						Flt	8,977				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
57-60-05-640-801-02		**Pressure Lubrication of the Aileron Bearings - RH Aileron Bearings**							RE		Acft Maint Ops (5-10)	
57 A/F		05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
							Hrs	13,276.7				
							Ldg	8,977				
		Note: A/C without M1382 or A/C not equipped with sealed stainless steel bearings					Flt	8,977				
57-60-05-640-802-01		**Lubrication of the Aileron Control Surface Hinges - LH Aileron**							RE		Acft Maint Ops (5-10)	
57 A/F		05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
		(Tol. Adjustment: -83d)					Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
57-60-05-640-802-02		**Lubrication of the Aileron Control Surface Hinges - RH Aileron**							RE		Acft Maint Ops (5-10)	
57 A/F		05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
		(Tol. Adjustment: -83d)					Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
57-70-03-640-801-01		**Lubrication of the Airbrake Hinges**							RE		Acft Maint Ops (5-10)	
57 A/F		05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
		(Tol. Adjustment: -83d)					Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
57-70-03-960-801-01		**Discard of Outboard Airbrake Center Hinge - LH Outboard Airbrake Center Hinge (L901Cd)**							RE		Comp Maint Ops (5-20)	**≈27-Apr-2055**
57 A/F		Left Outboard					Mos					
Unknown							Hrs					
Unknown							Ldg					
		Note: P/N F50B165003001 or FGFC165003001					Flt		20,000		20,000	10,867 Flt
57-70-03-960-801-01 (5-40)		**Discard of Outboard Airbrake Center Hinge - LH Outboard Airbrake Center Hinge (L901Cd)**							RE		AWL (5-40), Life Limit	**≈27-Apr-2055**
57 A/F		Left Outboard					Mos					
Unknown							Hrs					
Unknown							Ldg					
		Note: P/N F50B165003001 or FGFC165003001					Flt		20,000		20,000	10,867 Flt
57-70-03-960-801-02		**Discard of Outboard Airbrake Center Hinge - RH Outboard Airbrake Center Hinge (R901Cd)**							RE		Comp Maint Ops (5-20)	**≈27-Apr-2055**
57 A/F		Right Outboard					Mos					
Unknown							Hrs					
Unknown							Ldg					
		Note: P/N F50B165003001 or FGFC165003001					Flt		20,000		20,000	10,867 Flt
57-70-03-960-801-02 (5-40)		**Discard of Outboard Airbrake Center Hinge - RH Outboard Airbrake Center Hinge (R901Cd)**							RE		AWL (5-40), Life Limit	**≈27-Apr-2055**
57 A/F		Right Outboard					Mos					
Unknown							Hrs					
Unknown							Ldg					
		Note: P/N F50B165003001 or FGFC165003001					Flt		20,000		20,000	10,867 Flt
F50-030		**Leading edge slat - Installation of anti-rumble buzz seals (Superseded by SB-F50-130) (No longer applicable)**							T (A/R)			
57 A/F							Mos					
Eff: 07-Mar-1980							Hrs					
							Ldg					
		Note: M0354, M0163B					Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-059	**Wing flaps - Installation of actuator with hinge pins locked by a cotter pin**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
Note: M0337						Flt					
F50-059 R1	**Wing flaps - Installation of actuator with hinge pins locked by a cotter pin**							T (A/R)			
57 A/F						Mos					
Eff: 20-Feb-1981						Hrs					
						Ldg					
Note: M0337						Flt					
F50-098	**Leading edge slats - Improved anti-rumble buzz device (Superseded by SB-F50-130) (No longer applicable)**							RE (-)			
57 A/F						Mos	28-Oct-1981				
Complied With						Hrs					
						Ldg					
Note: M0736, M0720						Flt					
F50-098 R1	**Leading edge slats - Improved anti-rumble buzz device (Superseded by SB-F50-130) (No longer applicable)**							T (A/R)			
57 A/F						Mos					
Eff: 05-May-1981						Hrs					
						Ldg					
Note: M0736, M0720						Flt					
F50-130	**Leading edge slats - Installation of anti-rumble buzz pads**							T (A/R)			
57 A/F						Mos					
Eff: 24-Jun-1983						Hrs					
						Ldg					
Note: M0392, M0163B, M0720, M						Flt					
F50-174	**Flaps - New titanium droplets brackets**							T (A/R)			
57 A/F						Mos	18-Jun-2023				
Eff: 04-Jun-1986	Partially Complied With					Hrs					
SB:F50-57-005						Ldg					
						Flt					
F50-194	**Airbrake actuator installation - Drainage of sealed housing**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
Note: M1467B						Flt					
F50-194 R1	**Airbrake actuator installation - Drainage of sealed housing**							T (A/R)			
57 A/F						Mos					
Eff: 27-Mar-1990						Hrs					
						Ldg					
Note: M1467B						Flt					
F50-230	**Wings - Main frame - Installation of brush seals with PR compound**							T (A/R)			
57 A/F						Mos					
Eff: 19-Apr-1993						Hrs					
						Ldg					
Note: M1784A						Flt					
F50-242	**Wing - Leading edge slats - Increased functional clearances**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
Note: M1880						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-242 R1	**Wing - Leading edge slats - Increased functional clearances**							T (A/R)			
57 A/F						Mos					
Eff: 10-May-2006						Hrs					
						Ldg					
Note: M1880						Flt					
F50-331	**Wing root recesses - New protective scheme**							RE (-)			
57 A/F						Mos	25-May-2010				
Complied With						Hrs					
						Ldg					
						Flt					
F50-331 R1	**Wing root recesses - New protective scheme**							RE (-)			
57 A/F						Mos	25-May-2010				
Complied With						Hrs					
						Ldg					
						Flt					
F50-331 R2	**Wing root recesses - New protective scheme**							RE (-)			
57 A/F						Mos					
Eff: 19-Feb-2004						Hrs					
						Ldg					
Note: M2551						Flt					
F50-347	**Flap tracks - Increased clearance between track 3 and track 4 stops and the track protection fairing**							T (A/R)			
57 A/F						Mos					
Eff: 11-Apr-2001						Hrs					
						Ldg					
Note: M2749						Flt					
F50-421	**Checking the lower surface of the outboard flaps near the flaps link rod protective fairings**							RE (-)			
57 A/F						Mos	03-Jul-2003				
						Hrs					
						Ldg					
						Flt					
F50-421 R1	**Checking the lower surface of the outboard flaps near the flaps link rod protective fairings**							T (A/R)			
57 A/F						Mos					
Eff: 13-Mar-2003						Hrs					
						Ldg					
						Flt					
F50-474	**Flap's fillets/fuselage door interference - Adding a protective shim on the karman fairings**							RE (-)			
57 A/F						Mos	25-May-2010				
Eff: 09-Mar-2006 Complied With						Hrs	11,245				
						Ldg	7,850				
Note: M3003						Flt					
F50-475	**Outboard slats - Anti-icing manifold conformity check**							RE (-)			
57 A/F						Mos	29-Aug-2006				
Eff: 01-Feb-2006						Hrs	10,346.8				
						Ldg	7,284				
Note: AD EASA 2006-0037 (AD FAA 2007-01-12)						Flt					
F50-478	**Outboard slats - Replacing anti-icing manifold for conformity**							RE (-)			
57 A/F						Mos	29-Aug-2006				
Eff: 01-Feb-2006						Hrs	10,346.8				
						Ldg	7,284				
Note: M3015, AD EASA 2006-0037 (AD FAA 2007-01-12)						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-496	**Wing tank modification**							RE (-)			
57 A/F						Mos	14-Aug-2013				
Complied With						Hrs					
						Ldg					
Note: M3106, M3140, AD EASA 2011-0193 (AD FAA 2013-09-03)						Flt					
F50-496 R1	**Wing tank modification**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
Note: M3106, M3140, AD EASA 2011-0193 (AD FAA 2013-09-03)						Flt					
F50-496 R2	**Wing tank modification**							RE (-)			
57 A/F						Mos					
Eff: 12-Mar-2010						Hrs					
						Ldg					
Note: M3106, M3140, AD EASA 2011-0193 (AD FAA 2013-09-03)						Flt					
F50-496 R3	**Wings - Wing Tank Modification**							RE (-)		Mandatory	
57 A/F						Mos					
Eff: 30-Oct-2009						Hrs					
(AVG MAN HRS: 640)						Ldg					
						Flt					
F50-508	**Wings - Airbrakes - Installation of new airbrakes**							RE (-)			
57 A/F						Mos					
						Hrs					
						Ldg					
Note: M2516						Flt					
F50-508 R1	**Wings - Airbrakes - Installation of new airbrakes**							T (A/R)			
57 A/F						Mos					
Eff: 13-Jan-2014						Hrs					
						Ldg					
Note: M2516						Flt					
F50-511	**Flaps deflector - Improvement of the sealing strip**							T (A/R)			
57 A/F						Mos					
Eff: 12-Oct-2009						Hrs					
						Ldg					
Note: M3155						Flt					
F50-516	**Improved corrosion protection on fore flap bonding plates**							T (A/R)			
57 A/F						Mos	28-Apr-2012				
Eff: 07-Nov-2011 Deferred						Hrs	11,487				
						Ldg	8,001				
Note: M3196, A/C without M3196						Flt					
F50-526	**Flap bonding springs - Improvement of corrosion protection**							T (A/R)			
57 A/F						Mos					
Eff: 21-Nov-2013						Hrs					
						Ldg					
Note: M3211						Flt					
F50-539	**Wings - Outboard Slats - Modification of Actuator Fairings to Install Actuator P/N 106132-08**							RE (-)		Optional	
57 A/F						Mos					
Eff: 13-Jun-2017						Hrs					
(AVG MAN HRS: 1.5)						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-539-1	**Wings - Outboard Slats - Modification of Actuator Fairings to Install Actuator P/N 106132-08 - LH Wing**							T (A/R)		Optional	
57 A/F						Mos					
Eff: 13-Jun-2017						Hrs					
(AVG MAN HRS: 1.5)						Ldg					
						Flt					
F50-539-2	**Wings - Outboard Slats - Modification of Actuator Fairings to Install Actuator P/N 106132-08 - RH Wing**							T (A/R)		Optional	
57 A/F						Mos					
Eff: 13-Jun-2017						Hrs					
(AVG MAN HRS: 1.5)						Ldg					
						Flt					
▼ 70 - STANDARD PRACTICES - ENGINES											
ST01007CH-D	**Installation of AlliedSignal Aerospace N1 Digital Electronic Engine Controls (DEEC)**							RE (-)			
70 A/F						Mos	07-May-1999				
Complied With						Hrs					
						Ldg					
						Flt					
▼ 71 - POWER PLANT											
	Engine Aft Mount							RE (O/C)			
71 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine Aft Mount							RE (O/C)			
71 A/F	No.3					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine Harness Assy							RE (O/C)			
71 A/F	Right					Mos	13-Sep-2012				
3070934-2						Hrs					
12-150262-31535						Ldg					
						Flt					
	Engine Hoist							RE (O/C)			
71 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine Left Front Shock Mount							RE (O/C)			
71 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine Lower Front Mount							RE (O/C)			
71 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine Lower Front Mount							RE (O/C)			
71 A/F	No.3					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Rear Shock Mount							RE (O/C)			
	71 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Right Front Shock Mount							RE (O/C)			
	71 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Upper Front Mount							RE (O/C)			
	71 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Upper Front Mount							RE (O/C)			
	71 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
2008-02-19		**High pressure (HP) turbine rotor assemblies**							RE (-)		Mandatory	
	71 ENG1						Mos	28-Feb-2008				
	Not Applicable	By Part number installed					Hrs	12,096.1				
	(ISSUING AUTHORITY: FAA)						Enc	9,688				
2008-02-19		**High pressure (HP) turbine rotor assemblies**							RE (-)		Mandatory	
	71 ENG2						Mos	28-Feb-2008				
	Not Applicable	by PN					Hrs					
	(ISSUING AUTHORITY: FAA)						Enc					
2008-02-19		**High pressure (HP) turbine rotor assemblies**							RE (-)		Mandatory	
	71 ENG3						Mos	28-Feb-2008				
	Not Applicable	BY PART NUMBER INSTALLED					Hrs					
	(ISSUING AUTHORITY: FAA)						Enc					
71-00-00-001		**Check Electrical Wiring And Connections**							RE		LMM - Requirement	**≈21-Feb-2026**
	71 ENG1	PKG 600/800 Hour					Mos	04-Jan-2023				
							Hrs	13,282.8	600		(13,882.8)	355.7 Hrs (+200)
							Enc	7,730				
71-00-00-001		**Check Electrical Wiring And Connections**							RE		LMM - Requirement	**≈24-Sep-2026**
	71 ENG2	PKG 600/800 Hour					Mos	20-Oct-2021				
							Hrs	13,213.1	600		(13,813.1)	567.1 Hrs (+200)
							Enc	8,940				
71-00-00-001		**Check Electrical Wiring And Connections**							RE		LMM - Requirement	**≈12-Mar-2025**
	71 ENG3	PKG 600/800 Hour					Mos	26-Feb-2014				
							Hrs	12,890.5	600		(13,490.5)	14.7 Hrs (+200)
							Enc	7,586				
71-00-LMM-002		**Check Plumbing Lines And Connections for security, loose or broken clamps and brackets, leaks, cracks, cuts, or rubbing**							RE		LMM - Requirement	**≈21-Feb-2026**
	71 ENG1	PKG 600/800 Hour					Mos	04-Jan-2023				
							Hrs	13,282.8	600	+200	(13,882.8)	355.7 Hrs (+200)
							Enc	7,730				
71-00-LMM-002		**Check Plumbing Lines And Connections for security, loose or broken clamps and brackets, leaks, cracks, cuts, or rubbing**							RE		LMM - Requirement	**≈24-Sep-2026**
	71 ENG2	PKG 600/800 Hour					Mos	20-Oct-2021				
							Hrs	13,213.1	600	+200	(13,813.1)	567.1 Hrs (+200)
							Enc	8,940				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
71-00-LMM-002	**Check Plumbing Lines And Connections for security, loose or broken clamps and brackets, leaks, cracks, cuts, or rubbing**							RE		LMM - Requirement	**≈12-Mar-2025**
71 ENG3	PKG 600/800 Hour					Mos	26-Feb-2014				
						Hrs	12,890.5	600	+200	(13,490.5)	14.7 Hrs (+200)
						Enc	7,586				
71-20-01-220-801-01 (5-40)	**Detailed Inspection of Engine 1 and 3 Front and Rear Mounts**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
71-20-02-250-801-01	**Special Detailed Inspection (Eddy Current) of the Engine 1 and 3 Front Mounts and Fail Safe Attachments - Engine 1 Front Mount**							RE (N/A)		Acft Maint Ops (5-10)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-02-250-801-02	**Special Detailed Inspection (Eddy Current) of the Engine 1 and 3 Front Mounts and Fail Safe Attachments - Engine 3 Front Mount**							RE (N/A)		Acft Maint Ops (5-10)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-02-250-801-03	**Special Detailed Inspection (Eddy Current) of the Engine 1 and 3 Front Mounts and Fail Safe Attachments - Engine 1 Fail Safe Attachments**							RE (N/A)		Acft Maint Ops (5-10)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-02-250-801-04	**Special Detailed Inspection (Eddy Current) of the Engine 1 and 3 Front Mounts and Fail Safe Attachments - Engine 3 Fail Safe Attachments**							RE (N/A)		Acft Maint Ops (5-10)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-05-350-801-01	**Restoration of the Engine 1 and 3 Front Mount Vibration Isolators (Overhaul) - Engine 1 Front Mount Upper Vibration Isolator (L901EZ1)**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-05-350-801-02	**Restoration of the Engine 1 and 3 Front Mount Vibration Isolators (Overhaul) - Engine 1 Front Mount Lower Vibration Isolator (L901EZ2)**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-05-350-801-03	**Restoration of the Engine 1 and 3 Front Mount Vibration Isolators (Overhaul) - Engine 3 Front Mount Upper Vibration Isolator (R901EZ1)**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-05-350-801-04	**Restoration of the Engine 1 and 3 Front Mount Vibration Isolators (Overhaul) - Engine 3 Front Mount Lower Vibration Isolator (R901EZ2)**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
71-20-07-250-801-01	**Special Detailed Inspection (Ndt) of the Engine 1 and 3 Rear Mounts - Engine 1 Rear Mount (L910Ez)**							RE (N/A)		Acft Maint Ops (5-10)	
71 A/F						Mos					
						Hrs					
						Ldg					
Note: Not Applicable per Engine variant						Flt					
71-20-07-250-801-02	**Special Detailed Inspection (Ndt) of the Engine 1 and 3 Rear Mounts - Engine 3 Rear Mount (R910Ez)**							RE (N/A)		Acft Maint Ops (5-10)	
71 A/F						Mos					
						Hrs					
						Ldg					
Note: Not Applicable per Engine variant						Flt					
71-20-07-960-801-01	**Discard of the Engine Rear Attachment Auxiliary Fitting Bolt - Engine 1**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-07-960-801-01 (5-40)	**Discard of the Engine Rear Attachment Auxiliary Fitting Bolt - Engine 1**							RE (N/A)		AWL (5-40), Life Limit	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-07-960-801-02	**Discard of the Engine Rear Attachment Auxiliary Fitting Bolt - Engine 3**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-07-960-801-02 (5-40)	**Discard of the Engine Rear Attachment Auxiliary Fitting Bolt - Engine 3**							RE (N/A)		AWL (5-40), Life Limit	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-09-350-801-01	**Restoration of the Engine 1 and 3 Rear Mount Vibration Isolators (Overhaul) - Engine 1 Rear Mount Vibration Isolator (L911EZ)**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-09-350-801-02	**Restoration of the Engine 1 and 3 Rear Mount Vibration Isolators (Overhaul) - Engine 3 Rear Mount Vibration Isolator (R911EZ)**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
71-20-11-220-801-01 (5-40)	**Detailed Inspection of Engine 2 Hoisting Plate and Mounts**							T		AWL (5-40), SSIP	**≈27-Apr-2055**
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt		20,000		20,000	10,867 Flt
71-20-17-230-801-01	**Special Detailed Inspection of the Engine 2 Front Vibration Isolators / Replacement of Rubber Cores - Engine 2 LH Front Vibration Isolator (M900EZ1)**							RE		Comp Maint Ops (5-20)	**≈03-Oct-2027**
71 A/F						Mos	03-Nov-2001				
						Hrs	9,457	5,000	+150	14,457	936.1 Hrs (+150)
						Ldg	6,703				
Note: P/N LM833-SA10 or LM833-SA13 To be performed during engine removal for MPI/CZI without exceeding 5150 FH A/C WITH TFE 731-3 ENGINES						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
71-20-17-230-801-02	**Special Detailed Inspection of the Engine 2 Front Vibration Isolators / Replacement of Rubber Cores - Engine 2 RH Front Vibration Isolator (M900EZ2)**							RE		Comp Maint Ops (5-20)	**≈03-Oct-2027**
71 A/F						Mos	03-Nov-2001				
						Hrs	9,457	5,000	+150	14,457	936.1 Hrs (+150)
						Ldg	6,703				
Note: P/N LM833-SA10 or LM833-SA13						Flt					
To be performed during engine removal for MPI/CZI without exceeding 5150 FH A/C WITH TFE 731-3 ENGINES											
71-20-21-230-801-01	**Special Detailed Inspection of the Engine 2 Rear Vibration Isolator / Replacement of Rubber Cores - Engine 2 Rear Vibration Isolator (M910Ez)**							RE		Comp Maint Ops (5-20)	**≈03-Oct-2027**
71 A/F						Mos	03-Nov-2001				
						Hrs	9,457	5,000	+150	14,457	936.1 Hrs (+150)
						Ldg	6,703				
Note: P/N LM833-SA9						Flt					
To be performed during engine removal for MPI/CZI without exceeding 5150 FH A/C WITH TFE 731-3 ENGINES											
71-20-21-960-801-01	**Discard of the Engine 2 Rear Mount Vibration Isolator - Engine 2 Rear Vibration Isolator (M910EZ)**							RE (N/A)		Comp Maint Ops (5-20)	
71 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
92-02-18	**Inflight Operation - to prevent multiple inflight failures**							RE (-)		Mandatory	
71 ENG1						Mos					
Eff: 10-Feb-1993 Not Applicable	per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
D200808000038	**New N2 Monopole Resistance Values**							RE (-)		Service Information Letter	
71 ENG1						Mos					
Eff: 20-Oct-2008						Hrs					
						Enc					
D200808000038	**New N2 Monopole Resistance Values**							RE (-)		Service Information Letter	
71 ENG2						Mos					
Eff: 20-Oct-2008						Hrs					
						Enc					
D200808000038	**New N2 Monopole Resistance Values**							RE (-)		Service Information Letter	
71 ENG3						Mos					
Eff: 20-Oct-2008						Hrs					
						Enc					
D200808000038 Rev 1	**New N2 Monopole Resistance Values**							T (-)		Service Information Letter	
71 ENG1						Mos					
Eff: 30-Oct-2018						Hrs					
						Enc					
D200808000038 Rev 1	**New N2 Monopole Resistance Values**							T (-)		Service Information Letter	
71 ENG2						Mos					
Eff: 30-Oct-2018						Hrs					
						Enc					
D200808000038 Rev 1	**New N2 Monopole Resistance Values**							T (-)		Service Information Letter	
71 ENG3						Mos					
Eff: 30-Oct-2018						Hrs					
						Enc					
D200808000038 Rev 2	**New N2 Monopole Resistance Values**							T (A/R)		Service Information Letter	
71 ENG1						Mos					
Eff: 08-Nov-2018						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
D200808000038 Rev 2	**New N2 Monopole Resistance Values**							T (A/R)		Service Information Letter	
71 ENG2						Mos					
Eff: 08-Nov-2018						Hrs					
						Enc					
D200808000038 Rev 2	**New N2 Monopole Resistance Values**							T (A/R)		Service Information Letter	
71 ENG3						Mos					
Eff: 08-Nov-2018						Hrs					
						Enc					
D201304000013 Rev 1	**TFE731 and HTF7000 Electronic Engine Interface (EEI) Software and Windows 10 Certification Date**							T (A/R)		Service Information Letter	
71 ENG1						Mos					
Eff: 06-Dec-2018						Hrs					
						Enc					
D201304000013 Rev 1	**TFE731 and HTF7000 Electronic Engine Interface (EEI) Software and Windows 10 Certification Date**							T (A/R)		Service Information Letter	
71 ENG2						Mos					
Eff: 06-Dec-2018						Hrs					
						Enc					
D201304000013 Rev 1	**TFE731 and HTF7000 Electronic Engine Interface (EEI) Software and Windows 10 Certification Date**							T (A/R)		Service Information Letter	
71 ENG3						Mos					
Eff: 06-Dec-2018						Hrs					
						Enc					
F50-021	**Improved installation of the center engine**							RE (-)			
71 A/F						Mos					
Eff: 04-Feb-1980						Hrs					
						Ldg					
Note: M0093						Flt					
F50-113	**Side engine - Bolt adapted to aft engine mount accomodating an auxiliary bracket**							T (A/R)			
71 A/F						Mos					
Eff: 03-Dec-1981						Hrs					
						Ldg					
Note: M0874						Flt					
F50-117	**Engine with center aft mount cut through - Rework for attachment of HP bleed air tubing**							T (A/R)			
71 A/F						Mos					
Eff: 22-Sep-1982						Hrs					
						Ldg					
Note: M0965						Flt					
F50-132	**Side engine front mount attachment - Upper forward bolt of proper dimensions**							RE (-)			
71 A/F						Mos					
						Hrs					
						Ldg					
Note: M1023, AD EASA 82-174-2						Flt					
F50-132 R1	**Side engine front mount attachment - Upper forward bolt of proper dimensions**							RE (-)			
71 A/F						Mos	06-Apr-1984				
Eff: 31-Jan-1983						Hrs					
						Ldg					
Note: M1023, AD EASA 82-174-2						Flt					
F50-221	**Side engine oil breather valve drainage - Discharge via new drain stubs**							T (A/R)			
71 A/F						Mos					
Eff: 21-Nov-1991						Hrs					
						Ldg					
Note: M1437						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-276	**DEEC - Software V41.02.03.00**							RE (-)			
71 A/F						Mos	12-Oct-2010				
Eff: 24-Jun-1998						Hrs					
						Ldg					
Note: M2193, AD EASA 98-228-021 (AD FAA 2000-04-19)						Flt					
F50-277	**Reidentify and serialize the aft engine mount assembly**							RE (-)			
71 A/F						Mos					
Eff: 12-Jan-2000						Hrs					
						Ldg					
Note: M2257						Flt					
F50-294	**Nacelle - Intake barrel - Introduction of drainage assemblies**							RE (-)			
71 A/F						Mos					
						Hrs					
						Ldg					
Note: M2404						Flt					
F50-294 R1	**Nacelle - Intake barrel - Introduction of drainage assemblies**							RE (-)			
71 A/F						Mos					
Eff: 06-Dec-1999						Hrs					
						Ldg					
Note: M2404						Flt					
F50-302	**Upper fan cowl doors - Replacement of drainage tube**							RE (-)			
71 A/F						Mos					
Eff: 06-Dec-1999						Hrs					
						Ldg					
Note: M2394						Flt					
F50-303	**Lower fan cowl doors - Drainage holes in drag fairing**							RE (-)			
71 A/F						Mos					
Eff: 10-Feb-1999						Hrs					
						Ldg					
Note: M2405						Flt					
F50-310	**Nacelle - General fret protection**							RE (-)			
71 A/F						Mos					
Eff: 06-Dec-2000						Hrs					
						Ldg					
Note: M2597						Flt					
F50-313	**EBU harness to fuel temperature sensor additional clamping**							RE (-)			
71 A/F						Mos					
Eff: 18-Dec-1998						Hrs					
						Ldg					
Note: M2477						Flt					
F50-315	**New DEEC software V41.02.03.00 use of the mach hold and N1 functions**							RE (-)			
71 A/F						Mos					
Eff: 16-May-2005						Hrs					
						Ldg					
Note: M2495						Flt					
F50-324	**Engine - LH, RH and center firewire system improvement**							RE (-)			
71 A/F						Mos					
Eff: 12-Sep-2001						Hrs					
						Ldg					
Note: M2730						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-327	**Fuel control unit drain to fan cowl door - Foul condition**							RE (-)			
71 A/F						Mos					
Eff: 12-Jul-2000						Hrs					
						Ldg					
Note: M2537						Flt					
F50-330	**New DEEC P/N 2118882-4005 software V41.03.00.00**							RE (-)			
71 A/F						Mos					
Eff: 25-Aug-1999						Hrs					
						Ldg					
Note: M2562						Flt					
F50-341	**Nacelle - Lower fan cowl door, RH expanded cut-out**							RE (-)			
71 A/F						Mos					
Eff: 14-Jun-2000						Hrs					
						Ldg					
Note: M2608						Flt					
F50-344	**Nacelle - Low pressure duct - Short bolts**							RE (-)			
71 A/F						Mos					
Eff: 15-Mar-2000						Hrs					
						Ldg					
Note: M2595						Flt					
F50-349	**Engine - LH Starter/generator control and power harness-re-routing**							RE (-)			
71 A/F						Mos					
Eff: 12-Sep-2001						Hrs					
						Ldg					
Note: M2648						Flt					
F50-352	**Engine - L/H Starter/generator harness - Re-route for oil drain-back improvement**							RE (-)			
71 A/F						Mos					
Eff: 12-Sep-2001						Hrs					
						Ldg					
Note: M2665, 251, 253 to 303, 309 and A/C with SB F50-349 or M2648						Flt					
F50-363	**Nacelles/pylons - Lower fan cowl door - Repair/replacement of forward zed member**							RE (-)			
71 A/F						Mos					
						Hrs					
						Ldg					
Note: M2717						Flt					
F50-363 R1	**Nacelles/pylons - Lower fan cowl door - Repair/replacement of forward zed member**							RE (-)			
71 A/F						Mos					
Eff: 16-Mar-2009						Hrs					
						Ldg					
Note: M2717						Flt					
F50-376	**New DEEC Honeywell P/N 2118882-4006**							RE (-)			
71 A/F						Mos					
						Hrs					
						Ldg					
Note: M2731, 2 to 250, 252 with TFE731-40-1C and DEEC P/N 2118882-4005 (SB F50-280) and 251, 253 to 324 with M2562 or SB F50-330						Flt					
F50-376 R1	**New DEEC Honeywell P/N 2118882-4006**							RE (-)			
71 A/F						Mos					
						Hrs					
						Ldg					
Note: M2731, 2 to 250, 252 with TFE731-40-1C and DEEC P/N 2118882-4005 (SB F50-280) and 251, 253 to 324 with M2562 or SB F50-330						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-376 R2	**New DEEC Honeywell P/N 2118882-4006**							T (A/R)			
71 A/F						Mos					
Eff: 10-Apr-2003						Hrs					
						Ldg					
Note: M2731, 2 to 250, 252 with TFE731-40-1C and DEEC P/N 2118882-4005 (SB F50-280) and 251, 253 to 324 with M2562 or SB F50-330						Flt					
F50-402	**Center engine, N1 harness bracket replacement**							RE (-)			
71 A/F						Mos					
Eff: 15-Jan-2003						Hrs					
						Ldg					
Note: M2739, 251, 253 to 352 without M2739 and A/C with SB F50-280						Flt					
▼ 72 - ENGINE											
	1st Low Pressure Turbine (LPT) Rotor							RE (O/C)			
72 ENG1						Mos	31-Mar-2006				
Unknown						Hrs					
Unknown						Enc					
	1st Stage Low Pressure Compressor (LPC) Blades							RE (O/C)			
72 ENG2						Mos	22-Aug-2006				
Unknown						Hrs	11,473.6				
Unknown						Enc	6,903				
	1st Stage Low Pressure Compressor (LPC) Blades							RE (O/C)			
72 ENG3						Mos	29-Aug-2006				
3072399-1						Hrs	11,703.4				
NSN						Enc	6,884				
	1st Stage Wheel Shroud							RE (O/C)			
72 ENG2						Mos	22-Aug-2006				
3071873-2						Hrs	11,473.6				
96132620000918						Enc	6,903				
	1st Stage Wheel Shroud							RE (O/C)			
72 ENG3						Mos	29-Aug-2006				
3071873-2						Hrs	11,703.4				
LOT8070						Enc	6,884				
	2nd Stage Comp Shroud							RE (O/C)			
72 ENG1						Mos	04-Nov-1980				
Unknown						Hrs	0				
Unknown						Enc	0				
	2nd Stage Comp Shroud							RE (O/C)			
72 ENG2						Mos	22-Aug-2006				
3072403-1						Hrs	11,473.6				
LOT9815						Enc	6,903				
	2nd Stage Comp Shroud							RE (O/C)			
72 ENG3						Mos	29-Aug-2006				
3072403-1						Hrs	11,703.4				
LOT8763						Enc	6,884				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		2nd Stage Low Pressure Compressor (LPC) Blades							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	Unknown						Hrs	11,473.6				
	Unknown						Enc	6,903				
		2nd Stage Low Pressure Compressor (LPC) Blades							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3072400-3						Hrs	11,703.4				
	NSN						Enc	6,884				
		2nd Stage Wheel Shroud							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3070289-2						Hrs	11,473.6				
	394110						Enc	6,903				
		2nd Stage Wheel Shroud							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3070289-2						Hrs	11,703.4				
	460226-001						Enc	6,884				
		3RD LPT Stator Assembly							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		3RD LPT Stator Assembly							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		3RD LPT Stator Assembly							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		3rd Stage Comp Shroud							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		3rd Stage Comp Shroud							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3072404-1						Hrs	11,473.6				
	LOT1298						Enc	6,903				
		3rd Stage Comp Shroud							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		3rd Stage Low Pressure Compressor (LPC) Blades							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	Unknown						Hrs	11,473.6				
	Unknown						Enc	6,903				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		3rd Stage Low Pressure Compressor (LPC) Blades							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3072401-1						Hrs	11,703.4				
	NSN						Enc	6,884				
		3rd Stage Wheel Shroud							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3070292-4						Hrs	11,473.6				
	LOT8146						Enc	6,903				
		3rd Stage Wheel Shroud							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3070292-4						Hrs	11,703.4				
	625451						Enc	6,884				
		4TH LP Compressor Stator							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3074555-9						Hrs					
	97P02903						Enc					
		4TH LP Compressor Stator							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		4TH LP Compressor Stator							RE (O/C)			
	72 ENG3		0				Mos	29-Aug-2006				
	3074555-9	New	0				Hrs	11,703.4				
	LT06P03231		0				Enc	6,884				
		4TH LPC Shouldered Shaft							RE (O/C)			
	72 ENG1						Mos	14-Jul-2022				
	3077077-2						Hrs					
	0P-23500						Enc					
		4TH LPC Shouldered Shaft							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		4TH LPC Shouldered Shaft							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		4TH LPC Stator and Shroud Assembly							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		4TH LPC Stator and Shroud Assembly							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		4TH LPC Stator and Shroud Assembly							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		4th Stage Comp Shroud							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		4th Stage Comp Shroud							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3072405-1						Hrs	11,473.6				
	07590-375763001R						Enc	6,903				
		4th Stage Comp Shroud							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3072405-1						Hrs	11,703.4				
	19241-0036						Enc	6,884				
		4th Stage Low Pressure Compressor (LPC) Blades							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	Unknown						Hrs	11,473.6				
	Unknown						Enc	6,903				
		4th Stage Low Pressure Compressor (LPC) Blades							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3072402-1						Hrs	11,703.4				
	NSN						Enc	6,884				
		Accessory Gearbox							RE (O/C)			
	72 ENG1						Mos	04-Jan-2023				
	3070003-26		1,738				Hrs	13,282.8				
	P-2197						Enc	7,730				
		Accessory Gearbox							RE (O/C)			
	72 ENG2						Mos	05-Oct-2001				
	3070003-26						Hrs	9,339.1				
	P-2194						Enc	5,878				
		Accessory Gearbox							RE (O/C)			
	72 ENG3						Mos	17-Dec-2001				
	3070003-26						Hrs	9,651.9				
	P-2207						Enc	5,893				
		Bearing							RE (O/C)			
	72 ENG2	No.1					Mos	22-Aug-2006				
	358752-3						Hrs	11,473.6				
	060233001971						Enc	6,903				
		Bearing							RE (O/C)			
	72 ENG2	No.2					Mos	22-Aug-2006				
	3072885-1						Hrs	11,473.6				
	050633113747						Enc	6,903				

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Carbon Seal Fuel Pump							RE (O/C)			
	72 ENG1						Mos	03-Nov-1980				
	3020052-5						Hrs					
	Unknown						Enc					
		Carbon Seal Fuel Pump							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Carbon Seal Fuel Pump							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Carbon Seal Hydraulic Pump							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Carbon Seal Hydraulic Pump							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Carbon Seal Hydraulic Pump							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Case HP							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3071722-14						Hrs					
	0-08165-302						Enc					
		Case Intermediate							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3071963-4						Hrs					
	0J-1703						Enc					
		Case Intermediate							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Case Intermediate							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Case LPC							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3071770-4						Hrs					
	8P-26154						Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Combustion Plenum Case							RE (O/C)			
	72 ENG1						Mos	04-Jan-2023				
	3072443-4		8,749				Hrs	13,282.8				
	0P-37552		7,644				Enc	7,730				
	Brand C:724120											
		Combustion Plenum Case							RE (O/C)			
	72 ENG2						Mos	05-Oct-2001				
	3072443-4						Hrs	9,339.1				
	8P-35972						Enc	5,878				
	Brand C:724120											
		Combustion Plenum Case							RE (O/C)			
	72 ENG3		0				Mos					
	3075749-1	New	0				Hrs	11,703.4				
	03P07218		0				Enc	6,884				
	Brand C:724120											
		Deswirl							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3075126-1						Hrs	11,473.6				
	NSN						Enc	6,903				
		Deswirl							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3075126-1						Hrs	11,703.4				
	NSN						Enc	6,884				
		Diffuser							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3077096-8						Hrs					
	8P-26236						Enc					
		Duct Fan							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3072420-7						Hrs					
	0-01599-1506						Enc					
		Engine Housing Fan Inlet							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3072262-8						Hrs					
	5-01599-540						Enc					
		Fan Assembly							RE (O/C)			
	72 ENG1	No.1					Mos	31-Mar-2006				
	3073570-6						Hrs					
	5-03229-4796						Enc					
		Fan Assembly							RE (O/C)			
	72 ENG1	No.2					Mos	31-Mar-2006				
	3073570-7						Hrs					
	5-03229-4796						Enc					
		Fan Disc							RE		LMM - Life Limit	**≈18-Dec-2042**
	72 ENG1						Mos	04-Jan-2023				
	3073563-2	Repaired	6,446.6		0		Hrs	13,282.8				
	5-03229-4796		3,430				Enc	7,730	10,000		14,300	6,414 Enc

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Fan Disc							RE		LMM - Life Limit	**≈21-Mar-2042**
	72 ENG2						Mos	22-Aug-2006				
	3073563-2						Hrs	11,473.6				
	5-03229-4792		2,763				Enc	6,903	10,000		14,140	6,147 Enc
		Fan Disc							RE		LMM - Life Limit	**≈19-Sep-2042**
	72 ENG3						Mos	29-Aug-2006				
	3073563-2		4,867.2				Hrs	11,703.4				
	5-03229-5065		2,584				Enc	6,884	10,000		14,300	6,326 Enc
		Fan Drive Shaft							RE (O/C)		LMM - Life Limit	
	72 ENG1						Mos	04-Jan-2023				
	3071955-5		13,772.1				Hrs	13,282.8				
	0P-53710		10,737				Enc	7,730				
		Note: Note: This component part have not had cyclic life limit assigned, but may be subject to failure as a result of undetected abuse and unpredictable contingencies. Therefore, to provide a record of service experience and cycles (partial cycle counting does not apply), a Life Limit Part Log Card must be maintained.										
		Fan Drive Shaft							RE (O/C)		LMM - Life Limit	
	72 ENG2						Mos	05-Oct-2001				
	3071955-5						Hrs	9,339.1				
	4P-6756						Enc	5,878				
		Note: Note: This component part have not had cyclic life limit assigned, but may be subject to failure as a result of undetected abuse and unpredictable contingencies. Therefore, to provide a record of service experience and cycles (partial cycle counting does not apply), a Life Limit Part Log Card must be maintained.										
		Fan Drive Shaft							RE (O/C)		LMM - Life Limit	
	72 ENG3						Mos					
	3071955-5		13,055.1				Hrs	11,703.4				
	8P11390		8,204				Enc	6,884				
		Note: Note: This component part have not had cyclic life limit assigned, but may be subject to failure as a result of undetected abuse and unpredictable contingencies. Therefore, to provide a record of service experience and cycles (partial cycle counting does not apply), a Life Limit Part Log Card must be maintained.										
		Fan Spinner							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	Unknown						Hrs	11,703.4				
	Unknown						Enc	6,884				
		Flange Shroud							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3071864-1						Hrs					
	Unknown						Enc					
		Flange Shroud							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3071864-1						Hrs	11,473.6				
	0606214						Enc	6,903				
		Flange Shroud							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		High Pressure Compressor Radial Impeller							RE		LMM - Life Limit	**≈11-Apr-2038**
	72 ENG1						Mos	04-Jan-2023				
	3073398-2		8,929.8				Hrs	13,282.8				
	0-12172-980		5,117				Enc	7,730	10,000		12,613	4,727 Enc
		High Pressure Compressor Radial Impeller							RE		LMM - Life Limit	**≈04-Sep-2044**
	72 ENG2						Mos	22-Aug-2006				
	3073398-3						Hrs	11,473.6				
	985332200048		1,878				Enc	6,903	10,000		15,025	7,032 Enc
		High Pressure Compressor Radial Impeller							RE		LMM - Life Limit	**≈01-Jun-2043**
	72 ENG3						Mos	29-Aug-2006				
	3073394-1		4,409.6				Hrs	11,703.4				
	0-23365-1168		2,332				Enc	6,884	10,000		14,552	6,578 Enc
		High Pressure Compressor Shouldered Shaft							RE		LMM - Life Limit	**≈31-Oct-2043**
	72 ENG1						Mos	04-Jan-2023				
	3072545-1		8,929.8				Hrs	13,282.8				
	2P-2983		5,117				Enc	7,730	12,000		14,613	6,727 Enc
		High Pressure Compressor Shouldered Shaft							RE		LMM - Life Limit	**≈11-Apr-2036**
	72 ENG2						Mos	22-Aug-2006				
	3072545-1						Hrs	11,473.6				
	0P-44319		6,903				Enc	6,903	12,000		12,000	4,007 Enc
		High Pressure Compressor Shouldered Shaft							RE		LMM - Life Limit	**≈30-Apr-2036**
	72 ENG3						Mos	29-Aug-2006				
	3072545-1		11,703.4				Hrs	11,703.4				
	0P48282		6,884				Enc	6,884	12,000		12,000	4,026 Enc
		High Pressure Rotor Stepped Seal Plate							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		High Pressure Rotor Stepped Seal Plate							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		High Pressure Rotor Stepped Seal Plate							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		High Pressure Turbine (HPT) Blades							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3074785-						Hrs	11,473.6				
	NSN						Enc	6,903				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		High Pressure Turbine Disc							RE		LMM - Life Limit	**≈26-Apr-2044**
	72 ENG1						Mos	04-Jan-2023				
	3075227-2		5,384.1				Hrs	13,282.8				
	961217200742		2,940				Enc	7,730	10,000		14,790	6,904 Enc
		Note: (TFE731-3B/-3BR only) Service Bulletin TFE731-72-3509 must be complied with. HP turbine disc, PN 3075814-1, can only be used with air cooled HP turbine blades, PN 3074785-4, -5, -6, -8. HP turbine disc, PN 3075814-1, cannot be used with pre Service Bulletin TFE731-72-3509 non air cooled HP turbine blades, PN 3072749-3.										
		High Pressure Turbine Disc							RE		LMM - Life Limit	**≈24-Jan-2043**
	72 ENG2						Mos	22-Aug-2006				
	3075227-2						Hrs	11,473.6				
	951217201331		2,460				Enc	6,903	10,000		14,443	6,450 Enc
		Note: (TFE731-3B/-3BR only) Service Bulletin TFE731-72-3509 must be complied with. HP turbine disc, PN 3075814-1, can only be used with air cooled HP turbine blades, PN 3074785-4, -5, -6, -8. HP turbine disc, PN 3075814-1, cannot be used with pre Service Bulletin TFE731-72-3509 non air cooled HP turbine blades, PN 3072749-3.										
		High Pressure Turbine Disc							RE		LMM - Life Limit	**≈29-Nov-2043**
	72 ENG3						Mos	29-Aug-2006				
	3075227-2		4,137.5				Hrs	11,703.4				
	961217201143		2,154				Enc	6,884	10,000		14,730	6,756 Enc
		High Pressure Turbine Rotor Seal Plate							RE		LMM - Life Limit	**≈23-Nov-2033**
	72 ENG1						Mos	04-Jan-2023				
	3072411-1		10,653.6				Hrs	13,282.8				
	4-18040-4462		6,696				Enc	7,730	10,000		11,034	3,148 Enc
		High Pressure Turbine Rotor Seal Plate							RE		LMM - Life Limit	**≈15-Dec-2040**
	72 ENG2						Mos	22-Aug-2006				
	3072411-1						Hrs	11,473.6				
	3-03160-1093		3,218				Enc	6,903	10,000		13,685	5,692 Enc
		High Pressure Turbine Rotor Seal Plate							RE		LMM - Life Limit	**≈13-Oct-2030**
	72 ENG3						Mos	29-Aug-2006				
	3072411-1		11,703.4				Hrs	11,703.4				
	0-18040-1119		6,884				Enc	6,884	10,000		10,000	2,026 Enc
		Inlet Stator Vanes							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Inlet Stator Vanes							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Inlet Stator Vanes							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3075478-2						Hrs	11,703.4				
	NSN						Enc	6,884				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Liner OTL							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3073632-2						Hrs					
	7-22151-7277						Enc					
		Liner, Combustion							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3073774-2						Hrs					
	05P10765						Enc					
		Liner, Combustion							RE (O/C)			
	72 ENG2						Mos					
	Unknown						Hrs					
	Unknown						Enc					
		Liner, Combustion							RE (O/C)			
	72 ENG3						Mos	03-Jun-1997				
	3073774-1						Hrs	7,565.9				
	4P-19930						Enc	4,730				
		Low Pressure Compressor Tie Rod							RE (O/C)		LMM - Life Limit	
	72 ENG1						Mos	04-Jan-2023				
	3073049-1		3,478.6				Hrs	13,282.8				
	2P-6209		4,012				Enc	7,730				
		Note: Note: This component part have not had cyclic life limit assigned, but may be subject to failure as a result of undetected abuse and unpredictable contingencies. Therefore, to provide a record of service experience and cycles (partial cycle counting does not apply), a Life Limit Part Log Card must be maintained.										
		Low Pressure Compressor Tie Rod							RE (O/C)		LMM - Life Limit	
	72 ENG2						Mos	05-Oct-2001				
	3070065-3						Hrs	9,339.1				
	0P-33600						Enc	5,878				
		Note: Note: This component part have not had cyclic life limit assigned, but may be subject to failure as a result of undetected abuse and unpredictable contingencies. Therefore, to provide a record of service experience and cycles (partial cycle counting does not apply), a Life Limit Part Log Card must be maintained.										
		Low Pressure Compressor Tie Rod							RE (O/C)		LMM - Life Limit	
	72 ENG3						Mos					
	3073049-1		6,928.9				Hrs	11,703.4				
	2P14497		3,998				Enc	6,884				
		Note: Note: This component part have not had cyclic life limit assigned, but may be subject to failure as a result of undetected abuse and unpredictable contingencies. Therefore, to provide a record of service experience and cycles (partial cycle counting does not apply), a Life Limit Part Log Card must be maintained.										
		Low Pressure Turbine 1st stage Rotating Seal Plate							RE		LMM - Life Limit	**≈26-Apr-2044**
	72 ENG1						Mos	04-Jan-2023				
	3073735-1		5,384.1				Hrs	13,282.8				
	960322903867		2,940				Enc	7,730	10,000		14,790	6,904 Enc
		Low Pressure Turbine 1st stage Rotating Seal Plate							RE		LMM - Life Limit	**≈24-Jan-2043**
	72 ENG2						Mos	22-Aug-2006				
	3073735-1						Hrs	11,473.6				
	960322903802		2,460				Enc	6,903	10,000		14,443	6,450 Enc

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Low Pressure Turbine 1st stage Rotating Seal Plate							RE		LMM - Life Limit	**≈29-Nov-2043**
	72 ENG3						Mos	29-Aug-2006				
	3073735-1		4,137.5				Hrs	11,703.4				
	960322903863		2,154				Enc	6,884	10,000		14,730	6,756 Enc
		Low Pressure Turbine Rotating Air Seal							RE (A/R)			
	72 ENG1						Mos	31-Mar-2006				
	3073765-10		6,825.9				Hrs					
	97P03018		3,858				Enc					
		Low Pressure Turbine Rotating Air Seal							RE (A/R)			
	72 ENG2						Mos	05-Oct-2001				
	3073765-10						Hrs	9,339.1				
	96P20390						Enc	5,878				
		Low Pressure Turbine Rotating Air Seal							RE (A/R)			
	72 ENG3						Mos	17-Dec-2001				
	3073765-10						Hrs	9,651.9				
	97P02003						Enc	5,893				
		Low Pressure Turbine Rotating Air Seal Support							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3073764-4		6,825.9				Hrs					
	97P03722		3,858				Enc					
		Low Pressure Turbine Rotating Air Seal Support							RE (O/C)			
	72 ENG2						Mos	05-Oct-2001				
	3073764-4						Hrs	9,339.1				
	96P15413						Enc	5,878				
		Low Pressure Turbine Rotating Air Seal Support							RE (O/C)			
	72 ENG3						Mos	17-Dec-2001				
	3073764-4						Hrs	9,651.9				
	9P7P01963						Enc	5,893				
		Low Pressure Turbine Rotating Seal							RE (O/C)			
	72 ENG1						Mos	04-Jan-2023				
	3072729-1		12,085.1				Hrs	13,282.8				
	9-23151-2356		8,120				Enc	7,730				
		Low Pressure Turbine Rotating Seal							RE (O/C)			
	72 ENG2						Mos	05-Oct-2001				
	3072729-1						Hrs	9,339.1				
	9-23151-2440						Enc	5,878				
		Low Pressure Turbine Rotating Seal							RE (O/C)			
	72 ENG3						Mos					
	3072729-1		10,906				Hrs	11,703.4				
	9P6659		7,004				Enc	6,884				
		No. 1 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	19-Oct-2022				
	3060457-1	New	0				Hrs					
	22-152826-25093		0				Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 1 Carbon Seal Assembly							RE (O/C)			
	72 ENG2		0				Mos					
	3075675-2	New	0				Hrs	11,473.6				
	060515856671		0				Enc	6,903				
		No. 1 Carbon Seal Assembly							RE (O/C)			
	72 ENG3		0				Mos					
	3075719-1	New	0				Hrs	11,703.4				
	060515856190		0				Enc	6,884				
		No. 3 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	23-Aug-2022				
	3060458-1	New	0				Hrs					
	22-152826-22205		0				Enc					
		No. 3 Carbon Seal Assembly							RE (O/C)			
	72 ENG2						Mos					
	Unknown						Hrs	11,473.6				
	Unknown						Enc	6,903				
		No. 3 Carbon Seal Assembly							RE (O/C)			
	72 ENG3		0				Mos					
	3075719-1	New	0				Hrs	11,703.4				
	060515856190		0				Enc	6,884				
		NO. 3 Thrust Ball Bearing							RE (O/C)			
	72 ENG1						Mos	08-Nov-2022				
	3072866-1						Hrs					
	MS11-151725-05041						Enc					
		NO. 3 Thrust Ball Bearing							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		NO. 3 Thrust Ball Bearing							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 4 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	30-Aug-2022				
	3060437-1	New	0				Hrs					
	22-152826-22248						Enc					
		No. 4 Carbon Seal Assembly							RE (O/C)			
	72 ENG2		0				Mos					
	3074574-2	New	0				Hrs	11,473.6				
	060515853580		0				Enc	6,903				
		No. 4 Carbon Seal Assembly							RE (O/C)			
	72 ENG3		0				Mos					
	3074573-2	New	0				Hrs	11,703.4				
	060515853604		0				Enc	6,884				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 5 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	04-Oct-2022				
	3060436-1	New		0			Hrs					
	22-152826-24081						Enc					
		No. 5 Carbon Seal Assembly							RE (O/C)			
	72 ENG2			0			Mos					
	3074574-2	New		0			Hrs	11,473.6				
	060515858453			0			Enc	6,903				
		No. 5 Carbon Seal Assembly							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Carbon Seal Runner							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3075633-2						Hrs					
	062141807074						Enc					
		No. 5 Carbon Seal Runner							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		No. 5 Carbon Seal Runner							RE (O/C)			
	72 ENG3			0			Mos					
	3074574-2	New		0			Hrs	11,703.4				
	060515852998			0			Enc	6,884				
		NO. 5 Thrust Ball Bearing							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	358825-1						Hrs	0				
	MS050233009988						Enc	0				
		NO. 5 Thrust Ball Bearing							RE (O/C)			
	72 ENG2			0			Mos					
	358825-1	New		0			Hrs	11,473.6				
	MS060233003626			0			Enc	6,903				
		NO. 5 Thrust Ball Bearing							RE (O/C)			
	72 ENG3			0			Mos					
	358825-1	New		0			Hrs	11,703.4				
	MS060233003623			0			Enc	6,884				
		No. 6 Carbon Seal Assembly							RE (O/C)			
	72 ENG1						Mos	04-Nov-1980				
	3071383-2						Hrs	0				
	060365000021						Enc	0				
		No. 6 Carbon Seal Assembly							RE (O/C)			
	72 ENG2			0			Mos					
	3071383-2	New		0			Hrs	11,473.6				
	060365000045			0			Enc	6,903				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		No. 6 Carbon Seal Assembly							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Nozzle LPT							RE (O/C)			
	72 ENG1	No.3					Mos	31-Mar-2006				
	3072342-4						Hrs					
	Unknown						Enc					
		Nozzle Segments							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	Unknown						Hrs	11,473.6				
	Unknown						Enc	6,903				
		Nozzle Segments							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3075584-14						Hrs	11,703.4				
	NSN						Enc	6,884				
		Pinion Gearshaft							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3072670-2						Hrs	11,473.6				
	05P29420						Enc	6,903				
		Planetary Gearshaft							RE (O/C)			
	72 ENG1						Mos	04-Nov-2022				
	3072116-4						Hrs					
	7P-17005						Enc					
		Planetary Gearshaft							RE (O/C)			
	72 ENG2		0				Mos					
	3072116-7	New	0				Hrs	11,473.6				
	06P15699		0				Enc	6,903				
		Planetary Gearshaft							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Retainer Bearing							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3071824-5						Hrs					
	Unknown						Enc					
		RNNR Seal - 1							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3075657-1						Hrs					
	052141802382						Enc					
		RNNR Seal - 3							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3075683-1						Hrs					
	05214180063						Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		RNNR Seal - 4							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3075639-2						Hrs					
	062141807440						Enc					
		Shroud Impeller							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3074567-1						Hrs					
	06P00701						Enc					
		Shroud Impeller							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3077047-12						Hrs	11,473.6				
	2P1323						Enc	6,903				
		Shroud Impeller							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3077047-12						Hrs	11,703.4				
	9P6860						Enc	6,884				
		Shroud LPC							RE (O/C)			
	72 ENG1	No.1					Mos	31-Mar-2006				
	3071873-2						Hrs					
	Unknown						Enc					
		Shroud LPC							RE (O/C)			
	72 ENG2	No.1					Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Shroud LPC							RE (O/C)			
	72 ENG3	No.1					Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Spinner Inlet Fan							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3072867-6						Hrs	11,703.4				
	4P24888						Enc	6,884				
		Stage 1 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈11-Jan-2031**
	72 ENG1						Mos	04-Nov-1980				
	3070440-10		0				Hrs	0				
	0-12112-485		0				Enc	0	10,000		10,000	2,114 Enc
		Stage 1 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈23-Sep-2030**
	72 ENG2						Mos	22-Aug-2006				
	3072395						Hrs	11,473.6				
	0-12112-498		6,903				Enc	6,903	10,000		10,000	2,007 Enc
		Stage 1 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈13-Oct-2030**
	72 ENG3						Mos	29-Aug-2006				
	3072395-1		11,703.4				Hrs	11,703.4				
	0-12112-672		6,884				Enc	6,884	10,000		10,000	2,026 Enc

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Stage 1 Low Pressure Turbine (LPT) Blades							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3074098-						Hrs	11,473.6				
	NSN						Enc	6,903				
		Stage 1 Low Pressure Turbine (LPT) Blades							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3074098-						Hrs	11,703.4				
	NSN						Enc	6,884				
		Stage 1 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈26-Apr-2044**
	72 ENG1						Mos	04-Jan-2023				
	3074076-2		5,384.1				Hrs	13,282.8				
	960322904413		2,940				Enc	7,730	10,000		14,790	6,904 Enc
		Stage 1 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈24-Jan-2043**
	72 ENG2						Mos	22-Aug-2006				
	3074076-2						Hrs	11,473.6				
	960322901916		2,460				Enc	6,903	10,000		14,443	6,450 Enc
		Stage 1 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈29-Nov-2043**
	72 ENG3						Mos	29-Aug-2006				
	3074076-2		4,137.5				Hrs	11,703.4				
	960322904500		2,154				Enc	6,884	10,000		14,730	6,756 Enc
		Stage 1 Low Pressure Turbine Nozzle							RE (O/C)			
	72 ENG1						Mos	04-Jan-2023				
	3072842-10		9,256.6				Hrs	13,282.8				
	7-01334-587						Enc	7,730				
		Stage 1 Low Pressure Turbine Nozzle							RE (O/C)			
	72 ENG2						Mos	05-Oct-2001				
	3072842-10						Hrs	9,339.1				
	9-01334-429						Enc	5,878				
		Stage 1 Low Pressure Turbine Nozzle							RE (O/C)			
	72 ENG3						Mos	17-Dec-2001				
	3072842-10						Hrs	9,651.9				
	4-08378-4522						Enc	5,893				
		Stage 2 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈11-Jan-2031**
	72 ENG1						Mos	04-Nov-1980				
	3072416-10		0				Hrs	0				
	0-12112-1689		0				Enc	0	10,000		10,000	2,114 Enc
		Stage 2 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈23-Sep-2030**
	72 ENG2						Mos	22-Aug-2006				
	3072396-1						Hrs	11,473.6				
	0-12112-1664		6,903				Enc	6,903	10,000		10,000	2,007 Enc
		Stage 2 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈13-Oct-2030**
	72 ENG3						Mos	29-Aug-2006				
	3072396-1		11,703.4				Hrs	11,703.4				
	0-12112-1567		6,884				Enc	6,884	10,000		10,000	2,026 Enc

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Stage 2 Low Pressure Turbine (LPT) Blades							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3074099-						Hrs	11,473.6				
	NSN						Enc	6,903				
		Stage 2 Low Pressure Turbine (LPT) Blades							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3074099-						Hrs	11,703.4				
	NSN						Enc	6,884				
		Stage 2 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈26-Apr-2044**
	72 ENG1						Mos	04-Jan-2023				
	3074077-1		5,384.1				Hrs	13,282.8				
	960322904479		2,940				Enc	7,730	10,000		14,790	6,904 Enc
		Stage 2 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈24-Jan-2043**
	72 ENG2						Mos	22-Aug-2006				
	3074077-1						Hrs	11,473.6				
	960322901915		2,460				Enc	6,903	10,000		14,443	6,450 Enc
		Stage 2 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈29-Nov-2043**
	72 ENG3						Mos	29-Aug-2006				
	3074077-1		4,137.5				Hrs	11,703.4				
	960322901943		2,154				Enc	6,884	10,000		14,730	6,756 Enc
		Stage 3 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈11-Jan-2031**
	72 ENG1						Mos	04-Nov-1980				
	3072417-2		0				Hrs	0				
	0-12112-1676		0				Enc	0	10,000		10,000	2,114 Enc
		Stage 3 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈23-Sep-2030**
	72 ENG2						Mos	22-Aug-2006				
	3072397-1						Hrs	11,473.6				
	0-12112-1659		6,903				Enc	6,903	10,000		10,000	2,007 Enc
		Stage 3 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈13-Oct-2030**
	72 ENG3						Mos	29-Aug-2006				
	3072397-1		11,703.4				Hrs	11,703.4				
	0-12112-1719		6,884				Enc	6,884	10,000		10,000	2,026 Enc
		Stage 3 Low Pressure Turbine (LPT) Blades							RE (O/C)			
	72 ENG2						Mos	22-Aug-2006				
	3072845-						Hrs	11,473.6				
	NSN						Enc	6,903				
		Stage 3 Low Pressure Turbine (LPT) Blades							RE (O/C)			
	72 ENG3						Mos	29-Aug-2006				
	3072845-						Hrs	11,703.4				
	NSN						Enc	6,884				
		Stage 3 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈01-Aug-2032**
	72 ENG1						Mos	04-Jan-2023				
	3074096-2		7,464.9				Hrs	13,282.8				
	4-12172-0534		4,168				Enc	7,730	7,000		10,562	2,676 Enc

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Stage 3 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈18-Aug-2032**
	72 ENG2						Mos	22-Aug-2006				
	3074096-2						Hrs	11,473.6				
	3-12172-1476		3,218				Enc	6,903	7,000		10,685	2,692 Enc
		Stage 3 Low Pressure Turbine Disc							RE		LMM - Life Limit	**≈16-Mar-2033**
	72 ENG3						Mos	29-Aug-2006				
	3074096-2		5,598.9				Hrs	11,703.4				
	3-12172-1430		3,010				Enc	6,884	7,000		10,874	2,900 Enc
		Stage 4 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈30-Jan-2072**
	72 ENG1						Mos	04-Jan-2023				
	3075326-2		5,384.1				Hrs	13,282.8				
	970350103552		2,940				Enc	7,730	20,000		24,790	16,904 Enc
		Stage 4 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈26-Oct-2070**
	72 ENG2						Mos	09-Sep-2006				
	3075326-3		4,166.5				Hrs	11,473.6				
	960350104228		2,460				Enc	6,903	20,000		24,443	16,450 Enc
		Stage 4 Low Pressure Compressor Disc							RE		LMM - Life Limit	**≈02-Sep-2071**
	72 ENG3						Mos	29-Aug-2006				
	3075326-3		4,137.5				Hrs	11,703.4				
	960350104177		2,154				Enc	6,884	20,000		24,730	16,756 Enc
		Support Assembly							RE (O/C)			
	72 ENG1						Mos	31-Mar-2006				
	3072165-1						Hrs					
	Unknown						Enc					
		Support Assembly							RE (O/C)			
	72 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Support Assembly							RE (O/C)			
	72 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Transfer Gearbox							RE (O/C)			
	72 ENG1						Mos	04-Jan-2023				
	3070093-12		1,738				Hrs	13,282.8				
	P-2898						Enc	7,730				
		Transfer Gearbox							RE (O/C)			
	72 ENG2						Mos	05-Oct-2001				
	3070093-12						Hrs	9,339.1				
	P-2896						Enc	5,878				
		Transfer Gearbox							RE (O/C)			
	72 ENG3						Mos	17-Dec-2001				
	3070093-12						Hrs	9,651.9				
	P-2913						Enc	5,893				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Turbine Interstage Transition Duct							RE (O/C)			
	72 ENG1						Mos	04-Jan-2023				
	3072318-4		8,396.2				Hrs	13,282.8				
	3P-12238		4,831				Enc	7,730				
		Turbine Interstage Transition Duct							RE (O/C)			
	72 ENG2						Mos	05-Oct-2001				
	3072318-4						Hrs	9,339.1				
	0P-14740						Enc	5,878				
		Turbine Interstage Transition Duct							RE (O/C)			
	72 ENG3						Mos	17-Dec-2001				
	3072318-4						Hrs	9,651.9				
	6P-28419						Enc	5,893				
2000-04-19		**Operative Engines**							RE (-)		Mandatory	
	72 A/F						Mos	12-Oct-2010				
	Eff: 04-Apr-2000 Complied With						Hrs	11,295				
	(ISSUING AUTHORITY: FAA)						Ldg	7,881				
							Flt					
2000-15-09		**HPC Impeller**							RE		Mandatory	**≈19-Feb-2036**
	72 ENG1						Mos	04-Jan-2023				
	Eff: 10-Oct-2000 Complied With	BY HONEYWELL IAW S/B A72-3641					Hrs	13,282.8	4,200		17,482.8	3,955.7 Hrs
	(ISSUING AUTHORITY: FAA)						Enc	7,730				
2000-15-09		**HPC Impeller**							RE		Mandatory	**≈24-Nov-2031**
	72 ENG2						Mos	22-Aug-2006				
	Eff: 10-Oct-2000 Complied With						Hrs	11,473.6	4,200		15,673.6	2,427.6 Hrs
	(ISSUING AUTHORITY: FAA)						Enc	6,903				
2000-15-09		**HPC Impeller**							RE		Mandatory	**≈24-Nov-2031**
	72 ENG3						Mos	29-Aug-2006				
	Eff: 10-Oct-2000 Complied With						Hrs	11,703.4	4,200		15,903.4	2,427.6 Hrs
	(ISSUING AUTHORITY: FAA)						Enc	6,884				
2001-23-09		**Fan Rotor Discs**							RE (-)		Mandatory	
	72 ENG1						Mos	07-Jan-2002				
	Eff: 21-Dec-2001 Complied With						Hrs	9,831				
	(ISSUING AUTHORITY: FAA)						Enc	5,855				
2001-23-09		**Fan Rotor Discs**							T (A/R)		Mandatory	
	72 ENG2						Mos					
	Eff: 21-Dec-2001						Hrs					
	(ISSUING AUTHORITY: FAA)						Enc					
2001-23-09		**Fan Rotor Discs**							RE (-)		Mandatory	
	72 ENG3						Mos	14-Jan-2002				
	Eff: 21-Dec-2001 Not Applicable	BY P/N OF FAN DISC					Hrs					
	(ISSUING AUTHORITY: FAA)						Enc					
2005-05-15		**LPT Stage 1 Disks**							RE (-)		Mandatory	
	72 ENG1						Mos	18-Oct-2007				
	Eff: 18-Apr-2005 Not Applicable	Per part number of the Engine					Hrs	12,006.8				
	(AVG MAN HRS: 2) (ISSUING AUTHORITY: FAA)						Enc	6,943				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2005-05-15	**LPT Stage 1 Disks**							RE (-)		Mandatory	
72 ENG2						Mos	18-Oct-2007				
Eff: 18-Apr-2005 Not Applicable	PER PART NUMBER OF THE ENGINES					Hrs					
						Enc					
(AVG MAN HRS: 2) (ISSUING AUTHORITY: FAA)											
2005-05-15	**LPT Stage 1 Disks**							RE (-)		Mandatory	
72 ENG3						Mos	18-Oct-2007				
Eff: 18-Apr-2005 Not Applicable	PER PART NUMBER OF THE ENGINES					Hrs					
						Enc					
(AVG MAN HRS: 2) (ISSUING AUTHORITY: FAA)											
2005-05-15 Paragraph (h),(i)	**(LPT) stage 1 Disks - Disk Replacement for TFE731-3, -3A, -3AR, -3R, -3B and -3BR Series Engines**							T (A/R)		Mandatory	
72 ENG1						Mos					
Eff: 18-Apr-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
2005-05-15 Paragraph (h),(i)	**(LPT) stage 1 Disks - Disk Replacement for TFE731-3, -3A, -3AR, -3R, -3B and -3BR Series Engines**							T (A/R)		Mandatory	
72 ENG2						Mos					
Eff: 18-Apr-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
2005-05-15 Paragraph (h),(i)	**(LPT) stage 1 Disks - Disk Replacement for TFE731-3, -3A, -3AR, -3R, -3B and -3BR Series Engines**							T (A/R)		Mandatory	
72 ENG3						Mos					
Eff: 18-Apr-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
2005-05-15 Paragraph (j)	**(LPT) Stage 1 Disks - Optional Terminating Actions**							T (A/R)		Mandatory	
72 ENG1						Mos					
Eff: 18-Apr-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
2005-05-15 Paragraph (j)	**(LPT) Stage 1 Disks - Optional Terminating Actions**							T (A/R)		Mandatory	
72 ENG2						Mos					
Eff: 18-Apr-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
2005-05-15 Paragraph (j)	**(LPT) Stage 1 Disks - Optional Terminating Actions**							T (A/R)		Mandatory	
72 ENG3						Mos					
Eff: 18-Apr-2005						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
2005-13-07	**Turbine Rotor Discs.**							RE (-)		Mandatory	
72 ENG1						Mos	18-Oct-2007				
Eff: 27-Jul-2005 Not Applicable	Per part number of the Engine					Hrs	12,006.8				
						Enc	6,943				
(AVG MAN HRS: 4) (ISSUING AUTHORITY: FAA)											
2005-13-07	**Turbine Rotor Discs.**							RE (-)		Mandatory	
72 ENG2						Mos	18-Oct-2007				
Eff: 27-Jul-2005 Not Applicable	PER PART NUMBER OF THE ENGINES					Hrs					
						Enc					
(AVG MAN HRS: 4) (ISSUING AUTHORITY: FAA)											
2005-13-07	**Turbine Rotor Discs.**							RE (-)		Mandatory	
72 ENG3						Mos	18-Oct-2007				
Eff: 27-Jul-2005 Not Applicable	PER PART NUMBER OF THE ENGINES					Hrs					
						Enc					
(AVG MAN HRS: 4) (ISSUING AUTHORITY: FAA)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
2010-06-11	**Second stage low-pressure compressor rotor (LPCR) discs**							RE (-)		Mandatory	
72 ENG1						Mos	30-Mar-2010				
Eff: 21-Apr-2010 Not Applicable	By Part number					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
2010-06-11	**Second stage low-pressure compressor rotor (LPCR) discs**							RE (-)		Mandatory	
72 ENG2						Mos	12-Oct-2010				
Eff: 21-Apr-2010 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
2010-06-11	**Second stage low-pressure compressor rotor (LPCR) discs**							RE (-)		Mandatory	
72 ENG3						Mos	12-Oct-2010				
Eff: 21-Apr-2010 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
3727214-SB-001	**Diskball Blade Mapping Software PN 3727214**							T (A/R)			
72 ENG1						Mos					
Eff: 28-Jan-2016						Hrs					
						Enc					
3727214-SB-001	**Diskball Blade Mapping Software PN 3727214**							T (A/R)			
72 ENG2						Mos					
Eff: 28-Jan-2016						Hrs					
						Enc					
3727214-SB-001	**Diskball Blade Mapping Software PN 3727214**							T (A/R)			
72 ENG3						Mos					
Eff: 28-Jan-2016						Hrs					
						Enc					
72-00-00-002	**Perform Engine Preservation Check**							RE (A/R)		LMM - Requirement	
72 ENG1						Mos	04-Jan-2023				
						Hrs					
						Enc					
72-00-00-002	**Perform Engine Preservation Check**							RE (A/R)		LMM - Requirement	
72 ENG2						Mos					
						Hrs					
						Enc					
72-00-00-002	**Perform Engine Preservation Check**							RE (A/R)		LMM - Requirement	
72 ENG3						Mos					
						Hrs					
						Enc					
72-00-LMM-005	**Compressor Zone Inspection (CZI)**							RE		LMM - Requirement	**≈24-Apr-2031**
72 ENG1						Mos	31-Mar-2006				
						Hrs	11,544.8	4,200	+200	15,744.8	2,217.7 Hrs (+200)
						Enc	6,704				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3105 R14											
72-00-LMM-005	**Compressor Zone Inspection (CZI)**							RE		LMM - Requirement	**≈24-Nov-2031**
72 ENG2						Mos	22-Aug-2006				
						Hrs	11,473.6	4,200	+200	15,673.6	2,427.6 Hrs (+200)
						Enc	6,903				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3105 R14											
72-00-LMM-005	**Compressor Zone Inspection (CZI)**							RE		LMM - Requirement	**≈24-Nov-2031**
72 ENG3						Mos					
						Hrs	11,703.4	4,200	+200	15,903.4	2,427.6 Hrs (+200)
						Enc	6,884				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3105 R14											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-00-LMM-006	**Major Periodic Inspection (MPI)**							RE		LMM - Requirement	**≈22-Apr-2030**
72 ENG1						Mos	04-Jan-2023				
						Hrs	13,282.8	2,100	+100	15,382.8	1,855.7 Hrs (+100)
Ref:SBTFE731-72-3105						Enc	7,730				
Note: recommended at intervals of engine operation specified in the SB TFE731-72-3527											
72-00-LMM-006	**Major Periodic Inspection (MPI)**							RE		LMM - Requirement	**≈26-Jan-2026**
72 ENG2						Mos	22-Aug-2006				
						Hrs	11,473.6	2,100	+100	13,573.6	327.6 Hrs (+100)
Ref:SBTFE731-72-3105						Enc	6,903				
Note: recommended at intervals of engine operation specified in the SB TFE731-72-3527											
72-00-LMM-006	**Major Periodic Inspection (MPI)**							RE		LMM - Requirement	**≈26-Jan-2026**
72 ENG3						Mos					
						Hrs	11,703.4	2,100	+100	13,803.4	327.6 Hrs (+100)
Ref:SBTFE731-72-3105						Enc	6,884				
Note: recommended at intervals of engine operation specified in the SB TFE731-72-3527											
72-00-LMM-007	**Accident or Incident Inspection**							RE (A/R)		LMM - Requirement	
72 ENG1						Mos					
						Hrs					
						Enc					
72-00-LMM-007	**Accident or Incident Inspection**							RE (A/R)		LMM - Requirement	
72 ENG2						Mos					
						Hrs					
						Enc					
72-00-LMM-007	**Accident or Incident Inspection**							RE (A/R)		LMM - Requirement	
72 ENG3						Mos					
						Hrs					
						Enc					
72-00-LMM-008	**Lightning Strike Inspection**							RE (A/R)		LMM - Requirement, Unscheduled Inspections	
72 ENG1						Mos					
						Hrs					
Ref:70-00-00, Standard Practices						Enc					
72-00-LMM-008	**Lightning Strike Inspection**							RE (A/R)		LMM - Requirement, Unscheduled Inspections	
72 ENG2						Mos					
						Hrs					
Ref:70-00-00, Standard Practices						Enc					
72-00-LMM-008	**Lightning Strike Inspection**							RE (A/R)		LMM - Requirement, Unscheduled Inspections	
72 ENG3						Mos					
						Hrs					
Ref:70-00-00, Standard Practices						Enc					
72-00-LMM-009	**Overtemperature Inspection Requirements**							RE (A/R)		LMM - Requirement, Unscheduled Inspections	
72 ENG1						Mos					
						Hrs					
						Enc					
72-00-LMM-009	**Overtemperature Inspection Requirements**							RE (A/R)		LMM - Requirement, Unscheduled Inspections	
72 ENG2						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
72-00-LMM-009	**Overtemperature Inspection Requirements**						RE (A/R)		LMM - Requirement, Unscheduled Inspections	
72 ENG3						Mos				
						Hrs				
						Enc				
72-00-LMM-011	**Pre Installation - Inspection**						RE (A/R)			
72 ENG1						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-011	**Pre Installation - Inspection**						RE (A/R)			
72 ENG2						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-011	**Pre Installation - Inspection**						RE (A/R)			
72 ENG3						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-012	**Pre Flight - Inspection**						RE (A/R)			
72 ENG1						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-012	**Pre Flight - Inspection**						RE (A/R)			
72 ENG2						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-012	**Pre Flight - Inspection**						RE (A/R)			
72 ENG3						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-013	**Post Flight - Inspection**						RE (A/R)			
72 ENG1						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-013	**Post Flight - Inspection**						RE (A/R)			
72 ENG2						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-013	**Post Flight - Inspection**						RE (A/R)			
72 ENG3						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-014	**Daily - Inspection**						RE (A/R)			
72 ENG1						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				
72-00-LMM-014	**Daily - Inspection**						RE (A/R)			
72 ENG2						Mos				
						Hrs				
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-00-LMM-014	**Daily - Inspection**							RE (A/R)			
72 ENG3						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-015	**Accident or Incident - Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG1						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-015	**Accident or Incident - Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG2						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-015	**Accident or Incident - Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG3						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-018	**Foreign Object Damage (FOD) and/or Bird Strike - Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG1						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-018	**Foreign Object Damage (FOD) and/or Bird Strike - Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG2						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-018	**Foreign Object Damage (FOD) and/or Bird Strike - Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG3						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-019	**Overspeed Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG1						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-019	**Overspeed Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG2						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-00-LMM-019	**Overspeed Inspection**							RE (A/R)		Unscheduled Inspections	
72 ENG3						Mos					
						Hrs					
	(SOURCE: Light Maintenance Manual TFE731-3)					Enc					
72-10-LMM-002	**Fan Rotor Assembly Blades – Inspect for foreign object damage**							RE		LMM - Requirement	**≈23-Apr-2025**
72 ENG1	PKG 300/400 Hour					Mos	04-Jan-2023				
						Hrs	13,282.8	300	+100	(13,582.8)	55.7 Hrs (+100)
						Enc	7,730				
72-10-LMM-002	**Fan Rotor Assembly Blades – Inspect for foreign object damage**							RE		LMM - Requirement	**≈17-Feb-2025**
72 ENG2	PKG 300/400 Hour					Mos	20-Oct-2021				
						Hrs	12,938.2	300	+100	(13,238.2)	0 Hrs (+92.2)
						Enc	7,801				
72-10-LMM-002	**Fan Rotor Assembly Blades – Inspect for foreign object damage**							RE		LMM - Requirement	**≈17-Feb-2025**
72 ENG3	PKG 300/400 Hour					Mos	20-Oct-2021				
						Hrs	13,168	300	+100	(13,468)	0 Hrs (+92.2)
						Enc	7,782				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-3007	**Replacement of Collars and Retainer of Fan Shaft Assembly**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
72-3072 R1	**Replace Outer Transition Liner With Liner Incorp. Improved Flange Config (Inactive For Further Accomplishment)**							RE (-)			
72 ENG1						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
72-3072 R1	**Replace Outer Transition Liner With Liner Incorp. Improved Flange Config (Inactive For Further Accomplishment)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Eff: 18-Mar-1994 Complied With						Hrs					
						Enc					
72-3072 R1	**Replace Outer Transition Liner With Liner Incorp. Improved Flange Config (Inactive For Further Accomplishment)**							RE (-)			
72 ENG3						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
72-3072 R2	**Replace Outer Transition Liner With Liner Incorp. Improved Flange Config (Inactive For Further Accomplishment)**							RE (-)			
72 ENG1						Mos					
Eff: 18-Mar-1994 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
72-3144	**Engine - High Pressure Rotor And Nozzle Assembly (Inactive For Further Accomplishment)**							RE (-)			
72 ENG1						Mos					
Eff: 13-May-1994 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
72-3144	**Engine - High Pressure Rotor And Nozzle Assembly (Inactive For Further Accomplishment)**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 13-May-1994 Complied With						Hrs					
						Enc					
72-3144	**Engine - High Pressure Rotor And Nozzle Assembly (Inactive For Further Accomplishment)**							RE (-)			
72 ENG3						Mos					
Eff: 13-May-1994						Hrs					
						Enc					
72-3181	**72-3181 Inactive For Further Accomplishment**							RE (A/R)			
72 ENG1						Mos	24-Jan-1985				
						Hrs					
						Enc					
72-3234RWK	**Rework Transition Liner P/N 3072337-1 To P/N 3072337-2**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Complied With						Hrs					
						Enc					
72-3259	**72-3259 Inactive For Further Accomplishment**							RE (A/R)			
72 ENG1						Mos	24-Jan-1985				
						Hrs					
						Enc					
72-3272	**Inspection Of LP Turbine Rotor Assembly Discs & Rework Of 1ST Stage LP Turbine Nozzle Assy Inactive (Inactive For Further Accomplishment)**							RE (-)			
72 ENG1						Mos	24-Jan-1985				
Eff: 12-Dec-2001 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-3287	**72-3287 Rework/Replace Accessory Drive Gearbox Housing**							RE (-)			
72 ENG1						Mos	27-Dec-1997				
Complied With	THE SERVICE BULLETIN HAS BEEN INCORPORATED					Hrs					
						Enc					
72-3361	**72-3361 Inactive For Further Accomplishment**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Not Applicable	DUE TO FAN DISC P/N					Hrs					
						Enc					
72-3452	**72-3452 Inactive For Further Accomplishment**							RE (A/R)			
72 ENG1						Mos	15-Apr-1992				
						Hrs					
						Enc					
72-3511	**Rework Lpt Stub Shaft**							RE (A/R)			
72 ENG2						Mos	14-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
72-3512	**Rework Lpt Tie Shaft**							RE (A/R)			
72 ENG2						Mos	14-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
72-40-LMM-001	**Combustion Chamber Plenum Case Inspection**							RE		LMM - Requirement	**≈22-Apr-2030**
72 ENG1						Mos	04-Jan-2023				
						Hrs	13,282.8	2,100	+400	15,382.8	1,855.7 Hrs (+400)
						Enc	7,730				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3466 Rev 3											
72-40-LMM-001	**Combustion Chamber Plenum Case Inspection**							RE		LMM - Requirement	**≈26-Jan-2026**
72 ENG2						Mos	22-Aug-2006				
						Hrs	11,473.6	2,100	+400	13,573.6	327.6 Hrs (+400)
						Enc	6,903				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3466 Rev 3											
72-40-LMM-001	**Combustion Chamber Plenum Case Inspection**							RE		LMM - Requirement	**≈26-Jan-2026**
72 ENG3						Mos					
						Hrs	11,703.4	2,100	+400	13,803.4	327.6 Hrs (+400)
						Enc	6,884				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3466 Rev 3											
72-60-LMM-001	**Accessory Drive Splines – Check Starter/Generator and Alternator Drive Splines for Wear**							RE (N/A)		LMM - Requirement	
72 ENG1						Mos					
						Hrs					
Ref:72-60-01						Enc					
72-60-LMM-001	**Accessory Drive Splines – Check Starter/Generator and Alternator Drive Splines for Wear**							RE (N/A)		LMM - Requirement	
72 ENG2						Mos	22-Aug-2006				
						Hrs	11,473.6				
Ref:72-60-01						Enc	6,903				
72-60-LMM-001	**Accessory Drive Splines – Check Starter/Generator and Alternator Drive Splines for Wear**							RE (N/A)		LMM - Requirement	
72 ENG3						Mos	29-Aug-2006				
						Hrs	11,703.4				
Ref:72-60-01						Enc	6,884				
72-60-LMM-002	**Accessory Gearbox Inspection**							RE		LMM - Requirement	**≈24-Apr-2031**
72 ENG1						Mos	31-Mar-2006				
						Hrs	11,544.8	4,200	+200	15,744.8	2,217.7 Hrs (+200)
						Enc	6,704				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3630 R1											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
72-60-LMM-002	**Accessory Gearbox Inspection**							RE		LMM - Requirement	**≈24-Nov-2031**
72 ENG2						Mos	22-Aug-2006				
						Hrs	11,473.6	4,200	+200	15,673.6	2,427.6 Hrs (+200)
						Enc	6,903				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3630 R1											
72-60-LMM-002	**Accessory Gearbox Inspection**							RE		LMM - Requirement	**≈24-Nov-2031**
72 ENG3						Mos					
						Hrs	11,703.4	4,200	+200	15,903.4	2,427.6 Hrs (+200)
						Enc	6,884				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3630 R1											
72-70-LMM-001	**Fan Support Assembly Periodic Inspection**							RE		LMM - Requirement	**≈24-Apr-2031**
72 ENG1						Mos	31-Mar-2006				
						Hrs	11,544.8	4,200	+200	15,744.8	2,217.7 Hrs (+200)
						Enc	6,704				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3639 R1											
72-70-LMM-001	**Fan Support Assembly Periodic Inspection**							RE		LMM - Requirement	**≈24-Nov-2031**
72 ENG2						Mos	22-Aug-2006				
						Hrs	11,473.6	4,200	+200	15,673.6	2,427.6 Hrs (+200)
						Enc	6,903				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3639 R1											
72-70-LMM-001	**Fan Support Assembly Periodic Inspection**							RE		LMM - Requirement	**≈24-Nov-2031**
72 ENG3						Mos					
						Hrs	11,703.4	4,200	+200	15,903.4	2,427.6 Hrs (+200)
						Enc	6,884				
Note: Ref.: SB TFE731-72-3233 R3, TFE731-72-3527 R4, TFE731-72-3639 R1											
73-3053	**73-3053 Inactive For Further Accomplishment**							RE (A/R)			
72 ENG1						Mos	03-Nov-1988				
Complied With						Hrs					
						Enc					
74-13-08	**Engine (Superseded by AD 74-23-05)**							RE (-)		Mandatory	
72 ENG1						Mos	13-Sep-2001				
Not Applicable	by model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
75-05-12	**Engine (Superseded by AD 82-23-03 R1)**							RE (-)		Mandatory	
72 ENG1						Mos	07-Jan-2002				
Superseded	by 82-23-03 R1					Hrs	9,830.8				
(ISSUING AUTHORITY: FAA)						Enc	5,855				
75-05-12	**Engine (Superseded by AD 82-23-03 R1)**							RE (-)		Mandatory	
72 ENG2						Mos	13-Sep-2001				
Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
75-05-12	**Engine (Superseded by AD 82-23-03 R1)**							RE (-)		Mandatory	
72 ENG3						Mos	29-Oct-2001				
Not Applicable	by P/N					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
75-07-10	**Transfer Gearbox Vertical Bevel Gear Bearing**							RE (-)		Mandatory	
72 ENG1						Mos	25-Jan-1995				
Eff: 01-May-1975 Not Applicable	Per SN					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
Note: Engine models affected TFE731-2-1C/-2B and TFE731-3-1E/-1G											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
75-07-10	**Transfer Gearbox Vertical Bevel Gear Bearing**							RE (-)		Mandatory	
72 ENG2						Mos	12-Jan-2000				
Eff: 01-May-1975 Not Applicable	per S/N					Hrs					
						Enc					
(ISSUING AUTHORITY: FAA)											
Note: Engine models affected TFE731-2-1C/-2B and TFE731-3-1E/-1G											
75-07-10	**Transfer Gearbox Vertical Bevel Gear Bearing**							RE (-)		Mandatory	
72 ENG3						Mos	14-Jan-2000				
Eff: 01-May-1975 Not Applicable	PER P/N					Hrs					
						Enc					
(ISSUING AUTHORITY: FAA)											
Note: Engine models affected TFE731-2-1C/-2B and TFE731-3-1E/-1G											
78-22-10	**Low Pressure Rotor Thrust Ball Bearings**							RE (-)		Mandatory	
72 ENG1						Mos	25-Jan-1995				
Eff: 13-Nov-1978 Not Applicable	Per SN					Hrs					
						Enc					
(ISSUING AUTHORITY: FAA)											
78-22-10	**Low Pressure Rotor Thrust Ball Bearings**							RE (-)		Mandatory	
72 ENG2						Mos	12-Jan-2000				
Eff: 13-Nov-1978 Not Applicable	per SN					Hrs					
						Enc					
(ISSUING AUTHORITY: FAA)											
78-22-10	**Low Pressure Rotor Thrust Ball Bearings**							RE (-)		Mandatory	
72 ENG3						Mos	14-Jan-2000				
Eff: 13-Nov-1978 Not Applicable	PER S/N					Hrs					
						Enc					
(ISSUING AUTHORITY: FAA)											
79-20-LMM-001	**Inspect Oil Chip Detector for contamination**							RE		LMM - Requirement	**≈20-May-2025**
72 ENG1	PKG 150/250 Hour					Mos	06-Dec-2024				
						Hrs	13,459.5	150	+100	(13,609.5)	82.4 Hrs (+100)
Ref:79-20-03						Enc	7,844				
79-20-LMM-001	**Inspect Oil Chip Detector for contamination**							RE		LMM - Requirement	**≈20-May-2025**
72 ENG2	PKG 150/250 Hour					Mos	06-Dec-2024				
						Hrs	13,178.4	150	+100	(13,328.4)	82.4 Hrs (+100)
Ref:79-20-03						Enc	7,951				
79-20-LMM-001	**Inspect Oil Chip Detector for contamination**							RE		LMM - Requirement	**≈20-May-2025**
72 ENG3	PKG 150/250 Hour					Mos	06-Dec-2024				
						Hrs	13,408.2	150	+100	(13,558.2)	82.4 Hrs (+100)
Ref:79-20-03						Enc	7,932				
79-3035	**79-3035 Inactive For Further Accomplishment**							RE (A/R)			
72 ENG1						Mos	24-Jan-1985				
						Hrs					
						Enc					
80-16-04	**Tie Rod**							RE (-)		Mandatory	
72 ENG1						Mos	25-Jan-1995				
Eff: 07-Aug-1980 Not Applicable	Per SN					Hrs					
						Enc					
(ISSUING AUTHORITY: FAA)											
80-16-04	**Tie Rod**							RE (-)		Mandatory	
72 ENG2						Mos	12-Jan-2000				
Eff: 07-Aug-1980 Not Applicable	per PN					Hrs					
						Enc					
(ISSUING AUTHORITY: FAA)											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
80-16-04	**Tie Rod**							RE (-)		Mandatory	
72 ENG3						Mos	28-Dec-1992				
Eff: 07-Aug-1980 Not Applicable	BY ENGINE SERIAL NUMBER					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
81-24-08	**Turbine Interstage Transition Ducts**							RE (-)		Mandatory	
72 ENG1						Mos	25-Jan-1995				
Eff: 06-Jan-1982 Not Applicable	Per SN					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
81-24-08	**Turbine Interstage Transition Ducts**							RE (-)		Mandatory	
72 ENG2						Mos					
Eff: 06-Jan-1982 Complied With	PCW					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
81-24-08	**Turbine Interstage Transition Ducts**							RE (-)		Mandatory	
72 ENG3						Mos	28-Dec-1992				
Eff: 06-Jan-1982 Not Applicable	S/B 72-3159 REV. 7 IS N/A					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
82-23-03	**High Pressure Compressor Impellers**							RE (-)		Mandatory	
72 ENG1						Mos	13-Nov-1984				
Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
82-23-03 R1	**High Pressure Compressor Impellers**							RE (-)		Mandatory	
72 ENG1						Mos	10-Mar-2010				
Eff: 09-Dec-1983 Not Applicable	DUE TO P/N HPC IMPELLER INSTALLED					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
831702-SB No. 3	**Engine Condition Trend Monitoring Kit-TFE731-P/N 831702-All; Possible Cable Short With P/N 832787-1/-2/-4**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 22-Jul-2010						Hrs					
						Enc					
831702-SB No. 3	**Engine Condition Trend Monitoring Kit-TFE731-P/N 831702-All; Possible Cable Short With P/N 832787-1/-2/-4**							T (A/R)		Recommended	
72 ENG2						Mos					
Eff: 22-Jul-2010						Hrs					
						Enc					
831702-SB No. 3	**Engine Condition Trend Monitoring Kit-TFE731-P/N 831702-All; Possible Cable Short With P/N 832787-1/-2/-4**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 22-Jul-2010						Hrs					
						Enc					
831708-SB-001	**Napoli A5 Nozzle Adjustment Software P/N 831708**							T (A/R)			
72 ENG1						Mos					
Eff: 30-Jun-2015						Hrs					
						Enc					
831708-SB-001	**Napoli A5 Nozzle Adjustment Software P/N 831708**							T (A/R)			
72 ENG2						Mos					
Eff: 30-Jun-2015						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
831708-SB-001	**Napoli A5 Nozzle Adjustment Software P/N 831708**							T (A/R)			
72 ENG3						Mos					
Eff: 30-Jun-2015						Hrs					
						Enc					
86-03-01	**Turbine Interstage Transition Ducts**							RE (-)		Mandatory	
72 ENG1						Mos	05-Jan-1987				
Eff: 24-Feb-1986 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
86-03-01	**Turbine Interstage Transition Ducts**							RE (-)		Mandatory	
72 ENG2						Mos	17-Dec-1982				
Eff: 24-Feb-1986 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
86-03-01	**Turbine Interstage Transition Ducts**							T (A/R)		Mandatory	
72 ENG3						Mos					
Eff: 24-Feb-1986						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
86-04-02	**Fan Rotor Discs (Superseded By FAA 1986-11-05)**							RE (-)			
72 ENG1						Mos	07-Jan-2002				
Not Applicable	BY P/N					Hrs					
						Enc					
86-04-02	**Fan Rotor Discs (Superseded By FAA 1986-11-05)**							RE (-)			
72 ENG2						Mos	13-Sep-2001				
Not Applicable	by PN					Hrs					
						Enc					
86-04-02	**Fan Rotor Discs (Superseded By FAA 1986-11-05)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
86-11-05	**Remove Fan Rotor Discs P/N'S 3072162-All, 3072816-All, 3073436-All, 3073539-All, and 3074529-All (Where All Denotes All Dash Numbers), and Replace With Serviceable Fan Rotor Discs At Next Access to the Fan Rotor Disc (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG1						Mos	15-Apr-1992				
Complied With	S/B A72-3328					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
86-11-05	**Remove Fan Rotor Discs P/N'S 3072162-All, 3072816-All, 3073436-All, 3073539-All, and 3074529-All (Where All Denotes All Dash Numbers), and Replace With Serviceable Fan Rotor Discs At Next Access to the Fan Rotor Disc (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG2						Mos	19-Dec-1990				
Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
86-11-05	**Remove Fan Rotor Discs P/N'S 3072162-All, 3072816-All, 3073436-All, 3073539-All, and 3074529-All (Where All Denotes All Dash Numbers), and Replace With Serviceable Fan Rotor Discs At Next Access to the Fan Rotor Disc (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG3						Mos	29-Oct-2001				
Not Applicable	BY P/N					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
86-11-05 R2	**Remove Fan Rotor Discs P/N'S 3072162-All, 3072816-All, 3073436-All, 3073539-All, and 3074529-All (Where All Denotes All Dash Numbers), and Replace With Serviceable Fan Rotor Discs At Next Access to the Fan Rotor Disc (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG1						Mos					
						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
86-11-05 R2	**Remove Fan Rotor Discs P/N'S 3072162-All, 3072816-All, 3073436-All, 3073539-All, and 3074529-All (Where All Denotes All Dash Numbers), and Replace With Serviceable Fan Rotor Discs At Next Access to the Fan Rotor Disc (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG2						Mos					
						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
86-11-05 R2	**Remove Fan Rotor Discs P/N'S 3072162-All, 3072816-All, 3073436-All, 3073539-All, and 3074529-All (Where All Denotes All Dash Numbers), and Replace With Serviceable Fan Rotor Discs At Next Access to the Fan Rotor Disc (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG3						Mos					
						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
88-18-03	**High Pressure Turbine Rotor Disc**							T (A/R)		Mandatory	
72 ENG1						Mos	03-Nov-1988				
Eff: 21-Jul-1989						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
88-18-03	**High Pressure Turbine Rotor Disc**							RE (-)		Mandatory	
72 ENG2						Mos	19-Dec-1990				
Eff: 21-Jul-1989 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
88-18-03	**High Pressure Turbine Rotor Disc**							RE (-)		Mandatory	
72 ENG3						Mos	28-Dec-1992				
Eff: 21-Jul-1989 Not Applicable	AS PER HP DISC SERIAL NO					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
90-03-04	**High Pressure Turbine Rotor Discs**							RE (-)		Mandatory	
72 ENG1						Mos	25-Jan-1995				
Eff: 22-Feb-1990 Not Applicable	PER S/N					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
90-03-04	**High Pressure Turbine Rotor Discs**							RE (-)		Mandatory	
72 ENG2						Mos	19-Dec-1990				
Eff: 22-Feb-1990 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
90-03-04	**High Pressure Turbine Rotor Discs**							RE (-)		Mandatory	
72 ENG3						Mos	28-Dec-1992				
Eff: 22-Feb-1990 Not Applicable	S/B A72-3388 IS N/A					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
91-08-13	**Initial and Repetitive Eddy Current Inspections Using an Improved, More Definitive Procedure For Detecting Fan Rotor Disk Dovetail Slot Cracks. (Superseded by AD 96-05-03)**							RE (-)		Mandatory	
72 ENG1						Mos	19-Jun-1991				
Complied With	S/B A72-3432 Rev. 2					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
91-08-13	**Initial and Repetitive Eddy Current Inspections Using an Improved, More Definitive Procedure For Detecting Fan Rotor Disk Dovetail Slot Cracks. (Superseded by AD 96-05-03)**							RE (-)		Mandatory	
72 ENG2						Mos	13-Sep-2001				
Not Applicable	by PN					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
91-08-13	**Initial and Repetitive Eddy Current Inspections Using an Improved, More Definitive Procedure For Detecting Fan Rotor Disk Dovetail Slot Cracks. (Superseded by AD 96-05-03)**							RE (-)		Mandatory	
72 ENG3						Mos	19-Jun-1991				
Complied With	S/B A72-3432 REV. 2					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
92-12-09	**Turbine Nozzles (Superseded By FAA AD 1994-07-03)**							RE (-)		Mandatory	
72 ENG1						Mos	08-May-1996				
Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
92-21-06	**Low Pressure Turbine (LPT) Rotor Disks**							RE (-)		Mandatory	
72 ENG1						Mos	28-Dec-1992				
Eff: 27-Nov-1992 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
92-21-06	**Low Pressure Turbine (LPT) Rotor Disks**							RE (-)		Mandatory	
72 ENG2						Mos	28-Dec-1992				
Eff: 27-Nov-1992 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
92-21-06	**Low Pressure Turbine (LPT) Rotor Disks**							RE (-)		Mandatory	
72 ENG3						Mos	29-Oct-2001				
Eff: 27-Nov-1992 Not Applicable	BY P/N					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
92-26-09	**Requires Eddy Current Inspection of Certain Fan Rotor Disks For Cracks, and Replacement, If Necessary, With Serviceable Parts. (Superseded by AD 96-04-01)**							RE (-)		Mandatory	
72 ENG1						Mos	28-Dec-1992				
Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
92-26-09	**Requires Eddy Current Inspection of Certain Fan Rotor Disks For Cracks, and Replacement, If Necessary, With Serviceable Parts. (Superseded by AD 96-04-01)**							RE (-)		Mandatory	
72 ENG2						Mos	28-Dec-1992				
Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
92-26-09	**Requires Eddy Current Inspection of Certain Fan Rotor Disks For Cracks, and Replacement, If Necessary, With Serviceable Parts. (Superseded by AD 96-04-01)**							RE (-)		Mandatory	
72 ENG3						Mos	28-Dec-1992				
Not Applicable	S/B A72-3504 IS N/A					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
93-25-16	**Requires Eddy Current Inspection of Certain Fan Rotor Disks For Cracks, and Replacement, If Necessary, of These Fan Rotor Disks. (Superseded by AD 98-17-01)**							RE (-)		Mandatory	
72 ENG1						Mos	02-Feb-1994				
Not Applicable	Per P/N S/N per SBA72-3504					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
93-25-16	**Requires Eddy Current Inspection of Certain Fan Rotor Disks For Cracks, and Replacement, If Necessary, of These Fan Rotor Disks. (Superseded by AD 98-17-01)**							RE (-)		Mandatory	
72 ENG2						Mos	01-Feb-1994				
Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
93-25-16	**Requires Eddy Current Inspection of Certain Fan Rotor Disks For Cracks, and Replacement, If Necessary, of These Fan Rotor Disks. (Superseded by AD 98-17-01)**							RE (-)		Mandatory	
72 ENG3						Mos	02-Feb-1994				
Not Applicable	PER S/B A72-3504					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
94-07-03	**Turbine Nozzles**							RE (-)		Mandatory	
72 ENG1						Mos	26-May-1994				
Eff: 06-Jun-1994 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					

Task No / SEQ	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
94-07-03	**Turbine Nozzles**							RE (-)		Mandatory	
72 ENG2						Mos	24-May-1994				
Eff: 06-Jun-1994 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
94-07-03	**Turbine Nozzles**							RE (-)		Mandatory	
72 ENG3						Mos	26-May-1994				
Eff: 06-Jun-1994 Not Applicable	AS SEAL WAS REPLACED					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
94-23-05	**Low Pressure Turbine Disk - Web Serrations - Remove/ Inspect**							RE (-)		Mandatory	
72 ENG1						Mos					
Eff: 01-Dec-1994 Not Applicable	per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
95-07-02	**Low Pressure Turbine Disks**							RE (-)		Mandatory	
72 ENG1						Mos	17-Feb-1997				
Eff: 19-Jun-1995 Not Applicable	By S/N Disks					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
95-07-02	**Low Pressure Turbine Disks**							RE (-)		Mandatory	
72 ENG2						Mos	08-May-1996				
Eff: 19-Jun-1995 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
95-07-02	**Low Pressure Turbine Disks**							RE (-)		Mandatory	
72 ENG3						Mos	03-Jun-1997				
Eff: 19-Jun-1995 Not Applicable	TO LPT S/N INSTALLED					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
96-04-01	**Fan Rotor Assembly**							RE (-)		Mandatory	
72 ENG1						Mos	08-Apr-1996				
Eff: 15-Mar-1996 Not Applicable	By FAN PN					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
96-04-01	**Fan Rotor Assembly**							RE (-)		Mandatory	
72 ENG2						Mos	06-Apr-1996				
Eff: 15-Mar-1996 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
96-04-01	**Fan Rotor Assembly**							RE (-)		Mandatory	
72 ENG3						Mos	08-Apr-1996				
Eff: 15-Mar-1996 Not Applicable	BY FAN P/N					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
96-05-03	**Fan rotor disks**							RE (-)		Mandatory	
72 ENG1						Mos	08-Apr-1996				
Eff: 02-Apr-1996 Not Applicable	PER P/N					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
96-05-03	**Fan rotor disks**							RE (-)		Mandatory	
72 ENG2						Mos	06-Apr-1996				
Eff: 02-Apr-1996 Not Applicable						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
96-05-03	**Fan rotor disks**							RE (-)		Mandatory	
72 ENG3						Mos	08-Apr-1996				
Eff: 02-Apr-1996 Not Applicable	BY FAN P/N					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
96-18-13	**To Prevent Failure of the Fan Rotor Disc Due to Fatigue Cracking In the Dovetail Slots, Which Could Result In In-Flight Engine Shutdown, Uncontained Engine Failure, and Damage to the Airplane, (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG1						Mos	24-Oct-1996				
Superseded	BY 2001-23-09					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
96-18-13	**To Prevent Failure of the Fan Rotor Disc Due to Fatigue Cracking In the Dovetail Slots, Which Could Result In In-Flight Engine Shutdown, Uncontained Engine Failure, and Damage to the Airplane, (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG2						Mos	24-Oct-1996				
Not Applicable	by PN					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
96-18-13	**To Prevent Failure of the Fan Rotor Disc Due to Fatigue Cracking In the Dovetail Slots, Which Could Result In In-Flight Engine Shutdown, Uncontained Engine Failure, and Damage to the Airplane, (Superseded by AD 2001-23-09)**							RE (-)		Mandatory	
72 ENG3						Mos	24-Oct-1996				
Not Applicable	BY P/N					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
97-04-03	**First stage low pressure turbine (LPT) seal plates**							RE (-)		Mandatory	
72 ENG1						Mos	11-Jan-2000				
Eff: 05-May-1997 Not Applicable	Per Model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
97-04-03	**First stage low pressure turbine (LPT) seal plates**							RE (-)		Mandatory	
72 ENG2						Mos	12-Jan-2000				
Eff: 05-May-1997 Not Applicable	per Model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
97-04-03	**First stage low pressure turbine (LPT) seal plates**							RE (-)		Mandatory	
72 ENG3						Mos	03-Jun-1997				
Eff: 05-May-1997 Not Applicable	TO ENG MODEL					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
D201012000013 Rev 2	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85 (Krypton 85) above 10,000 Becquerels**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 12-Aug-2021						Hrs					
						Enc					
D201012000013 Rev 2	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85 (Krypton 85) above 10,000 Becquerels**							T (A/R)		Service Information Letter	
72 ENG2						Mos					
Eff: 12-Aug-2021						Hrs					
						Enc					
D201012000013 Rev 2	**General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85 (Krypton 85) above 10,000 Becquerels**							T (A/R)		Service Information Letter	
72 ENG3						Mos					
Eff: 12-Aug-2021						Hrs					
						Enc					
D201801000060	**Crossover Tube, Oil Cap/Dipstick, Packing Removal/Installation**							T (A/R)		Service Information Letter	
72 ENG1						Mos					
Eff: 30-Mar-2018						Hrs					
						Enc					
Note: EFFECTIVITY: This service information letter (SIL) is applicable to all operators of TFE731 series turbofan engines.											

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
D201801000060	**Crossover Tube, Oil Cap/Dipstick, Packing Removal/Installation**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 30-Mar-2018					Hrs					
					Enc					
	Note: EFFECTIVITY: This service information letter (SIL) is applicable to all operators of TFE731 series turbofan engines.									
D201801000060	**Crossover Tube, Oil Cap/Dipstick, Packing Removal/Installation**						T (A/R)		Service Information Letter	
72 ENG3					Mos					
Eff: 30-Mar-2018					Hrs					
					Enc					
	Note: EFFECTIVITY: This service information letter (SIL) is applicable to all operators of TFE731 series turbofan engines.									
D201808000040	**Prevention of Migration of Super Absorbent Polymer (SAP) Filter Medium Particles into Aircraft Fuel Supplies and Engine Operation with Jet Fuel Contaminated with Diesel Exhaust Fluid (DEF)**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 15-Oct-2018					Hrs					
					Enc					
D201808000040	**Prevention of Migration of Super Absorbent Polymer (SAP) Filter Medium Particles into Aircraft Fuel Supplies and Engine Operation with Jet Fuel Contaminated with Diesel Exhaust Fluid (DEF)**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 15-Oct-2018					Hrs					
					Enc					
D201808000040	**Prevention of Migration of Super Absorbent Polymer (SAP) Filter Medium Particles into Aircraft Fuel Supplies and Engine Operation with Jet Fuel Contaminated with Diesel Exhaust Fluid (DEF)**						T (A/R)		Service Information Letter	
72 ENG3					Mos					
Eff: 15-Oct-2018					Hrs					
					Enc					
D201809000003	**Guidelines for Calibration of the Airflow Rig(s) Used on TFE731 A4 Nozzle Segments**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 30-Oct-2020					Hrs					
					Enc					
D201809000003	**Guidelines for Calibration of the Airflow Rig(s) Used on TFE731 A4 Nozzle Segments**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 30-Oct-2020					Hrs					
					Enc					
D201809000003	**Guidelines for Calibration of the Airflow Rig(s) Used on TFE731 A4 Nozzle Segments**						T (A/R)		Service Information Letter	
72 ENG3					Mos					
Eff: 30-Oct-2020					Hrs					
					Enc					
D202001000409	**Usage-Based MSP Program**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 22-Jan-2020					Hrs					
					Enc					
D202001000409	**Usage-Based MSP Program**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 22-Jan-2020					Hrs					
					Enc					
D202001000409	**Usage-Based MSP Program**						T (A/R)		Service Information Letter	
72 ENG3					Mos					
Eff: 22-Jan-2020					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
Engine 1	**Honeywell - TFE731-3D-1C**							RE (-)			
72 A/F						Mos					
3074570-1	Time at install:					Hrs					
P-76304C						Ldg					
						Flt					
Engine 2	**Honeywell - TFE731-3D-1C**							RE (-)			
72 A/F						Mos					
3074570-1	Time at install:					Hrs					
P-76302C						Ldg					
						Flt					
Engine 3	**Honeywell - TFE731-3D-1C**							RE (-)			
72 A/F						Mos					
3074570-1	Time at install:					Hrs					
P-76309C						Ldg					
						Flt					
F50-087	**Engine operation possible with conical spinner without anti-icing**							RE (-)			
72 A/F						Mos	09-Apr-1984				
Complied With						Hrs					
						Ldg					
Note: M0039A, M0029-1, M0039, A/C with engines with elliptical spinners						Flt					
F50-087 R1	**Engine operation possible with conical spinner without anti-icing**							T (A/R)			
72 A/F						Mos					
Eff: 15-Apr-1983						Hrs					
						Ldg					
Note: M0039A, M0029-1, M0039, A/C with engines with elliptical spinners						Flt					
F50-280	**Installation of ALLIED SIGNAL TFE731-40-1C engines**							RE (-)			
72 A/F						Mos					
						Hrs					
						Ldg					
Note: M2518, 2 to 250, 252 and A/C with Pro Line 4 V6.1 as per D.G.A.C. STC No 163 to SI to 2066						Flt					
F50-280 R1	**Installation of ALLIED SIGNAL TFE731-40-1C engines**							T (A/R)			
72 A/F						Mos					
Eff: 12-Jun-2002						Hrs					
						Ldg					
Note: M2518, 2 to 250, 252 and A/C with Pro Line 4 V6.1 as per D.G.A.C. STC No 163 to SI to 2066						Flt					
F731-90	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 21-Mar-2000						Hrs					
						Enc					
F731-90	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Service Information Letter	
72 ENG2						Mos					
Eff: 21-Mar-2000						Hrs					
						Enc					
F731-90	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Service Information Letter	
72 ENG3						Mos					
Eff: 21-Mar-2000						Hrs					
						Enc					
F731-90 Rev 1	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Service Information Letter	
72 ENG1						Mos					
Eff: 14-Oct-2005						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
F731-90 Rev 1	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**						RE (-)		Service Information Letter	
72 ENG2					Mos					
Eff: 14-Oct-2005					Hrs					
					Enc					
F731-90 Rev 1	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**						RE (-)		Service Information Letter	
72 ENG3					Mos					
Eff: 14-Oct-2005					Hrs					
					Enc					
F731-90 Rev 3	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 26-Jul-2024					Hrs					
					Enc					
F731-90 Rev 3	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 26-Jul-2024					Hrs					
					Enc					
F731-90 Rev 3	**The N1 DEEC on TFE731-2, -3, -4, and -5 Engine Models**						T (A/R)		Service Information Letter	
72 ENG3					Mos					
Eff: 26-Jul-2024					Hrs					
					Enc					
SIL No. 74	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**						RE (-)		Service Information Letter	
72 ENG1					Mos					
					Hrs					
					Enc					
SIL No. 74	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**						RE (-)		Service Information Letter	
72 ENG2					Mos					
					Hrs					
					Enc					
SIL No. 74	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**						RE (-)		Service Information Letter	
72 ENG3					Mos					
					Hrs					
					Enc					
SIL No. 74 Rev 1	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**						T (A/R)		Service Information Letter	
72 ENG1					Mos					
Eff: 06-Jun-2018					Hrs					
					Enc					
SIL No. 74 Rev 1	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**						T (A/R)		Service Information Letter	
72 ENG2					Mos					
Eff: 06-Jun-2018					Hrs					
					Enc					
SIL No. 74 Rev 1	**Engine Condition Trend Monitoring (ECTM) Kit, PN 831702-ALL, Superseded Dash Numbers**						T (A/R)		Service Information Letter	
72 ENG3					Mos					
Eff: 06-Jun-2018					Hrs					
					Enc					
TFE731-72-3001	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 06-Nov-1972					Hrs					
					Enc					
TFE731-72-3001	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 06-Nov-1972					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 06-Nov-1972						Hrs					
						Enc					
TFE731-72-3001 R1	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 25-Oct-1973						Hrs					
						Enc					
TFE731-72-3001 R1	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 25-Oct-1973						Hrs					
						Enc					
TFE731-72-3001 R1	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos	12-Jul-1997				
Eff: 25-Oct-1973 Complied With						Hrs					
						Enc					
TFE731-72-3001 R10	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 12-Nov-1980						Hrs					
						Enc					
TFE731-72-3001 R10	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 12-Nov-1980						Hrs					
						Enc					
TFE731-72-3001 R10	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos	01-Nov-1980				
Eff: 12-Nov-1980 Complied With						Hrs					
						Enc					
TFE731-72-3001 R11	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 17-Feb-1981						Hrs					
						Enc					
TFE731-72-3001 R11	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 17-Feb-1981						Hrs					
						Enc					
TFE731-72-3001 R11	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 17-Feb-1981						Hrs					
						Enc					
TFE731-72-3001 R12	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 23-Apr-1981						Hrs					
						Enc					
TFE731-72-3001 R12	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 23-Apr-1981						Hrs					
						Enc					
TFE731-72-3001 R12	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 23-Apr-1981						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R13	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos	27-Dec-1997				
Eff: 11-Jun-1982 Complied With						Hrs					
						Enc					
TFE731-72-3001 R13	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 11-Jun-1982						Hrs					
						Enc					
TFE731-72-3001 R13	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 11-Jun-1982						Hrs					
						Enc					
TFE731-72-3001 R14	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 13-Sep-1982						Hrs					
						Enc					
TFE731-72-3001 R14	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 13-Sep-1982						Hrs					
						Enc					
TFE731-72-3001 R14	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 13-Sep-1982						Hrs					
						Enc					
TFE731-72-3001 R15	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 30-Jun-1983						Hrs					
						Enc					
TFE731-72-3001 R15	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 30-Jun-1983						Hrs					
						Enc					
TFE731-72-3001 R15	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 30-Jun-1983						Hrs					
						Enc					
TFE731-72-3001 R16	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 26-Oct-1983						Hrs					
						Enc					
TFE731-72-3001 R16	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 26-Oct-1983						Hrs					
						Enc					
TFE731-72-3001 R16	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 26-Oct-1983						Hrs					
						Enc					
TFE731-72-3001 R17	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 08-Dec-1983						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R17	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 08-Dec-1983					Hrs					
					Enc					
TFE731-72-3001 R17	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 08-Dec-1983					Hrs					
					Enc					
TFE731-72-3001 R18	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 15-Nov-1984					Hrs					
					Enc					
TFE731-72-3001 R18	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 15-Nov-1984					Hrs					
					Enc					
TFE731-72-3001 R18	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 15-Nov-1984					Hrs					
					Enc					
TFE731-72-3001 R19	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 30-Nov-1984					Hrs					
					Enc					
TFE731-72-3001 R19	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 30-Nov-1984					Hrs					
					Enc					
TFE731-72-3001 R19	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 30-Nov-1984					Hrs					
					Enc					
TFE731-72-3001 R2	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 28-Dec-1973					Hrs					
					Enc					
TFE731-72-3001 R2	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 28-Dec-1973					Hrs					
					Enc					
TFE731-72-3001 R2	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 28-Dec-1973					Hrs					
					Enc					
TFE731-72-3001 R20	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 07-Mar-1985					Hrs					
					Enc					
TFE731-72-3001 R20	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 07-Mar-1985					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R20	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 07-Mar-1985					Hrs					
					Enc					
TFE731-72-3001 R21	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 17-May-1985					Hrs					
					Enc					
TFE731-72-3001 R21	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 17-May-1985					Hrs					
					Enc					
TFE731-72-3001 R21	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 17-May-1985					Hrs					
					Enc					
TFE731-72-3001 R22	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 19-Sep-1986					Hrs					
					Enc					
TFE731-72-3001 R22	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 19-Sep-1986					Hrs					
					Enc					
TFE731-72-3001 R22	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 19-Sep-1986					Hrs					
					Enc					
TFE731-72-3001 R23	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 24-Jun-1988					Hrs					
					Enc					
TFE731-72-3001 R23	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 24-Jun-1988					Hrs					
					Enc					
TFE731-72-3001 R23	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 24-Jun-1988					Hrs					
					Enc					
TFE731-72-3001 R24	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 20-Oct-1989					Hrs					
					Enc					
TFE731-72-3001 R24	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 20-Oct-1989					Hrs					
					Enc					
TFE731-72-3001 R24	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 20-Oct-1989					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R25	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 06-Jun-1990					Hrs					
					Enc					
TFE731-72-3001 R25	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 06-Jun-1990 Complied With					Hrs					
					Enc					
TFE731-72-3001 R25	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 06-Jun-1990 Complied With					Hrs					
					Enc					
TFE731-72-3001 R26	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 29-Mar-1991					Hrs					
					Enc					
TFE731-72-3001 R26	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 29-Mar-1991					Hrs					
					Enc					
TFE731-72-3001 R26	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 29-Mar-1991					Hrs					
					Enc					
TFE731-72-3001 R27	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 29-Nov-1991					Hrs					
					Enc					
TFE731-72-3001 R27	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 29-Nov-1991					Hrs					
					Enc					
TFE731-72-3001 R27	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 29-Nov-1991					Hrs					
					Enc					
TFE731-72-3001 R28	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 17-Jan-1992					Hrs					
					Enc					
TFE731-72-3001 R28	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 17-Jan-1992					Hrs					
					Enc					
TFE731-72-3001 R28	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 17-Jan-1992					Hrs					
					Enc					
TFE731-72-3001 R29	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 23-Mar-1992					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R29	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 23-Mar-1992						Hrs					
						Enc					
TFE731-72-3001 R29	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 23-Mar-1992						Hrs					
						Enc					
TFE731-72-3001 R3	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 17-Dec-1974						Hrs					
						Enc					
TFE731-72-3001 R3	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 17-Dec-1974						Hrs					
						Enc					
TFE731-72-3001 R3	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 17-Dec-1974						Hrs					
						Enc					
TFE731-72-3001 R30	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 24-Apr-1992						Hrs					
						Enc					
TFE731-72-3001 R30	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 24-Apr-1992						Hrs					
						Enc					
TFE731-72-3001 R30	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 24-Apr-1992						Hrs					
						Enc					
TFE731-72-3001 R31	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 23-Jun-1992						Hrs					
						Enc					
TFE731-72-3001 R31	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 23-Jun-1992						Hrs					
						Enc					
TFE731-72-3001 R31	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos	28-Dec-1992				
Eff: 23-Jun-1992 Complied With						Hrs					
						Enc					
TFE731-72-3001 R32	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 20-Nov-1992						Hrs					
						Enc					
TFE731-72-3001 R32	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 20-Nov-1992						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R32	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 20-Nov-1992					Hrs					
					Enc					
TFE731-72-3001 R33	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 29-Jan-1993					Hrs					
					Enc					
TFE731-72-3001 R33	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 29-Jan-1993					Hrs					
					Enc					
TFE731-72-3001 R33	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 29-Jan-1993					Hrs					
					Enc					
TFE731-72-3001 R34	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 11-May-1993					Hrs					
					Enc					
TFE731-72-3001 R34	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 11-May-1993					Hrs					
					Enc					
TFE731-72-3001 R34	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 11-May-1993					Hrs					
					Enc					
TFE731-72-3001 R35	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 01-Jun-1993					Hrs					
					Enc					
TFE731-72-3001 R35	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 01-Jun-1993					Hrs					
					Enc					
TFE731-72-3001 R35	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 01-Jun-1993					Hrs					
					Enc					
TFE731-72-3001 R36	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 27-Jul-1993					Hrs					
					Enc					
TFE731-72-3001 R36	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 27-Jul-1993					Hrs					
					Enc					
TFE731-72-3001 R36	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 27-Jul-1993					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R37	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 20-Aug-1993					Hrs					
					Enc					
TFE731-72-3001 R37	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 20-Aug-1993					Hrs					
					Enc					
TFE731-72-3001 R37	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 20-Aug-1993					Hrs					
					Enc					
TFE731-72-3001 R38	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 16-Dec-1993					Hrs					
					Enc					
TFE731-72-3001 R38	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 16-Dec-1993					Hrs					
					Enc					
TFE731-72-3001 R38	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 16-Dec-1993					Hrs					
					Enc					
TFE731-72-3001 R39	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 04-Jan-1994					Hrs					
					Enc					
TFE731-72-3001 R39	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 04-Jan-1994					Hrs					
					Enc					
TFE731-72-3001 R39	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 04-Jan-1994					Hrs					
					Enc					
TFE731-72-3001 R4	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 28-Feb-1975					Hrs					
					Enc					
TFE731-72-3001 R4	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 28-Feb-1975					Hrs					
					Enc					
TFE731-72-3001 R4	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 28-Feb-1975					Hrs					
					Enc					
TFE731-72-3001 R40	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 04-May-1994					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R40	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 04-May-1994						Hrs					
						Enc					
TFE731-72-3001 R40	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 04-May-1994						Hrs					
						Enc					
TFE731-72-3001 R41	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 04-Aug-1994						Hrs					
						Enc					
TFE731-72-3001 R41	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 04-Aug-1994						Hrs					
						Enc					
TFE731-72-3001 R41	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 04-Aug-1994						Hrs					
						Enc					
TFE731-72-3001 R42	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 17-Jul-1995						Hrs					
						Enc					
TFE731-72-3001 R42	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 17-Jul-1995						Hrs					
						Enc					
TFE731-72-3001 R42	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 17-Jul-1995						Hrs					
						Enc					
TFE731-72-3001 R43	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 07-Mar-1997						Hrs					
						Enc					
TFE731-72-3001 R43	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 07-Mar-1997						Hrs					
						Enc					
TFE731-72-3001 R43	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos	03-Jun-1997				
Eff: 07-Mar-1997 Complied With						Hrs					
						Enc					
TFE731-72-3001 R44	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 30-Dec-1997						Hrs					
						Enc					
TFE731-72-3001 R44	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 30-Dec-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R44	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 30-Dec-1997						Hrs					
						Enc					
TFE731-72-3001 R45	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 09-Oct-1998						Hrs					
						Enc					
TFE731-72-3001 R45	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 09-Oct-1998						Hrs					
						Enc					
TFE731-72-3001 R45	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 09-Oct-1998						Hrs					
						Enc					
TFE731-72-3001 R46	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 18-Oct-1999						Hrs					
						Enc					
TFE731-72-3001 R46	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 18-Oct-1999						Hrs					
						Enc					
TFE731-72-3001 R46	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 18-Oct-1999						Hrs					
						Enc					
TFE731-72-3001 R47	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 20-Nov-2000						Hrs					
						Enc					
TFE731-72-3001 R47	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 20-Nov-2000						Hrs					
						Enc					
TFE731-72-3001 R47	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 20-Nov-2000						Hrs					
						Enc					
TFE731-72-3001 R48	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos	07-Jan-2002				
Eff: 09-Apr-2001 Complied With						Hrs	9,830.8				
						Enc	5,855				
TFE731-72-3001 R48	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 09-Apr-2001						Hrs					
						Enc					
TFE731-72-3001 R48	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos	29-Oct-2001				
Eff: 09-Apr-2001 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R49	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 25-Jun-2003						Hrs					
						Enc					
TFE731-72-3001 R49	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 25-Jun-2003						Hrs					
						Enc					
TFE731-72-3001 R49	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 25-Jun-2003						Hrs					
						Enc					
TFE731-72-3001 R5	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 28-Feb-1978						Hrs					
						Enc					
TFE731-72-3001 R5	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 28-Feb-1978						Hrs					
						Enc					
TFE731-72-3001 R5	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 28-Feb-1978						Hrs					
						Enc					
TFE731-72-3001 R50	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos	31-Mar-2006				
Eff: 01-Nov-2004 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3001 R50	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 01-Nov-2004						Hrs					
						Enc					
TFE731-72-3001 R50	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 01-Nov-2004						Hrs					
						Enc					
TFE731-72-3001 R51	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 02-Mar-2006						Hrs					
						Enc					
TFE731-72-3001 R51	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 02-Mar-2006						Hrs					
						Enc					
TFE731-72-3001 R51	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos	29-Aug-2006				
Eff: 02-Mar-2006 Complied With						Hrs					
						Enc					
TFE731-72-3001 R52	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 06-Feb-2007						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R52	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 06-Feb-2007						Hrs					
						Enc					
TFE731-72-3001 R52	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 06-Feb-2007						Hrs					
						Enc					
TFE731-72-3001 R53	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 10-Aug-2007						Hrs					
						Enc					
TFE731-72-3001 R53	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 10-Aug-2007						Hrs					
						Enc					
TFE731-72-3001 R53	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 10-Aug-2007						Hrs					
						Enc					
TFE731-72-3001 R54	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 22-Sep-2008						Hrs					
						Enc					
TFE731-72-3001 R54	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 22-Sep-2008						Hrs					
						Enc					
TFE731-72-3001 R54	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 22-Sep-2008						Hrs					
						Enc					
TFE731-72-3001 R55	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 09-Mar-2009						Hrs					
						Enc					
TFE731-72-3001 R55	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 09-Mar-2009						Hrs					
						Enc					
TFE731-72-3001 R55	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 09-Mar-2009						Hrs					
						Enc					
TFE731-72-3001 R56	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							RE (-)		Informational	
72 ENG1						Mos	04-Jan-2023				
Eff: 29-Jun-2011 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-72-3001 R56	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**							T (A/R)		Informational	
72 ENG2						Mos					
Eff: 29-Jun-2011						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3001 R56	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						T (A/R)		Informational	
72 ENG3					Mos					
Eff: 29-Jun-2011					Hrs					
					Enc					
TFE731-72-3001 R6	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 15-May-1979					Hrs					
					Enc					
TFE731-72-3001 R6	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 15-May-1979					Hrs					
					Enc					
TFE731-72-3001 R6	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 15-May-1979					Hrs					
					Enc					
TFE731-72-3001 R7	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 20-Jul-1979					Hrs					
					Enc					
TFE731-72-3001 R7	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 20-Jul-1979					Hrs					
					Enc					
TFE731-72-3001 R7	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 20-Jul-1979					Hrs					
					Enc					
TFE731-72-3001 R8	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 20-Jun-1980	REVIEW OF SERVICE BULLETIN IS NECESSARY TO DETERMINE INCORPORATION				Hrs					
					Enc					
TFE731-72-3001 R8	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 20-Jun-1980					Hrs					
					Enc					
TFE731-72-3001 R8	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 20-Jun-1980					Hrs					
					Enc					
TFE731-72-3001 R9	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 27-Oct-1980					Hrs					
					Enc					
TFE731-72-3001 R9	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 27-Oct-1980					Hrs					
					Enc					
TFE731-72-3001 R9	**Engine- Service Life - Service Life Limits of Critical Life Limited Components**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 27-Oct-1980					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3020 R3	**Remove & Replace Transfer Gearbox Bearing Support**							RE (-)			
72 ENG1						Mos					
Eff: 26-May-1976 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3020 R3	**Remove & Replace Transfer Gearbox Bearing Support**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 26-May-1976 Complied With						Hrs					
						Enc					
TFE731-72-3020 R3	**Remove & Replace Transfer Gearbox Bearing Support**							T (A/R)			
72 ENG3						Mos					
Eff: 26-May-1976						Hrs					
						Enc					
TFE731-72-3022 R1	**Installation of Compressor With Increased Low Cycle Fatigue Life**							RE (-)			
72 ENG1						Mos					
Eff: 28-Oct-1975 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3022 R1	**Installation of Compressor With Increased Low Cycle Fatigue Life**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 28-Oct-1975 Complied With						Hrs					
						Enc					
TFE731-72-3022 R1	**Installation of Compressor With Increased Low Cycle Fatigue Life**							T (A/R)			
72 ENG3						Mos					
Eff: 28-Oct-1975						Hrs					
						Enc					
TFE731-72-3024	**ENGINE - TRANSFER SHAFT - Remove and Replace Internal Retaining Ring for Transfer Gearbox (INACTIVATED)**							RE (-)			
72 ENG1						Mos					
Eff: 25-Jul-1975						Hrs					
						Enc					
TFE731-72-3024	**ENGINE - TRANSFER SHAFT - Remove and Replace Internal Retaining Ring for Transfer Gearbox (INACTIVATED)**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 25-Jul-1975 Complied With						Hrs					
						Enc					
TFE731-72-3024	**ENGINE - TRANSFER SHAFT - Remove and Replace Internal Retaining Ring for Transfer Gearbox (INACTIVATED)**							RE (-)			
72 ENG3						Mos					
Eff: 25-Jul-1975						Hrs					
						Enc					
TFE731-72-3024 R1	**ENGINE - TRANSFER SHAFT - Remove and Replace Internal Retaining Ring for Transfer Gearbox (INACTIVATED)**							RE (-)			
72 ENG1						Mos					
Eff: 12-Dec-2001 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3025	**Replace Fan Spinner Support Bolts**							RE (-)			
72 ENG1						Mos					
Eff: 10-Jul-1975 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3025	**Replace Fan Spinner Support Bolts**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 10-Jul-1975 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3025	**Replace Fan Spinner Support Bolts**							T (A/R)			
72 ENG3						Mos					
Eff: 10-Jul-1975						Hrs					
						Enc					
TFE731-72-3033 R1	**Replace Low Pressure Turbine Bearing**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 24-May-1976 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3033 R1	**Replace Low Pressure Turbine Bearing**							RE (-)		Optional	
72 ENG2						Mos	17-Apr-1997				
Eff: 24-May-1976 Complied With						Hrs					
						Enc					
TFE731-72-3033 R1	**Replace Low Pressure Turbine Bearing**							T (A/R)		Optional	
72 ENG3						Mos					
Eff: 24-May-1976						Hrs					
						Enc					
TFE731-72-3034 R6	**Repl By-Pass Duct Panel**							T (A/R)			
72 ENG1						Mos					
Eff: 07-Aug-1980						Hrs					
(AVG MAN HRS: 16)						Enc					
TFE731-72-3034 R6	**Repl By-Pass Duct Panel**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 07-Aug-1980 Complied With						Hrs					
(AVG MAN HRS: 16)						Enc					
TFE731-72-3034 R6	**Repl By-Pass Duct Panel**							T (A/R)			
72 ENG3						Mos					
Eff: 07-Aug-1980						Hrs					
(AVG MAN HRS: 16)						Enc					
TFE731-72-3039 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3039 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Complied With						Hrs					
						Enc					
TFE731-72-3039 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3041 R1	**Replace Igniter Access Door PN 3071837-2**							T (A/R)		Optional	
72 ENG1						Mos					
Eff: 20-May-1977						Hrs					
						Enc					
TFE731-72-3041 R1	**Replace Igniter Access Door PN 3071837-2**							RE (-)		Optional	
72 ENG2						Mos	17-Apr-1997				
Eff: 20-May-1977 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3041 R1	**Replace Igniter Access Door PN 3071837-2**							T (A/R)		Optional	
72 ENG3						Mos					
Eff: 20-May-1977						Hrs					
						Enc					
TFE731-72-3042 Rev4	**ENGINE - COMBUSTION CHAMBER ASSEMBLY - Replace Combustion Liner, Part No. 3072448-4, with Improved Combustion Liner, Part No. 3072674-1/-3/-5/-6, or Part No. 3077002-1/-2/-3 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG1						Mos					
Eff: 30-Jan-1980 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3042 Rev4	**ENGINE - COMBUSTION CHAMBER ASSEMBLY - Replace Combustion Liner, Part No. 3072448-4, with Improved Combustion Liner, Part No. 3072674-1/-3/-5/-6, or Part No. 3077002-1/-2/-3 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 30-Jan-1980 Complied With						Hrs					
						Enc					
TFE731-72-3042 Rev4	**ENGINE - COMBUSTION CHAMBER ASSEMBLY - Replace Combustion Liner, Part No. 3072448-4, with Improved Combustion Liner, Part No. 3072674-1/-3/-5/-6, or Part No. 3077002-1/-2/-3 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG3						Mos					
Eff: 30-Jan-1980						Hrs					
						Enc					
TFE731-72-3044	**Add Jumper Assy To Improve Elec Sys**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 23-May-1977 Complied With	INCORPORATED IN PRODUCTION					Hrs					
(AVG MAN HRS: 0.5)						Enc					
TFE731-72-3044	**Add Jumper Assy To Improve Elec Sys**							RE (-)		Optional	
72 ENG2						Mos	01-Oct-1980				
Eff: 23-May-1977 Complied With						Hrs					
(AVG MAN HRS: 0.5)						Enc					
TFE731-72-3044	**Add Jumper Assy To Improve Elec Sys**							T (A/R)		Optional	
72 ENG3						Mos					
Eff: 23-May-1977						Hrs					
(AVG MAN HRS: 0.5)						Enc					
TFE731-72-3047	**ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR - Repair or Replace Pt2 Sensor Part No. 3070816-2 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG1						Mos	04-Nov-1980				
Eff: 18-Aug-1977 Complied With	INCORPORATED IN PRODUCTION					Hrs	0				
						Enc	0				
TFE731-72-3047	**ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR - Repair or Replace Pt2 Sensor Part No. 3070816-2 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG2						Mos					
Eff: 18-Aug-1977						Hrs					
						Enc					
TFE731-72-3047	**ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR - Repair or Replace Pt2 Sensor Part No. 3070816-2 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG3						Mos					
Eff: 18-Aug-1977						Hrs					
						Enc					
TFE731-72-3047 R3	**ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR - Repair or Replace Pt2 Sensor Part No. 3070816-2 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG1						Mos					
Eff: 15-May-1978						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3047 R3	**ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR - Repair or Replace Pt2 Sensor Part No. 3070816-2 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Eff: 15-May-1978 Complied With						Hrs					
						Enc					
TFE731-72-3047 R3	**ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR - Repair or Replace Pt2 Sensor Part No. 3070816-2 (Inactive for Further Accomplishment)**							RE (-)			
72 ENG3						Mos					
Eff: 15-May-1978						Hrs					
						Enc					
TFE731-72-3053 R1	**Install Improved LP 3Rd Stage Turbine Blade**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 01-Aug-1978 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3053 R1	**Install Improved LP 3Rd Stage Turbine Blade**							RE (-)		Optional	
72 ENG2						Mos	01-Oct-1980				
Eff: 01-Aug-1978 Complied With						Hrs					
						Enc					
TFE731-72-3053 R1	**Install Improved LP 3Rd Stage Turbine Blade**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 01-Aug-1978						Hrs					
						Enc					
TFE731-72-3054	**Install Planet Bearing PN 3072775-1/-2**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 02-Mar-1978						Hrs					
						Enc					
TFE731-72-3054	**Install Planet Bearing PN 3072775-1/-2**							RE (-)		Recommended	
72 ENG2						Mos	28-Dec-1992				
Eff: 02-Mar-1978 Complied With						Hrs					
						Enc					
TFE731-72-3054	**Install Planet Bearing PN 3072775-1/-2**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 02-Mar-1978						Hrs					
						Enc					
TFE731-72-3054 R2	**Install Planet Bearing PN 3072775-1/-2**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 02-Feb-1979						Hrs					
						Enc					
TFE731-72-3054 R2	**Install Planet Bearing PN 3072775-1/-2**							RE (-)		Recommended	
72 ENG2						Mos	14-Jan-2000				
Eff: 02-Feb-1979 Not Applicable						Hrs					
						Enc					
TFE731-72-3054 R2	**Install Planet Bearing PN 3072775-1/-2**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 02-Feb-1979						Hrs					
						Enc					
TFE731-72-3057 R2	**Install Improved Low Press Turbine Rotating Seal**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 12-Jul-1979 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3057 R2	**Install Improved Low Press Turbine Rotating Seal**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 12-Jul-1979 Complied With						Hrs					
						Enc					
TFE731-72-3057 R2	**Install Improved Low Press Turbine Rotating Seal**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 12-Jul-1979						Hrs					
						Enc					
TFE731-72-3058	**Install Planet Bearing PN 358733-4**							RE (-)		Recommended	
72 ENG1						Mos	25-Jan-1995				
Eff: 02-Mar-1978 Not Applicable						Hrs					
						Enc					
TFE731-72-3058	**Install Planet Bearing PN 358733-4**							RE (-)		Recommended	
72 ENG2						Mos	16-Mar-1995				
Eff: 02-Mar-1978 Not Applicable	by Eng P/N					Hrs					
						Enc					
TFE731-72-3058	**Install Planet Bearing PN 358733-4**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 02-Mar-1978						Hrs					
						Enc					
TFE731-72-3060	**Install HP Impeller PN 3072639-1**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 02-May-1978						Hrs					
						Enc					
TFE731-72-3060	**Install HP Impeller PN 3072639-1**							RE (-)		Optional	
72 ENG2						Mos	17-Apr-1997				
Eff: 02-May-1978 Complied With						Hrs					
						Enc					
TFE731-72-3060	**Install HP Impeller PN 3072639-1**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 02-May-1978						Hrs					
						Enc					
TFE731-72-3060 R3	**Install HP Impeller PN 3072639-1**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 07-Jul-1980 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3060 R3	**Install HP Impeller PN 3072639-1**							RE (-)		Optional	
72 ENG2						Mos	01-Oct-1980				
Eff: 07-Jul-1980 Complied With						Hrs					
						Enc					
TFE731-72-3060 R3	**Install HP Impeller PN 3072639-1**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 07-Jul-1980						Hrs					
						Enc					
TFE731-72-3062 R1	**Install Improved LP 1St Stage Turb Blade**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 01-Aug-1978						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3062 R1	**Install Improved LP 1St Stage Turb Blade**							RE (-)		Optional	
72 ENG2						Mos	01-Oct-1980				
Eff: 01-Aug-1978 Complied With						Hrs					
						Enc					
TFE731-72-3062 R1	**Install Improved LP 1St Stage Turb Blade**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 01-Aug-1978						Hrs					
						Enc					
TFE731-72-3063	**Install Improved LP 2Nd Stage Turbine Blade**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 16-Dec-1977						Hrs					
						Enc					
TFE731-72-3063	**Install Improved LP 2Nd Stage Turbine Blade**							RE (-)		Optional	
72 ENG2						Mos	17-Apr-1997				
Eff: 16-Dec-1977 Complied With						Hrs					
						Enc					
TFE731-72-3063	**Install Improved LP 2Nd Stage Turbine Blade**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 16-Dec-1977						Hrs					
						Enc					
TFE731-72-3063 R1	**Install Improved LP 2Nd Stage Turbine Blade**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 01-Aug-1978						Hrs					
						Enc					
TFE731-72-3063 R1	**Install Improved LP 2Nd Stage Turbine Blade**							RE (-)		Optional	
72 ENG2						Mos	01-Oct-1980				
Eff: 01-Aug-1978 Complied With						Hrs					
						Enc					
TFE731-72-3063 R1	**Install Improved LP 2Nd Stage Turbine Blade**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 01-Aug-1978						Hrs					
						Enc					
TFE731-72-3064	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3064	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Complied With						Hrs					
						Enc					
TFE731-72-3064	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3064 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3064 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3064 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3067 R1	**ENGINE - BY-PASS FAN SUPPORT - Install Seal Carrier Bolts, Part No. 145-131-9007. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 18-Sep-1978						Hrs					
						Enc					
TFE731-72-3067 R1	**ENGINE - BY-PASS FAN SUPPORT - Install Seal Carrier Bolts, Part No. 145-131-9007. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Eff: 18-Sep-1978 Complied With						Hrs					
						Enc					
TFE731-72-3067 R1	**ENGINE - BY-PASS FAN SUPPORT - Install Seal Carrier Bolts, Part No. 145-131-9007. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 18-Sep-1978						Hrs					
						Enc					
TFE731-72-3070	**Rework Fan Duct Set To Increase Interchangeability**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 23-May-1978 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3070	**Rework Fan Duct Set To Increase Interchangeability**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 23-May-1978 Complied With						Hrs					
						Enc					
TFE731-72-3070	**Rework Fan Duct Set To Increase Interchangeability**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 23-May-1978						Hrs					
						Enc					
TFE731-72-3076 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3076 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-72-3076 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3077 R1	**Replace Bolts Attaching Retainer Platet P/N 3072379-1 to Pinion Gear Assy**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 27-Jun-1978	REVIEW OF SERVICE BULLETIN IS NECESSARY TO DETERMINE INCORPORATION					Hrs					
						Enc					
TFE731-72-3077 R1	**Replace Bolts Attaching Retainer Platet P/N 3072379-1 to Pinion Gear Assy**							T (A/R)		Recommended	
72 ENG2						Mos					
Eff: 27-Jun-1978						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3077 R1	**Replace Bolts Attaching Retainer Platet P/N 3072379-1 to Pinion Gear Assy**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 27-Jun-1978						Hrs					
						Enc					
TFE731-72-3078	**Install New Bolts W/Lockwire Feature**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 06-Jun-1978						Hrs					
						Enc					
TFE731-72-3078	**Install New Bolts W/Lockwire Feature**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 06-Jun-1978 Complied With						Hrs					
						Enc					
TFE731-72-3078	**Install New Bolts W/Lockwire Feature**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 06-Jun-1978						Hrs					
						Enc					
TFE731-72-3078 R1	**Install New Bolts W/Lockwire Feature**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 30-May-1986 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3080	**Replace Anti-Ice Seal PN 3071297-2**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 09-Jun-1978 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3080	**Replace Anti-Ice Seal PN 3071297-2**							RE (-)		Optional	
72 ENG2						Mos	01-Oct-1980				
Eff: 09-Jun-1978 Complied With						Hrs					
						Enc					
TFE731-72-3080	**Replace Anti-Ice Seal PN 3071297-2**							T (A/R)		Optional	
72 ENG3						Mos					
Eff: 09-Jun-1978						Hrs					
						Enc					
TFE731-72-3081	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3081	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-72-3081	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3085	**Replace Fan Spinner & Related Anti-Ice Components**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 31-Aug-1978						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3085	**Replace Fan Spinner & Related Anti-Ice Components**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 31-Aug-1978 Complied With						Hrs					
						Enc					
TFE731-72-3085	**Replace Fan Spinner & Related Anti-Ice Components**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 31-Aug-1978						Hrs					
						Enc					
TFE731-72-3085 R2	**Replace Fan Spinner & Related Anti-Ice Components**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 11-May-1979						Hrs					
						Enc					
TFE731-72-3085 R2	**Replace Fan Spinner & Related Anti-Ice Components**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 11-May-1979 Complied With						Hrs					
						Enc					
TFE731-72-3085 R2	**Replace Fan Spinner & Related Anti-Ice Components**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 11-May-1979						Hrs					
						Enc					
TFE731-72-3086	**Engine - Interstage and HP Turbine Rotor Installation - First Stage Turbine Nozzle Assembly - Replacement of Part No. 3072319-1 with Part No. 3072319-4**							RE (-)		Service Bulletin	
72 ENG1						Mos					
Eff: 10-Apr-1979 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3086	**Engine - Interstage and HP Turbine Rotor Installation - First Stage Turbine Nozzle Assembly - Replacement of Part No. 3072319-1 with Part No. 3072319-4**							RE (-)		Service Bulletin	
72 ENG2						Mos	17-Apr-1997				
Eff: 10-Apr-1979 Complied With						Hrs					
						Enc					
TFE731-72-3086	**Engine - Interstage and HP Turbine Rotor Installation - First Stage Turbine Nozzle Assembly - Replacement of Part No. 3072319-1 with Part No. 3072319-4**							RE (-)		Service Bulletin	
72 ENG3						Mos					
Eff: 10-Apr-1979						Hrs					
						Enc					
TFE731-72-3086 Rev 2	**Engine - Interstage and HP Turbine Rotor Installation - First Stage Turbine Nozzle Assembly - Replacement of Part No. 3072319-1 with Part No. 3072319-4 (Superseded by TFE731-72-8086 R03)**							RE (-)		Service Bulletin	
72 ENG1						Mos					
Eff: 22-Jul-1983						Hrs					
						Enc					
TFE731-72-3086 Rev 2	**Engine - Interstage and HP Turbine Rotor Installation - First Stage Turbine Nozzle Assembly - Replacement of Part No. 3072319-1 with Part No. 3072319-4 (Superseded by TFE731-72-8086 R03)**							RE (-)		Service Bulletin	
72 ENG2						Mos	17-Apr-1997				
Eff: 22-Jul-1983 Complied With						Hrs					
						Enc					
TFE731-72-3086 Rev 2	**Engine - Interstage and HP Turbine Rotor Installation - First Stage Turbine Nozzle Assembly - Replacement of Part No. 3072319-1 with Part No. 3072319-4 (Superseded by TFE731-72-8086 R03)**							RE (-)		Service Bulletin	
72 ENG3						Mos					
Eff: 22-Jul-1983						Hrs					
						Enc					
TFE731-72-3087	**Incorporate Replacement Tie Shaft**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 05-Apr-1979 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3087	**Incorporate Replacement Tie Shaft**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 05-Apr-1979 Complied With						Hrs					
						Enc					
TFE731-72-3087	**Incorporate Replacement Tie Shaft**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 05-Apr-1979						Hrs					
						Enc					
TFE731-72-3095	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3095	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-72-3095	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3095 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3095 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Complied With						Hrs					
						Enc					
TFE731-72-3095 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3096	**Incorporate Replacement LP Shaft & Seal Assy**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 03-Apr-1979 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3096	**Incorporate Replacement LP Shaft & Seal Assy**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 03-Apr-1979 Complied With						Hrs					
						Enc					
TFE731-72-3096	**Incorporate Replacement LP Shaft & Seal Assy**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 03-Apr-1979						Hrs					
						Enc					
TFE731-72-3098	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3098	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-72-3098	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3106	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG1						Mos					
Eff: 03-Jul-1979						Hrs					
						Enc					
TFE731-72-3106 R14	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG1						Mos					
Eff: 20-Apr-1990						Hrs					
						Enc					
TFE731-72-3106 R14	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG2						Mos	19-Dec-1990				
Eff: 20-Apr-1990 Complied With						Hrs					
						Enc					
TFE731-72-3106 R14	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG3						Mos					
Eff: 20-Apr-1990						Hrs					
						Enc					
TFE731-72-3106 R15	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Eff: 30-Apr-1991 Not Applicable						Hrs					
						Enc					
TFE731-72-3106 R15	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Eff: 30-Apr-1991 Not Applicable						Hrs					
						Enc					
TFE731-72-3106 R15	**Establishing Periodic Inspection Intervals**							T (A/R)			
72 ENG3						Mos					
Eff: 30-Apr-1991						Hrs					
						Enc					
TFE731-72-3113	**Replace Support Housing**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 29-Aug-1979 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3113	**Replace Support Housing**							RE (-)		Optional	
72 ENG2						Mos	01-Oct-1980				
Eff: 29-Aug-1979 Complied With						Hrs					
						Enc					
TFE731-72-3113	**Replace Support Housing**							T (A/R)		Optional	
72 ENG3						Mos					
Eff: 29-Aug-1979						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3116	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3116	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-72-3116	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3119	**Decrease Turbine End Shaft Strech Dimension on LP Tie Rod**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 27-Mar-1980 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3119	**Decrease Turbine End Shaft Strech Dimension on LP Tie Rod**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 27-Mar-1980 Complied With						Hrs					
						Enc					
TFE731-72-3119	**Decrease Turbine End Shaft Strech Dimension on LP Tie Rod**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 27-Mar-1980						Hrs					
						Enc					
TFE731-72-3124	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 16-Nov-1981						Hrs					
						Enc					
TFE731-72-3124	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG2						Mos					
Eff: 16-Nov-1981 Complied With						Hrs					
						Enc					
TFE731-72-3124	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 16-Nov-1981 Complied With						Hrs					
						Enc					
TFE731-72-3124 R1	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 07-Jun-1983						Hrs					
						Enc					
TFE731-72-3124 R1	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG2						Mos					
Eff: 07-Jun-1983						Hrs					
						Enc					
TFE731-72-3124 R1	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 07-Jun-1983						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3124 R2	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG1					Mos					
Eff: 11-Oct-1983					Hrs					
					Enc					
TFE731-72-3124 R2	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG2					Mos					
Eff: 11-Oct-1983					Hrs					
					Enc					
TFE731-72-3124 R2	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG3					Mos					
Eff: 11-Oct-1983					Hrs					
					Enc					
TFE731-72-3124 R3	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG1					Mos					
Eff: 26-Sep-1984					Hrs					
					Enc					
TFE731-72-3124 R3	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG2					Mos					
Eff: 26-Sep-1984					Hrs					
					Enc					
TFE731-72-3124 R3	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG3					Mos					
Eff: 26-Sep-1984					Hrs					
					Enc					
TFE731-72-3124 R4	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG1					Mos					
Eff: 22-Aug-1986					Hrs					
					Enc					
TFE731-72-3124 R4	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG2					Mos					
Eff: 22-Aug-1986					Hrs					
					Enc					
TFE731-72-3124 R4	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG3					Mos					
Eff: 22-Aug-1986					Hrs					
					Enc					
TFE731-72-3124 R5	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG1					Mos					
Eff: 02-Jun-1989					Hrs					
					Enc					
TFE731-72-3124 R5	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG2					Mos					
Eff: 02-Jun-1989					Hrs					
					Enc					
TFE731-72-3124 R5	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG3					Mos					
Eff: 02-Jun-1989					Hrs					
					Enc					
TFE731-72-3124 R6	**Modify Starter/Generator Drive Spur Gearshaft**						RE (-)		Optional	
72 ENG1					Mos					
Eff: 18-Feb-1984					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3124 R6	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG2						Mos					
Eff: 18-Feb-1984						Hrs					
						Enc					
TFE731-72-3124 R6	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 18-Feb-1984						Hrs					
						Enc					
TFE731-72-3124 R7	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 09-Jun-1994						Hrs					
						Enc					
TFE731-72-3124 R7	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG2						Mos	17-Jun-1994				
Eff: 09-Jun-1994 Complied With						Hrs					
						Enc					
TFE731-72-3124 R7	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 09-Jun-1994						Hrs					
						Enc					
TFE731-72-3124 R8	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG1						Mos	20-May-1997				
Eff: 24-Jun-1996 Complied With						Hrs	7,478				
						Enc	4,553				
TFE731-72-3124 R8	**Modify Starter/Generator Drive Spur Gearshaft**							T (A/R)		Optional	
72 ENG2						Mos					
Eff: 24-Jun-1996						Hrs					
						Enc					
TFE731-72-3124 R8	**Modify Starter/Generator Drive Spur Gearshaft**							RE (-)		Optional	
72 ENG3						Mos	23-Aug-1997				
Eff: 24-Jun-1996 Complied With						Hrs					
						Enc					
TFE731-72-3126 R5	**Replace/Rework Planet Gearshaft Assembly**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3126 R5	**Replace/Rework Planet Gearshaft Assembly**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-72-3126 R5	**Replace/Rework Planet Gearshaft Assembly**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3128	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos	20-May-1997				
Eff: 16-Nov-1981 Complied With						Hrs	7,478				
						Enc	4,553				
TFE731-72-3128	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 16-Nov-1981						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3128	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos	03-Jun-1997				
Eff: 16-Nov-1981						Hrs					
						Enc					
TFE731-72-3128 R1	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 07-Jun-1983						Hrs					
						Enc					
TFE731-72-3128 R1	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 07-Jun-1983						Hrs					
						Enc					
TFE731-72-3128 R1	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 07-Jun-1983						Hrs					
						Enc					
TFE731-72-3128 R2	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 11-Oct-1983						Hrs					
						Enc					
TFE731-72-3128 R2	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 11-Oct-1983						Hrs					
						Enc					
TFE731-72-3128 R2	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 11-Oct-1983						Hrs					
						Enc					
TFE731-72-3128 R3	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 26-Sep-1984						Hrs					
						Enc					
TFE731-72-3128 R3	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 26-Sep-1984						Hrs					
						Enc					
TFE731-72-3128 R3	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 26-Sep-1984						Hrs					
						Enc					
TFE731-72-3128 R4	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 22-Aug-1986						Hrs					
						Enc					
TFE731-72-3128 R4	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 22-Aug-1986						Hrs					
						Enc					
TFE731-72-3128 R4	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 22-Aug-1986						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3128 R5	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 02-Jun-1989						Hrs					
						Enc					
TFE731-72-3128 R5	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 02-Jun-1989						Hrs					
						Enc					
TFE731-72-3128 R5	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 02-Jun-1989						Hrs					
						Enc					
TFE731-72-3128 R6	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 18-Feb-1994						Hrs					
						Enc					
TFE731-72-3128 R6	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 18-Feb-1994						Hrs					
						Enc					
TFE731-72-3128 R6	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 18-Feb-1994						Hrs					
						Enc					
TFE731-72-3128 R7	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 09-Jun-1994						Hrs					
						Enc					
TFE731-72-3128 R7	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 09-Jun-1994						Hrs					
						Enc					
TFE731-72-3128 R7	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 09-Jun-1994						Hrs					
						Enc					
TFE731-72-3128 R8	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG1						Mos	27-Dec-1997				
Eff: 24-Jun-1996 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-72-3128 R8	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG2						Mos	17-Apr-1997				
Eff: 24-Jun-1996 Complied With						Hrs					
						Enc					
TFE731-72-3128 R8	**Modify Alternator Drive Spur Gearshaft**							RE (-)		Category 3	
72 ENG3						Mos	23-Aug-1997				
Eff: 24-Jun-1996 Complied With						Hrs					
						Enc					
TFE731-72-3128 R9	**Modify Alternator Drive Spur Gearshaft**							T (A/R)		Category 3	
72 ENG1						Mos					
Eff: 18-Feb-2003						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3128 R9	**Modify Alternator Drive Spur Gearshaft**							T (A/R)		Category 3	
72 ENG2						Mos					
Eff: 18-Feb-2003						Hrs					
						Enc					
TFE731-72-3128 R9	**Modify Alternator Drive Spur Gearshaft**							T (A/R)		Category 3	
72 ENG3						Mos					
Eff: 18-Feb-2003						Hrs					
						Enc					
TFE731-72-3129	**Incorporate Breather System For No. 4 & 5 Bearing Sump Area**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 27-Feb-1980						Hrs					
						Enc					
TFE731-72-3129 R3	**Incorporate Breather System For No. 4 & 5 Bearing Sump Area**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 30-Apr-1981						Hrs					
						Enc					
TFE731-72-3129 R3	**Incorporate Breather System For No. 4 & 5 Bearing Sump Area**							RE (-)		Optional	
72 ENG2						Mos	13-Nov-1984				
Eff: 30-Apr-1981 Complied With						Hrs					
						Enc					
TFE731-72-3129 R3	**Incorporate Breather System For No. 4 & 5 Bearing Sump Area**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 30-Apr-1981						Hrs					
						Enc					
TFE731-72-3133	**Inspect & Replace Fan By-Pass Stator Alignment Pins**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 21-Apr-1980						Hrs					
						Enc					
TFE731-72-3133	**Inspect & Replace Fan By-Pass Stator Alignment Pins**							RE (-)		Recommended	
72 ENG2						Mos	16-Mar-1995				
Eff: 21-Apr-1980 Complied With	by Eng P/N					Hrs					
						Enc					
TFE731-72-3133	**Inspect & Replace Fan By-Pass Stator Alignment Pins**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 21-Apr-1980						Hrs					
						Enc					
TFE731-72-3136	**Replace Annular Ball Bearings PN 358206**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 04-Oct-1977						Hrs					
						Enc					
TFE731-72-3136	**Replace Annular Ball Bearings PN 358206**							RE (-)		Recommended	
72 ENG2						Mos	17-Apr-1997				
Eff: 04-Oct-1977 Complied With						Hrs					
						Enc					
TFE731-72-3136	**Replace Annular Ball Bearings PN 358206**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 04-Oct-1977						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3136 R1	**Replace Annular Ball Bearings PN 358206**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 20-Jul-1980 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3136 R1	**Replace Annular Ball Bearings PN 358206**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 20-Jul-1980 Complied With						Hrs					
						Enc					
TFE731-72-3136 R1	**Replace Annular Ball Bearings PN 358206**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 20-Jul-1980						Hrs					
						Enc					
TFE731-72-3145	**Internal Corrosion Prevention**							RE (-)		Recommended	
72 ENG1						Mos	03-Nov-1988				
Eff: 15-Oct-1980						Hrs					
						Enc					
TFE731-72-3145 R2	**Internal Corrosion Prevention**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 25-May-1983						Hrs					
						Enc					
TFE731-72-3145 R2	**Internal Corrosion Prevention**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 25-May-1983 Complied With						Hrs					
						Enc					
TFE731-72-3145 R2	**Internal Corrosion Prevention**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 25-May-1983						Hrs					
						Enc					
TFE731-72-3148	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-72-3148	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-72-3148	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3148 R3	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 13-May-1994						Hrs					
						Enc					
TFE731-72-3148 R3	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Eff: 13-May-1994 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3148 R3	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 13-May-1994						Hrs					
						Enc					
TFE731-72-3159	**Inspect and/or Replace Turbine Interstage Transition Duct**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 23-Apr-1981 Complied With						Hrs					
						Enc					
TFE731-72-3159	**Inspect and/or Replace Turbine Interstage Transition Duct**							RE (-)		Recommended	
72 ENG2						Mos	01-Oct-1980				
Eff: 23-Apr-1981 Complied With						Hrs					
						Enc					
TFE731-72-3159	**Inspect and/or Replace Turbine Interstage Transition Duct**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 23-Apr-1981						Hrs					
						Enc					
TFE731-72-3159 R1	**Inspect and/or Replace Turbine Interstage Transition Duct**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 16-Sep-1981						Hrs					
						Enc					
TFE731-72-3159 R1	**Inspect and/or Replace Turbine Interstage Transition Duct**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 16-Sep-1981 Complied With						Hrs					
						Enc					
TFE731-72-3159 R1	**Inspect and/or Replace Turbine Interstage Transition Duct**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 16-Sep-1981						Hrs					
						Enc					
TFE731-72-3164	**Interchange of 4Th Stage Axial Flow Compressor Rotor Assy**							RE (-)		Optional	
72 ENG1						Mos					
Eff: 06-May-1981						Hrs					
						Enc					
TFE731-72-3164	**Interchange of 4Th Stage Axial Flow Compressor Rotor Assy**							RE (-)		Optional	
72 ENG2						Mos	16-Mar-1995				
Eff: 06-May-1981 Not Applicable	by Eng P/N					Hrs					
						Enc					
TFE731-72-3164	**Interchange of 4Th Stage Axial Flow Compressor Rotor Assy**							RE (-)		Optional	
72 ENG3						Mos					
Eff: 06-May-1981						Hrs					
						Enc					
TFE731-72-3167	**ENGINE - FAN SUPPORT SHAFT AND HOUSING ASSEMBLY - Replace Gasket, Part No. 3071968-1/-2, With Seal Plate, Part No. 3073213-1 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 12-Feb-1982						Hrs					
						Enc					
TFE731-72-3167	**ENGINE - FAN SUPPORT SHAFT AND HOUSING ASSEMBLY - Replace Gasket, Part No. 3071968-1/-2, With Seal Plate, Part No. 3073213-1 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Eff: 12-Feb-1982 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3167	**ENGINE - FAN SUPPORT SHAFT AND HOUSING ASSEMBLY - Replace Gasket, Part No. 3071968-1/-2, With Seal Plate, Part No. 3073213-1 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 12-Feb-1982						Hrs					
						Enc					
TFE731-72-3169	**Replace Identified HP Rotor Thrust (No. 5) Bearing**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 09-Jun-1981						Hrs					
						Enc					
TFE731-72-3169	**Replace Identified HP Rotor Thrust (No. 5) Bearing**							RE (-)		Recommended	
72 ENG2						Mos	16-Mar-1995				
Eff: 09-Jun-1981 Not Applicable						Hrs					
						Enc					
TFE731-72-3169	**Replace Identified HP Rotor Thrust (No. 5) Bearing**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 09-Jun-1981						Hrs					
						Enc					
TFE731-72-3169 R2	**Replace Identified HP Rotor Thrust (No. 5) Bearing**							RE (-)		Recommended	
72 ENG1						Mos	25-Jan-1995				
Eff: 19-Mar-1982 Not Applicable						Hrs					
						Enc					
TFE731-72-3174	**Install New Or Reworked High Pressure Compressor Diffuser (Superseded By TFE731-72-3174 R01)**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3174 R3	**Install New Or Reworked High Pressure Compressor Diffuser (Superseded By TFE731-72-3174 R04)**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Complied With						Hrs					
						Enc					
TFE731-72-3177	**Replace SHPNg Gskt Under HP BI Air Port Cov**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 11-Aug-1981						Hrs					
						Enc					
TFE731-72-3177 R1	**Replace SHPNg Gskt Under HP BI Air Port Cov**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 08-Jul-1982						Hrs					
						Enc					
TFE731-72-3177 R1	**Replace SHPNg Gskt Under HP BI Air Port Cov**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 08-Jul-1982 Complied With						Hrs					
						Enc					
TFE731-72-3177 R1	**Replace SHPNg Gskt Under HP BI Air Port Cov**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 08-Jul-1982						Hrs					
						Enc					
TFE731-72-3181	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	24-Jan-1985				
Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3181	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	12-Jan-1987				
Complied With						Hrs					
						Enc					
TFE731-72-3181	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3190	**Install Reworked Spur Ring Gear PN 3077000-1/-2**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1985				
Eff: 07-Jan-1982 Complied With						Hrs					
						Enc					
TFE731-72-3190 R2	**Install Reworked Spur Ring Gear PN 3077000-1/-2**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 12-Apr-1982						Hrs					
						Enc					
TFE731-72-3190 R2	**Install Reworked Spur Ring Gear PN 3077000-1/-2**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 12-Apr-1982 Complied With						Hrs					
						Enc					
TFE731-72-3190 R2	**Install Reworked Spur Ring Gear PN 3077000-1/-2**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 12-Apr-1982						Hrs					
						Enc					
TFE731-72-3216	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	24-Jan-1985				
						Hrs					
						Enc					
TFE731-72-3216	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Complied With						Hrs					
						Enc					
TFE731-72-3216	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3216 R5	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
TFE731-72-3216 R5	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Eff: 18-Mar-1994 Complied With						Hrs					
						Enc					
TFE731-72-3216 R5	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
TFE731-72-3219	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 25-Aug-1982						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3219	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 25-Aug-1982						Hrs					
						Enc					
TFE731-72-3219	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 25-Aug-1982						Hrs					
						Enc					
TFE731-72-3219 R1	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 20-Oct-1982						Hrs					
						Enc					
TFE731-72-3219 R1	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 20-Oct-1982						Hrs					
						Enc					
TFE731-72-3219 R1	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 20-Oct-1982						Hrs					
						Enc					
TFE731-72-3219 R2	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 10-Jan-1986						Hrs					
						Enc					
TFE731-72-3219 R2	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 10-Jan-1986						Hrs					
						Enc					
TFE731-72-3219 R2	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 10-Jan-1986						Hrs					
						Enc					
TFE731-72-3219 R3	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG1						Mos	15-May-1992				
Eff: 11-Nov-1988 Complied With						Hrs	4,353				
						Enc	2,613				
TFE731-72-3219 R3	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 11-Nov-1988						Hrs					
						Enc					
TFE731-72-3219 R3	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 11-Nov-1988						Hrs					
						Enc					
TFE731-72-3219 R4	**Ident Of LP & HP Turb Rtr Assemblies**							T (A/R)		Informational	
72 ENG1						Mos					
Eff: 23-Feb-1996						Hrs					
						Enc					
TFE731-72-3219 R4	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG2						Mos	17-Apr-1997				
Eff: 23-Feb-1996 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3219 R4	**Ident Of LP & HP Turb Rtr Assemblies**							RE (-)		Informational	
72 ENG3						Mos	23-Aug-1997				
Eff: 23-Feb-1996 Complied With						Hrs					
						Enc					
TFE731-72-3224	**Inspectionect Comb Chamber Liner Pn 3072674-3**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 12-Aug-1982 Complied With						Hrs					
						Enc					
TFE731-72-3224	**Inspectionect Comb Chamber Liner Pn 3072674-3**							T (A/R)		Recommended	
72 ENG2						Mos	14-Jun-1984				
Eff: 12-Aug-1982 Complied With						Hrs					
						Enc					
TFE731-72-3224	**Inspectionect Comb Chamber Liner Pn 3072674-3**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 12-Aug-1982						Hrs					
						Enc					
TFE731-72-3225	**Remove 1St Stg LP Turbine Blades Pn 3072311-2**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1985				
Eff: 09-Jul-1992						Hrs					
						Enc					
TFE731-72-3225 R1	**Remove 1St Stg LP Turbine Blades Pn 3072311-2**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 19-Apr-1984						Hrs					
						Enc					
TFE731-72-3225 R1	**Remove 1St Stg LP Turbine Blades Pn 3072311-2**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 19-Apr-1984 Complied With						Hrs					
						Enc					
TFE731-72-3225 R1	**Remove 1St Stg LP Turbine Blades Pn 3072311-2**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 19-Apr-1984						Hrs					
						Enc					
TFE731-72-3227	**Replace LP Compressor Bearing Housing**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1985				
Eff: 17-Sep-1982						Hrs					
						Enc					
TFE731-72-3227	**Replace LP Compressor Bearing Housing**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 17-Sep-1982 Complied With						Hrs					
						Enc					
TFE731-72-3227	**Replace LP Compressor Bearing Housing**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 17-Sep-1982						Hrs					
						Enc					
TFE731-72-3234	**3070039-4 transition liner to 3070039-6**							RE (-)			
72 ENG1						Mos	05-Jan-1987				
						Hrs					
						Enc					
TFE731-72-3237	**Install HP Compressor Impeller**							RE (-)			
72 ENG1						Mos					
Eff: 13-Sep-1982						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3237 R3	**Install HP Compressor Impeller**							T (A/R)			
72 ENG1						Mos					
Eff: 15-Dec-1989						Hrs					
						Enc					
TFE731-72-3237 R3	**Install HP Compressor Impeller**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Eff: 15-Dec-1989 Complied With	PCW					Hrs					
						Enc					
TFE731-72-3237 R3	**Install HP Compressor Impeller**							T (A/R)			
72 ENG3						Mos					
Eff: 15-Dec-1989						Hrs					
						Enc					
TFE731-72-3239RWK	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3239RWK	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3239RWK	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3239RWK R1	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3239RWK R1	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3239RWK R1	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3239RWK R2	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3239RWK R2	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3239RWK R2	**Rework HP Compressor Radial Impeller**							RE (-)		Service Bulletin	
72 ENG3						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3239RWK R3	**Rework HP Compressor Radial Impeller**							T (A/R)		Service Bulletin	
72 ENG1						Mos					
Eff: 12-Apr-1999						Hrs					
						Enc					
TFE731-72-3239RWK R3	**Rework HP Compressor Radial Impeller**							T (A/R)		Service Bulletin	
72 ENG2						Mos					
Eff: 12-Apr-1999						Hrs					
						Enc					
TFE731-72-3239RWK R3	**Rework HP Compressor Radial Impeller**							T (A/R)		Service Bulletin	
72 ENG3						Mos					
Eff: 12-Apr-1999						Hrs					
						Enc					
TFE731-72-3252	**Inspectection Of Second Stage LP Turbine Disk**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1985				
Eff: 29-Apr-1983						Hrs					
						Enc					
TFE731-72-3252	**Inspectection Of Second Stage LP Turbine Disk**							RE (-)		Recommended	
72 ENG2						Mos	16-Mar-1995				
Eff: 29-Apr-1983 Not Applicable	by S/N					Hrs					
						Enc					
TFE731-72-3252	**Inspectection Of Second Stage LP Turbine Disk**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 29-Apr-1983						Hrs					
						Enc					
TFE731-72-3253	**ENGINE COMPRESSOR SECTION - Rework/Replace Fourth Stage LP Compressor Stator, Part No. 3071523-3 to Part No. 3071523-4 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	24-Jan-1985				
Eff: 26-Jul-1983						Hrs					
						Enc					
TFE731-72-3253 Rev4	**ENGINE COMPRESSOR SECTION - Rework/Replace Fourth Stage LP Compressor Stator, Part No. 3071523-3 to Part No. 3071523-4 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 13-May-1994						Hrs					
						Enc					
TFE731-72-3253 Rev4	**ENGINE COMPRESSOR SECTION - Rework/Replace Fourth Stage LP Compressor Stator, Part No. 3071523-3 to Part No. 3071523-4 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Eff: 13-May-1994 Complied With						Hrs					
						Enc					
TFE731-72-3253 Rev4	**ENGINE COMPRESSOR SECTION - Rework/Replace Fourth Stage LP Compressor Stator, Part No. 3071523-3 to Part No. 3071523-4 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 13-May-1994						Hrs					
						Enc					
TFE731-72-3259	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	24-Jan-1985				
Complied With						Hrs					
						Enc					
TFE731-72-3259 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 13-May-1994						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3259 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Eff: 13-May-1994 Complied With						Hrs					
						Enc					
TFE731-72-3259 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 13-May-1994						Hrs					
						Enc					
TFE731-72-3272 R4	**Inspect LP Turbine Rotor Assy Disks (Inactive for further accomplishment)**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Complied With						Hrs					
						Enc					
TFE731-72-3275	**ENGINE COMPRESSOR INSTALLATION - Install Improved Seal in Diffuser to Eliminate Potential Oil Leakage (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	24-Jan-1985				
Eff: 27-Mar-1984						Hrs					
						Enc					
TFE731-72-3275 R2	**ENGINE COMPRESSOR INSTALLATION - Install Improved Seal in Diffuser to Eliminate Potential Oil Leakage (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
TFE731-72-3275 R2	**ENGINE COMPRESSOR INSTALLATION - Install Improved Seal in Diffuser to Eliminate Potential Oil Leakage (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	13-Nov-1984				
Eff: 18-Mar-1994 Complied With						Hrs					
						Enc					
TFE731-72-3275 R2	**ENGINE COMPRESSOR INSTALLATION - Install Improved Seal in Diffuser to Eliminate Potential Oil Leakage (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
TFE731-72-3280	**Replace/Rework Compressor Interstage Diffuser**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1985				
Eff: 30-Jul-1984						Hrs					
						Enc					
TFE731-72-3280 R1	**Replace/Rework Compressor Interstage Diffuser**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 14-Mar-1986						Hrs					
						Enc					
TFE731-72-3280 R1	**Replace/Rework Compressor Interstage Diffuser**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 14-Mar-1986 Complied With						Hrs					
						Enc					
TFE731-72-3280 R1	**Replace/Rework Compressor Interstage Diffuser**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 14-Mar-1986						Hrs					
						Enc					
TFE731-72-3287	**Rewk Or Repl Access Drive Gearbox Hsg Assy**							T (A/R)			
72 ENG1						Mos					
Eff: 25-Mar-1985						Hrs					
						Enc					
TFE731-72-3287	**Rewk Or Repl Access Drive Gearbox Hsg Assy**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 25-Mar-1985 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3287	**Rewk Or Repl Access Drive Gearbox Hsg Assy**							T (A/R)			
72 ENG3						Mos					
Eff: 25-Mar-1985						Hrs					
						Enc					
TFE731-72-3288	**Modification to Provide Positive Retention of Engine Nameplate**							T (A/R)		Recommended	
72 ENG1						Mos	24-Jan-1985				
Eff: 11-Sep-1984						Hrs					
						Enc					
TFE731-72-3288	**Modification to Provide Positive Retention of Engine Nameplate**							RE (-)		Recommended	
72 ENG2						Mos	13-Nov-1984				
Eff: 11-Sep-1984 Complied With						Hrs					
						Enc					
TFE731-72-3288	**Modification to Provide Positive Retention of Engine Nameplate**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 11-Sep-1984						Hrs					
						Enc					
TFE731-72-3293 R1	**Repl Shim At Xfr Grbx/Tower Shaft Hsg Intfc**							T (A/R)		Recommended	
72 ENG1						Mos	15-Apr-1992				
Eff: 31-May-1985						Hrs					
						Enc					
TFE731-72-3293 R1	**Repl Shim At Xfr Grbx/Tower Shaft Hsg Intfc**							RE (-)		Recommended	
72 ENG2						Mos	12-Jan-1987				
Eff: 31-May-1985 Complied With						Hrs					
						Enc					
TFE731-72-3293 R1	**Repl Shim At Xfr Grbx/Tower Shaft Hsg Intfc**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 31-May-1985						Hrs					
						Enc					
TFE731-72-3298	**Replace/Rework Outer Transition Liner (Inactive For Further Accomplishment)**							RE (-)		Optional	
72 ENG1						Mos	05-Jan-1987				
Eff: 14-Jan-1985						Hrs					
						Enc					
TFE731-72-3298 R3	**Replace/Rework Outer Transition Liner (Inactive For Further Accomplishment)**							T (A/R)		Optional	
72 ENG1						Mos					
Eff: 12-Dec-2001						Hrs					
						Enc					
TFE731-72-3298 R3	**Replace/Rework Outer Transition Liner (Inactive For Further Accomplishment)**							RE (-)		Optional	
72 ENG2						Mos	12-Jan-1987				
Eff: 12-Dec-2001 Complied With						Hrs					
						Enc					
TFE731-72-3298 R3	**Replace/Rework Outer Transition Liner (Inactive For Further Accomplishment)**							T (A/R)		Optional	
72 ENG3						Mos					
Eff: 12-Dec-2001						Hrs					
						Enc					
TFE731-72-3299	**Replace/Rework 2Nd Stage LP Turbine Nozzle**							RE (-)		Recommended	
72 ENG1						Mos	05-Jan-1987				
Eff: 14-Jan-1985						Hrs					
						Enc					
TFE731-72-3299	**Replace/Rework 2Nd Stage LP Turbine Nozzle**							RE (-)		Recommended	
72 ENG2						Mos	02-Nov-1988				
Eff: 14-Jan-1985 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3299	**Replace/Rework 2Nd Stage LP Turbine Nozzle**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 14-Jan-1985						Hrs					
						Enc					
TFE731-72-3299 R3	**Replace/Rework 2Nd Stage LP Turbine Nozzle**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 13-Sep-1991						Hrs					
						Enc					
TFE731-72-3299 R3	**Replace/Rework 2Nd Stage LP Turbine Nozzle**							RE (-)		Recommended	
72 ENG2						Mos	14-Jan-2000				
Eff: 13-Sep-1991 Not Applicable						Hrs					
						Enc					
TFE731-72-3299 R3	**Replace/Rework 2Nd Stage LP Turbine Nozzle**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 13-Sep-1991						Hrs					
						Enc					
TFE731-72-3304	**Repl/Rewk Fan Disc Nut 3071981-1**							RE (-)			
72 ENG1						Mos	27-Dec-1997				
Eff: 24-May-1985 Complied With	THE SERVICE BULLETIN HAS BEEN INCORPORATED					Hrs					
						Enc					
TFE731-72-3304	**Repl/Rewk Fan Disc Nut 3071981-1**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 24-May-1985 Complied With						Hrs					
						Enc					
TFE731-72-3304	**Repl/Rewk Fan Disc Nut 3071981-1**							T (A/R)			
72 ENG3						Mos					
Eff: 24-May-1985						Hrs					
						Enc					
TFE731-72-3306	**Remove 1St Stage LP Turbine Disc Serial Number 2-18040-Xxxx**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 01-Feb-1985						Hrs					
						Enc					
TFE731-72-3306	**Remove 1St Stage LP Turbine Disc Serial Number 2-18040-Xxxx**							RE (-)		Recommended	
72 ENG2						Mos					
Eff: 01-Feb-1985 Not Applicable						Hrs					
						Enc					
TFE731-72-3306	**Remove 1St Stage LP Turbine Disc Serial Number 2-18040-Xxxx**							RE (-)		Recommended	
72 ENG3						Mos	28-Dec-1992				
Eff: 01-Feb-1985 Not Applicable						Hrs					
						Enc					
TFE731-72-3309	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG1						Mos	27-Nov-1989				
Not Applicable						Hrs					
						Enc					
TFE731-72-3309	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3309	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R1	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG1						Mos	05-Jan-1987				
Complied With						Hrs					
						Enc					
TFE731-72-3309 R1	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG2						Mos					
Complied With						Hrs					
						Enc					
TFE731-72-3309 R1	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG3						Mos	24-Dec-1986				
Complied With						Hrs					
						Enc					
TFE731-72-3309 R2	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R2	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R2	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R3	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R3	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R3	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R4	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R4	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3309 R4	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3309 R5	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							T (A/R)			
72 ENG1						Mos					
Eff: 20-Oct-2004						Hrs					
						Enc					
TFE731-72-3309 R5	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							T (A/R)			
72 ENG2						Mos					
Eff: 20-Oct-2004						Hrs					
						Enc					
TFE731-72-3309 R5	**Inspection and/or Repair/Replace Specific Indentified Turbine Interstage Transition Ducts**							T (A/R)			
72 ENG3						Mos					
Eff: 20-Oct-2004						Hrs					
						Enc					
TFE731-72-3322	**Permanently Plug CPRSR Intstg Diffuser Bs Port**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 20-Dec-1985						Hrs					
						Enc					
TFE731-72-3322	**Permanently Plug CPRSR Intstg Diffuser Bs Port**							RE (-)		Recommended	
72 ENG2						Mos	12-Jan-1987				
Eff: 20-Dec-1985 Complied With						Hrs					
						Enc					
TFE731-72-3322	**Permanently Plug CPRSR Intstg Diffuser Bs Port**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 20-Dec-1985						Hrs					
						Enc					
TFE731-72-3322 R1	**Permanently Plug CPRSR Intstg Diffuser Bs Port**							T (A/R)		Recommended	
72 ENG1						Mos	15-Apr-1992				
Eff: 04-Apr-1986						Hrs					
						Enc					
TFE731-72-3330	**Incorporation of Improved Cooling Air Scheme for LP Turbine Assy**							RE (-)		Recommended	
72 ENG1						Mos	25-Jan-1995				
Eff: 16-Jul-1986 Not Applicable						Hrs					
						Enc					
TFE731-72-3330	**Incorporation of Improved Cooling Air Scheme for LP Turbine Assy**							RE (-)		Recommended	
72 ENG2						Mos	16-Mar-1995				
Eff: 16-Jul-1986 Not Applicable	by S/N					Hrs					
						Enc					
TFE731-72-3330	**Incorporation of Improved Cooling Air Scheme for LP Turbine Assy**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 16-Jul-1986						Hrs					
						Enc					
TFE731-72-3346	**Weld Titanium Strips To Ends Of Vanes**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 03-Jul-1987 Complied With						Hrs					
						Enc					
TFE731-72-3346	**Weld Titanium Strips To Ends Of Vanes**							RE (-)			
72 ENG2						Mos					
Eff: 03-Jul-1987						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3346	**Weld Titanium Strips To Ends Of Vanes**							RE (-)			
72 ENG3						Mos	29-Aug-2006				
Eff: 03-Jul-1987 Complied With						Hrs					
						Enc					
TFE731-72-3346 R1	**Weld Titanium Strips To Ends Of Vanes**							T (A/R)			
72 ENG1						Mos					
Eff: 12-Jan-2007						Hrs					
						Enc					
TFE731-72-3346 R1	**Weld Titanium Strips To Ends Of Vanes**							T (A/R)			
72 ENG2						Mos					
Eff: 12-Jan-2007						Hrs					
						Enc					
TFE731-72-3346 R1	**Weld Titanium Strips To Ends Of Vanes**							T (A/R)			
72 ENG3						Mos					
Eff: 12-Jan-2007						Hrs					
						Enc					
TFE731-72-3357	**ENGINE COMPRESSOR SECTION - Replace Spring Tension Washer, Part No. 3000005-2 With Part No. 3000005-56 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	03-Nov-1988				
Eff: 03-Dec-1987						Hrs					
						Enc					
TFE731-72-3357 R1	**ENGINE COMPRESSOR SECTION - Replace Spring Tension Washer, Part No. 3000005-2 With Part No. 3000005-56 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
TFE731-72-3357 R1	**ENGINE COMPRESSOR SECTION - Replace Spring Tension Washer, Part No. 3000005-2 With Part No. 3000005-56 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	02-Nov-1988				
Eff: 18-Mar-1994 Complied With						Hrs					
						Enc					
TFE731-72-3357 R1	**ENGINE COMPRESSOR SECTION - Replace Spring Tension Washer, Part No. 3000005-2 With Part No. 3000005-56 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
TFE731-72-3361	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3361	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	16-Mar-1995				
Not Applicable by S/N						Hrs					
						Enc					
TFE731-72-3361	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3367	**Perform One Time Inspection of Nozzle Throat (A5) Opening for Proper Dimension**							RE (-)			
72 ENG1						Mos	03-Nov-1988				
Eff: 27-May-1988						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3367	**Perform One Time Inspection of Nozzle Throat (A5) Opening for Proper Dimension**							RE (-)			
72 ENG2						Mos	26-Oct-1990				
Eff: 27-May-1988 Complied With						Hrs					
						Enc					
TFE731-72-3367	**Perform One Time Inspection of Nozzle Throat (A5) Opening for Proper Dimension**							RE (-)			
72 ENG3						Mos					
Eff: 27-May-1988						Hrs					
						Enc					
TFE731-72-3367 R3	**Perform One Time Inspection of Nozzle Throat (A5) Opening for Proper Dimension**							RE (-)			
72 ENG1						Mos	09-Feb-1995				
Eff: 02-Sep-1994 Complied With						Hrs					
						Enc					
TFE731-72-3369RWK	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG1						Mos					
Eff: 27-Sep-1988						Hrs					
						Enc					
TFE731-72-3369RWK	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG2						Mos					
Eff: 27-Sep-1988						Hrs					
						Enc					
TFE731-72-3369RWK	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG3						Mos					
Eff: 27-Sep-1988						Hrs					
						Enc					
TFE731-72-3369RWK R1	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG1						Mos					
Eff: 13-Jul-1990						Hrs					
						Enc					
TFE731-72-3369RWK R1	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG2						Mos					
Eff: 13-Jul-1990						Hrs					
						Enc					
TFE731-72-3369RWK R1	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG3						Mos					
Eff: 13-Jul-1990						Hrs					
						Enc					
TFE731-72-3369RWK R2	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG1						Mos	09-Feb-1995				
Eff: 01-May-1992 Complied With						Hrs					
						Enc					
TFE731-72-3369RWK R2	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG2						Mos					
Eff: 01-May-1992						Hrs					
						Enc					
TFE731-72-3369RWK R2	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG3						Mos					
Eff: 01-May-1992						Hrs					
						Enc					
TFE731-72-3369RWK R3	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG1						Mos					
Eff: 28-Mar-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3369RWK R3	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG2						Mos					
Eff: 28-Mar-1997						Hrs					
						Enc					
TFE731-72-3369RWK R3	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG3						Mos					
Eff: 28-Mar-1997						Hrs					
						Enc					
TFE731-72-3369RWK R4	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG1						Mos					
Eff: 16-Sep-1997						Hrs					
						Enc					
TFE731-72-3369RWK R4	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG2						Mos					
Eff: 16-Sep-1997						Hrs					
						Enc					
TFE731-72-3369RWK R4	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG3						Mos					
Eff: 16-Sep-1997						Hrs					
						Enc					
TFE731-72-3369RWK R5	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG1						Mos					
Eff: 09-Aug-2001						Hrs					
						Enc					
TFE731-72-3369RWK R5	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG2						Mos					
Eff: 09-Aug-2001						Hrs					
						Enc					
TFE731-72-3369RWK R5	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG3						Mos					
Eff: 09-Aug-2001						Hrs					
						Enc					
TFE731-72-3369RWK R6	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							RE (-)			
72 ENG1						Mos	04-Jan-2023				
Eff: 26-Jun-2002 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-72-3369RWK R6	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							T (A/R)			
72 ENG2						Mos					
Eff: 26-Jun-2002						Hrs					
						Enc					
TFE731-72-3369RWK R6	**Engine - Turbine Section - Adjust Nozzle Throat (A5) Opening(S) Effective (Ae) Flow Area**							T (A/R)			
72 ENG3						Mos					
Eff: 26-Jun-2002						Hrs					
						Enc					
TFE731-72-3370	**Inspecte & Rework Turbine Interstage Transition Ducts**							RE (-)			
72 ENG1						Mos	02-Feb-1990				
Eff: 26-Jun-1989						Hrs					
						Enc					
TFE731-72-3370 R1	**Inspecte & Rework Turbine Interstage Transition Ducts**							T (A/R)			
72 ENG1						Mos					
Eff: 15-Jun-1990						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3370 R1	**Inspecte & Rework Turbine Interstage Transition Ducts**							RE (-)			
72 ENG2						Mos	19-Dec-1990				
Eff: 15-Jun-1990 Complied With						Hrs					
						Enc					
TFE731-72-3370 R1	**Inspecte & Rework Turbine Interstage Transition Ducts**							T (A/R)			
72 ENG3						Mos					
Eff: 15-Jun-1990						Hrs					
						Enc					
TFE731-72-3380	**Install Outer Transition Liner W/Tbc Applied**							T (A/R)		Recommended	
72 ENG1						Mos	20-Feb-1990				
Eff: 25-Aug-1989						Hrs					
						Enc					
TFE731-72-3380	**Install Outer Transition Liner W/Tbc Applied**							RE (-)		Recommended	
72 ENG2						Mos	19-Dec-1990				
Eff: 25-Aug-1989 Complied With						Hrs					
						Enc					
TFE731-72-3380	**Install Outer Transition Liner W/Tbc Applied**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 25-Aug-1989						Hrs					
						Enc					
TFE731-72-3384	**Replace Oil Diflector or Rework Existing Oil Diflector**							RE (-)			
72 ENG1						Mos					
Eff: 13-Jan-1989						Hrs					
						Enc					
TFE731-72-3384	**Replace Oil Diflector or Rework Existing Oil Diflector**							RE (-)			
72 ENG2						Mos					
Eff: 13-Jan-1989 Complied With						Hrs					
						Enc					
TFE731-72-3384	**Replace Oil Diflector or Rework Existing Oil Diflector**							RE (-)			
72 ENG3						Mos					
Eff: 13-Jan-1989 Complied With						Hrs					
						Enc					
TFE731-72-3384 R1	**Replace Oil Diflector or Rework Existing Oil Diflector**							RE (-)			
72 ENG1						Mos	27-Dec-1997				
Eff: 23-Nov-1994 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-72-3384 R1	**Replace Oil Diflector or Rework Existing Oil Diflector**							RE (-)			
72 ENG2						Mos					
Eff: 23-Nov-1994						Hrs					
						Enc					
TFE731-72-3384 R1	**Replace Oil Diflector or Rework Existing Oil Diflector**							RE (-)			
72 ENG3						Mos	03-Jun-1997				
Eff: 23-Nov-1994 Complied With						Hrs					
						Enc					
TFE731-72-3384 R2	**Replace Oil Diflector or Rework Existing Oil Diflector**							T (A/R)			
72 ENG1						Mos					
Eff: 06-Mar-2001						Hrs					
						Enc					
TFE731-72-3384 R2	**Replace Oil Diflector or Rework Existing Oil Diflector**							T (A/R)			
72 ENG2						Mos					
Eff: 06-Mar-2001						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3384 R2	**Replace Oil Diflector or Rework Existing Oil Diflector**							T (A/R)			
72 ENG3						Mos					
Eff: 06-Mar-2001						Hrs					
						Enc					
TFE731-72-3397	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG1						Mos					
Eff: 20-Oct-1989						Hrs					
						Enc					
TFE731-72-3397	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG2						Mos					
Eff: 20-Oct-1989						Hrs					
						Enc					
TFE731-72-3397	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG3						Mos					
Eff: 20-Oct-1989						Hrs					
						Enc					
TFE731-72-3397 R1	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG1						Mos					
Eff: 04-Jan-1991						Hrs					
						Enc					
TFE731-72-3397 R1	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG2						Mos					
Eff: 04-Jan-1991						Hrs					
						Enc					
TFE731-72-3397 R1	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG3						Mos					
Eff: 04-Jan-1991						Hrs					
						Enc					
TFE731-72-3397 R2	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG1						Mos	31-Mar-2006				
Eff: 21-Jun-1991 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3397 R2	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Eff: 21-Jun-1991 Complied With	PCW					Hrs					
						Enc					
TFE731-72-3397 R2	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG3						Mos	29-Aug-2006				
Eff: 21-Jun-1991 Complied With						Hrs					
						Enc					
TFE731-72-3397 R3	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG1						Mos					
Eff: 14-Sep-2010						Hrs					
						Enc					
TFE731-72-3397 R3	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG2						Mos					
Eff: 14-Sep-2010						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3397 R3	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							RE (-)			
72 ENG3						Mos					
Eff: 14-Sep-2010						Hrs					
						Enc					
TFE731-72-3397 R4	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							T (A/R)			
72 ENG1						Mos					
Eff: 14-Nov-2012						Hrs					
						Enc					
TFE731-72-3397 R4	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							T (A/R)			
72 ENG2						Mos					
Eff: 14-Nov-2012						Hrs					
						Enc					
TFE731-72-3397 R4	**ENGINE - GENERAL - Initiate Component Maintenance/Modification Record Card (CMMC)**							T (A/R)			
72 ENG3						Mos					
Eff: 14-Nov-2012						Hrs					
						Enc					
TFE731-72-3405	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Dec-1989						Hrs					
						Enc					
TFE731-72-3405	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 22-Dec-1989						Hrs					
						Enc					
TFE731-72-3405	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 22-Dec-1989						Hrs					
						Enc					
TFE731-72-3405 R1	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	31-Mar-2006				
Eff: 24-May-1991 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3405 R1	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 24-May-1991						Hrs					
						Enc					
TFE731-72-3405 R1	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 24-May-1991						Hrs					
						Enc					
TFE731-72-3405 R2	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 14-Jul-1995						Hrs					
						Enc					
TFE731-72-3405 R2	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	08-May-1996				
Eff: 14-Jul-1995 Complied With						Hrs					
						Enc					
TFE731-72-3405 R2	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos	23-Aug-1997				
Eff: 14-Jul-1995 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3405 R3	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 01-Feb-2002						Hrs					
						Enc					
TFE731-72-3405 R3	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 01-Feb-2002						Hrs					
						Enc					
TFE731-72-3405 R3	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 01-Feb-2002						Hrs					
						Enc					
TFE731-72-3405 R4	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 26-Nov-2002						Hrs					
						Enc					
TFE731-72-3405 R4	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 26-Nov-2002						Hrs					
						Enc					
TFE731-72-3405 R4	**Engine - Turbine Section - Install Improved Shroud Retaining Sleeve**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 26-Nov-2002						Hrs					
						Enc					
TFE731-72-3408	**Repl Spring Tension Washer 3000005-2/-56 W/-64**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 19-Feb-1990 Complied With						Hrs					
						Enc					
TFE731-72-3408	**Repl Spring Tension Washer 3000005-2/-56 W/-64**							RE (-)			
72 ENG2						Mos	28-Dec-1992				
Eff: 19-Feb-1990 Complied With						Hrs					
						Enc					
TFE731-72-3408	**Repl Spring Tension Washer 3000005-2/-56 W/-64**							T (A/R)			
72 ENG3						Mos					
Eff: 19-Feb-1990						Hrs					
						Enc					
TFE731-72-3409 R1	**Instl 1St Stg CPRSR Wheel Assy Blade Retainer**							T (A/R)		Recommended	
72 ENG1						Mos	15-Apr-1992				
Eff: 10-Aug-1990						Hrs					
						Enc					
TFE731-72-3409 R1	**Instl 1St Stg CPRSR Wheel Assy Blade Retainer**							RE (-)		Recommended	
72 ENG2						Mos	15-Mar-1995				
Eff: 10-Aug-1990 Complied With						Hrs					
						Enc					
TFE731-72-3409 R1	**Instl 1St Stg CPRSR Wheel Assy Blade Retainer**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 10-Aug-1990						Hrs					
						Enc					
TFE731-72-3410 R1	**Instl 2Nd Stg CPRSR Rtr Assy Blade Retainer**							T (A/R)		Recommended	
72 ENG1						Mos	15-Apr-1992				
Eff: 10-Aug-1990						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3410 R1	**Instl 2Nd Stg CPRSR Rtr Assy Blade Retainer**							RE (-)		Recommended	
72 ENG2						Mos	15-Mar-1995				
Eff: 10-Aug-1990 Complied With						Hrs					
						Enc					
TFE731-72-3410 R1	**Instl 2Nd Stg CPRSR Rtr Assy Blade Retainer**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 10-Aug-1990						Hrs					
						Enc					
TFE731-72-3411 R1	**Instl 3Rd Stg CPRSR Rtr Assy Blade Retainer**							T (A/R)		Recommended	
72 ENG1						Mos	15-Apr-1992				
Eff: 10-Aug-1990						Hrs					
						Enc					
TFE731-72-3411 R1	**Instl 3Rd Stg CPRSR Rtr Assy Blade Retainer**							RE (-)		Recommended	
72 ENG2						Mos	15-Mar-1995				
Eff: 10-Aug-1990 Complied With						Hrs					
						Enc					
TFE731-72-3411 R1	**Instl 3Rd Stg CPRSR Rtr Assy Blade Retainer**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 10-Aug-1990						Hrs					
						Enc					
TFE731-72-3413	**Instl Dr Valves & Tee Pl That Inc Lkwr Holes**							RE (-)		Category 3	
72 ENG1						Mos	27-Dec-1997				
Eff: 15-Jun-1990 Complied With						Hrs					
						Enc					
TFE731-72-3413	**Instl Dr Valves & Tee Pl That Inc Lkwr Holes**							RE (-)		Category 3	
72 ENG2						Mos	17-Apr-1997				
Eff: 15-Jun-1990 Complied With						Hrs					
						Enc					
TFE731-72-3413	**Instl Dr Valves & Tee Pl That Inc Lkwr Holes**							RE (-)		Category 3	
72 ENG3						Mos	03-Jun-1997				
Eff: 15-Jun-1990 Complied With						Hrs					
						Enc					
TFE731-72-3413 R1	**Instl Dr Valves & Tee Pl That Inc Lkwr Holes**							T (A/R)		Category 3	
72 ENG1						Mos					
Eff: 19-Jul-2006						Hrs					
						Enc					
TFE731-72-3413 R1	**Instl Dr Valves & Tee Pl That Inc Lkwr Holes**							T (A/R)		Category 3	
72 ENG2						Mos					
Eff: 19-Jul-2006						Hrs					
						Enc					
TFE731-72-3413 R1	**Instl Dr Valves & Tee Pl That Inc Lkwr Holes**							T (A/R)		Category 3	
72 ENG3						Mos					
Eff: 19-Jul-2006						Hrs					
						Enc					
TFE731-72-3416	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 07-Sep-1990						Hrs					
						Enc					
TFE731-72-3416	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 07-Sep-1990						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3416	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 07-Sep-1990						Hrs					
						Enc					
TFE731-72-3416 R1	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	15-May-1992				
Eff: 29-Mar-1991 Complied With						Hrs	4,353				
						Enc	2,613				
TFE731-72-3416 R1	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 29-Mar-1991						Hrs					
						Enc					
TFE731-72-3416 R1	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 29-Mar-1991						Hrs					
						Enc					
TFE731-72-3416 R2	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 19-Mar-1992						Hrs					
						Enc					
TFE731-72-3416 R2	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 19-Mar-1992						Hrs					
						Enc					
TFE731-72-3416 R2	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 19-Mar-1992						Hrs					
						Enc					
TFE731-72-3416 R3	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 18-Sep-1992						Hrs					
						Enc					
TFE731-72-3416 R3	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Mar-1995				
Eff: 18-Sep-1992 Complied With						Hrs					
						Enc					
TFE731-72-3416 R3	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 18-Sep-1992 Complied With						Hrs					
						Enc					
TFE731-72-3416 R4	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 27-Aug-1993						Hrs					
						Enc					
TFE731-72-3416 R4	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 27-Aug-1993						Hrs					
						Enc					
TFE731-72-3416 R4	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 27-Aug-1993						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3416 R5	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 21-Apr-1995						Hrs					
						Enc					
TFE731-72-3416 R5	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 21-Apr-1995						Hrs					
						Enc					
TFE731-72-3416 R5	**Instl HP Implr Shrd W/Improved Al Coating**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	12-Jul-1997				
Eff: 21-Apr-1995 Complied With						Hrs					
						Enc					
TFE731-72-3416 R6	**Instl HP Implr Shrd W/Improved Al Coating**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 22-Jan-2001						Hrs					
						Enc					
TFE731-72-3416 R6	**Instl HP Implr Shrd W/Improved Al Coating**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 22-Jan-2001						Hrs					
						Enc					
TFE731-72-3416 R6	**Instl HP Implr Shrd W/Improved Al Coating**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 22-Jan-2001						Hrs					
						Enc					
TFE731-72-3421	**Instl Lp Cprsr Brg Hsg 3071691-7 Or 3077043-3**							RE (-)			
72 ENG1						Mos	27-Dec-1997				
Eff: 24-May-1991 Complied With	THE SERVICE BULLETIN HAS BEEN INCORPORATED					Hrs					
						Enc					
TFE731-72-3421	**Instl Lp Cprsr Brg Hsg 3071691-7 Or 3077043-3**							RE (-)			
72 ENG2						Mos	17-Apr-1997				
Eff: 24-May-1991 Complied With						Hrs					
						Enc					
TFE731-72-3421	**Instl Lp Cprsr Brg Hsg 3071691-7 Or 3077043-3**							T (A/R)			
72 ENG3						Mos					
Eff: 24-May-1991						Hrs					
						Enc					
TFE731-72-3422	**Perform one Time Inspection of Pin Gear Retainer Plate Assy**							T (A/R)			
72 ENG1						Mos	15-Apr-1992				
Eff: 03-Jan-1991						Hrs					
						Enc					
TFE731-72-3422	**Perform one Time Inspection of Pin Gear Retainer Plate Assy**							RE (-)			
72 ENG2						Mos	15-Mar-1995				
Eff: 03-Jan-1991 Complied With						Hrs					
						Enc					
TFE731-72-3422	**Perform one Time Inspection of Pin Gear Retainer Plate Assy**							T (A/R)			
72 ENG3						Mos					
Eff: 03-Jan-1991						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3426	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							RE (-)			
72 ENG1						Mos	15-May-1992				
Eff: 13-Sep-1991 Complied With						Hrs	4,353				
						Enc	2,613				
TFE731-72-3426	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							RE (-)			
72 ENG2						Mos	15-Mar-1995				
Eff: 13-Sep-1991 Complied With	PCW					Hrs					
						Enc					
TFE731-72-3426	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							RE (-)			
72 ENG3						Mos	04-May-1995				
Eff: 13-Sep-1991 Complied With						Hrs					
						Enc					
TFE731-72-3426 R1	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							RE (-)			
72 ENG1						Mos					
Eff: 03-Feb-1994						Hrs					
						Enc					
TFE731-72-3426 R1	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							RE (-)			
72 ENG2						Mos					
Eff: 03-Feb-1994						Hrs					
						Enc					
TFE731-72-3426 R1	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							RE (-)			
72 ENG3						Mos					
Eff: 03-Feb-1994						Hrs					
						Enc					
TFE731-72-3426 R2	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							T (A/R)			
72 ENG1						Mos					
Eff: 08-May-1996						Hrs					
						Enc					
TFE731-72-3426 R2	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							T (A/R)			
72 ENG2						Mos					
Eff: 08-May-1996						Hrs					
						Enc					
TFE731-72-3426 R2	**Replacement/Rework 3Rd Stage LP Turbine Nozzle**							T (A/R)			
72 ENG3						Mos					
Eff: 08-May-1996						Hrs					
						Enc					
TFE731-72-3427	**Install HP Compressor Diffuser Inc Honeycomb Seal**							RE (-)		Recommended	
72 ENG1						Mos	15-Apr-1992				
Eff: 30-Apr-1991						Hrs					
						Enc					
TFE731-72-3427 R1	**Install HP Compressor Diffuser Inc Honeycomb Seal**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 01-May-1992						Hrs					
						Enc					
TFE731-72-3427 R1	**Install HP Compressor Diffuser Inc Honeycomb Seal**							RE (-)		Recommended	
72 ENG2						Mos	15-Mar-1995				
Eff: 01-May-1992 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3427 R1	**Install HP Compressor Diffuser Inc Honeycomb Seal**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 01-May-1992						Hrs					
						Enc					
TFE731-72-3429	**Replace LP Compressor Tie Bolt**							RE (-)			
72 ENG1						Mos					
Eff: 26-Apr-1991						Hrs					
						Enc					
TFE731-72-3429	**Replace LP Compressor Tie Bolt**							RE (-)			
72 ENG2						Mos	16-Mar-1995				
Eff: 26-Apr-1991 Not Applicable	by S/N					Hrs					
						Enc					
TFE731-72-3429	**Replace LP Compressor Tie Bolt**							RE (-)			
72 ENG3						Mos					
Eff: 26-Apr-1991						Hrs					
						Enc					
TFE731-72-3429 R1	**Replace LP Compressor Tie Bolt**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 03-Apr-1992 Not Applicable						Hrs					
						Enc					
TFE731-72-3443	**Engine - Compressor Rotor - Replacement of LP Compressor 2nd Stage (Static) Shroud**							RE (-)		Recommended	
72 ENG1						Mos	25-Jan-1995				
Eff: 06-Sep-1991 Not Applicable						Hrs					
						Enc					
TFE731-72-3443	**Engine - Compressor Rotor - Replacement of LP Compressor 2nd Stage (Static) Shroud**							RE (-)		Recommended	
72 ENG2						Mos	14-Jan-2000				
Eff: 06-Sep-1991 Not Applicable						Hrs					
						Enc					
TFE731-72-3443	**Engine - Compressor Rotor - Replacement of LP Compressor 2nd Stage (Static) Shroud**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 06-Sep-1991						Hrs					
						Enc					
TFE731-72-3449	**Instl Washers On Bolts That Secure Hp Shroud**							T (A/R)		Recommended	
72 ENG1						Mos	15-Apr-1992				
Eff: 07-Feb-1992						Hrs					
						Enc					
TFE731-72-3449	**Instl Washers On Bolts That Secure Hp Shroud**							RE (-)		Recommended	
72 ENG2						Mos	15-Mar-1995				
Eff: 07-Feb-1992 Complied With						Hrs					
						Enc					
TFE731-72-3449	**Instl Washers On Bolts That Secure Hp Shroud**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 07-Feb-1992						Hrs					
						Enc					
TFE731-72-3451	**Engine - Turbine Section - Replacement of Specific Serial Numbered LP Second Stage Turbine Rotor Disc, Pn3072542-5, Manufactured From The Same Billet**							RE (-)		Recommended	
72 ENG1						Mos	07-Jan-2002				
Eff: 14-Oct-1991 Not Applicable						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3451	**Engine - Turbine Section - Replacement of Specific Serial Numbered LP Second Stage Turbine Rotor Disc, Pn3072542-5, Manufactured From The Same Billet**							RE (-)		Recommended	
72 ENG2						Mos	13-Sep-2001				
Eff: 14-Oct-1991 Complied With						Hrs					
						Enc					
TFE731-72-3451	**Engine - Turbine Section - Replacement of Specific Serial Numbered LP Second Stage Turbine Rotor Disc, Pn3072542-5, Manufactured From The Same Billet**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 14-Oct-1991						Hrs					
						Enc					
TFE731-72-3453 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	15-Apr-1992				
						Hrs					
						Enc					
TFE731-72-3455	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 29-Oct-1991						Hrs					
						Enc					
TFE731-72-3455	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 29-Oct-1991						Hrs					
						Enc					
TFE731-72-3455	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 29-Oct-1991						Hrs					
						Enc					
TFE731-72-3455 R1	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 21-Aug-1992						Hrs					
						Enc					
TFE731-72-3455 R1	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 21-Aug-1992						Hrs					
						Enc					
TFE731-72-3455 R1	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 21-Aug-1992						Hrs					
						Enc					
TFE731-72-3455 R2	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 21-Jul-1993						Hrs					
						Enc					
TFE731-72-3455 R2	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Mar-1995				
Eff: 21-Jul-1993 Complied With						Hrs					
						Enc					
TFE731-72-3455 R2	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 21-Jul-1993						Hrs					
						Enc					
TFE731-72-3455 R3	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	27-Dec-1997				
Eff: 24-Sep-1996 Complied With						Hrs	8,120				
						Enc	4,955				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3455 R3	**Instl Packings & Seals On Oil Transfer Tube**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 24-Sep-1996						Hrs					
						Enc					
TFE731-72-3455 R3	**Instl Packings & Seals On Oil Transfer Tube**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	12-Jul-1997				
Eff: 24-Sep-1996 Complied With						Hrs					
						Enc					
TFE731-72-3458	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 10-Jan-1992						Hrs					
						Enc					
TFE731-72-3458	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos	15-Mar-1995				
Eff: 10-Jan-1992 Complied With						Hrs					
						Enc					
TFE731-72-3458	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos	04-May-1995				
Eff: 10-Jan-1992 Complied With						Hrs					
						Enc					
TFE731-72-3458 R1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 30-Nov-1992						Hrs					
						Enc					
TFE731-72-3458 R1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 30-Nov-1992						Hrs					
						Enc					
TFE731-72-3458 R1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 30-Nov-1992						Hrs					
						Enc					
TFE731-72-3458 R10	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 05-Feb-2004						Hrs					
						Enc					
TFE731-72-3458 R10	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 05-Feb-2004						Hrs					
						Enc					
TFE731-72-3458 R10	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 05-Feb-2004						Hrs					
						Enc					
TFE731-72-3458 R11	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos	31-Mar-2006				
Eff: 31-May-2005 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3458 R11	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos	31-Jul-2006				
Eff: 31-May-2005 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3458 R11	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos	29-Aug-2006				
Eff: 31-May-2005 Complied With						Hrs					
						Enc					
TFE731-72-3458 R12	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							T (A/R)		Informational	
72 ENG1						Mos					
Eff: 23-Jun-2008						Hrs					
						Enc					
TFE731-72-3458 R12	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							T (A/R)		Informational	
72 ENG2						Mos					
Eff: 23-Jun-2008						Hrs					
						Enc					
TFE731-72-3458 R12	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							T (A/R)		Informational	
72 ENG3						Mos					
Eff: 23-Jun-2008						Hrs					
						Enc					
TFE731-72-3458 R2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 21-Jun-1993						Hrs					
						Enc					
TFE731-72-3458 R2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 21-Jun-1993						Hrs					
						Enc					
TFE731-72-3458 R2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 21-Jun-1993						Hrs					
						Enc					
TFE731-72-3458 R3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 07-Dec-1994						Hrs					
						Enc					
TFE731-72-3458 R3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 07-Dec-1994						Hrs					
						Enc					
TFE731-72-3458 R3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 07-Dec-1994						Hrs					
						Enc					
TFE731-72-3458 R4	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 22-Mar-1996						Hrs					
						Enc					
TFE731-72-3458 R4	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 22-Mar-1996						Hrs					
						Enc					
TFE731-72-3458 R4	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 22-Mar-1996						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3458 R5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 13-Feb-1998						Hrs					
						Enc					
TFE731-72-3458 R5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 13-Feb-1998						Hrs					
						Enc					
TFE731-72-3458 R5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 13-Feb-1998						Hrs					
						Enc					
TFE731-72-3458 R6	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 19-Aug-1998						Hrs					
						Enc					
TFE731-72-3458 R6	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 19-Aug-1998						Hrs					
						Enc					
TFE731-72-3458 R6	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 19-Aug-1998						Hrs					
						Enc					
TFE731-72-3458 R7	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos	07-Jan-2002				
Eff: 09-Feb-2001 Complied With						Hrs					
						Enc					
TFE731-72-3458 R7	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos	10-Sep-2001				
Eff: 09-Feb-2001 Complied With						Hrs					
						Enc					
TFE731-72-3458 R7	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos	29-Oct-2001				
Eff: 09-Feb-2001 Complied With						Hrs					
						Enc					
TFE731-72-3458 R8	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 19-Nov-2002						Hrs					
						Enc					
TFE731-72-3458 R8	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 19-Nov-2002						Hrs					
						Enc					
TFE731-72-3458 R8	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 19-Nov-2002						Hrs					
						Enc					
TFE731-72-3458 R9	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 27-Aug-2003						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3458 R9	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 27-Aug-2003						Hrs					
						Enc					
TFE731-72-3458 R9	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 27-Aug-2003						Hrs					
						Enc					
TFE731-72-3458WA	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
Eff: 10-Jan-1992						Hrs					
						Enc					
TFE731-72-3458WA	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
Eff: 10-Jan-1992						Hrs					
						Enc					
TFE731-72-3458WA	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG3						Mos					
Eff: 10-Jan-1992						Hrs					
						Enc					
TFE731-72-3458WA R1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R1	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R10	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R10	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R10	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R11	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							T (A/R)			
72 ENG1						Mos					
Eff: 23-Jun-2008						Hrs					
						Enc					
TFE731-72-3458WA R11	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							T (A/R)			
72 ENG2						Mos					
Eff: 23-Jun-2008						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3458WA R11	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							T (A/R)			
72 ENG3						Mos					
Eff: 23-Jun-2008						Hrs					
						Enc					
TFE731-72-3458WA R12	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)		Informational	
72 ENG1						Mos	04-Jan-2023				
Eff: 23-Jun-2008 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-72-3458WA R12	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							T (A/R)		Informational	
72 ENG2						Mos					
Eff: 23-Jun-2008						Hrs					
						Enc					
TFE731-72-3458WA R12	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							T (A/R)		Informational	
72 ENG3						Mos					
Eff: 23-Jun-2008						Hrs					
						Enc					
TFE731-72-3458WA R2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R2	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R3	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R4	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R4	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R4	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3458WA R5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R6	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R6	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R6	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R7	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R7	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R7	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R8	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R8	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R8	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-72-3458WA R9	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3458WA R9	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3458WA R9	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions For Fan Disc Dovetail Slots**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3469 Rev1	**REPL NO. 3 CARBON FACE SEAL & SEAL ROTOR (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 01-Apr-1992						Hrs					
						Enc					
TFE731-72-3469 Rev1	**REPL NO. 3 CARBON FACE SEAL & SEAL ROTOR (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos					
Eff: 01-Apr-1992 Complied With						Hrs					
						Enc					
TFE731-72-3469 Rev1	**REPL NO. 3 CARBON FACE SEAL & SEAL ROTOR (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 01-Apr-1992 Complied With						Hrs					
						Enc					
TFE731-72-3469 Rev2	**REPL NO. 3 CARBON FACE SEAL & SEAL ROTOR (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 23-Apr-1992 Complied With						Hrs					
						Enc					
TFE731-72-3469 Rev3	**REPL NO. 3 CARBON FACE SEAL & SEAL ROTOR (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
Eff: 14-Sep-2001						Hrs					
						Enc					
TFE731-72-3469 Rev3	**REPL NO. 3 CARBON FACE SEAL & SEAL ROTOR (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos					
Eff: 14-Sep-2001						Hrs					
						Enc					
TFE731-72-3469 Rev3	**REPL NO. 3 CARBON FACE SEAL & SEAL ROTOR (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
Eff: 14-Sep-2001						Hrs					
						Enc					
TFE731-72-3471 R1	**Replace Support & Seal Assy In HP Turbine Nozzle Assy**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 21-Aug-1992						Hrs					
						Enc					
TFE731-72-3471 R1	**Replace Support & Seal Assy In HP Turbine Nozzle Assy**							RE (-)		Recommended	
72 ENG2						Mos	15-Mar-1995				
Eff: 21-Aug-1992 Complied With						Hrs					
						Enc					
TFE731-72-3471 R1	**Replace Support & Seal Assy In HP Turbine Nozzle Assy**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 21-Aug-1992						Hrs					
						Enc					
TFE731-72-3471 R2	**Replace Support & Seal Assy In HP Turbine Nozzle Assy**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1995				
Eff: 02-Sep-1994 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3473	**Additional Soap Sampling Requirement**							RE (-)			
72 ENG1						Mos	25-Jan-1995				
Eff: 03-Apr-1992 Not Applicable						Hrs					
						Enc					
TFE731-72-3473	**Additional Soap Sampling Requirement**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Eff: 03-Apr-1992 Not Applicable						Hrs					
						Enc					
TFE731-72-3473	**Additional Soap Sampling Requirement**							T (A/R)			
72 ENG3						Mos					
Eff: 03-Apr-1992						Hrs					
						Enc					
TFE731-72-3475	**ENGINE - BY-PASS SECTION - Replace No. 1 Carbon Face Seal And Seal Rotor.(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 08-Jan-1993 Complied With						Hrs					
						Enc					
TFE731-72-3475	**ENGINE - BY-PASS SECTION - Replace No. 1 Carbon Face Seal And Seal Rotor.(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos	15-Mar-1995				
Eff: 08-Jan-1993 Complied With						Hrs					
						Enc					
TFE731-72-3475	**ENGINE - BY-PASS SECTION - Replace No. 1 Carbon Face Seal And Seal Rotor.(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos	14-Jan-2000				
Eff: 08-Jan-1993 Not Applicable						Hrs					
						Enc					
TFE731-72-3475 R1	**ENGINE - BY-PASS SECTION - Replace No. 1 Carbon Face Seal And Seal Rotor.(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3475 R1	**ENGINE - BY-PASS SECTION - Replace No. 1 Carbon Face Seal And Seal Rotor.(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3475 R1	**ENGINE - BY-PASS SECTION - Replace No. 1 Carbon Face Seal And Seal Rotor.(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3476	**Instl Hp Turb Piston Ring Seal 3000002-10**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 08-May-1992						Hrs					
						Enc					
TFE731-72-3476	**Instl Hp Turb Piston Ring Seal 3000002-10**							RE (-)		Recommended	
72 ENG2						Mos	28-Jan-1994				
Eff: 08-May-1992 Complied With						Hrs					
						Enc					
TFE731-72-3476	**Instl Hp Turb Piston Ring Seal 3000002-10**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 08-May-1992						Hrs					
						Enc					
TFE731-72-3476 R1	**Instl Hp Turb Piston Ring Seal 3000002-10**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1995				
Eff: 16-Oct-1992 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3477	**Repl Accessory Drive Gearbox Gasket**							RE (-)		Optional	
72 ENG1						Mos	27-Dec-1997				
Eff: 08-Apr-1992 Complied With	THE SERVICE BULLETIN HAS BEEN INCORPORATED					Hrs					
						Enc					
TFE731-72-3482	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	24-Jan-1995				
Eff: 28-Sep-1992 Complied With						Hrs	5,818				
						Enc	3,562				
TFE731-72-3482	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Mar-1995				
Eff: 28-Sep-1992 Complied With						Hrs					
						Enc					
TFE731-72-3482	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	04-May-1995				
Eff: 28-Sep-1992 Complied With						Hrs					
						Enc					
TFE731-72-3482 R1	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 16-Jul-1993						Hrs					
						Enc					
TFE731-72-3482 R1	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 16-Jul-1993						Hrs					
						Enc					
TFE731-72-3482 R1	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 16-Jul-1993						Hrs					
						Enc					
TFE731-72-3482 R2	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 17-Dec-1993						Hrs					
						Enc					
TFE731-72-3482 R2	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 17-Dec-1993						Hrs					
						Enc					
TFE731-72-3482 R2	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 17-Dec-1993						Hrs					
						Enc					
TFE731-72-3482 R3	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 06-May-1994						Hrs					
						Enc					
TFE731-72-3482 R3	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 06-May-1994						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3482 R3	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG3					Mos					
Eff: 06-May-1994					Hrs					
					Enc					
TFE731-72-3482 R4	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 02-Jul-1994					Hrs					
					Enc					
TFE731-72-3482 R4	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 02-Jul-1994					Hrs					
					Enc					
TFE731-72-3482 R4	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG3					Mos					
Eff: 02-Jul-1994					Hrs					
					Enc					
TFE731-72-3482 R5	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 05-Jun-1997					Hrs					
					Enc					
TFE731-72-3482 R5	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 05-Jun-1997					Hrs					
					Enc					
TFE731-72-3482 R5	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG3					Mos					
Eff: 05-Jun-1997					Hrs					
					Enc					
TFE731-72-3482 R6	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 25-Aug-1998					Hrs					
					Enc					
TFE731-72-3482 R6	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 25-Aug-1998					Hrs					
					Enc					
TFE731-72-3482 R6	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						RE (-)		Cat.2-Reliability	
72 ENG3					Mos					
Eff: 25-Aug-1998					Hrs					
					Enc					
TFE731-72-3482 R7	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						T (A/R)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 24-Jun-2003					Hrs					
					Enc					
TFE731-72-3482 R7	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						T (A/R)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 24-Jun-2003					Hrs					
					Enc					
TFE731-72-3482 R7	**Install LP Turbine 3rd Stage Rotor Assy P/N 3072848-1/-2/-3/-4 OR 3074097-1, and Associated Parts**						T (A/R)		Cat.2-Reliability	
72 ENG3					Mos					
Eff: 24-Jun-2003					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3483 R1	**Install LP Compressor 4Th Stage Stator**							RE (-)		Category 2	
72 ENG1						Mos	09-Feb-1995				
Eff: 07-May-1993 Complied With						Hrs					
						Enc					
TFE731-72-3483 R1	**Install LP Compressor 4Th Stage Stator**							RE (-)		Category 2	
72 ENG2						Mos	15-Mar-1995				
Eff: 07-May-1993 Complied With						Hrs					
						Enc					
TFE731-72-3483 R1	**Install LP Compressor 4Th Stage Stator**							RE (-)		Category 2	
72 ENG3						Mos					
Eff: 07-May-1993						Hrs					
						Enc					
TFE731-72-3485RWK	**Engine - Compressor Section - Inspect/Rework HP Compressor Diffuser Mounting Bolt Holes As Required**							T (A/R)		Service Bulletin	
72 ENG1						Mos					
Eff: 24-Jul-1992						Hrs					
						Enc					
TFE731-72-3485RWK	**Engine - Compressor Section - Inspect/Rework HP Compressor Diffuser Mounting Bolt Holes As Required**							T (A/R)		Service Bulletin	
72 ENG2						Mos					
Eff: 24-Jul-1992						Hrs					
						Enc					
TFE731-72-3485RWK	**Engine - Compressor Section - Inspect/Rework HP Compressor Diffuser Mounting Bolt Holes As Required**							T (A/R)		Service Bulletin	
72 ENG3						Mos					
Eff: 24-Jul-1992						Hrs					
						Enc					
TFE731-72-3487	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 13-May-1994						Hrs					
						Enc					
TFE731-72-3487	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	11-Apr-1996				
Eff: 13-May-1994 Complied With						Hrs					
						Enc					
TFE731-72-3487	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	09-Apr-1996				
Eff: 13-May-1994 Complied With						Hrs					
						Enc					
TFE731-72-3487 R1	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 02-Dec-1994						Hrs					
						Enc					
TFE731-72-3487 R1	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Mar-1995				
Eff: 02-Dec-1994 Complied With						Hrs					
						Enc					
TFE731-72-3487 R1	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	12-Apr-1996				
Eff: 02-Dec-1994 Complied With						Hrs					
						Enc					
TFE731-72-3487 R2	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	07-Jan-2002				
Eff: 23-Jan-1997 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3487 R2	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	13-Sep-2001				
Eff: 23-Jan-1997 Complied With						Hrs					
						Enc					
TFE731-72-3487 R2	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Oct-2001				
Eff: 23-Jan-1997 Complied With						Hrs					
						Enc					
TFE731-72-3487 R3	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	04-Jan-2023				
Eff: 20-Jun-2003 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-72-3487 R3	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Eff: 20-Jun-2003 Complied With						Hrs					
						Enc					
TFE731-72-3487 R3	**Inspect/Rework Fan Blade**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 20-Jun-2003 Complied With						Hrs					
						Enc					
TFE731-72-3488	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 18-Sep-1992						Hrs					
						Enc					
TFE731-72-3488	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 18-Sep-1992						Hrs					
						Enc					
TFE731-72-3488	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 18-Sep-1992						Hrs					
						Enc					
TFE731-72-3488 R1	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 01-Nov-1994						Hrs					
						Enc					
TFE731-72-3488 R1	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 01-Nov-1994						Hrs					
						Enc					
TFE731-72-3488 R1	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 01-Nov-1994						Hrs					
						Enc					
TFE731-72-3488 R2	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 25-Jan-1996						Hrs					
						Enc					
TFE731-72-3488 R2	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 25-Jan-1996						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3488 R2	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 25-Jan-1996						Hrs					
						Enc					
TFE731-72-3488 R3	**Provide Different P/N HP Turb Shroud Segments**							RE (-)		Informational	
72 ENG1						Mos	31-Mar-2006				
Eff: 02-Oct-1998 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3488 R3	**Provide Different P/N HP Turb Shroud Segments**							T (A/R)		Informational	
72 ENG2						Mos					
Eff: 02-Oct-1998						Hrs					
						Enc					
TFE731-72-3488 R3	**Provide Different P/N HP Turb Shroud Segments**							T (A/R)		Informational	
72 ENG3						Mos					
Eff: 02-Oct-1998						Hrs					
						Enc					
TFE731-72-3492	**Install O-Ring Packing Between Spinner Supprt & Fan Blades**							RE (-)			
72 ENG1						Mos	09-Apr-1996				
Eff: 30-Jul-1993 Complied With						Hrs					
						Enc					
TFE731-72-3492	**Install O-Ring Packing Between Spinner Supprt & Fan Blades**							RE (-)			
72 ENG2						Mos	08-Apr-1996				
Eff: 30-Jul-1993 Complied With						Hrs					
						Enc					
TFE731-72-3492	**Install O-Ring Packing Between Spinner Supprt & Fan Blades**							RE (-)			
72 ENG3						Mos	30-Jul-1993				
Eff: 30-Jul-1993 Complied With						Hrs					
						Enc					
TFE731-72-3494	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	15-Mar-1995				
Complied With						Hrs					
						Enc					
TFE731-72-3494	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	04-May-1995				
Complied With						Hrs					
						Enc					
TFE731-72-3494 R1	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R1	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R1	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3494 R10	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R10	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R10	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R11	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R11	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R11	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R12	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							T (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 24-Sep-2013						Hrs					
						Enc					
TFE731-72-3494 R12	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							T (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 24-Sep-2013						Hrs					
						Enc					
TFE731-72-3494 R12	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							T (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 24-Sep-2013						Hrs					
						Enc					
TFE731-72-3494 R13	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE		Category 2	**≈22-Apr-2030**
72 ENG1						Mos	04-Jan-2023				
Complied With						Hrs	13,282.8	2,100		15,382.8	1,855.7 Hrs
(AVG MAN HRS: 3)						Enc	7,730				
TFE731-72-3494 R13	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 06-Aug-2015						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-3494 R13	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Category 2	
72 ENG3						Mos					
Eff: 06-Aug-2015						Hrs					
(AVG MAN HRS: 3)						Enc					
TFE731-72-3494 R2	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3494 R2	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	08-May-1996				
Complied With						Hrs					
						Enc					
TFE731-72-3494 R2	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	03-Jun-1997				
Complied With						Hrs					
						Enc					
TFE731-72-3494 R3	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R3	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R3	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R4	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	07-Jan-2002				
Complied With						Hrs					
						Enc					
TFE731-72-3494 R4	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	13-Sep-2001				
Complied With						Hrs					
						Enc					
TFE731-72-3494 R4	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Oct-2001				
Complied With						Hrs					
						Enc					
TFE731-72-3494 R5	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R5	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R5	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R6	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R6	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3494 R6	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R7	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R7	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R7	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R8	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	31-Mar-2006				
Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3494 R8	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Complied With						Hrs					
						Enc					
TFE731-72-3494 R8	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Complied With						Hrs					
						Enc					
TFE731-72-3494 R9	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R9	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3494 R9	**High Pressure (HP) And Low Pressure (LP) Turbine Blade Hour Tracking And Turbine Blade Life Limits**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3497	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 13-Nov-1992						Hrs					
						Enc					
TFE731-72-3497	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG2						Mos					
Eff: 13-Nov-1992						Hrs					
						Enc					
TFE731-72-3497	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 13-Nov-1992						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3497 R1	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 31-Mar-1995						Hrs					
						Enc					
TFE731-72-3497 R1	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG2						Mos					
Eff: 31-Mar-1995						Hrs					
						Enc					
TFE731-72-3497 R1	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 31-Mar-1995						Hrs					
						Enc					
TFE731-72-3497 R2	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG1						Mos	27-Dec-1997				
Eff: 09-Dec-1996 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-72-3497 R2	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG2						Mos	14-Jan-2000				
Eff: 09-Dec-1996 Complied With	PCW					Hrs					
						Enc					
TFE731-72-3497 R2	**Engine - Compressor Section - Install LP Compressor 4th Stage Stator**							RE (-)		Recommended	
72 ENG3						Mos	23-Aug-1997				
Eff: 09-Dec-1996 Complied With						Hrs					
						Enc					
TFE731-72-3498	**Install Fan Shaft & Ring Gear With New Retaining Ring**							RE (-)			
72 ENG1						Mos					
Eff: 22-Jan-1993						Hrs					
						Enc					
TFE731-72-3498	**Install Fan Shaft & Ring Gear With New Retaining Ring**							RE (-)			
72 ENG2						Mos	28-Jan-1994				
Eff: 22-Jan-1993 Complied With						Hrs					
						Enc					
TFE731-72-3498	**Install Fan Shaft & Ring Gear With New Retaining Ring**							RE (-)			
72 ENG3						Mos					
Eff: 22-Jan-1993						Hrs					
						Enc					
TFE731-72-3498 R1	**Install Fan Shaft & Ring Gear With New Retaining Ring**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 07-May-1993 Complied With						Hrs					
						Enc					
TFE731-72-3499 R2	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG1						Mos					
Eff: 12-Mar-1993						Hrs					
						Enc					
TFE731-72-3499 R2	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG2						Mos					
Eff: 12-Mar-1993						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3499 R2	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG3						Mos					
Eff: 12-Mar-1993						Hrs					
						Enc					
TFE731-72-3499 R5	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG1						Mos	20-May-1997				
Eff: 17-Aug-1993 Complied With						Hrs					
						Enc					
TFE731-72-3499 R5	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Eff: 17-Aug-1993 Not Applicable						Hrs					
						Enc					
TFE731-72-3499 R5	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG3						Mos					
Eff: 17-Aug-1993						Hrs					
						Enc					
TFE731-72-3499 R6	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3499 R6	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3499 R6	**ENGINE - BY-PASS SECTION - Install Component Parts to Prevent Oil Leakage in the No. 1 Oil Seal Region (Inactive for Further Accomplishment)**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3502	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG1						Mos	28-Dec-1992				
Eff: 25-Nov-1992 Complied With						Hrs					
						Enc					
TFE731-72-3502	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG2						Mos					
Eff: 25-Nov-1992 Complied With						Hrs					
						Enc					
TFE731-72-3502	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG3						Mos	28-Dec-1992				
Eff: 25-Nov-1992 Complied With						Hrs					
						Enc					
TFE731-72-3502 R1	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG1						Mos					
Eff: 21-Dec-1992						Hrs					
						Enc					
TFE731-72-3502 R1	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG2						Mos	20-Feb-1993				
Eff: 21-Dec-1992 Complied With						Hrs					
						Enc					
TFE731-72-3502 R1	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG3						Mos					
Eff: 21-Dec-1992						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3502 R2	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG1						Mos					
Eff: 15-Mar-1993						Hrs					
						Enc					
TFE731-72-3502 R2	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG2						Mos					
Eff: 15-Mar-1993						Hrs					
						Enc					
TFE731-72-3502 R2	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG3						Mos					
Eff: 15-Mar-1993						Hrs					
						Enc					
TFE731-72-3502 R3	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG1						Mos					
Eff: 01-Feb-2002						Hrs					
						Enc					
TFE731-72-3502 R3	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG2						Mos					
Eff: 01-Feb-2002						Hrs					
						Enc					
TFE731-72-3502 R3	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							RE (-)			
72 ENG3						Mos					
Eff: 01-Feb-2002						Hrs					
						Enc					
TFE731-72-3502 R4	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							T (A/R)			
72 ENG1						Mos					
Eff: 10-Jun-2003						Hrs					
						Enc					
TFE731-72-3502 R4	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							T (A/R)			
72 ENG2						Mos					
Eff: 10-Jun-2003						Hrs					
						Enc					
TFE731-72-3502 R4	**Install/Rework LP 1St Stg Turbine Nozzle W/Air Seal Assy**							T (A/R)			
72 ENG3						Mos					
Eff: 10-Jun-2003						Hrs					
						Enc					
TFE731-72-3507 R1	**Rework Fan Shaft Housing 3072160-1/-2 To 3077082-1/-2**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3507 R1	**Rework Fan Shaft Housing 3072160-1/-2 To 3077082-1/-2**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
TFE731-72-3507 R1	**Rework Fan Shaft Housing 3072160-1/-2 To 3077082-1/-2**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3507RWK Rev 1	**Engine - By-Pass Section - Rework Fan Support Housing Assembly Pn 3072160-X**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Eff: 07-Jun-1994 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3510 R1	**Rework 4th LPC Rotor Assy/Shaft**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3510 R1	**Rework 4th LPC Rotor Assy/Shaft**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
TFE731-72-3510 R1	**Rework 4th LPC Rotor Assy/Shaft**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3510RWK R01	**Engine-Compressor Sec-Rework Lp Compressor 4Th Stage Rotor Assembly Shouldered Shaft**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Complied With						Hrs					
						Enc					
TFE731-72-3511RWK	**Engine-Turbine Sec-Rework Lp Turbine Shaft Coupling Half**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Complied With						Hrs					
						Enc					
TFE731-72-3512RWK	**Engine-Turbine Sec-Rework Lp Turbine Assembly Tie Shaft To 3072780-2**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Complied With						Hrs					
						Enc					
TFE731-72-3520	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG1						Mos					
Eff: 07-May-1993						Hrs					
						Enc					
TFE731-72-3520	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG2						Mos					
Eff: 07-May-1993						Hrs					
						Enc					
TFE731-72-3520	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG3						Mos					
Eff: 07-May-1993						Hrs					
						Enc					
TFE731-72-3520 R1	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG1						Mos					
Eff: 17-Jun-1993						Hrs					
						Enc					
TFE731-72-3520 R1	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG2						Mos					
Eff: 17-Jun-1993						Hrs					
						Enc					
TFE731-72-3520 R1	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG3						Mos					
Eff: 17-Jun-1993						Hrs					
						Enc					
TFE731-72-3520 R2	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG1						Mos					
Eff: 17-Aug-1998						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3520 R2	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG2						Mos					
Eff: 17-Aug-1998						Hrs					
						Enc					
TFE731-72-3520 R2	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG3						Mos					
Eff: 17-Aug-1998						Hrs					
						Enc					
TFE731-72-3520 R3	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Eff: 15-Oct-1999 Complied With						Hrs	9,093				
						Enc	5,486				
TFE731-72-3520 R3	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Eff: 15-Oct-1999 Complied With	PCW					Hrs					
						Enc					
TFE731-72-3520 R3	**Install LP 3Rd Stage Turbine Rotor Assy Incorporating a Newly Designed Seal Rotor**							T (A/R)			
72 ENG3						Mos					
Eff: 15-Oct-1999						Hrs					
						Enc					
TFE731-72-3523	**Instl LP 4Th Stg CPRSR Rtr Assy**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 27-Mar-1993						Hrs					
						Enc					
TFE731-72-3523	**Instl LP 4Th Stg CPRSR Rtr Assy**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 27-Mar-1993						Hrs					
						Enc					
TFE731-72-3523	**Instl LP 4Th Stg CPRSR Rtr Assy**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 27-Mar-1993						Hrs					
						Enc					
TFE731-72-3523 R1	**Instl LP 4Th Stg CPRSR Rtr Assy**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 25-Feb-1995						Hrs					
						Enc					
TFE731-72-3523 R1	**Instl LP 4Th Stg CPRSR Rtr Assy**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 25-Feb-1995						Hrs					
						Enc					
TFE731-72-3523 R1	**Instl LP 4Th Stg CPRSR Rtr Assy**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 25-Feb-1995						Hrs					
						Enc					
TFE731-72-3523 R2	**Instl LP 4Th Stg CPRSR Rtr Assy**							T (A/R)		Category 3	
72 ENG1						Mos					
Eff: 17-Jun-2003						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3523 R2	**Instl LP 4Th Stg CPRSR Rtr Assy**							T (A/R)		Category 3	
72 ENG2						Mos					
Eff: 17-Jun-2003						Hrs					
						Enc					
TFE731-72-3523 R2	**Instl LP 4Th Stg CPRSR Rtr Assy**							T (A/R)		Category 3	
72 ENG3						Mos					
Eff: 17-Jun-2003						Hrs					
						Enc					
TFE731-72-3524	**Instl Retaining (Damper) Ring 3072463-2**							RE (-)			
72 ENG1						Mos	04-Jan-2023				
Eff: 04-Jun-1993 Complied With						Hrs					
						Enc					
TFE731-72-3524	**Instl Retaining (Damper) Ring 3072463-2**							RE (-)			
72 ENG2						Mos	15-Mar-1995				
Eff: 04-Jun-1993 Complied With						Hrs					
						Enc					
TFE731-72-3524	**Instl Retaining (Damper) Ring 3072463-2**							T (A/R)			
72 ENG3						Mos					
Eff: 04-Jun-1993						Hrs					
						Enc					
TFE731-72-3527	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG1						Mos					
Eff: 09-Jun-1993						Hrs					
						Enc					
TFE731-72-3527	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG2						Mos					
Eff: 09-Jun-1993						Hrs					
						Enc					
TFE731-72-3527	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG3						Mos					
Eff: 09-Jun-1993						Hrs					
						Enc					
TFE731-72-3527 R1	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG1						Mos					
Eff: 02-Dec-1994						Hrs					
						Enc					
TFE731-72-3527 R1	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG2						Mos					
Eff: 02-Dec-1994						Hrs					
						Enc					
TFE731-72-3527 R1	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG3						Mos					
Eff: 02-Dec-1994						Hrs					
						Enc					
TFE731-72-3527 R2	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG1						Mos	27-Dec-1997				
Eff: 12-Jun-1997 Complied With						Hrs					
						Enc					
TFE731-72-3527 R2	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG2						Mos					
Eff: 12-Jun-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3527 R2	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG3						Mos					
Eff: 12-Jun-1997						Hrs					
						Enc					
TFE731-72-3527 R3	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG1						Mos	07-Jan-2002				
Eff: 18-May-2001 Complied With						Hrs	9,831				
						Enc	5,855				
TFE731-72-3527 R3	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG2						Mos	13-Sep-2001				
Eff: 18-May-2001 Complied With						Hrs					
						Enc					
TFE731-72-3527 R3	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG3						Mos	29-Oct-2001				
Eff: 18-May-2001 Complied With						Hrs					
						Enc					
TFE731-72-3527 R4	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG1						Mos	04-Jan-2023				
Eff: 18-Mar-2005 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-72-3527 R4	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG2						Mos	22-Aug-2006				
Eff: 18-Mar-2005 Complied With						Hrs					
						Enc					
TFE731-72-3527 R4	**Establishing Periodic Inspection Intervals**							RE (-)			
72 ENG3						Mos	29-Aug-2006				
Eff: 18-Mar-2005 Complied With						Hrs					
						Enc					
TFE731-72-3529	**Redesigned Fan Disc**							RE (-)			
72 ENG1						Mos	08-Apr-1996				
Eff: 30-Jul-1993 Complied With						Hrs	6,767				
						Enc	4,134				
TFE731-72-3529	**Redesigned Fan Disc**							RE (-)			
72 ENG2						Mos					
Eff: 30-Jul-1993						Hrs					
						Enc					
TFE731-72-3529	**Redesigned Fan Disc**							RE (-)			
72 ENG3						Mos					
Eff: 30-Jul-1993						Hrs					
						Enc					
TFE731-72-3529 R1	**Redesigned Fan Disc**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Eff: 13-Apr-1995 Complied With	PCW					Hrs					
						Enc					
TFE731-72-3529 R1	**Redesigned Fan Disc**							RE (-)			
72 ENG2						Mos	11-Apr-1996				
Eff: 13-Apr-1995 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3529 R1	**Redesigned Fan Disc**							RE (-)			
72 ENG3						Mos	12-Apr-1996				
Eff: 13-Apr-1995 Complied With						Hrs					
						Enc					
TFE731-72-3529 R2	**Redesigned Fan Disc**							T (A/R)			
72 ENG1						Mos					
Eff: 25-Oct-2000						Hrs					
						Enc					
TFE731-72-3529 R2	**Redesigned Fan Disc**							T (A/R)			
72 ENG2						Mos					
Eff: 25-Oct-2000						Hrs					
						Enc					
TFE731-72-3529 R2	**Redesigned Fan Disc**							T (A/R)			
72 ENG3						Mos					
Eff: 25-Oct-2000						Hrs					
						Enc					
TFE731-72-3530	**Install LP 2nd Stage Turbine Nozzle that Incorporate a Honeycomb Air Seal**							RE (-)			
72 ENG1						Mos					
Eff: 09-Jul-1993						Hrs					
						Enc					
TFE731-72-3530	**Install LP 2nd Stage Turbine Nozzle that Incorporate a Honeycomb Air Seal**							RE (-)			
72 ENG2						Mos	28-Jan-1994				
Eff: 09-Jul-1993 Complied With						Hrs					
						Enc					
TFE731-72-3530	**Install LP 2nd Stage Turbine Nozzle that Incorporate a Honeycomb Air Seal**							RE (-)			
72 ENG3						Mos					
Eff: 09-Jul-1993						Hrs					
						Enc					
TFE731-72-3530 R1	**Install LP 2nd Stage Turbine Nozzle that Incorporate a Honeycomb Air Seal**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 08-Oct-1993 Complied With						Hrs					
						Enc					
TFE731-72-3531	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG1						Mos	09-Apr-1996				
Eff: 01-Mar-1994 Complied With						Hrs	6,748				
						Enc	4,123				
TFE731-72-3531	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG2						Mos	11-Apr-1996				
Eff: 01-Mar-1994 Complied With						Hrs					
						Enc					
TFE731-72-3531	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG3						Mos	12-Apr-1996				
Eff: 01-Mar-1994 Complied With						Hrs					
						Enc					
TFE731-72-3531 R1	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG1						Mos					
Eff: 25-Mar-1997						Hrs					
						Enc					
TFE731-72-3531 R1	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG2						Mos					
Eff: 25-Mar-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3531 R1	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG3						Mos					
Eff: 25-Mar-1997						Hrs					
						Enc					
TFE731-72-3531 R2	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG1						Mos					
Eff: 03-Mar-1999						Hrs					
						Enc					
TFE731-72-3531 R2	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG2						Mos					
Eff: 03-Mar-1999						Hrs					
						Enc					
TFE731-72-3531 R2	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG3						Mos					
Eff: 03-Mar-1999						Hrs					
						Enc					
TFE731-72-3531 R3	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG1						Mos					
Eff: 21-Feb-2001						Hrs					
						Enc					
TFE731-72-3531 R3	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG2						Mos					
Eff: 21-Feb-2001						Hrs					
						Enc					
TFE731-72-3531 R3	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							RE (-)			
72 ENG3						Mos					
Eff: 21-Feb-2001						Hrs					
						Enc					
TFE731-72-3531 R4	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							T (A/R)			
72 ENG1						Mos					
Eff: 28-Jan-2003						Hrs					
						Enc					
TFE731-72-3531 R4	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							T (A/R)			
72 ENG2						Mos					
Eff: 28-Jan-2003						Hrs					
						Enc					
TFE731-72-3531 R4	**Instl Of Fan Blades & Ident Of Fan Rtr Assy**							T (A/R)			
72 ENG3						Mos					
Eff: 28-Jan-2003						Hrs					
						Enc					
TFE731-72-3532	**Rework Compressor Interstage Diffuser**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3532	**Rework Compressor Interstage Diffuser**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Not Applicable						Hrs					
						Enc					
TFE731-72-3532	**Rework Compressor Interstage Diffuser**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3532RWK	**Engine - Compressor Section - Rework Compressor Interstage Diffuser To Incorporate Oil Scavenge Slots**							RE (-)		Category 2	
72 ENG1						Mos	09-Feb-1995				
Eff: 17-Sep-1993 Complied With						Hrs					
						Enc					
TFE731-72-3536	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG1						Mos					
Eff: 02-Nov-1993						Hrs					
						Enc					
TFE731-72-3536	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG2						Mos					
Eff: 02-Nov-1993 Complied With						Hrs					
						Enc					
TFE731-72-3536	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG3						Mos	04-May-1995				
Eff: 02-Nov-1993 Complied With						Hrs					
						Enc					
TFE731-72-3536 R1	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG1						Mos					
Eff: 21-Apr-1995						Hrs					
						Enc					
TFE731-72-3536 R1	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG2						Mos					
Eff: 21-Apr-1995						Hrs					
						Enc					
TFE731-72-3536 R1	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG3						Mos					
Eff: 21-Apr-1995						Hrs					
						Enc					
TFE731-72-3536 R2	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG1						Mos	17-Feb-1997				
Eff: 01-Aug-1996 Complied With						Hrs	7,267				
						Enc	4,434				
TFE731-72-3536 R2	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG2						Mos					
Eff: 01-Aug-1996						Hrs					
						Enc					
TFE731-72-3536 R2	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							RE (-)			
72 ENG3						Mos					
Eff: 01-Aug-1996						Hrs					
						Enc					
TFE731-72-3536 R3	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							T (A/R)			
72 ENG1						Mos					
Eff: 24-Jan-2002						Hrs					
						Enc					
TFE731-72-3536 R3	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							T (A/R)			
72 ENG2						Mos					
Eff: 24-Jan-2002						Hrs					
						Enc					
TFE731-72-3536 R3	**Install Combustion Chamber & Inner Transition Liner (Controlled Fit/Low Smoke)**							T (A/R)			
72 ENG3						Mos					
Eff: 24-Jan-2002						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3540 R1	**ENGINE - COMPRESSOR SECTION - Improved No. 4 And 5 Bearing Sump Scavenge (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
72 ENG1						Mos	09-Feb-1995				
Eff: 21-Jan-1994 Complied With						Hrs					
						Enc					
TFE731-72-3542	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	04-Nov-1980				
Complied With	PCW					Hrs	0				
						Enc	0				
TFE731-72-3542	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3542	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3542 R1	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3542 R1	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3542 R1	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3542 R2	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3542 R2	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Complied With	PCW					Hrs					
						Enc					
TFE731-72-3542 R2	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Complied With						Hrs					
						Enc					
TFE731-72-3542 R3	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					
TFE731-72-3542 R3	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					
TFE731-72-3542 R3	**Instl LP 2Nd Stg Cprsr Rtr Assy W/Insp Blades**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 28-Mar-2007						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3549	**Inspect Forward & Aft Welds For Machining**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1995				
Eff: 04-Apr-1994 Complied With						Hrs					
						Enc					
TFE731-72-3549	**Inspect Forward & Aft Welds For Machining**							RE (-)		Recommended	
72 ENG2						Mos	15-Mar-1995				
Eff: 04-Apr-1994 Complied With						Hrs					
						Enc					
TFE731-72-3549	**Inspect Forward & Aft Welds For Machining**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 04-Apr-1994						Hrs					
						Enc					
TFE731-72-3556	**Replace LP 2Nd Stg Turbine Blades 3072012-1/-2**							RE (-)		Optional	
72 ENG1						Mos	24-Jan-1995				
Eff: 06-May-1994 Complied With						Hrs					
						Enc					
TFE731-72-3556	**Replace LP 2Nd Stg Turbine Blades 3072012-1/-2**							RE (-)		Optional	
72 ENG2						Mos	15-Mar-1995				
Eff: 06-May-1994 Complied With						Hrs					
						Enc					
TFE731-72-3556	**Replace LP 2Nd Stg Turbine Blades 3072012-1/-2**							T (A/R)		Optional	
72 ENG3						Mos					
Eff: 06-May-1994						Hrs					
						Enc					
TFE731-72-3560	**LP 1St Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3560	**LP 1St Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3560	**LP 1St Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3560 R1	**LP 1St Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos	31-Mar-2006				
Eff: 26-Mar-1996 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3560 R1	**LP 1St Stage Cprsr Rotor Assy Blades**							T (A/R)		Informational	
72 ENG2						Mos					
Eff: 26-Mar-1996						Hrs					
						Enc					
TFE731-72-3560 R1	**LP 1St Stage Cprsr Rotor Assy Blades**							T (A/R)		Informational	
72 ENG3						Mos					
Eff: 26-Mar-1996						Hrs					
						Enc					
TFE731-72-3561	**LP 2Nd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3561	**LP 2Nd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3561	**LP 2Nd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3561 R1	**LP 2Nd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 26-Mar-1995						Hrs					
						Enc					
TFE731-72-3561 R1	**LP 2Nd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 26-Mar-1995						Hrs					
						Enc					
TFE731-72-3561 R1	**LP 2Nd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 26-Mar-1995						Hrs					
						Enc					
TFE731-72-3561 R2	**LP 2Nd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos	31-Mar-2006				
Eff: 05-May-2005 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3561 R2	**LP 2Nd Stage Cprsr Rotor Assy Blades**							T (A/R)		Informational	
72 ENG2						Mos					
Eff: 05-May-2005						Hrs					
						Enc					
TFE731-72-3561 R2	**LP 2Nd Stage Cprsr Rotor Assy Blades**							T (A/R)		Informational	
72 ENG3						Mos					
Eff: 05-May-2005						Hrs					
						Enc					
TFE731-72-3562	**LP 3Rd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3562	**LP 3Rd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3562	**LP 3Rd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3562 R1	**LP 3Rd Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos	31-Mar-2006				
Eff: 26-Mar-1996 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3562 R1	**LP 3Rd Stage Cprsr Rotor Assy Blades**							T (A/R)		Informational	
72 ENG2						Mos					
Eff: 26-Mar-1996						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3562 R1	**LP 3Rd Stage Cprsr Rotor Assy Blades**							T (A/R)		Informational	
72 ENG3						Mos					
Eff: 26-Mar-1996						Hrs					
						Enc					
TFE731-72-3563	**LP 4Th Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3563	**LP 4Th Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG2						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3563	**LP 4Th Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG3						Mos					
Eff: 29-Aug-1995						Hrs					
						Enc					
TFE731-72-3563 R1	**LP 4Th Stage Cprsr Rotor Assy Blades**							RE (-)		Informational	
72 ENG1						Mos	31-Mar-2006				
Eff: 26-Mar-1996 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3563 R1	**LP 4Th Stage Cprsr Rotor Assy Blades**							T (A/R)		Informational	
72 ENG2						Mos					
Eff: 26-Mar-1996						Hrs					
						Enc					
TFE731-72-3563 R1	**LP 4Th Stage Cprsr Rotor Assy Blades**							T (A/R)		Informational	
72 ENG3						Mos					
Eff: 26-Mar-1996						Hrs					
						Enc					
TFE731-72-3564	**Engine - Bank/Spare Engine Conversions**							RE (-)			
72 ENG1						Mos					
Eff: 21-Nov-1994						Hrs					
						Enc					
TFE731-72-3564	**Engine - Bank/Spare Engine Conversions**							RE (-)			
72 ENG2						Mos					
Eff: 21-Nov-1994						Hrs					
						Enc					
TFE731-72-3564	**Engine - Bank/Spare Engine Conversions**							RE (-)			
72 ENG3						Mos					
Eff: 21-Nov-1994						Hrs					
						Enc					
TFE731-72-3564 R1	**Engine - Bank/Spare Engine Conversions**							RE (-)			
72 ENG1						Mos					
Eff: 14-Feb-1996						Hrs					
						Enc					
TFE731-72-3564 R1	**Engine - Bank/Spare Engine Conversions**							RE (-)			
72 ENG2						Mos					
Eff: 14-Feb-1996						Hrs					
						Enc					
TFE731-72-3564 R1	**Engine - Bank/Spare Engine Conversions**							RE (-)			
72 ENG3						Mos					
Eff: 14-Feb-1996						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3564 R2	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG1					Mos					
Eff: 16-Dec-1996					Hrs					
					Enc					
TFE731-72-3564 R2	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG2					Mos					
Eff: 16-Dec-1996					Hrs					
					Enc					
TFE731-72-3564 R2	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG3					Mos					
Eff: 16-Dec-1996					Hrs					
					Enc					
TFE731-72-3564 R3	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG1					Mos					
Eff: 22-Oct-1997					Hrs					
					Enc					
TFE731-72-3564 R3	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG2					Mos					
Eff: 22-Oct-1997					Hrs					
					Enc					
TFE731-72-3564 R3	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG3					Mos					
Eff: 22-Oct-1997					Hrs					
					Enc					
TFE731-72-3564 R4	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG1					Mos					
Eff: 11-Feb-1999					Hrs					
					Enc					
TFE731-72-3564 R4	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG2					Mos					
Eff: 11-Feb-1999					Hrs					
					Enc					
TFE731-72-3564 R4	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG3					Mos					
Eff: 11-Feb-1999					Hrs					
					Enc					
TFE731-72-3564 R5	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG1					Mos					
Eff: 21-Apr-1999					Hrs					
					Enc					
TFE731-72-3564 R5	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG2					Mos					
Eff: 21-Apr-1999					Hrs					
					Enc					
TFE731-72-3564 R5	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG3					Mos					
Eff: 21-Apr-1999					Hrs					
					Enc					
TFE731-72-3564 R6	**Engine - Bank/Spare Engine Conversions**						RE (-)			
72 ENG1					Mos					
Eff: 20-Nov-2000					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3564 R6	**Engine - Bank/Spare Engine Conversions**							RE (-)			
72 ENG2						Mos					
Eff: 20-Nov-2000						Hrs					
						Enc					
TFE731-72-3564 R6	**Engine - Bank/Spare Engine Conversions**							RE (-)			
72 ENG3						Mos					
Eff: 20-Nov-2000						Hrs					
						Enc					
TFE731-72-3564 R7	**Engine - Bank/Spare Engine Conversions**							T (A/R)			
72 ENG1						Mos					
Eff: 07-Jan-2003						Hrs					
						Enc					
TFE731-72-3564 R7	**Engine - Bank/Spare Engine Conversions**							T (A/R)			
72 ENG2						Mos					
Eff: 07-Jan-2003						Hrs					
						Enc					
TFE731-72-3564 R7	**Engine - Bank/Spare Engine Conversions**							T (A/R)			
72 ENG3						Mos					
Eff: 07-Jan-2003						Hrs					
						Enc					
TFE731-72-3568 R1	**Convert TFE731-3 To -3D & -3R To -3DR**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	27-Dec-1997				
Eff: 18-Sep-1996 Complied With	THE SERVICE BULLETIN HAS BEEN INCORPORATED					Hrs					
						Enc					
TFE731-72-3568 R1	**Convert TFE731-3 To -3D & -3R To -3DR**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	17-Apr-1997				
Eff: 18-Sep-1996 Complied With						Hrs					
						Enc					
TFE731-72-3568 R1	**Convert TFE731-3 To -3D & -3R To -3DR**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 18-Sep-1996						Hrs					
						Enc					
TFE731-72-3590	**Engine - Turbine Section - Provide for Installation of HP Turbine Blade**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	04-Nov-1980				
Eff: 31-Jan-1996 Complied With	PCW					Hrs	0				
						Enc	0				
TFE731-72-3590	**Engine - Turbine Section - Provide for Installation of HP Turbine Blade**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 31-Jan-1996						Hrs					
						Enc					
TFE731-72-3590	**Engine - Turbine Section - Provide for Installation of HP Turbine Blade**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 31-Jan-1996						Hrs					
						Enc					
TFE731-72-3596	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 22-May-1996						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3596	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 22-May-1996						Hrs					
						Enc					
TFE731-72-3596	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG3						Mos					
Eff: 22-May-1996						Hrs					
						Enc					
TFE731-72-3596 R1	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 16-Aug-1996						Hrs					
						Enc					
TFE731-72-3596 R1	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 16-Aug-1996						Hrs					
						Enc					
TFE731-72-3596 R1	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG3						Mos					
Eff: 16-Aug-1996						Hrs					
						Enc					
TFE731-72-3596 R2	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 27-Nov-1996						Hrs					
						Enc					
TFE731-72-3596 R2	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 27-Nov-1996						Hrs					
						Enc					
TFE731-72-3596 R2	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG3						Mos					
Eff: 27-Nov-1996						Hrs					
						Enc					
TFE731-72-3596 R3	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 03-Mar-1997						Hrs					
						Enc					
TFE731-72-3596 R3	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG2						Mos	17-Apr-1997				
Eff: 03-Mar-1997 Complied With						Hrs					
						Enc					
TFE731-72-3596 R3	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG3						Mos	12-Jul-1997				
Eff: 03-Mar-1997 Complied With						Hrs					
						Enc					
TFE731-72-3596 R4	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 07-Aug-1997						Hrs					
						Enc					
TFE731-72-3596 R4	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 07-Aug-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3596 R4	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG3						Mos					
Eff: 07-Aug-1997						Hrs					
						Enc					
TFE731-72-3596 R5	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG1						Mos	27-Dec-1997				
Eff: 17-Sep-1997 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-72-3596 R5	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 17-Sep-1997						Hrs					
						Enc					
TFE731-72-3596 R5	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG3						Mos					
Eff: 17-Sep-1997						Hrs					
						Enc					
TFE731-72-3596 R6	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG1						Mos					
Eff: 11-Dec-1998						Hrs					
						Enc					
TFE731-72-3596 R6	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG2						Mos					
Eff: 11-Dec-1998						Hrs					
						Enc					
TFE731-72-3596 R6	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 2	
72 ENG3						Mos					
Eff: 11-Dec-1998						Hrs					
						Enc					
TFE731-72-3596 R7	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (A/R)		Category 2	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3596 R7	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (A/R)		Category 2	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3596 R7	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (A/R)		Category 2	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3596 R8	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 14-Sep-2001						Hrs					
						Enc					
TFE731-72-3596 R8	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 14-Sep-2001						Hrs					
						Enc					
TFE731-72-3596 R8	**ENGINE - Replace Mainshaft Carbon Ring Seals and Associated Vent/Oil System Components (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 14-Sep-2001						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3600	**Compressor Section - Install LP Compressor Stator Shim, Part No. 3060360-1 Thru -11**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	27-Dec-1997				
Eff: 13-Jan-1997 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-72-3600	**Compressor Section - Install LP Compressor Stator Shim, Part No. 3060360-1 Thru -11**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	17-Apr-1997				
Eff: 13-Jan-1997 Complied With						Hrs					
						Enc					
TFE731-72-3600	**Compressor Section - Install LP Compressor Stator Shim, Part No. 3060360-1 Thru -11**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	12-Jul-1997				
Eff: 13-Jan-1997 Complied With						Hrs					
						Enc					
TFE731-72-3602	**Engine - Turbine Section - Perform One Time Inspection of Anti-Rotation Tangs on HP Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	27-Dec-1997				
Eff: 20-May-1996 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-72-3602	**Engine - Turbine Section - Perform One Time Inspection of Anti-Rotation Tangs on HP Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	17-Apr-1997				
Eff: 20-May-1996 Complied With						Hrs					
						Enc					
TFE731-72-3602	**Engine - Turbine Section - Perform One Time Inspection of Anti-Rotation Tangs on HP Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos	23-Aug-1997				
Eff: 20-May-1996 Complied With						Hrs					
						Enc					
TFE731-72-3603Rwk R1	**Rework Compressor Interstage Diffuser to Incorporate/Enlarge Oil Scavenge Slots**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
TFE731-72-3603Rwk R1	**Rework Compressor Interstage Diffuser to Incorporate/Enlarge Oil Scavenge Slots**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
TFE731-72-3603Rwk R1	**Rework Compressor Interstage Diffuser to Incorporate/Enlarge Oil Scavenge Slots**							RE (-)			
72 ENG3						Mos	14-Jan-2000				
Complied With						Hrs					
						Enc					
TFE731-72-3604	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Mar-1996						Hrs					
						Enc					
TFE731-72-3604	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	14-May-1997				
Eff: 22-Mar-1996 Complied With						Hrs	7,307.4				
						Enc					
TFE731-72-3604	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos	23-Aug-1997				
Eff: 22-Mar-1996 Complied With						Hrs					
						Enc					
TFE731-72-3604 R1	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	20-May-1997				
Eff: 17-Sep-1996 Complied With						Hrs	7,478				
						Enc	4,553				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3604 R1	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 17-Sep-1996						Hrs					
						Enc					
TFE731-72-3604 R1	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 17-Sep-1996						Hrs					
						Enc					
TFE731-72-3604 R2	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 06-Feb-1997						Hrs					
						Enc					
TFE731-72-3604 R2	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	17-Apr-1997				
Eff: 06-Feb-1997 Complied With						Hrs					
						Enc					
TFE731-72-3604 R2	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos	12-Jul-1997				
Eff: 06-Feb-1997 Complied With						Hrs					
						Enc					
TFE731-72-3604 R3	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 17-Jan-2001						Hrs					
						Enc					
TFE731-72-3604 R3	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 17-Jan-2001						Hrs					
						Enc					
TFE731-72-3604 R3	**Rewk Transfer Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 17-Jan-2001						Hrs					
						Enc					
TFE731-72-3604 R4	**Rewk Transfer Gearbox Assy**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 08-Dec-2004						Hrs					
						Enc					
TFE731-72-3604 R4	**Rewk Transfer Gearbox Assy**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 08-Dec-2004						Hrs					
						Enc					
TFE731-72-3604 R4	**Rewk Transfer Gearbox Assy**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 08-Dec-2004						Hrs					
						Enc					
TFE731-72-3604 R5	**Rewk Transfer Gearbox Assy**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 20-Mar-2015						Hrs					
						Enc					
TFE731-72-3604 R5	**Rewk Transfer Gearbox Assy**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 20-Mar-2015						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3604 R5	**Rewk Transfer Gearbox Assy**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 20-Mar-2015						Hrs					
						Enc					
TFE731-72-3605	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Mar-1996						Hrs					
						Enc					
TFE731-72-3605	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	14-May-1997				
Eff: 22-Mar-1996 Complied With						Hrs	7,307.4				
						Enc					
TFE731-72-3605	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos	23-Aug-1997				
Eff: 22-Mar-1996 Complied With						Hrs					
						Enc					
TFE731-72-3605 R1	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	20-May-1997				
Eff: 26-Jul-1996 Complied With						Hrs	7,478				
						Enc	4,553				
TFE731-72-3605 R1	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 26-Jul-1996						Hrs					
						Enc					
TFE731-72-3605 R1	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 26-Jul-1996						Hrs					
						Enc					
TFE731-72-3605 R2	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 16-Dec-1996						Hrs					
						Enc					
TFE731-72-3605 R2	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	17-Apr-1997				
Eff: 16-Dec-1996 Complied With						Hrs					
						Enc					
TFE731-72-3605 R2	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos	12-Jul-1997				
Eff: 16-Dec-1996 Complied With						Hrs					
						Enc					
TFE731-72-3605 R3	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 18-Feb-2003						Hrs					
						Enc					
TFE731-72-3605 R3	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 18-Feb-2003						Hrs					
						Enc					
TFE731-72-3605 R3	**Instl/Rewk Accessory Drive Gearbox Assy**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 18-Feb-2003						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3605 R4	**Instl/Rewk Accessory Drive Gearbox Assy**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 16-Jun-2004						Hrs					
						Enc					
TFE731-72-3605 R4	**Instl/Rewk Accessory Drive Gearbox Assy**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 16-Jun-2004						Hrs					
						Enc					
TFE731-72-3605 R4	**Instl/Rewk Accessory Drive Gearbox Assy**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 16-Jun-2004						Hrs					
						Enc					
TFE731-72-3613	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	20-May-1997				
Eff: 06-Feb-1997 Complied With						Hrs	7,478				
						Enc	4,553				
TFE731-72-3613	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 06-Feb-1997						Hrs					
						Enc					
TFE731-72-3613	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 06-Feb-1997						Hrs					
						Enc					
TFE731-72-3613 R1	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 24-Apr-1997						Hrs					
						Enc					
TFE731-72-3613 R1	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 24-Apr-1997						Hrs					
						Enc					
TFE731-72-3613 R1	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 24-Apr-1997						Hrs					
						Enc					
TFE731-72-3613 R2	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 07-Aug-1997						Hrs					
						Enc					
TFE731-72-3613 R2	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 07-Aug-1997						Hrs					
						Enc					
TFE731-72-3613 R2	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 07-Aug-1997						Hrs					
						Enc					
TFE731-72-3613 R3	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 29-Jan-1989						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3613 R3	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 29-Jan-1989						Hrs					
						Enc					
TFE731-72-3613 R3	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 29-Jan-1989						Hrs					
						Enc					
TFE731-72-3613 R4	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 22-Feb-1999						Hrs					
						Enc					
TFE731-72-3613 R4	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	14-Jan-2000				
Eff: 22-Feb-1999 Complied With	PCW					Hrs					
						Enc					
TFE731-72-3613 R4	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	14-Jan-2000				
Eff: 22-Feb-1999 Complied With						Hrs					
						Enc					
TFE731-72-3613 R5	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 14-Dec-2001						Hrs					
						Enc					
TFE731-72-3613 R5	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 14-Dec-2001						Hrs					
						Enc					
TFE731-72-3613 R5	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 14-Dec-2001						Hrs					
						Enc					
TFE731-72-3613 R6	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 14-Nov-2003						Hrs					
						Enc					
TFE731-72-3613 R6	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 14-Nov-2003						Hrs					
						Enc					
TFE731-72-3613 R6	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 14-Nov-2003						Hrs					
						Enc					
TFE731-72-3613 R7	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 11-Nov-2004						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3613 R7	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 11-Nov-2004						Hrs					
						Enc					
TFE731-72-3613 R7	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 11-Nov-2004						Hrs					
						Enc					
TFE731-72-3613 R8	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 23-Jan-2009						Hrs					
						Enc					
TFE731-72-3613 R8	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 23-Jan-2009						Hrs					
						Enc					
TFE731-72-3613 R8	**Engine - By-Pass Section - Replace No. 1 And No. 3 Carbon Ring Seals And Associated Vent/Oil System Components**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 23-Jan-2009						Hrs					
						Enc					
TFE731-72-3614Rwk	**Bypass Section-Rework No.1 Seal & Seal Housing to Part No. 3071966-5 or 3077122-1/-2/-3**							RE (-)			
72 ENG1						Mos	20-May-1997				
Complied With						Hrs					
						Enc					
TFE731-72-3614Rwk	**Bypass Section-Rework No.1 Seal & Seal Housing to Part No. 3071966-5 or 3077122-1/-2/-3**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
TFE731-72-3614Rwk	**Bypass Section-Rework No.1 Seal & Seal Housing to Part No. 3071966-5 or 3077122-1/-2/-3**							RE (-)			
72 ENG3						Mos	03-Jun-1997				
						Hrs					
						Enc					
TFE731-72-3615	**Rework Air Breather Valve, P/N 3071564-7 /-8 to P/N 3071564-9,Used in Air Breather Valve P/N 3075323-3**							RE (-)			
72 ENG1						Mos	13-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
TFE731-72-3615	**Rework Air Breather Valve, P/N 3071564-7 /-8 to P/N 3071564-9,Used in Air Breather Valve P/N 3075323-3**							RE (-)			
72 ENG2						Mos	14-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
TFE731-72-3615	**Rework Air Breather Valve, P/N 3071564-7 /-8 to P/N 3071564-9,Used in Air Breather Valve P/N 3075323-3**							RE (-)			
72 ENG3						Mos	14-Jan-2000				
Complied With						Hrs					
						Enc					
TFE731-72-3617	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 22-Oct-1997						Hrs					
						Enc					
TFE731-72-3617	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 22-Oct-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3617	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 22-Oct-1997						Hrs					
						Enc					
TFE731-72-3617 R1	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 06-Mar-2001						Hrs					
						Enc					
TFE731-72-3617 R1	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 06-Mar-2001						Hrs					
						Enc					
TFE731-72-3617 R1	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos	29-Oct-2001				
Eff: 06-Mar-2001 Complied With						Hrs					
						Enc					
TFE731-72-3617 R2	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	31-Mar-2006				
Eff: 10-Aug-2005 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3617 R2	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	22-Aug-2006				
Eff: 10-Aug-2005 Complied With						Hrs					
						Enc					
TFE731-72-3617 R2	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							T (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 10-Aug-2005						Hrs					
						Enc					
TFE731-72-3617 R3	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 29-Aug-2018						Hrs					
						Enc					
TFE731-72-3617 R3	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 29-Aug-2018						Hrs					
						Enc					
TFE731-72-3617 R3	**Engine - Turbine Section - Provide Improved High Pressure Turbine Nozzle Segments**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 29-Aug-2018						Hrs					
						Enc					
TFE731-72-3618	**Engine - Compressor Section - Provide An Alternative LP Compressor Fourth Stage Stator Seal, P/N 3060334-1 With Required Washers P/N 3060367-1**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	20-May-1997				
Eff: 02-Jun-1997 Complied With						Hrs	7,478				
						Enc	4,553				
TFE731-72-3618	**Engine - Compressor Section - Provide An Alternative LP Compressor Fourth Stage Stator Seal, P/N 3060334-1 With Required Washers P/N 3060367-1**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 02-Jun-1997						Hrs					
						Enc					
TFE731-72-3618	**Engine - Compressor Section - Provide An Alternative LP Compressor Fourth Stage Stator Seal, P/N 3060334-1 With Required Washers P/N 3060367-1**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 02-Jun-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3635	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, P/N 3072231-1 To P/N 3072231-4**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	31-Mar-2006				
Eff: 16-Nov-1998 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3635	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, P/N 3072231-1 To P/N 3072231-4**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	22-Aug-2006				
Eff: 16-Nov-1998 Complied With						Hrs					
						Enc					
TFE731-72-3635	**Engine - Accessory Drives Section - Inspect/Rework/Install Oil Filter Cover, P/N 3072231-1 To P/N 3072231-4**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 16-Nov-1998						Hrs					
						Enc					
TFE731-72-3637	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 07-Oct-1998						Hrs					
						Enc					
TFE731-72-3637	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 07-Oct-1998						Hrs					
						Enc					
TFE731-72-3637	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 07-Oct-1998						Hrs					
						Enc					
TFE731-72-3637 R1	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 08-Dec-1998						Hrs					
						Enc					
TFE731-72-3637 R1	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 08-Dec-1998						Hrs					
						Enc					
TFE731-72-3637 R1	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 08-Dec-1998						Hrs					
						Enc					
TFE731-72-3637 R2	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					
TFE731-72-3637 R2	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					
TFE731-72-3637 R2	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					
TFE731-72-3637 R3	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 28-Mar-2001						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3637 R3	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 28-Mar-2001						Hrs					
						Enc					
TFE731-72-3637 R3	**Engine - By-Pass Section - Install Fan Shaft Assembly, P/N 3071955-6 Or 3074641-4 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 28-Mar-2001						Hrs					
						Enc					
TFE731-72-3638	**Engine - Accessory Drives Section - Installation Of Transfer Gearbox Housing Assembly, P/N 3070429-8**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3638	**Engine - Accessory Drives Section - Installation Of Transfer Gearbox Housing Assembly, P/N 3070429-8**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3638	**Engine - Accessory Drives Section - Installation Of Transfer Gearbox Housing Assembly, P/N 3070429-8**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3638 R1	**Engine - Accessory Drives Section - Installation Of Transfer Gearbox Housing Assembly, P/N 3070429-8**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 02-Apr-2007						Hrs					
						Enc					
TFE731-72-3638 R1	**Engine - Accessory Drives Section - Installation Of Transfer Gearbox Housing Assembly, P/N 3070429-8**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 02-Apr-2007						Hrs					
						Enc					
TFE731-72-3638 R1	**Engine - Accessory Drives Section - Installation Of Transfer Gearbox Housing Assembly, P/N 3070429-8**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 02-Apr-2007						Hrs					
						Enc					
TFE731-72-3640	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 20-Nov-1998						Hrs					
						Enc					
TFE731-72-3640	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 20-Nov-1998						Hrs					
						Enc					
TFE731-72-3640	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 20-Nov-1998						Hrs					
						Enc					
TFE731-72-3640 R1	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 08-Dec-1998						Hrs					
						Enc					
TFE731-72-3640 R1	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 08-Dec-1998						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3640 R1	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 08-Dec-1998						Hrs					
						Enc					
TFE731-72-3640 R2	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	13-Jan-2000				
Eff: 07-Jun-1999 Complied With	PCW					Hrs	9,093				
						Enc	5,486				
TFE731-72-3640 R2	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	14-Jan-2000				
Eff: 07-Jun-1999 Complied With	PCW					Hrs					
						Enc					
TFE731-72-3640 R2	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	14-Jan-2000				
Eff: 07-Jun-1999 Complied With						Hrs					
						Enc					
TFE731-72-3640 R3	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 10-Nov-2000						Hrs					
						Enc					
TFE731-72-3640 R3	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 10-Nov-2000						Hrs					
						Enc					
TFE731-72-3640 R3	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 10-Nov-2000						Hrs					
						Enc					
TFE731-72-3640 R4	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 16-Oct-2001						Hrs					
						Enc					
TFE731-72-3640 R4	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 16-Oct-2001						Hrs					
						Enc					
TFE731-72-3640 R4	**(Inactive For Further Accomplishment) - Engine - Servicing With Mobil 254 Oil**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 16-Oct-2001						Hrs					
						Enc					
TFE731-72-3643	**Engine - By-Pass Section - Install Fan Blade Retainer Ring, PN 3073789-1**							RE (-)			
72 ENG1						Mos	31-Mar-2006				
Eff: 03-Mar-1999 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3643	**Engine - By-Pass Section - Install Fan Blade Retainer Ring, PN 3073789-1**							T (A/R)			
72 ENG2						Mos					
Eff: 03-Mar-1999						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3643	**Engine - By-Pass Section - Install Fan Blade Retainer Ring, PN 3073789-1**							T (A/R)			
72 ENG3						Mos					
Eff: 03-Mar-1999						Hrs					
						Enc					
TFE731-72-3644	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 24-Mar-1999						Hrs					
						Enc					
TFE731-72-3644	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 24-Mar-1999						Hrs					
						Enc					
TFE731-72-3644	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 24-Mar-1999						Hrs					
						Enc					
TFE731-72-3644 R1	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 15-Oct-1999						Hrs					
						Enc					
TFE731-72-3644 R1	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 15-Oct-1999						Hrs					
						Enc					
TFE731-72-3644 R1	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 15-Oct-1999						Hrs					
						Enc					
TFE731-72-3644 R2	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	31-Mar-2006				
Eff: 10-Jan-2001 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3644 R2	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 10-Jan-2001						Hrs					
						Enc					
TFE731-72-3644 R2	**Engine - Compressor Section - Install HP Impeller Shroud, P/N 3074567-1/-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 10-Jan-2001						Hrs					
						Enc					
TFE731-72-3645	**Engine - Turbine Section - Replace "Reworked" HP Turbine Nozzle Segments, P/N 3074783-7/-8/-9**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 07-Jun-1999						Hrs					
						Enc					
TFE731-72-3645	**Engine - Turbine Section - Replace "Reworked" HP Turbine Nozzle Segments, P/N 3074783-7/-8/-9**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 07-Jun-1999						Hrs					
						Enc					
TFE731-72-3645	**Engine - Turbine Section - Replace "Reworked" HP Turbine Nozzle Segments, P/N 3074783-7/-8/-9**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 07-Jun-1999						Hrs					
						Enc					

Task No / SEQ PN/SN / MOC Note or Component Condition	Description	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3645 R1	**Engine - Turbine Section - Replace "Reworked" HP Turbine Nozzle Segments, P/N 3074783-7/-8/-9**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	31-Mar-2006				
Eff: 05-Dec-2001 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3645 R1	**Engine - Turbine Section - Replace "Reworked" HP Turbine Nozzle Segments, P/N 3074783-7/-8/-9**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Eff: 05-Dec-2001 Complied With						Hrs					
						Enc					
TFE731-72-3645 R1	**Engine - Turbine Section - Replace "Reworked" HP Turbine Nozzle Segments, P/N 3074783-7/-8/-9**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 05-Dec-2001 Complied With						Hrs					
						Enc					
TFE731-72-3650	**Engine - Accessory Drives Section - New Nameplate, P/N S20048-1, For Transfer Gearbox Assembly**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					
TFE731-72-3650	**Engine - Accessory Drives Section - New Nameplate, P/N S20048-1, For Transfer Gearbox Assembly**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					
TFE731-72-3650	**Engine - Accessory Drives Section - New Nameplate, P/N S20048-1, For Transfer Gearbox Assembly**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					
TFE731-72-3654	**Engine - Turbine Section - Prevent LP Third Stage Turbine Rotor Disc From Rubbing The LP Third Stage Turbine Nozzle**							RE (-)		Category 2	
72 ENG1						Mos	31-Mar-2006				
Eff: 10-Sep-1999 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3654	**Engine - Turbine Section - Prevent LP Third Stage Turbine Rotor Disc From Rubbing The LP Third Stage Turbine Nozzle**							RE (-)		Category 2	
72 ENG2						Mos	13-Sep-2001				
Eff: 10-Sep-1999 Complied With						Hrs					
						Enc					
TFE731-72-3654	**Engine - Turbine Section - Prevent LP Third Stage Turbine Rotor Disc From Rubbing The LP Third Stage Turbine Nozzle**							RE (-)		Category 2	
72 ENG3						Mos	29-Aug-2006				
Eff: 10-Sep-1999 Complied With						Hrs					
						Enc					
TFE731-72-3654 R1	**Engine - Turbine Section - Prevent LP Third Stage Turbine Rotor Disc From Rubbing The LP Third Stage Turbine Nozzle**							T (A/R)		Category 2	
72 ENG1						Mos					
Eff: 10-Dec-2010						Hrs					
						Enc					
TFE731-72-3654 R1	**Engine - Turbine Section - Prevent LP Third Stage Turbine Rotor Disc From Rubbing The LP Third Stage Turbine Nozzle**							T (A/R)		Category 2	
72 ENG2						Mos					
Eff: 10-Dec-2010						Hrs					
						Enc					
TFE731-72-3654 R1	**Engine - Turbine Section - Prevent LP Third Stage Turbine Rotor Disc From Rubbing The LP Third Stage Turbine Nozzle**							T (A/R)		Category 2	
72 ENG3						Mos					
Eff: 10-Dec-2010						Hrs					
						Enc					
TFE731-72-3658	**Engine - Air Inlet Section - Replace Fan Inlet Housing**							RE (-)			
72 ENG1						Mos					
Eff: 08-Mar-2000						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3658	**Engine - Air Inlet Section - Replace Fan Inlet Housing**							RE (-)			
72 ENG2						Mos					
Eff: 08-Mar-2000						Hrs					
						Enc					
TFE731-72-3658	**Engine - Air Inlet Section - Replace Fan Inlet Housing**							RE (-)			
72 ENG3						Mos					
Eff: 08-Mar-2000						Hrs					
						Enc					
TFE731-72-3658 R1	**Engine - Air Inlet Section - Replace Fan Inlet Housing**							T (A/R)			
72 ENG1						Mos					
Eff: 21-Sep-2001						Hrs					
						Enc					
TFE731-72-3658 R1	**Engine - Air Inlet Section - Replace Fan Inlet Housing**							T (A/R)			
72 ENG2						Mos					
Eff: 21-Sep-2001						Hrs					
						Enc					
TFE731-72-3658 R1	**Engine - Air Inlet Section - Replace Fan Inlet Housing**							T (A/R)			
72 ENG3						Mos					
Eff: 21-Sep-2001						Hrs					
						Enc					
TFE731-72-3661	**Engine - Turbine Section - Inspectionect Specific Identified LP Third Stage Turbine (LPt3) Rotor Assemblies Incorporating LPt3 Rotor Blade, Pn 3072845-1, With Manufacture Code of 24217**							RE (-)		Category 2	
72 ENG1						Mos	04-Nov-1980				
Eff: 24-Jan-2000 Complied With	PCW					Hrs	0				
						Enc	0				
TFE731-72-3661	**Engine - Turbine Section - Inspectionect Specific Identified LP Third Stage Turbine (LPt3) Rotor Assemblies Incorporating LPt3 Rotor Blade, Pn 3072845-1, With Manufacture Code of 24217**							RE (-)		Category 2	
72 ENG2						Mos	13-Sep-2001				
Eff: 24-Jan-2000 Not Applicable						Hrs					
						Enc					
TFE731-72-3661	**Engine - Turbine Section - Inspectionect Specific Identified LP Third Stage Turbine (LPt3) Rotor Assemblies Incorporating LPt3 Rotor Blade, Pn 3072845-1, With Manufacture Code of 24217**							RE (-)		Category 2	
72 ENG3						Mos	29-Aug-2006				
Eff: 24-Jan-2000 Not Applicable						Hrs					
						Enc					
TFE731-72-3662	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 28-Jan-2000						Hrs					
						Enc					
TFE731-72-3662	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 28-Jan-2000						Hrs					
						Enc					
TFE731-72-3662	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 28-Jan-2000 Complied With						Hrs					
						Enc					
TFE731-72-3662 R1	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 04-Feb-2000						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3662 R1	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 04-Feb-2000						Hrs					
						Enc					
TFE731-72-3662 R1	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 04-Feb-2000						Hrs					
						Enc					
TFE731-72-3662 R2	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 17-Mar-2000						Hrs					
						Enc					
TFE731-72-3662 R2	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 17-Mar-2000						Hrs					
						Enc					
TFE731-72-3662 R2	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 17-Mar-2000						Hrs					
						Enc					
TFE731-72-3662 R3	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 31-May-2000						Hrs					
						Enc					
TFE731-72-3662 R3	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 31-May-2000						Hrs					
						Enc					
TFE731-72-3662 R3	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 31-May-2000						Hrs					
						Enc					
TFE731-72-3662 R4	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 30-Oct-2002						Hrs					
						Enc					
TFE731-72-3662 R4	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 30-Oct-2002						Hrs					
						Enc					
TFE731-72-3662 R4	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 30-Oct-2002						Hrs					
						Enc					
TFE731-72-3662 R5	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 08-Sep-2003						Hrs					
						Enc					
TFE731-72-3662 R5	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 08-Sep-2003						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3662 R5	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 08-Sep-2003						Hrs					
						Enc					
TFE731-72-3662 R6	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	31-Mar-2006				
Eff: 12-Feb-2004 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3662 R6	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Eff: 12-Feb-2004 Complied With						Hrs					
						Enc					
TFE731-72-3662 R6	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 12-Feb-2004						Hrs					
						Enc					
TFE731-72-3662 R7	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 28-Jan-2009						Hrs					
						Enc					
TFE731-72-3662 R7	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 28-Jan-2009						Hrs					
						Enc					
TFE731-72-3662 R7	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 28-Jan-2009						Hrs					
						Enc					
TFE731-72-3662 R8	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 12-Apr-2012						Hrs					
						Enc					
TFE731-72-3662 R8	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 12-Apr-2012						Hrs					
						Enc					
TFE731-72-3662 R8	**ENGINE - COMPRESSOR SECTION - Replace No. 4 and No. 5 Carbon Ring Seals and Associated Vent/Oil System Components**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 12-Apr-2012						Hrs					
						Enc					
TFE731-72-3664	**Engine - Compressor Section - Inspection/Replacement (As Required) Of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) P/N 3073049-1 And 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	07-Jan-2002				
Eff: 05-May-2000 Complied With						Hrs	9,831				
						Enc	5,855				
TFE731-72-3664	**Engine - Compressor Section - Inspection/Replacement (As Required) Of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) P/N 3073049-1 And 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	13-Sep-2001				
Eff: 05-May-2000 Complied With						Hrs					
						Enc					
TFE731-72-3664	**Engine - Compressor Section - Inspection/Replacement (As Required) Of Threaded Ends Tie Rod, (Low Pressure (LP) Tie Rod) P/N 3073049-1 And 3074744-1**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 05-May-2000 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3671	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						RE (-)	Cat.3-Product Improvement		
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-72-3671	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						RE (-)	Cat.3-Product Improvement		
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-72-3671	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						RE (-)	Cat.3-Product Improvement		
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-72-3671 R1	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						RE (-)	Cat.3-Product Improvement		
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-72-3671 R1	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						RE (-)	Cat.3-Product Improvement		
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-72-3671 R1	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						RE (-)	Cat.3-Product Improvement		
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-72-3671 R2	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						T (A/R)	Cat.3-Product Improvement		
72 ENG1					Mos					
Eff: 28-Jul-2009					Hrs					
					Enc					
TFE731-72-3671 R2	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						T (A/R)	Cat.3-Product Improvement		
72 ENG2					Mos					
Eff: 28-Jul-2009					Hrs					
					Enc					
TFE731-72-3671 R2	**Engine - Compressor Section - Install Redesigned Combustion Chamber Plenum Case**						T (A/R)	Cat.3-Product Improvement		
72 ENG3					Mos					
Eff: 28-Jul-2009					Hrs					
					Enc					
TFE731-72-3672	**Engine - Turbine Section - Provide A Low Pressure 1St Stage Turbine (LPT1) Nozzle Without The Air (A5) Seal Assembly Attached**						T (A/R)	Cat.3-Product Improvement		
72 ENG1					Mos					
Eff: 26-Mar-2004					Hrs					
					Enc					
TFE731-72-3672	**Engine - Turbine Section - Provide A Low Pressure 1St Stage Turbine (LPT1) Nozzle Without The Air (A5) Seal Assembly Attached**						T (A/R)	Cat.3-Product Improvement		
72 ENG2					Mos					
Eff: 26-Mar-2004					Hrs					
					Enc					
TFE731-72-3672	**Engine - Turbine Section - Provide A Low Pressure 1St Stage Turbine (LPT1) Nozzle Without The Air (A5) Seal Assembly Attached**						T (A/R)	Cat.3-Product Improvement		
72 ENG3					Mos					
Eff: 26-Mar-2004					Hrs					
					Enc					
TFE731-72-3674	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 12-Sep-2001					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3674	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 12-Sep-2001						Hrs					
						Enc					
TFE731-72-3674	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 12-Sep-2001						Hrs					
						Enc					
TFE731-72-3674 R1	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 26-Jun-2002						Hrs					
						Enc					
TFE731-72-3674 R1	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 26-Jun-2002						Hrs					
						Enc					
TFE731-72-3674 R1	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 26-Jun-2002						Hrs					
						Enc					
TFE731-72-3674 R2	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	31-Mar-2006				
Eff: 16-Sep-2003 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3674 R2	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Eff: 16-Sep-2003 Not Applicable						Hrs					
						Enc					
TFE731-72-3674 R2	**Engine - Compressor Section - Inspection Of Specific Identified Main Support Frame Assemblies**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 16-Sep-2003 Not Applicable						Hrs					
						Enc					
TFE731-72-3675	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG1						Mos	04-Nov-1980				
Eff: 29-May-2002 Complied With PCW						Hrs	0				
						Enc	0				
TFE731-72-3675	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG2						Mos					
Eff: 29-May-2002						Hrs					
						Enc					
TFE731-72-3675	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG3						Mos					
Eff: 29-May-2002						Hrs					
						Enc					
TFE731-72-3675 R1	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3675 R1	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R1	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R2	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R2	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R2	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R3	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R3	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG2						Mos	22-Aug-2006				
Complied With						Hrs					
						Enc					
TFE731-72-3675 R3	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG3						Mos	29-Aug-2006				
Complied With						Hrs					
						Enc					
TFE731-72-3675 R4	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R4	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R4	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3675 R5	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							T (A/R)			
72 ENG1						Mos					
Eff: 13-Jan-2010						Hrs					
						Enc					
TFE731-72-3675 R5	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**							T (A/R)			
72 ENG2						Mos					
Eff: 13-Jan-2010						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3675 R5	**Engine - By-Pass Section - Inspect Fan Blades For Unauthorized Markings On The Fan Blade Dovetail Aft Region**						T (A/R)			
72 ENG3					Mos					
Eff: 13-Jan-2010					Hrs					
					Enc					
TFE731-72-3678	**Engine - Consumables Kits**						RE (-)		Informational	
72 ENG1					Mos					
Eff: 10-Apr-2003					Hrs					
					Enc					
TFE731-72-3678	**Engine - Consumables Kits**						RE (-)		Informational	
72 ENG2					Mos					
Eff: 10-Apr-2003					Hrs					
					Enc					
TFE731-72-3678	**Engine - Consumables Kits**						RE (-)		Informational	
72 ENG3					Mos					
Eff: 10-Apr-2003					Hrs					
					Enc					
TFE731-72-3678 R1	**Engine - Consumables Kits**						T (A/R)		Informational	
72 ENG1					Mos					
Eff: 11-Nov-2004					Hrs					
					Enc					
TFE731-72-3678 R1	**Engine - Consumables Kits**						T (A/R)		Informational	
72 ENG2					Mos					
Eff: 11-Nov-2004					Hrs					
					Enc					
TFE731-72-3678 R1	**Engine - Consumables Kits**						T (A/R)		Informational	
72 ENG3					Mos					
Eff: 11-Nov-2004					Hrs					
					Enc					
TFE731-72-3679	**Engine - Performance Recovery Techniques For Engine Models TFE731-2/-3/-4/-5**						T (A/R)			
72 ENG1					Mos					
Eff: 19-Nov-2001					Hrs					
					Enc					
TFE731-72-3679	**Engine - Performance Recovery Techniques For Engine Models TFE731-2/-3/-4/-5**						T (A/R)			
72 ENG2					Mos					
Eff: 19-Nov-2001					Hrs					
					Enc					
TFE731-72-3679	**Engine - Performance Recovery Techniques For Engine Models TFE731-2/-3/-4/-5**						T (A/R)			
72 ENG3					Mos					
Eff: 19-Nov-2001					Hrs					
					Enc					
TFE731-72-3682	**Engine - Turbine Section - Replacement Of Specific Serial Numbered LP 1St And 2Nd Stage Turbine Rotor Discs Heat Treated In An Oil Fired Furnace**						T (A/R)			
72 ENG1					Mos					
Eff: 26-Nov-2002					Hrs					
					Enc					
TFE731-72-3682	**Engine - Turbine Section - Replacement Of Specific Serial Numbered LP 1St And 2Nd Stage Turbine Rotor Discs Heat Treated In An Oil Fired Furnace**						T (A/R)			
72 ENG2					Mos					
Eff: 26-Nov-2002					Hrs					
					Enc					
TFE731-72-3682	**Engine - Turbine Section - Replacement Of Specific Serial Numbered LP 1St And 2Nd Stage Turbine Rotor Discs Heat Treated In An Oil Fired Furnace**						T (A/R)			
72 ENG3					Mos					
Eff: 26-Nov-2002					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3685	**Engine - Turbine Section - Replace Specified Identified LP Second Stage Turbine Blades, PN 3072012-2 And 3074099-1**							RE (-)			
72 ENG1						Mos	04-Nov-1980				
Eff: 08-Mar-2002 Complied With	PCW					Hrs	0				
						Enc	0				
TFE731-72-3685	**Engine - Turbine Section - Replace Specified Identified LP Second Stage Turbine Blades, PN 3072012-2 And 3074099-1**							RE (-)			
72 ENG2						Mos	22-Aug-2006				
Eff: 08-Mar-2002 Not Applicable						Hrs					
						Enc					
TFE731-72-3685	**Engine - Turbine Section - Replace Specified Identified LP Second Stage Turbine Blades, PN 3072012-2 And 3074099-1**							RE (-)			
72 ENG3						Mos	29-Aug-2006				
Eff: 08-Mar-2002 Not Applicable						Hrs					
						Enc					
TFE731-72-3687	**Engine - Compressor Section - Remove Specific Identified LP Compressor Second Stage (LPC2) Discs**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	31-Mar-2006				
Eff: 07-Nov-2002 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3687	**Engine - Compressor Section - Remove Specific Identified LP Compressor Second Stage (LPC2) Discs**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Eff: 07-Nov-2002 Not Applicable						Hrs					
						Enc					
TFE731-72-3687	**Engine - Compressor Section - Remove Specific Identified LP Compressor Second Stage (LPC2) Discs**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 07-Nov-2002 Not Applicable						Hrs					
						Enc					
TFE731-72-3692	**Engine - Turbine Section Section - Install High Pressure Turbine (HPT) Assembly P/N 3075777-1 Or P/N 3075778-1 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 17-Sep-2003						Hrs					
						Enc					
TFE731-72-3692	**Engine - Turbine Section Section - Install High Pressure Turbine (HPT) Assembly P/N 3075777-1 Or P/N 3075778-1 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 17-Sep-2003						Hrs					
						Enc					
TFE731-72-3692	**Engine - Turbine Section Section - Install High Pressure Turbine (HPT) Assembly P/N 3075777-1 Or P/N 3075778-1 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 17-Sep-2003						Hrs					
						Enc					
TFE731-72-3692 R1	**Engine - Turbine Section Section - Install High Pressure Turbine (HPT) Assembly P/N 3075777-1 Or P/N 3075778-1 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 04-May-2005						Hrs					
						Enc					
TFE731-72-3692 R1	**Engine - Turbine Section Section - Install High Pressure Turbine (HPT) Assembly P/N 3075777-1 Or P/N 3075778-1 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 04-May-2005						Hrs					
						Enc					
TFE731-72-3692 R1	**Engine - Turbine Section Section - Install High Pressure Turbine (HPT) Assembly P/N 3075777-1 Or P/N 3075778-1 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 04-May-2005						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3693	**Engine - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, P/N 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 09-Dec-2003						Hrs					
						Enc					
TFE731-72-3693	**Engine - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, P/N 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 09-Dec-2003						Hrs					
						Enc					
TFE731-72-3693	**Engine - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, P/N 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 09-Dec-2003						Hrs					
						Enc					
TFE731-72-3693 R1	**Engine - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, P/N 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	31-Mar-2006				
Eff: 28-Jun-2004 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3693 R1	**Engine - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, P/N 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Eff: 28-Jun-2004 Not Applicable						Hrs					
						Enc					
TFE731-72-3693 R1	**Engine - Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, P/N 3070151-4**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 28-Jun-2004 Not Applicable						Hrs					
						Enc					
TFE731-72-3696	**Engine - Accessory Drives Section - Install Air-Oil Separator, Part No. 3075781-1**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos	31-Mar-2006				
Eff: 16-Jun-2004 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3696	**Engine - Accessory Drives Section - Install Air-Oil Separator, Part No. 3075781-1**							RE (-)		Cat.3-Product Improvement	
72 ENG2						Mos	22-Aug-2006				
Eff: 16-Jun-2004 Complied With						Hrs					
						Enc					
TFE731-72-3696	**Engine - Accessory Drives Section - Install Air-Oil Separator, Part No. 3075781-1**							RE (-)		Cat.3-Product Improvement	
72 ENG3						Mos	29-Aug-2006				
Eff: 16-Jun-2004 Complied With						Hrs					
						Enc					
TFE731-72-3699	**Engine - Turbine Section - Remove Specific Identified HPT Rotor Discs**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	31-Mar-2006				
Eff: 05-Mar-2004 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-72-3699	**Engine - Turbine Section - Remove Specific Identified HPT Rotor Discs**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Eff: 05-Mar-2004 Not Applicable						Hrs					
						Enc					
TFE731-72-3699	**Engine - Turbine Section - Remove Specific Identified HPT Rotor Discs**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 05-Mar-2004 Not Applicable						Hrs					
						Enc					
TFE731-72-3703	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG1						Mos					
Eff: 19-Jan-2007						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3703	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG2						Mos					
Eff: 19-Jan-2007						Hrs					
						Enc					
TFE731-72-3703	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG3						Mos					
Eff: 19-Jan-2007						Hrs					
						Enc					
TFE731-72-3703 R1	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R1	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R1	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R2	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R2	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R2	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R3	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R3	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R3	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-72-3703 R4	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							T (A/R)			
72 ENG1						Mos					
Eff: 12-Feb-2013						Hrs					
						Enc					
TFE731-72-3703 R4	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**							T (A/R)			
72 ENG2						Mos					
Eff: 12-Feb-2013						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3703 R4	**Engine - Convert Engine Models TFE731-3/-3D-1C To TFE731-4-1C**						T (A/R)			
72 ENG3					Mos					
Eff: 12-Feb-2013					Hrs					
					Enc					
TFE731-72-3705 R2	**Engine - Turbine Section - Install A Low Pressure First Stage Turbine (LPT1) Rotor Assembly With An Improved LPT1 Rotor Disc**						T (A/R)		Cat.1-Safety	
72 ENG1					Mos					
Eff: 09-Nov-2005					Hrs					
					Enc					
TFE731-72-3705 R2	**Engine - Turbine Section - Install A Low Pressure First Stage Turbine (LPT1) Rotor Assembly With An Improved LPT1 Rotor Disc**						T (A/R)		Cat.1-Safety	
72 ENG2					Mos					
Eff: 09-Nov-2005					Hrs					
					Enc					
TFE731-72-3705 R2	**Engine - Turbine Section - Install A Low Pressure First Stage Turbine (LPT1) Rotor Assembly With An Improved LPT1 Rotor Disc**						T (A/R)		Cat.1-Safety	
72 ENG3					Mos					
Eff: 09-Nov-2005					Hrs					
					Enc					
TFE731-72-3711	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 22-Sep-2004					Hrs					
					Enc					
TFE731-72-3711	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 22-Sep-2004					Hrs					
					Enc					
TFE731-72-3711	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG3					Mos					
Eff: 22-Sep-2004					Hrs					
					Enc					
TFE731-72-3711 R1	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 15-Dec-2004					Hrs					
					Enc					
TFE731-72-3711 R1	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 15-Dec-2004					Hrs					
					Enc					
TFE731-72-3711 R1	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG3					Mos					
Eff: 15-Dec-2004					Hrs					
					Enc					
TFE731-72-3711 R2	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG1					Mos					
Eff: 05-May-2005					Hrs					
					Enc					
TFE731-72-3711 R2	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG2					Mos					
Eff: 05-May-2005					Hrs					
					Enc					
TFE731-72-3711 R2	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**						RE (-)		Cat.2-Reliability	
72 ENG3					Mos					
Eff: 05-May-2005					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3711 R3	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 20-Dec-2005						Hrs					
						Enc					
TFE731-72-3711 R3	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 20-Dec-2005						Hrs					
						Enc					
TFE731-72-3711 R3	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 20-Dec-2005						Hrs					
						Enc					
TFE731-72-3711 R4	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							T (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 06-Mar-2006						Hrs					
						Enc					
TFE731-72-3711 R4	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	22-Aug-2006				
Eff: 06-Mar-2006 Not Applicable						Hrs					
						Enc					
TFE731-72-3711 R4	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	29-Aug-2006				
Eff: 06-Mar-2006 Not Applicable						Hrs					
						Enc					
TFE731-72-3711 R5	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 22-Oct-2015						Hrs					
						Enc					
TFE731-72-3711 R5	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 22-Oct-2015						Hrs					
						Enc					
TFE731-72-3711 R5	**Engine - Compressor Section - Install Improved 2Nd Stage Low Pressure Compressor (LPC2) Disc**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 22-Oct-2015						Hrs					
						Enc					
TFE731-72-3720	**Engine - Turbine Section - Inspect/Replace (If Required) Specific Identified High Pressure (HP) Turbine Rotor Discs, Part No. 3075772-1**							RE (-)		Cat.1-Safety	
72 ENG1						Mos	05-Jul-2006				
Eff: 05-Jul-2006 Not Applicable	by P/N not installed					Hrs					
						Enc					
TFE731-72-3720	**Engine - Turbine Section - Inspect/Replace (If Required) Specific Identified High Pressure (Hp) Turbine Rotor Discs, Part No. 3075772-1**							T (A/R)			
72 ENG1						Mos					
Eff: 05-Jul-2006						Hrs					
						Enc					
TFE731-72-3720	**Engine - Turbine Section - Inspect/Replace (If Required) Specific Identified High Pressure (Hp) Turbine Rotor Discs, Part No. 3075772-1**							RE (-)			
72 ENG2						Mos	22-Aug-2006				
Eff: 05-Jul-2006 Not Applicable						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3720	**Engine - Turbine Section - Inspect/Replace (If Required) Specific Identified High Pressure (HP) Turbine Rotor Discs, Part No. 3075772-1**							T (A/R)		Cat.1-Safety	
72 ENG2						Mos					
Eff: 05-Jul-2006						Hrs					
						Enc					
TFE731-72-3720	**Engine - Turbine Section - Inspect/Replace (If Required) Specific Identified High Pressure (HP) Turbine Rotor Discs, Part No. 3075772-1**							RE (-)		Cat.1-Safety	
72 ENG3						Mos	29-Aug-2006				
Eff: 05-Jul-2006 Not Applicable						Hrs					
						Enc					
TFE731-72-3720	**Engine - Turbine Section - Inspect/Replace (If Required) Specific Identified High Pressure (Hp) Turbine Rotor Discs, Part No. 3075772-1**							T (A/R)			
72 ENG3						Mos					
Eff: 05-Jul-2006						Hrs					
						Enc					
TFE731-72-3739	**Engine - By-Pass Section - Install Improved No. 1 Segmented Carbon Seal, P/N 3060457-1 Or -2 (As Applicable), And/Or No. 3 Segmented Carbon Seal, P/N 3060458-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	04-Jan-2023				
Eff: 21-Apr-2008 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-72-3739	**Engine - By-Pass Section - Install Improved No. 1 Segmented Carbon Seal, P/N 3060457-1 Or -2 (As Applicable), And/Or No. 3 Segmented Carbon Seal, P/N 3060458-1**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 21-Apr-2008						Hrs					
						Enc					
TFE731-72-3739	**Engine - By-Pass Section - Install Improved No. 1 Segmented Carbon Seal, P/N 3060457-1 Or -2 (As Applicable), And/Or No. 3 Segmented Carbon Seal, P/N 3060458-1**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 21-Apr-2008						Hrs					
						Enc					
TFE731-72-3740	**Engine - Turbine Section - Install High Pressure Turbine (HPT) Rotor Assembly, P/N 3075819-1 Or P/N 3075821-1 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 13-Aug-2008						Hrs					
						Enc					
TFE731-72-3740	**Engine - Turbine Section - Install High Pressure Turbine (HPT) Rotor Assembly, P/N 3075819-1 Or P/N 3075821-1 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 13-Aug-2008						Hrs					
						Enc					
TFE731-72-3740	**Engine - Turbine Section - Install High Pressure Turbine (HPT) Rotor Assembly, P/N 3075819-1 Or P/N 3075821-1 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 13-Aug-2008						Hrs					
						Enc					
TFE731-72-3741	**Engine - Compressor Section - Install Improved No. 4 Segmented Carbon Seal, P/N 3060437-1, And No. 5 Segmented Carbon Seal, P/N 3060436-1**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	04-Jan-2023				
Eff: 21-Apr-2008 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-72-3741	**Engine - Compressor Section - Install Improved No. 4 Segmented Carbon Seal, P/N 3060437-1, And No. 5 Segmented Carbon Seal, P/N 3060436-1**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 21-Apr-2008						Hrs					
						Enc					
TFE731-72-3741	**Engine - Compressor Section - Install Improved No. 4 Segmented Carbon Seal, P/N 3060437-1, And No. 5 Segmented Carbon Seal, P/N 3060436-1**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 21-Apr-2008						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3758	**Inspect Suspect High Pressure Turbine (HPT) Rotor Assemblies, PN 3072314-2, -3**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 19-Jan-2010						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-72-3758	**Inspect Suspect High Pressure Turbine (HPT) Rotor Assemblies, PN 3072314-2, -3**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 19-Jan-2010						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-72-3758	**Inspect Suspect High Pressure Turbine (HPT) Rotor Assemblies, PN 3072314-2, -3**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 19-Jan-2010						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-72-3759	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal, P/N 3020052-25**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 07-Jun-2011						Hrs					
						Enc					
TFE731-72-3759	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal, P/N 3020052-25**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 07-Jun-2011						Hrs					
						Enc					
TFE731-72-3759	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal, P/N 3020052-25**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 07-Jun-2011						Hrs					
						Enc					
TFE731-72-3759 R1	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal, P/N 3020052-25**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	04-Jan-2023				
Eff: 28-Oct-2011 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-72-3759 R1	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal, P/N 3020052-25**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 28-Oct-2011						Hrs					
						Enc					
TFE731-72-3759 R1	**Engine - Accessory Drives Section - Install Improved Plain Encased Seal, P/N 3020052-25**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 28-Oct-2011						Hrs					
						Enc					
TFE731-72-3762	**Introduction Of New Second Stage Low Pressure Compressor (LPC2) Blade, P/N 3075840-3**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 08-Nov-2010						Hrs					
						Enc					
TFE731-72-3762	**Introduction Of New Second Stage Low Pressure Compressor (LPC2) Blade, P/N 3075840-3**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 08-Nov-2010						Hrs					
						Enc					
TFE731-72-3762	**Introduction Of New Second Stage Low Pressure Compressor (LPC2) Blade, P/N 3075840-3**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 08-Nov-2010						Hrs					
						Enc					
TFE731-72-3764	**Engine - Compressor Section - Remove Specific Identified Third Stage Axial Compressor Disks, P/N 3072397-3**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 14-Jun-2011						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3764	**Engine - Compressor Section - Remove Specific Identified Third Stage Axial Compressor Disks, P/N 3072397-3**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 14-Jun-2011						Hrs					
						Enc					
TFE731-72-3764	**Engine - Compressor Section - Remove Specific Identified Third Stage Axial Compressor Disks, P/N 3072397-3**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 14-Jun-2011						Hrs					
						Enc					
TFE731-72-3771	**Engine - Compressor Section - Introduction Of Alternate Low Pressure Second Stage Axial Compressor (LPC2) Rotor Assembly, P/N 3075841-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 28-Jan-2011						Hrs					
						Enc					
Note: Note: The service bulletin(s) TFE731-72-3711 listed in Table 3 shall be accomplished prior to or concurrent with this service bulletin. The accomplishment instructions outlined in each service bulletin stand alone; therefore, compliance with this service bulletin does not indicate compliance with any other service bulletin. Compliance: This service bulletin may be accomplished at operator's option, when replacement of the axial compressor shroud, PN 3072403-4, or LPC2 rotor assembly, PN 3075841-1, is required.											
TFE731-72-3771	**Engine - Compressor Section - Introduction Of Alternate Low Pressure Second Stage Axial Compressor (LPC2) Rotor Assembly, P/N 3075841-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG2						Mos					
Eff: 28-Jan-2011						Hrs					
						Enc					
Note: Note: The service bulletin(s) TFE731-72-3711 listed in Table 3 shall be accomplished prior to or concurrent with this service bulletin. The accomplishment instructions outlined in each service bulletin stand alone; therefore, compliance with this service bulletin does not indicate compliance with any other service bulletin. Compliance: This service bulletin may be accomplished at operator's option, when replacement of the axial compressor shroud, PN 3072403-4, or LPC2 rotor assembly, PN 3075841-1, is required.											
TFE731-72-3771	**Engine - Compressor Section - Introduction Of Alternate Low Pressure Second Stage Axial Compressor (LPC2) Rotor Assembly, P/N 3075841-2**							T (A/R)		Cat.3-Product Improvement	
72 ENG3						Mos					
Eff: 28-Jan-2011						Hrs					
						Enc					
Note: Note: The service bulletin(s) TFE731-72-3711 listed in Table 3 shall be accomplished prior to or concurrent with this service bulletin. The accomplishment instructions outlined in each service bulletin stand alone; therefore, compliance with this service bulletin does not indicate compliance with any other service bulletin. Compliance: This service bulletin may be accomplished at operator's option, when replacement of the axial compressor shroud, PN 3072403-4, or LPC2 rotor assembly, PN 3075841-1, is required.											
TFE731-72-3773	**Compressor Section - Introduction Of Improved Stage 4 Case And Vane Assemblies, Pn 3074555-10, -11**							T (A/R)		Category 2	
72 ENG1						Mos					
Eff: 08-Jul-2011						Hrs					
						Enc					
TFE731-72-3773	**Compressor Section - Introduction Of Improved Stage 4 Case And Vane Assemblies, Pn 3074555-10, -11**							T (A/R)		Category 2	
72 ENG2						Mos					
Eff: 08-Jul-2011						Hrs					
						Enc					
TFE731-72-3773	**Compressor Section - Introduction Of Improved Stage 4 Case And Vane Assemblies, Pn 3074555-10, -11**							T (A/R)		Category 2	
72 ENG3						Mos					
Eff: 08-Jul-2011						Hrs					
						Enc					
TFE731-72-3777	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 22-Jul-2011						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3777	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 22-Jul-2011						Hrs					
						Enc					
TFE731-72-3777	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 22-Jul-2011						Hrs					
						Enc					
TFE731-72-3777 R1	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 05-Aug-2011						Hrs					
						Enc					
TFE731-72-3777 R1	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 05-Aug-2011						Hrs					
						Enc					
TFE731-72-3777 R1	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 05-Aug-2011						Hrs					
						Enc					
TFE731-72-3777 R2	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							T (A/R)		Cat.2-Reliability	
72 ENG1						Mos					
Eff: 17-Aug-2012						Hrs					
						Enc					
TFE731-72-3777 R2	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							T (A/R)		Cat.2-Reliability	
72 ENG2						Mos					
Eff: 17-Aug-2012						Hrs					
						Enc					
TFE731-72-3777 R2	**Engine - Compressor Section - Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, P/N 3072403-6**							T (A/R)		Cat.2-Reliability	
72 ENG3						Mos					
Eff: 17-Aug-2012						Hrs					
						Enc					
TFE731-72-3786	**Engine - Fan Inlet Housing Installation - Installation Of New Or Reworked Fan Inlet Housing**							RE (-)		Category 3	
72 ENG1						Mos					
Eff: 26-Jul-2013						Hrs					
						Enc					
TFE731-72-3786	**Engine - Fan Inlet Housing Installation - Installation Of New Or Reworked Fan Inlet Housing**							RE (-)		Category 3	
72 ENG2						Mos					
Eff: 26-Jul-2013						Hrs					
						Enc					
TFE731-72-3786	**Engine - Fan Inlet Housing Installation - Installation Of New Or Reworked Fan Inlet Housing**							RE (-)		Category 3	
72 ENG3						Mos					
Eff: 26-Jul-2013						Hrs					
						Enc					
TFE731-72-3801	**ENGINE - COMPRESSOR SECTION - Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5 on TFE731-2, -3, -4, and -5 Model Engines**							RE (-)		Cat.3-Product Improvement	
72 ENG1						Mos					
Eff: 02-Dec-2015						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-3801	**ENGINE - COMPRESSOR SECTION - Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5 on TFE731-2, -3, -4, and -5 Model Engines**						RE (-)		Cat.3-Product Improvement	
72 ENG2					Mos					
Eff: 02-Dec-2015					Hrs					
					Enc					
TFE731-72-3801	**ENGINE - COMPRESSOR SECTION - Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5 on TFE731-2, -3, -4, and -5 Model Engines**						RE (-)		Cat.3-Product Improvement	
72 ENG3					Mos					
Eff: 02-Dec-2015					Hrs					
					Enc					
TFE731-72-3805 Rev 1	**Engine - Compressor Section - Identify and Replace Specific Low Pressure Compressor 4th Stage (LPC4) Case and Vane Assembly, PN 3074555-10 or PN 3074555-11, on TFE731-2, -3, -4, -5 Series Engine Models (INACTIVE FOR FURTHER ACCOMPLISHMENT) (Deleted)**						RE (-)			
72 ENG1					Mos					
Eff: 10-Jul-2019					Hrs					
					Enc					
TFE731-72-3805 Rev 1	**Engine - Compressor Section - Identify and Replace Specific Low Pressure Compressor 4th Stage (LPC4) Case and Vane Assembly, PN 3074555-10 or PN 3074555-11, on TFE731-2, -3, -4, -5 Series Engine Models (INACTIVE FOR FURTHER ACCOMPLISHMENT) (Deleted)**						RE (-)			
72 ENG2					Mos					
Eff: 10-Jul-2019					Hrs					
					Enc					
TFE731-72-3805 Rev 1	**Engine - Compressor Section - Identify and Replace Specific Low Pressure Compressor 4th Stage (LPC4) Case and Vane Assembly, PN 3074555-10 or PN 3074555-11, on TFE731-2, -3, -4, -5 Series Engine Models (INACTIVE FOR FURTHER ACCOMPLISHMENT) (Deleted)**						RE (-)			
72 ENG3					Mos					
Eff: 10-Jul-2019					Hrs					
					Enc					
TFE731-72-5163 Rev 5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots on TFE731 Model Engines**						T (A/R)		Category 3, Optional	
72 ENG1					Mos					
Eff: 27-Nov-2019					Hrs					
					Enc					
TFE731-72-5163 Rev 5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots on TFE731 Model Engines**						T (A/R)		Category 3, Optional	
72 ENG2					Mos					
Eff: 27-Nov-2019					Hrs					
					Enc					
TFE731-72-5163 Rev 5	**Engine - By-Pass Section - Provide Eddy Current Inspection Instructions for the Fan Disk Dovetail Slots on TFE731 Model Engines**						T (A/R)		Category 3, Optional	
72 ENG3					Mos					
Eff: 27-Nov-2019					Hrs					
					Enc					
TFE731-72-A3748	**Engine - Compressor Section - Replace Specific Identified Second Stage Low Pressure Compressor (LPC2) And Third Stage Low Pressure Compressor (LPC3) Rotor Discs**						RE (-)		Cat.1-Safety	
72 ENG1					Mos	30-Mar-2010				
Eff: 21-Aug-2008 Not Applicable	By Part number				Hrs					
					Enc					
TFE731-72-A3748	**Engine - Compressor Section - Replace Specific Identified Second Stage Low Pressure Compressor (LPC2) And Third Stage Low Pressure Compressor (LPC3) Rotor Discs**						RE (-)		Cat.1-Safety	
72 ENG2					Mos	12-Oct-2010				
Eff: 21-Aug-2008 Complied With					Hrs					
					Enc					
TFE731-72-A3748	**Engine - Compressor Section - Replace Specific Identified Second Stage Low Pressure Compressor (LPC2) And Third Stage Low Pressure Compressor (LPC3) Rotor Discs**						RE (-)		Cat.1-Safety	
72 ENG3					Mos	12-Oct-2010				
Eff: 21-Aug-2008 Complied With					Hrs					
					Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-72-A3803	**Compressor Section - Replacement Of Specific No. 4 High Pressure Rotor Roller Bearing On TFE731-2, -2A, -3, And -5 Model Engines, Alert Service Bulletin**							RE (-)		Category 1	
72 ENG1						Mos	30-Sep-2015				
Complied With						Hrs					
						Enc					
TFE731-72-A3803	**Compressor Section - Replacement Of Specific No. 4 High Pressure Rotor Roller Bearing On TFE731-2, -2A, -3, And -5 Model Engines, Alert Service Bulletin**							RE (-)		Category 1	
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-72-A3803	**Compressor Section - Replacement Of Specific No. 4 High Pressure Rotor Roller Bearing On TFE731-2, -2A, -3, And -5 Model Engines, Alert Service Bulletin**							RE (-)		Category 1	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-A72-3140	**Replace Tie Rod**							RE (-)		Recommended	
72 ENG1						Mos					
Eff: 20-Jun-1980						Hrs					
						Enc					
TFE731-A72-3140	**Replace Tie Rod**							RE (-)		Recommended	
72 ENG2						Mos	28-Jan-1994				
Eff: 20-Jun-1980 Complied With						Hrs					
						Enc					
TFE731-A72-3140	**Replace Tie Rod**							RE (-)		Recommended	
72 ENG3						Mos					
Eff: 20-Jun-1980						Hrs					
						Enc					
TFE731-A72-3140 R1	**Replace Tie Rod**							RE (-)		Recommended	
72 ENG1						Mos	24-Jan-1995				
Eff: 16-Jun-1982 Not Applicable						Hrs					
						Enc					
TFE731-A72-3140 R1	**Replace Tie Rod**							RE (-)		Recommended	
72 ENG2						Mos	17-Apr-1997				
Eff: 16-Jun-1982 Complied With						Hrs					
						Enc					
TFE731-A72-3140 R1	**Replace Tie Rod**							T (A/R)		Recommended	
72 ENG3						Mos					
Eff: 16-Jun-1982						Hrs					
						Enc					
TFE731-A72-3328	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 26-Dec-1985						Hrs					
						Enc					
TFE731-A72-3328	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 26-Dec-1985						Hrs					
						Enc					
TFE731-A72-3328	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 26-Dec-1985						Hrs					
						Enc					
TFE731-A72-3328 R1	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 17-Feb-1986						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3328 R1	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 17-Feb-1986						Hrs					
						Enc					
TFE731-A72-3328 R1	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 17-Feb-1986						Hrs					
						Enc					
TFE731-A72-3328 R2	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 04-Apr-1986						Hrs					
						Enc					
TFE731-A72-3328 R2	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 04-Apr-1986						Hrs					
						Enc					
TFE731-A72-3328 R2	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 04-Apr-1986						Hrs					
						Enc					
TFE731-A72-3328 R3	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 24-Oct-1986						Hrs					
						Enc					
TFE731-A72-3328 R3	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 24-Oct-1986						Hrs					
						Enc					
TFE731-A72-3328 R3	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 24-Oct-1986						Hrs					
						Enc					
TFE731-A72-3328 R4	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos	24-Jan-1995				
Eff: 24-Jun-1988 Complied With						Hrs					
						Enc					
TFE731-A72-3328 R4	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 24-Jun-1988						Hrs					
						Enc					
TFE731-A72-3328 R4	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos	28-Dec-1992				
Eff: 24-Jun-1988 Complied With						Hrs					
						Enc					
TFE731-A72-3328 R5	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 31-May-1995						Hrs					
						Enc					
TFE731-A72-3328 R5	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos	14-Jan-2000				
Eff: 31-May-1995 Not Applicable						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3328 R5	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 31-May-1995						Hrs					
						Enc					
TFE731-A72-3328 R6	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3328 R6	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3328 R6	**REPLACEMENT OF FAN ROTOR DISC (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3376	**Replace Specific Serial Numbered HP Turbine Rotor Disc**							RE (-)		Alert	
72 ENG1						Mos	24-Jan-1995				
Eff: 19-Aug-1988 Complied With						Hrs					
						Enc					
TFE731-A72-3376	**Replace Specific Serial Numbered HP Turbine Rotor Disc**							RE (-)		Alert	
72 ENG2						Mos	19-Dec-1990				
Eff: 19-Aug-1988 Not Applicable						Hrs					
						Enc					
TFE731-A72-3376	**Replace Specific Serial Numbered HP Turbine Rotor Disc**							RE (-)		Alert	
72 ENG3						Mos	04-May-1995				
Eff: 19-Aug-1988 Not Applicable						Hrs					
						Enc					
TFE731-A72-3388	**Inspection Specific Serial Numbered HP Turbine Rotor Disc**							T (A/R)		Recommended	
72 ENG1						Mos					
Eff: 28-Feb-1989						Hrs					
						Enc					
TFE731-A72-3388	**Inspection Specific Serial Numbered HP Turbine Rotor Disc**							RE (-)		Recommended	
72 ENG2						Mos	19-Dec-1990				
Eff: 28-Feb-1989 Not Applicable						Hrs					
						Enc					
TFE731-A72-3388	**Inspection Specific Serial Numbered HP Turbine Rotor Disc**							RE (-)		Recommended	
72 ENG3						Mos	28-Dec-1992				
Eff: 28-Feb-1989 Not Applicable						Hrs					
						Enc					
TFE731-A72-3424	**ENGINE – BY-PASS SECTION – Replacement of Fan Rotor Assembly Containing Specific Serial Numbered Disc and Hub Manufactured from the Same Material Heat Code. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-A72-3424	**ENGINE – BY-PASS SECTION – Replacement of Fan Rotor Assembly Containing Specific Serial Numbered Disc and Hub Manufactured from the Same Material Heat Code. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Complied With	Incorporated in Production					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3424	**ENGINE – BY-PASS SECTION – Replacement of Fan Rotor Assembly Containing Specific Serial Numbered Disc and Hub Manufactured from the Same Material Heat Code. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos	28-Dec-1990				
Not Applicable						Hrs					
						Enc					
TFE731-A72-3424 R1	**ENGINE – BY-PASS SECTION – Replacement of Fan Rotor Assembly Containing Specific Serial Numbered Disc and Hub Manufactured from the Same Material Heat Code. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3424 R1	**ENGINE – BY-PASS SECTION – Replacement of Fan Rotor Assembly Containing Specific Serial Numbered Disc and Hub Manufactured from the Same Material Heat Code. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3424 R1	**ENGINE – BY-PASS SECTION – Replacement of Fan Rotor Assembly Containing Specific Serial Numbered Disc and Hub Manufactured from the Same Material Heat Code. (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3432	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 11-Apr-1991						Hrs					
						Enc					
TFE731-A72-3432	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 11-Apr-1991						Hrs					
						Enc					
TFE731-A72-3432	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos	04-May-1995				
Eff: 11-Apr-1991 Not Applicable						Hrs					
						Enc					
TFE731-A72-3432 R1	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 30-Apr-1991						Hrs					
						Enc					
TFE731-A72-3432 R1	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 30-Apr-1991						Hrs					
						Enc					
TFE731-A72-3432 R1	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 30-Apr-1991						Hrs					
						Enc					
TFE731-A72-3432 R2	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos	19-Jun-1991				
Eff: 03-Jun-1991 Complied With						Hrs					
						Enc					
TFE731-A72-3432 R2	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 03-Jun-1991 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3432 R2	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos	19-Jun-1991				
Eff: 03-Jun-1991 Complied With						Hrs					
						Enc					
TFE731-A72-3432 R3	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 17-Oct-1991						Hrs					
						Enc					
TFE731-A72-3432 R3	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 17-Oct-1991						Hrs					
						Enc					
TFE731-A72-3432 R3	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 17-Oct-1991						Hrs					
						Enc					
TFE731-A72-3432 R4	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos	27-Dec-1997				
Eff: 06-Aug-1993 Complied With						Hrs					
						Enc					
TFE731-A72-3432 R4	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 06-Aug-1993						Hrs					
						Enc					
TFE731-A72-3432 R4	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 06-Aug-1993						Hrs					
						Enc					
TFE731-A72-3432 R5	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-A72-3432 R5	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Complied With	Incorporated in Production					Hrs					
						Enc					
TFE731-A72-3432 R5	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos	14-Jan-2000				
Not Applicable						Hrs					
						Enc					
TFE731-A72-3432 R6	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3432 R6	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3432 R6	**INSPECTION OF FAN ROTOR DISCS (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 23-May-2007						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3474	**Replacement of Specific Serial Numbered LP Turbine 3Rd Stage Rotor Disc**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 03-Apr-1992 Complied With						Hrs					
						Enc					
TFE731-A72-3474	**Replacement of Specific Serial Numbered LP Turbine 3Rd Stage Rotor Disc**							RE (-)			
72 ENG2						Mos	28-Dec-1992				
Eff: 03-Apr-1992 Not Applicable						Hrs					
						Enc					
TFE731-A72-3474	**Replacement of Specific Serial Numbered LP Turbine 3Rd Stage Rotor Disc**							T (A/R)			
72 ENG3						Mos					
Eff: 03-Apr-1992						Hrs					
						Enc					
TFE731-A72-3504	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos	28-Dec-1992				
Eff: 25-Nov-1992 Complied With						Hrs					
						Enc					
TFE731-A72-3504	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos	28-Dec-1992				
Eff: 25-Nov-1992 Not Applicable						Hrs					
						Enc					
TFE731-A72-3504	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos	28-Dec-1992				
Eff: 25-Nov-1992 Not Applicable						Hrs					
						Enc					
TFE731-A72-3504 R1	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 02-Jul-1993						Hrs					
						Enc					
TFE731-A72-3504 R1	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 02-Jul-1993						Hrs					
						Enc					
TFE731-A72-3504 R1	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 02-Jul-1993						Hrs					
						Enc					
TFE731-A72-3504 R2	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-A72-3504 R2	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3504 R2	**ENGINE – BY-PASS SECTION – Inspection of Fan Rotor Assembly containing Disc and Hub, Part No. 3072162-1 thru -4, 3073436-1 thru -4, 3073539-2 or 3074529-2 (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-A72-3544	**Repl Specific 1St & 2Nd Stg LP Turb Disks**							RE (-)			
72 ENG1						Mos	24-Jan-1995				
Eff: 08-Oct-1993						Hrs					
						Enc					
TFE731-A72-3544	**Repl Specific 1St & 2Nd Stg LP Turb Disks**							RE (-)			
72 ENG2						Mos	01-Jun-1994				
Eff: 08-Oct-1993 Not Applicable	by S/N					Hrs					
						Enc					
TFE731-A72-3544	**Repl Specific 1St & 2Nd Stg LP Turb Disks**							T (A/R)			
72 ENG3						Mos					
Eff: 08-Oct-1993						Hrs					
						Enc					
TFE731-A72-3557	**Replace Specific 1St & 2Nd Stg LP Turbine Discs**							RE (-)		Alert	
72 ENG1						Mos	01-Jun-1994				
Eff: 12-May-1994 Complied With						Hrs					
						Enc					
TFE731-A72-3557	**Replace Specific 1St & 2Nd Stg LP Turbine Discs**							RE (-)		Alert	
72 ENG2						Mos	14-Jan-2000				
Eff: 12-May-1994 Not Applicable						Hrs					
						Enc					
TFE731-A72-3557	**Replace Specific 1St & 2Nd Stg LP Turbine Discs**							RE (-)		Alert	
72 ENG3						Mos	01-Jun-1994				
Eff: 12-May-1994 Not Applicable	BY S/N-P/N					Hrs					
						Enc					
TFE731-A72-3569	**ENGINE – BY-PASS SECTION – Fan Rotor Disc Cycle Service Life Reduction (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos	24-Jan-1995				
Eff: 31-May-1995						Hrs					
						Enc					
TFE731-A72-3569	**ENGINE – BY-PASS SECTION – Fan Rotor Disc Cycle Service Life Reduction (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos	11-Apr-1996				
Eff: 31-May-1995 Complied With						Hrs					
						Enc					
TFE731-A72-3569	**ENGINE – BY-PASS SECTION – Fan Rotor Disc Cycle Service Life Reduction (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos	31-May-1995				
Eff: 31-May-1995 Complied With						Hrs					
						Enc					
TFE731-A72-3569 R1	**ENGINE – BY-PASS SECTION – Fan Rotor Disc Cycle Service Life Reduction (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3569 R1	**ENGINE – BY-PASS SECTION – Fan Rotor Disc Cycle Service Life Reduction (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos	06-Apr-1996				
Eff: 23-May-2007 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3569 R1	**ENGINE – BY-PASS SECTION – Fan Rotor Disc Cycle Service Life Reduction (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 23-May-2007						Hrs					
						Enc					
TFE731-A72-3578	**ENGINE – BY-PASS SECTION – Inspect Specific Serial Numbered Fan Rotor Discs (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG1						Mos	19-Sep-1995				
Eff: 31-May-1995 Not Applicable	by PN					Hrs					
						Enc					
TFE731-A72-3578	**ENGINE – BY-PASS SECTION – Inspect Specific Serial Numbered Fan Rotor Discs (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG2						Mos	14-Jan-2000				
Eff: 31-May-1995 Not Applicable						Hrs					
						Enc					
TFE731-A72-3578	**ENGINE – BY-PASS SECTION – Inspect Specific Serial Numbered Fan Rotor Discs (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)		Category 1	
72 ENG3						Mos	19-Sep-1995				
Eff: 31-May-1995 Not Applicable	BY SN					Hrs					
						Enc					
TFE731-A72-3624	**One Time Oil & Filter Resample**							RE (-)		Cat.2-Reliability	
72 ENG1						Mos	04-Nov-1980				
Eff: 21-Jan-1998 Complied With						Hrs	0				
						Enc	0				
TFE731-A72-3624	**One Time Oil & Filter Resample**							RE (-)		Cat.2-Reliability	
72 ENG2						Mos	14-Jan-2000				
Eff: 21-Jan-1998 Not Applicable						Hrs					
						Enc					
TFE731-A72-3624	**One Time Oil & Filter Resample**							RE (-)		Cat.2-Reliability	
72 ENG3						Mos	14-Jan-2000				
Eff: 21-Jan-1998 Not Applicable						Hrs					
						Enc					
TFE731-A72-3625	**ENGINE - COMPRESSOR SECTION - Replace Specific Identified HP Compressor Impellers(INACTIVATED)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 26-Feb-1998						Hrs					
						Enc					
TFE731-A72-3625	**ENGINE - COMPRESSOR SECTION - Replace Specific Identified HP Compressor Impellers(INACTIVATED)**							RE (-)		Category 1	
72 ENG2						Mos	17-Apr-1997				
Eff: 26-Feb-1998 Complied With						Hrs					
						Enc					
TFE731-A72-3625	**ENGINE - COMPRESSOR SECTION - Replace Specific Identified HP Compressor Impellers(INACTIVATED)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 26-Feb-1998						Hrs					
						Enc					
TFE731-A72-3625 R1	**ENGINE - COMPRESSOR SECTION - Replace Specific Identified HP Compressor Impellers(INACTIVATED)**							RE (-)		Category 1	
72 ENG1						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					
TFE731-A72-3625 R1	**ENGINE - COMPRESSOR SECTION - Replace Specific Identified HP Compressor Impellers(INACTIVATED)**							RE (-)		Category 1	
72 ENG2						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3625 R1	**ENGINE - COMPRESSOR SECTION - Replace Specific Identified HP Compressor Impellers(INACTIVATED)**							RE (-)		Category 1	
72 ENG3						Mos					
Eff: 10-Aug-1999						Hrs					
						Enc					
TFE731-A72-3631	**Engine - Turbine Section - Replace Specific Serial Numbered HP Turbine Rotor Assembly Discs**							RE (-)		Cat.1-Safety	
72 ENG1						Mos	13-Jan-2000				
Eff: 18-May-1998 Not Applicable						Hrs					
						Enc					
TFE731-A72-3631	**Engine - Turbine Section - Replace Specific Serial Numbered HP Turbine Rotor Assembly Discs**							RE (-)		Cat.1-Safety	
72 ENG2						Mos	14-Jan-2000				
Eff: 18-May-1998 Not Applicable						Hrs					
						Enc					
TFE731-A72-3631	**Engine - Turbine Section - Replace Specific Serial Numbered HP Turbine Rotor Assembly Discs**							T (A/R)		Cat.1-Safety	
72 ENG3						Mos					
Eff: 18-May-1998						Hrs					
						Enc					
TFE731-A72-3636	**(Inactive For Further Accomplishment) Engine - Review Engine Log Book And Supply Data For Specific HP Compressor Impellers**							RE (-)			
72 ENG1						Mos	16-Sep-1998				
Complied With						Hrs					
						Enc					
TFE731-A72-3636 R1	**(Inactive For Further Accomplishment) Engine - Review Engine Log Book And Supply Data For Specific HP Compressor Impellers**							T (A/R)			
72 ENG1						Mos					
Eff: 02-Nov-1998						Hrs					
						Enc					
TFE731-A72-3636 R1	**(Inactive For Further Accomplishment) Engine - Review Engine Log Book And Supply Data For Specific HP Compressor Impellers**							RE (-)			
72 ENG2						Mos	16-Sep-1998				
Eff: 02-Nov-1998 Complied With						Hrs					
						Enc					
TFE731-A72-3636 R1	**(Inactive For Further Accomplishment) Engine - Review Engine Log Book And Supply Data For Specific HP Compressor Impellers**							T (A/R)			
72 ENG3						Mos					
Eff: 02-Nov-1998						Hrs					
						Enc					
TFE731-A72-3641	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG1						Mos					
Eff: 24-Nov-1998						Hrs					
						Enc					
TFE731-A72-3641	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG2						Mos					
Eff: 24-Nov-1998						Hrs					
						Enc					
TFE731-A72-3641	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG3						Mos					
Eff: 24-Nov-1998						Hrs					
						Enc					
TFE731-A72-3641 R1	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG1						Mos					
Eff: 20-Oct-1999						Hrs					
						Enc					
TFE731-A72-3641 R1	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG2						Mos					
Eff: 20-Oct-1999						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3641 R1	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG3					Mos					
Eff: 20-Oct-1999					Hrs					
					Enc					
TFE731-A72-3641 R2	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG1					Mos					
Eff: 06-Nov-2000					Hrs					
					Enc					
TFE731-A72-3641 R2	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG2					Mos					
Eff: 06-Nov-2000					Hrs					
					Enc					
TFE731-A72-3641 R2	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG3					Mos					
Eff: 06-Nov-2000					Hrs					
					Enc					
TFE731-A72-3641 R3	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG1					Mos					
Eff: 08-May-2001					Hrs					
					Enc					
TFE731-A72-3641 R3	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG2					Mos					
Eff: 08-May-2001					Hrs					
					Enc					
TFE731-A72-3641 R3	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG3					Mos					
Eff: 08-May-2001					Hrs					
					Enc					
TFE731-A72-3641 R4	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG1					Mos					
Eff: 27-Aug-2003					Hrs					
					Enc					
TFE731-A72-3641 R4	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG2					Mos					
Eff: 27-Aug-2003					Hrs					
					Enc					
TFE731-A72-3641 R4	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG3					Mos					
Eff: 27-Aug-2003					Hrs					
					Enc					
TFE731-A72-3641 R5	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG1					Mos					
Eff: 02-Jun-2004					Hrs					
					Enc					
TFE731-A72-3641 R5	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG2					Mos					
Eff: 02-Jun-2004					Hrs					
					Enc					
TFE731-A72-3641 R5	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPc) Compressor Impeller**						RE (-)		Cat.1-Safety	
72 ENG3					Mos					
Eff: 02-Jun-2004					Hrs					
					Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3641 R6	**Engine - Compressor Section - Perform Eddy Current Inspection of HP (HPC) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG1						Mos	31-Mar-2006				
Eff: 09-Jun-2005 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-A72-3641 R6	**Engine - Compressor Section - Perform Eddy Current Inspection of HP (HPC) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG2						Mos	22-Aug-2006				
Eff: 09-Jun-2005 Complied With						Hrs					
						Enc					
TFE731-A72-3641 R6	**Engine - Compressor Section - Perform Eddy Current Inspection of HP (HPC) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG3						Mos	29-Aug-2006				
Eff: 09-Jun-2005 Complied With						Hrs					
						Enc					
TFE731-A72-3641 R7	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE		Cat.1-Safety	**≈19-Feb-2036**
72 ENG1						Mos	04-Jan-2023				
Complied With						Hrs	13,282.8	4,200		17,482.8	3,955.7 Hrs
						Enc	7,730				
TFE731-A72-3641 R7	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG2						Mos					
Eff: 06-Jul-2010						Hrs					
						Enc					
TFE731-A72-3641 R7	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)		Cat.1-Safety	
72 ENG3						Mos					
Eff: 06-Jul-2010						Hrs					
						Enc					
TFE731-A72-3641WA	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-A72-3641WA	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-A72-3641WA	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-A72-3641WA R1	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					
TFE731-A72-3641WA R1	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)			
72 ENG2						Mos					
						Hrs					
						Enc					
TFE731-A72-3641WA R1	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)			
72 ENG3						Mos					
						Hrs					
						Enc					
TFE731-A72-3641WA R2	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							RE (-)			
72 ENG1						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3641WA R2	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R2	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R3	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R3	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R3	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R4	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R4	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R4	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R5	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG1					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R5	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG2					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R5	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**						RE (-)			
72 ENG3					Mos					
					Hrs					
					Enc					
TFE731-A72-3641WA R6	**Engine - Compressor Section - Perform Eddy Current Inspection of HP (HPC) Compressor Impeller**						T (A/R)			
72 ENG1					Mos					
Eff: 06-Jul-2010					Hrs					
					Enc					
TFE731-A72-3641WA R6	**Engine - Compressor Section - Perform Eddy Current Inspection of HP (HPC) Compressor Impeller**						T (A/R)			
72 ENG2					Mos					
Eff: 06-Jul-2010					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A72-3641WA R6	**Engine - Compressor Section - Perform Eddy Current Inspection of HP (HPC) Compressor Impeller**							T (A/R)			
72 ENG3						Mos					
Eff: 06-Jul-2010						Hrs					
						Enc					
TFE731-A72-3641WA R7	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							T (A/R)		Cat.1-Safety	
72 ENG1						Mos					
Eff: 06-Jul-2010						Hrs					
						Enc					
TFE731-A72-3641WA R7	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							T (A/R)		Cat.1-Safety	
72 ENG2						Mos					
Eff: 06-Jul-2010						Hrs					
						Enc					
TFE731-A72-3641WA R7	**Engine - Compressor Section - Perform Eddy Current Inspection Of HP (HPC) Compressor Impeller**							T (A/R)		Cat.1-Safety	
72 ENG3						Mos					
Eff: 06-Jul-2010						Hrs					
						Enc					
TFE731-A72-3668	**Engine - By-Pass Section - Fan Rotor Disc Removal Schedule (Plan)**							RE (-)			
72 ENG1						Mos	07-Jan-2002				
Eff: 25-Oct-2000 Complied With						Hrs	9,831				
						Enc	5,855				
TFE731-A72-3668	**Engine - By-Pass Section - Fan Rotor Disc Removal Schedule (Plan)**							RE (-)			
72 ENG2						Mos	13-Sep-2001				
Eff: 25-Oct-2000 Complied With	PCW					Hrs					
						Enc					
TFE731-A72-3668	**Engine - By-Pass Section - Fan Rotor Disc Removal Schedule (Plan)**							RE (-)			
72 ENG3						Mos	29-Aug-2006				
Eff: 25-Oct-2000 Complied With						Hrs					
						Enc					
TFE731-A72-3700	**Inspection of Specific Low Pressure 1St Stg (A5) Turbine (LPT1) Nozzle/ITT Ducts**							RE (-)			
72 ENG1						Mos	04-Jan-2023				
Eff: 22-Apr-2004 Complied With						Hrs					
						Enc					
TFE731-A73-3128	**Engine Fuel And Control - Distribution - Install Flex Tube Assembly, P/N 399-5500-0003 Or 3074376-1**							RE (-)			
72 ENG1						Mos	30-May-1997				
Eff: 26-Feb-1997 Complied With						Hrs					
						Enc					
TFE731-A73-3128	**Engine Fuel And Control - Distribution - Install Flex Tube Assembly, P/N 399-5500-0003 Or 3074376-1**							RE (-)			
72 ENG2						Mos	20-May-1997				
Eff: 26-Feb-1997 Complied With						Hrs					
						Enc					
TFE731-A73-3128	**Engine Fuel And Control - Distribution - Install Flex Tube Assembly, P/N 399-5500-0003 Or 3074376-1**							RE (-)			
72 ENG3						Mos					
Eff: 26-Feb-1997						Hrs					
						Enc					
TFE731-A73-3128 R1	**Engine Fuel And Control - Distribution - Install Flex Tube Assembly, P/N 399-5500-0003 Or 3074376-1**							T (A/R)			
72 ENG1						Mos					
Eff: 17-Aug-2000						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-A73-3128 R1	**Engine Fuel And Control - Distribution - Install Flex Tube Assembly, P/N 399-5500-0003 Or 3074376-1**							T (A/R)			
72 ENG2						Mos					
Eff: 17-Aug-2000						Hrs					
						Enc					
TFE731-A73-3128 R1	**Engine Fuel And Control - Distribution - Install Flex Tube Assembly, P/N 399-5500-0003 Or 3074376-1**							T (A/R)			
72 ENG3						Mos					
Eff: 17-Aug-2000						Hrs					
						Enc					
▼ 73 - ENGINE - FUEL AND CONTROL											
	Engine - Solenoid Control Valve							RE (O/C)			
73 A/F	No.1					Mos	31-Mar-2006				
109696-3-1						Hrs					
P-2905						Ldg					
						Flt					
	Engine - Solenoid Control Valve							RE (O/C)			
73 A/F	No.2					Mos	23-Dec-2009				
109696-3-1						Hrs					
P-2537						Ldg					
						Flt					
	Engine - Solenoid Control Valve							RE (O/C)			
73 A/F	No.3					Mos	23-Dec-2009				
109696-3-1						Hrs					
P-2508						Ldg					
						Flt					
	Engine Digital Electronic Engine Control (DEEC 1) Computer							RE (O/C)			
73 A/F	No.1					Mos	24-Mar-2021				
2119020-1001						Hrs					
50-AK0222						Ldg					
						Flt					
	Engine Digital Electronic Engine Control (DEEC 2) Computer							RE (O/C)			
73 A/F	No.2	0				Mos	12-Jun-2001				
2119020	New	0				Hrs					
120-AK0329		0				Ldg					
						Flt					
	Engine Digital Electronic Engine Control (DEEC 3) Computer							RE (O/C)			
73 A/F	No.3					Mos	25-May-2000				
2119020-1						Hrs					
118-V0125						Ldg					
						Flt					
	Engine Fuel Flow Indicator							RE (O/C)			
73 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine Fuel Flow Indicator							RE (O/C)			
73 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Engine Fuel Flow Indicator							RE (O/C)			
	73 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Flow Transmitter							RE (O/C)			
	73 A/F	No.1					Mos	24-Mar-2021				
	9-127-27						Hrs					
	837						Ldg					
							Flt					
		Engine Fuel Flow Transmitter							RE (O/C)			
	73 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Flow Transmitter							RE (O/C)			
	73 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Flowmeter							RE (O/C)			
	73 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Flowmeter							RE (O/C)			
	73 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Low Pressure Switch							RE (O/C)			
	73 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Low Pressure Switch							RE (O/C)			
	73 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Low Pressure Switch							RE (O/C)			
	73 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Pressure Switch							RE (O/C)			
	73 A/F	No.1					Mos	24-Mar-2021				
	8G1256-1						Hrs					
	1947						Ldg					
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Fuel Pressure Switch							RE (O/C)			
	73 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Pressure Switch							RE (O/C)			
	73 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Pump							RE (O/C)			
	73 ENG1						Mos	04-Jan-2023				
	3070850-14						Hrs	13,282.8				
	MX-340687						Enc	7,730				
		Engine Fuel Pump							RE (O/C)			
	73 ENG2						Mos	31-Oct-1980				
	3010850-14						Hrs	0				
	MX-373386C						Enc	0				
		Engine Fuel Pump							RE (O/C)			
	73 ENG3			0			Mos	03-Feb-2004				
	3070850-28	Overhauled		0			Hrs	10,629.1				
	MX298163			0			Enc	6,357				
		Engine Fuel Temperature Sensor							RE (O/C)			
	73 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Temperature Sensor							RE (O/C)			
	73 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Fuel Temperature Sensor							RE (O/C)			
	73 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Flow Divider/Drain Valve							RE (O/C)			
	73 ENG1						Mos	31-Mar-2006				
	394396-1-1						Hrs					
	P-3002						Enc					
		Flow Divider/Drain Valve							RE (O/C)			
	73 ENG2						Mos	31-Oct-1980				
	394396-1-1						Hrs	0				
	P-1922						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Flow Divider/Drain Valve							RE (O/C)			
73 ENG3	394396-1-1						Mos	04-Dec-1980				
	P-3068						Hrs	0				
							Enc	0				
		Fuel Control Unit							RE (O/C)			
73 ENG1	3070800-22						Mos	04-Jan-2023				
	4050CPT						Hrs	13,282.8				
							Enc	7,730				
		Fuel Control Unit							RE (O/C)			
73 ENG2	3070800-22	Overhauled		0			Mos	25-May-2000				
	A8222C			0			Hrs	8,741.2				
				0			Enc	5,571				
		Fuel Control Unit							RE (O/C)			
73 ENG3	3070800-22						Mos	26-Mar-2021				
	A4916CPT						Hrs	13,116.3				
							Enc	7,752				
		Fuel Heater							RE (O/C)			
73 ENG1	158670-5						Mos	31-Mar-2006				
	79-1804						Hrs					
							Enc					
		Fuel Heater							RE (O/C)			
73 ENG2	158670-5						Mos	31-Oct-1980				
	78-1360						Hrs	0				
							Enc	0				
		Fuel Heater							RE (O/C)			
73 ENG3	158670-5						Mos	04-Dec-1980				
	78-1332						Hrs	0				
							Enc	0				
		Fuel Totalizer							RE (O/C)			
73 A/F	9-138-01	Serviceable					Mos	24-Sep-2024				
	33						Hrs	13,400.7				
							Ldg	9,055				
							Flt	9,055				
		Fuel/Oil Cooler							RE (O/C)			
73 ENG1	158610-8						Mos	31-Mar-2006				
	30-3011						Hrs					
							Enc					
		Fuel/Oil Cooler							RE (O/C)			
73 ENG2	Unknown						Mos	31-Oct-1980				
	Unknown						Hrs	0				
							Enc	0				
		Fuel/Oil Cooler							RE (O/C)			
73 ENG3	Unknown						Mos	04-Dec-1980				
	Unknown						Hrs	0				
							Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Manifold Assembly, Fuel							RE (O/C)			
	73 ENG1						Mos	26-Jul-2022				
	3073591-2	Overhauled			0		Hrs					
	93-464						Enc					
		Manifold Assembly, Fuel							RE (O/C)			
	73 ENG2				0		Mos					
	3073591-2	Overhauled			0		Hrs	11,473.6				
	2-258C				0		Enc	6,903				
		Manifold Assembly, Fuel							RE (O/C)			
	73 ENG3				0		Mos					
	3073591-2	Overhauled			0		Hrs	11,703.4				
	91-253C				0		Enc	6,884				
		Pressure Limiter Valve							RE (O/C)			
	73 ENG1						Mos	31-Mar-2006				
	3070685-6						Hrs					
	A6025						Enc					
		Pressure Limiter Valve							RE (O/C)			
	73 ENG2						Mos	31-Oct-1980				
	3070685-6						Hrs	0				
	A4153						Enc	0				
		Pressure Limiter Valve							RE (O/C)			
	73 ENG3						Mos	04-Dec-1980				
	3070685-6						Hrs	0				
	A5997						Enc	0				
		Surge Bleed Valve							RE (O/C)			
	73 ENG1						Mos	31-Mar-2006				
	978812-7-1						Hrs					
	12445						Enc					
		Surge Bleed Valve							RE (O/C)			
	73 ENG2						Mos	31-Oct-1980				
	978812-5-1						Hrs	0				
	P-1443C						Enc	0				
		Surge Bleed Valve							RE (O/C)			
	73 ENG3						Mos	04-Dec-1980				
	978812-5-1						Hrs	0				
	P-845C						Enc	0				
730800		**ICA Digital Electronic Engines Controls (DEEC)**							RE		ICA	
	73 A/F						Mos	14-Sep-2023	72		14-Sep-2029	4.5 Years
							Hrs	13,276.7				
							Ldg	8,977				
							Flt	8,977				
73-20-01-710-802-01		**Operational Test of the Engine 1 Digital Electronic Computer (Deec 1) Dual Power Supply**							RE (N/A)		Acft Maint Ops (5-10)	
	73 A/F						Mos					
							Hrs					
							Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
73-20-01-710-802-01 (5-40)	**Operational Test of the Engine 1 Digital Electronic Computer (Deec 1) Dual Power Supply**							RE (N/A)		AWL (5-40), CMR	
73 A/F						Mos					
						Hrs					
						Ldg					
						Flt					
73-21-02-001	**Remove and Replace Fuel Filter Element (Routine)**							RE		LMM - Requirement	**≈21-Feb-2026**
73 ENG1	PKG 600/800 Hour					Mos	04-Jan-2023				
						Hrs	13,282.8	600	+50	13,882.8	355.7 Hrs (+50)
Ref:73-21-02						Enc	7,730				
Note: Fuel filter replacement may be aligned with airframe inspection, not to exceed 650 hours between filter replacement											
73-21-02-001	**Remove and Replace Fuel Filter Element (Routine)**							RE		LMM - Requirement	**≈09-Mar-2026**
73 ENG2	PKG 600/800 Hour					Mos	07-Mar-2024				
						Hrs	13,017.5	600	+50	13,617.5	371.5 Hrs (+50)
Ref:73-21-02						Enc	7,852				
Note: Fuel filter replacement may be aligned with airframe inspection, not to exceed 650 hours between filter replacement											
73-21-02-001	**Remove and Replace Fuel Filter Element (Routine)**							RE		LMM - Requirement	**≈12-Mar-2025**
73 ENG3	PKG 600/800 Hour					Mos	26-Feb-2014				
						Hrs	12,890.5	600	+50	13,490.5	14.7 Hrs (+50)
Ref:73-21-02						Enc	7,587				
Note: Fuel filter replacement may be aligned with airframe inspection, not to exceed 650 hours between filter replacement											
732117	**Download No. 1 Engine Deec**							RE			
73 A/F						Mos	26-Feb-2025	1		26-Mar-2025	20 Days
						Hrs	13,520.9				
						Ldg	9,133				
Note: -						Flt	9,133				
732182	**Download No. 2 Engine Deec**							RE			
73 A/F						Mos	26-Feb-2025	1		26-Mar-2025	20 Days
						Hrs	13,520.9				
						Ldg	9,133				
Note: -						Flt	9,133				
732247	**Download No. 3 Engine Deec**							RE			
73 A/F						Mos	26-Feb-2025	1		26-Mar-2025	20 Days
						Hrs	13,520.9				
						Ldg	9,133				
Note: -						Flt	9,133				
73-3014	**Fuel Distribution - Replace Fuel Nozzle Shrouds (Inactive For Further Accomplishment)**							RE (-)			
73 ENG1						Mos					
Eff: 08-Jul-1994 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
73-3014	**Fuel Distribution - Replace Fuel Nozzle Shrouds (Inactive For Further Accomplishment)**							RE (-)			
73 ENG2						Mos	01-Oct-1980				
Eff: 08-Jul-1994 Complied With						Hrs					
						Enc					
73-3014	**Fuel Distribution - Replace Fuel Nozzle Shrouds (Inactive For Further Accomplishment)**							RE (-)			
73 ENG3						Mos					
Eff: 08-Jul-1994						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
73-3074	**Engine Fuel And Control - Distribution - Rework Fuel Pump Filter Bypass Valve And Replace Mounting Flange Screws**						T (A/R)			
73 ENG1						Mos				
Eff: 22-Oct-1984						Hrs				
						Enc				
73-3074	**Engine Fuel And Control - Distribution - Rework Fuel Pump Filter Bypass Valve And Replace Mounting Flange Screws**						T (A/R)			
73 ENG2						Mos				
Eff: 22-Oct-1984						Hrs				
						Enc				
73-3074	**Engine Fuel And Control - Distribution - Rework Fuel Pump Filter Bypass Valve And Replace Mounting Flange Screws**						T (A/R)			
73 ENG3						Mos				
Eff: 22-Oct-1984						Hrs				
						Enc				
73-3099RWK	**Engine Fuel And Control - Distribution - Replace Fuel Pump Filter Bypass Valve Assembly**						T (A/R)			
73 ENG1						Mos				
Eff: 23-Feb-1990						Hrs				
						Enc				
73-3099RWK	**Engine Fuel And Control - Distribution - Replace Fuel Pump Filter Bypass Valve Assembly**						T (A/R)			
73 ENG2						Mos				
Eff: 23-Feb-1990						Hrs				
						Enc				
73-3099RWK	**Engine Fuel And Control - Distribution - Replace Fuel Pump Filter Bypass Valve Assembly**						T (A/R)			
73 ENG3						Mos				
Eff: 23-Feb-1990						Hrs				
						Enc				
73-SB05 Rev 1	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**						RE (-)			
73 ENG1						Mos				
						Hrs				
						Enc				
73-SB05 Rev 1	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**						RE (-)			
73 ENG2						Mos				
						Hrs				
						Enc				
73-SB05 Rev 1	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**						RE (-)			
73 ENG3						Mos				
						Hrs				
						Enc				
73-SB05 Rev 2	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**						T (A/R)			
73 ENG1						Mos				
Eff: 06-Feb-2004						Hrs				
						Enc				
73-SB05 Rev 2	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**						T (A/R)			
73 ENG2						Mos				
Eff: 06-Feb-2004						Hrs				
						Enc				
73-SB05 Rev 2	**Convers Auth Pns 3070800-8/-30 To 3070800-21/-30**						T (A/R)			
73 ENG3						Mos				
Eff: 06-Feb-2004						Hrs				
						Enc				
73-SB08	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**						RE (-)			
73 ENG1						Mos				
Eff: 22-Dec-1999						Hrs				
						Enc				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
73-SB08	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG2						Mos					
Eff: 22-Dec-1999						Hrs					
						Enc					
73-SB08	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG3						Mos					
Eff: 22-Dec-1999						Hrs					
						Enc					
73-SB08 Rev 1	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG1						Mos					
						Hrs					
						Enc					
73-SB08 Rev 1	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG2						Mos					
						Hrs					
						Enc					
73-SB08 Rev 1	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							RE (-)			
73 ENG3						Mos					
						Hrs					
						Enc					
73-SB08 Rev 2	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							T (A/R)			
73 ENG1						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
73-SB08 Rev 2	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							T (A/R)			
73 ENG2						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
73-SB08 Rev 2	**Tfe731 Fuel Control Units, Head Sensor Bellows Assembly Inspection And Replacement**							T (A/R)			
73 ENG3						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
73-SB09	**Model Ch-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly P/N 3070800-7 Through 3070800-30**							RE (-)			
73 ENG1						Mos					
						Hrs					
						Enc					
73-SB09	**Model Ch-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly P/N 3070800-7 Through 3070800-30**							RE (-)			
73 ENG2						Mos					
						Hrs					
						Enc					
73-SB09	**Model Ch-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly P/N 3070800-7 Through 3070800-30**							RE (-)			
73 ENG3						Mos					
						Hrs					
						Enc					
73-SB09 Rev 1	**Model Ch-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly P/N 3070800-7 Through 3070800-30**							T (A/R)			
73 ENG1						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
73-SB09 Rev 1	**Model Ch-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly P/N 3070800-7 Through 3070800-30**							T (A/R)			
73 ENG2						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
73-SB09 Rev 1	**Model Ch-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly P/N 3070800-7 Through 3070800-30**							T (A/R)			
73 ENG3						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
73-SB13	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							RE (-)			
73 ENG1						Mos					
Eff: 14-Mar-2012						Hrs					
						Enc					
73-SB13	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							RE (-)			
73 ENG2						Mos					
Eff: 14-Mar-2012						Hrs					
						Enc					
73-SB13	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							RE (-)			
73 ENG3						Mos					
Eff: 14-Mar-2012						Hrs					
						Enc					
73-SB13 Rev 1	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							T (A/R)			
73 ENG1						Mos					
Eff: 18-Sep-2012						Hrs					
						Enc					
73-SB13 Rev 1	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							T (A/R)			
73 ENG2						Mos					
Eff: 18-Sep-2012						Hrs					
						Enc					
73-SB13 Rev 1	**Convert Fuel Control Assemblies, Pn 3070800-3X To Pn 3070800-4X**							T (A/R)			
73 ENG3						Mos					
Eff: 18-Sep-2012						Hrs					
						Enc					
74-13-09	**Fuel Pump Assemblies**							RE (-)		Mandatory	
73 ENG1						Mos	11-Jan-2000				
Eff: 31-Jul-1974 Not Applicable	Per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
74-18-12	**Fuel Control Orifice Assembly**							RE (-)		Mandatory	
73 ENG1						Mos	11-Jan-2000				
Eff: 03-Sep-1974 Not Applicable	Per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
74-18-16	**Fuel Control Computer**							RE (-)		Mandatory	
73 ENG1						Mos	11-Jan-2000				
Eff: 06-Sep-1974 Not Applicable	Per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
74-23-05	**Fuel Pumps**							RE (-)		Mandatory	
73 ENG1						Mos	11-Jan-2000				
Eff: 14-Nov-1974 Not Applicable	Per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
93-10-10	**Prevent Leaking Fuel From Spraying In Or Around Electrical Components (Superseded by AD 98-17-01)**							RE (-)		Mandatory	
73 ENG1						Mos	25-Jan-1995				
Eff: 14-Jun-1993 Complied With	PCW					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
93-10-10	**Prevent Leaking Fuel From Spraying In Or Around Electrical Components (Superseded by AD 98-17-01)**							RE (-)		Mandatory	
73 ENG2						Mos	08-May-1996				
Eff: 14-Jun-1993 Complied With	PCW					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
93-10-10	**Prevent Leaking Fuel From Spraying In Or Around Electrical Components (Superseded by AD 98-17-01)**							RE (-)		Mandatory	
73 ENG3						Mos	03-Jun-1997				
Eff: 14-Jun-1993 Complied With	BY S/B 73-3107					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
98-10-15	**Fuel Line, P/N 3061191-1 - Replacement**							RE (-)		Mandatory	
73 ENG1						Mos					
Eff: 19-May-1998 Not Applicable	per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
98-17-01	**Flex Fuel Tube**							RE (-)		Mandatory	
73 ENG1						Mos					
Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
98-17-01	**Flex Fuel Tube**							RE (-)		Mandatory	
73 ENG2						Mos	03-Jun-1997				
Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
98-17-01	**Flex Fuel Tube**							RE (-)		Mandatory	
73 ENG3						Mos	03-Jun-1997				
Complied With	PER SB TFE731-73-3128					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
98-17-01 R1	**Flex Fuel Tube**							RE (-)		Mandatory	
73 ENG1						Mos	20-May-1997				
Eff: 19-May-1999 Complied With	PCW					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
98-17-01 R1	**Flex Fuel Tube**							T (A/R)		Mandatory	
73 ENG2						Mos					
Eff: 19-May-1999 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
98-17-01 R1	**Flex Fuel Tube**							T (A/R)		Mandatory	
73 ENG3						Mos					
Eff: 19-May-1999 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
99-07-19	**Fuel Flow Meter Tube Assembly, P/N 3061157-2 - Inspect/ Replace**							RE (-)		Mandatory	
73 ENG1						Mos					
Eff: 21-Apr-1999 Not Applicable	per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
F50-003	**Engine - Installation of a consumed fuel and instantaneous airplane weight indicator**							T (A/R)			
73 A/F						Mos					
Eff: 20-Feb-1980						Hrs					
						Ldg					
Note: M0379						Flt					
TFE731-73-3009 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG1						Mos					
Eff: 02-Sep-1994						Hrs					
						Enc					
TFE731-73-3009 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG2						Mos	01-Oct-1980				
Eff: 02-Sep-1994 Complied With						Hrs					
						Enc					
TFE731-73-3009 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG3						Mos					
Eff: 02-Sep-1994						Hrs					
						Enc					
TFE731-73-3015 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-73-3015 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG2						Mos	17-Apr-1997				
Complied With						Hrs					
						Enc					
TFE731-73-3015 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG3						Mos					
						Hrs					
						Enc					
TFE731-73-3016 R1	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace Fuel Manifold Assembly (Inactive For Further Accomplishment)**							RE (-)			
73 ENG1						Mos					
Eff: 08-Aug-1977						Hrs					
						Enc					
TFE731-73-3016 R1	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace Fuel Manifold Assembly (Inactive For Further Accomplishment)**							RE (-)			
73 ENG2						Mos	01-Oct-1980				
Eff: 08-Aug-1977 Complied With						Hrs					
						Enc					
TFE731-73-3016 R1	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace Fuel Manifold Assembly (Inactive For Further Accomplishment)**							RE (-)			
73 ENG3						Mos					
Eff: 08-Aug-1977						Hrs					
						Enc					
TFE731-73-3016 R2	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace Fuel Manifold Assembly (Inactive For Further Accomplishment)**							RE (-)			
73 ENG1						Mos					
Eff: 16-Sep-2002 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-73-3020	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3020	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-73-3020	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG3						Mos					
						Hrs					
						Enc					
TFE731-73-3021	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-73-3021	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-73-3021	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG3						Mos					
						Hrs					
						Enc					
TFE731-73-3022	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-73-3022	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-73-3022	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG3						Mos					
						Hrs					
						Enc					
TFE731-73-3027 R2	**Replace Fuel Pump Assy Incorporating Fuel Inlet Temp Boss**							RE (-)		Optional	
73 ENG1						Mos					
Eff: 05-Mar-1980 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-73-3027 R2	**Replace Fuel Pump Assy Incorporating Fuel Inlet Temp Boss**							RE (-)		Optional	
73 ENG2						Mos	01-Oct-1980				
Eff: 05-Mar-1980 Complied With						Hrs					
						Enc					
TFE731-73-3027 R2	**Replace Fuel Pump Assy Incorporating Fuel Inlet Temp Boss**							RE (-)		Optional	
73 ENG3						Mos					
Eff: 05-Mar-1980						Hrs					
						Enc					
TFE731-73-3028	**Replace Flow Divider & Drain Valve With New FlowDivider Valve wthout Drain Fuction**							RE (-)		Optional	
73 ENG1						Mos					
Eff: 05-Jul-1979 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3028	**Replace Flow Divider & Drain Valve With New FlowDivider Valve wthout Drain Fuction**							T (A/R)		Optional	
73 ENG2						Mos	01-Oct-1980				
Eff: 05-Jul-1979 Complied With						Hrs					
						Enc					
TFE731-73-3028	**Replace Flow Divider & Drain Valve With New FlowDivider Valve wthout Drain Fuction**							T (A/R)		Optional	
73 ENG3						Mos					
Eff: 05-Jul-1979						Hrs					
						Enc					
TFE731-73-3030	**Reidentify/Replaceace Fuel Control**							RE (-)		Optional	
73 ENG1						Mos					
Eff: 08-Dec-1980						Hrs					
						Enc					
TFE731-73-3030	**Reidentify/Replaceace Fuel Control**							RE (-)		Optional	
73 ENG2						Mos	17-Apr-1997				
Eff: 08-Dec-1980 Complied With						Hrs					
						Enc					
TFE731-73-3030	**Reidentify/Replaceace Fuel Control**							RE (-)		Optional	
73 ENG3						Mos					
Eff: 08-Dec-1980						Hrs					
						Enc					
TFE731-73-3049 R1	**Install Reworked Fuel Control Assembly**							RE (-)		Recommended	
73 ENG1						Mos	09-Feb-1995				
Eff: 05-Oct-1984 Complied With						Hrs					
						Enc					
TFE731-73-3049 R1	**Install Reworked Fuel Control Assembly**							RE (-)		Recommended	
73 ENG2						Mos	14-Jan-2000				
Eff: 05-Oct-1984 Complied With	PCW					Hrs					
						Enc					
TFE731-73-3049 R1	**Install Reworked Fuel Control Assembly**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 05-Oct-1984						Hrs					
						Enc					
TFE731-73-3050	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace/Rework Fuel Manifold Assemblies (Matched Sets) (Inactive For Further Accomplishment)**							RE (-)			
73 ENG1						Mos					
Eff: 04-May-1982						Hrs					
						Enc					
TFE731-73-3050	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace/Rework Fuel Manifold Assemblies (Matched Sets) (Inactive For Further Accomplishment)**							RE (-)			
73 ENG2						Mos					
Eff: 04-May-1982						Hrs					
						Enc					
TFE731-73-3050	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace/Rework Fuel Manifold Assemblies (Matched Sets) (Inactive For Further Accomplishment)**							RE (-)			
73 ENG3						Mos					
Eff: 04-May-1982						Hrs					
						Enc					
TFE731-73-3050 R1	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace/Rework Fuel Manifold Assemblies (Matched Sets) (Inactive For Further Accomplishment)**							RE (-)			
73 ENG1						Mos					
Eff: 16-Sep-2002						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3050 R1	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace/Rework Fuel Manifold Assemblies (Matched Sets) (Inactive For Further Accomplishment)**							RE (-)			
73 ENG2						Mos					
Eff: 16-Sep-2002						Hrs					
						Enc					
TFE731-73-3050 R1	**ENGINE - FUEL MANIFOLD INSTALLATION - Replace/Rework Fuel Manifold Assemblies (Matched Sets) (Inactive For Further Accomplishment)**							RE (-)			
73 ENG3						Mos	14-Jan-2000				
Eff: 16-Sep-2002 Complied With						Hrs					
						Enc					
TFE731-73-3053	**ENGINE FUEL AND CONTROL -CONTROLLING-Replace fuel Filter (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG1						Mos					
Eff: 22-Jun-1982						Hrs					
						Enc					
TFE731-73-3053	**ENGINE FUEL AND CONTROL -CONTROLLING-Replace fuel Filter (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG2						Mos	02-Nov-1988				
Eff: 22-Jun-1982 Complied With						Hrs					
						Enc					
TFE731-73-3053	**ENGINE FUEL AND CONTROL -CONTROLLING-Replace fuel Filter (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG3						Mos					
Eff: 22-Jun-1982						Hrs					
						Enc					
TFE731-73-3053 R1	**ENGINE FUEL AND CONTROL -CONTROLLING-Replace fuel Filter (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG1						Mos					
Eff: 08-Jul-1994						Hrs					
						Enc					
TFE731-73-3053 R1	**ENGINE FUEL AND CONTROL -CONTROLLING-Replace fuel Filter (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG2						Mos	30-Sep-1983				
Eff: 08-Jul-1994 Complied With						Hrs					
						Enc					
TFE731-73-3053 R1	**ENGINE FUEL AND CONTROL -CONTROLLING-Replace fuel Filter (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG3						Mos					
Eff: 08-Jul-1994						Hrs					
						Enc					
TFE731-73-3055	**Replace Fuel-In Tube**							RE (-)		Optional	
73 ENG1						Mos	14-Jul-1997				
Eff: 16-Sep-1982 Complied With						Hrs					
						Enc					
TFE731-73-3055	**Replace Fuel-In Tube**							RE (-)		Optional	
73 ENG2						Mos	09-May-2001				
Eff: 16-Sep-1982 Complied With						Hrs					
						Enc					
TFE731-73-3055	**Replace Fuel-In Tube**							T (A/R)		Optional	
73 ENG3						Mos					
Eff: 16-Sep-1982						Hrs					
						Enc					
TFE731-73-3064	**Install Leaf Spring Between Variable Resistor (Potentiometer) & Spur Gear**							RE (-)			
73 ENG1						Mos	09-Feb-1995				
Eff: 19-Jul-1983 Complied With						Hrs					
						Enc					
TFE731-73-3064	**Install Leaf Spring Between Variable Resistor (Potentiometer) & Spur Gear**							RE (-)			
73 ENG2						Mos	02-Nov-1988				
Eff: 19-Jul-1983 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3064	**Install Leaf Spring Between Variable Resistor (Potentiometer) & Spur Gear**							T (A/R)			
73 ENG3						Mos					
Eff: 19-Jul-1983						Hrs					
						Enc					
TFE731-73-3074RWK	**Engine Fuel And Control - Distribution - Rework Fuel Pump Filter Bypass Valve And Replace Mounting Flange Screws**							T (A/R)			
73 ENG1						Mos					
Eff: 22-Oct-1984						Hrs					
						Enc					
TFE731-73-3074RWK	**Engine Fuel And Control - Distribution - Rework Fuel Pump Filter Bypass Valve And Replace Mounting Flange Screws**							T (A/R)			
73 ENG2						Mos					
Eff: 22-Oct-1984						Hrs					
						Enc					
TFE731-73-3074RWK	**Engine Fuel And Control - Distribution - Rework Fuel Pump Filter Bypass Valve And Replace Mounting Flange Screws**							T (A/R)			
73 ENG3						Mos					
Eff: 22-Oct-1984						Hrs					
						Enc					
TFE731-73-3075	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG1						Mos					
Eff: 09-Jul-1984						Hrs					
						Enc					
TFE731-73-3075	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG2						Mos					
Eff: 09-Jul-1984						Hrs					
						Enc					
TFE731-73-3075	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG3						Mos	08-Apr-1985				
Eff: 09-Jul-1984 Complied With						Hrs					
						Enc					
TFE731-73-3075 R1	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG1						Mos					
Eff: 29-Nov-1983						Hrs					
						Enc					
TFE731-73-3075 R1	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG2						Mos					
Eff: 29-Nov-1983						Hrs					
						Enc					
TFE731-73-3075 R1	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG3						Mos					
Eff: 29-Nov-1983						Hrs					
						Enc					
TFE731-73-3075 R2	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG1						Mos					
Eff: 25-Jul-1985						Hrs					
						Enc					
TFE731-73-3075 R2	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG2						Mos					
Eff: 25-Jul-1985						Hrs					
						Enc					
TFE731-73-3075 R2	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG3						Mos					
Eff: 25-Jul-1985						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3075 R3	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG1						Mos	27-Dec-1997				
Eff: 14-Mar-1986 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-73-3075 R3	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG2						Mos					
Eff: 14-Mar-1986						Hrs					
						Enc					
TFE731-73-3075 R3	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG3						Mos					
Eff: 14-Mar-1986						Hrs					
						Enc					
TFE731-73-3075 R4	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG1						Mos					
Eff: 02-Jun-1995						Hrs					
						Enc					
TFE731-73-3075 R4	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG2						Mos					
Eff: 02-Jun-1995						Hrs					
						Enc					
TFE731-73-3075 R4	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG3						Mos					
Eff: 02-Jun-1995						Hrs					
						Enc					
TFE731-73-3075 R5	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG1						Mos	13-Jan-2000				
Eff: 08-Feb-1996 Complied With PCW						Hrs					
						Enc					
TFE731-73-3075 R5	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG2						Mos					
Eff: 08-Feb-1996						Hrs					
						Enc					
TFE731-73-3075 R5	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG3						Mos					
Eff: 08-Feb-1996						Hrs					
						Enc					
TFE731-73-3075 R6	**Repl Fuel Pump Differential Press Indicator**							T (A/R)		Category 2	
73 ENG1						Mos					
Eff: 13-Jun-2003						Hrs					
						Enc					
TFE731-73-3075 R6	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG2						Mos					
Eff: 13-Jun-2003 Complied With						Hrs					
						Enc					
TFE731-73-3075 R6	**Repl Fuel Pump Differential Press Indicator**							RE (-)		Category 2	
73 ENG3						Mos					
Eff: 13-Jun-2003 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3083	**Repl Fuel Pump Anti-Icing Valve**							RE (-)		Recommended	
73 ENG1						Mos					
Eff: 26-Jul-1985						Hrs					
						Enc					
TFE731-73-3083	**Repl Fuel Pump Anti-Icing Valve**							RE (-)		Recommended	
73 ENG2						Mos	19-Dec-1990				
Eff: 26-Jul-1985 Complied With						Hrs					
						Enc					
TFE731-73-3083	**Repl Fuel Pump Anti-Icing Valve**							RE (-)		Recommended	
73 ENG3						Mos					
Eff: 26-Jul-1985						Hrs					
						Enc					
TFE731-73-3083 R1	**Repl Fuel Pump Anti-Icing Valve**							RE (-)		Recommended	
73 ENG1						Mos	09-Feb-1995				
Eff: 20-Oct-1989 Not Applicable						Hrs					
						Enc					
TFE731-73-3090	**Remove Fuel Cont Having Improper Plugs Installed**							RE (-)		Recommended	
73 ENG1						Mos	09-Feb-1995				
Eff: 21-Aug-1986 Complied With						Hrs					
						Enc					
TFE731-73-3090	**Remove Fuel Cont Having Improper Plugs Installed**							RE (-)		Recommended	
73 ENG2						Mos	15-Mar-1995				
Eff: 21-Aug-1986 Not Applicable						Hrs					
						Enc					
TFE731-73-3090	**Remove Fuel Cont Having Improper Plugs Installed**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 21-Aug-1986						Hrs					
						Enc					
TFE731-73-3098	**ENGINE FUEL AND CONTROL - DISTRIBUTION - Rework Fuel Heater Mounting Pads Bolt Hole (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG1						Mos	24-Jan-1995				
Eff: 23-Feb-1990 Complied With						Hrs					
						Enc					
TFE731-73-3098	**ENGINE FUEL AND CONTROL - DISTRIBUTION - Rework Fuel Heater Mounting Pads Bolt Hole (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG2						Mos	28-Jan-1994				
Eff: 23-Feb-1990 Complied With						Hrs					
						Enc					
TFE731-73-3098	**ENGINE FUEL AND CONTROL - DISTRIBUTION - Rework Fuel Heater Mounting Pads Bolt Hole (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
73 ENG3						Mos					
Eff: 23-Feb-1990						Hrs					
						Enc					
TFE731-73-3099RWK	**Engine Fuel And Control - Distribution - Replace Fuel Pump Filter Bypass Valve Assembly**							T (A/R)			
73 ENG1						Mos					
Eff: 23-Feb-1990						Hrs					
						Enc					
TFE731-73-3099RWK	**Engine Fuel And Control - Distribution - Replace Fuel Pump Filter Bypass Valve Assembly**							T (A/R)			
73 ENG2						Mos					
Eff: 23-Feb-1990						Hrs					
						Enc					
TFE731-73-3099RWK	**Engine Fuel And Control - Distribution - Replace Fuel Pump Filter Bypass Valve Assembly**							T (A/R)			
73 ENG3						Mos					
Eff: 23-Feb-1990						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3106 R2	**Replacement of Ball & Spring Assy in Fuel Heater Check Valve when unit Fails Internal Leakage Check**							RE (-)		Recommended	
73 ENG1						Mos	24-Jan-1995				
Eff: 18-Sep-1992 Complied With						Hrs					
						Enc					
TFE731-73-3107	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							RE (-)			
73 ENG1						Mos	15-Apr-1992				
Eff: 21-Jun-1991						Hrs					
						Enc					
TFE731-73-3107	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							RE (-)			
73 ENG2						Mos	27-May-1994				
Eff: 21-Jun-1991 Complied With	by visual inspection					Hrs					
						Enc					
TFE731-73-3107	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							RE (-)			
73 ENG3						Mos	27-May-1994				
Eff: 21-Jun-1991 Complied With						Hrs					
						Enc					
TFE731-73-3107 R1	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							RE (-)			
73 ENG1						Mos					
						Hrs					
						Enc					
TFE731-73-3107 R1	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							RE (-)			
73 ENG2						Mos	09-Jul-1993				
Complied With						Hrs					
						Enc					
TFE731-73-3107 R1	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							RE (-)			
73 ENG3						Mos					
						Hrs					
						Enc					
TFE731-73-3107 R4	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							RE (-)			
73 ENG1						Mos	24-Jan-1995				
Eff: 20-Apr-1994						Hrs					
						Enc					
TFE731-73-3107 R4	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							RE (-)			
73 ENG2						Mos	27-May-1994				
Eff: 20-Apr-1994 Complied With						Hrs					
						Enc					
TFE731-73-3107 R4	**Install Support CLAMP & Plate (Bracket) on Fuel Line**							T (A/R)			
73 ENG3						Mos					
Eff: 20-Apr-1994						Hrs					
						Enc					
TFE731-73-3108	**Instl Fuel Cont P3 Sense Line Gskt**							RE (-)		Recommended	
73 ENG1						Mos	15-Apr-1992				
Eff: 28-Aug-1991						Hrs					
						Enc					
TFE731-73-3108	**Instl Fuel Cont P3 Sense Line Gskt**							RE (-)		Recommended	
73 ENG2						Mos	28-Jan-1994				
Eff: 28-Aug-1991 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3108	**Instl Fuel Cont P3 Sense Line Gskt**							RE (-)		Recommended	
73 ENG3						Mos					
Eff: 28-Aug-1991						Hrs					
						Enc					
TFE731-73-3108 R1	**Instl Fuel Cont P3 Sense Line Gskt**							T (A/R)		Recommended	
73 ENG1						Mos					
Eff: 06-Oct-1995						Hrs					
						Enc					
TFE731-73-3108 R1	**Instl Fuel Cont P3 Sense Line Gskt**							RE (-)		Recommended	
73 ENG2						Mos	13-Sep-2001				
Eff: 06-Oct-1995 Complied With	PCW					Hrs					
						Enc					
TFE731-73-3108 R1	**Instl Fuel Cont P3 Sense Line Gskt**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 06-Oct-1995						Hrs					
						Enc					
TFE731-73-3110	**Repl Secondary Flexible Hose Assy**							RE (-)		Recommended	
73 ENG1						Mos	15-Apr-1992				
Eff: 21-Jan-1992						Hrs					
						Enc					
TFE731-73-3110	**Repl Secondary Flexible Hose Assy**							RE (-)		Recommended	
73 ENG2						Mos	15-Mar-1995				
Eff: 21-Jan-1992 Complied With						Hrs					
						Enc					
TFE731-73-3110	**Repl Secondary Flexible Hose Assy**							RE (-)		Recommended	
73 ENG3						Mos					
Eff: 21-Jan-1992						Hrs					
						Enc					
TFE731-73-3112	**Insp & Repl Identified Fuel Cont Var Res**							RE (-)		Recommended	
73 ENG1						Mos	09-Feb-1995				
Eff: 14-Feb-1992 Complied With						Hrs					
						Enc					
TFE731-73-3112	**Insp & Repl Identified Fuel Cont Var Res**							RE (-)		Recommended	
73 ENG2						Mos					
Eff: 14-Feb-1992 Complied With	PCW					Hrs					
						Enc					
TFE731-73-3112	**Insp & Repl Identified Fuel Cont Var Res**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 14-Feb-1992						Hrs					
						Enc					
TFE731-73-3113	**Repl Fuel Heater Outlet Adptr & Oil Xfr Tube**							T (A/R)		Recommended	
73 ENG1						Mos					
Eff: 10-Mar-1992						Hrs					
						Enc					
TFE731-73-3113	**Repl Fuel Heater Outlet Adptr & Oil Xfr Tube**							RE (-)		Recommended	
73 ENG2						Mos	28-Dec-1992				
Eff: 10-Mar-1992 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3113	**Repl Fuel Heater Outlet Adptr & Oil Xfr Tube**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 10-Mar-1992						Hrs					
						Enc					
TFE731-73-3114	**Replace Metering Valve Adjustment Shaft & Threaded Restrictor at Component Overhaul/Repair Facility**							RE (-)		Recommended	
73 ENG1						Mos	13-Jan-2000				
Eff: 29-May-1992 Not Applicable						Hrs					
						Enc					
TFE731-73-3114	**Replace Metering Valve Adjustment Shaft & Threaded Restrictor at Component Overhaul/Repair Facility**							RE (-)		Recommended	
73 ENG2						Mos					
Eff: 29-May-1992 Complied With	PCW					Hrs					
						Enc					
TFE731-73-3114	**Replace Metering Valve Adjustment Shaft & Threaded Restrictor at Component Overhaul/Repair Facility**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 29-May-1992						Hrs					
						Enc					
TFE731-73-3115	**Instl Fuel Cont W/Min Mod Configuration Std**							RE (-)		Recommended	
73 ENG1						Mos					
Eff: 29-Jun-1992						Hrs					
						Enc					
TFE731-73-3115	**Instl Fuel Cont W/Min Mod Configuration Std**							RE (-)		Recommended	
73 ENG2						Mos					
Eff: 29-Jun-1992 Complied With	PCW					Hrs					
						Enc					
TFE731-73-3115	**Instl Fuel Cont W/Min Mod Configuration Std**							RE (-)		Recommended	
73 ENG3						Mos					
Eff: 29-Jun-1992						Hrs					
						Enc					
TFE731-73-3115 R1	**Instl Fuel Cont W/Min Mod Configuration Std**							RE (-)		Recommended	
73 ENG1						Mos	27-Dec-1997				
Eff: 18-Mar-1994 Complied With	THE SERVICE BULLETIN HAS BEEN INCORPORATED					Hrs					
						Enc					
TFE731-73-3115 R1	**Instl Fuel Cont W/Min Mod Configuration Std**							RE (-)		Recommended	
73 ENG2						Mos	17-Apr-1997				
Eff: 18-Mar-1994 Complied With						Hrs					
						Enc					
TFE731-73-3115 R1	**Instl Fuel Cont W/Min Mod Configuration Std**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 18-Mar-1994						Hrs					
						Enc					
TFE731-73-3119	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace/Rework Governor Flyweight Assembly at Component Overhaul/Repair Facility**							RE (-)		Recommended	
73 ENG1						Mos	13-Jan-2000				
Eff: 07-May-1993 Complied With						Hrs					
						Enc					
TFE731-73-3119	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace/Rework Governor Flyweight Assembly at Component Overhaul/Repair Facility**							RE (-)		Recommended	
73 ENG2						Mos					
Eff: 07-May-1993 Complied With	PCW					Hrs					
						Enc					

Task No / SEQ	Description / PN/SN / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3119	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace/Rework Governor Flyweight Assembly at Component Overhaul/Repair Facility**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 07-May-1993						Hrs					
						Enc					
TFE731-73-3120RWK	**Engine Fuel And Control - Distribution - Rework Fuel Manifold Assembly, Pn 3071101-15, To Pn 3073522-1 And Pn 3071101-16 To Pn 3073522-2 Inactive For Further Accomplishment**							RE (-)		Category 2	
73 ENG1						Mos	15-Feb-1997				
Complied With						Hrs					
						Enc					
TFE731-73-3120RWK	**Engine Fuel And Control - Distribution - Rework Fuel Manifold Assembly, Pn 3071101-15, To Pn 3073522-1 And Pn 3071101-16 To Pn 3073522-2 Inactive For Further Accomplishment**							RE (-)		Category 2	
73 ENG2						Mos	14-Jan-2000				
Complied With	PCW					Hrs					
						Enc					
TFE731-73-3121	**Repl Secondary Flexible Hose Assy**							RE (-)		Recommended	
73 ENG1						Mos	24-Jan-1995				
Eff: 03-Nov-1993 Complied With						Hrs					
						Enc					
TFE731-73-3121	**Repl Secondary Flexible Hose Assy**							RE (-)		Recommended	
73 ENG2						Mos	15-Mar-1995				
Eff: 03-Nov-1993 Not Applicable						Hrs					
						Enc					
TFE731-73-3121	**Repl Secondary Flexible Hose Assy**							T (A/R)		Recommended	
73 ENG3						Mos					
Eff: 03-Nov-1993						Hrs					
						Enc					
TFE731-73-3131	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 30-Apr-1997						Hrs					
						Enc					
TFE731-73-3131	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	30-Mar-2000				
Eff: 30-Apr-1997 Complied With						Hrs					
						Enc					
TFE731-73-3131	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG3						Mos	23-Aug-1997				
Eff: 30-Apr-1997 Complied With						Hrs					
						Enc					
TFE731-73-3131 R1	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	27-Dec-1997				
Eff: 26-Sep-1997 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-73-3131 R1	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 26-Sep-1997						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3131 R1	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**						RE (-)		Cat.2-Reliability	
73 ENG3					Mos					
Eff: 26-Sep-1997					Hrs					
					Enc					
TFE731-73-3131 R2	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**						T (A/R)		Cat.2-Reliability	
73 ENG1					Mos					
Eff: 16-Jun-2004					Hrs					
					Enc					
TFE731-73-3131 R2	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**						T (A/R)		Cat.2-Reliability	
73 ENG2					Mos					
Eff: 16-Jun-2004					Hrs					
					Enc					
TFE731-73-3131 R2	**Engine Fuel And Control - Controlling - One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, P/N3074139-2, And Replacement (As Required) Of The Metering Valve Assembly**						T (A/R)		Cat.2-Reliability	
73 ENG3					Mos					
Eff: 16-Jun-2004					Hrs					
					Enc					
TFE731-73-3134	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**						RE (-)		Cat.2-Reliability	
73 ENG1					Mos	04-Nov-1980				
Eff: 12-Nov-1998 Complied With					Hrs	0				
					Enc	0				
TFE731-73-3134	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**						RE (-)		Cat.2-Reliability	
73 ENG2					Mos					
Eff: 12-Nov-1998 Not Applicable					Hrs					
					Enc					
TFE731-73-3134	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**						RE (-)		Cat.2-Reliability	
73 ENG3					Mos					
Eff: 12-Nov-1998					Hrs					
					Enc					
TFE731-73-3134 R1	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**						RE (-)		Cat.2-Reliability	
73 ENG1					Mos					
Eff: 08-Dec-1998					Hrs					
					Enc					
TFE731-73-3134 R1	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**						RE (-)		Cat.2-Reliability	
73 ENG2					Mos					
Eff: 08-Dec-1998					Hrs					
					Enc					
TFE731-73-3134 R1	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**						RE (-)		Cat.2-Reliability	
73 ENG3					Mos					
Eff: 08-Dec-1998					Hrs					
					Enc					
TFE731-73-3134 R2	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**						RE (-)		Cat.2-Reliability	
73 ENG1					Mos	13-Jan-2000				
Eff: 30-Apr-1999 Not Applicable					Hrs					
					Enc					
TFE731-73-3134 R2	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**						T (A/R)		Cat.2-Reliability	
73 ENG2					Mos					
Eff: 30-Apr-1999					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3134 R2	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control**							RE (-)		Cat.2-Reliability	
73 ENG3						Mos	14-Jan-2000				
Eff: 30-Apr-1999 Not Applicable						Hrs					
						Enc					
TFE731-73-3135	**Engine Fuel And Control - Distribution - Inspect/Replace Flex Tube Assembly, PN 3074376-1 (399-5500-0003) Or 3074376-2 (As Applicable)**							RE (-)			
73 ENG1						Mos	09-Apr-2001				
Eff: 17-Aug-2000 Complied With						Hrs	9,536				
						Enc	5,711				
TFE731-73-3135	**Engine Fuel And Control - Distribution - Inspect/Replace Flex Tube Assembly, PN 3074376-1 (399-5500-0003) Or 3074376-2 (As Applicable)**							RE (-)			
73 ENG2						Mos	09-Apr-2001				
Eff: 17-Aug-2000 Complied With						Hrs					
						Enc					
TFE731-73-3135	**Engine Fuel And Control - Distribution - Inspect/Replace Flex Tube Assembly, PN 3074376-1 (399-5500-0003) Or 3074376-2 (As Applicable)**							RE (-)			
73 ENG3						Mos	09-Apr-2001				
Eff: 17-Aug-2000						Hrs					
						Enc					
TFE731-73-3136	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG1						Mos					
Eff: 03-Feb-1999						Hrs					
						Enc					
TFE731-73-3136	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG2						Mos					
Eff: 03-Feb-1999						Hrs					
						Enc					
TFE731-73-3136	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG3						Mos					
Eff: 03-Feb-1999						Hrs					
						Enc					
TFE731-73-3136 R1	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG1						Mos					
Eff: 17-Mar-2000						Hrs					
						Enc					
TFE731-73-3136 R1	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG2						Mos					
Eff: 17-Mar-2000						Hrs					
						Enc					
TFE731-73-3136 R1	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG3						Mos	12-Jul-1997				
Eff: 17-Mar-2000 Complied With						Hrs					
						Enc					
TFE731-73-3136 R2	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG1						Mos					
Eff: 18-May-2001						Hrs					
						Enc					
TFE731-73-3136 R2	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG2						Mos					
Eff: 18-May-2001						Hrs					
						Enc					
TFE731-73-3136 R2	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG3						Mos					
Eff: 18-May-2001						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3136 R3	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							RE (-)		Cat.3-Product Improvement	
73 ENG1						Mos	31-Mar-2006				
Eff: 10-Sep-2002 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-73-3136 R3	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							T (A/R)		Cat.3-Product Improvement	
73 ENG2						Mos					
Eff: 10-Sep-2002						Hrs					
						Enc					
TFE731-73-3136 R3	**Incorporate Improved Primary And Secondary Manifold Fuel Feeder Tube Assemblies And Associated Hardware Released For Full Distribution At Rev 2**							T (A/R)		Cat.3-Product Improvement	
73 ENG3						Mos					
Eff: 10-Sep-2002						Hrs					
						Enc					
TFE731-73-3137	**Engine Fuel And Control - Distribution - Replace The Fuel Heater Check Valve, P/N 3073932-5 With P/N 3073932-6, And Connecting Metal Tubes Assemblies**							T (A/R)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 03-Nov-2000						Hrs					
						Enc					
TFE731-73-3137	**Engine Fuel And Control - Distribution - Replace The Fuel Heater Check Valve, P/N 3073932-5 With P/N 3073932-6, And Connecting Metal Tubes Assemblies**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	13-Sep-2001				
Eff: 03-Nov-2000 Not Applicable						Hrs					
						Enc					
TFE731-73-3137	**Engine Fuel And Control - Distribution - Replace The Fuel Heater Check Valve, P/N 3073932-5 With P/N 3073932-6, And Connecting Metal Tubes Assemblies**							T (A/R)		Cat.2-Reliability	
73 ENG3						Mos					
Eff: 03-Nov-2000						Hrs					
						Enc					
TFE731-73-3138	**Engine Fuel And Control - Distribution - Replace Fuel Nozzle Gaskets**							RE (-)		Cat.3-Product Improvement	
73 ENG1						Mos	31-Mar-2006				
Eff: 20-Oct-2000 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-73-3138	**Engine Fuel And Control - Distribution - Replace Fuel Nozzle Gaskets**							T (A/R)		Cat.3-Product Improvement	
73 ENG2						Mos					
Eff: 20-Oct-2000						Hrs					
						Enc					
TFE731-73-3138	**Engine Fuel And Control - Distribution - Replace Fuel Nozzle Gaskets**							T (A/R)		Cat.3-Product Improvement	
73 ENG3						Mos					
Eff: 20-Oct-2000						Hrs					
						Enc					
TFE731-73-3142	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	31-Mar-2006				
Eff: 07-Oct-2002 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-73-3142	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG2						Mos	22-Aug-2006				
Eff: 07-Oct-2002 Not Applicable						Hrs					
						Enc					
TFE731-73-3142	**Engine Fuel And Control - Controlling - Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And/Or Manual Mode Solenoid Valve Installed**							RE (-)		Cat.1-Safety	
73 ENG3						Mos	29-Aug-2006				
Eff: 07-Oct-2002 Not Applicable						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3147	**Engine Fuel And Control - Controlling - Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed**							RE (-)		Cat.1-Safety	
73 ENG1						Mos	31-Mar-2006				
Eff: 29-Mar-2005 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-73-3147	**Engine Fuel And Control - Controlling - Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed**							T (A/R)			
73 ENG1						Mos					
Eff: 29-Mar-2005						Hrs					
						Enc					
TFE731-73-3147	**Engine Fuel And Control - Controlling - Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed**							RE (-)			
73 ENG2						Mos	22-Aug-2006				
Eff: 29-Mar-2005 Not Applicable						Hrs					
						Enc					
TFE731-73-3147	**Engine Fuel And Control - Controlling - Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed**							T (A/R)		Cat.1-Safety	
73 ENG2						Mos					
Eff: 29-Mar-2005						Hrs					
						Enc					
TFE731-73-3147	**Engine Fuel And Control - Controlling - Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed**							RE (-)		Cat.1-Safety	
73 ENG3						Mos	29-Aug-2006				
Eff: 29-Mar-2005 Not Applicable						Hrs					
						Enc					
TFE731-73-3147	**Engine Fuel And Control - Controlling - Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed**							T (A/R)			
73 ENG3						Mos					
Eff: 29-Mar-2005						Hrs					
						Enc					
TFE731-73-3149	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace Main Turbine Engine Fuel Pump Fuel Filter Element, PN 897513-1 With PN 897830-1**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	31-Mar-2006				
Eff: 12-Sep-2005 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-73-3149	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace Main Turbine Engine Fuel Pump Fuel Filter Element, PN 897513-1 With PN 897830-1**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos	22-Aug-2006				
Eff: 12-Sep-2005 Complied With						Hrs					
						Enc					
TFE731-73-3149	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace Main Turbine Engine Fuel Pump Fuel Filter Element, PN 897513-1 With PN 897830-1**							RE (-)		Cat.2-Reliability	
73 ENG3						Mos	29-Aug-2006				
Eff: 12-Sep-2005 Complied With						Hrs					
						Enc					
TFE731-73-3149 R1	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace Main Turbine Engine Fuel Pump Fuel Filter Element, PN 897513-1 With PN 897830-1**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos	04-Jan-2023				
Eff: 20-Feb-2012 Complied With						Hrs	13,282.8				
						Enc	7,730				
TFE731-73-3149 R1	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace Main Turbine Engine Fuel Pump Fuel Filter Element, PN 897513-1 With PN 897830-1**							T (A/R)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 20-Feb-2012						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3149 R1	**ENGINE FUEL AND CONTROL - CONTROLLING - Replace Main Turbine Engine Fuel Pump Fuel Filter Element, PN 897513-1 With PN 897830-1**							RE (-)		Cat.2-Reliability	
73 ENG3						Mos	29-Aug-2006				
Eff: 20-Feb-2012 Complied With						Hrs	11,703.4				
						Enc	6,884				
TFE731-73-3155	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly PN 3070800-42 Thru -46**							RE (-)		Category 3	
73 ENG1						Mos					
Eff: 28-Mar-2012						Hrs					
						Enc					
TFE731-73-3155	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly PN 3070800-42 Thru -46**							RE (-)		Category 3	
73 ENG2						Mos					
Eff: 28-Mar-2012						Hrs					
						Enc					
TFE731-73-3155	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly PN 3070800-42 Thru -46**							RE (-)		Category 3	
73 ENG3						Mos					
Eff: 28-Mar-2012						Hrs					
						Enc					
TFE731-73-3155 R1	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly PN 3070800-42 Thru -46**							T (A/R)		Category 3	
73 ENG1						Mos					
Eff: 21-Jun-2012						Hrs					
						Enc					
TFE731-73-3155 R1	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly PN 3070800-42 Thru -46**							T (A/R)		Category 3	
73 ENG2						Mos					
Eff: 21-Jun-2012						Hrs					
						Enc					
TFE731-73-3155 R1	**Engine Fuel And Control - Controlling - Install Improved Main Turbine Engine Fuel Control Assembly PN 3070800-42 Thru -46**							T (A/R)		Category 3	
73 ENG3						Mos					
Eff: 21-Jun-2012						Hrs					
						Enc					
TFE731-73-3157	**Install Improved Fuel Control Assembly (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, or -74, with Improved Solenoid Attachment Screws on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 04-May-2017						Hrs					
(AVG MAN HRS: 6)						Enc					
TFE731-73-3157	**Install Improved Fuel Control Assembly (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, or -74, with Improved Solenoid Attachment Screws on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 04-May-2017						Hrs					
(AVG MAN HRS: 6)						Enc					
TFE731-73-3157	**Install Improved Fuel Control Assembly (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, or -74, with Improved Solenoid Attachment Screws on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG3						Mos					
Eff: 04-May-2017						Hrs					
(AVG MAN HRS: 6)						Enc					
TFE731-73-3157 R1	**Install Improved Fuel Control Assembly (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, or -74, with Improved Solenoid Attachment Screws on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG1						Mos					
Eff: 24-Jan-2018						Hrs					
(AVG MAN HRS: 6)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-73-3157 R1	**Install Improved Fuel Control Assembly (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, or -74, with Improved Solenoid Attachment Screws on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG2						Mos					
Eff: 24-Jan-2018						Hrs					
(AVG MAN HRS: 6)						Enc					
TFE731-73-3157 R1	**Install Improved Fuel Control Assembly (FCA), PN 3070800-21, -26, -27, -32, -35, -36, -42, -45, -46, -52, -54, -63, -64, -73, or -74, with Improved Solenoid Attachment Screws on TFE731-2, -3, -4, and -5 Engine Models**							RE (-)		Cat.2-Reliability	
73 ENG3						Mos					
Eff: 24-Jan-2018						Hrs					
(AVG MAN HRS: 6)						Enc					
TFE731-73-A3158 R1 Para (E)(2)(B)(1)(C)	**Accomplish, Alert Service Bulletin Replace Or Rework The Installed Suspect FCA**							RE (-)		Category 1	
73 ENG1						Mos	31-Oct-2018				
Not Applicable	Per PN					Hrs					
						Enc					
TFE731-73-A3158 R1 Para (E)(2)(B)(1)(C)	**Accomplish, Alert Service Bulletin Replace Or Rework The Installed Suspect FCA**							RE (-)		Category 1	
73 ENG2						Mos	31-Oct-2018				
Not Applicable	Per PN					Hrs					
						Enc					
TFE731-73-A3158 R1 Para (E)(2)(B)(1)(C)	**Accomplish, Alert Service Bulletin Replace Or Rework The Installed Suspect FCA**							RE (-)		Category 1	
73 ENG3						Mos	31-Oct-2018				
Not Applicable	Per PN					Hrs					
						Enc					
TFE731-73-SB09	**Model CH-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly Pn 3070800-7 Through 3070800-30**							RE (-)			
73 ENG1						Mos					
Eff: 22-Jan-2002						Hrs					
						Enc					
TFE731-73-SB09	**Model CH-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly Pn 3070800-7 Through 3070800-30**							RE (-)			
73 ENG2						Mos					
Eff: 22-Jan-2002						Hrs					
						Enc					
TFE731-73-SB09	**Model CH-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly Pn 3070800-7 Through 3070800-30**							RE (-)			
73 ENG3						Mos					
Eff: 22-Jan-2002						Hrs					
						Enc					
TFE731-73-SB09 R1	**Model CH-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly Pn 3070800-7 Through 3070800-30**							T (A/R)			
73 ENG1						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
TFE731-73-SB09 R1	**Model CH-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly Pn 3070800-7 Through 3070800-30**							T (A/R)			
73 ENG2						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					
TFE731-73-SB09 R1	**Model CH-R1 Fuel Control Assembly - Identifies Deleted Parts For Fuel Control Assembly Pn 3070800-7 Through 3070800-30**							T (A/R)			
73 ENG3						Mos					
Eff: 27-Jun-2003						Hrs					
						Enc					

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 74 - IGNITION											
	6 O'Clock Igniter Plug							RE (O/C)			
74 ENG1						Mos	04-Nov-1980				
Unknown						Hrs	0				
Unknown						Enc	0				
	6 O'Clock Igniter Plug							RE (O/C)			
74 ENG2						Mos	31-Aug-2015				
3074541-1						Hrs	12,125.7				
Unknown						Enc	7,353				
	6 O'Clock Igniter Plug							RE (O/C)			
74 ENG3		0				Mos					
3074541-4	New	0				Hrs	11,703.4				
NSN		0				Enc	6,884				
	7 O'Clock Igniter Plug							RE (O/C)			
74 ENG1						Mos	04-Nov-1980				
Unknown						Hrs	0				
Unknown						Enc	0				
	7 O'Clock Igniter Plug							RE (O/C)			
74 ENG2						Mos	31-Aug-2015				
3074541-1						Hrs	12,125.7				
Unknown						Enc	7,353				
	7 O'Clock Igniter Plug							RE (O/C)			
74 ENG3		0				Mos					
3074541-4	New	0				Hrs	11,703.4				
NSN		0				Enc	6,884				
	Igniter Lead							RE (O/C)			
74 ENG2						Mos	22-Aug-2006				
3071590-12						Hrs	11,473.6				
NSN						Enc	6,903				
	Igniter Lead							RE (O/C)			
74 ENG3						Mos	29-Aug-2006				
3071590-12						Hrs	11,703.4				
NSN						Enc	6,884				
	Ignition Unit							RE (O/C)			
74 ENG1						Mos	04-Jan-2023				
3070378-2						Hrs	13,282.8				
427458						Enc	7,730				
	Ignition Unit							RE (O/C)			
74 ENG2			0			Mos	12-Jul-2003				
10-392000-2	Overhauled		0			Hrs	10,153.3				
392686			0			Enc	6,267				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Ignition Unit							RE (O/C)			
74 ENG3						Mos	22-Jan-2025				
10-392000-2F	Serviceable					Hrs	13,438.8				
459791						Enc	7,953				
74-00-LMM-001	**Ignition System - Perform Ignition System Operational Test**							RE		LMM - Requirement	**≈12-Nov-2026**
74 ENG3	PKG 1000/1500 Hour					Mos	26-Feb-2014				
						Hrs	12,890.5	1,200	+300	(14,090.5)	614.7 Hrs (+300)
Ref:74-00-01						Enc	7,586				
74-00-LMM-001	**Ignition System – Perform Ignition System Operational Test**							RE		LMM - Requirement	**≈03-Apr-2027**
74 ENG1	PKG 1000/1500 Hour					Mos	04-Jan-2023				
						Hrs	13,282.8	1,000	+500	(14,282.8)	755.7 Hrs (+500)
Ref:74-00-01						Enc	7,730				
74-00-LMM-001	**Ignition System – Perform Ignition System Operational Test**							RE		LMM - Requirement	**≈19-Sep-2024**
74 ENG2	PKG 1000/1500 Hour					Mos	20-Oct-2021				
						Hrs	13,213.1	1,000	+500	(13,125.7)	0 Hrs (+379.7)
Ref:74-00-01						Enc	8,940				
74-00-LMM-002	**Remove and Inspect 6 O'Clock Igniter Plug and Leads Terminals**							RE		LMM - Requirement	**≈03-Apr-2027**
74 ENG1	PKG 1000/1500 Hour					Mos	04-Jan-2023				
						Hrs	13,282.8	1,000	+500	(14,282.8)	755.7 Hrs (+500)
Ref:74-00-01						Enc	7,730				
74-00-LMM-002	**Remove and Inspect 6 O'Clock Igniter Plug and Leads Terminals**							RE		LMM - Requirement	**≈19-Sep-2024**
74 ENG2	PKG 1000/1500 Hour					Mos	20-Oct-2021				
						Hrs	13,213.1	1,000	+500	(13,125.7)	0 Hrs (+379.7)
Ref:74-00-01						Enc	8,940				
74-00-LMM-002	**Remove and Inspect 6 O'Clock Igniter Plug and Leads Terminals**							RE		LMM - Requirement	**≈12-Nov-2026**
74 ENG3	PKG 1000/1500 Hour					Mos	26-Feb-2014				
						Hrs	12,890.5	1,200	+300	(14,090.5)	614.7 Hrs (+300)
Ref:74-00-01						Enc	7,586				
74-00-LMM-003	**Remove and Inspect 7 O'Clock Igniter Plug and Lead Terminals**							RE		LMM - Requirement	**≈03-Apr-2027**
74 ENG1	PKG 1000/1500 Hour					Mos	04-Jan-2023				
						Hrs	13,282.8	1,000	+500	(14,282.8)	755.7 Hrs (+500)
						Enc	7,730				
74-00-LMM-003	**Remove and Inspect 7 O'Clock Igniter Plug and Lead Terminals**							RE		LMM - Requirement	**≈19-Sep-2024**
74 ENG2	PKG 1000/1500 Hour					Mos	20-Oct-2021				
						Hrs	13,213.1	1,000	+500	(13,125.7)	0 Hrs (+379.7)
						Enc	8,940				
74-00-LMM-003	**Remove and Inspect 7 O'Clock Igniter Plug and Lead Terminals**							RE		LMM - Requirement	**≈12-Nov-2026**
74 ENG3						Mos	26-Feb-2014				
						Hrs	12,890.5	1,200	+300	14,090.5	614.7 Hrs (+300)
						Enc	7,586				
F50-207	**Provision for new asynchronous ignition unit**							T (A/R)			
74 A/F						Mos					
Eff: 18-Jun-1991						Hrs					
						Ldg					
Note: M1507A						Flt					
TFE731-74-3002 R4	**Replace Igniter Plug, Gasket & Attaching Bolts**							T (A/R)		Optional	
74 ENG1						Mos					
Eff: 04-Oct-1979	REVIEW OF SERVICE BULLETIN IS NECESSARY TO DETERMINE INCORPORATION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-74-3002 R4	**Replace Igniter Plug, Gasket & Attaching Bolts**							T (A/R)		Optional	
74 ENG2						Mos	01-Oct-1980				
Eff: 04-Oct-1979 Complied With						Hrs					
						Enc					
TFE731-74-3002 R4	**Replace Igniter Plug, Gasket & Attaching Bolts**							T (A/R)		Optional	
74 ENG3						Mos					
Eff: 04-Oct-1979						Hrs					
						Enc					
TFE731-74-3006	**Instl Ignition Igniter Plug 3074541-1**							RE (-)		Optional	
74 ENG1						Mos	02-Feb-1990				
Eff: 31-Mar-1989						Hrs					
						Enc					
TFE731-74-3006 R1	**Instl Ignition Igniter Plug 3074541-1**							T (A/R)		Optional	
74 ENG1						Mos					
Eff: 20-Apr-1990						Hrs					
						Enc					
TFE731-74-3006 R1	**Instl Ignition Igniter Plug 3074541-1**							RE (-)		Optional	
74 ENG2						Mos	19-Dec-1990				
Eff: 20-Apr-1990 Complied With						Hrs					
						Enc					
TFE731-74-3006 R1	**Instl Ignition Igniter Plug 3074541-1**							T (A/R)		Optional	
74 ENG3						Mos					
Eff: 20-Apr-1990						Hrs					
						Enc					
TFE731-74-3007	**Insp Plugs For Loose Center Firing Tip Elctd**							RE (-)		Recommended	
74 ENG1						Mos					
Eff: 03-Aug-1993						Hrs					
						Enc					
TFE731-74-3007	**Insp Plugs For Loose Center Firing Tip Elctd**							RE (-)		Recommended	
74 ENG2						Mos	28-Jan-1994				
Eff: 03-Aug-1993 Complied With						Hrs					
						Enc					
TFE731-74-3007	**Insp Plugs For Loose Center Firing Tip Elctd**							RE (-)		Recommended	
74 ENG3						Mos					
Eff: 03-Aug-1993						Hrs					
						Enc					
TFE731-74-3007 R1	**Insp Plugs For Loose Center Firing Tip Elctd**							RE (-)		Recommended	
74 ENG1						Mos	24-Jan-1995				
Eff: 11-Nov-1993 Complied With						Hrs					
						Enc					
TFE731-74-3007 R1	**Insp Plugs For Loose Center Firing Tip Elctd**							RE (-)		Recommended	
74 ENG2						Mos	14-Jan-2000				
Eff: 11-Nov-1993 Complied With PCW						Hrs					
						Enc					
TFE731-74-3007 R1	**Insp Plugs For Loose Center Firing Tip Elctd**							T (A/R)		Recommended	
74 ENG3						Mos					
Eff: 11-Nov-1993						Hrs					
						Enc					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 75 - BLEED AIR												
		Engine Anti-Ice Shut-Off Valve							RE (O/C)			
	75 A/F	No.1					Mos	01-Apr-2021				
	1159-00-9C						Hrs					
	1105ABC						Ldg					
							Flt					
		Engine Anti-Ice Shut-Off Valve							RE (O/C)			
	75 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Anti-Ice Shut-Off Valve							RE (O/C)			
	75 A/F	No.3					Mos	01-Apr-2021				
	1780-00-1						Hrs					
	0185						Ldg					
							Flt					
TFE731-75-3004		**Replace Anti-Ice Manifold Gasket & Seal Housing**							RE (-)		Recommended	
	75 ENG1						Mos					
	Eff: 01-Dec-1976 Complied With	INCORPORATED IN PRODUCTION					Hrs					
							Enc					
TFE731-75-3004		**Replace Anti-Ice Manifold Gasket & Seal Housing**							T (A/R)		Recommended	
	75 ENG2						Mos	01-Oct-1980				
	Eff: 01-Dec-1976 Complied With						Hrs					
							Enc					
TFE731-75-3004		**Replace Anti-Ice Manifold Gasket & Seal Housing**							T (A/R)		Recommended	
	75 ENG3						Mos					
	Eff: 01-Dec-1976						Hrs					
							Enc					
TFE731-75-3007 R2		**Incorporate Improved Buffered Air System Components**							RE (-)		Recommended	
	75 ENG1						Mos	04-Nov-1980				
	Eff: 22-Jun-1978 Complied With	INCORPORATED IN PRODUCTION					Hrs	0				
							Enc	0				
TFE731-75-3007 R2		**Incorporate Improved Buffered Air System Components**							RE (-)		Recommended	
	75 ENG2						Mos	17-Apr-1997				
	Eff: 22-Jun-1978 Complied With	Incorporated in Production					Hrs					
							Enc					
TFE731-75-3007 R2		**Incorporate Improved Buffered Air System Components**							RE (-)		Recommended	
	75 ENG3						Mos	12-Jul-1997				
	Eff: 22-Jun-1978 Complied With						Hrs					
							Enc					
TFE731-75-3008 R1		**Incorporate Improved Face Bellows Seal PN 3072683-3/-4**							T (A/R)		Recommended	
	75 ENG1						Mos					
	Eff: 07-Aug-1978						Hrs					
							Enc					
TFE731-75-3008 R1		**Incorporate Improved Face Bellows Seal PN 3072683-3/-4**							RE (-)		Recommended	
	75 ENG2						Mos	17-Apr-1997				
	Eff: 07-Aug-1978 Complied With	Incorporated in Production					Hrs					
							Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-75-3008 R1	**Incorporate Improved Face Bellows Seal PN 3072683-3/-4**							RE (-)		Recommended	
75 ENG3						Mos	12-Jul-1997				
Eff: 07-Aug-1978 Complied With						Hrs					
						Enc					
▼ 76 - ENGINE CONTROLS											
	Engine Teleflex Control Cable							RE (O/C)			
76 A/F	Center					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine Teleflex Control Cable							RE (O/C)			
76 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Engine Teleflex Control Cable							RE (O/C)			
76 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Throttle Control Unit							RE (O/C)			
76 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
74-11-06	**Fuel Control Computer**							RE (-)		Mandatory	
76 ENG1						Mos	11-Jan-2000				
Eff: 23-Sep-1974 Not Applicable	Per model					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
76-10-00-220-801-01	**Check Lh Engine Teleflex Control Cable Throttle Lever For Friction Points**							RE (-)			
76 A/F	Left					Mos	16-Sep-2018				
Unknown						Hrs					
Unknown						Ldg					
						Flt					
76-10-00-220-801-02	**Check Center Engine Teleflex Control Cable Throttle Lever For Friction Points**							RE (-)			
76 A/F	Center					Mos	16-Sep-2018				
Unknown						Hrs					
Unknown						Ldg					
						Flt					
76-10-00-220-801-03	**Check Rh Engine Teleflex Control Cable Throttle Lever For Friction Points**							RE (-)			
76 A/F	Right					Mos	16-Sep-2018				
Unknown						Hrs					
Unknown						Ldg					
						Flt					
76-10-21-640-801-01	**Lubrication of the Teleflex Control Cable and Teleflex Control Unit - LH Engine Teleflex Control Cable (L502Ec)**							RE		Acft Maint Ops (5-10)	
76 A/F						Mos	24-Mar-2021	74		24-May-2027	2.2 Years
						Hrs	13,161.4				
						Ldg	8,910				
						Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
76-10-21-640-801-02	**Lubrication of the Teleflex Control Cable and Teleflex Control Unit - Center Engine Teleflex Control Cable (M502Ec)**							RE		Acft Maint Ops (5-10)	
76 A/F						Mos	07-Aug-2024	74		07-Oct-2030	5.6 Years
						Hrs	13,360.3				
						Ldg	9,031				
						Flt	9,030				
76-10-21-640-801-03	**Lubrication of the Teleflex Control Cable and Teleflex Control Unit - RH Engine Teleflex Control Cable (R502Ec)**							RE		Acft Maint Ops (5-10)	
76 A/F						Mos	24-Mar-2021	74		24-May-2027	2.2 Years
						Hrs	13,161.4				
						Ldg	8,910				
						Flt					
76-10-21-640-801-04	**Lubrication of the Teleflex Control Cable and Teleflex Control Unit - Engine 1 Control Unit**							RE		Acft Maint Ops (5-10)	
76 A/F						Mos	05-Nov-2024	74		05-Jan-2031	5.8 Years
						Hrs	13,427.3				
						Ldg	9,074				
						Flt	9,074				
76-10-21-640-801-05	**Lubrication of the Teleflex Control Cable and Teleflex Control Unit - Engine 2 Control Unit**							RE		Acft Maint Ops (5-10)	
76 A/F						Mos	05-Nov-2024	74		05-Jan-2031	5.8 Years
						Hrs	13,427.3				
						Ldg	9,074				
						Flt	9,074				
76-10-21-640-801-06	**Lubrication of the Teleflex Control Cable and Teleflex Control Unit - Engine 3 Control Unit**							RE		Acft Maint Ops (5-10)	
76 A/F						Mos	05-Nov-2024	74		05-Jan-2031	5.8 Years
						Hrs	13,427.3				
						Ldg	9,074				
						Flt	9,074				
76-10-33-820-801-01	**Check of the Throttle Control Cable Tension - Engine 1 Control Cable (L501Ec)**							RE		Acft Maint Ops (5-10)	
76 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
76-10-33-820-801-02	**Check of the Throttle Control Cable Tension - Engine 2 Control Cable (M501Ec)**							RE		Acft Maint Ops (5-10)	
76 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
76-10-33-820-801-03	**Check of the Throttle Control Cable Tension - Engine 3 Control Cable (R501Ec)**							RE		Acft Maint Ops (5-10)	
76 A/F	05-10-00-1C					Yrs	14-Sep-2023	6	+5m	(31-Oct-2028)	3.7 Years (+61 Days)
						Hrs	13,276.7				
(Tol. Adjustment: -225.9d)						Ldg	8,977				
						Flt	8,977				
76-10-LMM-001	**Download ECTM**							RE (N/A)		LMM - Requirement	
76 ENG1						Mos	21-Dec-2023				
						Hrs	13,294.6				
						Enc	7,744				
76-10-LMM-001	**Download ECTM**							RE (N/A)		LMM - Requirement	
76 ENG2						Mos	21-Dec-2023				
						Hrs	13,013.5				
						Enc	7,851				
76-10-LMM-001	**Download ECTM**							RE (N/A)		LMM - Requirement	
76 ENG3						Mos	21-Dec-2023				
						Hrs	13,243.3				
						Enc	7,832				

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
89-22-16	**Engine Acceleration or Deceleration**							RE (-)		Mandatory	
76 ENG1						Mos	22-Jan-1995				
Not Applicable	PER MODEL					Hrs					
(ISSUING AUTHORITY: FAA)						Enc					
F50-038	**Thrust reverser control - Main throttle latching when the piggy-back throttle is used**							RE (-)			
76 A/F						Mos					
						Hrs					
						Ldg					
Note: M0220						Flt					
F50-038 R1	**Thrust reverser control - Main throttle latching when the piggy-back throttle is used**							RE (-)			
76 A/F						Mos	22-Jan-1981				
Eff: 04-Apr-1980						Hrs					
						Ldg					
Note: M0220						Flt					
F50-235	**Side engine throttle controls - Improved reliability of cable assemblies**							T (A/R)			
76 A/F						Mos					
Eff: 07-Jun-1994						Hrs					
						Ldg					
Note: M1848, 2 to 252 with TELEFLEX engine throttle P/N 7-43497-1 or 7-43497-3						Flt					
F50-299	**Provision for installation of a new digital electronic engine control (N1 DEEC)**							RE (-)			
76 A/F						Mos					
						Hrs					
						Ldg					
Note: M2259, 2 to 250, 252 without SB F50 to 280						Flt					
F50-299 R1	**Provision for installation of a new digital electronic engine control (N1 DEEC)**							T (A/R)			
76 A/F						Mos					
Eff: 19-Sep-2003						Hrs					
						Ldg					
Note: M2259, 2 to 250, 252 without SB F50 to 280						Flt					
F50-419	**TFE731-3 and TFE731-40 engine 2 throttle control - Protecting the control linkage quick disconnect coupling at frame 42 against icing**							T (A/R)			
76 A/F						Mos					
Eff: 10-Apr-2003						Hrs					
						Ldg					
Note: M2870						Flt					
TFE731-76-3008	**Replace Pneumatic Modulating & Shutoff Valve**							RE (-)			
76 ENG1						Mos					
Eff: 22-Sep-1975 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-76-3008	**Replace Pneumatic Modulating & Shutoff Valve**							T (A/R)			
76 ENG2						Mos	01-Oct-1980				
Eff: 22-Sep-1975 Complied With						Hrs					
						Enc					
TFE731-76-3008	**Replace Pneumatic Modulating & Shutoff Valve**							T (A/R)			
76 ENG3						Mos					
Eff: 22-Sep-1975						Hrs					
						Enc					
TFE731-76-3009 R1	**Replace Solenoid Controller Valve**							RE (-)		Optional	
76 ENG1						Mos					
Eff: 31-Jan-1979 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3009 R1	**Replace Solenoid Controller Valve**							T (A/R)		Optional	
76 ENG2						Mos	01-Oct-1980				
Eff: 31-Jan-1979 Complied With						Hrs					
						Enc					
TFE731-76-3009 R1	**Replace Solenoid Controller Valve**							T (A/R)		Optional	
76 ENG3						Mos					
Eff: 31-Jan-1979						Hrs					
						Enc					
TFE731-76-3014	**CVRSN of Elek Cmptr By Adjusting Itt Limiter**							T (A/R)		Optional	
76 ENG1						Mos					
Eff: 09-Aug-1979						Hrs					
(AVG MAN HRS: 2)						Enc					
TFE731-76-3014	**CVRSN of Elek Cmptr By Adjusting Itt Limiter**							T (A/R)		Optional	
76 ENG2						Mos					
Eff: 09-Aug-1979						Hrs					
(AVG MAN HRS: 2)						Enc					
TFE731-76-3014	**CVRSN of Elek Cmptr By Adjusting Itt Limiter**							RE (-)		Optional	
76 ENG3						Mos	12-Jul-1997				
Eff: 09-Aug-1979 Complied With						Hrs					
(AVG MAN HRS: 2)						Enc					
TFE731-76-3017	**1 Time Insp of Elek Cmptr PN 2101144-1/-2**							RE (-)		Recommended	
76 ENG1						Mos	09-Feb-1995				
Eff: 17-Apr-1980 Not Applicable						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-76-3017	**1 Time Insp of Elek Cmptr PN 2101144-1/-2**							RE (-)		Recommended	
76 ENG2						Mos	14-Jan-2000				
Eff: 17-Apr-1980 Not Applicable						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-76-3017	**1 Time Insp of Elek Cmptr PN 2101144-1/-2**							RE (-)		Recommended	
76 ENG3						Mos	14-Jan-2000				
Eff: 17-Apr-1980 Not Applicable						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-76-3018	**Install Computer Assy Pn 2101144-5**							RE (-)		Recommended	
76 ENG1						Mos	05-Sep-1991				
Eff: 14-Sep-1981						Hrs					
						Enc					
TFE731-76-3018	**Install Computer Assy Pn 2101144-5**							RE (-)		Recommended	
76 ENG2						Mos	03-Sep-1991				
Eff: 14-Sep-1981 Complied With						Hrs					
						Enc					
TFE731-76-3018	**Install Computer Assy Pn 2101144-5**							RE (-)		Recommended	
76 ENG3						Mos					
Eff: 14-Sep-1981						Hrs					
						Enc					
TFE731-76-3018 R1	**Install Computer Assy Pn 2101144-5**							T (A/R)		Recommended	
76 ENG1						Mos					
Eff: 23-Sep-1982						Hrs					
						Enc					
TFE731-76-3018 R1	**Install Computer Assy Pn 2101144-5**							RE (-)		Recommended	
76 ENG2						Mos	14-Jan-2000				
Eff: 23-Sep-1982 Not Applicable						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3018 R1	**Install Computer Assy Pn 2101144-5**							T (A/R)		Recommended	
76 ENG3						Mos					
Eff: 23-Sep-1982						Hrs					
						Enc					
TFE731-76-3022	**Inspect/Replace Capacitors on A9 and A10 Power Supply Boards**							RE (-)		Recommended	
76 ENG1						Mos	09-Feb-1995				
Eff: 01-Jun-1982 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-76-3022	**Inspect/Replace Capacitors on A9 and A10 Power Supply Boards**							RE (-)		Recommended	
76 ENG2						Mos	14-Jan-2000				
Eff: 01-Jun-1982 Not Applicable						Hrs					
						Enc					
TFE731-76-3022	**Inspect/Replace Capacitors on A9 and A10 Power Supply Boards**							RE (-)		Recommended	
76 ENG3						Mos	14-Jan-2000				
Eff: 01-Jun-1982 Not Applicable						Hrs					
						Enc					
TFE731-76-3036	**Replace Fuel Control Computer Air Filter**							T (A/R)		Optional	
76 ENG1						Mos					
Eff: 09-May-1983						Hrs					
						Enc					
TFE731-76-3036	**Replace Fuel Control Computer Air Filter**							T (A/R)		Optional	
76 ENG2						Mos					
Eff: 09-May-1983						Hrs					
						Enc					
TFE731-76-3036	**Replace Fuel Control Computer Air Filter**							T (A/R)		Optional	
76 ENG3						Mos					
Eff: 09-May-1983						Hrs					
						Enc					
TFE731-76-3038 R1	**Rework Computer Pn 2101144-5 S1-S3**							RE (-)		Recommended	
76 ENG1						Mos	09-Feb-1995				
Eff: 01-Aug-1983 Complied With						Hrs					
						Enc					
TFE731-76-3038 R1	**Rework Computer Pn 2101144-5 S1-S3**							RE (-)		Recommended	
76 ENG2						Mos	14-Jan-2000				
Eff: 01-Aug-1983 Not Applicable						Hrs					
						Enc					
TFE731-76-3038 R1	**Rework Computer Pn 2101144-5 S1-S3**							T (A/R)		Recommended	
76 ENG3						Mos					
Eff: 01-Aug-1983						Hrs					
						Enc					
TFE731-76-3054	**Instl Surge Control Gasket 3075481-1/-3**							RE (-)		Recommended	
76 ENG1						Mos	15-Apr-1992				
Eff: 28-Aug-1991						Hrs					
						Enc					
TFE731-76-3054	**Instl Surge Control Gasket 3075481-1/-3**							RE (-)		Recommended	
76 ENG2						Mos	16-Mar-1995				
Eff: 28-Aug-1991 Not Applicable	by Eng P/N					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3054	**Instl Surge Control Gasket 3075481-1/-3**						RE (-)		Recommended	
76 ENG3					Mos					
Eff: 28-Aug-1991					Hrs					
					Enc					
TFE731-76-3067	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG1					Mos					
Eff: 03-Apr-1998					Hrs					
					Enc					
TFE731-76-3067	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG2					Mos					
Eff: 03-Apr-1998					Hrs					
					Enc					
TFE731-76-3067	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG3					Mos					
Eff: 03-Apr-1998					Hrs					
					Enc					
TFE731-76-3067 R1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG1					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG2					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R1	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG3					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R10	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG1					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R10	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG2					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R10	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG3					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R11	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG1					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R11	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG2					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R11	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG3					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3067 R12	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R12	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R12	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R13	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R13	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R13	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R14	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R14	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R14	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R15	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R15	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R15	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R16	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3067 R16	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG2					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R16	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG3					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R17	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG1					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R17	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG2					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R17	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG3					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R18	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG1					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R18	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG2					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R18	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG3					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R19	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						T (A/R)			
76 ENG1					Mos					
Eff: 05-Dec-2005					Hrs					
					Enc					
TFE731-76-3067 R19	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						T (A/R)			
76 ENG2					Mos					
Eff: 05-Dec-2005					Hrs					
					Enc					
TFE731-76-3067 R19	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						T (A/R)			
76 ENG3					Mos					
Eff: 05-Dec-2005					Hrs					
					Enc					
TFE731-76-3067 R2	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG1					Mos					
					Hrs					
					Enc					
TFE731-76-3067 R2	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**						RE (-)			
76 ENG2					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3067 R2	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R3	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R3	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R3	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R4	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos	13-Dec-1999				
Complied With						Hrs					
						Enc					
TFE731-76-3067 R4	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos	13-Dec-1999				
Complied With						Hrs					
						Enc					
TFE731-76-3067 R4	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos	13-Dec-1999				
						Hrs					
						Enc					
TFE731-76-3067 R5	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R5	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R5	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R6	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R6	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R6	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3067 R7	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R7	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R7	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R8	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R8	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R8	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R9	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG1						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R9	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG2						Mos					
						Hrs					
						Enc					
TFE731-76-3067 R9	**Engine Controls - Power Control - Install Digital Electronic Engine Control (N1 DEEC)**							RE (-)			
76 ENG3						Mos					
						Hrs					
						Enc					
TFE731-76-3069	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**							RE (-)		Cat.2-Reliability	
76 ENG1						Mos	11-Mar-2004				
Eff: 20-Aug-2001 Complied With						Hrs					
						Enc					
TFE731-76-3069	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**							RE (-)		Cat.2-Reliability	
76 ENG2						Mos	02-Sep-2016				
Eff: 20-Aug-2001						Hrs	12,703.7				
						Enc	7,645				
TFE731-76-3069	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**							RE (-)		Cat.2-Reliability	
76 ENG3						Mos	11-Mar-2004				
Eff: 20-Aug-2001 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3069 R1	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**						RE (-)		Cat.2-Reliability	
76 ENG1					Mos					
Eff: 26-Jul-2002					Hrs					
					Enc					
TFE731-76-3069 R1	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**						RE (-)		Cat.2-Reliability	
76 ENG2					Mos					
Eff: 26-Jul-2002					Hrs					
					Enc					
TFE731-76-3069 R1	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**						RE (-)		Cat.2-Reliability	
76 ENG3					Mos					
Eff: 26-Jul-2002					Hrs					
					Enc					
TFE731-76-3069 R2	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**						T (A/R)		Cat.2-Reliability	
76 ENG1					Mos					
Eff: 08-Sep-2015					Hrs					
					Enc					
Note: Only engines having N1 DEEC, PN 2119020-1, are affected by this service bulletin										
TFE731-76-3069 R2	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**						T (A/R)		Cat.2-Reliability	
76 ENG2					Mos					
Eff: 08-Sep-2015					Hrs					
					Enc					
Note: Only engines having N1 DEEC, PN 2119020-1, are affected by this service bulletin										
TFE731-76-3069 R2	**Engine Controls - Power Control - Rework N1 Digital Electronic Engine Control (Deec), PN 2119020-1 To PN 2119020-1001, For TFE731-2 And -3 Engine Models**						T (A/R)		Cat.2-Reliability	
76 ENG3					Mos					
Eff: 08-Sep-2015					Hrs					
					Enc					
Note: Only engines having N1 DEEC, PN 2119020-1, are affected by this service bulletin										
TFE731-76-3072	**Engine Controls - Power Control - Install Improved Surge Bleed Valve, P/N 978812-7-1**						RE (-)		Cat.3-Product Improvement	
76 ENG1					Mos					
Eff: 12-Jun-2002					Hrs					
					Enc					
TFE731-76-3072	**Engine Controls - Power Control - Install Improved Surge Bleed Valve, P/N 978812-7-1**						RE (-)		Cat.3-Product Improvement	
76 ENG2					Mos					
Eff: 12-Jun-2002					Hrs					
					Enc					
TFE731-76-3072	**Engine Controls - Power Control - Install Improved Surge Bleed Valve, P/N 978812-7-1**						RE (-)		Cat.3-Product Improvement	
76 ENG3					Mos					
Eff: 12-Jun-2002					Hrs					
					Enc					
TFE731-76-3072 R1	**Engine Controls - Power Control - Install Improved Surge Bleed Valve, P/N 978812-7-1**						RE (-)		Cat.3-Product Improvement	
76 ENG1					Mos	04-Nov-1980				
Eff: 24-Feb-2003 Complied With	INCORPORATED IN PRODUCTION				Hrs	0				
					Enc	0				
TFE731-76-3072 R1	**Engine Controls - Power Control - Install Improved Surge Bleed Valve, P/N 978812-7-1**						T (A/R)		Cat.3-Product Improvement	
76 ENG2					Mos					
Eff: 24-Feb-2003					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-76-3072 R1	**Engine Controls - Power Control - Install Improved Surge Bleed Valve, P/N 978812-7-1**							T (A/R)		Cat.3-Product Improvement	
76 ENG3						Mos					
Eff: 24-Feb-2003						Hrs					
						Enc					
TFE731-76-3075	**Engine Power Control - Replace Specific Identified N1 DEECS**							T (A/R)		Cat.2-Reliability	
76 ENG1						Mos					
Eff: 23-Feb-2004						Hrs					
						Enc					
TFE731-76-3075	**Engine Power Control - Replace Specific Identified N1 DEECS**							T (A/R)		Cat.2-Reliability	
76 ENG2						Mos					
Eff: 23-Feb-2004						Hrs					
						Enc					
TFE731-76-3075	**Engine Power Control - Replace Specific Identified N1 DEECS**							T (A/R)		Cat.2-Reliability	
76 ENG3						Mos					
Eff: 23-Feb-2004						Hrs					
						Enc					
TFE731-A76-3079	**Engine Conrols - Power Control - Replace Specific Identified N1 Digital Electronic Engine Controls (Deec), Part Number 2119010 and 2119020**							T (A/R)		Cat.1-Safety	
76 ENG1						Mos					
Eff: 21-Dec-2006						Hrs					
						Enc					
TFE731-A76-3079	**Engine Conrols - Power Control - Replace Specific Identified N1 Digital Electronic Engine Controls (Deec), Part Number 2119010 and 2119020**							T (A/R)		Cat.1-Safety	
76 ENG2						Mos					
Eff: 21-Dec-2006						Hrs					
						Enc					
TFE731-A76-3079	**Engine Conrols - Power Control - Replace Specific Identified N1 Digital Electronic Engine Controls (Deec), Part Number 2119010 and 2119020**							T (A/R)		Cat.1-Safety	
76 ENG3						Mos					
Eff: 21-Dec-2006						Hrs					
						Enc					
▼ 77 - ENGINE INDICATING											
	Audible Warning Speaker							RE (O/C)			
77 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	EDC							RE (O/C)			
77 A/F	No.1					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	EDC							RE (O/C)			
77 A/F	No.2					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	EDC							RE (O/C)			
77 A/F	No.3					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine High-Pressure (N2) Indicator							RE (O/C)			
	77 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine High-Pressure (N2) Indicator							RE (O/C)			
	77 A/F	No.2					Mos	31-May-2013				
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
		Engine High-Pressure (N2) Indicator							RE (O/C)			
	77 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Indicator Electronic Display (EIED)							RE (O/C)			
	77 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Indicator Electronic Display (EIED)							RE (O/C)			
	77 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Indicator Electronic Display (EIED)							RE (O/C)			
	77 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Inlet Pressure/Temperature Sensor							RE (O/C)			
	77 A/F	No.1					Mos	04-Nov-2022				
	3070816-4						Hrs					
	27851						Ldg					
							Flt					
		Engine Inlet Pressure/Temperature Sensor							RE (O/C)			
	77 A/F	No.2					Mos	23-Dec-2009				
	3070816-12						Hrs					
	2746						Ldg					
							Flt					
		Engine Inlet Pressure/Temperature Sensor							RE (O/C)			
	77 A/F	No.3					Mos	23-Dec-2009				
	3070816-12						Hrs					
	051789317997						Ldg					
							Flt					
		Engine ITT Indicator							RE (O/C)			
	77 A/F	No.1					Mos	21-Aug-2024				
	224-901-002	Serviceable					Hrs	13,385.7				
	1224						Ldg	9,043				
							Flt	9,042				

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Engine ITT Indicator							RE (O/C)			
	77 A/F	No.2					Mos	09-Apr-2021				
	224-901-002						Hrs					
	1377						Ldg					
							Flt					
		Engine ITT Indicator							RE (O/C)			
	77 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Low-Pressure (N1) Indicator							RE (O/C)			
	77 A/F	No.1					Mos	15-Jun-2014				
	224-902-002						Hrs					
	367A						Ldg					
							Flt					
		Engine Low-Pressure (N1) Indicator							RE (O/C)			
	77 A/F	No.2					Mos	14-Sep-2023				
	224-902-002	Repaired				0	Hrs	13,276.7				
	343A					0	Ldg	8,977				
						0	Flt	8,977				
		Engine Low-Pressure (N1) Indicator							RE (O/C)			
	77 A/F	No.3					Mos	15-Jun-2014				
	224-902-002						Hrs					
	323A						Ldg					
							Flt					
		Engine Vibration Computer							RE (O/C)			
	77 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Vibration Computer							RE (O/C)			
	77 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Vibration Computer							RE (O/C)			
	77 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Vibration Transducer							RE (O/C)			
	77 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Vibration Transducer							RE (O/C)			
	77 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Engine Vibration Transducer							RE (O/C)			
	77 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		High Pressure (N2) Transducer							RE (O/C)			
	77 ENG1						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		High Pressure (N2) Transducer							RE (O/C)			
	77 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		High Pressure (N2) Transducer							RE (O/C)			
	77 ENG3						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		ITT Thermocouple Harness							RE (O/C)			
	77 ENG1						Mos	04-Nov-2022				
	3073595-1						Hrs					
	012021900368						Enc					
		ITT Thermocouple Harness							RE (O/C)			
	77 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		ITT Thermocouple Harness							RE (O/C)			
	77 ENG3		0				Mos					
	3073595-1	New	0				Hrs	11,703.4				
	062021904996		0				Enc	6,884				
		Low Pressure (N1) Transducer							RE (O/C)			
	77 ENG1						Mos	24-Oct-2022				
	3073827-1						Hrs					
	6758						Enc					
		Low Pressure (N1) Transducer							RE (O/C)			
	77 ENG2						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Unknown						Enc	0				
		Low Pressure (N1) Transducer							RE (O/C)			
	77 ENG3						Mos	03-Jun-1997				
	3073827-4						Hrs	7,565.9				
	97-19360-00955						Enc	4,730				
		Monitor Fan Speed							RE (O/C)			
	77 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
	Tone Audible Warning Generator							RE (O/C)			
	77 A/F					Mos	20-Jan-1981				
	Unknown					Hrs	0				
	Unknown					Ldg	0				
						Flt					
90-24-06	**Thermocouple Lead Assemblies**							RE (-)		Mandatory	
	77 ENG1					Mos					
	Eff: 13-Nov-1990 Not Applicable BY P/N PER S/B 77-3020					Hrs					
	(ISSUING AUTHORITY: FAA)					Enc					
90-24-06	**Thermocouple Lead Assemblies**							RE (-)		Mandatory	
	77 ENG2					Mos	19-Dec-1990				
	Eff: 13-Nov-1990 Not Applicable					Hrs					
	(ISSUING AUTHORITY: FAA)					Enc					
90-24-06	**Thermocouple Lead Assemblies**							RE (-)		Mandatory	
	77 ENG3					Mos	28-Dec-1992				
	Eff: 13-Nov-1990 Not Applicable S/B A72-3020 IS N/A					Hrs					
	(ISSUING AUTHORITY: FAA)					Enc					
F50-263	**EIEDs Version V04**							RE (-)			
	77 A/F					Mos					
	Eff: 25-Mar-1998					Hrs					
						Ldg					
	Note: M2191, with V03 EIED					Flt					
F50-278	**EDCs Version V04 software**							RE (-)			
	77 A/F					Mos					
	Eff: 31-Mar-1999					Hrs					
						Ldg					
	Note: M2239					Flt					
F50-287	**New ITT harness of center engine**							RE (-)			
	77 A/F					Mos					
						Hrs					
						Ldg					
	Note: M2319, 251, 253 to 277, 280 to 282 with ITT harnesses P/N 3060730-1 or -3					Flt					
F50-287 R1	**New ITT harness of center engine**							RE (-)			
	77 A/F					Mos					
	Eff: 08-Dec-1999					Hrs					
						Ldg					
	Note: M2319, 251, 253 to 277, 280 to 282 with ITT harnesses P/N 3060730-1 or -3					Flt					
F50-427	**New EIED indicators**							RE (-)			
	77 A/F					Mos					
	Eff: 14-Sep-2004					Hrs					
						Ldg					
	Note: M2890, 251, 253 to 334 and A/C with SB F50-280 and EIEDs P/N C14155AA04 (M2191), C14155AB04 (M2716) or C14155BA04 (M2662)					Flt					
TFE731-77-3001 R1	**Instl N1 Transducer With Change In Design and Functional Requirements**							RE (-)		Recommended	
	77 ENG1					Mos					
	Eff: 05-Jul-1979 Complied With INCORPORATED IN PRODUCTION					Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-77-3001 R1	**Instl N1 Transducer With Change In Design and Functional Requirements**							T (A/R)		Recommended	
77 ENG2						Mos	01-Oct-1980				
Eff: 05-Jul-1979 Complied With						Hrs					
						Enc					
TFE731-77-3001 R1	**Instl N1 Transducer With Change In Design and Functional Requirements**							T (A/R)		Recommended	
77 ENG3						Mos					
Eff: 05-Jul-1979						Hrs					
						Enc					
TFE731-77-3002	**Install N2 Transducer Incorporating Improved Sealant**							RE (-)		Recommended	
77 ENG1						Mos					
Eff: 16-Dec-1977 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-77-3002	**Install N2 Transducer Incorporating Improved Sealant**							RE (-)		Recommended	
77 ENG2						Mos	17-Apr-1997				
Eff: 16-Dec-1977 Complied With						Hrs					
						Enc					
TFE731-77-3002	**Install N2 Transducer Incorporating Improved Sealant**							RE (-)		Recommended	
77 ENG3						Mos					
Eff: 16-Dec-1977						Hrs					
						Enc					
TFE731-77-3003 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
77 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-77-3003 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
77 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-77-3003 R2	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
77 ENG3						Mos					
						Hrs					
						Enc					
TFE731-77-3006 R4	**Install 2-Piece Interstage Turbine Temperature (ITT) Harness**							T (A/R)		Optional	
77 ENG1						Mos					
Eff: 10-Oct-1985						Hrs					
						Enc					
TFE731-77-3006 R4	**Install 2-Piece Interstage Turbine Temperature (ITT) Harness**							RE (-)		Optional	
77 ENG2						Mos	19-Dec-1990				
Eff: 10-Oct-1985 Not Applicable						Hrs					
						Enc					
TFE731-77-3006 R4	**Install 2-Piece Interstage Turbine Temperature (ITT) Harness**							T (A/R)		Optional	
77 ENG3						Mos					
Eff: 10-Oct-1985						Hrs					
						Enc					
TFE731-77-3019	**Install Thermocouple Harness 3073595-1**							RE (-)			
77 ENG1						Mos	24-Jan-1985				
Eff: 21-Jun-1989 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-77-3019 R2	**Install Thermocouple Harness 3073595-1**							T (A/R)			
77 ENG1						Mos					
Eff: 19-Jun-1990						Hrs					
						Enc					
TFE731-77-3019 R2	**Install Thermocouple Harness 3073595-1**							RE (-)			
77 ENG2						Mos	19-Dec-1990				
Eff: 19-Jun-1990 Complied With						Hrs					
						Enc					
TFE731-77-3019 R2	**Install Thermocouple Harness 3073595-1**							T (A/R)			
77 ENG3						Mos					
Eff: 19-Jun-1990						Hrs					
						Enc					
TFE731-77-3020								RE (-)			
77 ENG1						Mos	15-Apr-1992				
						Hrs					
						Enc					
TFE731-77-3021	**Repl N1 Motional Pickup Transducer**							RE (-)		Category 3	
77 ENG1						Mos					
Eff: 12-Sep-1995						Hrs					
						Enc					
TFE731-77-3021	**Repl N1 Motional Pickup Transducer**							RE (-)		Category 3	
77 ENG2						Mos					
Eff: 12-Sep-1995						Hrs					
						Enc					
TFE731-77-3021	**Repl N1 Motional Pickup Transducer**							RE (-)		Category 3	
77 ENG3						Mos	03-Jun-1997				
Eff: 12-Sep-1995 Complied With						Hrs					
						Enc					
TFE731-77-3021 R1	**Repl N1 Motional Pickup Transducer**							T (A/R)		Category 3	
77 ENG1						Mos					
Eff: 16-Jan-2006						Hrs					
						Enc					
TFE731-77-3021 R1	**Repl N1 Motional Pickup Transducer**							T (A/R)		Category 3	
77 ENG2						Mos					
Eff: 16-Jan-2006						Hrs					
						Enc					
TFE731-77-3021 R1	**Repl N1 Motional Pickup Transducer**							T (A/R)		Category 3	
77 ENG3						Mos					
Eff: 16-Jan-2006						Hrs					
						Enc					
TFE731-77-3023	**Install Improved Design N2 Transducer, P/N 3070722-10**							T (-)	Cat.3-Product Improvement		
77 ENG1						Mos					
Eff: 12-Mar-2009						Hrs					
						Enc					
TFE731-77-3023	**Install Improved Design N2 Transducer, P/N 3070722-10**							T (-)	Cat.3-Product Improvement		
77 ENG2						Mos					
Eff: 12-Mar-2009						Hrs					
						Enc					
TFE731-77-3023	**Install Improved Design N2 Transducer, P/N 3070722-10**							T (-)	Cat.3-Product Improvement		
77 ENG3						Mos					
Eff: 12-Mar-2009						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-77-3023 R1	**Install Improved Design N2 Transducer, P/N 3070722-10**							RE (-)		Cat.3-Product Improvement	
77 ENG1						Mos					
Eff: 10-Aug-2015						Hrs					
						Enc					
TFE731-77-3023 R1	**Install Improved Design N2 Transducer, P/N 3070722-10**							RE (-)		Cat.3-Product Improvement	
77 ENG2						Mos					
Eff: 10-Aug-2015						Hrs					
						Enc					
TFE731-77-3023 R1	**Install Improved Design N2 Transducer, P/N 3070722-10**							RE (-)		Cat.3-Product Improvement	
77 ENG3						Mos					
Eff: 10-Aug-2015						Hrs					
						Enc					
TFE731-A77-3020	**Rmv & Repl Thermocouple Lead Assemblies**							T (A/R)		Alert	
77 ENG1						Mos					
Eff: 27-Apr-1990						Hrs					
						Enc					
TFE731-A77-3020	**Rmv & Repl Thermocouple Lead Assemblies**							RE (-)		Alert	
77 ENG2						Mos	19-Dec-1990				
Eff: 27-Apr-1990 Not Applicable						Hrs					
						Enc					
TFE731-A77-3020	**Rmv & Repl Thermocouple Lead Assemblies**							T (A/R)		Alert	
77 ENG3						Mos					
Eff: 27-Apr-1990						Hrs					
						Enc					
▼ 78 - EXHAUST											
	Thrust Reverser Accumulator							RE (O/C)			
78 A/F						Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Thrust Reverser Check Valve							RE (O/C)			
78 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Thrust Reverser Check Valve							RE (O/C)			
78 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Thrust Reverser Discharge Valve							RE (O/C)			
78 A/F	Left					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					
	Thrust Reverser Discharge Valve							RE (O/C)			
78 A/F	Right					Mos	20-Jan-1981				
Unknown						Hrs	0				
Unknown						Ldg	0				
						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Thrust Reverser Door Actuator							RE (O/C)			
	78 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reverser Filler Valve							RE (O/C)			
	78 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reverser Junction Actuator							RE (O/C)			
	78 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reverser Latching Solenoid							RE (O/C)			
	78 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reverser Locking Solenoid							RE (O/C)			
	78 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reverser Locking Solenoid							RE (O/C)			
	78 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reverser Pressure Indicator							RE (O/C)			
	78 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reverser Solenoid Valve							RE (O/C)			
	78 A/F						Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reversers Doors Bushing Lower Position Change							RE (O/C)			
	78 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust Reversers Doors Bushing Lower Position Change							RE (O/C)			
	78 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Thrust-Reverser Door							RE (O/C)			
	78 A/F	Left					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Thrust-Reverser Door							RE (O/C)			
	78 A/F	Right					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
780000		**Thrust Reverser Assembly**							RE (O/C)			
	78 A/F						Mos					
	Unknown						Hrs					
	Unknown						Ldg					
							Flt					
78-31-00-250-802-01		**Special Detailed Inspection (Fluorescent Penetrant) of the Thrust Reverser Door Hinge Fittings - LH Thrust-Reverser Door (456Dl)**							RE		Acft Maint Ops (5-10)	
	78 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
	(Tol. Adjustment: -83d)						Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
78-31-00-250-802-01 (5-40)		**Special Detailed Inspection (Fluorescent Penetrant) of the Thrust Reverser Door Hinge Fittings - LH Thrust-Reverser Door (456Dl)**							RE		AWL (5-40), CMR	**≈12-Feb-2028**
	78 A/F						Mos	30-Aug-2024				
							Hrs	13,386.3				
							Ldg	9,044				
	Note: Count flights since door first installation. If door flights count is unknown, perform test before 1155 flights. No tolerance.						Flt	9,043	1,155		10,198	1,065 Flt
78-31-00-250-802-02		**Special Detailed Inspection (Fluorescent Penetrant) of the Thrust Reverser Door Hinge Fittings - RH Thrust-Reverser Door (456Dr)**							RE		Acft Maint Ops (5-10)	
	78 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
	(Tol. Adjustment: -83d)						Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
78-31-00-250-802-02 (5-40)		**Special Detailed Inspection (Fluorescent Penetrant) of the Thrust Reverser Door Hinge Fittings - RH Thrust-Reverser Door (456Dr)**							RE		AWL (5-40), CMR	**≈12-Feb-2028**
	78 A/F						Mos	30-Aug-2024				
							Hrs	13,386.3				
							Ldg	9,044				
	Note: Count flights since door first installation. If door flights count is unknown, perform test before 1155 flights. No tolerance.						Flt	9,043	1,155		10,198	1,065 Flt
78-31-00-640-801-01		**Greasing of the Thrust Reverser Assembly**							RE		Acft Maint Ops (5-10)	
	78 A/F	05-10-00-12M					Mos	30-Aug-2024	12	+1m	(30-Aug-2025)	5.9 Months (+31 Days)
	(Tol. Adjustment: -83d)						Hrs	13,386.3				
							Ldg	9,044				
							Flt	9,043				
94-14-15		**Exhaust Duct Attachment Clamps**							RE (-)		Mandatory	
	78 A/F						Mos	12-Dec-2000				
	Eff: 05-Aug-1994 Complied With						Hrs					
	(ISSUING AUTHORITY: FAA)						Ldg					
							Flt					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
94-14-15 Par. (a)(b) Engine 1	**Exhaust Duct Attachment Clamps - Engine 1 - Inspect or Replace Clamps**							RE (-)		Mandatory	
78 A/F						Mos					
Eff: 05-Aug-1994 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
94-14-15 Par. (a)(b) Engine 2	**Exhaust Duct Attachment Clamps - Engine 2 - Inspect or Replace Clamps**							RE (-)		Mandatory	
78 A/F						Mos					
Eff: 05-Aug-1994 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
94-14-15 Par. (a)(b) Engine 3	**Exhaust Duct Attachment Clamps - Engine 3 - Inspect or Replace Clamps**							RE (-)		Mandatory	
78 A/F						Mos					
Eff: 05-Aug-1994 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
Note: For airplanes equipped with exhaust duct attachment clamps having P/N NH1002299-10, replace with attachment clamps having P/N NH1007763-10						Flt					
F50-162	**Exhaust - Thrust reverser - Control lever latching circuit and warning lights connected to same stage of microswitch**							T (A/R)			
78 A/F						Mos					
Eff: 15-Apr-1985						Hrs					
						Ldg					
Note: M1242						Flt					
F50-253	**Thrust reverser control - New 34K microswitch**							RE (-)			
78 A/F						Mos					
						Hrs					
						Ldg					
Note: M1946, M2486						Flt					
F50-253 R1	**Thrust reverser control - New 34K microswitch**							T (A/R)			
78 A/F						Mos					
Eff: 11-Oct-2000						Hrs					
						Ldg					
Note: M1946, M2486						Flt					
F50-286	**Thrust reverser - Improved clamshell door retention and sealing**							RE (-)			
78 A/F						Mos					
Eff: 28-May-1999						Hrs					
						Ldg					
Note: M2326, M2247, 251, 253 to 255, 257 to 270 with No. 2 engine nacelle afterbody 5MC03, 6MC04, 7MC05, 8MC06, 9MC07, 10MC08, 1HP/11, 2HP/12, 3HP/13, 4HP/14, 5HP/15, 7HP/17, 8HP/18, 9HP/19, 10HP/20, 11HP/21, 12HP/22, 13HP/23, 14HP/24, 16HP26 or 18HP28						Flt					
F50-434	**Inspection of thrust reverser door hinge fittings**							T (A/R)			
78 A/F						Mos					
Eff: 13-Oct-2004						Hrs					
						Ldg					
						Flt					
F50-541	**Inspection of TR door hinge fittings**							RE (-)			
78 A/F						Mos					
						Hrs					
						Ldg					
Note: AD EASA 2015-0165, 2 to 317 which have not changed the TR doors since Oct 2004						Flt					
F50-541 R1	**Inspection of TR door hinge fittings**							T (A/R)			
78 A/F						Mos					
Eff: 12-Aug-2015						Hrs					
						Ldg					
Note: AD EASA 2015-0165, 2 to 317 which have not changed the TR doors since Oct 2004						Flt					

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
▼ 79 - OIL												
		Engine Oil Pressure Switch							RE (O/C)			
79 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Oil Pressure Switch							RE (O/C)			
79 A/F		No.2					Mos	17-Apr-2014				
8G1126-2							Hrs					
2226							Ldg					
							Flt					
		Engine Oil Pressure Switch							RE (O/C)			
79 A/F		No.3					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Oil Pressure Transmitter							RE (O/C)			
79 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Oil Pressure Transmitter							RE (O/C)			
79 A/F		No.2					Mos	10-Dec-2016				
418-26044							Hrs					
04-79-561							Ldg					
							Flt					
		Engine Oil Pressure Transmitter							RE (O/C)			
79 A/F		No.3					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Oil Tank							RE (O/C)			
79 A/F		No.1					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Oil Tank							RE (O/C)			
79 A/F		No.2					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Oil Tank							RE (O/C)			
79 A/F		No.3					Mos	20-Jan-1981				
Unknown							Hrs	0				
Unknown							Ldg	0				
							Flt					
		Engine Oil Temperature Probe							RE (O/C)			
79 A/F		No.1					Mos	05-Nov-2024				
56B17		Serviceable					Hrs	13,427.3				
FE538							Ldg	9,074				
							Flt	9,074				

Task No SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories DUE	Time Remaining
		Engine Oil Temperature Probe							RE (O/C)			
	79 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Oil Temperature Probe							RE (O/C)			
	79 A/F	No.3					Mos	09-Apr-2021				
	56B17						Hrs					
	95582						Ldg					
							Flt					
		Engine Pressure/Temperature Indicator							RE (O/C)			
	79 A/F	No.1					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Pressure/Temperature Indicator							RE (O/C)			
	79 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Pressure/Temperature Indicator							RE (O/C)			
	79 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Oil Thermocouple							RE (O/C)			
	79 A/F	No.1					Mos	28-Jan-2011				
	MS28034-3						Hrs					
	96620						Ldg					
							Flt					
		Engine Oil Thermocouple							RE (O/C)			
	79 A/F	No.2					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Engine Oil Thermocouple							RE (O/C)			
	79 A/F	No.3					Mos	20-Jan-1981				
	Unknown						Hrs	0				
	Unknown						Ldg	0				
							Flt					
		Oil Cooler							RE (O/C)			
	79 ENG1	Lower - Left					Mos	31-Mar-2006				
	159910-3						Hrs					
	80-3137						Enc					
		Oil Cooler							RE (O/C)			
	79 ENG2	Lower - Left					Mos	31-Oct-1980				
	159910-3						Hrs	0				
	10-3038						Enc	0				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Oil Cooler							RE (O/C)			
79 ENG3	159910-3	Lower - Left					Mos	04-Dec-1980				
	80-3103						Hrs	0				
							Enc	0				
		Oil Cooler							RE (O/C)			
79 ENG1	159900-3	Lower - Right					Mos	31-Mar-2006				
	90-3150						Hrs					
							Enc					
		Oil Cooler							RE (O/C)			
79 ENG2	159900-3	Lower - Right					Mos	31-Oct-1980				
	80-3168						Hrs	0				
							Enc	0				
		Oil Cooler							RE (O/C)			
79 ENG3	159900-3	Lower - Right					Mos	04-Dec-1980				
	80-3156						Hrs	0				
							Enc	0				
		Oil Cooler							RE (O/C)			
79 ENG1	158600-7	Upper					Mos	31-Mar-2006				
	70-2111						Hrs					
							Enc					
		Oil Cooler							RE (O/C)			
79 ENG2	158600-7	Upper					Mos	31-Oct-1980				
	10-2130						Hrs	0				
							Enc	0				
		Oil Cooler							RE (O/C)			
79 ENG3	158600-7	Upper					Mos	04-Dec-1980				
	85-682						Hrs	0				
							Enc	0				
		Oil Filter By-Pass Indicator							RE (O/C)			
79 ENG1	Unknown						Mos	04-Nov-1980				
	Unknown						Hrs	0				
	Ref:LMM 79-30-01						Enc	0				
		Oil Filter By-Pass Indicator							RE (O/C)			
79 ENG2	Unknown						Mos	31-Oct-1980				
	Unknown						Hrs	0				
	Ref:LMM 79-30-01						Enc	0				
		Oil Filter By-Pass Indicator							RE (O/C)			
79 ENG3	Unknown						Mos	04-Dec-1980				
	Unknown						Hrs	0				
	Ref:LMM 79-30-01						Enc	0				
		Oil Pump							RE (O/C)			
79 ENG1	3060785-3		1,502.8				Mos	04-Jan-2023				
	1216225400026						Hrs	13,282.8				
							Enc	7,730				

Task No / SEQ	PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
		Oil Pump							RE (O/C)			
79 ENG2				0			Mos					
3060785-2		Overhauled		0			Hrs	11,473.6				
051405700443				0			Enc	6,903				
		Oil Pump							RE (O/C)			
79 ENG3							Mos	04-Dec-1980				
3071949-11							Hrs	0				
86-14157-1514							Enc	0				
		Oil Temperature Regulator							RE (O/C)			
79 ENG3							Mos	29-Aug-2006				
15861-8							Hrs	11,703.4				
11264							Enc	6,884				
		Oil Temperature Valve							RE (O/C)			
79 ENG1							Mos	31-Mar-2006				
158465-3							Hrs					
17-5509							Enc					
		Oil Temperature Valve							RE (O/C)			
79 ENG2							Mos	31-Oct-1980				
158465-3							Hrs	0				
75-7866							Enc	0				
		Oil Temperature Valve							RE (O/C)			
79 ENG3							Mos	04-Dec-1980				
158465-3							Hrs	0				
109-1718							Enc	0				
		Pressure Breather Valve Assembly							RE (O/C)			
79 ENG1							Mos	04-Nov-1980				
Unknown							Hrs	0				
Unknown							Enc	0				
Ref:LMM 79-20-02												
		Pressure Breather Valve Assembly							RE (O/C)			
79 ENG2							Mos	14-Apr-2016				
3075323-3							Hrs					
N/A							Enc					
Ref:LMM 79-20-02												
		Pressure Breather Valve Assembly							RE (O/C)			
79 ENG3							Mos	14-Apr-2016				
3075323-3							Hrs					
970814502938							Enc					
Ref:LMM 79-20-02												
790100-0101		**Filter, Oil**							RE (O/C)			
79 ENG1							Mos	04-Nov-1980				
Unknown							Hrs	0				
Unknown							Enc	0				
790100-0101		**Filter, Oil**							RE (O/C)			
79 ENG2							Mos	31-Oct-1980				
Unknown							Hrs	0				
Unknown							Enc	0				

Task No / SEQ / PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
790100-0101	**Filter, Oil**							RE (O/C)			
79 ENG3						Mos	04-Dec-1980				
Unknown						Hrs	0				
Unknown						Enc	0				
79-20-02-001	**Oil and Filter Analysis (Routine)**							RE		LMM - Requirement	**≈20-May-2025**
79 ENG1	PKG 150/250 Hour					Mos	06-Dec-2024				
						Hrs	13,459.5	150	+100	(13,609.5)	82.4 Hrs (+100)
Ref:72-00-00-200-015-A01						Enc	7,844				
79-20-02-001	**Oil and Filter Analysis (Routine)**							RE		LMM - Requirement	**≈20-May-2025**
79 ENG2	PKG 150/250 Hour					Mos	06-Dec-2024				
						Hrs	13,178.4	150	+100	(13,328.4)	82.4 Hrs (+100)
Ref:72-00-00-200-015-A01						Enc	7,951				
79-20-02-001	**Oil and Filter Analysis (Routine)**							RE		LMM - Requirement	**≈20-May-2025**
79 ENG3	PKG 150/250 Hour					Mos	06-Dec-2024				
						Hrs	13,408.2	150	+100	(13,558.2)	82.4 Hrs (+100)
Ref:72-00-00-200-015-A01						Enc	7,932				
79-20-LMM-003	**Change Oil**							RE		LMM - Requirement	**≈03-Apr-2027**
79 ENG1						Mos	04-Jan-2023				
						Hrs	13,282.8	1,000	+550	14,282.8	755.7 Hrs (+550)
						Enc	7,730				
79-20-LMM-003	**Change Oil**							RE		LMM - Requirement	**≈23-Dec-2018**
79 ENG2						Mos	04-Apr-2015				
						Hrs	11,871.3	1,000	+550	12,871.3	0 Hrs (+175.3)
						Enc	7,208				
79-20-LMM-003	**Change Oil**							RE		LMM - Requirement	**≈22-Apr-2026**
79 ENG3						Mos	26-Feb-2014				
						Hrs	12,890.5	1,000	+550	13,890.5	414.7 Hrs (+550)
						Enc	7,587				
F50-273	**Engine oil pressure - New oil pressure transducer**							RE (-)			
79 A/F						Mos					
Eff: 25-Feb-1998						Hrs					
						Ldg					
Note: M2224						Flt					
SIL F731-34	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG1						Mos					
						Hrs					
						Enc					
SIL F731-34	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG2						Mos					
						Hrs					
						Enc					
SIL F731-34	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG3						Mos					
						Hrs					
						Enc					
SIL F731-34 R1	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG1						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34 R1	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R1	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R10	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R10	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R10	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R11	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R11	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R11	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R12	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R12	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R12	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R13	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R13	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34 R13	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R14	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R14	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R14	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R15	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R15	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R15	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R16	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R16	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R16	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R17	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R17	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R17	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34 R18	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R18	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R18	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R19	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R19	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R19	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R2	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R2	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R2	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R20	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (A/R)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R20	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (A/R)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R20	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (A/R)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R3	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34 R3	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R3	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R4	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R4	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R4	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R5	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R5	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R5	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R6	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R6	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					
SIL F731-34 R6	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG3					Mos					
					Hrs					
					Enc					
SIL F731-34 R7	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG1					Mos					
					Hrs					
					Enc					
SIL F731-34 R7	**Honeywell Oil Filter Analysis Program for TFE731 Engines**						RE (-)		Service Information Letter	
79 ENG2					Mos					
					Hrs					
					Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
SIL F731-34 R7	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG3						Mos					
						Hrs					
						Enc					
SIL F731-34 R8	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG1						Mos					
						Hrs					
						Enc					
SIL F731-34 R8	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG2						Mos					
						Hrs					
						Enc					
SIL F731-34 R8	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG3						Mos					
						Hrs					
						Enc					
SIL F731-34 R9	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG1						Mos					
						Hrs					
						Enc					
SIL F731-34 R9	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG2						Mos					
						Hrs					
						Enc					
SIL F731-34 R9	**Honeywell Oil Filter Analysis Program for TFE731 Engines**							RE (-)		Service Information Letter	
79 ENG3						Mos					
						Hrs					
						Enc					
TFE731-79-3004 R1	**OIL - COOLING - Rework and Replacement of Oil Cooler Transfer Tubes (Inactive for Further Accomplishment)**							RE (-)			
79 ENG1						Mos					
Eff: 07-Nov-1974 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-79-3004 R1	**OIL - COOLING - Rework and Replacement of Oil Cooler Transfer Tubes (Inactive for Further Accomplishment)**							RE (-)			
79 ENG2						Mos	01-Oct-1980				
Eff: 07-Nov-1974 Complied With						Hrs					
						Enc					
TFE731-79-3004 R1	**OIL - COOLING - Rework and Replacement of Oil Cooler Transfer Tubes (Inactive for Further Accomplishment)**							RE (-)			
79 ENG3						Mos					
Eff: 07-Nov-1974						Hrs					
						Enc					
TFE731-79-3005 R1	**Installation Of New 2 Piece No. 3 Oil Jet**							RE (-)			
79 ENG1						Mos					
Eff: 07-Aug-1978 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-79-3005 R1	**Installation Of New 2 Piece No. 3 Oil Jet**							T (A/R)			
79 ENG2						Mos	01-Oct-1980				
Eff: 07-Aug-1978 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3005 R1	**Installation Of New 2 Piece No. 3 Oil Jet**							T (A/R)			
79 ENG3						Mos					
Eff: 07-Aug-1978						Hrs					
						Enc					
TFE731-79-3007	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-79-3007	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG2						Mos	01-Oct-1980				
Complied With						Hrs					
						Enc					
TFE731-79-3007	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG3						Mos					
						Hrs					
						Enc					
TFE731-79-3012 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-79-3012 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG2						Mos	17-Apr-1997				
Complied With						Hrs					
						Enc					
TFE731-79-3012 R1	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG3						Mos					
						Hrs					
						Enc					
TFE731-79-3013	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG1						Mos					
Eff: 06-Aug-1976						Hrs					
						Enc					
TFE731-79-3013	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG2						Mos					
Eff: 06-Aug-1976						Hrs					
						Enc					
TFE731-79-3013	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG3						Mos					
Eff: 06-Aug-1976						Hrs					
						Enc					
TFE731-79-3013 R1	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG1						Mos					
Eff: 16-Sep-1976						Hrs					
						Enc					
TFE731-79-3013 R1	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG2						Mos					
Eff: 16-Sep-1976						Hrs					
						Enc					
TFE731-79-3013 R1	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG3						Mos					
Eff: 16-Sep-1976						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3013 R2	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG1						Mos					
Eff: 24-May-1977						Hrs					
						Enc					
TFE731-79-3013 R2	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG2						Mos					
Eff: 24-May-1977						Hrs					
						Enc					
TFE731-79-3013 R2	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG3						Mos					
Eff: 24-May-1977						Hrs					
						Enc					
TFE731-79-3013 R3	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG1						Mos					
Eff: 19-Sep-1978						Hrs					
						Enc					
TFE731-79-3013 R3	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG2						Mos	17-Apr-1997				
Eff: 19-Sep-1978 Complied With	Incorporated in Production					Hrs					
						Enc					
TFE731-79-3013 R3	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							RE (-)			
79 ENG3						Mos	12-Jul-1997				
Eff: 19-Sep-1978 Complied With						Hrs					
						Enc					
TFE731-79-3013 R4	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							T (A/R)			
79 ENG1						Mos					
Eff: 01-Dec-2006						Hrs					
						Enc					
TFE731-79-3013 R4	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							T (A/R)			
79 ENG2						Mos					
Eff: 01-Dec-2006						Hrs					
						Enc					
TFE731-79-3013 R4	**Replace Flow Control Thermostat of Oil Temperature Control Valve**							T (A/R)			
79 ENG3						Mos					
Eff: 01-Dec-2006						Hrs					
						Enc					
TFE731-79-3014 R4	**Replace Thermostat Assy of Oil Temperature Regulator**							RE (-)		Recommended	
79 ENG1						Mos					
Eff: 19-Sep-1978 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-79-3014 R4	**Replace Thermostat Assy of Oil Temperature Regulator**							RE (-)		Recommended	
79 ENG2						Mos	17-Apr-1997				
Eff: 19-Sep-1978 Complied With						Hrs					
						Enc					
TFE731-79-3014 R4	**Replace Thermostat Assy of Oil Temperature Regulator**							T (A/R)		Recommended	
79 ENG3						Mos					
Eff: 19-Sep-1978						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3017	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG1						Mos					
Eff: 30-Aug-1977						Hrs					
						Enc					
TFE731-79-3017	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG2						Mos					
Eff: 30-Aug-1977						Hrs					
						Enc					
TFE731-79-3017	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG3						Mos	23-Aug-1997				
Eff: 30-Aug-1977 Complied With						Hrs					
						Enc					
TFE731-79-3017 R1	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG1						Mos					
Eff: 24-Jan-1978						Hrs					
						Enc					
TFE731-79-3017 R1	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG2						Mos	17-Apr-1997				
Eff: 24-Jan-1978 Complied With	Incorporated in Production					Hrs					
						Enc					
TFE731-79-3017 R1	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG3						Mos	12-Jul-1997				
Eff: 24-Jan-1978 Complied With						Hrs					
						Enc					
TFE731-79-3017 R2	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG1						Mos					
Eff: 20-Sep-1982						Hrs					
						Enc					
TFE731-79-3017 R2	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG2						Mos					
Eff: 20-Sep-1982						Hrs					
						Enc					
TFE731-79-3017 R2	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							RE (-)			
79 ENG3						Mos					
Eff: 20-Sep-1982						Hrs					
						Enc					
TFE731-79-3017 R3	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							T (A/R)			
79 ENG1						Mos					
Eff: 31-Jul-2006						Hrs					
						Enc					
TFE731-79-3017 R3	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							T (A/R)			
79 ENG2						Mos					
Eff: 31-Jul-2006						Hrs					
						Enc					
TFE731-79-3017 R3	**Replace Air/Oil Cooler & Bypass Valve to Prevent Oil Leakage by Reducing Fretting at Flow Connections**							T (A/R)			
79 ENG3						Mos					
Eff: 31-Jul-2006						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3023	**Install of Redesigned Oil Cooler oil Transfer Tube**							RE (-)			
79 ENG1						Mos					
Eff: 01-Jun-1979 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-79-3023	**Install of Redesigned Oil Cooler oil Transfer Tube**							RE (-)			
79 ENG2						Mos	17-Apr-1997				
Eff: 01-Jun-1979 Complied With	Incorporated in Production					Hrs					
						Enc					
TFE731-79-3023	**Install of Redesigned Oil Cooler oil Transfer Tube**							RE (-)			
79 ENG3						Mos	12-Jul-1997				
Eff: 01-Jun-1979 Complied With						Hrs					
						Enc					
TFE731-79-3023 R1	**Install of Redesigned Oil Cooler oil Transfer Tube**							T (A/R)			
79 ENG1						Mos					
Eff: 30-Nov-2006						Hrs					
						Enc					
TFE731-79-3023 R1	**Install of Redesigned Oil Cooler oil Transfer Tube**							T (A/R)			
79 ENG2						Mos					
Eff: 30-Nov-2006						Hrs					
						Enc					
TFE731-79-3023 R1	**Install of Redesigned Oil Cooler oil Transfer Tube**							T (A/R)			
79 ENG3						Mos					
Eff: 30-Nov-2006						Hrs					
						Enc					
TFE731-79-3025	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG1						Mos	24-Jan-1985				
Eff: 06-Jul-1981 Complied With						Hrs					
						Enc					
TFE731-79-3025	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG2						Mos					
Eff: 06-Jul-1981						Hrs					
						Enc					
TFE731-79-3025	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG3						Mos	08-Apr-1985				
Eff: 06-Jul-1981 Complied With						Hrs					
						Enc					
TFE731-79-3025 R1	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG1						Mos					
Eff: 10-Aug-1981						Hrs					
						Enc					
TFE731-79-3025 R1	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG2						Mos					
Eff: 10-Aug-1981						Hrs					
						Enc					
TFE731-79-3025 R1	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG3						Mos					
Eff: 10-Aug-1981						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3025 R2	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG1						Mos					
Eff: 15-Aug-1983						Hrs					
						Enc					
TFE731-79-3025 R2	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG2						Mos					
Eff: 15-Aug-1983						Hrs					
						Enc					
TFE731-79-3025 R2	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG3						Mos					
Eff: 15-Aug-1983						Hrs					
						Enc					
TFE731-79-3025 R3	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG1						Mos					
Eff: 27-Feb-2002						Hrs					
						Enc					
TFE731-79-3025 R3	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG2						Mos					
Eff: 27-Feb-2002						Hrs					
						Enc					
TFE731-79-3025 R3	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG3						Mos					
Eff: 27-Feb-2002						Hrs					
						Enc					
TFE731-79-3025 R4	**Replace or Rework Oil Lubricating Nozzle**							T (A/R)			
79 ENG1						Mos					
Eff: 11-Nov-2002						Hrs					
						Enc					
TFE731-79-3025 R4	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG2						Mos	22-Aug-2006				
Eff: 11-Nov-2002 Complied With						Hrs					
						Enc					
TFE731-79-3025 R4	**Replace or Rework Oil Lubricating Nozzle**							RE (-)			
79 ENG3						Mos	29-Aug-2006				
Eff: 11-Nov-2002 Complied With						Hrs					
						Enc					
TFE731-79-3031 R1	**Replace/Rework No. 6 Bearing Lubrication Tube Assy**							RE (-)		Recommended	
79 ENG1						Mos	24-Jan-1995				
Eff: 21-Jul-1983 Not Applicable						Hrs					
						Enc					
TFE731-79-3032	**Rework/Replace No. 6 Bearing Lubrication Tube Assy**							RE (-)			
79 ENG1						Mos	24-Jan-1985				
Eff: 06-Apr-1983						Hrs					
						Enc					
TFE731-79-3032 R2	**Rework/Replace No. 6 Bearing Lubrication Tube Assy**							T (A/R)			
79 ENG1						Mos					
Eff: 22-Dec-1989						Hrs					
						Enc					
TFE731-79-3032 R2	**Rework/Replace No. 6 Bearing Lubrication Tube Assy**							RE (-)			
79 ENG2						Mos	13-Nov-1984				
Eff: 22-Dec-1989 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3032 R2	**Rework/Replace No. 6 Bearing Lubrication Tube Assy**							T (A/R)			
79 ENG3						Mos					
Eff: 22-Dec-1989						Hrs					
						Enc					
TFE731-79-3033 R1	**Replace Oil-In Tube & Oil-In Gasket With Packing**							RE (-)		Optional	
79 ENG1						Mos	24-Jan-1995				
Eff: 20-Sep-1983 Complied With						Hrs					
						Enc					
TFE731-79-3033 R1	**Replace Oil-In Tube & Oil-In Gasket With Packing**							RE (-)		Optional	
79 ENG2						Mos	02-Nov-1988				
Eff: 20-Sep-1983 Complied With						Hrs					
						Enc					
TFE731-79-3033 R1	**Replace Oil-In Tube & Oil-In Gasket With Packing**							T (A/R)		Optional	
79 ENG3						Mos					
Eff: 20-Sep-1983						Hrs					
						Enc					
TFE731-79-3034	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	03-Nov-1988				
Eff: 01-Jun-1984 Complied With						Hrs					
						Enc					
TFE731-79-3034	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 01-Jun-1984						Hrs					
						Enc					
TFE731-79-3034	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG3						Mos	30-Apr-1986				
Eff: 01-Jun-1984 Complied With						Hrs					
						Enc					
TFE731-79-3034 R1	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 24-Oct-1984						Hrs					
						Enc					
TFE731-79-3034 R1	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 24-Oct-1984						Hrs					
						Enc					
TFE731-79-3034 R1	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 24-Oct-1984						Hrs					
						Enc					
TFE731-79-3034 R2	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 14-Aug-1985						Hrs					
						Enc					
TFE731-79-3034 R2	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 14-Aug-1985						Hrs					
						Enc					
TFE731-79-3034 R2	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG3						Mos	28-Dec-1992				
Eff: 14-Aug-1985 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3034 R3	**Replacement/Rework Of Plug (Chip Detector)**							T (A/R)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 28-Jan-2000						Hrs					
						Enc					
TFE731-79-3034 R3	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 28-Jan-2000 Complied With						Hrs					
						Enc					
TFE731-79-3034 R3	**Replacement/Rework Of Plug (Chip Detector)**							RE (-)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 28-Jan-2000 Complied With						Hrs					
						Enc					
TFE731-79-3035 R1	**OIL - DISTRIBUTION - Replace Seal, Part No. 3020052-5 with Seal, Part No. 3020052-16 in Breather Pressurization Valve (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG1						Mos					
Eff: 08-Jul-1994						Hrs					
						Enc					
TFE731-79-3035 R1	**OIL - DISTRIBUTION - Replace Seal, Part No. 3020052-5 with Seal, Part No. 3020052-16 in Breather Pressurization Valve (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG2						Mos	13-Nov-1984				
Eff: 08-Jul-1994 Complied With						Hrs					
						Enc					
TFE731-79-3035 R1	**OIL - DISTRIBUTION - Replace Seal, Part No. 3020052-5 with Seal, Part No. 3020052-16 in Breather Pressurization Valve (INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG3						Mos					
Eff: 08-Jul-1994						Hrs					
						Enc					
TFE731-79-3038	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG1						Mos	03-Nov-1988				
						Hrs					
						Enc					
TFE731-79-3038	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG2						Mos	04-Mar-1988				
Complied With						Hrs					
						Enc					
TFE731-79-3038	**(INACTIVE FOR FURTHER ACCOMPLISHMENT)**							RE (-)			
79 ENG3						Mos					
						Hrs					
						Enc					
TFE731-79-3041	**Replacement/Inspection/Rework Of Chip Detector**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos	27-Dec-1997				
Eff: 24-Jan-1986 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-79-3041	**Replacement/Inspection/Rework Of Chip Detector**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 24-Jan-1986 Complied With						Hrs					
						Enc					
TFE731-79-3041	**Replacement/Inspection/Rework Of Chip Detector**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos	30-Apr-1986				
Eff: 24-Jan-1986 Complied With						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3041 R1	**Replacement/Inspection/Rework Of Chip Detector**							T (A/R)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 28-Jan-2000						Hrs					
						Enc					
TFE731-79-3041 R1	**Replacement/Inspection/Rework Of Chip Detector**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 28-Jan-2000 Complied With						Hrs					
						Enc					
TFE731-79-3041 R1	**Replacement/Inspection/Rework Of Chip Detector**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos					
Eff: 28-Jan-2000 Complied With						Hrs					
						Enc					
TFE731-79-3050 R1	**Instl Gearbox Oil Scavenge Transfer**							RE (-)		Optional	
79 ENG1						Mos	27-Dec-1997				
Eff: 24-Feb-1995 Complied With	THE SERVICE BULLETIN HAS BEEN INCORPORATED					Hrs					
						Enc					
TFE731-79-3050 R1	**Instl Gearbox Oil Scavenge Transfer**							RE (-)		Optional	
79 ENG2						Mos	17-Apr-1997				
Eff: 24-Feb-1995 Complied With						Hrs					
						Enc					
TFE731-79-3050 R1	**Instl Gearbox Oil Scavenge Transfer**							T (A/R)		Optional	
79 ENG3						Mos					
Eff: 24-Feb-1995						Hrs					
						Enc					
TFE731-79-3051	**Install Metal Gasket 3075481-2**							RE (-)		Optional	
79 ENG1						Mos	09-Feb-1995				
Eff: 18-Feb-1994 Complied With						Hrs					
						Enc					
TFE731-79-3051	**Install Metal Gasket 3075481-2**							RE (-)		Optional	
79 ENG2						Mos	15-Mar-1995				
Eff: 18-Feb-1994 Complied With						Hrs					
						Enc					
TFE731-79-3051	**Install Metal Gasket 3075481-2**							T (A/R)		Optional	
79 ENG3						Mos					
Eff: 18-Feb-1994						Hrs					
						Enc					
TFE731-79-3053	**Repl Rear Turb Bearing Oil-Out Tube & Gasket**							RE (-)			
79 ENG1						Mos	07-Jan-2002				
Eff: 01-Apr-1994 Complied With						Hrs					
						Enc					
TFE731-79-3053	**Repl Rear Turb Bearing Oil-Out Tube & Gasket**							RE (-)			
79 ENG2						Mos	13-Sep-2001				
Eff: 01-Apr-1994 Complied With						Hrs					
						Enc					
TFE731-79-3053	**Repl Rear Turb Bearing Oil-Out Tube & Gasket**							T (A/R)			
79 ENG3						Mos					
Eff: 01-Apr-1994						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3054	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)		Optional	
79 ENG1						Mos	24-Jan-1995				
Eff: 31-May-1994 Complied With						Hrs	5,818				
						Enc	3,562				
TFE731-79-3054	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)		Optional	
79 ENG2						Mos	17-Apr-1997				
Eff: 31-May-1994 Complied With						Hrs					
						Enc					
TFE731-79-3054	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)		Optional	
79 ENG3						Mos	22-Dec-1994				
Eff: 31-May-1994 Complied With						Hrs					
						Enc					
TFE731-79-3054 R1	**Instl/Rewk Oil Lube & Scavenge Pump**							T (A/R)		Optional	
79 ENG1						Mos					
Eff: 29-Jul-1997						Hrs					
						Enc					
TFE731-79-3054 R1	**Instl/Rewk Oil Lube & Scavenge Pump**							T (A/R)		Optional	
79 ENG2						Mos					
Eff: 29-Jul-1997						Hrs					
						Enc					
TFE731-79-3054 R1	**Instl/Rewk Oil Lube & Scavenge Pump**							T (A/R)		Optional	
79 ENG3						Mos					
Eff: 29-Jul-1997						Hrs					
						Enc					
TFE731-79-3055 R2	**Repl Seal In Air Breather Valve Assy**							RE (-)		Optional	
79 ENG1						Mos	09-Apr-1996				
Eff: 30-Mar-1995 Complied With						Hrs					
						Enc					
TFE731-79-3055 R2	**Repl Seal In Air Breather Valve Assy**							RE (-)		Optional	
79 ENG2						Mos	08-Apr-1996				
Eff: 30-Mar-1995 Complied With						Hrs					
						Enc					
TFE731-79-3055 R2	**Repl Seal In Air Breather Valve Assy**							RE (-)		Optional	
79 ENG3						Mos	30-Mar-1995				
Eff: 30-Mar-1995 Complied With	PCW					Hrs					
						Enc					
TFE731-79-3057	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)	Cat.3-Product Improvement		
79 ENG1						Mos					
Eff: 14-Jul-1995						Hrs					
						Enc					
TFE731-79-3057	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)	Cat.3-Product Improvement		
79 ENG2						Mos					
Eff: 14-Jul-1995						Hrs					
						Enc					
TFE731-79-3057	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)	Cat.3-Product Improvement		
79 ENG3						Mos					
Eff: 14-Jul-1995						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3057 R1	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 08-Sep-1995						Hrs					
						Enc					
TFE731-79-3057 R1	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 08-Sep-1995						Hrs					
						Enc					
TFE731-79-3057 R1	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos					
Eff: 08-Sep-1995						Hrs					
						Enc					
TFE731-79-3057 R2	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos	04-Nov-1980				
Eff: 30-May-1996 Complied With	INCORPORATED IN PRODUCTION					Hrs	0				
						Enc	0				
TFE731-79-3057 R2	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 30-May-1996						Hrs					
						Enc					
TFE731-79-3057 R2	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos					
Eff: 30-May-1996						Hrs					
						Enc					
TFE731-79-3057 R3	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							T (A/R)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 03-May-1997						Hrs					
						Enc					
TFE731-79-3057 R3	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							T (A/R)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 03-May-1997						Hrs					
						Enc					
TFE731-79-3057 R3	**Instl Oil Tank Liquid Level Gage 3075532-1/-2**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos	03-Jun-1997				
Eff: 03-May-1997						Hrs					
						Enc					
TFE731-79-3058	**(Inactivated) Instl Oil Jet Strainer 894764-11**							RE (-)			
79 ENG1						Mos	13-Jan-2000				
Not Applicable						Hrs					
						Enc					
TFE731-79-3058	**(Inactivated) Instl Oil Jet Strainer 894764-11**							RE (-)			
79 ENG2						Mos	14-Jan-2000				
Not Applicable						Hrs					
						Enc					
TFE731-79-3058	**(Inactivated) Instl Oil Jet Strainer 894764-11**							RE (-)			
79 ENG3						Mos					
						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3059	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)	Cat.3-Product Improvement		
79 ENG1						Mos					
Eff: 22-May-1996						Hrs					
						Enc					
TFE731-79-3059	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)	Cat.3-Product Improvement		
79 ENG2						Mos					
Eff: 22-May-1996						Hrs					
						Enc					
TFE731-79-3059	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)	Cat.3-Product Improvement		
79 ENG3						Mos					
Eff: 22-May-1996						Hrs					
						Enc					
TFE731-79-3059 R1	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)	Cat.3-Product Improvement		
79 ENG1						Mos	27-Dec-1997				
Eff: 01-Nov-1996 Complied With						Hrs	8,120				
						Enc	4,955				
TFE731-79-3059 R1	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)	Cat.3-Product Improvement		
79 ENG2						Mos	17-Apr-1997				
Eff: 01-Nov-1996 Complied With						Hrs					
						Enc					
TFE731-79-3059 R1	**Instl/Rewk Oil Lube & Scavenge Pump**							RE (-)	Cat.3-Product Improvement		
79 ENG3						Mos	12-Jul-1997				
Eff: 01-Nov-1996 Complied With						Hrs					
						Enc					
TFE731-79-3061	**Oil - Air/Oil Cooler Installation - Install Bottom Panel, P/N3071860-10, And Associated Screws And Washers**							RE (-)	Cat.3-Product Improvement		
79 ENG1						Mos					
Eff: 16-Sep-1997						Hrs					
						Enc					
TFE731-79-3061	**Oil - Air/Oil Cooler Installation - Install Bottom Panel, P/N3071860-10, And Associated Screws And Washers**							RE (-)	Cat.3-Product Improvement		
79 ENG2						Mos					
Eff: 16-Sep-1997						Hrs					
						Enc					
TFE731-79-3061	**Oil - Air/Oil Cooler Installation - Install Bottom Panel, P/N3071860-10, And Associated Screws And Washers**							RE (-)	Cat.3-Product Improvement		
79 ENG3						Mos	12-Jul-1997				
Eff: 16-Sep-1997 Complied With						Hrs					
						Enc					
TFE731-79-3061 R1	**Oil - Air/Oil Cooler Installation - Install Bottom Panel, P/N3071860-10, And Associated Screws And Washers**							T (A/R)	Cat.3-Product Improvement		
79 ENG1						Mos					
Eff: 22-Feb-1999						Hrs					
						Enc					
TFE731-79-3061 R1	**Oil - Air/Oil Cooler Installation - Install Bottom Panel, P/N3071860-10, And Associated Screws And Washers**							T (A/R)	Cat.3-Product Improvement		
79 ENG2						Mos					
Eff: 22-Feb-1999						Hrs					
						Enc					
TFE731-79-3061 R1	**Oil - Air/Oil Cooler Installation - Install Bottom Panel, P/N3071860-10, And Associated Screws And Washers**							T (A/R)	Cat.3-Product Improvement		
79 ENG3						Mos					
Eff: 22-Feb-1999						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3062	**Oil - Distribution - Replace De-Oil Valve (Check Valve), P/N 3074372-1 With P/N 3074372-2**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	04-Nov-1980				
Eff: 19-Jun-1998 Complied With	PCW					Hrs	0				
						Enc	0				
TFE731-79-3062	**Oil - Distribution - Replace De-Oil Valve (Check Valve), P/N 3074372-1 With P/N 3074372-2**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos	13-Sep-2001				
Eff: 19-Jun-1998 Complied With						Hrs					
						Enc					
TFE731-79-3062	**Oil - Distribution - Replace De-Oil Valve (Check Valve), P/N 3074372-1 With P/N 3074372-2**							T (A/R)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 19-Jun-1998						Hrs					
						Enc					
TFE731-79-3063	**Oil - Distribution - Install No. 6 Bearing Lube Tube Assembly, P/N 3073736-1, And Associated Bracket, P/N 3073788-1/3075507-1 (As Applicable)**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos	31-Mar-2006				
Eff: 16-Jul-1999 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-79-3063	**Oil - Distribution - Install No. 6 Bearing Lube Tube Assembly, P/N 3073736-1, And Associated Bracket, P/N 3073788-1/3075507-1 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 16-Jul-1999						Hrs					
						Enc					
TFE731-79-3063	**Oil - Distribution - Install No. 6 Bearing Lube Tube Assembly, P/N 3073736-1, And Associated Bracket, P/N 3073788-1/3075507-1 (As Applicable)**							T (A/R)		Cat.3-Product Improvement	
79 ENG3						Mos					
Eff: 16-Jul-1999						Hrs					
						Enc					
TFE731-79-3064	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 04-Dec-2000						Hrs					
						Enc					
TFE731-79-3064	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 04-Dec-2000 Complied With						Hrs					
						Enc					
TFE731-79-3064	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos					
Eff: 04-Dec-2000						Hrs					
						Enc					
TFE731-79-3064 R1	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 25-Jul-2002 Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-79-3064 R1	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 25-Jul-2002						Hrs					
						Enc					
TFE731-79-3064 R1	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos					
Eff: 25-Jul-2002						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3064 R2	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 12-Feb-2004						Hrs					
						Enc					
TFE731-79-3064 R2	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 12-Feb-2004						Hrs					
						Enc					
TFE731-79-3064 R2	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos					
Eff: 12-Feb-2004						Hrs					
						Enc					
TFE731-79-3064 R3	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							T (A/R)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 19-Aug-2005						Hrs					
						Enc					
TFE731-79-3064 R3	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							T (A/R)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 19-Aug-2005						Hrs					
						Enc					
TFE731-79-3064 R3	**Instll Oil Lube & Scavenge Pump P/N 3071949-12**							RE (-)		Cat.3-Product Improvement	
79 ENG3						Mos	29-Aug-2006				
Eff: 19-Aug-2005 Complied With						Hrs					
						Enc					
TFE731-79-3066	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	31-Mar-2006				
Eff: 26-Jul-2002 Complied With						Hrs	11,545				
						Enc	6,704				
TFE731-79-3066	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 26-Jul-2002						Hrs					
						Enc					
TFE731-79-3066	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 26-Jul-2002						Hrs					
						Enc					
TFE731-79-3066 R1	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 12-Aug-2003						Hrs					
						Enc					
TFE731-79-3066 R1	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos	22-Aug-2006				
Eff: 12-Aug-2003 Complied With						Hrs					
						Enc					
TFE731-79-3066 R1	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							RE (-)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 12-Aug-2003						Hrs					
						Enc					
TFE731-79-3066 R2	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							T (A/R)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 12-Apr-2012						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3066 R2	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							T (A/R)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 12-Apr-2012						Hrs					
						Enc					
TFE731-79-3066 R2	**OIL - DISTRIBUTION - Install Improved Oil Lube and Scavenge Pump**							T (A/R)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 12-Apr-2012						Hrs					
						Enc					
TFE731-79-3068	**Oil - Distribution -Install Fuel Oil Cooler Orifice, Part No. 3075838-1**							T (A/R)			
79 ENG1						Mos					
Eff: 11-Mar-2005						Hrs					
						Enc					
TFE731-79-3068	**Oil - Distribution -Install Fuel Oil Cooler Orifice, Part No. 3075838-1**							T (A/R)			
79 ENG2						Mos					
Eff: 11-Mar-2005						Hrs					
						Enc					
TFE731-79-3068	**Oil - Distribution -Install Fuel Oil Cooler Orifice, Part No. 3075838-1**							T (A/R)			
79 ENG3						Mos					
Eff: 11-Mar-2005						Hrs					
						Enc					
TFE731-79-3069	**Oil - Indicating - Replace The Oil Filter By-Pass Indicator Valve**							T (A/R)		Cat.3-Product Improvement	
79 ENG1						Mos					
Eff: 16-Feb-2005						Hrs					
						Enc					
TFE731-79-3069	**Oil - Indicating - Replace The Oil Filter By-Pass Indicator Valve**							T (A/R)		Cat.3-Product Improvement	
79 ENG2						Mos					
Eff: 16-Feb-2005						Hrs					
						Enc					
TFE731-79-3069	**Oil - Indicating - Replace The Oil Filter By-Pass Indicator Valve**							T (A/R)		Cat.3-Product Improvement	
79 ENG3						Mos					
Eff: 16-Feb-2005						Hrs					
						Enc					
TFE731-79-3070	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos					
Complied With	INCORPORATED IN PRODUCTION					Hrs					
						Enc					
TFE731-79-3070	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							RE (-)		Cat.2-Reliability	
79 ENG2						Mos					
						Hrs					
						Enc					
TFE731-79-3070	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							RE (-)		Cat.2-Reliability	
79 ENG3						Mos					
						Hrs					
						Enc					
TFE731-79-3070 R1	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							T (-)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 09-Sep-2010						Hrs					
						Enc					
TFE731-79-3070 R1	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							T (-)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 09-Sep-2010						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3070 R1	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							T (-)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 09-Sep-2010						Hrs					
						Enc					
TFE731-79-3070 R2	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							T (A/R)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 09-May-2018						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-79-3070 R2	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							T (A/R)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 09-May-2018						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-79-3070 R2	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-3, -4, -5 Model Engines**							T (A/R)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 09-May-2018						Hrs					
(AVG MAN HRS: 1)						Enc					
TFE731-79-3072	**Install Improved Packings In Oil Lube And Scavenge Pumps, P/N 3060785-2 And P/N 3071949-3 Thru -12**							T (A/R)		Cat.2-Reliability	
79 ENG1						Mos					
Eff: 09-Jul-2010						Hrs					
						Enc					
TFE731-79-3072	**Install Improved Packings In Oil Lube And Scavenge Pumps, P/N 3060785-2 And P/N 3071949-3 Thru -12**							T (A/R)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 09-Jul-2010						Hrs					
						Enc					
TFE731-79-3072	**Install Improved Packings In Oil Lube And Scavenge Pumps, P/N 3060785-2 And P/N 3071949-3 Thru -12**							T (A/R)		Cat.2-Reliability	
79 ENG3						Mos					
Eff: 09-Jul-2010						Hrs					
						Enc					
TFE731-79-3075	**Oil - Distribution - Install Lube With Regulator And Scavenge Pump (Oil Lube Pump) PN 3060785-3**							RE (-)		Category 2	
79 ENG1						Mos					
Eff: 29-Feb-2012						Hrs					
						Enc					
TFE731-79-3075	**Oil - Distribution - Install Lube With Regulator And Scavenge Pump (Oil Lube Pump) PN 3060785-3**							RE (-)		Category 2	
79 ENG2						Mos					
Eff: 29-Feb-2012						Hrs					
						Enc					
TFE731-79-3075	**Oil - Distribution - Install Lube With Regulator And Scavenge Pump (Oil Lube Pump) PN 3060785-3**							RE (-)		Category 2	
79 ENG3						Mos					
Eff: 29-Feb-2012						Hrs					
						Enc					
TFE731-79-3077	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-2, -3, and -5 Model Engines**							RE (-)		Cat.2-Reliability	
79 ENG1						Mos	04-Nov-1980				
Eff: 09-May-2018 Complied With	INCORPORATED IN PRODUCTION					Hrs	0				
(AVG MAN HRS: 1)						Enc	0				
TFE731-79-3077	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-2, -3, and -5 Model Engines**							T (A/R)		Cat.2-Reliability	
79 ENG2						Mos					
Eff: 09-May-2018						Hrs					
(AVG MAN HRS: 1)						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
TFE731-79-3077	**Oil - Storage - Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing on TFE731-2, -3, and -5 Model Engines**							RE (-)		Cat.2-Reliability	
79 ENG3						Mos	12-Jul-1997				
Eff: 09-May-2018 Complied With						Hrs					
(AVG MAN HRS: 1)						Enc					
▼ 80 - STARTING											
F50-072	**Starting - Start bus - Isolated from the batteries in parallel in case of a start with the batteries in series**							T (A/R)			
80 A/F						Mos					
Eff: 25-Feb-1982						Hrs					
						Ldg					
Note: M0356						Flt					
F50-217	**Starting - Replacement of start push-buttons**							T (A/R)			
80 A/F						Mos					
Eff: 14-Mar-1991						Hrs					
						Ldg					
Note: M1619						Flt					
F50-293	**Starter generator - Replacement of manifold duct**							RE (-)			
80 A/F						Mos					
Eff: 31-Mar-1999						Hrs					
						Ldg					
Note: M2359						Flt					
▼ 100 - GENERAL											
	Automatic Dependent Surveillance-Broadcast (ADS-B) Out Compliant							RE (O/C)			
100 A/F						Mos	24-Mar-2021				
010-00860-30						Hrs					
22U002081						Ldg					
						Flt					
000020	**Perform Preflight Inspection**							RE (A/R)			
100 A/F						Days	12-Feb-2019				
						Hrs					
(ZONE: -)						Ldg					
						Flt					
2001-22-10	**Airplane Flight Manual - Pressurization or Oxygen Level Changes**							RE (-)		Mandatory	
100 A/F						Mos	09-Nov-2001				
Eff: 03-Dec-2001 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
2019-05-14	**This AD removes AD 2012-02-18**							RE (-)		Mandatory	
100 A/F						Mos	10-Nov-2021				
Eff: 28-Mar-2019 Complied With						Hrs					
(ISSUING AUTHORITY: FAA)						Ldg					
						Flt					
5837088-SB No. 1	**Removal/Installation Of Low Pressure Tie Rod - Lp Compressor Shaft Stretch Fixture**							T (A/R)			
100 ENG1						Mos					
Eff: 16-Sep-2011						Hrs					
						Enc					
5837088-SB No. 1	**Removal/Installation Of Low Pressure Tie Rod - Lp Compressor Shaft Stretch Fixture**							T (A/R)			
100 ENG2						Mos					
Eff: 16-Sep-2011						Hrs					
						Enc					

Task No / SEQ PN/SN	Description / MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI		CW	REQ	TOL	Categories / DUE	Time Remaining
5837088-SB No. 1	**Removal/Installation Of Low Pressure Tie Rod - Lp Compressor Shaft Stretch Fixture**							T (A/R)			
100 ENG3						Mos					
Eff: 16-Sep-2011						Hrs					
						Enc					
D202005000806	**Biocide Treatment Process**							T (A/R)	Service Information Letter		
100 APU1						Mos					
Eff: 06-May-2020						Hrs					
						APUS					
F50-450 R2	**Requirements for application of the SSIP and of the CPCP to maintain airworthiness up through the aircraft Limit Of Validity -LOV-**							T (-)			
100 A/F						Mos					
Eff: 26-Jan-2005						Hrs					
						Ldg					
Note: M2955, AD EASA F-2004-163						Flt					
F50-450 R3	**Requirements for Application of the Supplemental Structural Inspection Program (S.S.I.P.) to Maintain Airworthiness up to Aircraft Limit of Validity (L.O.V.)**							RE (-)		Mandatory	
100 A/F						Mos					
Eff: 25-May-2016						Hrs					
(ISSUING AUTHORITY: DGAC)						Ldg					
						Flt					