

OWNER: FLIGHT OPERATIONS PTY LTD
ADDRESS: WESTERN AUSTRALIA 6105

OPERATOR: FLIGHT OPERATIONS PTY LTD
ADDRESS: WESTERN AUSTRALIA 6105

PHONE:
FAX:

PHONE:
FAX:

ANALYST: RICHARD RAYBURN
EMAIL: RICHARD.RAYBURN@CAMPSYSTEMS.COM
+1-912-298-1304 (DIRECT)
912-298-1280 (OFFICE)
WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

AIRCRAFT **SERIAL/REGNO:** 6101/N47TR **MODEL:** G650 **MANUFACTURER:** GULFSTREAM AEROSPACE CORPORATION

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 13-AUG-2014	1245.8 A/C HRS as of 23-APR-2020	A/C HRS as of ____/____/____
INSERVICE DATE: 14-NOV-2014	507 AFL as of 23-APR-2020	AFL as of ____/____/____
MANUFACTURER DATE: 27-JUL-2014	1272.5 APH as of 23-APR-2020	APH as of ____/____/____
	0 APS as of 23-APR-2020	APS as of ____/____/____

APU **SERIAL/PART:** P-209/RE220[GVI] (CMP) **MODEL:** RE220(G650) **MANUFACTURER:** HONEYWELL

INSTALLED ON 10-JUN-2014	LAST ACTUALS	CURRENT ACTUAL
0 APU HRS	1272.5 APU HRS as of 23-APR-2020	APU HRS as of ____/____/____
0 APUS	0 APUS as of 23-APR-2020	APUS as of ____/____/____

ENGINE NO. 1 **SERIAL/PART:** 25317/BR725A1-12 (CMP) **MODEL:** BR725A1-12 (G650) **MANUFACTURER:** ROLLS-ROYCE DERBY PLC

INSTALLED ON 11-JUN-2014	LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS 0 A/C HRS	1245.8 ENG. HRS as of 23-APR-2020	ENG. HRS as of ____/____/____
0 ENC	507 ENC as of 23-APR-2020	ENC as of ____/____/____

ENGINE NO. 2 **SERIAL/PART:** 25316/BR725A1-12 (CMP) **MODEL:** BR725A1-12 (G650) **MANUFACTURER:** ROLLS-ROYCE DERBY PLC

INSTALLED ON 11-JUN-2014	LAST ACTUALS	CURRENT ACTUAL
0 ENG. HRS 0 A/C HRS	1245.8 ENG. HRS as of 23-APR-2020	ENG. HRS as of ____/____/____
0 ENC	507 ENC as of 23-APR-2020	ENC as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 6101/N47TR							
FAA 1974-08-09 R03	AD74-08-09R3 - LAVATORY MODIFICATION (REVISION 3)					MANDATORY	COMPLIED WITH - CW
		MOS		11-JUL-2017		RECURRING	
		HRS/MSC	1000	733.6	1733.6		
		AFL		277			
FAA 2015-20-10	AD 2015-20-10 GULFSTREAM AEROSPACE CORPORATION					MANDATORY	COMPLIED WITH - CW
		MOS		01-DEC-2015			
13-NOV-2015		HRS/MSC	- (s)	301.4			
		AFL		115			
FAA 2015-24-06	AD 2015-24-06 GULFSTREAM AEROSPACE CORPORATION					CANCELLED	COMPLIED WITH - CW. NOTE- THE SELF SEALING COUPLERS HAVE BEEN PERMANENTLY REMOVED UNDER THIS WORK ORDER, REFERENCE 5.48 (CB155), 5.54 (CB155A), 5.49 (ASC084), & 5.53 (ASC084A).
		MOS		23-AUG-2016			
04-DEC-2015		HRS/MSC	-	529.6			
		AFL		192			
FAA 2017-04-01	AD 2017-04-01 - LARGE AIRPLANE/GULFSTREAM AEROSPACE CORPORATION (MODEL GVI)					MANDATORY	COMPLIED WITH - CW
		MOS		13-JUL-2017			
28-MAR-2017		HRS/MSC	- (s)	733.6			
		AFL		277			
FAA 2017-20-08	AD 2017-20-08 - GULFSTREAM AEROSPACE - GULFSTREAM AFM SUPPLEMENT INCORPORATION					MANDATORY	COMPLIED WITH - CW
		MOS		13-NOV-2017			
06-NOV-2017		HRS/MSC	- (s)	772.1			
		AFL		292			
FAA 2018-12-07	2018-12-07 GULFSTREAM AEROSPACE CORPORATION: AMENDMENT 39-19311; DOCKET NO. FAA-2018-0104; PRODUCT IDENTIFIER 2017-CE-36-AD.					MANDATORY	COMPLIED WITH - CW
		MOS		19-JUL-2018			
23-JUL-2018		HRS/MSC	- (s)	893.9			
		AFL		348			
FAA 2018-20-04	AD 2018-20-04 GULFSTREAM AEROSPACE CORPORATION: AMENDMENT 39-19438; DOCKET NO. FAA-2018-0870,					MANDATORY	COMPLIED WITH - CW
		MOS		14-NOV-2018			
15-OCT-2018		HRS/MSC	- (s)	978.5			
		AFL		395			
FAA 2019-23-11	AD 2019-23-11 GULFSTREAM AEROSPACE CORPORATION: AMENDMENT 39-19805; DOCKET NO. FAA-2019-0960; PRODUCT IDENTIFIER 2019-CE-049-AD.					MANDATORY	NOT APPLICABLE
		DAYS		05-MAR-2020			
30-DEC-2019		HRS/MSC	-	1240.5			
		AFL		504			
FAA 2020-02-18	AD 2020-02-18 AIRPLANE FLIGHT MANUAL SUPPLEMENT					MANDATORY	COMPLIED WITH
		DAYS		05-MAR-2020			
13-FEB-2020		HRS/MSC	-	1240.5			
		AFL		504			
FAA 2020-11-01	AD 2020-11-01 PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) SOFTWARE UPDATE					MANDATORY	
		MOS	24		27-JUL-2022		
27-JUL-2020		HRS/MSC					
		AFL					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APPLIANCE - 6101/N47TR							
EASA 2013-0020	EASA AD 2013-0020 - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE - CANCELLED. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW (SUPERCEDED REF R1 993107)(RRR)
14-FEB-2013		MOS HRS/MSC - AFL		13-AUG-2014 0 0			
EASA 2013-0020 R01	EASA AD 2013-0020R1 - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					CANCELLED	COMPLIED WITH - CW. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW (CANCELED BY EASA AD 2013-0020R2 (993110)(RRR)
12-MAR-2013		MOS HRS/MSC - AFL		13-AUG-2014 0 0			
EASA 2013-0020 R02	EASA AD 2013-0020R2 - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE - CANCELLED. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW (CANCELED BY EASA AD 2013-0020R3 (993120)(RRR)
11-JUL-2013		MOS HRS/MSC - AFL		13-AUG-2014 0 0			
EASA 2013-0020 R03	EASA AD 2013-0020R3 - SAFETY BELT / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					CANCELLED	NOT APPLICABLE - CANCELLED. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW (CANCELED BY EASA AD 2013-0020 A4 993121)(RRR)
28-MAR-2014		MOS HRS/MSC - AFL		13-AUG-2014 0 0			
EASA 2013-0020 R04	EASA AD 2013-0020R4 - SAFETY BELT / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT					MANDATORY	COMPLIED WITH - CW. REMOVED FREQUENCY . CUSTOMER IS NOT REGULATED BY EASA 6/26/2015 (RRR)
11-JUL-2014		MOS HRS/MSC - AFL		23-DEC-2014 60.3 24			
EASA 2014-0142	EASA AD 2014-0142 - OXYGEN MASK REGULATOR INFLATABLE HARNESS / HOSE					CANCELLED	NOT APPLICABLE - CANCELLED. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW (CANCELLED BY EASA AD 2014-142 R1)(RRR)
18-JUN-2014		MOS HRS/MSC - AFL		13-AUG-2014 0 0			
FAA 2012-02-08	AD 2012-02-08 - AVIATION COMMUNICATION & SURVEILLANCE SYSTEMS, LLC					MANDATORY	NOT APPLICABLE - NA
13-MAR-2012		MOS HRS/MSC - (s) AFL		13-AUG-2014 8.7 4			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2015-08-07	AD 2015-08-07 ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) - OXYGEN MASK REGULATOR INFLATABLE HARNESS - IDENTIFICATION / REPLACEMENT					MANDATORY	COMPLIED WITH - CW. MID CABIN TEMPERATURE RHEOSTAT REQUIRES MORE SELECTION OF HOT AIR TO MAINTAIN SELECTED TEMPERATURE.
16-JUN-2015		MOS HRS/MSC AFL	- (s)	26-AUG-2016 531.2 193			
FAA 2015-16-04	AD 2015-16-04 KIDDE GRAVINER					MANDATORY	NOT APPLICABLE - NA
15-SEP-2015		MOS HRS/MSC AFL	- (s)	18-JAN-2016 345 134			
FAA 2015-23-09	AD 2015-23-09 ZODIAC AEROTECHNICS FLIGHTCREW OXYGEN MASK REGULATORS (PART 2 - REPLACE)					MANDATORY	NOT APPLICABLE - NA. PART NUMBER / SERIAL NUMBER NOT AFFECTED
28-DEC-2015		MOS HRS/MSC AFL	- (s)	08-AUG-2016 529.6 192			
FAA 2015-23-09 PARA (H)(2)(I)	AD 2015-23-09 ZODIAC AEROTECHNICS FLIGHTCREW OXYGEN MASK REGULATORS (PART 1 - INSPECT)					MANDATORY	NOT APPLICABLE - NA
28-DEC-2015		MOS HRS/MSC AFL	- (s)	18-JAN-2016 345 134			
FAA 2016-11-20	AD 2016-11-20 - B/E AEROSPACE PBE P/N 119003-11					CANCELLED	NOT APPLICABLE - NA
15-JUL-2016		MOS HRS/MSC AFL	-	25-AUG-2016 529.6 192			
FAA 2017-18-12	AD 2017-18-12 B/E AEROSPACE					MANDATORY	NOT APPLICABLE - NA
		MOS HRS/MSC AFL	- (s)	01-MAR-2018 828.3 318			
FAA 2018-21-14	AD 2018-21-14 ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE) - OXYGEN MASK REGULATOR HARNESS INFLATION HOSE - IDENTIFICATION / REPLACEMENT					MANDATORY	
27-MAR-2019		MOS HRS/MSC AFL	36	(EFF)	27-MAR-2022		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 6101/N47TR							
#	3202908-36-1912	HONEYWELL SB 3202908-36-1912 - REWORK RIGHT FOUR-INCH DIAMETER CHECK VALVE, PN 3202908-1 TO PN 3202908-2, USED ON THE GULFSTREAM G650.				RECOMMENDED	COMPLIED WITH - CW
		MOS		15-AUG-2016			
		HRS/MSC -		529.6			
		AFL		192			
ACB	ACB001	ACB 1 - REPLACEMENT - ENGINE SPILL RETURN FUEL TUBE - ROLLS-ROYCE SB-BR700-73-101847				MANDATORY	NOT APPLICABLE - NA. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW (NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER)(RRR)
	21-MAY-2013	MOS		14-AUG-2014			
		HRS/MSC - (s)		0			
		AFL		0			
ACB	ACB002	ACB 2 - OPERATIONAL INSTRUCTIONS - REVISED ENGINE OPERATING PROCEDURES AFTER IN-FLIGHT SHUTDOWN				MANDATORY	NOT APPLICABLE - NA
	13-AUG-2013	MOS		12-AUG-2014			
		HRS/MSC - (s)		0			
		AFL		0			
ACB	ACB003	ACB 3 - INSPECTION - FLAP TRACK LOWER ATTACH POINT FASTNERS				CANCELLED	NOT APPLICABLE - NA. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW (NOT APPLICABLE BY AIRCRAFT SERIAL NUMBER)(RRR)
	24-JUL-2014	MOS		13-AUG-2014			
		HRS/MSC -		0			
		AFL		0			
ACB	ACB003A	ACB 3A - INSPECTION - FLAP TRACK LOWER ATTACH POINT FASTENERS				CANCELLED	NOT APPLICABLE - NA
	24-JUL-2014	MOS		12-AUG-2014			
		HRS/MSC - (s)		0			
		AFL		0			
ACB	ACB004	ACB 4 INSPECTION - BRAKE INLET SELF-SEALING COUPLINGS TORQUE				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
	06-NOV-2015	MOS		16-NOV-2015			
		HRS/MSC -		0			
		AFL		0			
ACB	ACB004A PART I	ACB 4A INSPECTION - BRAKE INLET SELF-SEALING COUPLINGS TORQUE (PART 1)				MANDATORY	COMPLIED WITH - CW
	06-NOV-2015	MOS		19-NOV-2015			
		HRS/MSC - (s)		301.4			
		AFL		115			
ACB	ACB004A PART II	ACB 4A INSPECTION - BRAKE INLET SELF-SEALING COUPLINGS TORQUE (PART 2)				MANDATORY	NOT APPLICABLE - NA. NOTE- THE SELF SEALING COUPLERS HAVE BEEN PERMANENTLY REMOVED UNDER THIS WORK ORDER, REFERENCE 5.48 (CB155), 5.54 (CB155A), 5.49 (ASC084), & 5.53 (ASC084A).
	06-NOV-2015	MOS		23-AUG-2016			
		HRS/MSC - (s)		529.6			
		AFL		192			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ACB ACB006	ACB 006 INSPECTION - HIGH PRESSURE COMPRESSOR VARIABLE STATOR VANES MECHANISM (ROLLS-ROYCE NMSB SB-BR700-72-900178)						COMPLIED WITH - CW
11-JUL-2019		MOS HRS/MSC - (s) AFL		18-JUL-2019 1115.4 450			
ASC ASC001B	ASC 001B - G650 DATAPLATE - INSTALLATION					CANCELLED	COMPLIED WITH - CW
		MOS HRS/MSC - AFL		13-AUG-2014 5.5 3			
ASC ASC003A	ASC 003A - COMMUNICATIONS MANAGEMENT FUNCTION (CMF) - SATCOM DIRECT DATALINK SERVICE PROVIDER					OPTIONAL	COMPLIED WITH - CW
08-APR-2014		MOS HRS/MSC - AFL		30-OCT-2015 274.4 109			
ASC ASC004	ASC 004 AIRCRAFT HEALTH AND TREND MONITORING SYSTEM (AHTMS) - CELL PHONE DATA TRANSMISSION OPTION					CANCELLED	COMPLIED WITH - PRODUCTION EQUIVALENT
16-AUG-2013		MOS HRS/MSC - AFL		02-NOV-2015 274.4 109			
ASC ASC006	ASC 006 - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION					CANCELLED	COMPLIED WITH - CW
03-DEC-2012		MOS HRS/MSC - AFL		13-AUG-2014 0 0			
ASC ASC006A	ASC 006A - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION					CANCELLED	COMPLIED WITH - CW
31-MAY-2013		MOS HRS/MSC - AFL		01-OCT-2014 0 0			
ASC ASC006B	ASC 006B - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
08-APR-2014		MOS HRS/MSC - AFL		30-MAR-2018 0 0			
ASC ASC006C	ASC 006C - LIGHTNING SENSOR SYSTEM (LSS) - INSTALLATION					OPTIONAL	COMPLIED WITH - CW. BY BOBBY T STRICKLAND GA674
		MOS HRS/MSC - AFL		01-OCT-2014 0 0			
ASC ASC014 PART 1	ASC 14(PART 1) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
15-OCT-2014		MOS HRS/MSC - AFL		15-JAN-2015 0 0			
ASC ASC014 PART 2	ASC 14(PART 2) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
15-OCT-2014		MOS HRS/MSC - AFL		15-JAN-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC014A PART 1	ASC 14A (PART 1) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
15-JAN-2015		MOS		17-FEB-2015			
		HRS/MSC -		0			
		AFL		0			
ASC ASC014A PART 2	ASC 14A (PART 2) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
15-JAN-2015		MOS		17-FEB-2015			
		HRS/MSC -		0			
		AFL		0			
ASC ASC014B PART 1	ASC 14B (PART 1) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-FEB-2015		MOS		05-APR-2016			
		HRS/MSC -		0			
		AFL		0			
ASC ASC014B PART 2	ASC 14B (PART 2) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-FEB-2015		MOS		05-APR-2016			
		HRS/MSC -		0			
		AFL		0			
ASC ASC014C PART 1	ASC 014C (PART 1) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
05-APR-2016		MOS		28-OCT-2016			
		HRS/MSC -		0			
		AFL		0			
ASC ASC014C PART 2	ASC 014C (PART 2) - GVI EXTENDED RANGE (G650ER) - MODIFICATIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
05-APR-2016		MOS		28-OCT-2016			
		HRS/MSC -		0			
		AFL		0			
ASC ASC016	ASC 016 ENGINE ELECTRONIC CONTROLLER - K7.1.3 SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - CW
		MOS		20-JUN-2017			
		HRS/MSC -		733.6			
		AFL		277			
ASC ASC018	ASC 018 PLANEVIEW II AVIONICS ENHANCEMENT					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
01-OCT-2014		MOS		30-OCT-2014			
		HRS/MSC -		0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC018A	ASC 018A - PLANEVIEW II AVIONICS ENHANCEMENT					OPTIONAL	COMPLIED WITH - PRODUCTION EQUIVALENT
29-OCT-2014		MOS HRS/MSC - AFL		03-NOV-2015 274.4 109			
ASC ASC025	ASC 025 - FLASHLIGHTS - REPLACEMENT					OPTIONAL	COMPLIED WITH - CW
06-JUL-2015		MOS HRS/MSC - AFL		05-NOV-2015 274.4 109			
ASC ASC026	ASC 026 AIRPORT ACCESS - 74,900 POUND WEIGHT LIMITATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-SEP-2013		MOS HRS/MSC - AFL		28-OCT-2016 0 0			
ASC ASC027	ASC 027 AIRPORT ACCESS - 90,000 POUND WEIGHT LIMITATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-SEP-2013		MOS HRS/MSC - AFL		28-OCT-2016 0 0			
ASC ASC028	ASC 028 AIRPORT ACCESS - 95,000 POUND WEIGHT LIMITATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-SEP-2013		MOS HRS/MSC - AFL		28-OCT-2016 0 0			
ASC ASC036	ASC 36 - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT VERSION 2 INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
15-DEC-2014		MOS HRS/MSC - AFL		15-JUN-2016 0 0			
ASC ASC036A	ASC 36A - AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT VERSION 2 INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
14-JUN-2016		MOS HRS/MSC - AFL		24-AUG-2016 0 0			
ASC ASC036B	ASC 36B AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT VERSION 2 INSTALLATION					OPTIONAL	COMPLIED WITH
23-AUG-2016		MOS HRS/MSC - AFL		06-DEC-2019 1207.4 492			
ASC ASC037	ASC 37 FCC SOFTWARE UPDATE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS HRS/MSC - AFL		29-JUN-2016 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC037A	ASC 37A FCC SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
		MOS		09-AUG-2016			
		HRS/MSC -		529.6			
		AFL		192			
ASC ASC038	ASC 038 INDICATING / RECORDING (ATA 31) - PLANEVIEW II AVIONICS ENHANCEMENT					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-DEC-2016		MOS		22-DEC-2016			
		HRS/MSC -		0			
		AFL		0			
ASC ASC038A	ASC 038A INDICATING / RECORDING (ATA 31) - PLANEVIEW II AVIONICS ENHANCEMENT					CANCELLED	COMPLIED WITH - CW
22-DEC-2016		MOS		12-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
ASC ASC040	ASC 40 - HYDRAULIC REPLENISHER PUMP - PLACARD INSTALLATION					OPTIONAL	COMPLIED WITH - CW
11-NOV-2014		MOS		29-OCT-2015			
		HRS/MSC -		274.4			
		AFL		109			
ASC ASC048 PART 2	ASC 048 SPOILER JOINT ANTI-ROTATION RETENTION WASHER - INSTALLATION (PART 2)					CANCELLED	COMPLIED WITH - CW
12-AUG-2016		MOS		21-JUN-2017			
		HRS/MSC -		733.6			
		AFL		277			
ASC ASC049 PART 1	ASC 049 - PART 1 COCKPIT IMPROVEMENTS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-FEB-2015		MOS		19-MAR-2015			
		HRS/MSC -		0			
		AFL		0			
ASC ASC049 PART 2	ASC 049 - PART 2 COCKPIT IMPROVEMENTS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-FEB-2015		MOS		19-MAR-2015			
		HRS/MSC -		0			
		AFL		0			
ASC ASC049 PART 3	ASC 049 - PART 3 COCKPIT IMPROVEMENTS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-FEB-2015		MOS		19-MAR-2015			
		HRS/MSC -		0			
		AFL		0			
ASC ASC049A PART 1	ASC 049A - PART 1 COCKPIT IMPROVEMENTS					CANCELLED	COMPLIED WITH - CW
19-MAR-2015		MOS		03-NOV-2015			
		HRS/MSC -		274.4			
		AFL		109			
ASC ASC049A PART 2	ASC 049A - PART 2 COCKPIT IMPROVEMENTS					CANCELLED	COMPLIED WITH - CW
19-MAR-2015		MOS		03-NOV-2015			
		HRS/MSC -		274.4			
		AFL		109			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC049A PART 3	ASC 049A - PART 3 COCKPIT IMPROVEMENTS					CANCELLED	COMPLIED WITH - CW
19-MAR-2015		MOS		03-NOV-2015			
		HRS/MSC -		274.4			
		AFL		109			
ASC ASC050	ASC 50 - FUEL SERVICING DOOR - REFUELING DECAL AND DOOR HOLD OPEN INSTALLATION					CANCELLED	COMPLIED WITH - CW. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
12-AUG-2015		MOS		01-NOV-2015			
		HRS/MSC -		274.4			
		AFL		109			
ASC ASC050A	ASC 50A FUEL SERVICING DOOR - REFUELING DECAL AND DOOR HOLD OPEN INSTALLATION					OPTIONAL	COMPLIED WITH - CW
06-OCT-2015		MOS		01-NOV-2015			
		HRS/MSC -		274.4			
		AFL		109			
ASC ASC051	ASC 051 SECONDARY POWER DISTRIBUTION SYSTEM (SPDS) SOFTWARE UPDATE					CANCELLED	COMPLIED WITH - CW
01-NOV-2016		MOS		28-JUN-2017			
		HRS/MSC -		733.6			
		AFL		277			
ASC ASC051A	ASC 051A SECONDARY POWER DISTRIBUTION SYSTEM (SPDS) SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW. UPDATE ONLY ASC 051 COMPLIED WITH JUN2017 W/O SC3900.5.17
		MOS		03-JUL-2018			
		HRS/MSC -		893.9			
		AFL		348			
ASC ASC052	ASC 052 MAIN ENTRANCE DOOR - NOISE REDUCTION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
29-OCT-2014		MOS		12-MAR-2015			
		HRS/MSC -		0			
		AFL		0			
ASC ASC052A	ASC 52A - MAIN ENTRANCE DOOR - NOISE REDUCTION					CANCELLED	COMPLIED WITH - CW
12-MAR-2015		MOS		03-NOV-2015			
		HRS/MSC -		274.4			
		AFL		109			
ASC ASC052B	ASC 52B - MAIN ENTRANCE DOOR - NOISE REDUCTION					MANDATORY	COMPLIED WITH - CW. PREVIOUSLY COMPLIED WITH ON W/O 433910 5.24
27-APR-2016		MOS		09-AUG-2016			
		HRS/MSC -		529.6			
		AFL		192			
ASC ASC053 PART 1	ASC 53 - (PART 1) MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP MECHANISM AND AIRSTAIR MODS					OPTIONAL	COMPLIED WITH - CW
23-OCT-2014		MOS		29-OCT-2015			
		HRS/MSC -		274.4			
		AFL		109			
ASC ASC053 PART 3	ASC 53 - (PART 3) MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP MECHANISM AND AIRSTAIR MODS					OPTIONAL	COMPLIED WITH - PRODUCTION EQUIVALENT
23-OCT-2014		MOS		29-OCT-2015			
		HRS/MSC -		274.4			
		AFL		109			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC055	ASC 55 AUTOBRAKE SYSTEM - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-NOV-2015		MOS HRS/MSC - AFL		11-DEC-2015 0 0			
ASC ASC055A	ASC 55A AUTOBRAKE SYSTEM - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
11-DEC-2015		MOS HRS/MSC - AFL		06-JUN-2016 0 0			
ASC ASC055B	ASC 55B AUTOBRAKE SYSTEM - INSTALLATION					CANCELLED	COMPLIED WITH - CW. CMP G650 970551 AIRFRAME ASC 55A AUTOBRAKE SYSTEM - INSTALLATIONPMO APPROVED AND HAS IT SLOTTED FOR 8/8/16DLRO 561065 CAL. DUE 10/16, TORQUE WRENCHS560292 CAL. DUE 04/17560431 CAL. DUE 01/17553006 CAL. DUE 12/16560120 CAL. DUE 11/16562
06-JUN-2016		MOS HRS/MSC - AFL		24-AUG-2016 529.6 192			
ASC ASC055C	ASC 55C AUTOBRAKE SYSTEM - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
06-DEC-2016		MOS HRS/MSC - AFL		27-JUN-2017 733.6 277			
ASC ASC057	ASC 57 - ENHANCED VISION SYSTEM (EVS) HEAD-DOWN VIDEO FUNCTION - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
15-OCT-2014		MOS HRS/MSC - AFL		03-NOV-2015 274.4 109			
ASC ASC058	ASC 058 - MAIN ENTRANCE DOOR STORAGE BOX SPRING REPLACEMENT					OPTIONAL	COMPLIED WITH - CW
28-MAY-2015		MOS HRS/MSC - AFL		28-OCT-2015 274.4 109			
ASC ASC059	ASC 59 MAIN ENTRANCE DOOR - WATER DRAINAGE MODIFICATION					OPTIONAL	COMPLIED WITH - CW
27-FEB-2015		MOS HRS/MSC - AFL		03-NOV-2015 274.4 109			
ASC ASC060	ASC 60 MAIN ENTRANCE DOOR - WATER INTRUSION REDUCTION MODIFICATION					OPTIONAL	COMPLIED WITH - CW
27-FEB-2015		MOS HRS/MSC - AFL		03-NOV-2015 274.4 109			
ASC ASC064	ASC 64 AFT EQUIPMENT BAY WATER SHIELD - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
09-SEP-2015		MOS HRS/MSC - AFL		10-JUL-2017 733.6 277			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC065	ASC 065 MAIN ENTRANCE DOOR MANUAL OPERATION MECHANISM - INSTALLATION					CANCELLED	COMPLIED WITH - CW
26-JUN-2017		MOS		06-SEP-2017			
		HRS/MSC -		740.5			
		AFL		280			
ASC ASC066A	ASC 066A MAIN ENTRANCE DOOR (MED) - EMED RIGGING IMPROVEMENT					OPTIONAL	COMPLIED WITH - CW
08-MAY-2017		MOS		06-SEP-2017			
		HRS/MSC -		740.5			
		AFL		280			
ASC ASC067	ASC 67 - WINDSHIELD HEAT TEMPERATURE SENSING ELEMENT BONDING JUMPER - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
21-SEP-2015		MOS		04-NOV-2015			
		HRS/MSC -		274.4			
		AFL		109			
ASC ASC068	ASC 68 BAGGAGE COMPARTMENT GRAB HANDLE - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
01-JUN-2016		MOS		12-OCT-2016			
		HRS/MSC -		0			
		AFL		0			
ASC ASC069	ASC 069 - PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) REMOTE ELECTRONICS UNIT (REU) SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
28-SEP-2017		MOS		16-JUL-2018			
		HRS/MSC -		893.9			
		AFL		348			
ASC ASC072	ASC 072 APU POWER FEEDER CABLE INSTALLATION - MODIFICATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
11-AUG-2016		MOS		16-MAR-2017			
		HRS/MSC -		0			
		AFL		0			
ASC ASC072A	ASC 072A APU POWER FEEDER CABLE INSTALLATION - MODIFICATION					OPTIONAL	COMPLIED WITH - CW
16-MAR-2017		MOS		19-JUL-2018			
		HRS/MSC -		893.9			
		AFL		348			
ASC ASC073	ASC 073 TIRE PRESSURE MONITORING UNIT (TPMU) SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - CW
18-AUG-2016		MOS		08-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
ASC ASC074	ASC 074 NOSE WHEEL STEERING SYSTEM - UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. AFTER COMPLIANCE SEE CMP CODES 325208 AND 325213 FOR CODE CHANGE.
14-APR-2017		MOS		16-JUN-2017			
		HRS/MSC -		0			
		AFL		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC074A	ASC 074 REV A NOSE WHEEL STEERING SYSTEM - UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-JUN-2017		MOS		15-AUG-2017			
		HRS/MSC -		0			
		AFL		0			
ASC ASC074B	ASC 074 REV B NOSE WHEEL STEERING SYSTEM - UPGRADE					OPTIONAL	COMPLIED WITH - CW. REF CORRIDOR 5.13
15-AUG-2017		MOS		20-JUL-2018			
		HRS/MSC -		893.9			
		AFL		348			
ASC ASC076B	ASC 076B AIRCRAFT HEALTH AND TREND MONITORING SYSTEM - SOFTWARE UPDATE 2					OPTIONAL	COMPLIED WITH
01-NOV-2019		MOS		23-JUL-2020			
		HRS/MSC -		1245.8			
		AFL		507			
ASC ASC079	ASC 79 LANDING GEAR CONTROL UNIT MOD D UPDATE					OPTIONAL	COMPLIED WITH - CW
06-MAY-2016		MOS		13-AUG-2016			
		HRS/MSC -		529.6			
		AFL		192			
ASC ASC081	ASC 081 MED LATCH ACTUATOR UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
08-MAY-2017		MOS		21-AUG-2017			
		HRS/MSC -		0			
		AFL		0			
ASC ASC081A	ASC 081A MED LATCH ACTUATOR UPGRADE					CANCELLED	COMPLIED WITH - CW
18-AUG-2017		MOS		06-SEP-2017			
		HRS/MSC -		740.5			
		AFL		280			
ASC ASC084	ASC 084 MAIN LANDING GEAR AND BRAKE ASSEMBLY - MODIFICATION					CANCELLED	COMPLIED WITH - CW
29-JUL-2016		MOS		09-AUG-2016			
		HRS/MSC -		529.6			
		AFL		192			
ASC ASC084A	ASC 084A MAIN LANDING GEAR AND BRAKE ASSEMBLY - MODIFICATION					OPTIONAL	COMPLIED WITH - CW
19-AUG-2016		MOS		23-AUG-2016			
		HRS/MSC -		529.6			
		AFL		192			
ASC ASC085	ASC 085 KA-BAND FIN CAP RADOME - INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
10-MAR-2017		MOS		07-MAR-2019			
		HRS/MSC -		0			
		AFL		0			
ASC ASC086	ASC 086 MAIN ENTRY DOOR - SERVICE DOOR PANEL SECURITY COVER - INSTALLATION					OPTIONAL	COMPLIED WITH - CW
23-JUN-2016		MOS		19-JUN-2017			
		HRS/MSC -		733.6			
		AFL		277			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC088	ASC 088 ENGINE ELECTRONIC CONTROLLER - K8.0.2 SOFTWARE UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
10-SEP-2018		MOS HRS/MSC - AFL		26-SEP-2018 0 0			
ASC ASC088A	ASC 088A ENGINE ELECTRONIC CONTROLLER - K8.0.2 SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - CW
26-SEP-2018		MOS HRS/MSC - AFL		13-JUN-2019 1103.7 440			
ASC ASC089	ASC 089 DOORS (ATA 52), MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP STOP BOLTS - REPLACEMENT					OPTIONAL	COMPLIED WITH - CW
16-DEC-2016		MOS HRS/MSC - AFL		09-FEB-2017 642 246			
ASC ASC091	ASC 091 ACOUSTIC DOOR NOISE REDUCTION - MODIFICATION					CANCELLED	COMPLIED WITH - CW
09-AUG-2017		MOS HRS/MSC - AFL		24-AUG-2017 740.5 280			
ASC ASC091A	ASC 091A ACOUSTIC DOOR NOISE REDUCTION - MODIFICATION					OPTIONAL	COMPLIED WITH - CW. COMPLIED WITH CMP G650 970911 AIRFRAME ASC 091A ACOUSTIC DOOR NOISE REDUCTION - MODIFICATION BY COMPLYING WITH THE MODIFICATION INSTRUCTIONS PER ASC091A TO MEET THE INTENT OF ASC 091A.REF SC519357 5.9 FOR OTHER COMPLIANCE INFORMATION.
01-DEC-2017		MOS HRS/MSC - AFL		10-JUL-2018 893.9 348			
ASC ASC092	ASC 092 PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) MOTOR CONTROL ELECTRONICS (MCE) SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
28-SEP-2017		MOS HRS/MSC - AFL		16-JUL-2018 893.9 348			
ASC ASC093	ASC 093 FLIGHT CONTROLS (ATA 27) - FCC SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
		MOS HRS/MSC - AFL		19-JUL-2018 893.9 348			
ASC ASC094	ASC 094 DOORS (ATA 52) - ELECTRIC MAIN ENTRANCE DOOR (EMED) WEAR PAD MODIFICATION					OPTIONAL	COMPLIED WITH - CW
21-DEC-2016		MOS HRS/MSC - AFL		12-JAN-2017 622.3 231			
ASC ASC097	ASC 097 PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) REMOTE ELECTRONICS UNIT (REU) CONNECTOR UPDATES					OPTIONAL	COMPLIED WITH - CW
28-SEP-2017		MOS HRS/MSC - AFL		16-JUL-2018 893.9 348			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC098	ASC 098 HORIZONTAL STABILIZER CONTROL UNIT (HSCU) SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - CW. REF 11.1, 11.3, 11.4.
		MOS		26-JUN-2018			
		HRS/MSC -		893.9			
		AFL		348			
ASC ASC099	ASC 099 MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP MECHANISM IMPROVEMENT					CANCELLED	COMPLIED WITH - CW
		MOS		06-SEP-2017			
		HRS/MSC -		740.5			
		AFL		280			
ASC ASC099A	ASC 099A MAIN ENTRANCE DOOR - BOTTOM FOLDING STEP MECHANISM IMPROVEMENT					OPTIONAL	NOT APPLICABLE - NA
		MOS		22-JAN-2018			
15-JAN-2018		HRS/MSC -		809.2			
		AFL		310			
ASC ASC102	ASC 102 MODIFICATION FCC SOFTWARE V8.2 UPDATE					OPTIONAL	COMPLIED WITH - CW
		MOS		17-JUN-2019			
15-NOV-2018		HRS/MSC -		1103.7			
		AFL		440			
ASC ASC103	ASC 103 AUXILIARY HYDRAULIC PUMP - GROUNDING INSTALLATION					OPTIONAL	COMPLIED WITH - CW
		MOS		11-JUN-2019			
07-AUG-2018		HRS/MSC -		1103.7			
		AFL		440			
ASC ASC105	ASC 105 - DATA LAN MANAGEMENT UNIT HARNESS - SERVICE LOOP INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		12-MAR-2019			
		HRS/MSC -		0			
		AFL		0			
ASC ASC111	ASC 111 ENGINE FIRE BOTTLE HARNESS INSTALLATION - MODIFICATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		22-MAR-2019			
31-JUL-2018		HRS/MSC -		0			
		AFL		0			
ASC ASC111A	ASC 111A ENGINE FIRE BOTTLE HARNESS INSTALLATION - MODIFICATION					OPTIONAL	COMPLIED WITH - CW
		MOS		18-JUN-2019			
21-MAR-2019		HRS/MSC -		1103.7			
		AFL		440			
ASC ASC113	ASC 113 APU EXHAUST FAIRING DRAINAGE - MODIFICATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		03-DEC-2018			
24-AUG-2018		HRS/MSC -		0			
		AFL		0			
ASC ASC113A	ASC 113A APU EXHAUST FAIRING DRAINAGE - MODIFICATION					OPTIONAL	COMPLIED WITH - CW
		MOS		12-JUN-2019			
30-NOV-2018		HRS/MSC -		1103.7			
		AFL		440			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC116	ASC 116 BATTERY CHARGER MODE CONTROL RELAYS AND ELECTRICAL BACKUP HYDRAULIC ACTUATOR BATTERY CHARGER NO. 2 - REMOVAL					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
13-FEB-2019		MOS		10-APR-2019			
		HRS/MSC -		0			
		AFL		0			
ASC ASC116A	ASC 116A BATTERY CHARGER MODE CONTROL RELAYS AND ELECTRICAL BACKUP HYDRAULIC ACTUATOR BATTERY CHARGER NO. 2 - REMOVAL					OPTIONAL	COMPLIED WITH - CW
10-APR-2019		MOS		18-JUN-2019			
		HRS/MSC -		1103.7			
		AFL		440			
ASC ASC117	ASC 117 HYDRAULIC LINE SUPPORT BRACKET INSTALLATION - MODIFICATION TO PROVIDE SIDE BRACE ACTUATOR CLEARANCE					OPTIONAL	COMPLIED WITH - CW
06-FEB-2019		MOS		06-JUN-2019			
		HRS/MSC -		1103.7			
		AFL		440			
ASC ASC123A	ASC 123A APU ELECTRONIC CONTROL UNIT SOFTWARE - UPDATE					OPTIONAL	COMPLIED WITH
27-APR-2020		MOS		27-JUL-2020			
		HRS/MSC -		1245.8			
		AFL		507			
ASC ASC124	ASC 124 PYLON SEAL RETAINER - MODIFICATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
21-JAN-2019		MOS		08-FEB-2019			
		HRS/MSC -		0			
		AFL		0			
ASC ASC133	ASC 133 ENGINE ELECTRONIC CONTROLLER - K9.0.1 SOFTWARE UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
05-AUG-2019		MOS		23-AUG-2019			
		HRS/MSC -		0			
		AFL		0			
ASC ASC134B PART I	ASC 134B (PART 1) WEDGE INSTALLATION - TRAILING EDGE, RUDDER					OPTIONAL	COMPLIED WITH
21-FEB-2020		MOS		23-DEC-2019			
		HRS/MSC -		1240.5			
		AFL		504			
ASC ASC901	ASC 901 - PLANEVIEW II MASTER OPERATING SYSTEM SOFTWARE UPDATE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
01-OCT-2014		MOS		30-OCT-2014			
		HRS/MSC -		0			
		AFL		0			
ASC ASC901A	ASC 901A - PLANEVIEW II MASTER OPERATING SYSTEM SOFTWARE UPDATE					OPTIONAL	COMPLIED WITH - PRODUCTION EQUIVALENT
29-OCT-2014		MOS		03-NOV-2015			
		HRS/MSC -		274.4			
		AFL		109			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ASC ASC902	ASC 902 INDICATING / RECORDING (ATA 31) - PLANEVIEW II MASTER OPERATING SYSTEM SOFTWARE UPDATE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		22-DEC-2016			
		HRS/MSC -		0			
		AFL		0			
ASC ASC902A	ASC 902A INDICATING / RECORDING (ATA 31) - PLANEVIEW II MASTER OPERATING SYSTEM SOFTWARE UPDATE					CANCELLED	COMPLIED WITH - CW
		MOS		12-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
CB 982600	CB 260 INSPECTION-SEAT BELT END RELEASE BUCKLES (AMSAFE)						NOT APPLICABLE
		MOS		12-NOV-2019			
		HRS/MSC -		1189.3			
		AFL		486			
CB CB059	CB 59 - MODIFICATION - MAIN ENTRANCE DOOR BOTTOM FOLDING STEP MECHANISM (ASC 053)					MANDATORY	COMPLIED WITH - PRODUCTION EQUIVALENT
		MOS		29-OCT-2015			
23-OCT-2014		HRS/MSC - (s)		274.4			
		AFL		109			
CB CB060	CB 60 - MODIFICATION - BATTERY CHARGER, P/N 100-1311-01					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		13-AUG-2015			
20-NOV-2014		HRS/MSC -		0			
		AFL		0			
CB CB060A	CB 60A - MODIFICATION - BATTERY CHARGER, P/N 100-1311-01					MANDATORY	COMPLIED WITH - CW
		MOS		28-OCT-2015			
20-NOV-2014		HRS/MSC - (s)		274.4			
		AFL		109			
CB CB061	CB 61 - INSPECTION - ENGINE DRIVEN HYDRAULIC AND FUEL PUMP V-BAND CLAMPS (ROLLS-ROYCE NMSB BR700-71-900003 AND BR700-73-900009)					MANDATORY	COMPLIED WITH - CW
		MOS		17-FEB-2015			
03-DEC-2014		HRS/MSC - (s)		120			
		AFL		52			
CB CB062	CB 62 - MODIFICATION - ENHANCED VISION SYSTEM PROCESSOR - SOFTWARE UPGRADE					MANDATORY	COMPLIED WITH - CW
		MOS		03-NOV-2015			
04-DEC-2014		HRS/MSC - (s)		274.4			
		AFL		109			
CB CB067A	CB 67A MODIFICATION - CO-PILOT'S CREW ALERTING SYSTEM (CAS) SCROLL SWITCH WIRING					MANDATORY	NOT APPLICABLE - NA
		MOS		19-NOV-2015			
20-JAN-2015		HRS/MSC - (s)		301.4			
		AFL		115			
CB CB068	CB 68 - INSTALLATION - HYDRAULIC REPLENISHER TANK PLACARD (ASC 040)					MANDATORY	COMPLIED WITH - CW
		MOS		29-OCT-2015			
11-NOV-2014		HRS/MSC - (s)		274.4			
		AFL		109			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB072	CB 72 - INSPECTION - CABIN PRESSURIZATION TEST PORT FITTING CAP					MANDATORY	COMPLIED WITH - CW
11-FEB-2015		MOS		16-MAR-2015			
		HRS/MSC	- (s)	131.6			
		AFL		54			
CB CB074	CB 74 MODIFICATION - MAIN ENTRANCE DOOR WATER DRAINAGE (ASC 059)					MANDATORY	COMPLIED WITH - CW
27-FEB-2015		MOS		03-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB075	CB 75 MODIFICATION - MAIN ENTRANCE DOOR WATER INTRUSION REDUCTION (ASC 060)					MANDATORY	COMPLIED WITH - CW
27-FEB-2015		MOS		03-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB076	CB 76 - MODIFICATION - HIGH SPEED DATA - SOFTWARE UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
18-MAR-2015		MOS		27-MAR-2015			
		HRS/MSC	-	0			
		AFL		0			
CB CB076A	CB 76A - MODIFICATION - HIGH SPEED DATA - SOFTWARE UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
18-MAR-2015		MOS		15-JUL-2015			
		HRS/MSC	-	0			
		AFL		0			
CB CB076B	CB 76B - MODIFICATION - HIGH SPEED DATA - SOFTWARE UPGRADE					MANDATORY	COMPLIED WITH - CW
18-MAR-2015		MOS		05-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB077	CB 77 - REPLACEMENT - EMERGENCY GEAR EXTENSION CABLE HARDWARE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
19-MAR-2015		MOS		12-JUN-2015			
		HRS/MSC	-	0			
		AFL		0			
CB CB077A	CB 77A - REPLACEMENT - EMERGENCY GEAR EXTENSION CABLE HARDWARE					MANDATORY	COMPLIED WITH - CW
19-MAR-2015		MOS		29-OCT-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB079	CB 79 - INSPECTION - HEATED FUEL RETURN LINE COUPLING NUT SUBASSEMBLY					MANDATORY	COMPLIED WITH - CW
27-APR-2015		MOS		05-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB080	CB 80 - INSPECTION - PARKING BRAKE CABLE					MANDATORY	COMPLIED WITH - CW
29-MAY-2015		MOS		28-OCT-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB081	CB 081 - REPLACEMENT - FUEL COOLED OIL COOLER (FCOC) TUBE					MANDATORY	COMPLIED WITH - CW
17-JUN-2015		MOS		05-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB082A	CB 82A - INSTALLATION - HYDRAULIC SYSTEM GROUND SERVICE PANEL PLACARD					MANDATORY	COMPLIED WITH - CW
17-JUN-2015		MOS		02-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB084	CB 84 - INSTALLATION - FUEL SERVICING DOOR REFUELING DECAL AND HOLD OPEN (ASC 050)					MANDATORY	COMPLIED WITH - CW
12-AUG-2015		MOS		01-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB087	CB 87 INSPECTION - ENGINE FIRE BOTTLE CARTRIDGE (SQUIB) ELECTRICAL CONNECTIONS					CANCELLED	COMPLIED WITH - CW
15-SEP-2015		MOS		29-OCT-2015			
		HRS/MSC	-	274.4			
		AFL		109			
CB CB087A	CB 87A INSPECTION - ENGINE FIRE BOTTLE CARTRIDGE (SQUIB) ELECTRICAL CONNECTIONS					MANDATORY	COMPLIED WITH - CW
15-SEP-2015		MOS		18-DEC-2015			
		HRS/MSC	- (s)	327.3			
		AFL		128			
CB CB088	CB 88 REPLACEMENT - MAIN ENTRANCE DOOR TORQUE TUBE BEARING HOUSING HARDWARE					MANDATORY	NOT APPLICABLE - NA. CUSTOMER REQUEST CODE ADDED.
15-SEP-2015		MOS		19-NOV-2015			
		HRS/MSC	- (s)	301.4			
		AFL		115			
CB CB089	CB 89 REPLACEMENT - FLASHLIGHTS (ASC025)					MANDATORY	COMPLIED WITH - CW
06-JUL-2015		MOS		05-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
CB CB090	CB 90 INSPECTION - PASSENGER SEAT RESTRAINT SYSTEM (AMSAFE SB NO. 504443-25-02)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-SEP-2015		MOS		02-OCT-2015			
		HRS/MSC	-	0			
		AFL		0			
CB CB090A	CB 90A INSPECTION - PASSENGER SEAT RESTRAINT SYSTEM (AMSAFE SB NO. 504443-25-02)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
16-SEP-2015		MOS		22-OCT-2015			
		HRS/MSC	-	0			
		AFL		0			
CB CB090B	CB 90B INSPECTION - PASSENGER SEAT RESTRAINT SYSTEM (AMSAFE SB NO. 504443-25-02)					MANDATORY	COMPLIED WITH - CW
16-OCT-2015		MOS		02-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB091	CB 91 INSPECTION - ITT CANNON CONNECTORS					CANCELLED	NOT APPLICABLE - NA
16-SEP-2015		MOS HRS/MSC - AFL		19-NOV-2015 301.4 115			
CB CB092	CB 92 INSPECTION - GEARBOX BREATHER FLEX BOOT CLAMPS					MANDATORY	COMPLIED WITH - CW
16-SEP-2015		MOS HRS/MSC - (s) AFL		29-OCT-2015 274.4 109			
CB CB093	CB 93 REPLACEMENT - FLASHLIGHTS (OXLEY)					MANDATORY	NOT APPLICABLE - NA
16-SEP-2015		MOS HRS/MSC - (s) AFL		05-NOV-2015 274.4 109			
CB CB094	CB 94 INSTALLATION - WINDSHIELD HEAT TEMPERATURE SENSING ELEMENT BONDING JUMPER (ASC 067)					MANDATORY	COMPLIED WITH - CW
21-SEP-2015		MOS HRS/MSC - (s) AFL		04-NOV-2015 274.4 109			
CB CB095	CB 95 REPLACEMENT - WATER STERILIZER FILTERS					MANDATORY	COMPLIED WITH - CW
14-OCT-2015		MOS HRS/MSC - (s) AFL		02-NOV-2015 274.4 109			
CB CB096	CB 96 INSPECTION - VELCRO INSTALLATION ON UPPER INSTRUMENT PANEL AND GLARESHIELD					MANDATORY	COMPLIED WITH - CW
20-OCT-2015		MOS HRS/MSC - (s) AFL		04-NOV-2015 274.4 109			
CB CB097	CB 97 INSPECTION - MAIN LANDING GEAR DOOR STOP BOLT RIGGING					MANDATORY	COMPLIED WITH - CW
20-OCT-2015		MOS HRS/MSC - (s) AFL		01-NOV-2015 274.4 109			
CB CB099	CB 99 INSPECTION - MAIN ENTRANCE DOOR (MED) WIRING HARNESS ASSEMBLIES					MANDATORY	NOT APPLICABLE - NA. N/A BY AIRCRAFT EFFECTIVITY
22-OCT-2015		MOS HRS/MSC - (s) AFL		19-NOV-2015 301.4 115			
CB CB102	CB 102 MODIFICATION - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPGRADE 6.24 (ASC 037)					MANDATORY	COMPLIED WITH - CW
06-NOV-2015		MOS HRS/MSC - (s) AFL		09-AUG-2016 529.6 192			
CB CB103	CB 103 INSPECTION - ENGINE FIRE BOTTLE ELECTRICAL HARNESS ROUTING					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
10-NOV-2015		MOS HRS/MSC - AFL		15-APR-2016 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB103A	CB 103A INSPECTION - ENGINE FIRE BOTTLE ELECTRICAL HARNESS ROUTING					MANDATORY	COMPLIED WITH - CW
10-NOV-2015		MOS		04-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB104	CB 104 MODIFICATION - UNINTERRUPTIBLE POWER SUPPLY (UPS) BATTERY UPGRADE					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
12-NOV-2015		MOS		20-NOV-2015			
		HRS/MSC	-	0			
		AFL		0			
CB CB104A	CB 104A MODIFICATION - UNINTERRUPTIBLE POWER SUPPLY (UPS) BATTERY UPGRADE					MANDATORY	NOT APPLICABLE - NA
12-NOV-2015		MOS		18-DEC-2015			
		HRS/MSC	- (s)	327.3			
		AFL		128			
CB CB105	CB 105 INSPECTION - STARTER AIR VALVE (ROLLS-ROYCE NMSB BR70					MANDATORY	COMPLIED WITH - CW
17-NOV-2015		MOS		05-JUL-2017			
		HRS/MSC	- (s)	733.6			
		AFL		277			
CB CB107	CB 107 INSPECTION - INBOARD WING SKINS FOR EXPOSURE OF SHAVED FASTENERS (TRIUMPH SB MAA7-71258-08)					CANCELLED	NOT APPLICABLE - NA
		MOS		18-DEC-2015			
		HRS/MSC	-	327.3			
		AFL		128			
CB CB107A	CB 107A INSPECTION - INBOARD WING SKINS FOR EXPOSURE OF SHAVED FASTENERS (TRIUMPH SB MAA7-71258-08)					MANDATORY	NOT APPLICABLE - NA
25-NOV-2015		MOS		10-NOV-2017			
		HRS/MSC	- (s)	772.1			
		AFL		292			
CB CB108	CB 108 REPLACEMENT - ENGINE DRIVEN FUEL PUMP V-BAND CLAMP (ROLLS-ROYCE SB-BR700-73-101929)					MANDATORY	NOT APPLICABLE - NA
		MOS		18-DEC-2015			
		HRS/MSC	- (s)	327.3			
		AFL		128			
CB CB110	CB 110 INSPECTION - WIRE HARNESS TO SUPPORT BRACKET CONTACT					MANDATORY	COMPLIED WITH - CW
07-JAN-2016		MOS		08-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB111	CB 111 INSPECTION - ELECTRICAL BACKUP HYDRAULIC ACTUATOR (EBHA) DISTRIBUTION BOX POWER CABLES					MANDATORY	COMPLIED WITH - CW
20-JAN-2016		MOS		04-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB112	CB 112 INSPECTION - TRANSFORMER RECTIFIER UNIT (TRU) ELECTRICAL CONNECTOR WIRING					MANDATORY	COMPLIED WITH - CW
27-JAN-2016		MOS		08-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB114	CB 114 INSPECTION - HYDRAULIC FITTINGS AT LEFT SIDE FUSELAGE STATION (FS) 739 BULKHEAD					MANDATORY	COMPLIED WITH - CW
28-JAN-2016		MOS		07-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB115	CB 115 REPLACEMENT - MAIN ENTRANCE DOOR HANDRAIL HARDWARE					MANDATORY	COMPLIED WITH - CW. T/W: 560287 CAL DUE: 06/17
16-FEB-2016		MOS HRS/MSC - (s) AFL		09-AUG-2016 529.6 192			
CB CB116	CB 116 INSPECTION - WATER SYSTEM TANK DRAIN HOSE CONTACT ON WATER TANK SHELF SUPPORT					MANDATORY	COMPLIED WITH - CW
17-FEB-2016		MOS HRS/MSC - (s) AFL		04-AUG-2016 529.6 192			
CB CB117	CB 117 INSPECTION - WATER TANK ELECTRICAL HARNESS INSTALLATION					MANDATORY	COMPLIED WITH - CW
17-FEB-2016		MOS HRS/MSC - (s) AFL		06-AUG-2016 529.6 192			
CB CB118	CB 118 REPLACEMENT - ENGINE DRIVEN HYDRAULIC PUMP V-BAND CLAMP (ROLLS-ROYCE SB-BR700-71-101928)					MANDATORY	NOT APPLICABLE - NA
17-FEB-2016		MOS HRS/MSC - (s) AFL		08-MAR-2016 398.9 149			
CB CB119	CB 119 INSTALLATION - ADD DRAIN HOLE IN FIXED TRAILING EDGE LOWER SKIN (TRIUMPH SB MAA7-71258-10)					CANCELLED	NOT APPLICABLE - NA. NA BY EFFECTIVITY (RRR)(2/20/2016)
18-FEB-2016		MOS HRS/MSC - AFL		08-MAR-2016 398.9 149			
CB CB119A	CB 119A INSTALLATION - ADD DRAIN HOLE IN FIXED TRAILING EDGE LOWER SKIN (TRIUMPH SB MAA7-71258-10)					MANDATORY	NOT APPLICABLE - NA. NA BY EFFECTIVITY (RRR)(5/21/2016)
18-FEB-2016		MOS HRS/MSC - (s) AFL		12-JAN-2017 622.3 231			
CB CB120A	CB 120A INSPECTION - ENGINE/AUXILIARY POWER UNIT (APU) FIRE BOTTLE THERMAL RELIEF DISCHARGE PORT					MANDATORY	NOT APPLICABLE - NA. NA BY EFFECTIVITY (RRR)(3/18/2016)
18-FEB-2016		MOS HRS/MSC - (s) AFL		13-MAY-2016 446 170			
CB CB121	CB 121 INSPECTION - FLAP TORQUE SHAFTS HARDWARE					MANDATORY	COMPLIED WITH - CW. TORQUE WRENCH #560287 CAL DUE 06/17
23-FEB-2016		MOS HRS/MSC - (s) AFL		09-AUG-2016 529.6 192			
CB CB122	CB 122 INSPECTION - RAM AIR TURBINE (RAT) ELECTRICAL HARNESS MISSING OVERBRAID GROUND					MANDATORY	COMPLIED WITH - CW
24-FEB-2016		MOS HRS/MSC - (s) AFL		05-AUG-2016 529.6 192			
CB CB123	CB 123 INSPECTION - HYDRAULIC SYSTEM MANIFOLDS - WIRING INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
25-FEB-2016		MOS HRS/MSC - AFL		28-APR-2016 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB123A	CB 123A INSPECTION - HYDRAULIC SYSTEM MANIFOLDS - WIRING INSTALLATION					MANDATORY	COMPLIED WITH - CW
25-FEB-2016		MOS		05-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB124	CB 124 INSPECTION - ELECTRICAL HARNESS AT FUSELAGE STATION 321 - BELOW FLOORS					MANDATORY	COMPLIED WITH - CW
25-FEB-2016		MOS		09-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB125	CB 125 INSPECTION - BAGGAGE COMPARTMENT FORWARD ELECTRONIC EQUIPMENT RACK FOR CONTACT WITH FUSELAGE					MANDATORY	NOT APPLICABLE - NA. N/A BY EFFECTIVITY (RRR)(3/4/2016)
03-MAR-2016		MOS		08-MAR-2016			
		HRS/MSC	- (s)	398.9			
		AFL		149			
CB CB126	CB 126 REPLACEMENT - ENGINE DRIVEN HYDRAULIC PUMP DEPRESSURIZATION VALVE CONNECTOR					CANCELLED	COMPLIED WITH - CW
		MOS		11-AUG-2016			
		HRS/MSC	-	529.6			
		AFL		192			
CB CB126A	CB 126A REPLACEMENT - ENGINE DRIVEN HYDRAULIC PUMP DEPRESSURIZATION VALVE CONNECTOR					MANDATORY	COMPLIED WITH - CW
08-MAR-2016		MOS		20-JUN-2017			
		HRS/MSC	- (s)	733.6			
		AFL		277			
CB CB127	CB 127 INSPECTION - RIGHT ENGINE GENERAL SERVICES HARNESS INSTALLATION (ROLLS-ROYCE NMSB SB-BR700-71-900578)					MANDATORY	COMPLIED WITH - CW
08-MAR-2016		MOS		04-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB128	CB 128 INSPECTION - WIRE HARNESS INSTALLATION IN PILOT'S SIDE CONSOLE					MANDATORY	COMPLIED WITH - CW
16-MAR-2016		MOS		05-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB129	CB 129 INSPECTION - WIRING HARNESS CLAMP INSTALLATIONS AT FUSELAGE STATION 893					MANDATORY	COMPLIED WITH - CW
16-MAR-2016		MOS		09-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB130	CB 130 INSPECTION - WIRE ROUTING AND SEPARATION AT RIGHT SIDE FUSELAGE STATION 1047 FRAME					MANDATORY	NOT APPLICABLE - NA. NA BY EFFECTIVITY (RRR)(3/18/2016)
17-MAR-2016		MOS		13-MAY-2016			
		HRS/MSC	- (s)	446			
		AFL		170			
CB CB131	CB 131 INSPECTION - WING ANTI-ICE OVERHEAT / LOW TEMPERATURE SWITCH WIRING CONTACTING BRACKET					MANDATORY	COMPLIED WITH - CW
23-MAR-2016		MOS		09-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB132	CB 132 WIRING INSTALLATION - TAIL COMPARTMENT ACCESS DOOR WARNING SWITCH					MANDATORY	COMPLIED WITH - CW
29-MAR-2016		MOS		04-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB133	CB 133 INSPECTION - HORIZONTAL AND VERTICAL STABILIZER WIRING					MANDATORY	NOT APPLICABLE - NA. NA BY EFFECTIVITY (RRR)(11/APR/2016)
06-APR-2016		MOS		13-MAY-2016			
		HRS/MSC	- (s)	446			
		AFL		170			
CB CB134	CB 134 INSPECTION - RIGHT ELECTRONIC EQUIPMENT RACK (REER) HARNESS SOLDER SLEEVE SHIELD TERMINATORS					MANDATORY	NOT APPLICABLE - NA. NA BY EFFECTIVITY (RRR)(11/APR/2016)
06-APR-2016		MOS		13-MAY-2016			
		HRS/MSC	- (s)	446			
		AFL		170			
CB CB135	CB 135 REPLACEMENT - MAIN ENTRANCE DOOR BOTTOM FOLDING STEP LINK ASSEMBLY, P/N 60P5260000A004					MANDATORY	COMPLIED WITH - CW. INSTALLED NEW P/N 60P5260000A004 DATED 03/08/2016REF: 12.75 FOR FOLDING STEP ADJUSTMENT CMP 521216
08-APR-2016		MOS		09-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB136	CB 136 MODIFICATION - ENVIRONMENTAL CONTROL SYSTEM HARNESS INSTALLATION AT FUSELAGE STATION 805					MANDATORY	COMPLIED WITH - CW
08-APR-2016		MOS		05-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB137	CB 137 INSPECTION _ MAIN WHEEL WELL MODULAR HARNESS ASSEMBLY - CLAMP INSTALLATION					MANDATORY	COMPLIED WITH - CW
13-APR-2016		MOS		04-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB138	CB 138 INSPECTION - ACCESSORY GEARBOX RADIAL DRIVE SHAFT SEAL (ROLLS-ROYCE SB-BR700-72-900589)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
15-APR-2016		MOS		27-APR-2016			
		HRS/MSC	-	0			
		AFL		0			
CB CB138A	CB 138A INSPECTION - ACCESSORY GEARBOX RADIAL DRIVE SHAFT SEAL (ROLLS-ROYCE SB-BR700-72-900589)					MANDATORY	COMPLIED WITH - CW. ** CMP UPDATE ** COMPLIED WITH BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
15-APR-2016		MOS		14-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB139	CB 139 INSPECTION - INLET DOOR ACTUATOR FITTING					MANDATORY	COMPLIED WITH - CW
15-APR-2016		MOS		14-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB140	CB 140 INSPECTION - WIRE HARNESS FORWARD OF LEFT ELECTRONIC EQUIPMENT RACK (LEER) CONTACTING OVERHEAD CLOSE-OUT PANEL SUPPORT BRACKET					MANDATORY	NOT APPLICABLE - NA. NA BY EFFECTIVITY (RRR)(4/23/2016)
19-APR-2016		MOS		13-MAY-2016			
		HRS/MSC - (s)		446			
		AFL		170			
CB CB141	CB 141 INSPECTION - ENGINE DRIVEN PUMP (EDP) CASE DRAIN HOSE CONTACT IN LEFT AND RIGHT ENGINE PYLONS					CANCELLED	COMPLIED WITH - CW
		MOS		04-AUG-2016			
		HRS/MSC -		529.6			
		AFL		192			
CB CB141A	CB 141A INSPECTION - ENGINE DRIVEN PUMP (EDP) CASE DRAIN HOSE CONTACT IN LEFT AND RIGHT ENGINE PYLONS					MANDATORY	COMPLIED WITH - CW
20-APR-2016		MOS		15-DEC-2016			
		HRS/MSC - (s)		622.3			
		AFL		231			
CB CB142	CB 142 REPLACEMENT - PRESSURE FUELING SHUT-OFF VALVES, P/N L94-51-602, WITH P/N L94-51-603					CANCELLED	COMPLIED WITH - CW
		MOS		21-JUN-2017			
02-MAY-2016		HRS/MSC -		733.6			
		AFL		277			
CB CB142A	CB 142A REPLACEMENT - PRESSURE FUELING SHUT-OFF VALVES, P/N L94-51-602, WITH P/N L94-51-603					CANCELLED	COMPLIED WITH - CW
17-OCT-2018		MOS		18-OCT-2018			
		HRS/MSC - (s)		947.9			
		AFL		384			
CB CB143	CB 143 MODIFICATION - LANDING GEAR CONTROL UNIT (LGCU) MOD D UPDATE (ASC 079)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
06-MAY-2016		MOS		10-MAY-2016			
		HRS/MSC -		0			
		AFL		0			
CB CB143A	CB 143A MODIFICATION - LANDING GEAR CONTROL UNIT (LGCU) MOD D UPDATE (ASC 079)					MANDATORY	COMPLIED WITH - CW
		MOS		12-AUG-2016			
06-MAY-2016		HRS/MSC - (s)		529.6			
		AFL		192			
CB CB144	CB 144 INSPECTION - COCKPIT WINDSHIELD AND SIDE WINDOW FRAME CORROSION					MANDATORY	COMPLIED WITH - CW
		MOS		11-AUG-2016			
19-MAY-2016		HRS/MSC - (s)		529.6			
		AFL		192			
CB CB145	CB 145 INSPECTION - ELECTRICAL HARNESS SUPPORT BRACKET AT FUSELAGE STATION 805					MANDATORY	COMPLIED WITH - CW
		MOS		11-JUL-2018			
01-JUN-2016		HRS/MSC - (s)		893.9			
		AFL		348			
CB CB146	CB 146 INSPECTION - AUXILIARY POWER CABLE BELOW FLOORS, FUSELAGE STATIONS (FS) 756 - 868					MANDATORY	NOT APPLICABLE - NA
		MOS		02-JUN-2016			
01-JUN-2016		HRS/MSC - (s)		457.7			
		AFL		174			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB147	CB 147 INSPECTION - HIGH FREQUENCY ANTENNA ADAPTER HARDWARE					MANDATORY	COMPLIED WITH - CW
23-JUN-2016		MOS		18-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB148	CB 148 REPLACEMENT - HORIZONTAL STABILIZER TRIM ACTUATOR					MANDATORY	NOT APPLICABLE - NA
24-JUN-2016		MOS		22-OCT-2016			
		HRS/MSC	- (s)	589.4			
		AFL		213			
CB CB149	CB 149 INSPECTION - INSTALLATION OF FASTENERS IN AIR DATA PROBE MOUNTING STRUCTURE - LEFT AND RIGHT FUSELAGE STATIONS (FS) 169 AND 184					MANDATORY	NOT APPLICABLE - NA
28-JUN-2016		MOS		22-OCT-2016			
		HRS/MSC	- (s)	589.4			
		AFL		213			
CB CB150	CB 150 INSPECTION - 60 HERTZ OUTLETS - 15 AMPERE, P/N 106360-2					MANDATORY	COMPLIED WITH - CW
28-JUN-2016		MOS		05-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB151	CB 151 INSTALLATION - FLAP TRACK RUB BLOCKS					MANDATORY	NOT APPLICABLE - NA
29-JUN-2016		MOS		22-OCT-2016			
		HRS/MSC	- (s)	589.4			
		AFL		213			
CB CB152	CB 152 - INSPECTION - HORIZONTAL STABILIZER INBOARD LEADING EDGE					MANDATORY	COMPLIED WITH - CW
21-JUL-2016		MOS		09-AUG-2016			
		HRS/MSC	- (s)	529.6			
		AFL		192			
CB CB153	CB 153 INSPECTION - HYDRAULIC SYSTEM RESERVOIR BLEED VALVES					MANDATORY	NOT APPLICABLE - NA
28-JUL-2016		MOS		22-OCT-2016			
		HRS/MSC	- (s)	589.4			
		AFL		213			
CB CB154	CB 154 INSPECTION - NOSE LANDING GEAR STEERING PRESSURE HOSE					MANDATORY	NOT APPLICABLE - NA
28-JUL-2016		MOS		22-OCT-2016			
		HRS/MSC	- (s)	589.4			
		AFL		213			
CB CB155	CB 155 MODIFICATION - MAIN LANDING GEAR AND BRAKE ASSEMBLY (ASC 084)					CANCELLED	COMPLIED WITH - CW
29-JUL-2016		MOS		10-AUG-2016			
		HRS/MSC	-	529.6			
		AFL		192			
CB CB155A	CB 155A MODIFICATION - MAIN LANDING GEAR AND BRAKE ASSEMBLY (ASC 084A)					CANCELLED	COMPLIED WITH - CW
		MOS		23-AUG-2016			
		HRS/MSC	-	529.6			
		AFL		192			
CB CB155B	CB 155B MODIFICATION - MAIN LANDING GEAR AND BRAKE ASSEMBLY (ASC 084A)					MANDATORY	NOT APPLICABLE - NA
		MOS		10-NOV-2017			
		HRS/MSC	- (s)	772.1			
		AFL		292			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB156	CB 156 INSPECTION - WIRING DISCONNECT FOR LIGHTNING SENSOR SYSTEM NOT BURNISHED FOR ELECTRICAL BONDING					MANDATORY	NOT APPLICABLE - NA
08-AUG-2016		MOS HRS/MSC - (s) AFL		22-OCT-2016 589.4 213			
CB CB157	CB 157 INSTALLATION - AUXILIARY POWER UNIT (APU) GENERATOR POWER FEEDER CABLES (ASC 072)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
11-AUG-2016		MOS HRS/MSC - AFL		16-MAR-2017 0 0			
CB CB157A	CB 157A INSTALLATION - AUXILIARY POWER UNIT (APU) GENERATOR POWER FEEDER CABLES (ASC 072)					MANDATORY	COMPLIED WITH - CW
16-MAR-2017		MOS HRS/MSC - (s) AFL		20-JUL-2018 893.9 348			
CB CB158	CB 158 MODIFICATION - TIRE PRESSURE MONITORING UNIT (TPMS) SOFTWARE UPGRADE (ASC 073)					MANDATORY	COMPLIED WITH - CW
18-AUG-2016		MOS HRS/MSC - (s) AFL		08-JUL-2017 733.6 277			
CB CB159	CB 159 INSPECTION - LEFT HYDRAULIC SYSTEM RETURN LINE AT RELIEF / UNLOADING VALVE					MANDATORY	NOT APPLICABLE - NA
26-AUG-2016		MOS HRS/MSC - (s) AFL		22-OCT-2016 589.4 213			
CB CB160	CB 160 MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) - K7.1.3 SOFTWARE UPGRADE (ASC 016)					CANCELLED	COMPLIED WITH - CW
		MOS HRS/MSC - AFL		20-JUN-2017 733.6 277			
CB CB160A	CB 160A MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) - K7.1.3 SOFTWARE UPGRADE (ASC 016)					MANDATORY	NOT APPLICABLE - NA
15-SEP-2016		MOS HRS/MSC - (s) AFL		10-NOV-2017 772.1 292			
CB CB161	CB 161 MODIFICATION - REPLACEMENT OF FUEL LOW PRESSURE SWITCH (ROLLS-ROYCE SB-BR700-73-101965)					MANDATORY	COMPLIED WITH - CW
		MOS HRS/MSC - (s) AFL		20-JUN-2017 733.6 277			
CB CB162	CB 162 MODIFICATION - REVISED FUEL SYSTEM (ROLLS-ROYCE SB-BR700-73-101957)					CANCELLED	COMPLIED WITH - CW
		MOS HRS/MSC - AFL		20-JUN-2017 733.6 277			
CB CB162A	CB 162A MODIFICATION - REVISED FUEL SYSTEM (ROLLS-ROYCE SB-BR700-73-101957)					MANDATORY	COMPLIED WITH - CW. REFERENCE GAC SAV SC467519.28.12 08.23.16 FOR COMPLIANCE OF CB 162
15-SEP-2016		MOS HRS/MSC - (s) AFL		20-JUL-2018 893.9 348			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB163	CB 163 RE-TORQUE - FLAP LEADING EDGE - TRACK B AND C BRIDGE FITTINGS (TRIUMPH SB MAA7-71258-02)					MANDATORY	NOT APPLICABLE - NA
29-SEP-2016		MOS		22-OCT-2016			
		HRS/MSC	- (s)	589.4			
		AFL		213			
CB CB164	CB 164 INSPECTION - BRAKE HYDRAULIC LINES AT LEFT FUSELAGE STATION (FS) 761					MANDATORY	COMPLIED WITH - CW
04-OCT-2016		MOS		10-JUL-2017			
		HRS/MSC	- (s)	733.6			
		AFL		277			
CB CB165	CB 165 INSPECTION - FLAP TRACK D FITTING FASTENERS					MANDATORY	COMPLIED WITH - CW
18-OCT-2016		MOS		26-JUN-2017			
		HRS/MSC	- (s)	733.6			
		AFL		277			
CB CB166	CB 166 MODIFICATION - SECONDARY POWER DISTRIBUTION SYSTEM (SPDS) SOFTWARE UPDATE (ASC 051)					CANCELLED	COMPLIED WITH - CW
01-NOV-2016		MOS		28-JUN-2017			
		HRS/MSC	-	733.6			
		AFL		277			
CB CB166A	CB 166A MODIFICATION - SECONDARY POWER DISTRIBUTION SYSTEM (SPDS) SOFTWARE UPDATE (ASC 051)					MANDATORY	COMPLIED WITH - CW. UPDATE ONLY JUN2017 REFERENCE W/O SC3900.5.17-
		MOS		03-JUL-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB167	CB 167 INSPECTION - BAGGAGE DOOR WARNING SWITCHES					MANDATORY	COMPLIED WITH - CW
02-NOV-2016		MOS		21-JUN-2017			
		HRS/MSC	- (s)	733.6			
		AFL		277			
CB CB168	CB 168 INSPECTION - MAIN ENTRANCE DOOR HANDRAIL DRIVE FITTINGS					MANDATORY	COMPLIED WITH - CW
17-NOV-2016		MOS		06-DEC-2016			
		HRS/MSC	- (s)	614.4			
		AFL		226			
CB CB169	CB 169 MODIFICATION - FORWARD LEFT SIDE LAVATORY WIRING INSTALLATION					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
22-NOV-2016		MOS		15-JUN-2018			
		HRS/MSC	-	0			
		AFL		0			
CB CB169A	CB 169A MODIFICATION - FORWARD LEFT SIDE LAVATORY WIRING INSTALLATION					MANDATORY	COMPLIED WITH - CW
		MOS		19-JUL-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB170	CB 170 MODIFICATION - REMOVAL OF WATER STERILIZER FILTER END CAP SET SCREW (IWG-A6 VENDOR SERVICE BULLETIN)					MANDATORY	COMPLIED WITH - CW. CUSTOMER REQUEST ALIGNMENT WITH 381002 AND 381003. LETTER ON FILE.
		MOS		10-MAR-2017			
		HRS/MSC	- (s)	661			
		AFL		255			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB171	CB 171 ELECTRICAL POWER (ATA 24), INSPECTION - MAIN BATTERY GROUND PADS					CANCELLED	COMPLIED WITH - CW
12-DEC-2016		MOS		15-DEC-2016			
		HRS/MSC -		622.3			
		AFL		231			
CB CB171A	CB 171A INSPECTION - MAIN BATTERY GROUND PADS					MANDATORY	NOT APPLICABLE - NA
12-DEC-2016		MOS		10-NOV-2017			
		HRS/MSC - (s)		772.1			
		AFL		292			
CB CB172	CB 172 REPLACEMENT - MAIN ENTRY DOOR - BOTTOM FOLDING STEP STOP BOLTS (ASC 089)					MANDATORY	COMPLIED WITH - CW
20-DEC-2016		MOS		09-FEB-2017			
		HRS/MSC - (s)		642			
		AFL		246			
CB CB173	CB 173 INSPECTION - AILERON CONTROL OVERRIDE PUSHROD ROD END					MANDATORY	COMPLIED WITH - CW
25-JAN-2017		MOS		28-JUN-2017			
		HRS/MSC - (s)		733.6			
		AFL		277			
CB CB174	CB 174 INSPECTION - HORIZONTAL STABILIZER TRIM ACTUATOR HARNESS					MANDATORY	COMPLIED WITH - CW
14-FEB-2017		MOS		06-JUL-2017			
		HRS/MSC - (s)		733.6			
		AFL		277			
CB CB175	CB 175 REPLACEMENT - RAM AIR TURBINE (RAT) CONTROL HANDLE LOCKOUT PIN					MANDATORY	COMPLIED WITH - CW
23-FEB-2017		MOS		21-JUN-2017			
		HRS/MSC - (s)		733.6			
		AFL		277			
CB CB176	CB 176 REPLACEMENT - MAIN ENTRANCE DOOR HANDRAIL DRIVE FITTINGS					MANDATORY	COMPLIED WITH - CW. TW: 553005 DUE: 10/17
27-FEB-2017		MOS		24-AUG-2017			
		HRS/MSC - (s)		740.5			
		AFL		280			
CB CB177	CB 177 INSPECTION - MAIN LANDING GEAR SIDE BRACE ACTUATOR BAND CLAMPS					CANCELLED	COMPLIED WITH - CW
01-MAR-2017		MOS		20-JUN-2017			
		HRS/MSC -		733.6			
		AFL		277			
CB CB177A	CB 177A INSPECTION - MAIN LANDING GEAR SIDE BRACE ACTUATOR CLAMP BANDS					CANCELLED	COMPLIED WITH - COMPLIED WITH CB 239 AND ASC117
06-FEB-2019		MOS		11-NOV-2019			
		HRS/MSC -		1189.3			
		AFL		486			
CB CB178	CB 178 INSPECTION - FUEL CELL OVER-WING WIRING HARNESS AT FUSELAGE STATION 536					MANDATORY	COMPLIED WITH - CW
01-MAR-2017		MOS		21-JUN-2017			
		HRS/MSC - (s)		733.6			
		AFL		277			
CB CB179	CB 179 INSPECTION - TAIL COMPARTMENT GROUND PADS					CANCELLED	COMPLIED WITH - CW
15-MAR-2017		MOS		20-JUN-2017			
		HRS/MSC -		733.6			
		AFL		277			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB179A	CB 179A INSPECTION - TAIL COMPARTMENT GROUND PADS					CANCELLED	NOT APPLICABLE - NA
		MOS		24-MAY-2018			
		HRS/MSC -		856.1			
		AFL		334			
CB CB179B	CB 179B INSPECTION - TAIL COMPARTMENT GROUND PADS						NOT APPLICABLE - NA
		MOS		18-JUL-2019			
11-JUL-2019		HRS/MSC - (s)		1115.4			
		AFL		450			
CB CB180	CB 180 INSPECTION - AFT MID LOWER DRAIN VALVES AT FUSELAGE STATION 756					MANDATORY	COMPLIED WITH - CW
		MOS		20-JUN-2017			
04-APR-2017		HRS/MSC - (s)		733.6			
		AFL		277			
CB CB181	CB 181 VESTIBULE POCKET DOOR SWING RESTRICTION					MANDATORY	NOT APPLICABLE - NA
		MOS		10-NOV-2017			
11-APR-2017		HRS/MSC - (s)		772.1			
		AFL		292			
CB CB182	CB 182 REPLACEMENT - MAIN ENTRANCE DOOR ELECTRICAL CONNECTORS					MANDATORY	COMPLIED WITH - CW
		MOS		06-SEP-2017			
08-MAY-2017		HRS/MSC - (s)		740.5			
		AFL		280			
CB CB183	CB 183 INSPECTION - MAIN ENTRANCE DOOR FORWARD AND AFT LOCK OUT MECHANICAL STOP BRACKET ASSEMBLIES SEALING					MANDATORY	COMPLIED WITH - CW
		MOS		18-AUG-2017			
08-MAY-2017		HRS/MSC - (s)		740.5			
		AFL		280			
CB CB184	CB 184 INSPECTION - MAIN ENTRANCE DOOR P-CLAMP ORIENTATION					MANDATORY	COMPLIED WITH - CW
		MOS		06-SEP-2017			
08-MAY-2017		HRS/MSC - (s)		740.5			
		AFL		280			
CB CB185	CB 185 INSPECTION - MAIN LANDING GEAR SPONSON BEAMS					MANDATORY	COMPLIED WITH - CW
		MOS		17-JUL-2018			
25-MAY-2017		HRS/MSC - (s)		893.9			
		AFL		348			
CB CB186 PART I	CB 186 (PART 1) REPLACEMENT - FLAP ELECTRONIC CONTROL UNIT					MANDATORY	COMPLIED WITH - CW
		MOS		30-JUN-2017			
06-JUN-2017		HRS/MSC - (s)		733.6			
		AFL		277			
CB CB186 PART II	CB 186 (PART 2) REPLACEMENT - FLAP ELECTRONIC CONTROL UNIT					MANDATORY	NOT APPLICABLE - NA
		MOS		30-JUN-2017			
06-JUN-2017		HRS/MSC - (s)		733.6			
		AFL		277			
CB CB187	CB 187 INSPECTION - NOSE LANDING GEAR UPPER TORQUE ARM PIN					CANCELLED	NOT APPLICABLE - NA
		MOS		10-OCT-2018			
22-JUN-2017		HRS/MSC -		947.9			
		AFL		384			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB187A	CB 187A INSPECTION - NOSE LANDING GEAR UPPER TORQUE ARM PIN						
15-MAY-2019		MOS HRS/MSC - AFL		(EFF)	31-DEC-2020 M		
CB CB188	CB 188 INSPECTION - FUEL LINE COUPLINGS IN PYLON					MANDATORY	COMPLIED WITH - CW
22-JUN-2017		MOS HRS/MSC - (s) AFL		12-JUL-2017 733.6 277			
CB CB189	CB 189 INSPECTION - MAIN LANDING GEAR FAIRING DOOR HINGES					CANCELLED	COMPLIED WITH - CW. PERFORMED INSPECTION NO CONTACT NOTED FOR AREAS OF INSPECTION IN CB 189 DATED 6/27/2017.
27-JUN-2017		MOS HRS/MSC - AFL		30-JUN-2018 893.9 348			
CB CB189A	CB 189A INSPECTION - MAIN LANDING GEAR FAIRING DOOR HINGES					MANDATORY	NOT APPLICABLE - NA
01-NOV-2018		MOS HRS/MSC - (s) AFL		14-NOV-2018 978.5 395			
CB CB190	CB 190 INSPECTION - BLEED AIR MANIFOLD GAMAH COUPLERS					MANDATORY	COMPLIED WITH - CW
27-JUN-2017		MOS HRS/MSC - (s) AFL		30-JUN-2018 893.9 348			
CB CB191	CB 191 AUXILIARY POWER UNIT (APU) FILTER BYPASS INDICATOR VALVE (HONEYWELL SB RE220-49-8218)					CANCELLED	NOT APPLICABLE - NA
29-JUN-2017		MOS HRS/MSC - AFL		10-NOV-2017 772.1 292			
CB CB191A	CB 191A AUXILIARY POWER UNIT (APU) FILTER BYPASS INDICATOR VALVE (HONEYWELL SB RE220-49-8218)					MANDATORY	NOT APPLICABLE - NA
29-JUN-2017		MOS HRS/MSC - (s) AFL		22-JAN-2018 809.2 310			
CB CB192	CB 192 INSPECTION - ELECTRICAL WIRING SECURED TO HOT AIR DUCTS BELOW BAGGAGE FLOOR					MANDATORY	COMPLIED WITH - CW
03-AUG-2017		MOS HRS/MSC - (s) AFL		26-JUN-2018 893.9 348			
CB CB193	CB 193 INSPECTION - NOSE LANDING GEAR DOOR ACTUATOR TORQUE TUBES - AFT BEARINGS					MANDATORY	COMPLIED WITH - CW
15-AUG-2017		MOS HRS/MSC - (s) AFL		30-JUN-2018 893.9 348			
CB CB194	CB 194 INSPECTION - HYDRAULIC RETURN TUBE AT FUSELAGE STATION (FS) 1080 LEFT					MANDATORY	COMPLIED WITH - CW
15-AUG-2017		MOS HRS/MSC - (s) AFL		30-JUN-2018 893.9 348			
CB CB195	CB 195 REPLACEMENT - MAIN ENTRANCE DOOR FORWARD HINGE WATER CLOSEOUT					MANDATORY	COMPLIED WITH - CW
18-AUG-2017		MOS HRS/MSC - (s) AFL		23-AUG-2017 740.5 280			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB196	CB 196 MODIFICATION - MAIN ENTRANCE DOOR BOTTOM FOLDING STEP MECHANISM IMPROVEMENT (ASC 099)					MANDATORY	COMPLIED WITH - CW
25-AUG-2017		MOS		06-SEP-2017			
		HRS/MSC	- (s)	740.5			
		AFL		280			
CB CB197	CB 197 MODIFICATION - FLIGHT CONTROL COMPUTER (FCC) SOFTWARE UPGRADE 7.1 (ASC 093)					MANDATORY	COMPLIED WITH - CW. NO DEFECTS NOTED AT THIS TIME.
31-AUG-2017		MOS		19-JUL-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB198	CB 198 INSPECTION - SPOILER ELECTRICAL BACKUP HYDRAULIC ACTUATOR (EBHA) MANIFOLD (PARKER SB 479500-27-001)					CANCELLED	COMPLIED WITH - CW
28-SEP-2017		MOS		16-JUL-2018			
		HRS/MSC	-	893.9			
		AFL		348			
CB CB198A	CB 198A INSPECTION - SPOILER ELECTRICAL BACKUP HYDRAULIC ACTUATOR (EBHA) MANIFOLD (PARKER SB 479500-27-001)					CANCELLED	NOT APPLICABLE - CB 198A SUPERSEDED BY CB 225
15-OCT-2018		MOS		11-NOV-2019			
		HRS/MSC	- (s)	1189.3			
		AFL		486			
CB CB199	CB 199 MODIFICATION - PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) MOTOR CONTROL ELECTRONICS (MCE) SOFTWARE UPGRADE (ASC 092)					MANDATORY	COMPLIED WITH - CW
28-SEP-2017		MOS		16-JUL-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB200	CB 200 MODIFICATION - PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) REMOTE ELECTRONICS UNIT (REU) CONNECTOR INSTALLATION (ASC 097)					MANDATORY	COMPLIED WITH - CW
28-SEP-2017		MOS		16-JUL-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB201	CB 201 INSPECTION - PRIMARY FLIGHT CONTROL ACTUATION SYSTEM (PFCAS) REMOTE ELECTRONICS UNIT (REU) SOFTWARE UPGRADE (ASC 069)					MANDATORY	COMPLIED WITH - CW
28-SEP-2017		MOS		16-JUL-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB202	CB 202 INSPECTION - WIRING INSTALLATION AT OUTBOARD FLIGHT SPOILER ATTACH FITTINGS					MANDATORY	COMPLIED WITH - CW
18-OCT-2017		MOS		05-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB203	CB 203 INSPECTION - WIRE ROUTING ON REER FORWARD BULKHEAD					MANDATORY	COMPLIED WITH - CW
12-DEC-2017		MOS		23-JUN-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB204	CB 204 MODIFICATION - HORIZONTAL STABILIZER CONTROL UNIT (HSCU) MOD 4 (ASC 098)					CANCELLED	COMPLIED WITH - CW. REF CB 204. REF 11.1, 11.3, 11.4.
25-JAN-2018		MOS		26-JUN-2018			
		HRS/MSC	-	893.9			
		AFL		348			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB204A	CB 204A MODIFICATION - HORIZONTAL STABILIZER CONTROL UNIT (HSCU) HARDWARE MOD 4 VERIFICATION AND SOFTWARE UPDATE	MOS		20-JUL-2018		CANCELLED	COMPLIED WITH - CW
		HRS/MSC	-	893.9			
		AFL		348			
CB CB204B	CB 204B MODIFICATION - HORIZONTAL STABILIZER CONTROL UNIT (HSCU) HARDWARE MOD 4 VERIFICATION AND SOFTWARE UPDATE (ASC 098)	MOS		14-NOV-2018		MANDATORY	NOT APPLICABLE - NA
06-NOV-2018		HRS/MSC	-(s)	978.5			
		AFL		395			
CB CB205	CB 205 REPLACEMENT - CABIN FLOORBOARD 7D	MOS	96	(EFF)	30-NOV-2022 M	MANDATORY	
02-MAR-2018		HRS/MSC					
		AFL					
CB CB206	CB 206 LIFE RAFT GAS CYLINDER REPLACEMENT AT OVERHAUL (UTAS SB 25-470)	MOS		18-MAY-2018		CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. ALIGNED WITH LIFE RAFT RESTORATION PER SCOTT BLACKLAW
06-MAR-2018		HRS/MSC	-	0			
		AFL		0			
CB CB206A	CB 206A LIFE RAFT GAS CYLINDER REPLACEMENT AT OVERHAUL (UTAS SB 25-470)	MOS	60	(EFF)	20-JUL-2020	CANCELLED	
		HRS/MSC					
		AFL					
CB CB206B	CB 206B LIFE RAFT GAS CYLINDER REPLACEMENT AT OVERHAUL (UTAS SB 25-470 / SB 25-476)	MOS	60	(EFF)	06-MAR-2023	MANDATORY	
05-DEC-2019		HRS/MSC					
		AFL					
CB CB207	CB 207 INSPECTION - WIRE ROUTING AFT EQUIPMENT BAY AND WHEEL WELL	MOS		10-JUN-2019		MANDATORY	COMPLIED WITH - CW
		HRS/MSC	-(s)	1103.7			
		AFL		440			
CB CB208	CB 208 INSPECTION - MAIN LANDING GEAR AXLE FITTING ASSEMBLY (UTC AEROSPACE SB C1A5400-32-009)	MOS		11-JUL-2018		CANCELLED	COMPLIED WITH - CW
		HRS/MSC	-	893.9			
		AFL		348			
CB CB208A	CB 208A INSPECTION - MAIN LANDING GEAR AXLE FITTING ASSEMBLY (UTC AEROSPACE SB C1A5400-32-009)	MOS		22-MAR-2019		MANDATORY	NOT APPLICABLE - NA. THIS CUSTOMER BULLETIN REVISION REPLACES CB 208. AIRCRAFT OPERATORS WHO HAVE PREVIOUSLY COMPLIED WITH CB 208 ARE IN COMPLIANCE WITH THIS REVISION AND SHOULD RETURN THE SERVICE REPLY CARD MARKED "PREVIOUSLY COMPLIED WITH."
13-FEB-2019		HRS/MSC	-(s)	1034.5			
		AFL		418			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB208B	CB 208B INSPECTION - MAIN LANDING GEAR AXLE FITTING ASSEMBLY (UTC AEROSPACE SB C1A5400-32-009)					MANDATORY	
08-MAY-2020		MOS	60		18-APR-2023		
		HRS/MSC					
		AFL					
CB CB209	CB 209 INSPECTION - OVERCOAT ON FUEL DISTRIBUTION BRACKET FASTENERS (TRIUMPH SB MAA7-71258-14)					MANDATORY	NOT APPLICABLE - NA
		MOS		24-MAY-2018			
		HRS/MSC	- (s)	856.1			
		AFL		334			
CB CB210	CB 210 INSPECTION - OVERCOAT ON WING SPLICE STRINGER FASTENERS					MANDATORY	NOT APPLICABLE - NA
		MOS		24-MAY-2018			
		HRS/MSC	- (s)	856.1			
		AFL		334			
CB CB211	CB 211 INSPECTION - FLIGHT CONTROLS WIRING HARNESS INSTALLATION UNDER ELECTRICAL BACKUP HYDRAULIC ACTUATOR (EBHA) BATTERY					MANDATORY	COMPLIED WITH - CW
		MOS		07-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB212	CB 212 IACOBUECCI COFFEE MAKER IMPROVED GROUND PATH					MANDATORY	NOT APPLICABLE - NA
		MOS		24-MAY-2018			
		HRS/MSC	- (s)	856.1			
		AFL		334			
CB CB213 PART I	CB 213 REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT (PART 1)					CANCELLED	COMPLIED WITH - CW
		MOS		30-JUN-2018			
		HRS/MSC	-	893.9			
		AFL		348			
CB CB213A PART I	CB 213A REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT (PART 1)					CANCELLED	NOT APPLICABLE - NA. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
07-SEP-2018		MOS		14-NOV-2018			
		HRS/MSC	-	978.5			
		AFL		395			
CB CB213A PART II	CB 213A REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT (PART 2)					CANCELLED	NOT APPLICABLE - NA. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
07-SEP-2018		MOS		14-NOV-2018			
		HRS/MSC	-	978.5			
		AFL		395			
CB CB213B PART I	CB 213B REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT (PART 1)					MANDATORY	COMPLIED WITH - CW
07-SEP-2018		MOS		14-NOV-2018			
		HRS/MSC	- (s)	978.5			
		AFL		395			
CB CB213B PART II	CB 213B REPLACEMENT - FLAP HYDRAULIC POWER DRIVE UNIT (PART 2)					MANDATORY	NOT APPLICABLE - NA
07-SEP-2018		MOS		14-NOV-2018			
		HRS/MSC	- (s)	978.5			
		AFL		395			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB214	CB 214 ELECTRONIC CONTROL UNIT (ECU) SOFTWARE FOR VIP SEATS (RCO SB RCO2017-10-12-1)	MOS		18-JUL-2018		MANDATORY	NOT APPLICABLE - NA
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB215	CB 215 MODIFICATION - FORWARD LEFT-SIDE LAVATORY CABINET WIRING INSTALLATION (GPM412004707-301 MONUMENT)	MOS		29-JUN-2018		MANDATORY	NOT APPLICABLE - NA. NOT APPLICABLE BY AIRCRAFT S/N
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB216	CB 216 FIXED COWL - CABIN BLEED AIR SEAL BOOT						NOT APPLICABLE - NA. N/A BY S/N
	27-JUN-2018	MOS		20-JUL-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB217	CB 217 INSPECTION - CONTACTS ON FORWARD LEFT ELECTRONIC EQUIPMENT RACK (LEER) CONNECTOR						COMPLIED WITH - CW
	29-JUN-2018	MOS		11-JUL-2018			
		HRS/MSC	- (s)	893.9			
		AFL		348			
CB CB218	CB 218 REPLACEMENT - AUXILIARY POWER UNIT STARTER GROUND LEAD					MANDATORY	NOT APPLICABLE - NA
	24-JUL-2018	MOS		14-NOV-2018			
		HRS/MSC	- (s)	978.5			
		AFL		395			
CB CB219	CB 219 HYDRAULIC SYSTEM UNION AT INBOARD FIXED TRAILING EDGE OF LEFT AND RIGHT WINGS (TRIUMPH SB MAA7-71258-20_TGI)						NOT APPLICABLE - NA
	25-JUL-2018	MOS		14-NOV-2018			
		HRS/MSC	- (s)	978.5			
		AFL		395			
CB CB220	CB 220 MODIFICATION - ENGINE FIRE BOTTLE HARNESS (ASC 111)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
	31-JUL-2018	MOS		22-MAR-2019			
		HRS/MSC	-	0			
		AFL		0			
CB CB220A	CB 220A MODIFICATION - ENGINE FIRE BOTTLE HARNESS (ASC 111)						COMPLIED WITH - CW
	21-MAR-2019	MOS		18-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB221	CB 221 MODIFICATION - AUXILIARY HYDRAULIC PUMP GROUNDING INSTALLATION (ASC 103)					MANDATORY	COMPLIED WITH - CW
	07-AUG-2018	MOS		11-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB222	CB 222 INSPECTION - OXYGEN SERVICE LINE FITTING AT FUSELAGE STATION (FS) 435						NOT APPLICABLE - NA
	08-AUG-2018	MOS		14-NOV-2018			
		HRS/MSC	- (s)	978.5			
		AFL		395			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB223	CB 223 INSPECTION / MODIFICATION - FUSELAGE SKIN AND APU EXHAUST FAIRING (ASC 113)						COMPLIED WITH - CW
24-AUG-2018		MOS		11-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB224	CB 224 MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) K8.0.2 SOFTWARE UPGRADE (ASC 088)						COMPLIED WITH - CW
10-SEP-2018		MOS		13-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB225	CB 225 RETROFIT OF ELECTRICAL BACKUP (EB) HYDRAULIC MANIFOLD					MANDATORY	COMPLIED WITH - CW
15-OCT-2018		MOS		12-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB226	CB 226 INSPECTION - MOTOR CONTROL ELECTRONICS (MCE) J3 CONNECTOR (PARKER SB 469300-27-002 AND SB 469400-27-002)					MANDATORY	COMPLIED WITH - CW
15-OCT-2018		MOS		10-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB227	CB 227 INSPECTION - AILERON MOTOR CONTROL ELECTRONICS (MCE) AND OUTBOARD SPOILER J-BOX CONNECTORS					MANDATORY	COMPLIED WITH - CW
15-OCT-2018		MOS		11-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB228	CB 228 AIR DATA PROBE HEAT FAULT MONITORING - LOADABLE DIAGNOSTIC INFORMATION (LDI) UPDATE					MANDATORY	COMPLIED WITH - CW
19-OCT-2018		MOS		10-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB229	CB 229 INSPECTION - ENGINE FUEL SUPPLY TUBE					MANDATORY	NOT APPLICABLE - NA
31-OCT-2018		MOS		14-NOV-2018			
		HRS/MSC	- (s)	978.5			
		AFL		395			
CB CB231	CB 231 MODIFICATION FCC SOFTWARE V8.2 UPDATE					MANDATORY	COMPLIED WITH - CW
15-NOV-2018		MOS		17-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			
CB CB232	CB 232 INSPECTION - RIGHT ENGINE FIRE BOTTLE ELECTRICAL HARNESS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
04-DEC-2018		MOS		05-DEC-2018			
		HRS/MSC	-	0			
		AFL		0			
CB CB232A	CB 232 REV A INSPECTION - RIGHT ENGINE FIRE BOTTLE ELECTRICAL HARNESS					MANDATORY	COMPLIED WITH - CW
05-DEC-2018		MOS		06-JUN-2019			
		HRS/MSC	- (s)	1103.7			
		AFL		440			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB233	CB 233 REPLACEMENT - BR725 ENGINE STARTER AIR VALVE (ROLLS ROYCE NMSB SB-BR700-80-900634)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
11-DEC-2018		MOS		11-JUN-2019			
		HRS/MSC -		0			
		AFL		0			
CB CB233A	CB 233A REPLACEMENT - BR725 ENGINE STARTER AIR VALVE (ROLLS ROYCE NMSB SB-BR700-80-900634)					MANDATORY	NOT APPLICABLE - NA
		MOS		18-JUL-2019			
		HRS/MSC - (s)		1115.4			
		AFL		450			
CB CB234	CB 234 REPLACEMENT - MAIN ENTRANCE DOOR MANUAL OPEN HANDLE SHAFT ADAPTER					MANDATORY	NOT APPLICABLE - NA
03-JAN-2019		MOS		22-MAR-2019			
		HRS/MSC - (s)		1034.5			
		AFL		418			
CB CB235	CB 235 INSPECTION - RADOME LATCH INSTALLATION					MANDATORY	NOT APPLICABLE - NA
16-JAN-2019		MOS		22-MAR-2019			
		HRS/MSC - (s)		1034.5			
		AFL		418			
CB CB236	CB 236 INSPECTION - FORWARD UPPER ENGINE MOUNT FITTING CONTACT WITH PYLON SEAL RETAINER (ASC 124)					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
21-JAN-2019		MOS		01-FEB-2019			
		HRS/MSC -		0			
		AFL		0			
CB CB236A	CB 236A INSPECTION - FORWARD UPPER ENGINE MOUNT FITTING CONTACT WITH PYLON SEAL RETAINER (ASC 124)					MANDATORY	
01-FEB-2019		MOS	48	(EFF)	30-JUN-2022		
		HRS/MSC					
		AFL					
CB CB237	CB 237 INSPECTION - DISPLAY UNIT TRAY ASSEMBLY, GROUND STRAP PLATING FLAKING					MANDATORY	NOT APPLICABLE - NA
31-JAN-2019		MOS		22-MAR-2019			
		HRS/MSC - (s)		1034.5			
		AFL		418			
CB CB238	CB 238 INSPECTION - FLIGHT CONTROL REMOTE ELECTRONICS UNIT (REU) INSTALLATION					MANDATORY	NOT APPLICABLE - NA
01-FEB-2019		MOS		22-MAR-2019			
		HRS/MSC - (s)		1034.5			
		AFL		418			
CB CB239	CB 239 MODIFICATION - MAIN LANDING GEAR SIDE BRACE ACTUATOR CONFIGURATION AND CLEARANCE (ASC 117)					MANDATORY	COMPLIED WITH - CW
06-FEB-2019		MOS		10-JUN-2019			
		HRS/MSC - (s)		1103.7			
		AFL		440			
CB CB240	CB 240 MODIFICATION - BATTERY CHARGER, P/N 100-1311-01, UPGRADE TO MOD 11						COMPLIED WITH - CW
13-FEB-2019		MOS		17-JUN-2019			
		HRS/MSC - (s)		1103.7			
		AFL		440			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB241	CB 241 REPLACEMENT - MAIN LANDING GEAR SHOCK STRUTS					MANDATORY	
13-FEB-2019		MOS HRS/MSC AFL	48	(EFF)	31-JUL-2022		
CB CB242	CB 242 MODIFICATION - BATTERY CHARGER MODE CONTROL RELAYS (ASC 116)					COMPLIED WITH - CW	
13-FEB-2019		MOS HRS/MSC AFL	- (s)	18-JUN-2019 1103.7 440			
CB CB243	CB 243 MODIFICATION - FIXED APRON FIREWALL DOUBLER (ASC 112)					NOT APPLICABLE - NA	
01-MAR-2019		MOS HRS/MSC AFL	- (s)	22-MAR-2019 1034.5 418			
CB CB244	CB 244 REPLACEMENT - LIFE RAFT CONTAINING SRB406 ELT					NOT APPLICABLE - NA	
15-MAR-2019		MOS HRS/MSC AFL	- (s)	22-MAR-2019 1034.5 418			
CB CB245	CB 245 INSPECTION - LEFT ENGINE FIRE BOTTLE GROUND TERMINALS					CANCELLED	COMPLIED WITH - CW
21-MAR-2019		MOS HRS/MSC AFL	-	26-MAR-2019 1034.5 418			
CB CB245A	CB 245A INSPECTION - LEFT ENGINE FIRE BOTTLE GROUND TERMINAL					MANDATORY	NOT APPLICABLE
13-AUG-2019		MOS HRS/MSC AFL	-	12-NOV-2019 1189.3 486			
CB CB246	CB 246 - INSPECTION - HIGH PRESSURE COMPRESSOR VARIABLE STATOR VANES MECHANISM (ROLLS-ROYCE NMSB SB-BR700-72-900178)					COMPLIED WITH - CW	
26-MAR-2019		MOS HRS/MSC AFL		06-JUN-2019 1103.7 440			
CB CB247	CB 247 INSPECTION - WING INTERNAL - IGNITION SOURCE PROTECTION SEALANT (TRIUMPH G650 WING SERVICE BULLETIN MAA7-71258-07_TGI)					MANDATORY	
28-MAR-2019		MOS HRS/MSC AFL	48	(EFF)	08-JUL-2022		
CB CB248	CB 248 INSPECTION - WIRE ROUTING FLIGHT DECK AND VESTIBULE					MANDATORY	
28-MAR-2019		MOS HRS/MSC AFL	24	(EFF)	28-MAR-2021		
CB CB249A	CB 249A UPDATE - APU ELECTRONIC CONTROL UNIT SOFTWARE (ASC 123)					MANDATORY	
27-APR-2020		MOS HRS/MSC AFL	48		01-APR-2023		
CB CB250	CB 250 INSPECTION - WIRE ROUTING CABIN AND BAGGAGE COMPARTMENT					MANDATORY	
16-APR-2019		MOS HRS/MSC AFL	48	(EFF)	16-APR-2023		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB251	CB 251 MODIFICATION - FLAP ELECTRONIC CONTROL UNIT (FECU) SOFTWARE (ASC 110)					MANDATORY	
09-MAY-2019		MOS HRS/MSC AFL	36	(EFF)	09-MAY-2022		
CB CB252	CB 252 MODIFICATION - JETWAVE SYSTEM BLV7.1 SOFTWARE RELEASE (HONEYWELL SB JETWAVE-23-0007)						NOT APPLICABLE - NA
30-MAY-2019		MOS HRS/MSC AFL	- (s)	31-MAY-2019 1082.3 436			
CB CB253	CB 253 MODIFICATION - ENGINE ELECTRONIC CONTROLLER (EEC) - K9.0.1 SOFTWARE UPGRADE (ASC 133)						COMPLIED WITH - CW
05-AUG-2019		MOS HRS/MSC AFL	- (s)	08-AUG-2019 1115.4 450			
CB CB254	CB 254 INSPECTION - WIRE ROUTING VESTIBULE OUTBOARD OF LEFT ELECTRONIC EQUIPMENT RACK (LEER)					MANDATORY	
14-AUG-2019		MOS HRS/MSC AFL	36	(EFF)	14-AUG-2022		
CB CB255	CB 255 FUEL (ATA 28), INSPECTION - OVERWING GRAVITY FUELING ADAPTER INSTALLATION					MANDATORY	COMPLIED WITH
17-SEP-2019		MOS HRS/MSC AFL	-	24-JUL-2020 1245.8 507			
CB CB256	CB 256 WINGS (ATA 57), INSPECTION - LEFT WING FLAP TRACK B					MANDATORY	NOT APPLICABLE
18-SEP-2019		MOS HRS/MSC AFL	- (s)	12-NOV-2019 1189.3 486			
CB CB257	CB 257 REPLACEMENT OF ENGINE IGNITER PLUGS WITH P/N CH34760-2 (ROLLS-ROYCE SB-BR700-74-102003)					MANDATORY	COMPLIED WITH
18-OCT-2019		MOS HRS/MSC AFL	-	11-NOV-2019 1189.3 486			
CB CB259	CB 259 HYDRAULIC FILTER MONITORING SYSTEM - INSTALLATION AND ACTIVATION (ASC 090)					MANDATORY	
25-OCT-2019		MOS HRS/MSC AFL	36	(EFF)	25-OCT-2022		
CB CB261	CB 261 INSPECTION - MAIN ENTRANCE DOOR WIRING HARNESS INSTALLATION					MANDATORY	COMPLIED WITH
07-NOV-2019		MOS HRS/MSC AFL	-	21-JUL-2020 1245.8 507			
CB CB262	CB 262 MODIFICATION - FLAP TRACK D RUB STRIPS REMOVAL (ASC 083)					MANDATORY	
12-DEC-2019		MOS HRS/MSC AFL	36	(EFF)	12-DEC-2022		
CB CB263	CB 263 MODIFICATION - AIRCRAFT HEALTH AND TREND MONITORING SYSTEM - SOFTWARE UPDATE 2 (ASC 076B)					MANDATORY	COMPLIED WITH
29-JAN-2020		MOS HRS/MSC AFL	-	23-JUL-2020 1245.8 507			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CB CB264A	CB 264A INSPECTION - WINGLET ATTACH JOINTS					MANDATORY	
03-APR-2020		MOS HRS/MSC AFL	24		20-FEB-2022		
CB CB265	CB 265 MODIFICATION OF RUDDER TRAILING EDGE (ASC 134)					MANDATORY	
03-DEC-2019		MOS HRS/MSC AFL	12		03-DEC-2020		
CB CB266	CB 266 INSPECTION - AHRU CONNECTORS					MANDATORY	
27-MAR-2020		MOS HRS/MSC AFL	48		27-MAR-2024		
CB CB267	CB 267 INSPECTION - BELOW-FLOORS WIRING INSTALLATION AT FUSELAGE STATION (FS) 370					MANDATORY	
01-APR-2020		MOS HRS/MSC AFL	48		01-APR-2024		
CB CB268	CB 268 INSPECTION - PYLON WIRING INSTALLATION FOR CONTACT WITH PYLON RIB OPENINGS					MANDATORY	
01-MAY-2020		MOS HRS/MSC AFL	24		01-MAY-2022		
CB CB269	CB 269 INSPECTION - HORIZONTAL DRAG BRACE SPLICE FASTENERS AT FUSELAGE STATION (FS) 245.5					MANDATORY	COMPLIED WITH
11-JUN-2020		MOS HRS/MSC AFL	-	31-JUL-2020 1245.8 507			
CB CB271	CB 271 COCKPIT LIGHTING CONTROL PANELS - CONNECTOR PLATE RETAINING SCREWS					MANDATORY	COMPLIED WITH
24-JUN-2020		MOS HRS/MSC AFL	-	14-JUL-2020 1245.8 507			
CB CB272	CB 272 REPLACEMENT - STAGE 5 HANDLING BLEED VALVES(ROLLS-ROYCE SB-BR700-75-900673)					MANDATORY	
01-JUL-2020		MOS HRS/MSC AFL	12		01-JUL-2021		
CB CB273	ELECTRICAL POWER (ATA 24) - INSPECTION - BUSBAR FOR EBHA BATTERY CHARGER NO. 1, VOLTAGE OUTPUT CIRCUITRY, CUSTOMER BULLETIN (MANDATORY)					MANDATORY	
13-AUG-2020		MOS HRS/MSC AFL	12		13-AUG-2021		
CSB 016	G650 GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 2) FIRMWARE UPDATE CSB 016 (CE-CSB-6016)					OPTIONAL	NOT APPLICABLE - NA
		MOS HRS/MSC AFL	-	24-MAY-2019 1082.3 436			
CSB CE-CSB-6017	CE-CSB-6017 CABIN SERVICE BULLETIN 017 GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 1) FIRMWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
08-APR-2019		MOS HRS/MSC AFL	-	06-JUN-2019 1103.7 440			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
CSB CE-CSB-6022	CE-CSB-6022 CABIN SERVICE BULLETIN 022 GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS 1) FIRMWARE UPDATE					OPTIONAL	COMPLIED WITH
10-SEP-2019		MOS HRS/MSC - AFL		13-FEB-2020 1240.5 504			
CSB CSB-6012	CSB 6012 GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS) FIRMWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
11-AUG-2017		MOS HRS/MSC - AFL		03-JUL-2018 893.9 348			
CSB CSB-6013 REV A	ADVANCED CABIN SERVER (ACS) (GEN 4) CABINVIEW SOFTWARE UPGRADE (CE-CSB-6013 REV A)					OPTIONAL	COMPLIED WITH - CW. LANGUAGE LICENSE KEY: 4WMOY-YB9ZO-S1AA9-GNTNO
		MOS HRS/MSC - AFL		09-JUL-2018 893.9 348			
CSB CSB-6015	CSB 6015 ADVANCED CABIN SERVER (ACS) (GEN 4) CABINVIEW SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - CW
31-DEC-2018		MOS HRS/MSC - AFL		06-JUN-2019 1103.7 440			
CSB CSB6010	CSB 6010 ADVANCED CABIN SERVER (ACS) SYSTEM SOFTWARE UPGRADE					OPTIONAL	COMPLIED WITH - CW. REF. CE-CSB-6010 REV. --
		MOS HRS/MSC - AFL		17-AUG-2016 529.6 192			
SB 3202908-36-1912	HONEYWELL SB 3202908-36-1912 - REWORK LEFT FOUR-INCH DIAMETER CHECK VALVE, PN 3202908-1 TO PN 3202908-2, USED ON THE GULFSTREAM G650.					RECOMMENDED	COMPLIED WITH - CW
		MOS HRS/MSC - AFL		15-AUG-2016 529.6 192			
SB 940180	GCMS 2 FIRMWARE V2.1.0					MANDATORY	NOT APPLICABLE - NA
		MOS HRS/MSC - AFL		24-MAY-2019 1082.3 436			
SB 941400	FAA NEXTGEN PROGRAM MANDATE: ADS-B OUT COMPLIANCE					RECOMMENDED	COMPLIED WITH
15-JAN-2019		MOS HRS/MSC - AFL		06-DEC-2019 1207.4 492			
SB CSB-6008 REV A	CSB 008 - ADVANCED CABIN SERVER (ACS) SYSTEM UPGRADE V4.4.3.15					OPTIONAL	COMPLIED WITH - CW
04-JUN-2015		MOS HRS/MSC - AFL		04-NOV-2015 274.4 109			
SB CSB-6009	CSB 009 - GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS) FIRMWARE					OPTIONAL	COMPLIED WITH - CW
04-JUN-2015		MOS HRS/MSC - AFL		04-NOV-2015 274.4 109			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB CSB-6011	CSB 6011 GULFSTREAM CABIN MANAGEMENT SYSTEM (GCMS) FIRMWARE UPDATE					OPTIONAL	COMPLIED WITH - CW
17-MAY-2016		MOS		20-AUG-2016			
		HRS/MSC	-	529.6			
		AFL		192			
SB MP-15-6504 RA	AFT LAV DOOR (RETROFIT PROGRAM) (MP-15-6504 REV A)					OPTIONAL	COMPLIED WITH - CW
		MOS		06-JUL-2017			
		HRS/MSC	-	733.6			
		AFL		277			
SB MP-15-6505	FWD LH LAV & CREW DOOR LATCHES (RETROFIT PROGRAM)					OPTIONAL	COMPLIED WITH - CW
		MOS		04-NOV-2015			
		HRS/MSC	- (s)	274.4			
		AFL		109			
SB MP-15-6510.1	SB 52-10-02-014 - POCKET DOOR GENERAL UPGRADE					OPTIONAL	COMPLIED WITH - CW
		MOS		12-JUL-2017			
		HRS/MSC	-	733.6			
		AFL		277			
SB MP-15-6510.2	SB 52-10-02-013 - MOTION CONTROLLER					OPTIONAL	COMPLIED WITH - CW
		MOS		12-JUL-2017			
		HRS/MSC	-	733.6			
		AFL		277			
SB MP-15-6510.3	SB 52-10-02-015 - RAIL REPLACEMENT					OPTIONAL	COMPLIED WITH - CW
		MOS		12-JUL-2017			
		HRS/MSC	-	733.6			
		AFL		277			
SB MP-15-6510.4	POCKET DOOR DESCENDER (MP-15-6510)					OPTIONAL	COMPLIED WITH - CW
		MOS		12-JUL-2017			
		HRS/MSC	-	733.6			
		AFL		277			
SB MP-15-6510.5	POCKET DOOR JAMB					CANCELLED	COMPLIED WITH - CW
		MOS		12-JUL-2017			
		HRS/MSC	-	733.6			
		AFL		277			
SB MP-15-6514	DOORS & DRAWERS MECHANISM (MP 15-6514)					OPTIONAL	COMPLIED WITH - CW
		MOS		26-JUN-2017			
		HRS/MSC	-	733.6			
		AFL		277			
SB MP-15-6516.1	COCKPIT STEP BOX COVER REPLACEMENT - FWD					OPTIONAL	COMPLIED WITH - CW. PER G650 AOMM 25-17-00
		MOS		11-AUG-2016			
		HRS/MSC	-	529.6			
		AFL		192			
SB MP-15-6516.2	COCKPIT STEP BOX COVER REPLACEMENT - AFT					OPTIONAL	COMPLIED WITH - CW. PER G650 AOMM 25-17-00
		MOS		11-AUG-2016			
		HRS/MSC	-	529.6			
		AFL		192			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB MP-16-6502.1	SUB-WOOFER WIRE HARNESS (NO: VMP-16-6502)	MOS HRS/MSC - AFL		09-JUL-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6502.2	PASSENGER SERVICE UNIT (PSU) LANYARD AND PANEL ADJUSTERS (NO: VMP-16-6502)	MOS HRS/MSC - AFL		27-JUN-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6504	AFT LAV DOOR ENHANCEMENT PROGRAM (MP 16-6504)	MOS HRS/MSC - AFL		03-JUL-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6505	EXIT SIGNS (MP-16-6505)	MOS HRS/MSC - AFL		27-JUN-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6506	GALLEY PULLOUT WORK SURFACE (MP-16-6506)	MOS HRS/MSC - AFL		26-JUN-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6507	TIA BREW BASKET (MP 16-6507)	MOS HRS/MSC - AFL		30-JUN-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6508	AFT LAVATORY ASHTRAY (MP 16-6508)	MOS HRS/MSC - AFL		27-JUN-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6510	GLASS RACK DOOR RATTLES (MP 16-6510)	MOS HRS/MSC - AFL		27-JUN-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6512	DOORS & DRAWERS: TRASH CAN CLIPS (MP 16-6512)	MOS HRS/MSC - AFL		27-JUN-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6513	TABLE LIGHT LENS RATTLE (MP -16-6513)	MOS HRS/MSC - AFL		05-JUL-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW
SB MP-16-6515	DOUBLE SEAT ARMREST (MP-16-6515)	MOS HRS/MSC - AFL		28-JUN-2017 733.6 277		OPTIONAL	COMPLIED WITH - CW

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB MP-16-6517	DECORATIVE COATING AND COVERING REQUIREMENTS (MP-16-6517)					OPTIONAL	COMPLIED WITH - CW
		MOS		13-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-16-6518	CABIN ACOUSTICS ENHANCEMENT (MP-16-6518)					OPTIONAL	COMPLIED WITH - CW
		MOS		12-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-16-6519	CONVECTION OVEN FIRMWARE UPDATE R09 (MP-16-6519)					OPTIONAL	COMPLIED WITH - CW
		MOS		03-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-16-6520	FWD CREW DOOR PAWL (MP-16-6520)					OPTIONAL	COMPLIED WITH - CW
		MOS		25-AUG-2016			
		HRS/MSC -		529.6			
		AFL		192			
SB MP-16-6521	REER INSULATION - (MP-16-6521)					OPTIONAL	COMPLIED WITH - CW
		MOS		27-JUN-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-16-6523	60 HZ DUAL CAPACITY INCREASE - (MP-16-6523)					OPTIONAL	COMPLIED WITH - CW
		MOS		08-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-16-6524	MANUAL DOOR SWITCH - (MP-16-6524)					OPTIONAL	COMPLIED WITH - CW
		MOS		13-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-16-6525	AFT LAV DOOR ENHANCEMENT MODIFICATION (AFT LAV CLOSET/TOILET LIGHT BLEED) (MP-16-6525)					OPTIONAL	COMPLIED WITH - CW
		MOS		11-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-16-6526	AFT LAV DOOR ENHANCEMENT MODIFICATION (MP 16-6526)					OPTIONAL	COMPLIED WITH - CW
		MOS		06-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-16-6527	X WASP SWITCH PANEL: REPLACEMENT NUMBER "8" BURNED INTO DISPLAY (MP 16-6527)					OPTIONAL	COMPLIED WITH - CW
		MOS		11-JUL-2017			
		HRS/MSC -		733.6			
		AFL		277			
SB MP-17-6501 R01	AFT LAVATORY DOOR MAGNETIC BUMPER ASSEMBLY - HANGING MIRROR CONFIGURATION - MP-17-6501 REV A					OPTIONAL	COMPLIED WITH - CW
		MOS		05-JUL-2017			
		HRS/MSC - (s)		733.6			
		AFL		277			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB MP-17-6510	FLIGHT CONTROL COMPUTERS (FCC) V7.1 SOFTWARE UPDATE (MP-17-6510)					OPTIONAL	COMPLIED WITH - CW
		MOS		26-JUN-2018			
		HRS/MSC	-	893.9			
		AFL		348			
SB MP-17-6512	EMED STOP BOLTS (MP-17-6512)					OPTIONAL	COMPLIED WITH - CW
		MOS		04-JUN-2019			
		HRS/MSC	-	1103.7			
		AFL		440			
SB MP-20-6501	G650 AIR DATA PROBE, SERVICE BULLETIN (OPTIONAL)					OPTIONAL	
		MOS	18		16-SEP-2021		
16-MAR-2020		HRS/MSC					
		AFL					
STC ST04252AT-D	ST04252AT-D AIRCRAFT INTERIOR					OPTIONAL	COMPLIED WITH - CW. GC62801A001 REV B FOR MAINTENANCE REQUIREMENTS - INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DATED AUGUST 28, 2012. INTERIOR INSTALLED IN SAVANNAH
		MOS		21-OCT-2014			
		HRS/MSC	-	5.5			
		AFL		3			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
APU - SB - P-209/RE220[GVI] (CMP)							
SB 49-7933 R05	APU - SB 49-7933R5 APU APPROVED OILS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
23-OCT-2014		MOS HRS/MSC - AFL APUS		29-JAN-2016 0 0			
SB 49-7933 R06	APU - SB 49-7933R6 APU APPROVED OILS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
26-JAN-2016		MOS HRS/MSC - APUS		13-MAR-2017 0 0			
SB RE220-49-8085	APU - SB RE220-49-8085 - REPLACE RETURN AND SUPPLY OIL TRANSFER TUBE ASSEMBLIES					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
26-OCT-2012		MOS HRS/MSC - APUS		03-NOV-2015 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - 25317/BR725A1-12 (CMP)							
EASA 2013-0110	NO. 1 ENGINE - EASA AD 2013-0110 ROLLS-ROYCE DEUTSCHLAND LTD @ CO KG					MANDATORY	NOT APPLICABLE - NA
31-MAY-2013		MOS		13-AUG-2014			
		HRS/MSC -		0			
		APUS					
		ENC		0			
EASA 2013-0229	NO. 1 ENGINE - EASA AD 2013-0229 REPLACEMENT OF THE FUEL METERING UNIT (FMU)					CANCELLED	NOT APPLICABLE - CANCELLED. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW . CANCELED EASA AD 2013-0229. SEE CODE 993112(RRR)
07-OCT-2013		MOS		13-AUG-2014			
		HRS/MSC -		0			
		ENC		0			
FAA 2013-12-03	NO. 1 ENGINE - AD 2013-12-03 ROLLS-ROYCE DEUTSCHLAND LTD @ CO KG					MANDATORY	NOT APPLICABLE - NA
14-JUN-2013		MOS		13-AUG-2014			
		HRS/MSC - (s)		0			
		ENC		0			
FAA 2014-12-03	NO. 1 ENGINE - AD 2014-12-03 - FMU REPLACEMENT					MANDATORY	COMPLIED WITH - CW. REFERENCE 28.12: RR SB 73-101957 FMU / FUEL SYSTEM PACKAGE (POI 25550) TERMINATING ACTION FOR 650 HOUR REPLACEMENT OF FMU, PERFORMED BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
		MOS		14-AUG-2016			
		HRS/MSC -		529.6			
		ENC		192			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - 25316/BR725A1-12 (CMP)							
EASA 2013-0110	NO. 2 ENGINE - EASA AD 2013-0110 ROLLS-ROYCE DEUTSCHLAND LTD @ CO KG					MANDATORY	NOT APPLICABLE - NA
		MOS		13-AUG-2014			
31-MAY-2013		HRS/MSC -		0			
		ENC		0			
EASA 2013-0229	NO. 2 ENGINE - EASA AD 2013-0229 REPLACEMENT OF THE FUEL METERING UNIT (FMU)					CANCELLED	NOT APPLICABLE - CANCELLED. CUSTOMER REQUESTED ADD ALL 99 SERIES SCOTT BLACKLAW .CANCELED EASA AD 2013-0229. SEE CODE 993112(RRR)
		MOS		13-AUG-2014			
07-OCT-2013		HRS/MSC -		0			
		ENC		0			
FAA 2013-12-03	NO. 2 ENGINE - AD 2013-12-03 ROLLS-ROYCE DEUTSCHLAND LTD @ CO KG					MANDATORY	NOT APPLICABLE - NA
		MOS		13-AUG-2014			
14-JUN-2013		HRS/MSC - (s)		0			
		ENC		0			
FAA 2014-12-03	NO. 2 ENGINE - AD 2014-12-03 - FMU REPLACEMENT					MANDATORY	COMPLIED WITH - CW. REFERENCE 28.12: RR SB 73-101957 FMU / FUEL SYSTEM PACKAGE (POI 25550) TERMINATING ACTION FOR 650 HOUR REPLACEMENT OF FMU, PERFORMED BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
		MOS		14-AUG-2016			
		HRS/MSC -		529.6			
		ENC		192			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - 25317/BR725A1-12 (CMP)							
ASB R02	BR700-73-A900309	NO. 1 ENGINE - SB BR700-73-A900309 REV 2 REPLACEMENT OF THE FMU				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		28-MAY-2015			
		HRS/MSC	-	0			
		ENC		0			
ASB R03	BR700-73-A900309	NO. 1 ENGINE - SB BR700-73-A900309 REV 3 REPLACEMENT OF THE FMU				MANDATORY	COMPLIED WITH - CW. ** CMP UPDATE ** COMPLIED WITH BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
		MOS		14-AUG-2016		RECURRING	
		HRS/MSC	650	529.6			
		ENC		192			
SB	889201	NO. 1 ENGINE - SB 73-101967 EEC SOFTWARE K7.1.3 ENGINE 1				OPTIONAL	COMPLIED WITH - CW
		MOS		14-AUG-2016			
		HRS/MSC	-	529.6			
		ENC		192			
SB	889202	NO. 1 ENGINE - SB 73-101965 NEW LOW FUEL SYSTEM PACKAGE ENGINE 1				OPTIONAL	COMPLIED WITH - CW
		MOS		14-AUG-2016			
		HRS/MSC	-	529.6			
		ENC		192			
SB	889203	NO. 1 ENGINE - SB 73-101957 FMU / FUEL SYSTEM PACKAGE ENGINE 1				OPTIONAL	COMPLIED WITH - CW
		MOS		14-AUG-2016			
		HRS/MSC	-	529.6			
		ENC		192			
SB	BR700-71-101928	NO. 1 ENGINE - SB BR700-71-101928 - INTRODUCTION OF A REVISED V-CLAMP COUPLING WITH TWO RETAINING SEGMENTS FOR THE HYDRAULIC PUMP.				RECOMMENDED	COMPLIED WITH - CW
	10-DEC-2015	MOS		19-JAN-2016			
		HRS/MSC	-	345			
		ENC		134			
SB	BR700-71-900003	NO. 1 ENGINE - SB BR700-71-900003 - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT - INSPECTION OF THE V-BAND COUPLING CLAMP				RECOMMENDED	COMPLIED WITH - CW
		MOS	6	17-FEB-2015			
		HRS/MSC		120			
		ENC		52			
SB	BR700-72-101698	NO. 1 ENGINE - SB BR_72-101698 (LP) TURBINE FUEL SHUT-OFF CABLE AND FITINGS - INTRODUCTION OF A NEW FSO ELBOW ASSY				OPTIONAL	NOT APPLICABLE - NA
	22-JAN-2013	MOS		22-JAN-2013			
		HRS/MSC	-	0			
		ENC		0			
SB	BR700-72-101903	NO. 1 ENGINE - SB BR700-72-101903 - INTRODUCTION OF NEW BEARING CARRIERS WITH TIGHTENED GEOMETRICAL TOLERANCES				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
	06-OCT-2014	MOS		28-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900178	NO. 1 ENGINE - SB BR700-72-900178 - INSPECTION AND LUBRICATION OF THE VIGV ACTUATING MECHANISM ON ENGINES OPERATING UNDER SPECIFIC ENVIRONMENTAL CONDITIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		18-MAR-2019			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900178 R01	NO. 1 ENGINE - SB BR700-72-900178R1 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		09-MAY-2019			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900178 R02	NO. 1 ENGINE - SB BR700-72-900178R2 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	COMPLIED WITH - CW
		MOS		06-JUN-2019			
08-MAY-2019		HRS/MSC -		1103.7			
		ENC		440			
SB BR700-72-900178 R03	NO. 1 ENGINE - SB BR700-72-900178R3 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		17-JUL-2019			
12-JUL-2019		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900178 R04	NO. 1 ENGINE - SB BR700-72-900178R4 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	COMPLIED WITH - CW. PREVIOUSLY C/W GAC LUTON SC14721
		MOS		18-JUL-2019			
16-JUL-2019		HRS/MSC -		1115.4			
		ENC		450			
SB BR700-72-900178 R05	NO. 1 ENGINE - SB BR700-72-900178R5 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		29-JUL-2019			
22-JUL-2019		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900589 R01 PART A	NO. 1 ENGINE - SB BR700-72-900589R1 (PART A) - INSPECTION OF THE RADIAL DRIVE SHAFT SEAL RING					CANCELLED	COMPLIED WITH - CW. ** CMP UPDATE ** COMPLIED WITH BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
		MOS		14-AUG-2016			
04-APR-2016		HRS/MSC -		529.6			
		ENC		192			
SB BR700-73-101886	NO. 1 ENGINE - SB BR700-73-101886 REV 0 4-16-14 K6.2.2 SW STANDARD ON EEC					RECOMMENDED	COMPLIED WITH - CW
		MOS		08-AUG-2014			
		HRS/MSC -		5.6			
		ENC		3			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101892	NO. 1 ENGINE - SB BR700-73-101892 - INTRODUCTION OF A LOW PRESSURE (LP) FUEL SWITCH SENSE LINE TUBE WITH INCREASED VOLUME					CANCELLED	COMPLIED WITH - CW. ** CMP UPDATE ** COMPLIED WITH BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
17-SEP-2014		MOS HRS/MSC - ENC		14-AUG-2016 529.6 192			
SB BR700-73-101923	NO. 1 ENGINE - SB BR700-73-101923 - INTRODUCTION OF A NEW FUEL TUBE WITH AN INCREASED WALL THICKNESS.					RECOMMENDED	COMPLIED WITH - CW
23-JAN-2015		MOS HRS/MSC - ENC		05-NOV-2015 274.4 109			
SB BR700-73-101929	NO. 1 ENGINE - SB BR700-73-101929 - INTRODUCTION OF A REVISED V-CLAMP COUPLING WITH TWO RETAINING SEGMENTS					RECOMMENDED	COMPLIED WITH - CW
27-MAY-2015		MOS HRS/MSC - ENC		29-OCT-2015 274.4 109			
SB BR700-73-101957	NO. 1 ENGINE - SB BR700-73-101957 - INTRODUCTION OF A REVISED FUEL SYSTEM					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
21-APR-2016		MOS HRS/MSC - ENC		23-SEP-2016 0 0			
SB BR700-73-101965	NO. 1 ENGINE - SB BR700-73-101965 - INTRODUCTION OF A REVISED FUEL LOW PRESSURE (LP) SWITCH WITH A DECREASED PRESSURE TRIGGER POINT.					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
14-APR-2016		MOS HRS/MSC - ENC		16-SEP-2016 0 0			
SB BR700-73-101967	NO. 1 ENGINE - SB BR700-73-101967 - INTRODUCTION OF K7.1.3 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
14-APR-2016		MOS HRS/MSC - ENC		16-SEP-2016 0 0			
SB BR700-73-102134 R01	NO. 1 ENGINE - SB BR700-73-102134R1 - INTRODUCTION OF K9.0.1 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01					CANCELLED	COMPLIED WITH - CW
30-JUL-2019		MOS HRS/MSC - (s) ENC		08-AUG-2019 1115.4 450			
SB BR700-73-900009	NO. 1 ENGINE - SB BR700-73-900009 - MAIN FUEL PUMP - INSPECTION OF THE V-BAND COUPLING CLAMP					CANCELLED	COMPLIED WITH - CW
		MOS HRS/MSC - ENC		17-FEB-2015 120 52			
SB BR700-73-900636	NO. 1 ENGINE - SB BR700-73-900636 - ENGINE FUEL AND CONTROL - FUEL LOW PRESSURE (LP) SWITCH - REPLACEMENT OF THE FUEL LP SWITCH					RECOMMENDED	COMPLIED WITH - CW
01-FEB-2018		MOS HRS/MSC - ENC		21-FEB-2018 828.3 318			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-74-102002	NO. 1 ENGINE - SB BR700-74-102002 - INTRODUCTION OF AN IGNITER PLUG WITH REVISED SEMICONDUCTOR PELLETT BONDING					OPTIONAL	COMPLIED WITH - CW. I/B P/N SC3712 S/N 007000/B P/N SC3712 S/N 00785
26-SEP-2017		MOS HRS/MSC - ENC		30-JUN-2018 893.9 348			
SB BR700-74-102003	NO. 1 ENGINE - SB BR700-74-102003 - INTRODUCTION OF AN ALTERNATIVE IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER					CANCELLED	COMPLIED WITH - CW
24-MAY-2019		MOS HRS/MSC - ENC		20-JUN-2019 1103.7 440			
SB BR700-74-900568	NO. 1 ENGINE - SB BR700-74-900568 - REPLACEMENT OF IGNITION UNITS					RECOMMENDED	NOT APPLICABLE - NA. NOT APPLICABLE BY ENGINE SERIAL NUMBER(RRR)
13-MAR-2015		MOS HRS/MSC - ENC		31-AUG-2015 210.4 87			
SB BR700-74-900594	NO. 1 ENGINE - SB BR700-74-900594 REPLACEMENT OF THE IGNITER PLUGS AT A SPECIFIED INTERVAL					CANCELLED	COMPLIED WITH - CW
		MOS HRS/MSC - ENC		07-DEC-2017 792 300			
SB BR700-74-900594 R01	NO. 1 ENGINE - SB BR700-74-900594R1 - REPLACEMENT OF THE IGNITER PLUGS AT A SPECIFIED INTERVAL					CANCELLED	NOT APPLICABLE
		MOS HRS/MSC - ENC		11-NOV-2019 1189.3 486			
SB BR700-74-900649	NO. 1 ENGINE - SB BR700-74-900649 - INSPECTION OF THE IGNITER PLUGS AT A SPECIFIED INTERVAL					RECOMMENDED	
		MOS HRS/MSC 1250 ENC		0 0	2143.9 M	RECURRING	
SB BR700-80-101904	NO. 1 ENGINE - SB BR700-80-101904 - INTRODUCTION OF A MODIFIED STARTER AIR VALVE					CANCELLED	COMPLIED WITH - CW
26-MAY-2015		MOS HRS/MSC - ENC		26-AUG-2016 531.2 193			
SB BR700-80-900020	NO. 1 ENGINE - SB BR700-80-900020 - INSPECTION OF STARTER AIR VALVES FOR FOREIGN OBJECT DEBRIS (FOD)					RECOMMENDED	COMPLIED WITH - CW. IT IS RECOMMENDED THAT THIS NON-MODIFICATION SERVICE BULLETIN BE ACCOMPLISHED ON ENGINES AT THE NEXT SCHEDULED MAINTENANCE OPPORTUNITY.
25-FEB-2015		MOS HRS/MSC - ENC		30-OCT-2015 274.4 109			
SB BR700-80-900629	NO. 1 ENGINE - SB-BR700-80-900629 - REPLACEMENT OF STARTER AIR VALVES WITH POTENTIAL FOREIGN OBJECT DEBRIS (FOD)					RECOMMENDED	COMPLIED WITH - CW
08-SEP-2017		MOS HRS/MSC - ENC		28-SEP-2017 744.4 284			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-80-900634	NO. 1 ENGINE - SB BR700-80-900634 - REPLACEMENT OF STARTER AIR VALVES WITH POTENTIAL OF INTERNAL FREEZING					RECOMMENDED	COMPLIED WITH - CW
		MOS		05-JUN-2019			
		HRS/MSC -		1103.7			
		ENC		440			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - 25316/BR725A1-12 (CMP)							
ASB R02	BR700-73-A900309	NO. 2 ENGINE - SB BR700-73-A900309 REV 2 REPLACEMENT OF THE FMU				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		28-MAY-2015			
		HRS/MSC	-	0			
		ENC		0			
ASB R03	BR700-73-A900309	NO. 2 ENGINE - SB BR700-73-A900309 REV 3 REPLACEMENT OF THE FMU				MANDATORY	COMPLIED WITH - CW. ** CMP UPDATE ** COMPLIED WITH BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
		MOS		14-AUG-2016		RECURRING	
		HRS/MSC	650	529.6			
		ENC		192			
SB	889201	NO. 2 ENGINE - SB 73-101967 EEC SOFTWARE K7.1.3 ENGINE 2				OPTIONAL	COMPLIED WITH - CW
		MOS		09-AUG-2016			
		HRS/MSC	-	529.6			
		ENC		192			
SB	889202	NO. 2 ENGINE - SB 73-101965 NEW LOW FUEL SYSTEM PACKAGE ENGINE 2				OPTIONAL	COMPLIED WITH - CW
		MOS		14-AUG-2016			
		HRS/MSC	-	529.6			
		ENC		192			
SB	889203	NO. 2 ENGINE - SB 73-101957 FMU / FUEL SYSTEM PACKAGE ENGINE 2				OPTIONAL	COMPLIED WITH - CW
		MOS		14-AUG-2016			
		HRS/MSC	-	529.6			
		ENC		192			
SB	BR700-71-101928	NO. 2 ENGINE - SB BR700-71-101928 - INTRODUCTION OF A REVISED V-CLAMP COUPLING WITH TWO RETAINING SEGMENTS FOR THE HYDRAULIC PUMP.				RECOMMENDED	COMPLIED WITH - CW
	10-DEC-2015	MOS		19-JAN-2016			
		HRS/MSC	-	345			
		ENC		134			
SB	BR700-71-900003	NO. 2 ENGINE - SB BR700-71-900003 - LEFT AND RIGHT QUICK ENGINE CHANGE UNIT - INSPECTION OF THE V-BAND COUPLING CLAMP				RECOMMENDED	COMPLIED WITH - CW
		MOS	6	17-FEB-2015			
		HRS/MSC		120			
		ENC		52			
SB	BR700-72-101698	NO. 2 ENGINE - SB BR_72-101698 (LP) TURBINE FUEL SHUT-OFF CABLE AND FITINGS - INTRODUCTION OF A NEW FSO ELBOW ASSY				OPTIONAL	NOT APPLICABLE - NA
	22-JAN-2013	MOS		22-JAN-2013			
		HRS/MSC	-	0			
		ENC		0			
SB	BR700-72-101903	NO. 2 ENGINE - SB BR700-72-101903 - INTRODUCTION OF NEW BEARING CARRIERS WITH TIGHTENED GEOMETRICAL TOLERANCES				CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
	06-OCT-2014	MOS		28-SEP-2015			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-72-900178	NO. 2 ENGINE - SB BR700-72-900178 - INSPECTION AND LUBRICATION OF THE VIGV ACTUATING MECHANISM ON ENGINES OPERATING UNDER SPECIFIC ENVIRONMENTAL CONDITIONS					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		18-MAR-2019			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900178 R01	NO. 2 ENGINE - SB BR700-72-900178R1 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		09-MAY-2019			
		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900178 R02	NO. 2 ENGINE - SB BR700-72-900178R2 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	COMPLIED WITH - CW
		MOS		06-JUN-2019			
08-MAY-2019		HRS/MSC -		1103.7			
		ENC		440			
SB BR700-72-900178 R03	NO. 2 ENGINE - SB BR700-72-900178R3 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		17-JUL-2019			
12-JUL-2019		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900178 R04	NO. 2 ENGINE - SB BR700-72-900178R4 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	COMPLIED WITH - CW. PREVIOUSLY C/W GAC LUTON SC14721
		MOS		18-JUL-2019			
16-JUL-2019		HRS/MSC -		1115.4			
		ENC		450			
SB BR700-72-900178 R05	NO. 2 ENGINE - SB BR700-72-900178R5 - INSPECTION AND LUBRICATION OF THE VSV MECHANISM					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
		MOS		29-JUL-2019			
22-JUL-2019		HRS/MSC -		0			
		ENC		0			
SB BR700-72-900589 R01 PART A	NO. 2 ENGINE - SB BR700-72-900589R1 (PART A) - INSPECTION OF THE RADIAL DRIVE SHAFT SEAL RING					CANCELLED	COMPLIED WITH - CW. ** CMP UPDATE ** COMPLIED WITH BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
		MOS		14-AUG-2016			
04-APR-2016		HRS/MSC -		529.6			
		ENC		192			
SB BR700-73-101886	NO. 2 ENGINE - SB BR700-73-101886 REV 0 4-16-14 K6.2.2 SW STANDARD ON EEC					RECOMMENDED	COMPLIED WITH - CW
		MOS		08-AUG-2014			
		HRS/MSC -		5.6			
		ENC		3			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-73-101892	NO. 2 ENGINE - SB BR700-73-101892 - INTRODUCTION OF A LOW PRESSURE (LP) FUEL SWITCH SENSE LINE TUBE WITH INCREASED VOLUME					CANCELLED	COMPLIED WITH - CW. ** CMP UPDATE ** COMPLIED WITH BY ROLLS ROYCE UNDER THEIR WORK ORDERS 0.001300687-3966 & 0.001300687-3967.
17-SEP-2014		MOS HRS/MSC - ENC		14-AUG-2016 529.6 192			
SB BR700-73-101923	NO. 2 ENGINE - SB BR700-73-101923 - INTRODUCTION OF A NEW FUEL TUBE WITH AN INCREASED WALL THICKNESS.					RECOMMENDED	COMPLIED WITH - CW
23-JAN-2015		MOS HRS/MSC - ENC		05-NOV-2015 274.4 109			
SB BR700-73-101929	NO. 2 ENGINE - SB BR700-73-101929 - INTRODUCTION OF A REVISED V-CLAMP COUPLING WITH TWO RETAINING SEGMENTS					RECOMMENDED	COMPLIED WITH - CW
27-MAY-2015		MOS HRS/MSC - ENC		29-OCT-2015 274.4 109			
SB BR700-73-101957	NO. 2 ENGINE - SB BR700-73-101957 - INTRODUCTION OF A REVISED FUEL SYSTEM					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
21-APR-2016		MOS HRS/MSC - ENC		23-SEP-2016 0 0			
SB BR700-73-101965	NO. 2 ENGINE - SB BR700-73-101965 - INTRODUCTION OF A REVISED FUEL LOW PRESSURE (LP) SWITCH WITH A DECREASED PRESSURE TRIGGER POINT.					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
14-APR-2016		MOS HRS/MSC - ENC		16-SEP-2016 0 0			
SB BR700-73-101967	NO. 2 ENGINE - SB BR700-73-101967 - INTRODUCTION OF K7.1.3 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01					CANCELLED	NOT APPLICABLE - CANCELLED. THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.
14-APR-2016		MOS HRS/MSC - ENC		16-SEP-2016 0 0			
SB BR700-73-102134 R01	NO. 2 ENGINE - SB BR700-73-102134R1 - INTRODUCTION OF K9.0.1 SOFTWARE STANDARD ON AN EEC WITH HARDWARE STANDARD G3010ECU01					CANCELLED	COMPLIED WITH - CW
30-JUL-2019		MOS HRS/MSC - (s) ENC		08-AUG-2019 1115.4 450			
SB BR700-73-900009	NO. 2 ENGINE - SB BR700-73-900009 - MAIN FUEL PUMP - INSPECTION OF THE V-BAND COUPLING CLAMP					CANCELLED	COMPLIED WITH - CW
		MOS HRS/MSC - ENC		17-FEB-2015 120 52			
SB BR700-73-900636	NO. 2 ENGINE - SB BR700-73-900636 - ENGINE FUEL AND CONTROL - FUEL LOW PRESSURE (LP) SWITCH - REPLACEMENT OF THE FUEL LP SWITCH					RECOMMENDED	NOT APPLICABLE - NA
01-FEB-2018		MOS HRS/MSC - ENC		21-FEB-2018 828.3 318			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB BR700-74-102002	NO. 2 ENGINE - SB BR700-74-102002 - INTRODUCTION OF AN IGNITER PLUG WITH REVISED SEMICONDUCTOR PELLETT BONDING					OPTIONAL	COMPLIED WITH - CW. I/B P/N SC3712 S/N 007070/B P/N SC3712 S/N 00697
26-SEP-2017		MOS HRS/MSC - ENC		30-JUN-2018 893.9 348			
SB BR700-74-102003 (890173)	NO. 2 ENGINE - SB BR700-74-102003 - INTRODUCTION OF AN ALTERNATIVE IGNITER PLUG MANUFACTURED BY A DIFFERENT SUPPLIER					CANCELLED	COMPLIED WITH - CW
24-MAY-2019		MOS HRS/MSC - ENC		20-JUN-2019 1103.7 440			
SB BR700-74-900568	NO. 2 ENGINE - SB BR700-74-900568 - REPLACEMENT OF IGNITION UNITS					RECOMMENDED	NOT APPLICABLE - NA. NOT APPLICABLE BY ENGINE SERIAL NUMBER(RRR)
13-MAR-2015		MOS HRS/MSC - ENC		31-AUG-2015 210.4 87			
SB BR700-74-900594	NO. 2 ENGINE - SB BR700-74-900594 REPLACEMENT OF THE IGNITER PLUGS AT A SPECIFIED INTERVAL					CANCELLED	COMPLIED WITH - CW
		MOS HRS/MSC - ENC		08-DEC-2017 792 300			
SB BR700-74-900594 R01	NO. 2 ENGINE - SB BR700-74-900594R1 - REPLACEMENT OF THE IGNITER PLUGS AT A SPECIFIED INTERVAL					CANCELLED	NOT APPLICABLE
		MOS HRS/MSC - ENC		11-NOV-2019 1189.3 486			
SB BR700-74-900649	NO. 2 ENGINE - SB BR700-74-900649 - INSPECTION OF THE IGNITER PLUGS AT A SPECIFIED INTERVAL					RECOMMENDED	
		MOS HRS/MSC 1250 ENC		0 0	2143.9 M	RECURRING	
SB BR700-80-101904	NO. 2 ENGINE - SB BR700-80-101904 - INTRODUCTION OF A MODIFIED STARTER AIR VALVE					CANCELLED	COMPLIED WITH - CW
26-MAY-2015		MOS HRS/MSC - ENC		26-AUG-2016 531.2 193			
SB BR700-80-900020	NO. 2 ENGINE - SB BR700-80-900020 - INSPECTION OF STARTER AIR VALVES FOR FOREIGN OBJECT DEBRIS (FOD)					RECOMMENDED	COMPLIED WITH - CW. IT IS RECOMMENDED THAT THIS NON-MODIFICATION SERVICE BULLETIN BE ACCOMPLISHED ON ENGINES AT THE NEXT SCHEDULED MAINTENANCE OPPORTUNITY.
25-FEB-2015		MOS HRS/MSC - ENC		30-OCT-2015 274.4 109			
SB BR700-80-900629	NO. 2 ENGINE - SB-BR700-80-900629 - REPLACEMENT OF STARTER AIR VALVES WITH POTENTIAL FOREIGN OBJECT DEBRIS (FOD)					RECOMMENDED	COMPLIED WITH - CW
08-SEP-2017		MOS HRS/MSC - ENC		28-SEP-2017 744.4 284			

Task No.		Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB	BR700-80-900634	NO. 2 ENGINE - SB BR700-80-900634 - REPLACEMENT OF STARTER AIR VALVES WITH POTENTIAL OF INTERNAL FREEZING					RECOMMENDED	COMPLIED WITH - CW
			MOS			05-JUN-2019		
			HRS/MSC	-		1103.7		
			ENC			440		