# GLASAIR GLASAIR SUPER II FT Model Guide

The GLASAIR GLASAIR SUPER II FT is a single-engine piston Glasair variant. The Super II series was originally called the Super II-S. The only source supplied is a Glasair advisory index dated 6/9/08, not a performance manual. It gives no speeds, weights, range or engine data, so this guide covers which service bulletins to check.

## KEY TAKEAWAYS

- Super II FT instruction manual revisions run through Rev. S2-C (8/31/97). There are no current ANORs, and the owner's manual has no revisions to date.
- Bulletin 146 (9/5/96), on nose gear trunnion attach plate fasteners, covers all II-S FTs and Super II FTs.
- Several bulletins depend on kit number. Compare your kit to the ranges #2200–2349, #2281–2306 and #2320, 2328, 2335–2356.
- The index says to keep all Glasair advisory publications together in one binder. Ask the seller for that binder.

## BULLETINS NAMING SUPER II OR II-S FT

Bulletin 146 covers nose gear trunnion attach plate fasteners on all II-S FTs and Super II FTs. Bulletin 112A (10/26/92) covers CG location and longitudinal stability and control on II-S FTs thru Kit #2184. Bulletins 130 and 150 cover the fuel filter bowl bolt and the Fram fuel filter assembly on all Super IIs. The index says II-S references apply equally to the Super II.

## KIT-NUMBER SPECIFIC BULLETINS

Bulletin 131 covers fuel venting overboard on Super II Kits #2200–2349. Bulletin 132 covers rudder pedal control weldments on Super II Kits #2281–2306. Bulletin 140 covers the elevator torque tube on Super II Kits #2320, 2328 and 2335–2356. Confirm the airframe's kit number and ask for proof that each applicable bulletin was done.

## BULLETINS FOR ALL GLASAIRS

Bulletin 18 covers fuel contamination. Bulletin 115 Rev. A covers the fuel selector valve. Bulletin 153 covers aileron counterweight assemblies. Bulletin 73 covers engine mount nuts. Bulletin 160 covers the nose gear axle nut on aircraft with nose gear. Service Letter 5 covers gross weights for all Glasairs. Check each one for compliance.

## SAFETY NOTES

- Check fuel-system bulletins: 18 (fuel contamination), 115 Rev. A (fuel selector valve) and, if the kit number is in range, 131 (fuel venting).
- The index marks mandatory bulletins in boldface, but the supplied text does not show which ones. Confirm mandatory status and compliance with the factory.
- Nose gear items to verify: bulletin 146 (trunnion attach plate fasteners) and bulletin 160 (nose gear axle nut).

AI-aggregated guide for the GLASAIR GLASAIR SUPER II FT · sources: INDEX OF GLASAIR ADVISORY PUBLICATIONS (#102837) · generated 2026-11-26 · Reference only, not for flight. Check the original documents before relying on this guide.